

Work Order History Report

11-Jun-2024

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
MS85		JCB 3CX BACKHOE						
	8181	GRV Radio Installed by Wideland;21.12.2021 - GRV Radio (sn#511TWK1054) Installed by Wideland Ad Toowoomba (SM)	21/12/2021		Hours	0.0	0.1	\$1,551.75
	8060	New Asset compliance inspection:23.02.2022_MWR_SC - Perform MSS Machine Inspection, upload photos onto compliance portal. (SM)23.02.2022_MWR_RC - Remove 300amp jump start point and replace with 175amp. complete (SM)	23/02/2022	8.6	Hours	0.0	2.0	\$258.72
	8061	MNM Site Intro:24.02.2022_MWR_SC - Perform MNM brake test, complete paperwork. Scan and submit paperwork. (SM) 23.02.2022_MWR_SC - Began MNM Site Intro, Brake test and possible hose register required. (SM)22.12.2021 - MNM work order attached (SM)	24/02/2022	8	Hours	2.0	2.0	\$240.00
	8064	Compliance mods:24.02.2022_MWR_SC - Perform hose audit/register engrave/sleeve and mark hoses, spiral wrap remaining exposed hosing for protection on loader section, bucket, jack legs. (SM)	24/02/2022			0.0	2.0	\$349.75
	8062	GRV Site Intro:24.02.2022_MWR_SC - Perform GRV brake test, complete compliance paperwork, scan and submit. (SM) 23.02.2022_MWR_SC - Began GRV Site Intro, brake test required. (SM)	25/02/2022			0.0	2.0	\$240.00
	8195	Reverse Camera not working;23.03.2022_MWR_SC - Inspected camera, not working, tested wiring to head unit, ok, tested signal from camera, failed, found loose connection in signal cable, tightened, test camera, ok. (SM)	23/03/2022	54	Hours	1.0	1.0	\$120.00
	8196	Unable to get Bucket Float to work.23.03.2022_MWR_SC - Inspected for Bucket float, no switches, bucket float was not installed on this model. (SM)22.03.2022 - Instructions supplied by Wideland to Sean (SM)21.03.2022 - Emailed Wideland for directions (SM)	23/03/2022		Hours	0.0	0.1	\$12.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	8239	Lots of Hydraulic Lag on the Hoe/Boom;28.07.2022_Replacing the Hoe Control Valves should rectify the fault (SM) 01.04.2022_MWR_WA - Inspect and report fault with backhoe control performance. Spoke with Wideland Ag regarding modification valve to obtain correct backhoe operation, correct kit needs to be installed as changing the hosing doesn't suit the machine valving & operating pressures (SM)	1/04/2022		Hours	0.0	0.0	\$120.00
	8392	GRV Brake Test due;04.05.2022_MWR_SC - Perform Brake Test, complete, scan and submit paperwork. (SM)	4/05/2022		Hours	0.5	0.8	\$90.00
	8393	MNM Brake Test due;04.05.2022_MWR_SC - Perform Brake Test, complete, scan and submit paperwork. (SM)	4/05/2022		Hours	0.0	0.8	\$90.00
	8424	Needs Front Mudguards;10.05.2022_MWR_SC - Remove wheels, fit mudguards as per instructions, refit wheels, test drive, ok. (SM)09.05.2022 - Guard Kit in stock (SM)21.03.2022 - Emailed Wideland & Terrequipe for quotes (SM)	10/05/2022	214	Hours	2.5	2.5	\$1,195.00
	8236	First Service due at 100hrs (218hrs on 15/05);Drain and replace rear diff oils,25.05.2022_SOS B result, recommended resample in 250hrs. (KD)15.05.2022 - Carry Out first service as per JCB sheet (SM)09.05.2022 - Service Kit in Stock (SM)06.05.2022 - Wideland is sending the Kit for us to Service, they will do the 500Hrs Service (SM)30.03.2022 - Service to be done by Wideland Ag (SM)	1/06/2022		Hours	6.0	6.0	\$1,412.43
	8267	Needs Cheek Plates or side cutting plates put on the Oz Buckets AT014, AT015 & AT016;01.07.2022_MWR_RC - Clean up side of bucket install side cutting/protection edges and torque bolts (SM)07.04.2022 - Parts in stock (SM)01.04.2022 - Ordered Edge Cutters(3 sets) from Oz Buckets (SM)01.05.2022_MWR_WA - Inspect buckets for shin plates (SM)	1/07/2022		Hours	0.0	0.0	\$447.00
	8801	Replace all engine and Cab air Filter:18.07.2022 - MWR_RC_change out all engine and cab air filters. (KD)10.06.2022 - Parts in stock (SM)06.06.2022 - Shipped from Mackay today (SM)31.05.2022 - Inner Cab Filter & Spare Outer Can & Primary Engine Air filters ordered from Terrequipe Mackay, ETA 06/06 (SM)	18/07/2022		Hours	1.5	1.5	\$397.61
	8796	Isaac Plains Site Intro:19.07.2020_MWR_SCR_Completed SIP inspection, completed, scanned and submitted paperwork. (KD) 19.07.2022_Sean emailed brake test, no MWR for 19.07	19/07/2022		Hours	0.0	0.0	\$360.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		yet. (KD) 18.07.2022_MWR_SCR_Received backhoe from GRV, had to wash, weed and seed machine as it was heavily caked in mud. Brake tested and began IP inspection					
	8841	MNM Brake Test:29.07.2022_MWR_SC_sent MWR. (KD) 27.07.2022_Sean emailed MWR but dated 27th, emailed to double check if done twice and need the brake test paperwork for 27th test. (KD) 19.07.2022_Sean emailed brake test, no MWR yet. (KD)	19/07/2022	Hours	1.0	1.0	\$120.00
	8840	GRV Brake Test:27.07.2022_Sean emailed MWR but dated 27th, emailed to double check if done twice and need the brake test paperwork for 27th test. Sean said he would backdate MWR to match (KD) 19.07.2022_Sean emailed brake test, no MWR yet. (KD)	29/07/2022	Hours	1.0	1.0	\$120.00
	8989	Low Hyd Oil:20.08.2022_MWR_WA - Top up Hyd Oil. (SM)	20/08/2022	Hours	1.0	1.0	\$190.60
	9245	Fire Ext out of date.28.09.2022_MWR_WA - Take fire extinguishers to be tested and refit cab extinguisher/replace external extinguisher with E220. (SM)	29/09/2022	Hours	0.0	2.0	\$240.00
	9250	Supply Grease Gun.30.09.2022_MWR_WA - Supplied Grease gun & Cartridges, had to get chuck/hose made from MHF . (SM)	30/09/2022	Hours	0.0	0.0	\$111.00
	9253	Service due at 500hrs(477hrs on 29/09) :29.09.2022_MWR_WA - Carry out 500hr service (SM) 29.09.2022_Parts in stock (SM)28.09.2022_Filters ordered from Terreque on MEX PO 1244 (SM)	30/09/2022	Hours	7.0	7.0	\$1,625.39
	9255	Beacons Faulty:02.10.2022_MWR_WA - Remove/ modify beacon mount to fit one beacon and refit, Second beacon put into store. (SM)01.10.2022_MWR_WA - Fit and connect 2x beacons, Will look at relocating bracket and fit only one beacon as site requirements. (SM)29.09.2022_MWR_WA - Test flashing light fault, needs new beacons. (SM)	2/10/2022	Hours	4.0	4.0	\$590.00
	9219	Punctured Tyre:05.10.2022_MWR_SC - Picked up wheel assembly, fitted to machine, test, ok. (SM) 04.10.2022_Tyrepower advised the tyre isn't repairable, new spare ordered to replace the one used (SM)30.09.2022_Clean muddy yard with spreader bar. Set up remove tyre deliver to tyre power. (SM)26.09.2022_Tyre needs to be dropped to Tyrepower to see if they can repair enough to run a tube. The	5/10/2022	Hours	48.0	7.5	\$3,375.45

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		swap tyres back. (SM)25.09.2022_MWR_SC - Received call from Zac about operator at Winchester downs has a punctured tyre on MS85. Drove out to site (30 min drive) located machine, removed wheel assembly, brought back to w/s. inspected puncture, punctured in 3 locations, appears to be spikes/splinters. Attempted to repair, as punctures were so close together and on the curvature of the tyre, Could not repair, may need to purchase a tube If tyre is to be used again..Removed tyre off of rim, fitted new Michelin XMCL 440/80R28 Tyre Backhoe tyre, inflated, loaded onto ute. Drove to site, fitted wheel assembly to backhoe, left site. Drove back to w/s. (SM)						
	9274	GRV Brake Test :05.10.2022_MWR_SC - Whilst testing, noticed that brake test is almost due performed GRV brake test, scanned and completed paperwork. (SM)	5/10/2022		Hours	0.0	0.5	\$60.00
	9275	MNM Brake Test :05.10.2022_MWR_SC - Whilst testing, noticed that brake test is almost due performed MNM brake test, scanned and completed paperwork. (SM)	5/10/2022		Hours	0.0	0.5	\$60.00
	9374	Overheating. 18.10.2022_MWR_RC - Clear out radiator, cooling pack and air cleaners, drive backhoe to front gate of farm to get it away from black soil plains. (SM)	18/10/2022		Hours	0.0	3.0	\$360.00
	9484	Fuel Tank damaged.07.11.2022_MWR_RC - Assemble and fit tank to machine refit isolators and steps, fill tanks prime up and test machine. (SM)05.11.2022_MWR_SC - Fuel tank has been ruptured, drain fuel from tank, remove tank, clean up, poly weld hole, Sikaflex remaining gap, fabricate and install patch, will allow to dry for 24Hrs prior to fitment. (SM)	7/11/2022		Hours	36.0	6.0	\$720.00
	9516	Foxleigh Site Intro.13.11.2022_MWR_WA - Fill out site intro paperwork and repair and adjust spring for l/h rear indicator. (SM)09.11.2022_MWR_WA - Start Foxleigh site intro. (SM)	13/11/2022		Hours	0.0	2.0	\$240.00
	9704	GRV Site Intro.03.12.2022_MWR_SC - Complete GRV annual inspection and paperwork, scan and submit. (SM)02.12.2022_MWR_SC - Begin annual inspection, perform brake test. (SM)	3/12/2022		Hours	1.0	2.0	\$240.00
	9705	MNM Site Intro.03.12.2022_MWR_SC - complete MNM annual inspection and paperwork, scan and submit. (SM)02.12.2022_MWR_SC - Begin annual inspection, perform brake test. (SM)	3/12/2022	579	Hours	1.0	2.0	\$240.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	9712	Repairs.04.12.2022_MWR_RC - Grease all points, fit squawker back up alarm, remove number plate light & repair cable connector for camera. Wash out coolers & wash machine. Weld repair fork tine support. (SM)	4/12/2022		Hours	6.5	6.5	\$815.00
	8197	Unable to select Excavator Pattern on Hoe;10.02.2023_Craig advised he doesn't want to go ahead with the fitment of the Kit. (SM)14/07/2022 12:00 AM - Wideland to supply the instructions for us to fit the kit. (SM)7/12/2022 12:00 AM - Kit is in Stock Toowoomba, awaiting Wideland to get back to me regarding install (SM)5/06/2022 12:00 AM - Wideland advised eta 14/06/2022 12:00 AM (SM)01.04.2022_MWR_WA - Travel to site. Draw out template for backhoe decal. Template delivered to create a sign (SM)30/03/2022 12:00 AM - Spoke with Create a Sign, they can make one but need an outline Template of the old Sticker for dimensions, asked Wayne to trace a template and drop to Jodee at Create a Sign (SM) 23/03/2022 12:00 AM - Contacted Wideland regarding replacement His Control Sticker to show SAE & ISO Patterns (SM)23/03/2022 12:00 AM_MWR_SC - Test function, backhoe mode is not easily switchable to excavator mode, inspected further, hoses can be swapped but adapter fittings necessary, drove to MHF, adapter fittings had to be fabricated due to unusual size in BSP fittings, picked up fittings, fitted, tested function, excavator mode is working. (SM)22/03/2022 12:00 AM - Advised by Wideland Ag this machine requires an upgrade for this function, quote pending (SM)21/03/2022 12:00 AM - Emailed Wideland for directions (SM)	10/02/2023		Hours	0.0	0.0	\$880.04
	10043	GRV Brake Test13.02.2023_MWR_SC - Perform brake test, complete, scan and submit paperwork. (SM)	13/02/2023	629	Hours	0.0	0.8	\$90.00
	10044	MNM Brake Test.13.02.2023_MWR_SC - Perform brake test, complete, scan and submit paperwork. (SM)	13/02/2023		Hours	0.0	0.8	\$90.00
	10078	Change Hoe function from Excavator pattern back to Standard.17.02.2023_MWR_WA - Reset hydraulic hoses back to factory arrangement. (SM)	17/02/2023		Hours	5.0	5.0	\$600.00
	10178	Reset Hoe Pattern back to Excavator Pattern by Wed 08/03.06.03.2023_MWR_WA - Re-connect hoses for back hoe back to digger pattern. Top up hyd oil. (SM)	6/03/2023		Hours	4.0	4.0	\$515.93
	10203	Overheating.09.03.2023_MWR_SC - Cleaned out cooler	9/03/2023		Hours	0.5	0.5	\$60.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		packs, cleaned out air filters. (SM)27.02.2023_Tim phoned to report a Critical Warning on Dash, checked online and found it was reporting Overheat warnings. Tim took the Service Trailer from the W/shop to blow out. (SM)						
10292		AC not working.26.03.2023_MWR_SC - A/C not working. Backhoe came into w/s. Inspected, very low flow out of vents/warm air. Disassembled evaporator, found it has frozen up and blocked filters. Removed filters, cleaned cores, installed new filters, reassembled interior, test, ok. (SM)	26/03/2023	720	Hours	2.0	2.0	\$268.46
10333		Service due at 750hrs (729 hrs on 29/03) 29.03.2023_MWR_SP - Conduct 250hr service as per service documents. (SM)14.03.2023_Parts in stock. (SM)	29/03/2023	729	Hours	4.0	4.0	\$789.64
10344		Daunia Site Intro.31.03.2023_MWR_SP - Hand brake test failed for site compliance Insp. Adjusted hand brake so it did pass. (SM)30.03.2023_Daunia Site Intro insp booked for 30/03. (SM)	31/03/2023	730	Hours	1.0	1.0	\$120.00
10370		RHS Tail Light broken.MRF Request No 6604_MS85_WS_01.04.2023.06.04.2023_MWR_WA - Replace R/h tail light lens. Straighten surrounding bracket. (SM)06.04.2023_Lens in stock. (SM)05.04.2023_Lens ordered from Terreque Mackay (SM)	6/04/2023		Hours	1.0	1.0	\$155.34
10394		Install BMA Daunia Radio by 12/04.11.04.2023_MWR_WA - Fit and wire radio 10 BMA mine radio (Radio #R10) (SM)	11/04/2023		Hours	0.0	2.0	\$405.00
10548		GRV Brake Test.03.05.2023_MWR_SC - Perform brake test, complete, scan and submit paperwork.	3/05/2023	794	Hours	0.0	0.8	\$90.00
10549		MNM Brake Test.03.05.2023_MWR_SC - Perform brake test, complete, scan and submit paperwork.	3/05/2023		Hours	0.0	0.8	\$90.00
10603		Remove BMA Radio #10.09.05.2023_MWR_WA - Remove radio 10. Taken to w/s/store cabinet (SM)	9/05/2023	795	Hours	0.0	1.5	\$180.00
10674		Cab Dust Leaks, noted by Sam at 750hr service.18.05.2023_MWR_WA - Inspect cabin window/doors seals and adjustment. Check for adjustment to rear window. (SM)	19/05/2023		Hours	3.0	3.0	\$374.50
10790		Replace Cab Air Filter.05.06.2023_MWR_WA - Replace 1x Cab Recirc Air Filter (SM)	5/06/2023		Hours	0.5	0.5	\$88.46
10825		AC not Cold.13.06.2023_MWR_SP - REMOVED DEBRIS FROM FRONT COOLER PACK/ CLEANED WITH AIR AND	13/06/2023	940	Hours	2.5	2.5	\$300.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		WATER. REMOVED FILTERS AND CLEANED/ CLEANED EVAPORATOR WITH AIR AND WATER. RAN UP MACHINE AIRCON WAS CONSIDERABLY BETTER (SM)						
	11012	Hyd Oil leak.16.07.2023_MWR_WA - Set up machine for safe access. Remove hydraulic control valve. Reseal fittings and reassemble/fit (SM)15.07.2023_MWR_WA - Inspect hyd oil leak under rear of machine. Found fittings on control valve leaking. Repairs un-safe to complete on-site. Machine will be brought to work shop 16/7/23 for valve removal and repair. If time allows will complete service (SM)	16/07/2023		Hours	5.5	5.5	\$660.00
	11018	Service due at 1000HRS (1027hrs on 16/07) 16.07.2023_MWR_WA - Carry out 1000hr service. Note: not enough gear oil for front diff replacement. JCB gear oil plus used in rear diff/ all final drives done. Shell Spirex used in transmission. JCB hyd oil used in hyd (SM)14.06.2023_Filters & Oil ordered from Terrequeipe (SM)	16/07/2023		Hours	5.0	5.0	\$1,831.75
	11046	Change front diff oil.22.07.2023_MWR_ES - REPLACED DIFF OIL (SM)18.07.2023_Oil in Stock (SM)17.07.2023_20L drum of Oil ordered from Terrequeipe (SM)16.07.2023_Didn't have enough gear oil to change front diff oil at the 1000hr service (SM)	22/07/2023		Hours	1.0	1.0	\$204.35
	11060	MNM Brake Test due.24.07.2023_MWR_SC - Perform brake test, complete, scan and submit paperwork. (SM)	24/07/2023		Hours	0.0	0.5	\$60.00
	11061	GRV Brake Test due.24.07.2023_MWR_SC - Perform brake test, complete, scan and submit paperwork. (SM)	24/07/2023	1037	Hours	0.0	0.5	\$60.00
	11045	Oil Filler Cap left off.03.08.2023_MWR_ES - REPLACED OIL FILTER & CHECKED OIL LEVEL. (SM)22.07.2023_MWR_ES - REPLACED ENG OIL DUE TO FILLER CAP WAS FOUND OFF. OIL FILTER TO BE ORDERED. (SM)	3/08/2023	1071	Hours	1.0	1.0	\$155.31
	11167	Flat Tyre.07.08.2023_MWR_ES/SC - TRAVELLED TO MACHINE, SETUP, REMOVED TYRE, LIFTED INTO UTE. DROPPED OFF AT DISCOUNT TYRES. COLLECTED TYRE, TRAVELLED TO MACHINE, FITTED & MOVED MACHINE OFF THE HIGHWAY MORE. (SM)	7/08/2023	1072	Hours	5.0	7.5	\$900.00
	11208	Flat Tyre.13.08.2023_MWR_WA - Remove and replace rear right tyre. (SM)	13/08/2023		Hours	2.5	2.5	\$3,445.91
	11274	Hyd Hose damaged.24.08.2023_MWR_SC - Operator has damaged hose, took to MHF for replacement. (SM)	24/08/2023		Hours	0.5	0.5	\$60.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	11275	900 Bucket needs New Teeth.MRF7301_MS85_EXP_15.08.2023.24.08.2023_MWR_SC - Replaced GET, 6x 18TVC Teeth & retainers. (SM)	24/08/2023		Hours	0.5	0.5	\$172.68
	11276	900 Bucket needs Pin retainer welded.MRF7301_MS85_EXP_15.08.2023.24.08.2023_MWR_SC - Welded in retainers. (SM)	24/08/2023		Hours	0.5	0.5	\$60.00
	11277	Adjust Rear Boom slack adjuster (needs to have gap to unlock) MRF7301_MS85_EXP_15.08.2023.24.08.2023_MWR_SC - Adjusted wedge for boom. (SM)	24/08/2023		Hours	0.5	0.5	\$60.00
	11307	Error Code flashing.29.08.2023_MWR_SC - Operator advised that error code was flashing, looked on JCB live link, advised that filter was plugged. Cleaned out filters and cooler packs. Code not present. (SM)	29/08/2023		Hours	1.0	1.0	\$120.00
	11322	COLLECTED FIRE EXTINGUISHERS FROM FSI & SWAPPED OUT.31.08.2023_MWR_ES - COLLECTED FIRE EXTINGUISHERS FROM FSI & SWAPPED OUT, 8KG E220 SWAPPED FOR E208, 2KG E235 SWAPPED FOR E250 (SM)	31/08/2023		Hours	0.0	0.5	\$60.00
	11420	Service due at 1250hrs (1184hrs on 13/09).13.09.2023_MWR_SP - Conducted service as per service sheet. Replaced rear axle bolt lhs and torqued to spec. Replaced rear tail light plastic lhs. Repaired fm radio and cleaned cab. Cleaned out cooler packs and air con condenser. Greased machine and inspected under machine. Topped up coolant and hyd oil. Washed machine and prepped for transport south. (SM)	13/09/2023	1184	Hours	8.0	8.0	\$1,356.55

No of W/O for MS85 : 63 Asset Total: MS85 174.5 131.7 \$30,295.62

MS85

JCB 3CX BACKHOE

	11759	Fit BMA Radio.02.11.2023_MWR_WA - Remove Cameby Radio#32 & bracket. Fabricate bracket and fit BMA radio #11 and speaker.	2/11/2023	1187	Hours	1.5	1.5	\$180.00
	11767	NDT Inspection.03.11.2023_MWR_WA - Assist with AIS with NDT inspection on MS85. (SM)	3/11/2023		Hours	0.0	0.5	\$60.00

No of W/O for MS85 : 2 Asset Total: MS85 1.5 2.0 \$240.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
MS85		JCB 3CX BACKHOE						
	11890	MNM Site Intro.15.11.2023_MWR_SC - Perform MNM intro, gather required documents, take photos, complete brake test, complete paperwork, scan and submit. (SM)	15/11/2023	1187	Hours	0.0	2.5	\$300.00
	11891	GRV Site Intro.15.11.2023_MWR_SC - Perform MNM intro, gather required documents, take photos, complete brake test, complete paperwork, scan and submit. (SM)	15/11/2023		Hours	0.0	1.0	\$120.00
	11798	NDT Inspection.08.11.2023_MWR_SP - REPAIRED CRACKS FOUND IN NDT (SM)07.11.2023_NDT Inspection completed by AIS, some Cracks identified on Fork Tine & Bucket for repair (SM)	16/11/2023		Hours	1.5	1.5	\$180.00
	12172	Inspect/repair fuel leak from diesel tank.11.01.2024_MWR_SP - Complete job (SM)10.01.2024_MWR_SP - Remove and start repair on fuel tank (SM)	13/01/2024		Hours	5.0	5.0	\$675.32
	12213	COMP - Anglo GRV Plant & Equipment Statutory Brake Tests.24.02.2024_MWR_SC - Perform brake test, complete, scan and submit paperwork. (SM)	24/02/2024			0.0	0.0	\$120.00
	12540	COMP - Anglo MNM Plant & Equipment Annual Site Introduction.03.03.2024_MWR_SC - Brake test machine, take photos, discussed paperwork with Nikki, new work order should be sent tomorrow. (SM)	4/03/2024			0.0	0.0	\$120.00
	12844	Checkover/Grease prior to site use.10.04.2024_MWR_BD - Check over, greased, blown out air filters, replaced park light, wash down. (SM)	10/04/2024		Hours	0.0	2.5	\$300.72
	12851	COMP - Anglo GRV Plant & Equipment Statutory Brake Tests.13.04.2024_MWR_SC - Perform GRV brake test, complete, scan and submit paperwork. (SM)	13/04/2024			0.0	0.0	\$120.00
	12919	COMP - Anglo MNM Plant & Equipment Statutory Brake Tests	13/04/2024			0.0	0.0	\$0.00
	13233	Prep for Sale. Remove mine radio #11 etc.09.06.2024_MWR_IH - Degrease and pressure wash machine. Truck wash and pressure wash machine. Clean wash pad after machine. Acetone adhesive residue remaining from compliance stickers. Scrape/wipe remaining stickers and residue including from glass. Remove mine radio and MSS first aid kit/snake bite kit. Remount UHF in machine. Brush and blow out interior, clean interior and detail. Clean all machine	10/06/2024		Hours	0.0	7.5	\$1,300.86

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		glass interior and exterior. Cut and polish bonnet (SM)						
	No of W/O for MS85	:	<u>10</u>	Asset Total:	MS85	<u>6.5</u>	<u>20.0</u>	<u>\$3,236.90</u>
	No of W/O for OMRC	:	<u>75</u>	Parent Total:	OMRC	<u>182.5</u>	<u>153.7</u>	<u>\$33,772.52</u>
	Grand Total		<u>75</u>			<u>182.5</u>	<u>153.7</u>	<u>\$33,772.52</u>