Coates Inspection Checklist]
Light Towers									Photos
See Light Tower Photo Log for required pictures Asset # 1113354									
General Information: ***Copy Data Plate information in this section *** Make/ Model Alliant MSGK-9 Engine / Motor - Make / Model CATERPILLAIZ C1.1 Year 2017 Engine Serial Number C3mD2286 Serial Number GIERAMLICLMO9861 Meter Reading 18602 HPS Comments: Beyond Medical Caterpillaiz C1.1									Data Plate
Features: List features or options for the machine:									4-Corner Photos Left-Front Corner
Number of Lights Height of Mast			Wattage per light Generator KVA Phase W/A Amps per outlet				Left-Rear Corner Right-Front Corner Right-Rear Corner Damage Damage		
Overall Appearance:	· · · · · · · · · · · · · · · · · · ·								
Control Station\Operator Station Sheet metal\Fiberglass Condition Paint Lights		Fair	Poor		X I L		NOT	MORKING	
Control Station									Hour Meter
Operator Controls	Operates es No	N/A □	Commer	nts:					Guages Damage Damage
Engine or Electric Motor:									Dight Side head open
Power: Diesel Y Does it start? Did it need to be jumped? Acceptable Power Unusual Noises	Gas es No		Commer					AND BATTERY. VALVE COVER BASE.	Right Side hood open Left Side hood open
Chassis				_	_				
Landing Gear / Outriggers Frame Condition Trailer Lights Trailer Electrical Connections Trailer Brakes Switches Light Tower (Take picture with to Lights (Take picture with lights o Power Cables				Poor	Inoper	Missing		Comments: - FRONT MATRIGGERS ARE STUCK OIL LEAK AT THE LIGHTS TILT CYLINDER SOME MAST LIMIT SWITCHES NEED NEW	Lights on Light Tower (Extended)
Tire Condition:							,		Tire pictures at a 45 degree angle showing the tread and side walls
Enand-NEXEN Size- 205R16C Condition- FAIR	Right Brand- Size- Condition	NEXE 2051	2160						Left Right