

B31 - 2016 DAF FTTXF105

2016 DAF FTTXF105

Unit #: B31
Tag #: 1106HU
Kilometers 959,089Serial #: GG103555
ENGINE NO A243949

Date	Kilometers	Notes	Vendor	Employee	Total Cost
4/10/2021	777,294	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -33DEG			\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
27/10/2021	782,127	NOISY TRANS// REPLACED GEARBOX ZS, AL REPLACED CLUETH FRICTION PLATE REPLACED CLUTCH PRESSURE PLATE REPLACED THROW OUT BEARING REPLACED SPIGOT BEARING REPLACED CLUCH FORK RESEALED POWER STEERING BOX REPLACED TOP AND BOTTOM TRANS COOLANT HOSES REPLACED EXHAUST MAN GASKETS REPLACED SMALL CHARGED COOLER HOSE			\$0.00
Maintenance Performed					Cost
REPAIRS					\$0.00
Total:					\$0.00
25/11/2021	786,719	REPLACED WIPER SWITCH RS #26175 CLEANED + TESTED 12V SOCKET RS CLEANED + TESTED AIR HORNS AL			\$0.00
Maintenance Performed					Cost
REPAIRS					\$0.00
Total:					\$0.00
31/01/2022	797,498	CARRIED OUT 100,000KM SERVICE AL ZS REPLACED OIL AND FILTERS COOLANT -35DEG ADJUSTED VALVES REPLACED TOP TRANS HOSES REPLACED OIL FILL PIPE REPLACED WATERPUMP			\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
18/03/2022	801,317	REPLACED STARTING RELAY AL REPAIRED RADIO			\$0.00
Maintenance Performed					Cost
REPAIRS					\$0.00
Total:					\$0.00

15/06/2022	816,351	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS, RS DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -38DEG	,	\$0.00
------------	---------	---	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

19/12/2022	837,665	CARRIES OUT 20,000KM SERVICE AS PER SERVICE SHEET AL REOLACED OIL AND FILTERS COOLANT -28 DEG REPLACED RH MUD GUARD REPLACED FRONT DRIVE FRONT LEFT AIRBAG REPLACED FRONT DRIVE RH REAR TORQUE ROD BUSH REPAIRED WIRING TO LH DRIVING LIGHT	,	\$0.00
------------	---------	---	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

17/02/2023	859,546	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS DW DID NOT CHANGE OIL OR FILTERS CHANGED COOLANT @-38DEG BLIND SPOT CAMERA NEEDS REPLACING FRONT SEAL LEAKING REPLACED FRONT DRIVE BREAK SHOES AND DRUMS REPLACED R/H SIDE SPOTTER MIRROR REPLACED HEADER TANK REPLACED Y-PEICE HOSE REPLACED SKINNY COOLANT HOSE REPAIRED L/H SIDE DAY LIGHT	,	\$0.00
------------	---------	--	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

18/04/2023	877,639	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS CHANGED ENGINE OIL AND FILTERS BR COOLANT@-38 DEG REPLACED LH INDICATOR CAMERA JS REPLACED LH SUNVISOR BRACKET JS REPLACED FRONT MAIN SEAL JS RESEALED FRONT COVER JS REPLACED BELTS AND TENSIONERS JS REPLACED RADIATOR JS REPLACED RH RADIATOR SUPPORT ROD BR REPLACED REAR LH INDICATOR JS REPLACED REPLACED REAR LH WHEEL SEAL, BEARINGS AND RACES JS REPAIRED FRONT RH SHOCKER UPPER MOUNT JS REPLACED FRONT RH SHOCKER UPPER BUSHES JS	,	\$0.00
------------	---------	--	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

13/07/2023 900,334 CARRIED OUT 100000KM SERVICE AS PER SHEET BR , \$0.00
 DID NOT CHANGE ENGINE OIL OR FILTER
 COOLANT @-38
 REPLACED TURN TABLE JAWS

Maintenance Performed		Cost
SERVICE		\$0.00
ANNUAL CHECK		\$0.00
Total:		\$0.00

30/08/2023 919,852 CARRIED OUT 20,000KM SERVICE AS PER SHEET BC , \$0.00
 CHANGED ENGINE OIL AND FILTERS
 COOLANT @-35 DEG
 =====JOBS DONE=====
 TIGHTENED UP TRANS OIL COOLER
 PLUG
 RE ALINED FUEL TANK
 =====JOBS TO BE DONE=====
 ENGINE MOUNTS
 RH SHACKLE BUSH
 FRONT DRIVE PINION SEAL LEAKING

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

26/10/2023 941,234 CARRIED OUT 20,000KM SERVICE AS PER SHEET JS DW , \$0.00
 DID NOT CHANGE OIL OR FILTERS
 COOLANT@-34 DEG
 REPLACED RH SHACKLE BUSH JS
 REPLACED LH HEADLIGHT PARKER
 GLOBE
 ===JOBS TO BE DONE===
 FRONT DRIVE OUTPUT SHAFT SEAL
 LEAKING
 FRONT DRIVE INPUT SHAFT NEEDS
 RETENSIONING

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

7/02/2024 959,089 CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET JS, AR, DW, BR , \$0.00
 CHANGED ENGINE OIL AND FILTERS
 CHECKED COOLANT -35DEG
 REPLACED L/H STEER CALLIPER WITH
 REBUILT CALLIPER
 REPLACED STEER AXLE BRAKE PADS
 REPLACED FRONT L/H DRIVE LOWER
 SHOCKER RUBBERS
 REPLACED ALL REAR DRIVE SHOCKER
 RUBBERS
 REPLACED CONTOUR PARK LIGHT
 ==JOBS TO BE DONE==
 ENGINE MOUNTS
 RETENSION THROUGH SHAFT PINION

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

Total:	Cost Per Mi/Km/Hr:	\$0.00	\$0.00
---------------	---------------------------	---------------	---------------

Grand Total:	\$0.00
---------------------	---------------