	Boom Lift	ates Inspection Checklist (Electric or Internal Combustion)	
Son Boom Life Burner		(allocation)	Photos
See Boom Lift Photo Log fo	or required pictures	Asset # 1029316	
General Information: *** Copy Data Plate information in this section *** Make/ Model Kubota D1105-ET03 Year 2010 Engine Serial Number Unknown Serial Number 23410-8050 Meter Reading 2027hrs			Data Plate
omments: Disposal due ag	ge - overall condition is fa	ir for its age - basket rotator and slew motor leaking oil -	7
intermittent electrical fault No Other known major fa	with fly jib basket tilt fun- ults with the machine	ction	
eatures:			
rive Syatem 2WD 🗌	4WD ■	Max Lift Height Platform size (L x W) Platform X 760mm	4-Corner Photos Left-Front Corner Left-Rear Corner Right-Front Corner
C Chord to Basket r to Basket Des Basket Rotate Buckle Boom raight Boom	Yes No	Battery Charger Generator Outriggers Extendable axles Articulating Jib	Right-Rear Comer Damage Damage Damage
omments:		, additing oil	
erall Appearance:	Cord -		
ontrol Station\Operator Station eet meta\Fiberglass Condition int int hts N/A	Good Fair	Poor	
erator Controls: Platform erator Controls: Ground uges Operational?		omments:	Hour Meter Ground Controls Basket Controls Guages Damage
gine or Electric Motor:			Damage
ver: Diesel Yes is it start? it need to be jumped? eptable Power sual Noises	No	al Fuel	Right Side hood open Left Side hood open
fraulics			
Operates Yes No pp es nders	-		Pump Cylinders Drive Motor Damage Damage Damage Damage
38is;			
ne Condition / Boom Sections n Extension Wear Guides et Condition ggers and Pads Condition ional Gear Condition idable Axle Table Bearing Play	Good Fair Po	or Inoper Missing N/A Comments: Comments: Slew motor is leaking oil	Rotational Gear Boom (Extended) Basket
Condition: - Front - Trac Chief 10-16.5 tion- Good	Left - Rear Brand- Trac Chief Size- 10-16.5 Condition- Good	Right-Front Right - Rear	Tire pictures at a 45 degree angleshowing the tread and side walls Left-Front Left-Rear Right-Front