

Afloat Slipped



Details

Owner: _____	Policy/Quotation Number: _____
Address: _____	Slipping Date: 24-Feb-21
Telephone No: _____	Inspected At: Noakes Boatyard, Sydney
Email Address: _____	_____
_____	Design: Manhattan 52
Builder: Sunseeker	Rig: N/A
Date Launched: 14-Feb-08	LOA: 15.24m
Construction Material - Hull: GRP	Deck: GRP Keel: N/A

Hull Construction / Condition

	ACCEPT	NON ACCEPT	COMMENTS / DETAILS / DESCRIPTION
Keel	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Keelbolts	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Surface U/W	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Difference in percussion test noted port mid ships to hull, possible prior re
Surface A/W	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Deck	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Cracks noted to swim platform
Cockpit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Coach-house	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Frames	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stringers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Repair noted to stringer under crew bunk, gelcoat chips noted to stringers i
Bulkheads	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Appears sound where accessible
Cabin/Interior	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Wood noted faded
Marine Toilet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Vacuum flush toilet out of order
Seacocks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Skin Fittings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Valves operated
Cockpit Drains	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Cockpit drains recently serviced
Propeller	<input checked="" type="checkbox"/>	<input type="checkbox"/>	4 blade coated in prop speed in good condition
Propeller Shaft	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Good condition coated in prop speed
Propeller Skeg	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Serviceable
Sterngland	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Serviceable
Rudder	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Good condition coated in antifoul
Rudder Mounts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rudder Stock/Gland	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Serviceable
Steering Linkages	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Auxiliary Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Chain Plates	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Stemhead Fitting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Recommendations:

Difference in percussion test noted port mid ships to hull, possible prior repair
Gelcoat cracks noted to bow, recommend repairing
Gelcoat damage noted to stringers in engine bay, recommend repairing

Motor Installation / Condition

PETROL: DIESEL: INBOARD: OUTBOARD: STERN DRIVE: JET:
 BRAND: **Volvo** MODEL No.: **D12D-D MP** SERIAL No.: **See Below** H.P.: **800** AGE **2008**

	ACCEPT	NON ACCEPT	COMMENTS / DETAILS / DESCRIPTION
Installation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Original install
Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Electronic controls
Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Original install
Fuel Lines/Fittings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Tanks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2x Stainless tanks fitted, capacity 1070L each
Filler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Good condition
Venting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Connection & Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Electrical Harness	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Electrical Fitting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stove	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Gas Bottles	<input type="checkbox"/>	<input type="checkbox"/>	Inc. Gas Compliance Plate No.: _____ N/A
Connection & Lines	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Position	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Venting	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Gas Detector	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Batteries	<input checked="" type="checkbox"/>	<input type="checkbox"/>	10x N70s located between engines, passed load test
Mounting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Bilge Pump - Manual	<input type="checkbox"/>	<input type="checkbox"/>	
- Electrical	<input checked="" type="checkbox"/>	<input type="checkbox"/>	4x Pumps fitted

Recommendations:

Engines showing error code, further diagnosis and repair required
Could not obtain HIN number as vessel has been wrapped

Engine serials - Starboard: 1012637737 Port: 1012637738

Mast / Spars / Rigging & Sails

MAST MATERIAL: ALUMINUM: TIMBER: CARBON: OTHER: _____

	ACCEPT	NON ACCEPT	COMMENTS / DETAILS / DESCRIPTION
Masts	<input type="checkbox"/>	<input type="checkbox"/>	TYPE: <input type="checkbox"/> MASTHEAD <input type="checkbox"/> FRACTIONAL How Old? _____ When last serviced? _____
Mast Step	<input type="checkbox"/>	<input type="checkbox"/>	
Boom/s	<input type="checkbox"/>	<input type="checkbox"/>	
Spin Pole/Jockey Pole	<input type="checkbox"/>	<input type="checkbox"/>	
Rigging	<input type="checkbox"/>	<input type="checkbox"/>	Rod: _____ Wire: _____ Age: _____
Spreaders	<input type="checkbox"/>	<input type="checkbox"/>	No Of: _____ Inline: _____ Swept Back: _____
Base Attachments	<input type="checkbox"/>	<input type="checkbox"/>	
Chain Plates	<input type="checkbox"/>	<input type="checkbox"/>	
Hydraulics	<input type="checkbox"/>	<input type="checkbox"/>	

Mast / Spars / Rigging & Sails Cont'd

Sail Inventory:

Sail Age:

Sail Conditions:

Date Mast &/or Rigging last serviced _____ & by whom: _____

Safety Equipment

	ACCEPT	NON ACCEPT	COMMENTS / DETAILS / DESCRIPTION
Anchor & Warp	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Fair condition
Flares	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fire Extinguisher	<input checked="" type="checkbox"/>	<input type="checkbox"/>	4x Fire Extinguishers onboard
Spot Light	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Motor turning, bulb out of order
Life Jackets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	12 Adults, 2 Childs
Navigation Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Life Raft	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Pulpits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Pushpits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Staunchions/Lifelines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Recommendations:

Recommend purchasing EPIRB

General Remarks & Recommendations

RESTRICTED WATERS

OPEN WATERS

Heavy corrosion noted to swim platform and steering system hydraulics, recommend servicing European GPO plugs fitted to vessel

DISCLAIMER:

It is to be clearly understood that the condition/state of items hereafter reported upon are strictly the opinion of the undersigned and that opinion reflects the condition/state found on 24-Feb-21, taking into consideration the vessel's age and that items reported upon are described in comparison with vessels of similar age and type. This report has been prepared specifically for Steve Tsakos, on 24-Feb-21, and is for their use only. Copies in whole or in part should not be released to, or consulted by, other parties without the express prior permission of BoatBuy Pty Ltd. Whilst all due care and diligence has been exercised in the collection of data for and the preparation of this report, BoatBuy Pty Ltd purports to provide an advisory service only, based on the opinion and experience of the individual consultant responsible for its compilation. BoatBuy Pty Ltd issues such advice in good faith and without prejudice or guarantee. Anyone wishing to rely on such opinion should first satisfy himself as to its accuracy and feasibility. BoatBuy Pty Ltd shall not be liable for any loss (including indirect and consequential loss), damage, delay, and loss of market, costs, expenses of whatsoever nature or kind and however sustained or occasioned. Notwithstanding the aforementioned, notice of a claim or suit must be made to BoatBuy Pty Ltd in writing within 90 days of the date the services were first performed or the date the damages were first discovered, whichever is the later, failing which lack of notice shall constitute an absolute bar to the claim or suit against BoatBuy Pty Ltd.

This survey is a factual report on the inspection carried out, and the opinions expressed are given in good faith as to the condition of the vessel as seen at the time of the survey. It implies no guarantee, no safeguard against latent defects, subsequent defects, or defects not discovered at the time of the survey in woodwork or areas of the vessel which are covered, unexposed, or not accessible to the surveyor internally due to the installation of non-removable linings, panels and internal structures, etc. This is a visual survey only. BoatBuy Pty Ltd accepts no responsibility or liability in relation to any part of the vessel, which cannot be accessed or viewed. Parts of the vessel were not accessed or viewed and therefore we cannot comment on this in relation to any patent or latent damage, including termite or other insect infestation. This report carries no warranty regarding ownership of the vessel or any warranty regarding outstanding mortgage, charge or other debt there may be on the vessel. This survey is personal and confidential to our client and has no extended warranty if disposed of to a third party for any purpose without the permission of BoatBuy Pty Ltd. This report does not address stability, vessel performance or overall design, and no warranty is conveyed under these headings. These standard trading terms, all agreements and disputes relating thereto, shall be governed by and interpreted in accordance with Australian Law. Liability is limited to five times the surveyor's fees for the inspection of this vessel.

Name: **Aaron O'Donoghue** Signature:  Date: **24-Feb-21**

Email Address: **info@boatbuy.com.au** Contact Number: **(02) 9188 5182**



BoatBuy Pty Ltd
 Ph. (02) 9188 5182
 Email: info@boatbuy.com.au
 Mail: PO Box 8028, Seven Hills, 2147, NSW
 ABN 62 607 039 154

