



Vehicle History Summary



| | |
|-----------------|-------------------|
| Fleet # | 123 |
| Registration | KST95 |
| Make | Kenworth |
| Model | K200 |
| VIN / Chassis # | 6F5000000LA467923 |
| Build Date | 2020 |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|--------|-------|--|---|-------------------------------|
| S-5164 | 19/11/2022 | 411155 | | A - 30 Days | | Kelvyn Fuller |
| S-5143 | 12/11/2022 | 406338 | 0 | A - 30 Days | | Colin Scott |
| R-2151 | 20/10/2022 | 391332 | 0 | ELECTRICIAL | REMOVE AND REPLACE FAULTY DRIVING LAMPS + DL9120SEC DRIVING LIGHT 120W 9" CHROME FACE PAIR 1.00 866.00 EACH 866.00 DL9120LC LED DRIVING LIGHT COVERS CLEAR 2.00 40.00 EACH 80.00 ERS ENVIRONMENTAL LEVY 1.00 17.50 EACH 17.50 S4 WORKSHOP SUNDRIES 1.00 49.00 EACH 49.00 T14 CABLE, 4MM SINGLE CORE COLOURED 2.00 0.90 METRE 1.80 0964555200 DEUTSCH TERMINALS & PLUGS 5.00 4.50 EACH 22.50 | SH&M Fuller Transport Repairs |
| S-5046 | 13/10/2022 | 387249 | 0 | B - 50k | | SH&M Fuller Transport Repairs |
| S-5080 | 07/10/2022 | 385151 | | A - 30 Days | | Kelvyn Fuller |
| T-1460 | 17/09/2022 | 0 | 0 | Rotate | Steer Rotation | Tyreright |
| R-2140 | 14/09/2022 | 0 | 0 | Air Conditioner | locate faulty dash unit. fit spare unit until unit repaired. | ROTHALE PTY LTD |
| S-4991 | 10/09/2022 | 366607 | 0 | A - 30 Days | | Colin Scott |
| I-61 | 05/09/2022 | 362719 | 0 | HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS | | |
| S-4984 | 27/08/2022 | 362719 | 0 | C - Annual | | Brown & Hurley |
| R-2117 | 26/08/2022 | 0 | 0 | TRANSMISSION | REPLACE TRANSMISSION OIL AND DIFF OILS | Brown & Hurley |
| S-4970 | 18/08/2022 | 361519 | 0 | A - 30 Days | | Colin Scott |
| S-4851 | 16/07/2022 | 343632 | 0 | A - 30 Days | | Colin Scott |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|--------|-------|--|---|-------------------------------|
| S-4807 | 15/06/2022 | 316119 | 0 | B - 50k | R & R FUEL STRAPS TIGHTEN PULLY BRACKET BOLTS, TURBO BRACKET BOLTS. TOP UP POWER STEERING | SH&M Fuller Transport Repairs |
| S-4689 | 16/04/2022 | 288804 | 0 | A - 30 Days | | Colin Scott |
| T-1383 | 05/04/2022 | 0 | 0 | FIT NEW | 2 NEW TYRES, 2 TYRES STRIP AND FIT | Tyreright |
| T-1373 | 30/03/2022 | 0 | 0 | Fit & Balance, FIT NEW | | Tyreright |
| S-4635 | 21/03/2022 | 273196 | 0 | A - 30 Days | D-Steering - Pitman arm - Moving on sector shaft Defect Notice D 845958 3 Robert Fisher - Yaamba NCR - 58 | Colin Scott |
| S-4641 | 18/03/2022 | 271840 | 0 | A - 30 Days | | Colin Scott |
| S-4561 | 17/02/2022 | 257034 | 0 | B - 50k | | Colin Scott |
| T-1372 | 15/02/2022 | 0 | 0 | STRIP & FIT | | Tyreright |
| S-4442 | 27/01/2022 | 244471 | 0 | A - 30 Days | | Colin Scott |
| S-4294 | 13/01/2022 | 224041 | 0 | A - 30 Days | | Colin Scott |
| S-4208 | 16/12/2021 | 217537 | 0 | A - 30 Days | | Colin Scott |
| T-1316 | 09/12/2021 | 0 | 0 | Puncture | 1 PUNCTURE | Tyreright |
| S-4198 | 04/11/2021 | 196892 | 0 | B - 50k | | Colin Scott |
| T-1292 | 19/10/2021 | 0 | 0 | Balance | | Tyreright |
| T-1291 | 19/10/2021 | 0 | 0 | STIP & FIT | | Tyreright |
| S-4172 | 18/09/2021 | 160249 | 0 | A - 30 Days | | Colin Scott |
| S-3212 | 04/09/2021 | 153444 | 0 | C - Annual | | Colin Scott |
| I-16 | 04/09/2021 | 153444 | 0 | HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS | | Colin Scott |
| S-3225 | 07/08/2021 | 136327 | 0 | B - 50k | | Colin Scott |
| S-3224 | 07/08/2021 | 136327 | 0 | A - 30 Days | | Colin Scott |
| R-1994 | 21/07/2021 | 0 | 0 | Brakes Reline | BRAKE ROLLER TEST | SH&M Fuller |
| T-1254 | 16/07/2021 | | | Rotate | | Tyreright |
| T-1253 | 16/07/2021 | | | STIP & FLIP | | Tyreright |
| R-1495 | 09/07/2021 | | | MISC | BREAKDOWN FOUND NUMEROUS CODES . CHECKED BATTERY TERMINALS AND ALL FUSES ON VEHICLE. FOUND LOOSE TERMINAL AT ISOLATOR SWITCH. TIGHTEN UP TILT BULL BAR AND CAB. CHECKED ALL FUSES ON ENGINE. CLEARED CODES CARRY OUT 40 MIN TEST DRIVE. FOUND TO CODE UP ONCE ON KSM. | PENSKE POWER SYSTEMS |
| S-4140 | 03/07/2021 | 119126 | 0 | A - 30 Days | | Colin Scott |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|--------|-------|---------------|--|----------------|
| R-1343 | 23/06/2021 | 110967 | | Body | REPAIR L/H CABIN STEP SUPPORT R & R SUPPLIED STEERING WHEEL FIT GRILL OVER INTERNAL VENT | SH&M Fuller |
| S-3121 | 19/03/2021 | 105636 | 0 | A - 30 Days | | Colin Scott |
| T-1130 | 13/03/2021 | | | Rotate | | TYRE EVOLUTION |
| T-1131 | 13/03/2021 | | | Pressure Test | | TYRE EVOLUTION |
| S-4246 | 11/03/2021 | 101824 | 0 | B - 50k | | Colin Scott |
| S-3624 | 19/02/2021 | 90582 | 0 | A - 30 Days | | Colin Scott |
| S-3625 | 22/01/2021 | 77644 | 0 | A - 30 Days | | Colin Scott |
| R-1242 | 22/01/2021 | 94127 | | EXHAUST | R & R EXHUAST STACK SUPPLIED MODIFY SUPPORT BRACKET AND PAINT | SH&M Fuller |
| S-3195 | 04/12/2020 | 50933 | 0 | B - 50k | | Kelvyn Fuller |

Signed: _____

Name: _____

Date: _____