Pre - Divestment Check list for Portable Buildings, Complexes and Toilet blocks

rspection Report:	Asset Détails:		
čey:	Date Inspected: 1218	Asset Number: 1099697	Inspected by: TROY
X = Considered Unsafe C = Changed	Manufactiirer (If known) / Make / Model: 12×3 Bull DING		Branch: ATHE
re-Sale / Pre-Transit Checks:			
Rails & Joists — Ensure all intact and secure for transport Lifting Lugs, Brackets, Frame, Tie Down points — Ensure Plumbing & Cabling — No loose or broken plumbing or conveil, roof & chassis fitment — Ensure building securely fixed Signage — Ensure all Coates signs and decals are removed Roof debris — Ensure no debris or loose materials on roof. Gutters & downpipes — Ensure all securely fixed to building	ure all inlact and secure for trai cabiling hanging off the unders ad to chassis, rivets secured to b prior to transporting. Asset num	ide of the building of comple pase channel, wall & roof flash	, pings.
External: Windows, Doors & Steps – Ensure all secured for transpose. Security Bars & Screens – Where filled, ensure all closed and secured to the secure of the secure o	ured for transport.		
Internal: Electrical – Ensure the switchboard door and all electric Light Diffusers / Cages – Where filled; ensure all secur	ed :		Qanger" elecifical sticker.
Complexes: \[\frac{A}{D} \] Complex Modules – Ensure âll modules have sufficient	bracing filled for transport.		
Disclaimer: So as to remove the threat of any potential legal action against Coa The equipment is being bought in unserviceable condition it hazardous to the health and safety of persons in any environme This check list report is purely a visual inspection of the equipm Assessment of the equipment prior to collection and any associ Full responsibility for determining what service, testing or modif Australian Standards and OH&S regulations applicable in the S	hat has not been tested or ent in which it's being used, ent and is by no means a contact transport thereof is the so- lated transport thereof is the so- lications are needed for the ec-	examined to determine with aprehensive structural asses ole responsibility of the Buyo adipment to ensure its compl	emer its use may be sment of such. er.
Signed for and on behalf of Coates Hire:			, ,
Name: Teoy si	ignalure;	Dale:	12/6/24
Signed for and on behalf of the Buyer:			
Name: Šī	ignalure;	Date	