

B34 - 2017 DAF FTTXF105

2017 DAF FTTXF105

Unit #: B34
Tag #: 11O6ID
Kilometers 887,249Serial #: GG111829
ENGINE NO A250419

Date	Kilometers	Notes	Vendor	Employee	Total Cost
8/12/2021	700,683	CARRIED OUT 100,000KM SERVICE AS PER SERVICE SHEET JI, ZS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -35DEG REPLACED REAR DRIVE S-CAM BUSHES REPLACED FRONT L/H DRIVE TORQUE ROD BUSH	,		\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
22/02/2022	722,159	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -38DEG REPLACED REAR DRIVE BRAKE SHOES AND DRUM	,		\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
27/07/2022	741,224	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET AL REPLACED OIL AND FILTERS COOLANT- 41DEG REPLACED MISSING LH SPOT MIRROR COVER REPLACED DRIVERS SIDE DOOR CONTROL REPLACED HEATER HOSES JS REPLACED WATER PUMP ZS JS REPLACED OIL FILL HOSE JS REPLACED LH MUDGUARD JS	,		\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
29/11/2022	762,698	CARRY OUT 20,000KM SERVICE AS PER SERVICE SHEET AL, RS DID NOT CHANGE ENGINE OIL AND FILTERS REPLACED REAR RH SLACK ADJUSTER REPLACED REAR LH HUB SEAL AND BEARINGS	,		\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
20/12/2022	775,744	REPLACED RH SPOTTER MIRROR ASSEM	,		\$0.00

Maintenance Performed			Cost
REPAIRS			\$0.00
Total:			\$0.00
11/01/2023	782,309	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JS DW CHANGED ENGINE OIL AND FILTERS COOLANT @-37DEG REPLACED FRONT CRANKSHAFT SEAL RESEALED FRONT COVER (HEADER TANK SLIGHTLY LEAKING)	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
8/03/2023	801,779	CARRIED OUT 100,000KM SERVICE AS PER SHEET DW ZS DID NOT CHANGE OIL OR FILTERS COOLANT @41DEG	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
ANNUAL CHECK			\$0.00
Total:			\$0.00
6/05/2023	824,483	CARRIED OUT 20,000KM SERVICE AS PER SHEET ZS CHANGED ENGINE OIL AND FILTERS COOLANT @-38DEG	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
1/07/2023	850,282	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS BR DID NOT CHANGE ENGINE OIL OR FILTERS COOLANT@-41 REPLACED NOX SENSOR AFTER CAT ===TRUCK TO RETURN FOR=== HEATER HOSE LEAKS ENGINE MOUNTS	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
16/08/2023	866,589	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS MY CHANGED ENGINE OIL AND FILTERS COOLANT @-41 REPLACED ENGINE MOUNTS REPLACED COOLANT HEADER TANK MY	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
16/11/2023	879,498	REVERSE LIGHTS AND BEEPER FUSE BLOWN BC DRIVERS SIDE WIPER BLADE EXHAST WARNING WAS NOT PRESENT	\$0.00

Maintenance Performed		Cost
REPAIRS		\$0.00
Total:		\$0.00

2/12/2023	880,411	REPLACED NOX SENSOR BEFORE CAT JS BR	\$0.00
-----------	---------	--------------------------------------	--------

Maintenance Performed		Cost
REPAIRS		\$0.00
Total:		\$0.00

23/01/2024	887,249	CARRIED OUT 20,000KM SEVICE AS PER SHEET JS BR DID NOT CHANGE ENGINE OIL OR FILTERS COOLANT@-40 DEG ADJUSTED RH WIPER ARM HEIGHT JS REPAIRED HEADLIGHT WIRING JS	\$0.00
------------	---------	--	--------

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

Total:	Cost Per Mi/Km/Hr:	\$0.00	\$0.00
---------------	---------------------------	---------------	---------------

Grand Total:	\$0.00
---------------------	---------------