

B33 - 2017 DAF FTTXF105

2017 DAF FTTXF105

Unit #: B33

Serial #: GG111821

Tag #: 11O6IC

ENGINE NO A250415

Kilometers 936,462

Date	Kilometers	Notes	Vendor	Employee	Total Cost
30/09/2021	712,041	REPAIRED R/H DAYLIGHT WIRING ZS BLEW OUT WIPER SPRAYERS TESTED MIRRORS - SERVICABLE	,		\$0.00
Maintenance Performed				Cost	
REPAIRS				\$0.00	
				Total:	\$0.00
26/10/2021	723,388	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -35DEG REPLACED REAR L/H DRIVE SHOCKER	,		\$0.00
Maintenance Performed				Cost	
SERVICE				\$0.00	
				Total:	\$0.00
23/12/2021	745,498	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET AL, ZS DID NOT CHANGE ENGINE OIL AND FILTERS CHECKED COOLANT -32DEG ADJUSTED FRONT L/H DRIVE WHEEL BEARING REPLACED BELTS REPLACED REAR R/H SHOCKER REPLACED REAR R/H S-CAM BUSHES	,		\$0.00
Maintenance Performed				Cost	
SERVICE				\$0.00	
				Total:	\$0.00
6/01/2022	750,830	#27862 RS CHARGED HOUSE BATTERIES + CLEANED CAB COOLER VENTS TIGHTENED ADBLUE SPOUT + REPLACED CAP	,		\$0.00
Maintenance Performed				Cost	
REPAIRS				\$0.00	
				Total:	\$0.00
14/02/2022	763,956	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI, RS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -35DEG CLEANED OUT FRONT DIFF BREATHER, LEAKING INPUT TENSIONED SUMP BOLTS	,		\$0.00
Maintenance Performed				Cost	
SERVICE				\$0.00	
				Total:	\$0.00
5/04/2022	784,287		,		\$0.00

CARRIED OUT 20,000KM SERVICE AS
 PER SERVICE SHEET
 DID NOT CHANGE OIL OR FILTERS
 COOLANT -35 DEG
 REATTACHED DRIVERS CAMERA
 ==NOTE==
 DRIVERS WINDOW SWITCH BROKEN

		Maintenance Performed		Cost
		SERVICE		\$0.00
			Total:	\$0.00
2/08/2022	788,163	REPLACED INDICATOR STALK AL JS	,	\$0.00
		Maintenance Performed		Cost
		REPAIRS		\$0.00
			Total:	\$0.00
14/11/2022	788,163	REPLACED SERVICE BRAKE SUSI COIL ZS REFITTED MISSING FUEL CAP	,	\$0.00
		Maintenance Performed		Cost
		REPAIRS		\$0.00
			Total:	\$0.00
6/01/2023	813,059	CARRIED OUT 100,000 KM SERVICE AS PER SERVICE SHEET JS DW CHANGED ENGINE OIL AND FILTERS COOLANT@-35DEG ADJUSTED TAPPETS	,	\$0.00
		Maintenance Performed		Cost
		SERVICE		\$0.00
		ANNUAL CHECK		\$0.00
			Total:	\$0.00
6/02/2023	827,094	REPLACED TURN TABLE LOCKING JAW JS RS	,	\$0.00
		Maintenance Performed		Cost
		REPAIRS		\$0.00
			Total:	\$0.00
20/02/2023	831,535	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS DW DID NOT CHANGE ENGINE OIL OR FILTERS COOLANT@-33 DEG REPLACED FRONT DRIVE RH BOTTOM SHOCKER RUBBERS SUMP LEAK IN REAR	,	\$0.00
		Maintenance Performed		Cost
		SERVICE		\$0.00
			Total:	\$0.00
24/03/2023	840,658	REPLACED COOLANT BLEED HOSE ZS REPLACED COOLANT DW	,	\$0.00
		Maintenance Performed		Cost
		REPAIRS		\$0.00
			Total:	\$0.00
6/06/2023	856,613	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS CHANGED ENGINE OIL AND FILTERS JS	,	\$0.00

REPLACED SUMP GASKET JS
TIGHTEND FRONT DIFF OUTPUT SHAFT
JS
REPLACED FRONT DIFF INPUT SHAFT
SEALS JS ZS
REPLACED BELTS AND TENSIONERS JS
ZS
REPLACED REAR LH SHOCKER
RUBBERS JS
REPLACED TURN TABLE WEAR PADS JS
REPLACED BOTH ENGINE MOUNTS JS
BR
REPLACED INTERCOOLER TORQUE ROD
JS
REPLACED LH STEER MUDGUARD JS

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

8/08/2023	878,332	CARRIED OUT 20,000KM SERVICE AS PER SHEET BR DID NOT CHANGE ENGINE OIL OR FILTERS COOLANT @-40 ADJUST RH FRONT DRIVE WB ADJSUT RH REAR DRIVE WB ENGINE REQUIRED 9 LTR TOP UP CHECK NEXT SERICE FOR OIL CONSUMPTION	\$0.00
-----------	---------	--	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

20/09/2023	897,334	CARRIED OUT 100,00KM SERVICE AS PER SHEET JS DW CHANGED ENGINE OIL AND FILTERS DW REPLACED COOLANT JS REPLACED FRONT LH TORSION ROD BUSH JS REPLACED SMALL POWER STEERING HOSE DW REPLACED POWER STEERING FLUID+FILTER DW REPLACED LIGHT PLUG DW ===JOBS TO BE DONE=== SUMP LEAKING RH KING PIN	\$0.00
------------	---------	--	--------

Maintenance Performed	Cost
SERVICE	\$0.00
ANNUAL CHECK	\$0.00
Total:	\$0.00

15/11/2023	919,901	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC DIDNT CHANGE ENGINE OIL AND FILTERS COOLANT @-40 DEG REPLACED HEADER TANK AND SMALL WATER PUMP HOSE REPLACED RH FRONT DRIVE BRAKE SHOES AND DRUMS REPLACED BOOST PRESSURE SENSOR REPLACED ADDBLUE TANK LEVEL SENSOR WITH SECOND HAND ONE	\$0.00
------------	---------	--	--------

Maintenance Performed			Cost
SERVICE			\$0.00
			Total: \$0.00
8/01/2024	932,490	REPLACED LH REAR DRIVE SHOES AND DRUM BC ADJUSTED ALL DRIVE BRAKES	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
			Total: \$0.00
24/01/2024	936,377	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET JS, BC, DW, AR CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -33DEG =JOBS COMPLETED= REPLACED RADIATOR REPLACED COOLANT FILTER REPLACED BOTH SHACKLE BUSHES REPLACED L/H INDICATOR RESISTOR	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
			Total: \$0.00
2/02/2024	936,462	REPLACED DRIVERS WINDOW REGULATOR DW REPLACED DRIVERS DOOR HANDLE CONTROLLER	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
			Total: \$0.00
Total:		Cost Per Mi/Km/Hr:	\$0.00
Grand Total:			\$0.00