



Sydney: 6/34 Yarrunga Steet Prestons NSW 2170  
 ABN: 27 000 761 259

**WORKSHOP TAX INVOICE**

Invoice To :

201323  
 IMMS (INTERSTATE MOTOR MARKETI  
 PO BOX 261  
  
 CAMDEN NSW 2570

Page no.....: 1

Invoice number...: 7499642 - 002200  
 Invoice Date.....: 31/08/22

Customer Ref.....: X053IX

Due Date.....:  
 Terms.....: NET 30 DAYS (A)

Our reference....: 7499642 - 002200  
 Advisor was.....:  
 James Di Bella

Remarks.....:

**Vehicle Details**

Reg Number: X053IX MACK (1) CMH 6\*4  
 Chassis No: 803960  
 Odometer..: 1,521,587 Engine Hrs: 30,805  
 Contract...:  
 VIN .....: 6FMM12H69CD803960  
 Fleet .....

Operation /Part Number	Description	List Price	Nett Price	--Quantity-- Invced B/Ord	Amount
	SAME FAULT AS BEFORE				
Subtotal: 001 Order Job 001:					0.00
210	DIAGNOSE ENGINE CUTTING OUT CONNECT LAPTOP AND CHECK FAULTS. CARRY OUT SENSOR MONITORING, CRANKCASE PRESSURE SENSOR NOT READING. REPLACE CRANKCASE PRESSURE SENSOR, NOW IT IS READING, VISUALLY INSPECT WIRING. NOTE: UPPER TIMING COVER LEAKING. TOP UP COOLANT AND PRESSURE TEST SYSTEM, FOUND COOLANT LEAK AT HOSE CLAMP ABOVE WATER PUMP. REPLACE CLAMP AND PRESSURE TEST, ALL OKAY				
VO 21634017	CRANKCASE PRESS	262.55	242.86	1.0	242.86
VO 994559	HOSE CLAMP	3.20	2.80	1.0	2.80
Subtotal: 002 Order Job 002:					245.66
430	GEARBOX REMOVE/REFIT CONNECT LAPTOP AND CHECK FAULTS Gearbox TECU (MID 130) PSID 24 - Range engagement system; FMI 1 Gearbox TECU (MID 130) PSID 24 - Range engagement system; FMI 0 REMOVE GEARBOX AND CONTROL HOUSING FOR INSPECTION, SPLITTER STOP BRACKET BROKEN, 3RD GEAR ON MAIN SHAFT DAMAGED. NEED TO DROP GEARBOX AND DISMANTLE FOR FULL EXTENT OF DAMAGE.				
Subtotal: 003 Order Job 003:					326.00
430	GEARBOX STRIP/INSPECT/REPAIR				1100.00

Sydney West	Sydney	Newcastle	Brisbane South	Brisbane North	Gold Coast
9 Oatley Close Blacktown NSW 2148 Phone (02) 9678 2000 Fax (02) 9678 2088 www.vcvsydneywest.com.au	6/34 Yarrunga Street Prestons NSW 2170 Phone (02) 9731 8600 Fax (02) 9731 8699 www.vcvsydney.com.au	8 Birraba Avenue, Beresfield NSW 2322 Phone (02) 4922 2600 Fax (02) 4966 1755 www.vcvnewcastle.com.au	41 Bivouac Place Wacol QLD 4076 Phone (07) 3710 3710 Fax (07) 3718 3408 www.vcvbrisbane.com.au	650 Macarthur Ave Pinkenba 4008 Phone (07) 3710 3710 Fax (07) 3260 1997	107 Spencer Rd Carrara QLD 4211 Phone (07) 5596 3972 Fax (07) 5596 4630



Sydney: 6/34 Yarrunga Steet Prestons NSW 2170  
 ABN: 27 000 761 259

**WORKSHOP TAX INVOICE**

Invoice To :

Page no.....: 2

201323  
 IMMS (INTERSTATE MOTOR MARKETI  
 PO BOX 261  
  
 CAMDEN NSW 2570

Invoice number...: 7499642 - 002200  
 Invoice Date.....: 31/08/22  
 Customer Ref.....: XO53IX

Operation /Part Number	Description	List Price	Nett Price	--Quantity-- Invced B/Ord	Amount
	REMOVE PTO, TAILSHAFT, GEARBOX HARNESS, GEARBOX COOLER LINES, DISCONNECT GEARBOX AIR TANK, FUEL CROSS OVER BRACKET. REMOVE GEARBOX, LID AND SELECTOR FORK DUE TO AIR LEAK, WORN GASKETS. REPLACE INTERNAL WIRING HARNESS AND GASKETS, TENSION ALL MOUNTING BOLTS TO SPEC. CONNECT LAPTOP AND CALIBRATE GEARBOX.. FILL GEARBOX OIL, REMOUNT PWM VALVE. REFIT GEARBOX AND ALL REMOVED COMPONENTS. REPLACE X2 BOLTS AT FRONT OF GEARBOX. ROAD TEST VEHICLE FOR ENGINE CUTTING OUT AND GEARBOX FAULT				
	NOTE: FOUND ACTIVE FAULT FOR PTO, LIGHTNING BOLT ON DASH.				
VO 22901068	FLANGE SCREW	7.60	6.84	4.0	27.36
VO 990971	HEXAGON NUT	3.13	2.74	4.0	10.96
VO 20930114	FLANGE SCREW SP	3.90	3.41	4.0	13.65
VO 20785252	KIT LID GASKET	288.48	279.83	1.0	279.83
VO 22117441	WIRING HARNESS	942.20	871.53	1.0	871.54
AU2 WUR0890117	BRAKE CLEANER S	6.27	5.80	2.0	11.60
VO 949647	O-RING,99.5MM I	17.76	15.54	1.0	15.54
VO 23166990	STOP BRACKET	68.32	59.78	1.0	59.78
	Subtotal: 004 Order Job 004:				2390.26
91	WORKSHOP CONSUMABLES				92.69
					-----
					Sub Total Parts...: 1535.92
					Sub Total Labour...: 1426.00
					Sub Total Other...: 92.69
					GST.....: 305.47
					=====
					T O T A L 3360.08
					=====

Sydney West	Sydney	Newcastle	Brisbane South	Brisbane North	Gold Coast
9 Oatley Close Blacktown NSW 2148 Phone (02) 9678 2000 Fax (02) 9678 2088 www.vcvsydneywest.com.au	6/34 Yarrunga Street Prestons NSW 2170 Phone (02) 9731 8600 Fax (02) 9731 8699 www.vcvsydney.com.au	8 Birraba Avenue, Beresfield NSW 2322 Phone (02) 4922 2600 Fax (02) 4966 1755 www.vcvnewcastle.com.au	41 Bivouac Place Wacol QLD 4076 Phone (07) 3710 3710 Fax (07) 3718 3408 www.vcvbrlsbane.com.au	650 Macarthur Ave Pinkenba 4008 Phone (07) 3710 3710 Fax (07) 3260 1997	107 Spencer Rd Carrara QLD 4211 Phone (07) 5596 3972 Fax (07) 5596 4630



Sydney: 6/34 Yarrunga Steet Prestons NSW 2170  
 ABN: 27 000 761 259

**WORKSHOP TAX INVOICE**

Invoice To :

201323  
 IMMS (INTERSTATE MOTOR MARKETI  
 PO BOX 261  
  
 CAMDEN NSW 2570

Page no.....: 1

Invoice number...: 7498276 - 002200  
 Invoice Date.....: 31/08/22

Customer Ref.....: X053IX

Due Date.....:  
 Terms.....: NET 30 DAYS (A)

Our reference....: 7498276 - 002200

Advisor was.....:

Nicole Totora

Remarks.....:

**Vehicle Details**

Reg Number: X053IX MACK (1) CMH 6\*4  
 Chassis No: 803960  
 Odometer...: 1,517,852 Engine Hrs: 0  
 Contract...:  
 VIN .....: 6FMM12H69CD803960  
 Fleet .....

Operation /Part Number	Description	List Price	Nett Price	--Quantity-- Invced B/Ord	Amount
	HOURS -				
	CONTACT - STEVE 0412 242 233				
	DRIVER JAMES 0488771903				
	NO REGO ON THE VEHICLE				
Subtotal: 001 Order Job 001:					0.00
210	CHECK AND REPORT ON VEHICLE SHUTTING DOWN				275.00
	PLEASE SEE ATTACHED EMAIL AND PREVIOUS WORK DONE TO THIS				
Subtotal: 002 Order Job 002:					275.00
210	CARRY OUT BEARING ROLL AS PER QUOTE AND CUSTOMER REQUEST				685.00
VO 20824906	OIL PUMP	2398.81	2098.96	1.0	2098.96
VO 22275838	SEALING RING	10.58	9.52	2.0	19.04
VO 21092243	SEALING RING	14.76	13.28	7.0	92.99
VO 23624058	MAIN BEARING KI	59.38	53.44	7.0	374.09
VO 21293367	SEALING STRIP	121.41	109.27	1.0	109.27
VO 21948261	THRUST WASHER	62.07	55.86	1.0	55.86
EX-MINTO					
AU2 AMP23068346	VOLVO ENGINE OI	6.24	5.77	38.0	219.34
VO 948211	CABLE TIE 4.6X2	0.46	0.40	15.0	6.04
VO 980464	CABLE TIE 7.6X3	0.95	0.83	15.0	12.47
VO 1161963	FETT GREASE	5.95	5.83	1.0	5.83
AU2 WUR0890117	BRAKE CLEANER S	6.16	5.70	2.0	11.40
VO 85114535	FILTER KIT MP8	270.91	237.05	1.0	237.05
VO 24049962	BIG-END BEARING	63.93	57.54	6.0	345.22
EX-MINTO					
VO 20462497	FLANGE - OIL FI	61.31	53.65	1.0	53.65
VO 21780376	SEALING RING PU	6.32	5.69	1.0	5.69

<b>Sydney West</b> 9 Oatley Close Blacktown NSW 2148 Phone (02) 9678 2000 Fax (02) 9678 2088 www.vcvsydneywest.com.au <small>THP041_V2</small>	<b>Sydney</b> 6/34 Yarrunga Street Prestons NSW 2170 Phone (02) 9731 8600 Fax (02) 9731 8699 www.vcvsydney.com.au	<b>Newcastle</b> 8 Birraba Avenue, Beresfield NSW 2322 Phone (02) 4922 2600 Fax (02) 4966 1755 www.vcvnewcastle.com.au	<b>Brisbane South</b> 41 Bivouac Place Wacol QLD 4076 Phone (07) 3710 3710 Fax (07) 3718 3408 www.vcvbrisbane.com.au	<b>Brisbane North</b> 650 Macarthur Ave Pinkenba 4008 Phone (07) 3710 3710 Fax (07) 3260 1997	<b>Gold Coast</b> 107 Spencer Rd Carrara QLD 4211 Phone (07) 5596 3972 Fax (07) 5596 4630
--	--	---	---	---	---



Sydney: 6/34 Yarrunga Steet Prestons NSW 2170  
 ABN: 27 000 761 259

**WORKSHOP TAX INVOICE**

Invoice To :

Page no.....: 2

201323  
 IMMS (INTERSTATE MOTOR MARKET)  
 PO BOX 261  
  
 CAMDEN NSW 2570

Invoice number...: 7498276 - 002200  
 Invoice Date.....: 31/08/22  
 Customer Ref.....: X053IX

Operation /Part Number	Description	List Price	Nett Price	--Quantity-- Invced B/Ord	Amount
VO 21523327	PIPE	111.38	97.46	1.0	97.46
VO 23474111	RETAINER	45.80	42.36	1.0	42.37
VO 22645240	SEALING RING	15.16	13.64	1.0	13.64
VO 22275838	SEALING RING	10.58	9.52	2.0	19.04
VO 471626	SEALING RING GR	11.93	10.74	6.0	64.42
VO 23658111	OIL FILTER	53.59	46.89	2.0	93.78
VO 21707135	FILTER LUBE BYP	53.59	46.89	1.0	46.89
VO 22055261	HOSE	130.35	114.06	1.0	114.06
AU2 WUR0937333481	BLIND RIVET M4.	0.07	0.06	6.0	0.39
AU2 WUR0411515	WASHER M5X15X1.	0.07	0.06	4.0	0.26

C:LOW ENGINE OIL PRESSURE AT IDLE, 1.2BAR HOT IDLE  
 C:BEARINGS FOR BIG ENDS AND MAIN BEARING JOURNALS WORN OUT, OIL PUMP SCORED BADLY AND WORN OUT  
 R:DRAIN ENGINE, PUT FRONT END ON STANDS. REMOVE SUMP, OIL PUMP PIPING, STRENGTHENING PLATE. REPLACE ALL MAIN BEARING SHELLS, REPLACE ALL BIG END BEARING SHELLS. INSPECT ALL JOURNALS, OKAY. REMOVE AND REPLACE OIL PUMP. REFIT STRENGTHENING PLATE, PIPES AND SUMP. REPLACE BROKEN OIL FILLER NECK ON SUMP, REPLACE FILLER TUBE FOR SUMP, UNABLE TO FIT ON SUMP NECK. REMOVE, STRIP AND INSPECT OIL FILTER HOUSING, OKAY. REFIT OIL FILTER HOUSING. FIT FUEL FILTER AND OIL FILTER KIT TO ENGINE. FILL ENGINE OIL AND CHECK OIL PRESSURE AFTER HOT AND HOLDING AT 3.25 BAR AT IDLE. ROAD TEST, BOTH TIMES OIL PRESSURE WAS GOING UNDER 1 BAR AT IDLE WHEN HOT AFTER REPAIRS. ROAD TEST AGAIN WHEN HOT, OIL PRESSURE WAS 2.5-3 BAR AT IDLE.

Subtotal: 003 Order Job 003: 4824.21

2221200 REMOVE AND INSPECT OIL FILTER AFTER METAL FOUND IN THE SUMP

VO 21574409	GASKET	142.24	128.02	1.0	128.02
-------------	--------	--------	--------	-----	--------

Subtotal: 004 Order Job 004: 128.02

91	WORKSHOP CONSUMABLES				62.40
----	----------------------	--	--	--	-------

Sydney West	Sydney	Newcastle	Brisbane South	Brisbane North	Gold Coast
9 Oatley Close Blacktown NSW 2148 Phone (02) 9678 2000 Fax (02) 9678 2088 www.vcvsydneywest.com.au	6/34 Yarrunga Street Prestons NSW 2170 Phone (02) 9731 8600 Fax (02) 9731 8699 www.vcvsydney.com.au	8 Birraba Avenue, Beresfield NSW 2322 Phone (02) 4922 2600 Fax (02) 4966 1755 www.vcvnewcastle.com.au	41 Bivouac Place Wacol QLD 4076 Phone (07) 3710 3710 Fax (07) 3718 3408 www.vcvbrisbane.com.au	650 Macarthur Ave Pinkenba 4008 Phone (07) 3710 3710 Fax (07) 3260 1997	107 Spencer Rd Carrara QLD 4211 Phone (07) 5596 3972 Fax (07) 5596 4630



Sydney: 6/34 Yarrunga Steet Prestons NSW 2170  
ABN: 27 000 761 259

WORKSHOP TAX INVOICE

Invoice To :

201323  
IMMS (INTERSTATE MOTOR MARKETI  
PO BOX 261  
  
CAMDEN NSW 2570

Page no.....: 3

Invoice number...: 7498276 - 002200  
Invoice Date.....: 31/08/22

Customer Ref.....: X053IX

Operation /Part Number	Description	List Price	Nett Price	--Quantity-- Invced B/Ord	Amount
-----					
Sub Total Parts...:					4267.23
Sub Total Labour..:					960.00
Sub Total Other...:					62.40
GST.....:					528.98
=====					
T O T A L					5818.61
=====					



# Vehicle History Summary

Fleet #	52360
Registration	Z00723
Make	Mack
Model	TRIDENT
VIN / Chassis #	6FMM12H69CD803960
Build Date	2013/01

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
T-5572	15/11/2021	0	0	Fitting Fee	FITTING POS 6 RE-TORQUE POS 5,6	TTS - Traralgon Tyre Service
R-19075	01/11/2021	0	0	Minor Repairs	Replace both headlight globes Test operation all ok	PTS - Progress Transport Services
T-5295	06/10/2021	0	0	Direct Fit	TRUCK TUBELESS VALVES PUNCTURE VALVE POS 2	Peter Baulch Bridgestone Service Centre
R-18290	01/10/2021	0	0	Minor Repairs		PTS - Progress Transport Services
R-18894	29/09/2021	0	0	Minor Repairs	Check for fault in spotlight. Found short in wiring Repair wiring	PTS - Progress Transport Services
S-10487	27/09/2021	1489031	1246	A - Grease & Brake Adj	Completed A-Service as per sheet	PTS - Progress Transport Services

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-18506	27/09/2021			Breakdown	p: no acceleration ? no power c: can't fault, maybe gearbox harness issues, as truck has some fresh inactive (however date\time stamp do not much) faults. r: got a call, drove to Creswick, located truck, spoke to driver he said after he was running truck with PTO to pump the milk, he went back on a road , and found that truck is limited to 1200rpm, and won't go over 5-6 gear. Connected laptop, readout faults, found fresh inactive but over 8hours old for gearbox range/gears position. Also found backpressure faults, carried out AVU tests - found AVU not working at all. Checked stationary - all revs up ok. Accelerator pedals test - ok Drove truck around the town - all ok Followed the driver to the next loading point, wait for him to load up and followed back to the western freeway and his base at Wallace. Truck did not miss a beat. Truck will be going to Warrnambool to the main depot next day,, and if something arise they will be looking at it there. drove home	CMV Truck & Bus - Dandenong
T-5228	23/09/2021	0	0	Direct Fit	NEW VALVE FITTED IN STEER RIM	Peter Baulch Bridgestone Service Centre
S-10337	10/09/2021	1484502	1246	A - Grease & Brake Adj	Carry out A service Replace rear light assemblies Checked compressor found bolts broken in rear timing cover Removed fuel pump and compressor Drill out and removed broken compressor mount bolts Fit new compressor and bolts and new oil feed hose Refitted fuel pump with new seal Refitted tailshaft Run and checked all ok	PTS - Progress Transport Services
R-18123	08/09/2021			Breakdown	Travel to Lavers Hill Rd Simpson - Tow truck & trailers to Warrnambool (air compressor fault)	PTS - Progress Transport Services
R-17539	25/08/2021	0	0	Minor Repairs	Work Carried Out: Replace top module on gearbox supplied Electronically adjust clutch	PTS - Progress Transport Services

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-16767	17/07/2021	0	0	Minor Repairs	Inspect for truck not shifting gears correct and dropping into neutral Ordered new air valve Fitted new air valve and replaced Test drove all ok	PTS - Progress Transport Services
R-16914	08/07/2021	1480118	0	Minor Repairs	Inspect for air leak in air system. Remove air dryer assembly and fit new unit on Test operation - all ok.	PTS - Progress Transport Services
R-15714	19/05/2021	0	0	Minor Repairs	REMOVE COOLANT HOUSING FROM WATER PUMP TO CYL HEAD ( CORRODED AWAY ) & ORING SLEEVE. REPLACE ALL & REFILL WITH WATER	GTM - Gippsland Truck Mechanic
S-8765	11/05/2021	1478676	1241	B - Oils & Filters	B SERVICE REPLACE R/H REAR M/GUARD RUBBER LINK. TIGHTEN LOOSE R/H/R M/GUARD POLE REPLACE L/H FRONT PARK LIGHT GLOBE SECURE LOOSE SUCTION HOSE P-CLAMPS. TIGHTEN LOOSE FRONT DRIVE LOWER SHOCKER MOUNTS	GTM - Gippsland Truck Mechanic
R-15051	28/04/2021	0	0	Minor Repairs	Remove interior trims and seats, repair roof and sun visor Repaint as required Remove and replace right hand door hinges Supply door hinges	Ace Truck Salvage
R-16678	21/04/2021			Minor Repairs	repair electrics. removed loom to get going so it can be used	Lunds Auto Electrical
S-8259	29/03/2021	1475481	17	A - Grease & Brake Adj	A SERVICE	WPL Workshop
R-14206	18/03/2021	0	0	Minor Repairs		Lunds Auto Electrical
R-14183	17/03/2021	0	0	Parts Only	CONTROL UNIT AIR CON & HEATER MACK	CMV Truck & Bus - Dandenong
R-14148	14/03/2021	0	0	Breakdown	CALL OUT TO DEPOT TO CHARGE UP AIR SYSTEM TO ENABLE TO START ENGINE STUCK IN 4TH GEAR REPAIR/FAULT # 57037	GTM - Gippsland Truck Mechanic
R-13676	23/02/2021	0	0	Minor Repairs	Replace all drive brake slack adjusters to manual slacks. Remove wheels, drum and brakes to slide scam out to allow room to change slack adjuster on RHF and both rear. Fit brake shoe kits to rear axle.	GTM - Gippsland Truck Mechanic
T-3846	18/02/2021	0	0	Balance, Direct Fit	2 x 295/80R22.5 R154 2 x balance beads and wheel balance pos 1 and 2	Latrobe Valley Bandag Pty Ltd



Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-7716	08/02/2021	1469291	0	A - Grease & Brake Adj	A SERVICE Check loose LH rear Ubolts - remove and clean threads. Refit and tension. Remove covers to access and fit new steering damper. Refit all repairs to RH seat - replace valve.	GTM - Gippsland Truck Mechanic
R-13263	28/01/2021			Parts Only	12V/5W narva globes	Burson Auto Parts
R-13131	25/01/2021	0	0	Minor Repairs	Hydraulics	Hydraulink
S-7428	22/01/2021	1467500	0	A - Grease & Brake Adj	A SERVICE	DRN Workshop
R-13377	22/01/2021	0	0	Parts Only	Triangle safety kit	Paccar - Hallam Truck Centre
R-13064	12/01/2021	1466289	0	Minor Repairs	Replace coolant sensor and top up coolant.	GTM - Gippsland Truck Mechanic
R-14045	07/01/2021	0	0	Minor Repairs	repair wiring loom on engine, remove loom and repair engine faults in LH side wiring	Lunds Auto Electrical
R-14041	04/01/2021	0	0	Minor Repairs	fit new batteries to mack and repair leads fault. removed earth leads and repaired	Lunds Auto Electrical
R-13993	24/12/2020	0	0	Minor Repairs	go to yard and get truck going	Lunds Auto Electrical
R-14040	22/12/2020	0	0	Minor Repairs	install new heater fan motor in mack and repair mount on fan assy	Lunds Auto Electrical
S-6977	15/12/2020	1460317	0	B - Oils & Filters	B SERVICE	GTM - Gippsland Truck Mechanic
T-4131	08/12/2020	0	0	Rotate	Wheel balance POS 1+2	Latrobe Valley Bandag Pty Ltd
R-14038	08/12/2020	0	0	Minor Repairs	repair high beam short and replace combo switch. repair wiring short under dash which caused issues	Lunds Auto Electrical
R-12867	30/11/2020	0	0	Parts Only	Heater motor	CMV Truck & Bus - Dandenong
R-12321	30/11/2020			Parts Only	Indicator switch	CMV Truck & Bus - Dandenong

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-12231	25/11/2020	0	0	Minor Repairs	Repair leaking air line at RHF, refit dislodged exhaust pipe at turbo. Adjust all brakes. Tightened loose fitting at steering box hose and top up oil	GTM - Gippsland Truck Mechanic
S-6725	16/11/2020	1446163	0	A - Grease & Brake Adj	A SERVICE Tightened all drive mudguard poles and various guard brackets	GTM - Gippsland Truck Mechanic
R-12160	15/11/2020	0	0	Minor Repairs	Tested system and found it empty of gas. Pressure tested and found a leak in the hose from compressor to condensor. Remove the pipe work by removing the bonnet, remake the hose, reassemble.	AAC Mobile Auto Air Conditioning
R-11334	09/10/2020	143629	0	Minor Repairs	Remove hydraulic pump and dismantle. worn and seals u/s. Fit new pump to truck with new fittings. Replace leaking air fitting at trailer protection valve. Remove RH inside trims and pedal to access mounting bolts. Refit all and check.	GTM - Gippsland Truck Mechanic
R-10734	29/09/2020			Minor Repairs	Replace hose to trailer	Hydraulink
R-10387	28/09/2020	1434723	0	Minor Repairs	Check trans and clutch function as clutch didnt disengage (once only) Check and adjust brakes Connect scan tool to check for faults - recalibrate clutch and transmission, monitor.	GTM - Gippsland Truck Mechanic
R-9921	15/09/2020			Minor Repairs	Purchase of GPS Unit	Bestrane Pty Ltd
S-5887	08/09/2020	1432370	0	B - Oils & Filters	B SERVICE Remove RH step bracket for repair Fit new tank strap rubbers on LHF Replace U/S RHF cab mount Replace leaking spring brake valve & repair supply line	GTM - Gippsland Truck Mechanic
R-11784	07/09/2020			Minor Repairs	Electrical faults repair. Remove wiring loom from engine to cabin and check and repair data wiring, repaired wiring to engine from main ECU plug	Lunds Auto Electrical
R-9771	31/08/2020	0	0	Parts Only	Engine fan clutch Oil & fuel sensor	CMV Truck & Bus - Dandenong
R-10276	31/08/2020			Parts Only	Exhaust flex Exhaust pipe clamps Flanged bolts & nuts Pipe set	CMV Truck & Bus - Dandenong
R-9773	31/08/2020	0	0	Parts Only	Exhaust elbow	CMV Truck & Bus - Dandenong

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-9435	27/08/2020	1432078	0	Minor Repairs	Replace leaking exhaust flex at turbo Replace exhaust pressure sensor hose assy	GTM - Gippsland Truck Mechanic
R-9444	21/08/2020	1432016	0	Minor Repairs	Replace RH lower exhaust stack elbow Connect scan tool to check engine cutting out. Refer to Lundy Pressure test CAC - replace clamp at RH side of CAC	GTM - Gippsland Truck Mechanic
R-9381	20/08/2020	1430002	0	Minor Repairs	Height valve faulty, seat base removed and inspected, height valve not exhausting correctly. valve removed and replaced, tested operation, functioning correctly. Steering wheel not straight, arm removed at box and adjusted. Tested - all ok.	CMV Truck & Bus - Dandenong
R-9157	29/07/2020	0	0	Parts Only	Valve seat height control	CMV Truck & Bus - Dandenong
R-9554	21/07/2020	0	0	Minor Repairs	REMOVED DASH CAMERA AND MIRROR CAMERAS X 2	Lunds Auto Electrical
R-8742	17/07/2020	0	0	Minor Repairs	REPAIRED PTO AIR LEAK REPAIR TO RH SEAT BELT	GTM - Gippsland Truck Mechanic
R-11130	15/07/2020			Minor Repairs	Mass Management	Mass Management
S-5097	03/07/2020	1421004	0	C - Diffs & G'Box Oils	CARRIED OUT SERVICE AS PER STOITSE SCHEDULE WE NOTICED: AIR LEAK AT RH REAR OF ROCKER COVER LEAKING SHOCKER SECOND DIFF LHS AND RHS SLIGHT MOVEMENT IN BOTH KING PINS RH SEATBELT NOT RETRACTING LOOP KIT ON GUARDS BROKEN RHS CAB SHOCKER BUSH WORN POSSIBLE BOOST LEAK	Hartwigs Trucks Pty Ltd
R-8645	30/06/2020	0	0	Parts Only	Adblue pump connector x 1 Adblue pump connector inlet x 1	CMV Truck & Bus - Dandenong
R-8648	30/06/2020	0	0	Parts Only	Heater motor x 1 LH Seat belt x 1	CMV Truck & Bus - Dandenong
R-8497	26/06/2020	0	0	Parts Only	1 X 82734047 NB THROT ASSY 1 X 22059325 HARNESS THROTTLE	H.M. Transport Maintenance
R-8641	26/06/2020	141245	0	Minor Repairs	Carried out gearbox calibration R & R brake pedal pad	CMV Truck & Bus - Dandenong

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-8214	25/06/2020	0	0	Minor Repairs	RWC Inspection	PTS - Progress Transport Services
S-5124	22/06/2020	0	0	A - Grease & Brake Adj	A SERVICE Replaced both tensioner pulleys Removed rear jack shaft tightened front diff rear yoke nut re installed jack shaft Checked tyre pressures Removed mud/grease from inside of ball race	WPL Workshop
S-4853	04/06/2020	1414387	0	A - Grease & Brake Adj	A SERVICE Remove gearbox, replaced slave cylinder and clutch control module Replaced Y piece in exhaust with all new clamps. Re adjusted steer brakes Fixed heater fan	WPL Workshop
R-7893	04/06/2020	1414387	0	Minor Repairs	Remove gearbox, replace slack cylinder and	WPL Workshop
R-8158	31/05/2020	0	0	Parts Only	Exhaust pressure sensor Clutch valve Clutch cylinder	CMV Truck & Bus - Dandenong
R-8157	31/05/2020	0	0	Parts Only	Exhaust pipe	CMV Truck & Bus - Dandenong
R-7897	19/05/2020	1411320	0	Minor Repairs	Replaced indicator stalk Fixed air leak LH side of engine	WPL Workshop
R-7580	08/05/2020	0	0	Parts Only	Indicator switch	CMV Truck & Bus - Dandenong
R-7492	07/05/2020	1408799	0	Minor Repairs	Replaced front drive shockers, repaired LH head light, repaired power steering leak, repaired exhaust, repaired adblue leak, tightened PTO, repaired air leak, topped up power steering oil.	PTS - Progress Transport Services
R-7599	29/04/2020	1407737	0	Minor Repairs	Drained coolant, removed belts and pulleys. Removed water pump. Removed balancer and removed water pump housing. Replaced missing seal at water pump housing. Topped up coolant Ran and checked for leaks - no leaks Replace front springs - replaced rear suspension bushes.	PTS - Progress Transport Services
S-4441	12/03/2020	1402706	0	A - Grease & Brake Adj	A SERVICE Clean down leaking house try repair with liquid metal. Check king pins for R/w. Replaced light globe.	PTS - Progress Transport Services
R-6257	05/03/2020	1404788	0	Minor Repairs	Removed and replaced air blower, checked oil and water.	PTS - Progress Transport Services

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-6356	06/02/2020	1403658	0	Minor Repairs	Removed and replaced new sun visor R & R overhead console Weld up roof and fit new hug nut insert	PTS - Progress Transport Services
R-5241	19/12/2019	1401366	0	Minor Repairs	Replaced broken RHR mudguard pole bolt	ATT- Allansford Truck & Trailer
T-1565	13/12/2019	1401226	0	Stock	POS 1+2+7+8+9+10	Goodyear Auto Care
S-2751	03/12/2019	1399484	0	B - Oils & Filters	B SERVICE Replaced a section of air lines on chassis rail Replaced 3 steering unis and bearings Replaced all batteries Replaced wiper blades Replaced exhaust clamp and tightened two others	PTS - Progress Transport Services

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-2496	17/10/2019	1394613	0	A - Grease & Brake Adj	A SERVICE Replace missing interior lights. Check for cause of high beam lights dropping out, found relay dropping out. Replace relay. Fit and wire up light bar. Replace broken rear diff temp sender. Check for cause of fuel gauge not working, found sender unit plug broken. Repair plug and test. Found faulty wiper/washer switch, check air leak at rear of cab, found cab ride height valve leaking. Replace valve and set ride height. Resecured broken RH step. Tighten RH stack flex clamps. Replace cracked LH exhaust stack elbox. Replace missing horn button. Check diff lock air leak, found split supply air line. Repair line and test - ok. Replace LH and RH roof marker lights. Replace failed RH work light. Tighten LHR & RHR guard poles. Replace front and rear diff top rods, Replace steer axle brake shoes and brake drums. Replace glad hand seals. Drill out and replace broken bolt in front cab support bar. Replace draglink. Remove turbo and exhaust manifold, replace leaking gaskets and refit. Replace leaking heater hose supply pipe Oring and replace bleed hose. Refill system and replace leaking header tank cap. Reseal leaking power steering reservoir. Replace missing fan shroud bolts. Replace fan and alternator belts. Resecure rear number plate. Adjust turn table jaws. Replace cracked LH headlight. Resecure deck plate	ATT- Allansford Truck & Trailer
R-4802	17/10/2019	1394613		Parts Only	Head lamp Light Bar Globes	PTS - Progress Transport Services
R-4585	13/10/2019	0	0	Minor Repairs	Repair leaking air lines with new hose clamps	PTS - Progress Transport Services
R-4663	07/10/2019	1388498	0	Minor Repairs	Inspect for air leaks Replace brake chamber 3rd LH, replaced worn air brake line Repaired air leak in chassis Straighten bent bumper	PTS - Progress Transport Services

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-4307	27/09/2019	1385057	0	Minor Repairs	Inspect for work light fault Repair damaged wiring	PTS - Progress Transport Services
S-2263	12/09/2019	1381456	0	A - Grease & Brake Adj	A SERVICE	SHP Workshop
R-4301	29/08/2019	0	0	Minor Repairs	R & R blown hydraulic hose. Refill with hydraulic oil and test	SGT Maintenance Services
R-3382	23/08/2019	1372282	0	Minor Repairs	Travel to yard and check for cause of engine not cranking. Found batteries flat. Replaced batteries and check charge rate - found ok.	ATT- Allansford Truck & Trailer
T-911	05/08/2019	1372229	0	Stock	POS 3+4+5+6	Goodyear Auto Care
S-1528	26/07/2019	1371491	0	B - Oils & Filters	B SERVICE Replaced air filter	PTS - Progress Transport Services
R-3072	19/07/2019	0	0	Parts Only	Valve Air Engine Brake Valve AVU Engine Brake	PTS - Progress Transport Services
R-2465	27/06/2019	1365008	0	Minor Repairs	Replace globes Check over for faults	PTS - Progress Transport Services
R-2450	19/06/2019	1361536	0	Minor Repairs	Replaced RHR guard pole bolt Check over for cause of engine loss of power, found exhaust brake staying closed. Check for cause and found air valve faulty. Replace air valves with upgrade kit and test - ok	ATT- Allansford Truck & Trailer
R-2211	05/06/2019	1355045	0	Parts Only	Socket	PTS - Progress Transport Services
R-2456	05/06/2019	1355045	0	Minor Repairs	Connect to truck and check active faults, found faults for exhaust pressure sensor, clear faults and test - ok	ATT- Allansford Truck & Trailer
R-2101	31/05/2019	1354917	0	Minor Repairs	Remove intake, fan, fan hub and idlers - change over studs etc Fit new fan hub, idlers, belts, etc cable tie wiring Test drive - ok	PTS - Progress Transport Services
R-1782	31/05/2019	0	0	Parts Only	Fan Clutch Engine Kit Valve Purge Air Drier Filters, Fan belt, Tensioner, Idler Pulley belt, Idler Pulley & Bracket complete. Fan Hub, brackets	CMV Truck & Bus - Dandenong

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-1517	15/05/2019	0	0	Minor Repairs	Removed compressor oil hose - made new hose Sealed bottom of oil fill tube, resealed compressor Run and checked for leaks	PTS - Progress Transport Services
S-757	08/05/2019	0	0	B - Oils & Filters	Topped up diff oils Tightened mudguards Replaced Nox sensor Road tested	PTS - Progress Transport Services
S-692	04/05/2019	0	0	A - Grease & Brake Adj		ATT- Allansford Truck & Trailer
R-2439	23/04/2019	0	0	Accident/Damage	Repairs after accident	Colac Body Works
R-1364	17/04/2019	0	0	Minor Repairs	Plug in and clear codes Faulty LH rear ABS sensor Reline both back axles and replace sensor Replace rear mud flaps	PTS - Progress Transport Services
R-2293	10/04/2019	1342557	0	Minor Repairs	Fit & balance 1 x steer tyre	Colac Body Works
S-586	10/04/2019	1342570	0	A - Grease & Brake Adj	Replaced batteries Replaced tail lights with LED Tightened indicator stalk Replaced LHF drive brake booster Topped up engine oil	PTS - Progress Transport Services
S-751	12/03/2019	1328578	0	A - Grease & Brake Adj	Removed and replaced indicator stalk	PTS - Progress Transport Services
T-166	23/02/2019	1332583	0	Puncture	POS 4	Goodyear Auto Care
T-161	20/02/2019	1331397	0	Own	POS 7+8+9 +10	Goodyear Auto Care
R-404	31/01/2019	1322105	0	Minor Repairs	check PTO for operation check air supply - ok found solenoid power pulsing not a constant 12v wiring in separate wiring for switch and PTO works fine test drive transmission codes go active inspect clutch air supply all ok fit 2nd hand servo codes went inactive remove previous wiring PTO works fine	PTS - Progress Transport Services
S-3459	13/12/2018	1299876	0	C - Diffs & G'Box Oils	C SERVICE	SHP Workshop
R-4186	13/12/2018	0	0	Minor Repairs	Supply and fit new hose and drier, regas. Test operation - found compressor clutch coil faulty. Supply and fit new compressor - test operation ok	PTS - Progress Transport Services



Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-20387			0	Minor Repairs		PTS - Progress Transport Services

Signed: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_