

# Hazard Register



Type	LOADER, WHEELED ARTICULATED WITH LOG GRAB	Location	
Make	-	Sale Number	3024329
Model	-	Lot Number	25
Serial Number			

ID	Hazard Type	Hazard Description
134977.1	ENTANGLEMENT.	HAIR, CLOTHING, GLOVES, JEWELLERY, TOOLS, RAGS OR OTHER MATERIALS OR BODY PARTS MAY BECOME ENTANGLED WITH MOVING PARTS OF THE EXCAVATOR SHOULD OPERATOR, MAINTENANCE PERSONNEL OR BYSTANDERS GET TO CLOSE TO THE MOVING PARTS OF THE EXCAVATOR.
134977.2	CRUSHING.	OPERATORS, MAINTENANCE PERSONNEL AND BYSTANDERS OR THEIR BODY PARTS CAN BE CRUSHED DUE TO MATERIAL FALLING OFF THE EXCAVATOR; UNCONTROLLED OR UNEXPECTED MOVEMENT OF THE EXCAVATOR; LACK OF ABILITY FOR THE EXCAVATOR TO BE SLOWED, SHOPPED OR IMMOBILISED; THE EXCAVATOR TIPPING OR ROLLING OVER; PART OF THE EXCAVATOR COLLAPSING; COMING IN CONTACT WITH MOVING PARTS OF THE EXCAVATOR DURING SETUP, TESTING, INSPECTION, OPERATION, MAINTENANCE, CLEANING AND REPAIR; OPERATORS BEING THROWN OFF OR UNDER THE PLANT; BEING TRAPPED BETWEEN PARTS OF THE MOBILE PLANT OR THE EXCAVATOR AND FIXED STRUCTURES.
134977.3	CUTTING, STABBING OR PUNCHING	FINGERS, HANDS, ARMS AND OTHER BODY PARTS CAN BE CUT, STABBED OR PUNCHED DUE TO COMING IN CONTACT WITH SHARP OR FLYING OBJECTS; THE MOVING PARTS OF THE EXCAVATOR DURING OPERATION, MAINTENANCE, CLEANING AND REPAIR; THE MOBILITY OF THE EXCAVATOR AND THE UNCONTROLLED OR UNEXPECTED MOVEMENT OF THE EXCAVATOR.
134977.5	STRICKING	OPERATORS OR BYSTANDERS CAN BE STRUCK BY MOVING OBJECTS DUE TO THE UNCONTROLLED OR UNEXPECTED MOVEMENT OF THE EXCAVATOR; LACK OF ABILITY FOR THE EXCAVATOR TO BE SLOWED, SHOPPED OR IMMOBILISED; OR MATERIAL HANDLED BY THE EXCAVATOR FLYING OR FALLING OFF THE EXCAVATOR.
134977.6	HIGH PRESSURE FLUID.	OPERATORS, BYSTANDERS AND MAINTENANCE PERSONNEL CAN COME IN CONTACT WITH FLUIDS UNDER PRESSURE, DUE TO FAILURE OF THE EXCAVATOR, MISUSE OF THE EXCAVATOR OR LACK OF ISOLATION PROCEDURES.
134977.8	ELECTROCUTION.	OPERATORS AND BYSTANDERS MAY BE BURNED OR ELECTROCUTED BY THE EXCAVATOR CONTACTING OR BEING OPERATED IN CLOSE PROXIMITY TO OVERHEAD OR UNDERGROUND ELECTRICAL CONDUCTORS.
134977.10	SLIP TRIP FALL	OPERATORS, BYSTANDERS AND PASSENGERS USING AND WORKING AROUND EXCAVATOR CAN SLIP, TRIP AND FALL DUE TO UNEVEN OR SLIPPERY SURFACES ON AND IN THE VICINITY OF THE EXCAVATOR.
134977.11	FALL FROM HEIGHTS	OPERATORS, BYSTANDERS, MAINTENANCE PERSONNEL AND PASSENGERS REQUIRED TO WORK ON THE TOP OF OR OUTSIDE OF THE EXCAVATOR CAN FALL FROM HEIGHTS DUE TO LACK OF PROPER WORK PLATFORM; LACK OF PROPER STAIRS OR LADDERS; LACK OF GUARD RAILS OR OTHER EDGE PROTECTION; AND POOR WALKING OR WORK SURFACES,

# Hazard Register



		SUCH AS UNEVEN, STEEP OR SLIPPERY WORK SURFACES.
134977.12	ERGONOMICS.	OPERATORS AND PASSENGERS CAN BE INJURED DUE TO POORLY DESIGNED AND MAINTAINED SEATING AND OPERATOR CONTROLS THAT REQUIRE REPETITIVE BODY MOVEMENT; CONSTRAINED BODY POSTURE OR THE NEED FOR EXCESSIVE EFFORT; AND MISMATCH OF EXCAVATOR WITH HUMAN TRAITS AND NATURAL LIMITATIONS.
134977.14	HIGH TEMPERATURE	OPERATORS, PASSENGERS AND MAINTENANCE PERSONNEL MAY BE BURNT BY COMING INTO CONTACT WITH PARTS OF THE EXCAVATOR AT HIGH TEMPERATURES.
134977.15	FIRE.	OPERATORS, MAINTENANCE PERSONNEL AND PEOPLE REQUIRED TO REFUEL THE EXCAVATOR CAN BE INJURED BY FIRE DUE TO FAILURE OF THE EXCAVATOR, MISUSE OF THE EXCAVATOR OR THE LACK OF OPERATION PROCEDURES.
134977.17	CHEMICALS, FUELS	EXPOSURE TO CHEMICALS (LPG, PETROL, DIESEL) THROUGH THE REFUELLING OF EXCAVATOR CAN CAUSE IRRITATION TO THE EYES, NOSE, THROAT AND SKIN. WHILE PROLONGED EXPOSURE CAN CAUSE IRREVERSIBLE HEALTH ISSUES.
134977.18	FUMES.	OPERATORS CAN BE INJURED OR SUFFER ILL-HEALTH FROM PROLONGED EXPOSURE TO FUMES GIVEN OFF BY THE OPERATION OF THIS EXCAVATOR.
134977.19	NOISE.	OPERATORS AND BYSTANDERS CAN BE INJURED OR SUFFER ILL-HEALTH FROM EXPOSURE TO NOISE LEVELS GREATER THAN 85db(A) CONTINUES OVER 8 HOURS OR 140db(C) PEAK, THROUGH THE OPERATION OF THIS EXCAVATOR.
134977.20	VIBRATION.	OPERATORS AND BYSTANDERS CAN BE INJURED OR SUFFER ILL-HEALTH FROM EXPOSURE TO VIBRATION GIVEN OFF THROUGH THE OPERATION OF THIS EXCAVATOR.
134977.22	SAFE WORKING LOAD (SWL)	THIS EXCAVATOR SHOULD HAVE A COMPLIANCE PLATE OR LOAD CHART INDICATING THE SAFE WORKING LOAD (SWL) LOAD OF THE EXCAVATOR. EXCEEDING THE SWL OF THE EXCAVATOR CAN CAUSE DAMAGE TO THE PLANT AND INJURIES TO OPERATORS AND BYSTANDERS.
134977.23	EXCAVATION.	OPERATORS AND BYSTANDERS CAN BE INJURED DUE TO EXCAVATOR COMING IN CONTACT WITH OR WORKING TOO CLOSE TO UNDER GROUND CABLES AND PIPES.
134977.24	TRAFFIC MANAGEMENT.	BYSTANDERS AND PEOPLE REQUIRED TO WORK AROUND EXCAVATOR CAN BE INJURED DUE TO THE LACK OF TRAFFIC MANAGEMENT PROCEDURES, BARRIERS AND GUARDING.
134977.25	PASSENGERS	PASSENGERS CAN BE SEVERELY INJURED OR KILLED AS A RESULT OF RIDING ON EXCAVATOR WHERE A PASSENGER SEAT AND SEAT BELT IS NOT PROVIDED. PASSENGERS SHOULD NOT RIDE ON OR IN EXCAVATOR WHERE A PASSENGER SEAT AND SEAT BELT IS NOT PROVIDED. NEVER CARRY PASSENGERS ON THE TRAY OR OTHER LOAD HANDLING AREAS.
134977.27	PLANT OPERATION.	THE EXCAVATOR SHOULD ONLY BE OPERATED BY LICENSED, COMPETENT, SKILLED AND TRAINED PERSONAL. ALL OPERATOR CONTROLS AND SAFETY SYSTEMS SHOULD BE TESTED PRIOR TO OPERATION AND ALL FAULTS REPORTED IMMEDIATELY. THIS EXCAVATOR SHOULD NEVER BE OPERATED WITHOUT ALL GUARDING IN PLACE AND ALL SAFETY SYSTEMS FUNCTIONING CORRECTLY.
134977.28	MAINTENANCE.	THE EXCAVATOR SHOULD ONLY BE MAINTAINED BY COMPETENT AND TRAINED PERSONNEL AND ALL ENERGY SOURCES ASSOCIATED WITH THE PLANT TO BE ISOLATED AND DE-ENERGISED WHILE EXCAVATOR IS BEING MAINTAINED. THE EXCAVATOR SHOULD

NOT BE PUT BACK IN SERVICE WITHOUT ALL GUARDS IN PLACE AND ALL SAFETY SYSTEMS TESTED AND OPERATING CORRECTLY.

134977.29 INFORMATION, INSTRUCTION, TRAINING & SUPERVISIONALL OPERATORS, MAINTENANCE PERSONNEL AND PEOPLE REQUIRED TO WORK AROUND THE EXCAVATOR, REQUIRE INFORMATION ON THE OPERATION, SETUP AND HAZARDS OF THE EXCAVATOR, INSTRUCTION AND TRAINING ON HOW TO OPERATE, REFUEL, SETUP, DISMANTLE, MAINTAIN AND WORK WITH THE EXCAVATOR AND PERSONNEL SHOULD ALWAYS BE SUPERVISED WHEN OPERATING, SETTING UP, DISMANTLING, MAINTAINING, REFUELLING OR REQUIRED TO WORK AROUND A EXCAVATOR.

Health and Safety  
Plant Safety  
Purchaser Information

This plant health and safety information has been prepared by Grays for the purchaser of the plant item as required by National WHS Legislation. Whilst every effort has been made to identify all of the hazards, it should be recognised that all reasonably practicable hazards have been identified given due consideration to:

- state of knowledge about the plant item
- the availability and suitability of ways to eliminate or control the hazards
- the cost of evaluating, eliminating or controlling the hazard

Consequently, if this plant item is being purchased for use at a place of work, the purchaser is reminded of their obligations to involve and consult with employees in identifying foreseeable hazards, assess their risks and to take action to eliminate or control the risks.

In order to assess the risk, it is necessary to consider for all the identified hazards, the chance (likelihood) of something happening that would impact (consequence) on health and safety at the workplace. The following guidelines are provided to assist the purchaser in consistently carrying out an assessment of risk:

Likelihood	Consequences
<ul style="list-style-type: none"><li>• Frequency and duration of exposure</li><li>• Probability of occurrence of hazard or event (including part history of incidents)</li><li>• Possibility to avoid / minimize or limit the damage, impact or harm</li><li>• Reliability and effectiveness of existing / established systems of control</li></ul>	<ul style="list-style-type: none"><li>• Assume “worst case” injury, but also competent follow-up medical and rehabilitation support</li><li>• Consider forces or energy levels, highest belt tensions, size of gears, pulleys or other entrapment points and therefore body parts likely to be injured</li><li>• Consider sharpness of entrapment points, surrounding parts likely to exacerbate injury, and any give in the entrapment point</li><li>• Consider, will entrapment continue until plant is stopped, or can an injured part travel through the entrapment area</li><li>• Are temperatures of plant, or chemicals, likely to further injure entrapped person</li></ul>

The outcome of the risk assessment will be a prioritised list of risk control strategies and actions consistent with the following ratings:

- Low risk- may be considered acceptable, where the existing controls in place are seen to be effective, requiring periodic monitoring for effectiveness.  
Medium risk- considered to be unacceptable and requiring additional risk controls within medium to long term.  
High risk – considered to be unacceptable and requiring action within the short to medium term.  
Extreme risk – unacceptable, where immediate action required.

In all of these cases employees/operators must be made aware of the risk controls in place to protect them from the hazards.