Job: 1C LEAKING FUEL

LabourTech#PriceLABOUR\$171.26

TRAVELLED TO JOB SITE
REMOVED INSPECTION PLATE FROM UNDERNEATH MACHINE
TRACKED LEAK TO FUEL FILTER AREA AT THE TOP OF MACHINE
OPENED HATCH ON TOP OF MACHINE & CLEANED
CHECKED FUEL FILTER WAS TIGHT
RAN MACHINE UP AGAIN = FUEL LEAK STILL PRESENT
CHECKED AROUND FUEL FILTER AREA & FOUND BLEED SCREW HAD COME LOOSE
TIGHTENED BLEED SCREW & RAN UP MACHINE AGAIN = NO LEAK
SHOWED OPERATOR WHERE THE LEAK HAD BEEN COMING FROM & ADVISED TO
CONTINUE TO MONITOR AFTER OPERATION
PACKED UP WORK AREA & TOOLS & UTE
TRAVELLED BACK TO WORKSHOP

 Workshop Consumables
 Job#
 Price

 SHOP SUPPLIES
 1
 15.00

 Total
 \$15.00

Job: 1C CHECK AUTO GREASER

 Labour
 Tech#
 Price

 LABOUR
 \$300.16

REMOVED CAP FROM AUTO GREASER
PUSHED THROUGH x13 TUBES OF GREASE
REPLACED CAP ON TOP OF AUTO GREASER
CLEANED AROUND AREA
FITTED NEW HYDRAULIC CAP ON BOOM RAM
FITTED x4 NEW AUTO GREASER LINES

Replacement Part Description	Part Number		Qty	Price
GREASE MP PLUS 450G	AGGREASE		13.00	152.45
		Total - Parts		\$152.45
Sublet		Job#		Price
PARTS EXTERNAL SUPPLY PLEASE SUPPLY A HYDRAULIC CAP FOR BOOM RAM & x4 AUTO GREASER LINES		1		43.81
		Total		\$43.81
Workshop Consumables		Job#		Price
SHOP SUPPLIES		1		15.00
		Total		\$15.00

Job: 1C AUTO GREASER REFILL

LabourTech#PriceLABOUR\$263,92

TRAVELLED TO JOB SITE SIGNED IN & WAS GUIDED TO MACHINE LOOSENED TOP OF AUTO GREASER & FILLED CANISTER CLEANED UP & REPLACED LID TRAVELLED BACK TO WORKSHOP

SERVICE DUE IN 200HRS

 Replacement Part Description
 Part Number
 Qty
 Price

 GREASE MP PLUS 450G
 AGGREASE
 14.00
 164.18

 Total - Parts
 \$164.18

*Carry out Kobelco 50 Hour Service as per manufacturer's recommendations as listed below KOBELCO SK500XDLC-10

Change Engine oil and oil filter (15W40)

Clean Outer air cleaner

Check Inner air cleaner

Change Reduction motor oil (80W90)

Check Air intake hoses

Check For exhaust leaks

Check Fuel filters

Check Fuel line condition

Top up Engine Coolant, check all clamps (Kobelco)

Clean Radiator and oil cooler free from excessive debris build-up

Clean Fuel cap and strainer

Check Engine mounts

Check Fan belt condition and tension

Check A/C belt condition and tension

Clean Cab filters

Top up Washer bottle

Change Hydraulic oil return filter

Top up Hydraulic oil level and condition (ISO46)

Check Hydraulic hoses, lines and fittings

Adjust Track tension

Check Sprockets and track Rollers

Check Machine for leaks

Check Battery electrolyte and connections
Check All lights and horn
Check Safety lock lever operation
Check Seatbelt
Grease All Pins
Check Slew motor oil
Grease Slew Bearing and pinion

Check Bucket teeth and side cutters (if fitted)

Check Quick Hitch Operation (Check safety pin is fitted if fitted)

Test operation

Fit service sticker

Check over all work carried out (i.e Filters, Fluid levels, Filler caps, Belts, Belly plates, Panels, Reset service indicator etc)

VH15(ENGINE OIL FILTER	1.00	65.68	65.68
4645015W40 DH-2 ENGINE OIL 1L	44.00	9.02	396.80
4018080W90 GEAR OIL 1L	35.00	7.90	276.50
VH15ÆNGINE OIL FILTER	1.00	32.56	32.56
LC52\HYDRAULIC RETURN FILTER KIT	2.00	302.24	604.47
Travel Charges	1.00	164.85	164.85