

LABOUR ROADSIDE REPAIRS

TRAVEL TO BREAKDOWN: KIDMAN WAY BETWEEN WARBURN & TABBITA
 CHECK AND REPAIR: COOLANT HOSE OFF & LOST ALL COOLANT

PACK BREAKDOWN VEHICLE, TRAVEL TO BREAKDOWN AT WARBURN.
 INSPECT TRUCK AND FIND BOTTOM COOLANT HOSE HAS COME OFF & TRUCK HAS
 LOST ALL COOLANT.
 REMOVE EXISTING HOSE CLAMP, ADJUST HOSE POSITION FOR CLAMPS WILL HOLD
 PROPERLY, REPLACE BOTH CLAMPS WITH NEW & TIGHTEN
 FILL RADIATOR WITH COOLANT, START ENGINE,
 CHECK FOR LEAKS - ALL OK, TOP UP HEADER TANKS WITH COOLANT.ALL OK.
 CLEAN UP, RETURN TRUCK TO SERVICE. RETURN TO WORKSHOP, COMPLETE
 PAPERWORK.

Labour

ROADSIDE REPAIRS T1 627.00

Parts

B9228-0275B CLAMP 2 26.72

365-8396 CAT COOLANT 20LTR 3 482.91

Others

VEHICLE KILOMETERAGE 69 119.37

WORKSHOP SUPPLIES 1 23.50

Sub Total ExGST: 1,279.50



Parts:	509.63
Labour:	627.00
Others:	142.87
otal GST:	127.95
Total:	1,407.45

Product	Description	Quantity	Price
LABOUR LOCAL FLEET			
	CHECK AND REPAIR: * R&R FRONT SHOCKS * ALARM SESNOR (CAB TILT) GOING OFF ALL THE TIME * DERATES RANDOMLY WHEN NOT FULL OF FUEL * EBS PLAYING UP, LIGHT COMES ON & OFF ***** INSPECT FRONT SHOCK ABSORBERS - RUBBER FINE, OPERATION FINE & NO LEAK - DETERMINE NO NEED TO REPLACE. INSPECT DERATE COMPLAINT, CONFIRM BUT UNABLE TO SCAN & DIAGNOSE. RECCOMENT TRUCK GOES TO VOLVO DEALER FOR DIAGNOSIS AND REPAIR. INSPECT FOR EBS COMPLAINT - ISOLATE ISSUE TO TRAILER. INSPECT FOR CAB TILT ALARM GOING OFF. FIND CAB TILT SENSOR FAILED. REMOVE & REPLACE SENSOR WITH NEW, TEST - ALL OK, CONFIRM REPAIR. CLEAN UP, COMPLETE PAPERWORK & RETURN TRUCK TO SERVICE. *****		
Labour	LABOUR CHARGES FOR THE FOLLOWING WORK		159.00
Parts			
23468944	CONTACT - TILT SENSOR	1	334.23
		Sub Total ExGST:	493.23
SCEHULED SERVICE (CLASS'B')			
	CARRIED OUT B SERVICE AS PER SHEET [] FILL IN & CHECK DRIVERS HANDBOOK [] TAKE ENGINE OIL SAMPLE (WHERE APPLICABLE) [] CHANGE ENGINE OIL [] CHANGE ENGINE OIL FILTERS [] CUT OPEN OIL FILTER & INSPECT FOR METAL [] CHECK IF OIL FILTER NEEDS TENSIONING (CUMMINS) [] CHANGE FUEL FILTERS [] INSPECT ENGINE FOR OIL LEAKS [] CHECK COOLANT LEVEL AND		

Continued ...

Product	Description	Quantity	Price
	<p>CONCENTRATION</p> <p><input type="checkbox"/> CHANGE WATER FILTER IF REQUIRED</p> <p><input type="checkbox"/> ENSURE ADBLUE FILLER AREA IS CLEAN</p> <p><input type="checkbox"/> ADBLUE SYSTEM CHANGE AIR FILTER</p> <p><input type="checkbox"/> ADBLUE SYSTEM CHECK FITTINGS ON PUMP TANK & DOSING UNITS FOR LEAKS</p> <p><input type="checkbox"/> CHECK AIR CLEANER ELEMENT</p> <p><input type="checkbox"/> INSPECT ALL BELTS AND REPORT</p> <p><input type="checkbox"/> CHECK STEER HUB OIL LEVELS & CHECK WHEEL BEARINGS FOR METAL</p> <p><input type="checkbox"/> GREASE ALL NIPPLES/LUBE POINTS</p> <p><input type="checkbox"/> REPLACE GREASE NIPPLES NOT TAKING GREASE</p> <p><input type="checkbox"/> CHECK CLUTCH ADJUSTMENT</p> <p><input type="checkbox"/> INSPECT DRIVELINE AND UNI JOINTS</p> <p><input type="checkbox"/> CHECK ALL STEERING COMPONENTS</p> <p><input type="checkbox"/> VISUAL CHECK ALL ON SUSPENSION BUSHES AND WEARING POINTS</p> <p><input type="checkbox"/> JACK UP FRONT AXLE & GREASE STEERING JOINTS & SUSPENSION POINTS</p> <p><input type="checkbox"/> INSPECT POWER STEERING SYSTEM FOR LEAKS AND CHECK LEVEL</p> <p><input type="checkbox"/> CHECK TENSION ON CHARGE AIR CLAMPS</p> <p><input type="checkbox"/> CHECK ALL LIGHTS</p> <p><input type="checkbox"/> CHECK BATTERIES-LEVEL & TERMINALS</p> <p><input type="checkbox"/> ADJUST ALL BRAKES AND CHECK FOR AIR LEAKS</p> <p><input type="checkbox"/> INSPECT BRAKE LININGS & RECORD PERCENTAGE LEFT</p> <p><input type="checkbox"/> LH STEER 70%</p> <p><input type="checkbox"/> LHF DRIVE 70%</p> <p><input type="checkbox"/> LHR DRIVE 70%</p> <p><input type="checkbox"/> RH STEER 70%</p> <p><input type="checkbox"/> RHF DRIVE 70%</p>		

Continued ...

Product	Description	Quantity	Price
	<input type="checkbox"/> RHR DRIVE 70% <input type="checkbox"/> DRAIN AIR TANKS <input type="checkbox"/> INSPECT TRANSMISSION FOR LEAKS AND CHECK OIL LEVELS <input type="checkbox"/> INSPECT BOTH DIFFS FOR LEAKS AND CHECK OIL LEVELS <input type="checkbox"/> VISUAL INSPECTION OVER UNIT AND REPORT <input type="checkbox"/> CHECK WIPER BLADES & TOP UP WASHER FLUID <input type="checkbox"/> RECHECK SUMP PLUG & OIL LEVEL <input type="checkbox"/> ATTACH NEXT SERVICE STICKER <input type="checkbox"/> TAKE ECM DOWNLOAD OF CURRENT TOTALS (CAT) ***** PLACE TRUCK IN WORKSHOP, CARRY OUT B SERVICE AS PER SHEET. DRAIN ENGINE OIL, REMOVE & REPLACE FILTER WITH NEW, TOP UP NEW OIL. REMOVE & REPLACE AIR, WATER & FUEL FILTER WITH NEW. CHECK ALL BELTS, PULLEYS & TENSIONERS, CHECK ALL HOSES & CLAMPS. CHECK ALL UNI JOINTS, STEERING & DRIVELINE COMPONENTS. CHECK ALL SUSPENSION FOR LEAKS & DAMAGE, CHECK & ADJUST BRAKES, CHECK WHEEL BEARING FREE PLAY. CHECK COOLANT LEVEL & CONDITION, CHECK POWER STEERING FLUID LEVEL & CONDITION, CHECK TRANSMISSION & DIFF OIL LEVELS & CONDITIONS. CHECK ALL BATTERIES, TERMINALS & LIGHTS. GREASE ALL POINTS. ATTACH NEW SERVICE STICKER. CLEAN UP, COMPLETE PAPERWORK & RETURN PROCEED TO REPAIRS. *****		
Labour	LABOUR CHARGES FOR THE FOLLOWING WORK		715.50
Parts			
24122024	SERVICE KIT	1	403.53
21693755	AIR FILTER	1	394.19
Others			
	WORKSHOP SUPPLIES	1	23.50
	ENVIRONMENTAL & OIL DISPOSAL LEVY	1	27.42
	Castrol Vecton 15W-40 CK-4/E9	35	277.20

Continued ...

Product	Description	Quantity	Price
	Grease: Premium Heavy Duty	1	20.16
	INWARD FREIGHT	8.5	42.50
			1,904.00
		Sub Total ExGST:	1,904.00



Parts:	1,131.95
Labour:	874.50
Others:	390.78
Total GST:	239.72
Total:	2,636.95

VIN: YV5XG30D4JD208416
Stock No: 208416

Last Clocking Date: 3/12/2024
Fleet No. #202

Repair Order: R02048682
Engine Hours: 16,665

Product	Description	Quantity	Price Excl.
ATTEND VOLVO BREAKDOWN 3 HRS MINIMUM			
01	BREAKDOWN LABOUR		292.30
TC	TRAVEL CUSTOMER		262.70
kt	KM TRAVEL CHARGE	15	22.50

TRAVEL TO SITE AND REPLACE LHR/2ND DRIVE BLOWN AIRBAG - TAKE PART AND STAND ETC TO REPAIR			

VT22058741	AIR BAG FH-M VER4 FR OF FR-RE OF RE RSTAB1 SMALL Travelled to customer. Jacked up chassis and secured on stand Removed blown air bag and installed new one. Filled truck with air and checked for leaks - ok Lowered truck	1	345.45
Sub Total:			922.95

Parts: \$345.45

Labour: \$555.00

Others: \$22.50

Sub Total: \$ 922.95

Total GST: \$ 92.30

Rounding: 0.00

INVOICE TOTAL 1,015.25

Product	Description	Quantity	Price
LABOUR ROADSIDE REPAIRS			
	TRAVEL TO BREAKDOWN: KIDMAN WAY BETWEEN WARBURN & TABBITA CHECK AND REPAIR: COOLANT HOSE OFF & LOST ALL COOLANT		
	PACK BREAKDOWN VEHICLE, TRAVEL TO BREAKDOWN AT WARBURN. INSPECT TRUCK AND FIND BOTTOM COOLANT HOSE HAS COME OFF & TRUCK HAS LOST ALL COOLANT. REMOVE EXISTING HOSE CLAMP, ADJUST HOSE POSITION FOR CLAMPS WILL HOLD PROPERLY, REPLACE BOTH CLAMPS WITH NEW & TIGHTEN FILL RADIATOR WITH COOLANT, START ENGINE, CHECK FOR LEAKS - ALL OK, TOP UP HEADER TANKS WITH COOLANT.ALL OK. CLEAN UP, RETURN TRUCK TO SERVICE. RETURN TO WORKSHOP, COMPLETE PAPERWORK. *****		
Labour	ROADSIDE REPAIRS T1		627.00
Parts			
B9228-0275B	CLAMP	2	26.72
365-8396	CAT COOLANT 20LTR	3	482.91
Others			
	VEHICLE KILOMETERAGE	69	119.37
	WORKSHOP SUPPLIES	1	23.50
			<hr/>
		Sub Total ExGST:	1,279.50



Parts:	509.63
Labour:	627.00
Others:	142.87
otal GST:	127.95
Total:	1,407.45

QTY	ITEM CODE	DESCRIPTION	UNIT PRICE (ex-GST)	DISC %	TOTAL PRICE (ex-GST)
4	11R22511G	11R22.5 Liaolun SR316+ (18)	\$460.00		\$1,840.00
2	29580R22510G	295/80R22.5 Bridgestone R154 154/152M (Steer)	\$750.00		\$1,500.00
2	BAG	Bag of Balance Beads	\$35.00		\$70.00
6	DISPOSALG DETAIL	Tyre Disposal JC 376043	\$15.00		\$90.00
PLEASE NOTE OUR BANK DETAILS HAVE CHANGED 01/03/24					

Memo: VOLVO TIPPER, 731708km, REGO: XO51RI

Subtotal:	\$3,500.00
Freight (ex-GST):	\$0.00
GST:	\$350.00
Total (inc-GST):	\$3,850.00
Paid to Date:	\$0.00
Balance Due:	\$3,850.00

Job: 1C DEFECT CLEARANCE

Code:

Labour

WORKSHOP LABOUR

Tech#

11713

Total

Price

1,980.00

\$1,980.00

DEFECT CLEARANCE - AHV1520092

1. ADVANCED BRAKING SYSTEM WARNING LAMP INDICATES A FAULT WITH A SYSTEM.
TRUCKS FAULT RESOLVED BY REPAIRING TRAILER FAULT.

2. DISPLAY SCREEN INDICATES AIR SYSTEM MALFUNCTION ADVANCED BRAKING SYSTEM WARNING
LAMP.

CONNECT COMPUTER & CHECK FOR FAULT CODES.

FOUND AIR DRIER FILTER BLOCKED.

REMOVE AND REPLACE AIR DRIER FILTER.

INSPECT AND FOUND RUBBED HOLE IN AIR COOLING

RING AROUND FAN, LEAKING AIR. ORDER NEW RING.

REMOVE HEADER TANK, TOP RADIATOR HOSE,

TOP INTERCOOLER HOSE. UNBOLT AND REMOVE FAN SHROUD.

UNBOLT FAN AND REMOVE. REMOVE AND REPLACE COOLING RING.

REFIT FAN AND BOLT FAN SHROUD IN TO RADIATOR.

FIT TOP INTERCOOLER AND RADIATOR HOSE.

REFIT HEADER TANK. FILL TRUCK WITH COOLANT.

PRESSURE TEST COOLING SYSTEM - NO LEAKS FOUND.

INSPECT HOSES FROM COMPRESSOR TO AIR DRYER.

FOUND HOSES FULL OF CARBON, REPLACE AVAILABLE PARTS,

CLEAN REMAINING HOSES AND REFIT. WASH DOWN TRUCK.

TEST DRIVE ALL OKAY, NO FAULTS FOUND.

3. BETWEEN AXLE 2 AND 3 BOTH SIDES - TIPPER BODY SUBFRAME IS CRACKED.

INSPECT AND CLEAR DEFECT.

4. ON BACK LHS REAR MARKER PLATE IS DAMAGED.

INSPECT AND CLEAR DEFECT.

REPLACE LHS LOW BEAM GLOBE, DUE TO BEING BLOWN.

CHECK OPERATION - ALL OKAY.

Replacement Part Description	Part Number	Job#	Qty	Price
SERVICE KIT	VO23690622	1	1.00	210.80
FAN RING	VO23752844	1	1.00	534.10
HOSE	VO23960136	1	1.00	249.25
COOLING COIL	VO22833163	1	1.00	173.95
HOSE CLAMP	VO994565	1	2.00	17.50
HOSE CLAMP 19-44	OTCLP-135	1	2.00	6.00

Petrols, Oils, Lubricants and Supplies

SHOP SUPPLIES

CLEAR DEFECT

Total - Parts

\$1,191.60

Job#

Price

1

33.00

1

43.00

Total

\$76.00

*** Thank you for your business. Please Use Customer Number As Reference ***

Payment Type: ACCOUNT SALES

I certify that the above repairs have been completed to my satisfaction:

CUSTOMERS SIGNATURE:

DATE:

_____ / ____ / ____

Total Invoice Amount: _____ \$3,247.60

Your Invoice Amount: _____ \$3,247.60

Includes GST of: _____ \$295.24