HONDA

Parramatta Honda

ACN 137 048 474 ABN 74 137 048 474 Unit A, 10-16 South Street Rydalmere NSW 2116 Telephone (02) 9028 2150

Inchurch Automotive Pty Ltd trading as Parramatta Honda. MD026661 MVRL 46674

Service TAX	Invoice	Page 1 of 1					Doc #: HO (CHW	223	33
Customer No. 235566					Advisor ALEX WILLIAMS 2	518 Colour		Tear	n nda	Ry
Doc. Date	1				Year / Make / Model			Tag	No.	
17/11/21					11/HONDA/Jazz VTi 5DR Hatchback 1.5L Manu					
Reg. No. CR42AL					Medel No. JA55MVTI12	Carline		Eng.	/Trans	š.
Stock No.					Chassis No.	178004	Prod. Date	1st I	Del. D	ate
Purchase Order No.	Driver			ntract No.	Contract Name	Contract Exp. Kms	Exp. Date			
	Home Phone	Business Pt	none	Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date	Wan	. Ехр.	Date
	Vehicle ID. Engi MRHGE8750CP040292		Engine No	o	Date & Time Promised 17/11/21 05:00pm	Time Received 11:00am	Quote Price	Air	Pwr	Turt
abour	Operatio	n D	escripti	ion		Units			Am	oun

Job# 1 99HO6CB Tech(s): 2452 Warranty

PASSENGER AB INFLTR CARRY OUT WORK AS PER CAMPAIGN BULLETIN

Complete Active recall on vehicle as per Honda

structions.

TE: SRS warning light was coming on the dash area before placement of the passenger side front air bag inflator, ecked and found found F3-11: the left side airbag ployed (relating for the driver's side air bag' and 5-11: both or only side curtain airbag and seatbelt

nsioner deployed'.

Parts	Qty	Number	Description	Unit Price	Amount
Job# 1	1	HO04790TF0405	KIT AS INFLATOR		Warranty

Comments

NOTE: if customer would like us to look at the SRS light it cost \$165 for one ho

	Total Labour Total Parts Total POL Total Sublet Total Misc	0.00 0.00 0.00 0.00 0.00
TOTAL AMOUNT INCLUDING GST	Total Tax Total Invoice	0.00

^{*} Lice No: MVRL46674. A.R.C Lic No: AU41055
* Privacy Policy available at www.parramattamotorgroup.
* Parts and labour covered by manufacturer's warranty.