



Your recall status

Please be sure to read the entire page and follow our advice carefully. To book a Toyota service, please [click here](#).

Safety Recalls

Campaign Code

[4E004]

Recall Description

The fuel vapour storage canister assembly vent hose can become pinched and cause a fuel leak

Recall Number

Recall Status

● Complete

Completion Date

02/12/2004

Campaign Code

[7525E]

Recall Description

Headlight dimmer switch may corrode & cause headlamps to flicker & extinguish momentarily, increasing the risk of an accident

Recall Number

Recall Status

● Complete

Completion Date

24/04/2008

Vehicle Details

VIN	6T153XK360X274044
Model	Camry (01.08.2002)
Colour	Champagne Metallic
Trim	GRANITA - FAWN
Series	Sedan A/T 3.0 Ateva
Production year/month	2002-11
Time/Date	11:24:16 09/03/2023

This search is provided for information purposes to assist Toyota guests and should not be solely relied upon. The Toyota VIN search tool is available for Toyota vehicles only that are supplied through authorised networks (i.e. it does not include 'grey imports'). The search results contain the best information currently available to Toyota.

*Recall Number (REC) is a unique identifier assigned to vehicle recalls by the Department of Infrastructure, Transport, Regional Development and Communications. Previously, Product Recall Australia (PRA) numbers were assigned by the Australian Competition and Consumer Commission (ACCC), therefore the Toyota Safety Recall Website may display REC number or PRA number formats.

For more detail about REC numbers and/or PRA numbers, please visit

<https://www.vehiclerecalls.gov.au/> or <https://www.productsafety.gov.au/>

Note: Takata airbag mandatory safety recalls are controlled/monitored by the ACCC and will display the PRA Number only.