



Mercedes-Benz

Digital Service Report

Vehicle info

Vehicle GLA 180
First reg. date 31.01.2020
FIN WDC1569422J690327

Next 12.2025
Service 93329 km

(Please note the additional information in your vehicle (owner's manual, service booklet and service interval indicator) on the performance of the next service)

Service report 5

Mercedes-Benz	Niplag Pty. Ltd. as trustee for The Carlin & Gazzard Trust Crouch Street South 5-11 Mount Gambier	Date 17.12.2024 Rep.-order-no. 246158 Mileage 68329 km
---------------	--	--

Performed services

Service Service A
Workshop code 505
Remaining time -45 Days
Remaining distance 12700 km

Oil quality/viscosity

Description Engine oil
Oil quality 229.5
Viscosity

Replaced / renewed

Perform Service A with Plus package ☒
Extra work for: Service: ☒
Replace air filter element
Extra work for: Service A: ☒
Replace brake fluid
Extra work for: Service A, ☒
Replace combination filter,
Perform Not for ECE veh.
Extra work for: Service: ☒
Replace spark plugs

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with ☒

Addwork in accordance with Mercedes-Benz AG specification

Accomplished ☒



Mercedes-Benz

Service report 4

Mercedes-Benz	RFW Holdings Pty Ltd as trustee for The Robert Wann Family Trust 884 South Road Edwardstown	Date Rep.-order-no. Mileage	24.10.2023 220 56028 km
---------------	--	-----------------------------------	-------------------------------

Performed services

Service	Service B
Workshop code	3609
Remaining time	4 Days
Remaining distance	10555 km

Oil quality/viscosity

Description	Engine oil
Oil quality	229.5
Viscosity	

Replaced / renewed

Air filter element replaced	<input checked="" type="checkbox"/>
Spark plugs replaced	<input checked="" type="checkbox"/>
Engine: oil and filter change	<input checked="" type="checkbox"/>

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with	<input checked="" type="checkbox"/>
---------------	-------------------------------------

Addwork in accordance with Mercedes-Benz AG specification

Accomplished	<input checked="" type="checkbox"/>
--------------	-------------------------------------

Comment

Replaced battery



Mercedes-Benz

Service report 3

Mercedes-Benz	RFW Holdings Pty Ltd as trustee for The Robert Wann Family Trust 884 South Road Edwardstown	Date Rep.-order-no. Mileage	28.10.2022 14012030 41583 km
---------------	--	-----------------------------------	------------------------------------

Performed services

Service	Service A
Workshop code	D0D
Remaining time	53 Days
Remaining distance	12736 km

Oil quality/viscosity

Description	Engine oil
Oil quality	229.5
Viscosity	5W-40

Replaced / renewed

Dust filter replaced	<input checked="" type="checkbox"/>
Engine: oil and filter change	<input checked="" type="checkbox"/>
Brake fluid replaced	<input checked="" type="checkbox"/>

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with	<input checked="" type="checkbox"/>
---------------	-------------------------------------

Addwork in accordance with Mercedes-Benz AG specification

Accomplished	<input checked="" type="checkbox"/>
--------------	-------------------------------------

Comment

Replaced windscreen wipers



Mercedes-Benz

Service report 2

Mercedes-Benz	RFW Holdings Pty Ltd as trustee for The Robert Wann Family Trust 884 South Road Edwardstown	Date Rep.-order-no. Mileage	20.12.2021 14010479 29319 km
---------------	--	-----------------------------------	------------------------------------

Performed services

Service	Service B
Workshop code	606
Remaining time	-5 Days
Remaining distance	7724 km

Oil quality/viscosity

Description	Engine oil
Oil quality	229.5
Viscosity	5W-40

Replaced / renewed

Dust filter replaced	<input checked="" type="checkbox"/>
Engine: oil and filter change	<input checked="" type="checkbox"/>

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with	<input checked="" type="checkbox"/>
---------------	-------------------------------------

Addwork in accordance with Mercedes-Benz AG specification

Accomplished	<input checked="" type="checkbox"/>
--------------	-------------------------------------

Comment

Updated navigation



Mercedes-Benz

Service report 1

Mercedes-Benz	RFW Holdings Pty Ltd as trustee	Date	15.12.2020
	for The Robert Wann Family Trust	Rep.-order-no.	14008653
	884 South Road	Mileage	12043 km
	Edwardstown		

Performed services

Service	Service A
Workshop code	505
Remaining time	53 Days
Remaining distance	13200 km

Oil quality/viscosity

Description	Engine oil
Oil quality	229.5
Viscosity	5W-40

Replaced / renewed

Dust filter replaced	<input checked="" type="checkbox"/>
Engine: oil and filter change	<input checked="" type="checkbox"/>

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with	<input checked="" type="checkbox"/>
---------------	-------------------------------------

Addwork in accordance with Mercedes-Benz AG specification

Accomplished	<input checked="" type="checkbox"/>
--------------	-------------------------------------

Comment

Updated navigation to version 9 2021



Mercedes-Benz

Service history

Mercedes-Benz	Niplag Pty. Ltd. as trustee for The Carlin & Gazzard Trust Crouch Street South 5-11 Mount Gambier	Date Mileage Service	17.12.2024 68329 km Service A
Mercedes-Benz	RFW Holdings Pty Ltd as trustee for The Robert Wann Family Trust 884 South Road Edwardstown	Date Mileage Service	24.10.2023 56028 km Service B
Mercedes-Benz	RFW Holdings Pty Ltd as trustee for The Robert Wann Family Trust 884 South Road Edwardstown	Date Mileage Service	28.10.2022 41583 km Service A
Mercedes-Benz	RFW Holdings Pty Ltd as trustee for The Robert Wann Family Trust 884 South Road Edwardstown	Date Mileage Service	20.12.2021 29319 km Service B
Mercedes-Benz	RFW Holdings Pty Ltd as trustee for The Robert Wann Family Trust 884 South Road Edwardstown	Date Mileage Service	15.12.2020 12043 km Service A