

## CP533E CATERPILLAR PADFOOT ROLLER

YEAR	2011
PIN.	CATCP533KTLH00229
SERIAL No.	TLH00229
ENGINE No.	CST02638
ENGINE MODEL	3054C
MODEL	CP533E
ID No.	503
CONDITIONAL REGO No.	NIL
CONDITIONAL REGO EXPIRY	NIL
UPDATED	12/02/2024

DATE	HOURS	JOB / SERVICE TYPE	SERVICE / REPAIR DETAIL
19/04/2016	535	Pre-start	
29/04/2016		Pre-start	
6/05/2016	541	Pre-start	
18/05/2016		Klaus	Supply & fit reverse camera & wire up
24/06/2016	549	Pre-start	
1/07/2016	552	Pre-start	
4/07/2016	552	Pre-start	
12/07/2016	-	R9790	On hire from William Adams Victoria
30/07/2016	560	Pre-start	
30/07/2016	562	Pre-start	
4/08/2016	563	Pre-start	
12/08/2016	575	Pre-start	
18/08/2016	596	Pre-start	
27/08/2016	606	Pre-start	
31/08/2016	608	Pre-start	
9/09/2016	619	Pre-start	
16/09/2016	629	Pre-start	
23/09/2016	631	Pre-start	Seatbelt seized.
28/09/2016	645	Pre-start	
28/09/2016	646	General	Topped up hydraulic oil, lockable isolator fitted, battery holder repaired.
7/10/2016	679	Pre-start	
15/10/2016	657	Pre-start	
21/10/2016	683	Pre-start	

24/10/2016	693	General	Scraper bars adjusted.
25/10/2016	700	Pre-start	
11/11/2016	710	Pre-start	
17/11/2016	717	Pre-start	
21/11/2016	717	Pre-start	
2/12/2016	717	Pre-start	
14/12/2016	719	Pre-start	
21/12/2016	732	Pre-start	
17/01/2017	744	Pre-start	
1/02/2017	750	Pre-start	
29/03/2017		Fuel truck	Greased
13/04/2017			
12/05/2017		Jennings	Replace front glass
17/05/2017		Autowise	Call out to yard, Remove & replace damaged AM/FM & UHS antennas, Drill out existing holes to fit new bases, Call out service fee, 2 x Base CB vehicle mount, Antenna CB 27MHZ 320mm, Aerial 15cm 477MHZ, 3 x Labour R&R 2X2 hrs
19/05/2017		Pre-start	Rear cover will not close
24/05/2017		Fuel truck	Greased
1/06/2017	780	Pre-start	No beacon - Fitted 7/06/2017
21/06/2017	783	Pre-start	
13/07/2017	788	Pre-start	
21/07/2017	796	Urgent	Fit new batteries (stolen)
21/07/2017	796	Pre-start	Batteries, fire extinguisher, beacon missing - stolen overnight.
19/08/2017	807	Pre-start	No fire extinguisher, low coolant - topped up, low eng oil.
23/08/2017		Fuel truck	Greased
24/08/2017		Fuel truck	Greased
25/08/2017	818	Pre-start	Eng oil nneeds constant topping up.
1/09/2017	836	Pre-start	
8/09/2017	848	Pre-start	
21/09/2017		General	UHF faulty, requires new aerial & repair on unit.
25/09/2017		Illawarra Communications	On glass antenna
28/09/2017	879	General	Replace uhf antenna, fit new fire extinguisher & bracket.
18/10/2017		Fuel truck	Greased
3/11/2017		Fuel truck	Greased
10/11/2017	892	Service	Service machine, r & r lube,fuel, hyd & air filters, top up coolant & hyd oil, grease machine.

10/11/2017		SOS	
10/11/2017		SOS	
13/11/2017	892	SOS Sample	T120-47321-0320
13/11/2017	892	SOS Sample	T120-47321-0058
13/11/2017	892	SOS Sample	T120-47321-0008
13/11/2017	892	SOS Sample	T120-47321-0320
13/11/2017	892	SOS Sample	T120-47321-0058
13/11/2017	892	SOS Sample	T120-47321-0008
17/11/2017	896	Pre-start	Beacon not working (greased Fuel truck)
21/11/2017		Fuel truck	Greased
24/11/2017	916	Pre-start	
28/11/2017		Fuel truck	Greased
29/11/2017	925	General	Adjusted a/c & fan belts.
1/12/2017		Fuel truck	Greased
1/12/2017	933	Pre-start	Slow leak from rhs of drum.
16/12/2017	936	Pre-start	
22/12/2017	940	Pre-start	Engine oil low, slow leak rhs drum.
5/01/2018	950	Pre-start	
11/01/2018	970	Fuel truck	Greased
12/01/2018	975	Pre-start	Front r/h windscreen cracked
20/01/2018	985	Pre-start	Cracked windscreen, slight oil leak rhf drum
25/01/2018	986	Pre-start	Park brake button broken, crack in windscreen, oil leak in drum.
16/02/2018	989	Pre-start	
21/02/2018	990	Pre-start	
22/02/2018	993	Pre-start	
3/03/2018	1004	Pre-start	Cracked windscreen
7/04/2018	1007	Pre-start	Cracked windscreen
12/04/2018	1008	Pre-start	
13/04/2018		Fuel truck	Greased
20/04/2018	1011	Pre-start	
11/05/2018	1011	Pre-start	
24/05/2018	1018	Pre-start	Greased - Fuel truck, crack in r/h windscreen, oil leak inside drum rhs
8/06/2018	1019	General	Checked over machine, tested a/c - found fault present, a/c spins free with belts off. Tightened oil level plug rhs of drum
21/06/2018		General	Checkover, fit new battery holdown stud, nut & washer.

<b>4/07/2018</b>	1020	General	Repair extinguisher bracket & fit inspected extinguisher, checkover machine - ok. Greased ( fuel truck )
<b>12/07/2018</b>	1020	General	Reseal vibratory motor mounting, repair burst protection, repaired front & rear window washers, repaired battery conections, checked over & greased, test drove - ok.
<b>13/08/2018</b>	1031	General	Blew out eng air & changed cab air filters, topped up eng oil, repair UHF cable, checked fluid levels & greased.
<b>10/09/2018</b>		Fuel truck	Greased
<b>27/09/2018</b>		Fuel truck	Greased
<b>29/10/2018</b>	1149	General	Check over, Replace wiper blades, Repair A/C
<b>11/04/2019</b>	1163	General	Refit new turbo, greased, check over of fluids lights ect, remount and date fire extinguisher. Repair rear hatch handle, blow out engine and cab filters.
<b>6/05/2019</b>	1802.2	Pre-start	
<b>7/05/2019</b>	1808.8	Pre-start	
<b>13/05/2019</b>	1827.7	Pre-start	
<b>15/05/2019</b>	1832.5	Pre-start	
<b>2/08/2019</b>	1213.5	Pre-start	
<b>6/08/2019</b>	1216.1	Pre-start	
<b>8/08/2019</b>	1220.9	Pre-start	
<b>9/08/2019</b>	1224.8	Pre-start	
<b>13/08/2019</b>	1226	Pre-start	
<b>14/08/2019</b>	1228.9	Pre-start	
<b>15/08/2019</b>	1232	Pre-start	Radio will short out once the button is pressed on the hand held device. Shorts both the radio and the stereo out but will turn back on when u let go of the button . Radio is fine in other machines
<b>16/08/2019</b>	1236.3	Pre-start	
<b>19/08/2019</b>	1241.2	Pre-start	
<b>20/08/2019</b>	1241.5	Pre-start	
<b>21/08/2019</b>	1245	Pre-start	
<b>22/08/2019</b>	1249	Pre-start	
<b>23/08/2019</b>	1251	Pre-start	
<b>3/09/2019</b>	1253	Pre-start	
<b>6/09/2019</b>	1263.7	Pre-start	
<b>9/09/2019</b>	1265.8	Pre-start	
<b>11/09/2019</b>	1268.3	Pre-start	
<b>12/09/2019</b>	1270	Pre-start	
<b>13/09/2019</b>	1270.5	Pre-start	
<b>16/09/2019</b>	1272	Pre-start	

19/09/2019	0	General	R/H side slid window
19/09/2019	0	General	R/H side slid window
25/09/2019	1273.3	Pre-start	
30/09/2019	1273	Pre-start	
1/10/2019	1274	Pre-start	
3/10/2019	1275.7	Pre-start	
8/10/2019	1278.5	Pre-start	
14/10/2019	1279	General	Check A/C system. Works fine. Greased and checked over. Repair battery cable.
17/10/2019	1279	Pre-start	
18/10/2019	1280	Pre-start	
23/10/2019	1283.3	Pre-start	
1/11/2019	1286	Pre-start	
4/11/2019	1287	Pre-start	
11/11/2019	1288	Pre-start	
22/11/2019	1293.2	Pre-start	
28/11/2019	1296.7	Pre-start	
4/12/2019	1297.9	Pre-start	
5/12/2019	1298.4	Pre-start	
9/12/2019	1299	General	Blow out filters, check fluids, repair 2way airial , greased
25/02/2020	1301	Pre-start	
17/03/2020	1303	Pre-start	
24/03/2020	1306	Pre-start	
6/04/2020	1317	General	Adjust belts. Grease machine. Check oils.
22/04/2020	1317	Pre-start	
21/05/2020	1336	Urgent	Replace UHF radio power cable due to corrosion.
6/07/2020	1337.5	Pre-start	
9/07/2020	1342.2	Pre-start	
10/07/2020	1343	Pre-start	Crack in top right windscreen
31/08/2020	1345	Pre-start	
3/09/2020	1348	Urgent	Repair A/C system. Faulty blend valve. Blow out filters and coolers. Check oils and grease
3/09/2020	1347	Pre-start	Air con does not work well on cold settings.
8/09/2020	1356	Pre-start	
16/09/2020	1364.4	Pre-start	
17/09/2020	1367	Urgent	Adjust bonnet latch. Inspect reverse camera system. New camera required
17/09/2020	1366	Pre-start	Flashing light not working Rear latch keeps opening if not locked
24/09/2020	1368	Pre-start	

29/09/2020	1374.3	Pre-start	
30/09/2020	1376.5	Pre-start	
11/12/2020	1388.4	Pre-start	
10/02/2021	1393	Pre-start	
12/02/2021	1395	Pre-start	
15/02/2021	1396	Service	Engine oil and filter, fuel filter, fuel water separator, blow out filters, stamp fire extinguisher, greased and check over
16/02/2021	0	Service	1xCAT ED ROLLER R/H WING GLASS, 1xURETHANE GLUE SEALER, 1xSEALER CLEAR
12/04/2021	1396.6	Pre-start	
19/04/2021	1399	Pre-start	
20/04/2021	1401.7	Pre-start	
20/05/2021	1402	Pre-start	
24/05/2021	1403.8	Pre-start	
27/05/2021	1404	Pre-start	
23/06/2021	1406	Pre-start	
24/06/2021	0	Insurance Claim	POS:3.4 FITTER:COOKES TYRES DATE:21/6/21 LOCATION:CURRARONG ZLCALLOUT STEFANUTTI JOB AT CURRARONG 2 X 23.1-26 ANCENSO R3 DIAMOND 2 X STRIP AND FIT 4HRS RD SERVICE
27/07/2021	1412	Service	Service machine. Replace vibratory support oil. Repair flashing light
4/08/2021	0	Tyres	WATERFILL 23.1R25 TYRES POS:3.4 FITTER:GREG DATE:26/7/21
19/08/2021	1490	General	A/c not working - broken wire to pressure switch repaired, replaced coolant bottle, cleaned out coolers
21/09/2021	1598	General	Start fault - broken wire from neutral relay to starter solenoid - ran new wire
3/11/2021	1695	General	Belts squealing - tighten belts, a/c not working- repaired broken wire to compressor
2/12/2021	2900.7	Pre-start	Right quarter windscreen is cracked Oil leaking from the rocker cover
21/12/2021	5000	Service	REPAIR VIBRATOR DRIVE, COMPLAINT: LEAKING COMPONENT CAUSE: DAMAGED SEAL RESULTANT DAMAGE: LOSS OF OIL THREAD ON SPINDLE WAS DAMAGED AND THE NEW NUT WOULDN'T GO ON SMOOTHLY HAD TO CAREFULLY FORCE WITHOUT DAMAGING THE SPINDLE OR NUT - FILE AND DRESS THREADS (CAUSED FROM CUSTOMER TRYING TO PREVIOUSLY REMOVE) CORRECTION: SET UP ALL PRESSING GEAR TO DISASSEMBLE COMPONENT DISASSEMBLE AS PER CAT PROCEDURE NOTICED CUSTOMER HAS TRIED TO REMOVE NUT THEMSELVES AS THERE WAS DAMAGE TO THE SPINDLE AND NUT THREAD HEAT BOTTOM BEARING OFF SPINDLE TO REPLACE SEAL THREADS ON SPINDLE WHERE DAMAGED, HAD TO CLEAN UP THREADS AS BEST AS POSSIBLE BEFORE ASSEMBLY WASHED SPINDLE TO REMOVE ALL CARBON FROM REMOVING THE BEARING FOLLOW SIS PROCEDURE AND START REASSEMBLING COMPONENT
16/02/2022	0.17285	Pre-start	
17/02/2022	1732	Pre-start	

22/04/2022	1748.7	Pre-start	
27/04/2022	0	Service	Exchange of : 1x9.0KG ABE Fire Extinguisher
2/05/2022	1752.2	Pre-start	
2/05/2022	1752	Pre-start	
4/05/2022	1755.7	Pre-start	
9/05/2022	1755.7	Pre-start	
17/05/2022	1759	Pre-start	
18/05/2022	1762	Pre-start	Crack in front window
19/05/2022	1764	Urgent	Hyd leak rh front - vibration motor to hose o-ring leaking - replaced o-ring and top up hyd oil
19/05/2022	1736	Pre-start	Crack in front window
20/05/2022	1765	Pre-start	Crack in front window
23/05/2022	1766	General	Replaced leaking orings in hoses for vibration motor
23/05/2022	1766	Pre-start	Crack in front window
24/05/2022	1768	Pre-start	Crack in front window
25/05/2022	1772	Pre-start	Window cracked
25/05/2022	1772	Pre-start	
26/05/2022	1774	Pre-start	
8/06/2022	1776	Pre-start	Crack in front window
9/06/2022	1777.2	Pre-start	
10/06/2022	1780.1	Pre-start	Crack in front windshield
15/06/2022	1781.6	Pre-start	Front window has a crack in it
16/06/2022	1784	Pre-start	Crack in front window
17/06/2022	1784.3	Pre-start	Crack in windshield
21/06/2022	1786	Pre-start	
22/06/2022	1787	Pre-start	Crack in front window
27/06/2022	2914.3	Pre-start	
27/06/2022	1789.1	Pre-start	Crack in windscreen
28/06/2022	1789	Pre-start	Crack in front window
30/06/2022	1789.5	Pre-start	
15/07/2022	1790	Pre-start	Crack in front window
18/07/2022	1790	Pre-start	Crack in front window
19/07/2022	1791	Pre-start	Crack in front window
21/07/2022	1792	Pre-start	Crack in front window
22/07/2022	1793	Pre-start	Crack in front window
26/07/2022	1794	Pre-start	Crack in front window
27/07/2022	1796	Pre-start	Crack in front window

<b>28/07/2022</b>	1797	Pre-start	Crack in front window
<b>29/07/2022</b>	1797	Pre-start	Crack in front window
<b>11/08/2022</b>	1803	Pre-start	Crack in front window
<b>12/08/2022</b>	1803	Pre-start	Crack in front window
<b>7/09/2022</b>	1811	Pre-start	Crack in front window
<b>10/10/2022</b>	18120	Pre-start	
<b>11/10/2022</b>	1815.5	Pre-start	
<b>24/10/2022</b>	1829	Pre-start	Roof at rear has a leak water all over floor
<b>9/11/2022</b>	1829	General	Checkover and grease machine
<b>27/01/2023</b>	1905	Pre-start	
<b>3/02/2023</b>	1917	Pre-start	
<b>6/02/2023</b>	1917	Urgent	Ignition barrel had snapped key replacement cat barrel assemble fitted
<b>24/02/2023</b>	1933	Pre-start	Back window not sealed at the bottom Crack in front window
<b>2/03/2023</b>	1942	Pre-start	Crack in front window, back window not sealed
<b>8/03/2023</b>	1946	Pre-start	Crack in front window back window not sealed at the bottom
<b>13/03/2023</b>	3056	Urgent	Not starting - found faulty fuel level sender.
<b>28/03/2023</b>	1950	General	Replace broken work lights, checkover
<b>1/05/2023</b>	1967.2	Pre-start	
<b>26/07/2023</b>	0	General	It is a service. Baileys Injector test
<b>3/08/2023</b>	1985.8	Pre-start	
<b>4/08/2023</b>	1985	General	Replaced 4x worn hydraulic hoses from pump front drive motor
<b>4/08/2023</b>	1985	Urgent	Faulty injectors - replaced 4x injectors
<b>4/08/2023</b>	1985	Service	Service engine due to fuel in engine oil
<b>4/08/2023</b>	1986.9	Pre-start	
<b>7/08/2023</b>	1980.8	Pre-start	
<b>8/08/2023</b>	1990	Pre-start	
<b>9/08/2023</b>	1993	Pre-start	
<b>11/08/2023</b>	1994.1	Pre-start	
<b>28/09/2023</b>	1997	General	grease machine