

Work Order	Start Date	Description
83022		grease blocks for arms u/s
83671		carousel needs rod fingers , not tube fingers
83673		wiper blades need changing
83936		drifter bed binding on rail
84018		metre counter, pen rate & auto drill not working
84925		air mist u/s
85436		l/h light u/s
85728		a/c fan only woking on stage 3
85730		hole depth intermittent
85733		gas strut u/s
85930		rock guard
86065		pito jaws need welding up
86535		carousel rotation ,rod arms & jaws all creeping
87244		l/h door latch will not open from outside
87423		grease line rod arms u/s
87424		grease reel will not lock
88698		bracket missing from bottom of rail for hose loom
88836		long arms creeping
88837		grease pump not working
88838		cradle sticking bottom of rail
90811		hole depth and rod counter playing up
93239		drifter bed sticking on v slides
93498		gas strut rock guard u/s
93499		light under tray u/s
93500		a/c fan u/s
93647		need new wiper blade
95741		rail washers not working
97358		gripper arms creeping out
98585		rod alignment out to drifter & pito
98586		hole depth /rod counter u/s
98794		rear rope pulley bearing u/s
98795		air compressor overheating
99970		bolt missing from back plate
100100		pito cylinder sloppy
101597		front wiper blade u/s
102011		pressure washer gun missing & hose reel leaking
103111		two lights not working
103383		pressure washer hose u/s
105931		auto drilling still playing up
106234		no handle on air tap
106235		pressure washer u/s
106847		pito cylinder eye flogged out
107759		grease pump shaft not long enough
107760		rod alignment out
108148		gerni wheel will not lock
108149		need bracket to hold spare shank
109194		top stinger creeping

109334		geri pissing from inlet
109488		carousel sticking when indexing
112475		cutting guard getting caught in gripper arm
112476		grease lines u/s
112477		stingers sloppy
116508		auto rod pulling missing sequence
116509		check service date on fire extinguisher
116719		rod tray bent
117317		pressure washer u/s
117765		rods not lining up at pito jaws
119054		front wiper blade u/s
120554		pressure washer u/s
120694		rod arms creeping
121109		oil transfer pump not working again
121541		r/h door latch broken
122626		rollover creeps when powered done
123468		l/h handrail on cab bent
123992		gerni u/s elbow
124141		seatbelt jamming up
125873		a/c needs checking
125874		pressure washer u/s spraying water out front
126146		rods not lining up
128964		grease pump
130003		oil leak from box on boom
130004		dip & dump sensors out by 1.5 degree
130592		missing guide bush from front stinger tube
131752		top stinger creeps
132894		cracked r/h window
133285		main grease nipple to pito & rollover
133423		a/c not working very well
133612		main water hose split
133998		left front light out
134459		front stinger creeps
135339		guard u/s on front jack
135341		front wiper u/s
135516		locking pin bolt missing in gripper arms
136604		main work lights u/s
138552		slop adjustment disc missing from front stinger
138747		a/c u/s
138748		r/h/f tyre cut
139345		pressure washer
139346		cradle sprays
139480		gripper arm bushes flogged out
139481		r/h door will not close latch u/s
139959		spiders bent
141616		back plate bolt
142777		r/h door latch not closing properly
142778		a/c needs checking

145573		a/c not working
147092		cover missing off top gripper
147095		long arm u/s
148975		two work light keeps going out
149524		water pump seal broken
151530		no rear wipers
152486		rail sprays not working
154574		depth counter not working
155291		joy stick sloppy
155608		air compressor belt loose
155671		bottom of carousel needs welding
156642		pito sloppy
156855		broken bolt in back of drifter
157023		top cover off grippers
158054		front work light yellow
158250		pito jaw grease block u/s
160094		top stinger bypassing
168536		pressure washer not working
169402		front rail sprays u/s
169850		Top Pitto block not taking grease
169909		Check top stinger in, is creeping down.
170784		grease nipples on arms not taking grease
171101		Pitto jaws seem out
172654		Ram leaky oil?? gripper arm cyl
174649		top stinger not holding
175256		Jaws on long arm - sensors not working
175300		Auto drill not working
177074		top stinger not holding
177615		pressure washer hose u/s
177631		seat air pump u/s
179287		zoom seals u/s
180023		front window cracked
187553		seat not locking in the centre position(crooked)
189463		hole in water hose on reel
189732		cracked r/h door window
189733		auto drill not working
191909		a/c hyd oil leaking out of motor
193308		carosel keeps indexing around on auto after
194537		engine derating when tramming
197315		Grease line on pito ram broken
197316		Pito jaws keep coming loose
199634		right hand door broken bottom hing
199636		Crack in drifter carrier
199637		RHS window broken
199738		Vent in cab broken
201253		r/h door cracked
204662		a/c not working
208161		air pressure gauge in cab u/s

208697		water ose reel not working
209206		hose on water reel u/s need new 60m hose
210618		oil leak back of drifter
211390		switch on a/c u/s
214631		Rods not lining up on shank
220811		right door window cracked
221599		air & oil pissing out of tell tail flushing head
224566		l/h joy stick not locking in properly
227296		fan belt needs replacing (none in stock 16722)
228230		front wiper not working properly
230462		will not uncouple on auto
236230		rear wiper doesnt touch window
244374		window washers not working
250869		reverse lights not working
251183		rig not starting well winding over for a long time
252176		rig still hard to start on diesel
252574		no auto drill
253465		rig still hard to start on diesel
253909		back cab lights not working
257363		drifter not going all the way back on auto
262283		a/c needs checking
263134		pito not holding
269289		wire guard on front of fan needs replacing
272405		lights need fixing front & back
273009		pressure washer u/s
273610		water not shutting off on drifter
276317		fire supression low
277825		r/h emegency stop broken
287504		artic cable broken
287505		flushing seals u/s
290359		auto pull u/s keeps indexing
297197		r/h front jack leg leaking
303003		front windscreen wipers u/s
555657	31-Oct-00	500HR HL710 DRIFTER CHANGE OUT FOR DRILLS
73219	20-Mar-09	Install Radio on Rig.
73436	20-Mar-09	do electrical inspection of new long hole rig, LH04
73537	23-Mar-09	Fit labels, touch up paint, inspect for UG use
73612	24-Mar-09	pre down the hole inspection and two way fit
73539	25-Mar-09	Install no welding signs on Longhole Rig 04
73831	25-Mar-09	Adjust rod handler to suit T45 rods
73850	25-Mar-09	blown hose
73782	26-Mar-09	DAILY SERVICE & INSPECTION
73893	26-Mar-09	Check the water pump operation
73792	31-Mar-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
73876	31-Mar-09	fast feed set too fast
74116	31-Mar-09	rod guide bottom gripper bent
73829	1-Apr-09	make up box and hose half clamp
74408	2-Apr-09	DAILY SERVICE & INSPECTION

74421	3-Apr-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
74654	5-Apr-09	blown hose
73766	6-Apr-09	crack in side window
74420	7-Apr-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
74988	7-Apr-09	Repalce card VME/CPU card as old card only has two modules
75123	9-Apr-09	DAILY SERVICE & INSPECTION
74551	10-Apr-09	t58 thread on rear stinger , need t45
75311	10-Apr-09	adjust feed ropes calibrate linear sensor
74237	14-Apr-09	need lube flow site glass and air water mist valve
74866	14-Apr-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
74466	16-Apr-09	pressure washer has hole in pipe on valve block
75746	16-Apr-09	DAILY SERVICE & INSPECTION
75854	16-Apr-09	repairs to rod handeler
75999	20-Apr-09	replace broken fitting
75779	21-Apr-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
76317	21-Apr-09	Adjust tight slides
75611	22-Apr-09	tilt cylinder creeps
76377	23-Apr-09	DAILY SERVICE & INSPECTION
76465	23-Apr-09	Replace broken feed rope
76797	27-Apr-09	fit return and feed rope
76410	28-Apr-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
76411	28-Apr-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
76834	28-Apr-09	r/h bottom door hinge
76947	28-Apr-09	overcentre valves for lift cyl
77095	29-Apr-09	air comp cutting out on high temp
77032	30-Apr-09	DAILY SERVICE & INSPECTION
77351	30-Apr-09	replace blown hose
77352	30-Apr-09	Replace blown hose
77557	2-May-09	Faulty gripper arm cylinder
77569	2-May-09	repair rod grippers
77573	3-May-09	Adjust sensors S34 & S35 on boom
77641	4-May-09	called down to LH04 at 4820, counter sensor not working
77074	5-May-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
77792	5-May-09	FOPS had hole drilled through it
77818	6-May-09	blown hose
77971	6-May-09	Check rig for air pressure problem
77972	6-May-09	Replace blown hose
77980	6-May-09	replace blown hose
77880	7-May-09	DAILY SERVICE & INSPECTION
78203	8-May-09	blown hose 7m long along loom
78337	10-May-09	blown hose
77931	12-May-09	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
77932	12-May-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
78549	12-May-09	lost power at 4820 ,jbox door pushed open with percussioin.
78788	13-May-09	fit bush on rod handler
78707	14-May-09	DAILY SERVICE & INSPECTION
78708	14-May-09	6 MONTHLY AIR COMPRESSOR SERVICE
78860	15-May-09	work order made up to book out a set of pito jaws for

78373	18-May-09	Make up spare stinger extension adapters
79054	18-May-09	C/O compressor - Bendigo Air & Hyd to do job Mon 18th
79182	18-May-09	make up and fit steel rack
78750	19-May-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
79471	20-May-09	module fault.
79404	21-May-09	DAILY SERVICE & INSPECTION
79858	24-May-09	fit blown hose
79443	26-May-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
79444	26-May-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
80243	27-May-09	move cable for long hole rig in the central4940
80251	27-May-09	auxillary contacts on main isolator rattled of reinstall
80108	28-May-09	DAILY SERVICE & INSPECTION
80547	29-May-09	Replace blown hose
80523	30-May-09	loosing oil cant find where from
80568	30-May-09	repair blown hose and broken fitting
79918	1-Jun-09	fit anti-fatigue mat in cab
80146	2-Jun-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
80277	2-Jun-09	rear window broken
80679	2-Jun-09	broken fittings and blown hose
80162	3-Jun-09	Replace cd player
80819	3-Jun-09	recalibrate clinos
80870	4-Jun-09	DAILY SERVICE & INSPECTION
81250	5-Jun-09	blown hose
80909	9-Jun-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
81563	9-Jun-09	blown hose on drifter dash 12 1.0m
81575	9-Jun-09	Blown hose under carrier. Large one with pin hole.
82077	9-Jun-09	To cover cost of Pirtek making hose. Job done on 081575
81624	11-Jun-09	DAILY SERVICE & INSPECTION
81922	11-Jun-09	repair air flush valve
81933	11-Jun-09	fault on GUI panel, sensor comms error.
81993	12-Jun-09	lost angle readings on GUI, fault code sensor comms error.
82001	13-Jun-09	check clinos
82043	13-Jun-09	replace hose
82024	14-Jun-09	Broke RHS joystick on GUI pannel, replace joystick.
82028	14-Jun-09	repair joy stick
82057	15-Jun-09	repair joy stick
82098	15-Jun-09	check electrics
82107	15-Jun-09	sensor comms fault. found damaged cable at B26 sensor
82113	15-Jun-09	low water pressure
82262	16-Jun-09	called down to solo 4 , water pump not working, checked the
82319	18-Jun-09	DAILY SERVICE & INSPECTION
82437	18-Jun-09	Replace flat tyre
81606	19-Jun-09	rail sprays off
81666	19-Jun-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
82700	20-Jun-09	adjust drifter slides
82720	20-Jun-09	blown hose
82361	23-Jun-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
82362	23-Jun-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL

83040	25-Jun-09	DAILY SERVICE & INSPECTION
83385	25-Jun-09	fit blown o-ring on drifter fitting
83391	25-Jun-09	pilot fault jack pressure switch
83554	26-Jun-09	Found loose hyd hose tightened hose, adjust jack pressure
83615	28-Jun-09	blown hose
83080	30-Jun-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
83856	1-Jul-09	Cancelled during entry
83858	1-Jul-09	rope and repairs (rope from out back)
83969	1-Jul-09	replace blown hose
83886	2-Jul-09	DAILY SERVICE & INSPECTION
83993	2-Jul-09	calibrate clinos
84036	2-Jul-09	fit pin and bushes to grippers
83935	3-Jul-09	windscreen washers u/s
84110	4-Jul-09	Check water and air mist operation
84136	5-Jul-09	Replace pos 2 trye
84139	5-Jul-09	REPAIR FRONT STINGER CYL
84240	6-Jul-09	fit air mist gauge
83924	7-Jul-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
84442	7-Jul-09	free up air valve
84503	9-Jul-09	DAILY SERVICE & INSPECTION
84079	10-Jul-09	fit struts to front window guard
84517	10-Jul-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
84956	10-Jul-09	replace flushing valve
84959	10-Jul-09	replace air mist valve
84973	11-Jul-09	Replace blown hose
84994	12-Jul-09	Rebuild pito jaws
85100	13-Jul-09	sensor comms error, 130.
84205	14-Jul-09	grease nipples on feed ext cylinder
84421	14-Jul-09	order spare stinger parts
84542	14-Jul-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
85469	15-Jul-09	blown accumulator
85379	16-Jul-09	DAILY SERVICE & INSPECTION
85658	18-Jul-09	blown hose
85056	20-Jul-09	Replace faulty air mist valve
85421	21-Jul-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
85781	21-Jul-09	fit blown hose
86015	23-Jul-09	DAILY SERVICE & INSPECTION
86120	23-Jul-09	fit pito jaws
86446	25-Jul-09	repair oil leak(fittings)
86461	25-Jul-09	Replace blown hose
86470	25-Jul-09	fault code B7 on Gui panel. wouldnt drill in auto.
86497	26-Jul-09	Repair air mist fault
86051	28-Jul-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
86742	30-Jul-09	DAILY SERVICE & INSPECTION
86757	31-Jul-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
87136	31-Jul-09	fit pin and bushes to gripper arm
87266	3-Aug-09	check feed
87490	4-Aug-09	check auto drilling

87554	6-Aug-09	DAILY SERVICE & INSPECTION
87569	7-Aug-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
88029	9-Aug-09	move location and lost pilot, and rod counter not working.
88281	11-Aug-09	repaired rod handlers and daily
87617	12-Aug-09	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
88439	12-Aug-09	parts for carusel
88456	12-Aug-09	Replace blown hose
88358	13-Aug-09	DAILY SERVICE & INSPECTION
88371	14-Aug-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
88372	14-Aug-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
88770	14-Aug-09	change pitto jaws
88728	15-Aug-09	re-gas accumulators
88790	16-Aug-09	lh04 reported to have fault 130 ,27, and 35 sent sparky
88867	17-Aug-09	Fit hyd filler from jb01 to lh04
88980	18-Aug-09	fit air cond switch
89004	18-Aug-09	refit bracket boom air mist fault
89177	19-Aug-09	Check air mist operation
89191	19-Aug-09	Refit feed rope and adjust
89053	20-Aug-09	DAILY SERVICE & INSPECTION
88835	21-Aug-09	pitto cylinder pins & bushes sloppy
89069	21-Aug-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
89805	26-Aug-09	daily and blown hose
89867	27-Aug-09	DAILY SERVICE & INSPECTION
89954	27-Aug-09	replace 2x blown hoses and daily
90003	27-Aug-09	fit 2x blown hoses
90009	27-Aug-09	check auto drill
90025	27-Aug-09	blown hose carrier
89881	28-Aug-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
90061	28-Aug-09	fit feed rope
90066	28-Aug-09	retension feed ropes
90110	29-Aug-09	feed ropes jumped off rods stuck up hole tramming up
90125	30-Aug-09	fit feed ropes
90839	2-Sep-09	check rod counter repair water valve
90747	3-Sep-09	DAILY SERVICE & INSPECTION
90917	3-Sep-09	had to replace trailing cable on solo 4, underground
90763	4-Sep-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
90232	7-Sep-09	fit deflector rubber to elephant ear
90696	9-Sep-09	rail weld on needs replacing
91514	9-Sep-09	blown hose
91376	10-Sep-09	DAILY SERVICE & INSPECTION
91602	10-Sep-09	MAKE NEW STINGER
91390	11-Sep-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
91391	11-Sep-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
91732	11-Sep-09	REPLACE REAR ROPE PULLEY BEARINGS
91885	12-Sep-09	drifter slides to tight adjust
91957	14-Sep-09	gripper arm jaw broken
92168	15-Sep-09	oil filler pump bleed
92272	17-Sep-09	DAILY SERVICE & INSPECTION

92365	17-Sep-09	check electrical fault
92374	17-Sep-09	system 130 fault on rig
92286	19-Sep-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
92506	19-Sep-09	blown hose
92510	19-Sep-09	Replace blown hose
92542	20-Sep-09	loosen drifter slides
76835	21-Sep-09	pressure washer and grease reel rachets keep
92882	23-Sep-09	blown hose and correct water fault
92895	23-Sep-09	start up generator for rig at portal
92938	24-Sep-09	DAILY SERVICE & INSPECTION
93044	24-Sep-09	parts for W/O 092882
93279	24-Sep-09	get auto drill working
93363	25-Sep-09	fit carousel gate check clino electrical fault
93375	25-Sep-09	replace cabeling on lh04
93408	26-Sep-09	jumpstart at ug cribroom
92953	27-Sep-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
93428	27-Sep-09	check angle sensor
93477	28-Sep-09	fit blown hose
93543	29-Sep-09	lh04 pilot fault found loose diode in the A cabinet
93698	29-Sep-09	repair lh04 rod handler sensor
93762	1-Oct-09	DAILY SERVICE & INSPECTION
93779	1-Oct-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
94007	1-Oct-09	fit gas struts to cab
94018	1-Oct-09	repair gripper arms
94046	2-Oct-09	was going out on low water pressure, cleaned pressure switch
94171	3-Oct-09	LH04 at 4900sth no power at jumbo box.
94207	4-Oct-09	check low air
94212	4-Oct-09	Replace hose
94288	6-Oct-09	Replace pito jaws and cylinder
94614	7-Oct-09	parts to repair rod handeler cylinder
94553	8-Oct-09	DAILY SERVICE & INSPECTION
94728	8-Oct-09	need new operator seat
94908	8-Oct-09	blown hose
94568	9-Oct-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
94569	10-Oct-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
94985	10-Oct-09	cut jammed drill steel from backs
95010	11-Oct-09	remove gripper arm assemble and weld broken housing and refi
95105	13-Oct-09	replace accumulator valve and regas
94949	14-Oct-09	water pressure cleaner hose u/s spitting
95073	14-Oct-09	hole depth / rod counter not working
95282	14-Oct-09	grease line (carousel box)
95308	14-Oct-09	replace broken accumulator bolts
95345	15-Oct-09	DAILY SERVICE & INSPECTION
95760	16-Oct-09	change feed ropes
95359	17-Oct-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
95794	17-Oct-09	Cancelled during entry
95830	18-Oct-09	build up pito jaws
95849	18-Oct-09	LH04 went out on E/L. meggered trailing cable, motors,

96125	20-Oct-09	blown hose and rebuild rod handler
96188	22-Oct-09	DAILY SERVICE & INSPECTION
96558	22-Oct-09	stinger end fitted made one up
96205	23-Oct-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
96579	23-Oct-09	Fit new pressure guage to pressure cleaner
96580	23-Oct-09	Fit new proxy switch to gripper arms
96593	23-Oct-09	fit front window wiper
96665	25-Oct-09	replace exhaust
96685	25-Oct-09	repair rod handler
96956	29-Oct-09	DAILY SERVICE & INSPECTION
96969	30-Oct-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
97509	1-Nov-09	Check stinger operation OK?
97535	2-Nov-09	low hydraulic oil and coolant
97651	3-Nov-09	rig is powered up but wont start power packs.
97895	5-Nov-09	DAILY SERVICE & INSPECTION
97909	6-Nov-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
98216	7-Nov-09	check perc fault
98227	8-Nov-09	regas accumulator
98474	9-Nov-09	adjust feed ropes
98828	11-Nov-09	fit blown hose
97971	12-Nov-09	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
98676	12-Nov-09	DAILY SERVICE & INSPECTION
98695	13-Nov-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
98696	13-Nov-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
99032	15-Nov-09	down on power
99150	16-Nov-09	LH04 at 4820sth rod counter not working.
99562	18-Nov-09	Check rod alignment when in autodrill
99573	18-Nov-09	repair carasoul movement
99471	19-Nov-09	DAILY SERVICE & INSPECTION
99582	19-Nov-09	assist fitters with sensor 30 alignment
99487	20-Nov-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
99841	20-Nov-09	replace rod handler pins and bushes
99885	21-Nov-09	rod alignment
99899	22-Nov-09	fit rh door lock
99998	23-Nov-09	fit pito jaws
100019	23-Nov-09	change jaws rod alignment
100121	24-Nov-09	tighten carousel rod gates
100139	24-Nov-09	blown orings and bolts acc low side
100175	26-Nov-09	DAILY SERVICE & INSPECTION
100341	26-Nov-09	error code 04 also mod04 on GUI.
100363	26-Nov-09	Replace ropes
100188	27-Nov-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
100577	27-Nov-09	clean and reterminate cables in R3and R4 boxes on LH04
100582	27-Nov-09	replace gripper jaws and pressure transducers
100935	3-Dec-09	DAILY SERVICE & INSPECTION
101222	3-Dec-09	jump start
100947	4-Dec-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
101329	4-Dec-09	Refit feed ropes to pulleys

101339	5-Dec-09	pirtek to bring out grease lines for rod handler
101785	8-Dec-09	pirtek dropped off grease line hose and fittings plus spare
101820	8-Dec-09	Replace hydraulic fitting
101947	9-Dec-09	rod alignment
101978	9-Dec-09	jumpstart
101987	9-Dec-09	replace blown hose
101884	10-Dec-09	DAILY SERVICE & INSPECTION
101897	11-Dec-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
101898	11-Dec-09	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
102218	11-Dec-09	6 MONTHLY AIR COMPRESSOR SERVICE
102270	12-Dec-09	blown hose
102686	17-Dec-09	DAILY SERVICE & INSPECTION
102701	18-Dec-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
103140	18-Dec-09	blown hose feed cyl
100315	19-Dec-09	gripper arms
103157	19-Dec-09	fit 2x xenon lights and wiper front
103158	19-Dec-09	repairs to rod handler
103611	20-Dec-09	compressor o/l burnt out bypassed o/l and disconnected
103811	23-Dec-09	check and repair high and low accumulator
103724	24-Dec-09	DAILY SERVICE & INSPECTION
103880	24-Dec-09	Long hole not starting on 1000v.
103738	25-Dec-09	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
103913	26-Dec-09	oil leak and jump start
104016	29-Dec-09	water reel bearings
104137	31-Dec-09	DAILY SERVICE & INSPECTION
104465	31-Dec-09	jumpstart
104155	1-Jan-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
104489	1-Jan-10	jump start
104509	2-Jan-10	JUMPSTART
104526	2-Jan-10	broken fittings on rod changer
104936	5-Jan-10	grease lines ripped off
105018	7-Jan-10	DAILY SERVICE & INSPECTION
105296	7-Jan-10	replace hose
105031	8-Jan-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
105032	8-Jan-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
105405	10-Jan-10	blown hose
105414	10-Jan-10	sensor 32 not working, dirty connections.
105693	12-Jan-10	replace blown feed hose
105850	13-Jan-10	check auto drill
105746	14-Jan-10	DAILY SERVICE & INSPECTION
105954	14-Jan-10	repairs to rod handler
105657	15-Jan-10	Replace front window
105759	15-Jan-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
106004	15-Jan-10	order long arm assembly for change out
106033	16-Jan-10	repair rhs joystick on lh04
106044	16-Jan-10	replace blown hyd hose
106079	18-Jan-10	replace 2 blown hoses
106080	18-Jan-10	repair rod gripper arms pin came out

106081	18-Jan-10	replace grease pump
105783	19-Jan-10	250 ENGINE HOUR SUPPLEMENT SERVICE OF DRILLS
106304	19-Jan-10	replace blown hose
106544	21-Jan-10	DAILY SERVICE & INSPECTION
106564	22-Jan-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
107006	23-Jan-10	boom repairs in general
106982	24-Jan-10	rod counter not working, reset counter.
107013	24-Jan-10	blown hose
107023	24-Jan-10	replace hose
107138	25-Jan-10	repairs to rod haneler and daily
107171	26-Jan-10	carasel shaft and bush replacement
107203	26-Jan-10	jump start
107353	27-Jan-10	replace pito jaws and daily
107374	27-Jan-10	repair pito jaws
107379	27-Jan-10	hyd oil leak
107388	27-Jan-10	called to long hole rig as no air. assisted operator to set
107268	28-Jan-10	DAILY SERVICE & INSPECTION
107432	28-Jan-10	rod alignment
107285	29-Jan-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
107810	1-Feb-10	fit 2x blown hoses
108130	3-Feb-10	replace blown hyd hose
108036	4-Feb-10	DAILY SERVICE & INSPECTION
108212	4-Feb-10	2 x hoses. Was plodded as 108175 but to such w/o
107979	5-Feb-10	l/h work light u/s
108051	6-Feb-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
108265	6-Feb-10	Replace feed ropes
108329	7-Feb-10	flushing seals and pito jaws
108387	8-Feb-10	repairs to rod handeler alignmment and wipers
108711	11-Feb-10	DAILY SERVICE & INSPECTION
108745	12-Feb-10	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
108746	12-Feb-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
108747	12-Feb-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
109211	12-Feb-10	replace brake treble valve and repair steering
109236	12-Feb-10	flushing head seals
109299	14-Feb-10	replace grease pump
109361	15-Feb-10	repair fitting for pressure wash
109517	16-Feb-10	replace flushing head seals
109546	16-Feb-10	blown hose pito jaws
109631	18-Feb-10	DAILY SERVICE & INSPECTION
109647	19-Feb-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
110200	22-Feb-10	S32 fault
110383	23-Feb-10	had to change out switches S32 and S34 auto rod
110487	23-Feb-10	change out flat tyre
110499	23-Feb-10	Repair oil leak at pito jaws
110506	24-Feb-10	pick up tyre for fitters from 4820 and bring up to
110581	24-Feb-10	blown hose
110409	25-Feb-10	DAILY SERVICE & INSPECTION
110426	26-Feb-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

110748	26-Feb-10	check air fault
110765	27-Feb-10	repair hose on water reel
110766	27-Feb-10	need air valve soleniod
110779	27-Feb-10	lh04 air pressure fault test and repair
111085	1-Mar-10	check condensor fans
111210	2-Mar-10	fit blown hose
111323	4-Mar-10	DAILY SERVICE & INSPECTION
111606	4-Mar-10	Repair oil leak
111186	5-Mar-10	replace fans on condenser /air con
111336	5-Mar-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
111751	6-Mar-10	adjust rod alignment
111756	6-Mar-10	repair hyd oil leak
111771	7-Mar-10	Replace blown hose
112045	9-Mar-10	drifter slides tight
112216	10-Mar-10	Slides are sticking
112260	10-Mar-10	blown water hose
112138	11-Mar-10	DAILY SERVICE & INSPECTION
112456	11-Mar-10	feed rope jumped off refit
112155	12-Mar-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
112156	13-Mar-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
112540	13-Mar-10	adjust clino
112648	15-Mar-10	tighten up junction box on boom
112813	16-Mar-10	WORK ORDER FOR MONTHLY ALLOCATION OF HYDRAULIC HOSES
113023	17-Mar-10	replace pito jaws
112933	18-Mar-10	DAILY SERVICE & INSPECTION
112949	20-Mar-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
113377	21-Mar-10	reported that left hand joystick was bent.
113555	22-Mar-10	Check operation of carasoul
113561	23-Mar-10	operator had trouble loading rods and an intermittant
113837	24-Mar-10	cut drill steel off shank U/G
113780	25-Mar-10	DAILY SERVICE & INSPECTION
113996	26-Mar-10	check loose electrical box
113798	27-Mar-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
114034	27-Mar-10	repair wiring for front stinger
114039	27-Mar-10	replace angle sensor
114037	28-Mar-10	find fault on stinger control and repair
114061	29-Mar-10	replace keeper bracket for gripper arm
114362	29-Mar-10	replace broken fitting
111040	30-Mar-10	airconditioner getting noisy & not always cold
114511	30-Mar-10	replace pito jaws
114709	31-Mar-10	replace 2 blown hosesand adjust pito
114609	1-Apr-10	DAILY SERVICE & INSPECTION
114634	3-Apr-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
114809	3-Apr-10	Replace leaking jack legs
114810	3-Apr-10	Replace pito jaw cylinder
114832	4-Apr-10	blown hose to pito jaws
114849	4-Apr-10	jump start
115366	7-Apr-10	blown hose

115229	8-Apr-10	DAILY SERVICE & INSPECTION
115422	8-Apr-10	replace missing rain cap for air filter
115694	9-Apr-10	pos 2 hub seal leaking
115706	9-Apr-10	replace fittings on pito jaws
115245	10-Apr-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
115246	10-Apr-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
115719	10-Apr-10	Replace front rope pulley bearings
115721	10-Apr-10	replace front driving lamp
115736	10-Apr-10	reclabriite clino
116075	13-Apr-10	replace cable to the b6 sensor
116109	13-Apr-10	calibrate clyno
110094	14-Apr-10	auto drilling not working
116276	14-Apr-10	this is a w order to book out materials used on the 13/4/10
116182	15-Apr-10	DAILY SERVICE & INSPECTION
116295	15-Apr-10	pilot fault . test and found pilot core o.k.4.5ohms. Problem
116589	16-Apr-10	rebuild ft stinger
116200	17-Apr-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
116563	17-Apr-10	tighten feed rope
116575	18-Apr-10	rebuild front stinger
116602	18-Apr-10	accumulator and hoses
116860	20-Apr-10	replace stinger wiper and plate
116976	22-Apr-10	DAILY SERVICE & INSPECTION
116997	24-Apr-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
117362	24-Apr-10	Replace flushing head seals LH04
117395	24-Apr-10	replace hyd hose
117425	25-Apr-10	replace blown hyd hose
117445	26-Apr-10	reste switches long and short prox
117461	26-Apr-10	repair oil leak and oil pump filler
117570	27-Apr-10	oil leak in cover at front box tram out to fix
117701	29-Apr-10	DAILY SERVICE & INSPECTION
118066	29-Apr-10	check water leak(carrier hose for serv day)
117719	1-May-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
118193	3-May-10	Replace faulty hydraulic filler pump
118432	4-May-10	Replace broken fitting
118613	5-May-10	Replace broken bolts in rear cover on drifter
118507	6-May-10	DAILY SERVICE & INSPECTION
118926	7-May-10	overhaul accumolor as req
118524	8-May-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
118525	8-May-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
118944	8-May-10	REPLACE POS 2 JACK LEG
118963	8-May-10	check why no start found 1 battery u/s and jump start
119013	10-May-10	RE-SEAL LOW PRESSURE ACC
119455	13-May-10	DAILY SERVICE & INSPECTION
119475	15-May-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
119885	15-May-10	change seat to truck air type
119892	16-May-10	change rope pully bearings
118567	17-May-10	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
119970	17-May-10	Make up new pressure washer hose

120108	18-May-10	Clyno faulty
120291	19-May-10	LH04 Replace tilt & rollover sensors cable. found S41, 30,
120206	20-May-10	DAILY SERVICE & INSPECTION
120520	20-May-10	replace worn pito jaws
120546	21-May-10	REPALE HYD FILL PUMP
120548	21-May-10	REPLACE RETURN ROPE PULLEY BEARINGS
120225	22-May-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
120626	23-May-10	hyd pump check fill oil tank hyd
120659	23-May-10	refit rod counter
120892	25-May-10	replace hyd hose and fitting
120970	27-May-10	DAILY SERVICE & INSPECTION
121136	27-May-10	Repair blocked lube passages in flushing head
121414	28-May-10	repair gripper cylinder
120989	29-May-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
121366	29-May-10	Replace blown hose
121421	29-May-10	blown hose
121580	30-May-10	Check integrity of AFFF system
121554	31-May-10	Repair blown hose
121919	2-Jun-10	top rod gripper arms need bushes & pins
121859	3-Jun-10	DAILY SERVICE & INSPECTION
122008	3-Jun-10	drifter lube fault
121320	4-Jun-10	Work order to repair spare tyres
122338	6-Jun-10	blown hose
121879	8-Jun-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
122604	8-Jun-10	WORK ORDER TO REPLACE DANFOSS COIL FROM WORKSHOP STORE
122653	8-Jun-10	fit gripper arm frame
122669	8-Jun-10	fit sensor on gripper arm
122674	8-Jun-10	water pump u/s
122866	9-Jun-10	disconnect and help the fitters with the pump on lh04
122749	10-Jun-10	DAILY SERVICE & INSPECTION
123011	12-Jun-10	daily and flushing seals
123252	14-Jun-10	hose bracket repairs
122750	15-Jun-10	6 MONTHLY AIR COMPRESSOR SERVICE
122772	15-Jun-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
122773	15-Jun-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
123448	15-Jun-10	fit pito jaws
123479	15-Jun-10	replace pito assy and general repairs
123637	16-Jun-10	over center valves needed for roll over
123575	17-Jun-10	DAILY SERVICE & INSPECTION
123594	19-Jun-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
124134	22-Jun-10	repair and order r3 box on rail
124136	22-Jun-10	C/O SHORT ARM PINS, BUSHES & BEARINGS
124148	22-Jun-10	REPLACE DANFOSS COIL
124182	22-Jun-10	repair box on boom
124526	24-Jun-10	DAILY SERVICE & INSPECTION
124545	26-Jun-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
124906	27-Jun-10	assist fitters with CAN cable fault
124911	27-Jun-10	check elec disterbance change feed valve ???

124949	27-Jun-10	Electrical disturbance fault. Short on pin x117
124957	28-Jun-10	get oil in to drill rig
125045	29-Jun-10	electrical disturbance fault, Galvanic isolation card is
125097	29-Jun-10	Fault find fault with S41 plus fault with rotatio
124142	30-Jun-10	pito jaw bolts keep coming loose
125201	1-Jul-10	DAILY SERVICE & INSPECTION
125509	2-Jul-10	REBULID LOWER ROD GRIPPER JAW
125552	2-Jul-10	rod alignment adjustment
125223	3-Jul-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
125598	4-Jul-10	fit din plug to water flushing valve
125656	5-Jul-10	adjust gripper arms check air fault
126046	8-Jul-10	DAILY SERVICE & INSPECTION
126297	9-Jul-10	Replace blown hose
126298	9-Jul-10	Replace blown hose
126062	10-Jul-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
126353	10-Jul-10	blown hose
126453	10-Jul-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
126499	12-Jul-10	B7 sensor U/S replaced
126513	12-Jul-10	Piston came off rod on gripper cylinder. didnt have new
126699	12-Jul-10	COMPRESSOR HOUR METER IS NOT COUNTING WHEN
125637	13-Jul-10	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
126712	13-Jul-10	pito arm to be changed out(face vworn)
126739	14-Jul-10	LH 04 Trailing cable plug saturated after service sitting on
126841	15-Jul-10	DAILY SERVICE & INSPECTION
127056	15-Jul-10	air comp keeps cutting out
127078	15-Jul-10	test and repair lh04 gui panel fault
127088	15-Jul-10	gripper arms not working
126858	17-Jul-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
127184	17-Jul-10	rod alignment and fix waterhose reel
127264	19-Jul-10	rod alignment
127627	21-Jul-10	anglel sensor fault shift boss said to leave and work on
127541	22-Jul-10	DAILY SERVICE & INSPECTION
127614	22-Jul-10	check angle sensor
127655	22-Jul-10	fix B7 sensor cable and replace B6 sensor cable, cable was
127558	24-Jul-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
128060	27-Jul-10	RIGHT HAND DRIVING LIGHT BROKEN
128326	28-Jul-10	stinger U/S leaking oil
128212	29-Jul-10	DAILY SERVICE & INSPECTION
128518	29-Jul-10	fit hyd filler pump
128519	29-Jul-10	repair top stinger cyl
128227	30-Jul-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
128595	30-Jul-10	repair top stinger hoses
128614	31-Jul-10	service lh04 as service sheet has not come out on pronto
128655	1-Aug-10	fit rubber deflectors
128797	2-Aug-10	top up comp
128988	3-Aug-10	fit feed rope
129087	5-Aug-10	DAILY SERVICE & INSPECTION
129382	5-Aug-10	Replace faulty oil transfer pump with a repaired one from

129442	6-Aug-10	repair water leak
126147	7-Aug-10	wipers need fixing
129104	7-Aug-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
129497	7-Aug-10	general repairs
129555	9-Aug-10	feed cyl rod repairs
129775	10-Aug-10	blown hose
129147	11-Aug-10	fit water trap replace hp acc
129793	11-Aug-10	repin and bush feed tilt cyl. need parts 1x 14556-68z
128769	12-Aug-10	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
129852	12-Aug-10	DAILY SERVICE & INSPECTION
129989	12-Aug-10	oil leak recal clino
130216	13-Aug-10	repair oil leak
129871	14-Aug-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
130226	14-Aug-10	blown hose carrier
130256	15-Aug-10	new bolt in drifter acc
130257	15-Aug-10	gripper arm creeping
130260	15-Aug-10	adjust isolator shaft (was not fitting into the handle on
130261	15-Aug-10	replace d-108 module and test
130275	15-Aug-10	re seal gripper arm cyl
130378	16-Aug-10	blown hose
130596	18-Aug-10	need to replace air cond fans
130626	19-Aug-10	DAILY SERVICE & INSPECTION
130878	19-Aug-10	replace hose
130647	21-Aug-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
130965	21-Aug-10	Make up spare percussion hoses
131298	26-Aug-10	DAILY SERVICE & INSPECTION
131524	26-Aug-10	change feed return ropes
131360	27-Aug-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
131629	27-Aug-10	adjust feed ropes
131314	28-Aug-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
131637	28-Aug-10	check and repair a/c (sam)
131661	28-Aug-10	weekly check of LH04. There was no W/O Generated this week
132049	31-Aug-10	replace hose on drifter x 4
132209	1-Sep-10	replace drifter bolts
132235	1-Sep-10	blown hose and fitting
132113	2-Sep-10	DAILY SERVICE & INSPECTION
132398	2-Sep-10	repair rod gripper assy
132506	3-Sep-10	blown accumulator
132132	4-Sep-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
132933	9-Sep-10	DAILY SERVICE & INSPECTION
132950	11-Sep-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
132951	11-Sep-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
133341	11-Sep-10	blown hose jack leg
133397	12-Sep-10	patch up water hose
133449	12-Sep-10	rhs joy stick not working pulled apart cleaned all contacts
133815	15-Sep-10	blown hose percussion and bolt on drifter plate
133732	16-Sep-10	DAILY SERVICE & INSPECTION
133896	17-Sep-10	reset o/l a couple of times until rod unbogged

133750	18-Sep-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
134069	18-Sep-10	sensor comm error, with angles, water was in R3 box, suspect
134130	20-Sep-10	replace cable for s41 sensor and clean out r3 box
134152	20-Sep-10	Replace dio8 module
134504	23-Sep-10	DAILY SERVICE & INSPECTION
134788	24-Sep-10	check oil in header tank flush tank and refill monitor
134520	25-Sep-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
134795	25-Sep-10	order tooling for lh04
134820	25-Sep-10	oil leak in r3 box
134853	26-Sep-10	fit water flushing valve and repair hyd oil leak
135078	28-Sep-10	fit water hose to reel
135113	28-Sep-10	retoque straping bolts and top up oil hyd
135374	29-Sep-10	repair work light
135279	30-Sep-10	DAILY SERVICE & INSPECTION
135299	1-Oct-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
135627	2-Oct-10	replace tubes with rods
135669	3-Oct-10	blown hose and pito jaws
135767	4-Oct-10	repairs to ropes and flushing fault
136123	7-Oct-10	DAILY SERVICE & INSPECTION
136317	7-Oct-10	repair gripper arm pin
136334	7-Oct-10	clino fault
136361	8-Oct-10	fit feed ropes
136492	8-Oct-10	replace tilt cylinder
136140	9-Oct-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
136141	9-Oct-10	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
136556	10-Oct-10	replace b7 senser on boom
137013	14-Oct-10	DAILY SERVICE & INSPECTION
137237	15-Oct-10	blown hose
137034	16-Oct-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
137268	16-Oct-10	fit pins and bushes to pito jaws
137291	17-Oct-10	rock lube fault fit pump unit
137507	18-Oct-10	repairs to broken rod gripper assy
137654	21-Oct-10	DAILY SERVICE & INSPECTION
137823	21-Oct-10	rebuild spare acculators x 3
137862	21-Oct-10	fit pins and bushes to gripper arms
137879	21-Oct-10	check gripper arm bush and alignmet
137920	22-Oct-10	adjust gripper arms
137932	22-Oct-10	fit blown hoses x 2 check rod alignment
137940	22-Oct-10	repair /reweld stinger mount
137970	24-Oct-10	replace blown hose fit hyd oil filler pump
138074	25-Oct-10	fit return rope
138094	26-Oct-10	find and replace damaged s33 sensor and cable
137674	27-Oct-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
138129	28-Oct-10	DAILY SERVICE & INSPECTION
138589	28-Oct-10	replace blown hose
138149	29-Oct-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
138695	30-Oct-10	S34 not working, operator drilled on bypass untill we
138757	31-Oct-10	WORK ORDER FOR MONTHLY ALLOCATION

138730	1-Nov-10	LH04 shut down on Tilt / Rotation Error. Found sensor B 6
138801	1-Nov-10	high side accumulator
139092	3-Nov-10	make up new stinger and daily
139161	3-Nov-10	change accumulator
139026	4-Nov-10	DAILY SERVICE & INSPECTION
139157	4-Nov-10	shut down on rock lube
139273	4-Nov-10	new pitto jaw and bolts
139278	4-Nov-10	rod counter not working
139295	4-Nov-10	Check oil filler pump
139046	5-Nov-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
139323	5-Nov-10	rewld thread on stinger
139358	5-Nov-10	fit blown hose
139390	6-Nov-10	test and repair lh04 filler pump for the oil
139399	6-Nov-10	check shank lube level fault fit level switch
139433	7-Nov-10	air flushing staying on fit flushing valve
139847	11-Nov-10	DAILY SERVICE & INSPECTION
140087	11-Nov-10	Replace broken fitting. Pumop tripping out. replace hyd
139908	12-Nov-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
138671	13-Nov-10	1 condensor fan U/S (need to measure up for ashdown)
139907	13-Nov-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
140255	13-Nov-10	Recharge drifter accumulators
140263	14-Nov-10	Air con
139883	15-Nov-10	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
140362	16-Nov-10	reported problems with clino tested all ok
140414	16-Nov-10	jump start
140509	18-Nov-10	DAILY SERVICE & INSPECTION
140890	19-Nov-10	strapping bolts and pressure switch playing up
140530	20-Nov-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
140903	20-Nov-10	fit pressure filter restriction sensor
140926	20-Nov-10	drifter lube fault and vee slides to tight
141145	22-Nov-10	repair air valve sticking on repair oil leaks
141240	23-Nov-10	repair air flushing valve
140471	24-Nov-10	damage to rod tray
141326	25-Nov-10	DAILY SERVICE & INSPECTION
141756	26-Nov-10	replace pitto jaw cyl and repairs
141131	27-Nov-10	air flushing valve sticking
141344	27-Nov-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
142326	1-Dec-10	replace feed rope
142159	2-Dec-10	DAILY SERVICE & INSPECTION
142402	2-Dec-10	fit shank
142424	3-Dec-10	test and repair/ replace work light on the long hole 04
142434	3-Dec-10	fit grease reel
142178	4-Dec-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
142307	4-Dec-10	Change diff & final drive oils to LSD SAE 140
142505	4-Dec-10	repair oil leak
142612	6-Dec-10	broken bolt acc fit orings
142816	7-Dec-10	replace blown hose fit pitto jaws
143181	8-Dec-10	fit stinger replace blown hose

143112	9-Dec-10	DAILY SERVICE & INSPECTION
143204	9-Dec-10	repair stinger plate
143241	9-Dec-10	check long arm adjustment stopper broke off serv day to fix
143312	10-Dec-10	repair water pump coupling
143131	11-Dec-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
143132	11-Dec-10	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
142350	13-Dec-10	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
143545	13-Dec-10	jack leg pressure switch DTE or cable, disconnected switch
144284	16-Dec-10	DAILY SERVICE & INSPECTION
144571	17-Dec-10	retorque drifter strapping bolts
144310	18-Dec-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
144596	18-Dec-10	check a/c system compressor u/s
144643	19-Dec-10	fit new led work lights x2
144919	20-Dec-10	blown percussion hose
145039	22-Dec-10	swap out trailing cable on lh04 and test
145126	22-Dec-10	fit laser glass lenses
145067	23-Dec-10	DAILY SERVICE & INSPECTION
145087	24-Dec-10	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
145451	27-Dec-10	repair air flush fault
145496	27-Dec-10	gas up accumulators
145678	29-Dec-10	oil leak drifter
145599	30-Dec-10	DAILY SERVICE & INSPECTION
145748	30-Dec-10	adjust rod handler
145617	2-Jan-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
145843	2-Jan-11	book out parts that havent been booked out of the store
145859	2-Jan-11	top up with oil
146029	3-Jan-11	rod alignment adjust
146090	5-Jan-11	no start repair wiring to starter and alt
146167	6-Jan-11	DAILY SERVICE & INSPECTION
146195	7-Jan-11	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
146194	8-Jan-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
146372	8-Jan-11	LH TRIPS OUT ON EL WHEN POWER PACK STARTS UP
146407	9-Jan-11	adjust rod aliment
146408	9-Jan-11	flushing head seal leaking replace seals
146470	10-Jan-11	replace flushing head seals
146489	10-Jan-11	top stinger creeping
146654	11-Jan-11	repair creeping stinger (check valves) ant ft wiper
146973	12-Jan-11	blown hose
146999	12-Jan-11	adjust jack leg sensor
147017	12-Jan-11	repairs to lower rod gripper
146890	13-Jan-11	DAILY SERVICE & INSPECTION
146607	15-Jan-11	Replace muffler & tail pipe
146910	15-Jan-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
147382	17-Jan-11	air comp belt u/s
146958	20-Jan-11	DAILY SERVICE & INSPECTION
147656	20-Jan-11	DAILY SERVICE & INSPECTION
147675	21-Jan-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
147630	26-Jan-11	Work order to capture cost of rod handler middle bar

148402	26-Jan-11	long arm cylinder pin come out and damaged cylinder
148230	27-Jan-11	DAILY SERVICE & INSPECTION
148431	27-Jan-11	long arm cyl and frame u/s replace
148251	28-Jan-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
148478	28-Jan-11	Sam to repair A/C unit - done Dec 2010
148494	28-Jan-11	rock guard struts to be fitted
148496	28-Jan-11	jack leg and zoom plate
148525	28-Jan-11	gui not counting metres
148563	29-Jan-11	check klyno / linear sensor
148632	30-Jan-11	tension strapping bolt
149089	2-Feb-11	fit work lights
149190	2-Feb-11	check a/c compressor u/s
149191	2-Feb-11	replace hyd fitting replace drifter bolt, tension strapping
148690	3-Feb-11	DAILY SERVICE & INSPECTION
148780	5-Feb-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
149401	5-Feb-11	change wiper blade and daily
149726	8-Feb-11	S35 not working, operator didn't want to stop to repair
149739	8-Feb-11	repairs to loose drifter and stinger
148976	9-Feb-11	depth counter not working
149960	9-Feb-11	Replace siezed water pump
149616	10-Feb-11	DAILY SERVICE & INSPECTION
150207	11-Feb-11	gripper arms faulty
150219	11-Feb-11	blown hose on fast feed in loom
149658	12-Feb-11	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
149659	12-Feb-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
149660	12-Feb-11	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
150241	12-Feb-11	repair a/c hose u/s evacuate and recharge
150311	13-Feb-11	adjust gripper arms tension strapping bolts replace
150330	13-Feb-11	adjust gripper arm alignment
149685	14-Feb-11	BATTERY ISOLATOR CHANGE OUT
150384	14-Feb-11	tension strapping bolts
150424	15-Feb-11	faulty angle sensors on lh04
150697	16-Feb-11	fit compressor belts
150724	17-Feb-11	DAILY SERVICE & INSPECTION
150744	19-Feb-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
150960	19-Feb-11	LH 04 lost power E/L fault at Jumbo box, meggered trailing
151036	20-Feb-11	extra work serv day .Seat belt, lights etc.Also stock up of
151581	23-Feb-11	Rotation motor for carasoul came of.
151471	24-Feb-11	DAILY SERVICE & INSPECTION
151710	24-Feb-11	grease pump and straps for hoses on boom
151767	24-Feb-11	replace hyd hose and fitting
151826	25-Feb-11	tension strapping bolts
151489	26-Feb-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
151967	26-Feb-11	adjust rod alignment
151970	26-Feb-11	replace broken rhs joystick
151983	27-Feb-11	rod alignment and drifter shank deflector
152012	28-Feb-11	check rod alignment
152209	1-Mar-11	blown hose 4.8m long dash 8

152221	1-Mar-11	blown hose
152407	2-Mar-11	replace blown hose
152426	2-Mar-11	broken leg extension fittings
152300	3-Mar-11	DAILY SERVICE & INSPECTION
152492	3-Mar-11	Repair jackleg fitting oil leak
152317	5-Mar-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
152725	5-Mar-11	Repair fault with shank lube
153012	6-Mar-11	blown hose
153361	10-Mar-11	DAILY SERVICE & INSPECTION
153380	10-Mar-11	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
153797	11-Mar-11	repair water hose
153379	12-Mar-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
153862	13-Mar-11	replace hyd hose, replace accumulator bolts
153924	14-Mar-11	depth counter fault, tension tie rod bolts
153937	14-Mar-11	C4620L sth LH04 fault with gripper arm sensor S41 changed
153998	15-Mar-11	repair oil leak tension strapping bolts
154271	16-Mar-11	tension flushing head bolts and strapping bolt
154170	17-Mar-11	DAILY SERVICE & INSPECTION
154391	18-Mar-11	Repairs to SLU. Unit operating on boost constantly
154405	18-Mar-11	fix faulty rocklube check linral sensor
154189	19-Mar-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
154621	21-Mar-11	Repair blown accumulator
154812	24-Mar-11	DAILY SERVICE & INSPECTION
155067	24-Mar-11	feed cylinder repairs
155081	25-Mar-11	fit front wiper
155121	25-Mar-11	damage to gripper arm cyl
154830	26-Mar-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
155171	26-Mar-11	kel ordered grease kit from pirtek
155247	28-Mar-11	fit hyd hose
155473	30-Mar-11	torque strapping bolts
155552	31-Mar-11	DAILY SERVICE & INSPECTION
155644	31-Mar-11	torque strapping bolts
155698	31-Mar-11	blown main pump hose in articulation
155574	2-Apr-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
155776	3-Apr-11	Gui panel showing "Comms System Error" fault.
156085	4-Apr-11	rod handler loose
156110	6-Apr-11	line up jaws and daily
156188	7-Apr-11	DAILY SERVICE & INSPECTION
156291	7-Apr-11	replace air pressure gauge for compressor
156342	7-Apr-11	fit stinger wear plates
156355	7-Apr-11	replace centre hitch blown hose
156205	9-Apr-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
156206	9-Apr-11	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
156460	9-Apr-11	loose jaws on gripper arm tighten
156795	11-Apr-11	C4620L sth LH04 L/H/S joystick replace
156805	11-Apr-11	torque strapping bolts
156820	11-Apr-11	change out gripper cyl and eye due to lost plate and pin
156891	12-Apr-11	tighten strapping bolts fit hyd hose

157064	13-Apr-11	torque strapping bolts
156964	14-Apr-11	DAILY SERVICE & INSPECTION
157098	14-Apr-11	replace shank , repairs to ropes and rod gripper jaws
157141	14-Apr-11	Bent fingers and accumulator needs gas
157270	15-Apr-11	Oil leak and noisy drifter
156980	16-Apr-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
157229	16-Apr-11	POWER TRIPPED ON RIG APON INVESTIGATION FOUND FAULT WITHIN
157288	17-Apr-11	LH04 HAP NO PILOT @R4680 UPON INSPECTION WAS NOT PLUGGED IN
157444	18-Apr-11	Repair oil leak at drifter
157459	19-Apr-11	replace perc on off valve .(to be put back on LH02)
157485	19-Apr-11	Tilt error Fault showed up on Gui, found damaged supply
157488	19-Apr-11	free up sticky long arm valve
157563	21-Apr-11	DAILY SERVICE & INSPECTION
157583	23-Apr-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
157836	23-Apr-11	fit front wiper blade torque strapping bolts
157899	25-Apr-11	R4680L LH04 replace worklight
157948	26-Apr-11	torque strapping bolts, replace bolt in acc, replace shank
158195	28-Apr-11	DAILY SERVICE & INSPECTION
158211	30-Apr-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
158524	30-Apr-11	Check drilling pressure and performance
158560	2-May-11	blown hose
158691	2-May-11	replace accumulator
158922	5-May-11	DAILY SERVICE & INSPECTION
159111	5-May-11	C4720L Nth LH04 Fault with clyno wouldnt read angles found
159123	5-May-11	align gripper arms
159149	6-May-11	fit lenses to laser on boom
159193	6-May-11	fit lights
158940	7-May-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
159235	7-May-11	replace rhs accumulator and bolts
159413	9-May-11	fit hid globe
159868	11-May-11	repair water hose, tension straping bolts, fit broken
159701	12-May-11	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
159702	12-May-11	DAILY SERVICE & INSPECTION
160050	12-May-11	daily
159739	14-May-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
159740	14-May-11	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
159850	15-May-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
160448	17-May-11	Replace accumulator diaphragm
160531	19-May-11	DAILY SERVICE & INSPECTION
160707	19-May-11	fit pito jaws
160547	21-May-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
160768	21-May-11	REBUILD DOWN TIME
161202	26-May-11	DAILY SERVICE & INSPECTION
161219	28-May-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
161765	2-Jun-11	DAILY SERVICE & INSPECTION
161784	4-Jun-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
162633	9-Jun-11	DAILY SERVICE & INSPECTION
162652	11-Jun-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

162653	11-Jun-11	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
163309	16-Jun-11	DAILY SERVICE & INSPECTION
163330	18-Jun-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
163975	23-Jun-11	DAILY SERVICE & INSPECTION
163990	24-Jun-11	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
163993	25-Jun-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
164845	30-Jun-11	DAILY SERVICE & INSPECTION
164874	2-Jul-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
165627	7-Jul-11	DAILY SERVICE & INSPECTION
165645	9-Jul-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
165646	9-Jul-11	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
166194	14-Jul-11	DAILY SERVICE & INSPECTION
166214	16-Jul-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
166895	19-Jul-11	testing and commissioning longhole after rebuild
166838	21-Jul-11	DAILY SERVICE & INSPECTION
167031	21-Jul-11	H4760L Fault no flush and water and air pressure switch.
167129	22-Jul-11	Repair check valves air fault etc
167140	23-Jul-11	Replace loose strapping bolts
167160	24-Jul-11	Replace broken accumulator bolts
167192	25-Jul-11	tow off wall
166855	27-Jul-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
167629	28-Jul-11	DAILY SERVICE & INSPECTION
167827	28-Jul-11	reset overload (bogged rods)
168002	29-Jul-11	make up tool box
167647	30-Jul-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
168081	31-Jul-11	replace laser lens on lh04
168093	31-Jul-11	bolts in drifter cradle and pito jaw accum oring replaced
168179	2-Aug-11	Rotation Error came up on the Gui Panel, traced fault to
168345	3-Aug-11	Rotation error traced fault to B7 sensor cable
168423	4-Aug-11	DAILY SERVICE & INSPECTION
168554	4-Aug-11	Check rod alignment
168442	6-Aug-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
168679	8-Aug-11	flushing seals and cartridge
169139	11-Aug-11	DAILY SERVICE & INSPECTION
169389	11-Aug-11	air/water flush valve sticking
169176	12-Aug-11	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
169198	13-Aug-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
169199	13-Aug-11	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
169437	13-Aug-11	change out grease lines
169795	18-Aug-11	DAILY SERVICE & INSPECTION
169957	18-Aug-11	air fault (sparkies set switch under step)
169813	19-Aug-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
169955	19-Aug-11	find scaled up air flow sensor, clean and recalibrate
170093	21-Aug-11	repair broken rod handler assy
170543	24-Aug-11	rebuild spare accumulator
170554	24-Aug-11	Grease line & shank
170450	25-Aug-11	DAILY SERVICE & INSPECTION
170612	25-Aug-11	fit pos 3 tyre, fit grease pump

170468	27-Aug-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
170566	27-Aug-11	Flat tyre - DONE ON 170612
170745	28-Aug-11	engine cut out while tramming out check fuel
170832	29-Aug-11	fit pito jaw assy, not taking grease bushes moved
170943	29-Aug-11	broken bolt low side acc
171045	30-Aug-11	change out flushing head seals and orings
171049	30-Aug-11	change out flushing housing seal holder and adjust pito jaw
171235	1-Sep-11	DAILY SERVICE & INSPECTION
171362	1-Sep-11	repair flushing
171370	1-Sep-11	Repair oil leak at stinger, adjust jaws
171254	2-Sep-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
171801	4-Sep-11	Replace broken strapping bolt
171804	4-Sep-11	Replace blown hose. Done by operator. Crazy Joe
172223	8-Sep-11	DAILY SERVICE & INSPECTION
172353	8-Sep-11	replace 3 strapping bolt and retension
172494	8-Sep-11	refit accumulator fallen off
172242	10-Sep-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
172243	10-Sep-11	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
172569	10-Sep-11	need pos 3 wheel seals changed leaking oil schedule next
172585	11-Sep-11	C4580 L sp1 x cut fault came up with system error 130 check
172610	11-Sep-11	fit flushing head seals and o-rings
172618	12-Sep-11	C4580L SFW LH02 kept loosening pilot jack leg wasnt all the
172682	12-Sep-11	fit flushing head seals and housing
172769	13-Sep-11	refit and adjust feed ropes
172925	13-Sep-11	111JBS16 had loose connections - burnt inside. See w/o
172961	15-Sep-11	DAILY SERVICE & INSPECTION
173055	15-Sep-11	replace broken bolt in rear of drifter
172982	16-Sep-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
173433	20-Sep-11	Replace 2 damaged rotation unit hoses
173436	20-Sep-11	repair gripper cylinder
173438	21-Sep-11	find and replace u/s b26 sensor
173524	22-Sep-11	DAILY SERVICE & INSPECTION
173670	22-Sep-11	replace broken bolt back off drifter
173683	23-Sep-11	LH 04 shut down on ERR-ERROR , Traaced fault to B7 sensor
173716	23-Sep-11	fit led lights
173543	24-Sep-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
173766	24-Sep-11	fit broken strapping bolt already booked out
174212	29-Sep-11	DAILY SERVICE & INSPECTION
174345	29-Sep-11	hose reel drive chain come off.
174354	29-Sep-11	Short arm pin came out and broke cylinders
174235	1-Oct-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
174754	4-Oct-11	Repair damaged B26 and Lazer Cables on longhole, also
174835	6-Oct-11	DAILY SERVICE & INSPECTION
174985	7-Oct-11	replace strapping bolt, check proximity switch gripper arms
174993	7-Oct-11	C4560L SFW intermittant gripper arm fault
175161	7-Oct-11	check carousel fault PROXY SWITCH S34 was loose
174860	8-Oct-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
174861	8-Oct-11	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL

175167	8-Oct-11	torque strapping bolts, replace shank,
175206	9-Oct-11	C4560L sth gripper arm fault adjusted s34 proxy switch
175336	11-Oct-11	andrew irvine checks for/on autodrill set up
175519	13-Oct-11	DAILY SERVICE & INSPECTION
175611	13-Oct-11	fit gripper cyl by two pin fallen out bending cyl
175538	15-Oct-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
175724	15-Oct-11	find why drill wont work on auto found to be a crook
176090	20-Oct-11	DAILY SERVICE & INSPECTION
176207	20-Oct-11	replace broken shank as req
176294	21-Oct-11	replace broken feed ropes
176109	22-Oct-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
176878	26-Oct-11	feed rope jammed jumped off pulley refit
176557	27-Oct-11	DAILY SERVICE & INSPECTION
176576	29-Oct-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
177440	2-Nov-11	Replace broken positioning joystick
177350	3-Nov-11	DAILY SERVICE & INSPECTION
177370	5-Nov-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
177679	5-Nov-11	air cond blown hose replace and regas system
177865	9-Nov-11	replace blown hose, light wiring u/s repair
178162	9-Nov-11	Fit stainless steel guards to both sides of cable reel
178033	10-Nov-11	DAILY SERVICE & INSPECTION
178075	12-Nov-11	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
178076	12-Nov-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
178077	12-Nov-11	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
178300	12-Nov-11	pilot fault when got there found jag leg was not down
178651	17-Nov-11	DAILY SERVICE & INSPECTION
178849	17-Nov-11	Blown hose, broken shank, drifter bolts
178916	17-Nov-11	Wait on installation of JBS20. Was unplanned and sparky only
178935	18-Nov-11	check power pack current draw
178670	19-Nov-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
178975	20-Nov-11	LH 04 @ C4640 lost part of its control pwer. Found burnt out
179133	23-Nov-11	no hand held radio on rig
179716	23-Nov-11	replace feed ext cyl
177614	24-Nov-11	linear sensor u/s depth & penetration rate not
179656	24-Nov-11	DAILY SERVICE & INSPECTION
179673	24-Nov-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
179805	24-Nov-11	Replace pito jaws
179899	26-Nov-11	repair lights on front RHS of rig (damaged cabling)
179915	26-Nov-11	Repair leaking accumulator
179931	27-Nov-11	Daily service and and repair auto drill (replace proxy
180001	28-Nov-11	Boom movement problems- U/g sparky looking at
180020	29-Nov-11	called to drill with reports of DPW Power disturbance
180389	30-Nov-11	Change out sensor
180022	1-Dec-11	air vent broken under window
180260	1-Dec-11	DAILY SERVICE & INSPECTION
180277	2-Dec-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
180487	2-Dec-11	need fittings for lh 04 dash 6 sockets bsp to jic nipple
180533	3-Dec-11	2 x blown hoses

180659	5-Dec-11	replace blown hoses,check feed fault and repair accumulator
180711	6-Dec-11	Blown hose under carrier.
180753	7-Dec-11	Replace blown compresor hose with one off JB06. It was BSP
180921	8-Dec-11	DAILY SERVICE & INSPECTION
180939	10-Dec-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
180940	10-Dec-11	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
181151	10-Dec-11	Replace broken accumulator bolts
181414	13-Dec-11	water pump reported not working found contactor coil
181563	15-Dec-11	DAILY SERVICE & INSPECTION
181639	15-Dec-11	long hole rig had no pilot found btb and extension cable
181590	17-Dec-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
181941	19-Dec-11	REPLACE LEAKING FLUSHING HEAD SEALS
182265	20-Dec-11	replace accumlator anf ix broken bolts and strap bolts and
182424	21-Dec-11	replace drifter strapping nut and retension
182373	22-Dec-11	DAILY SERVICE & INSPECTION
182464	22-Dec-11	1st call- No pilot, found dirty BTB
182394	24-Dec-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
182626	27-Dec-11	repairs to ropes and daily
182814	28-Dec-11	Recharge accumulators
182739	29-Dec-11	DAILY SERVICE & INSPECTION
182759	30-Dec-11	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
182960	1-Jan-12	fit front window guard struts
183279	3-Jan-12	fit pito jaws
183353	5-Jan-12	DAILY SERVICE & INSPECTION
183606	5-Jan-12	replace flushing head seals
183662	6-Jan-12	replace pito grippers cable bolts
183375	7-Jan-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
187003	9-Jan-12	Inspect turbo hose as per Normet Safety alert
187164	12-Jan-12	DAILY SERVICE & INSPECTION
187305	12-Jan-12	replace faulty hyd hose
187444	13-Jan-12	replace work lights
187509	15-Jan-12	run off decline into drain,inspect for damage(bent handrail)
187135	18-Jan-12	Check transmission mounting bolts for tightness. Found to be
187211	18-Jan-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
187212	18-Jan-12	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
188081	19-Jan-12	DAILY SERVICE & INSPECTION
188427	19-Jan-12	called to drill rig with reports of electrical disturbance
188431	19-Jan-12	pito jaws not gripping. spaced up to grip.
188555	22-Jan-12	reported no pilot found the isolater off on the
187193	23-Jan-12	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
188687	23-Jan-12	going from rods to tubes.
188701	24-Jan-12	called to rig with reports of Electrical disturbance checked
188127	25-Jan-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
188895	25-Jan-12	supply fittings to repair water hose.
188908	25-Jan-12	repair electrical disturbance
188833	26-Jan-12	DAILY SERVICE & INSPECTION
188949	26-Jan-12	replace 3 x broken bolts hp accumulator, tension strapping
189132	31-Jan-12	fit led light

189207	31-Jan-12	repair oil leak hose and fitting
188874	1-Feb-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
189286	2-Feb-12	DAILY SERVICE & INSPECTION
189639	3-Feb-12	repairs to air flushing valve. Stuck on
189624	5-Feb-12	repair damaged grippers and stuck rods
189653	6-Feb-12	adjust jack leg pressure switch
189849	7-Feb-12	Investigate not working on auto drill, suspect S41 sensor is
189325	8-Feb-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
190110	8-Feb-12	feed rail stainles strips need changing
190116	8-Feb-12	Clino not working
189962	9-Feb-12	DAILY SERVICE & INSPECTION
190118	9-Feb-12	clino was not working so hooked up new cable and was good
189999	12-Feb-12	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
190740	13-Feb-12	fit front wiper
190749	13-Feb-12	fit feed ropes
190037	15-Feb-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
190038	15-Feb-12	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
190999	16-Feb-12	DAILY SERVICE & INSPECTION
191231	17-Feb-12	SLU not working
191251	18-Feb-12	replace pito jaws , repair water hose and daily
191342	20-Feb-12	low water pressure. Bleed air out of system. and daily
191438	21-Feb-12	Engine derating
191030	22-Feb-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
191471	22-Feb-12	engine over heating. Clutch U/S in fan hub
191515	23-Feb-12	DAILY SERVICE & INSPECTION
191730	25-Feb-12	oil leak box on end off rail and caresoul
191737	25-Feb-12	a/c hyd drive motor u/s leaking from main shaft
191779	26-Feb-12	fit pito jaw
191546	28-Feb-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
191377	29-Feb-12	Sample both diffs and all final drives. SAMPLES ONLY
192031	1-Mar-12	DAILY SERVICE & INSPECTION
192147	1-Mar-12	H4725L fault linear sensor & rod counter sensor fault
192077	6-Mar-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
192853	8-Mar-12	DAILY SERVICE & INSPECTION
193099	11-Mar-12	blown hose
193137	12-Mar-12	change out hp acc u/s
192881	13-Mar-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
192882	13-Mar-12	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
193348	13-Mar-12	stuck in drain tow/ sight to get out
193564	15-Mar-12	DAILY SERVICE & INSPECTION
193797	17-Mar-12	Machien stuck in drain
193594	20-Mar-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
193871	20-Mar-12	general repairs service day and tooling. Repairs including
194049	20-Mar-12	order new water hose for solo
194263	21-Mar-12	Repair leaking flushing head
194176	22-Mar-12	DAILY SERVICE & INSPECTION
194308	22-Mar-12	recalibrate climo fault wiring issue
194312	22-Mar-12	change 2 x hid lights

194333	22-Mar-12	fit pito jaws
194376	23-Mar-12	check out tilt angle sensor
194420	23-Mar-12	calibrate clino
194465	25-Mar-12	C4540 L SFW LH04 has done a trailing cable change out.
194570	26-Mar-12	check carousel long arm flogged out
194207	27-Mar-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
194644	27-Mar-12	reuild long arm new bushes and cylinders
195079	28-Mar-12	tension strapping bolts, fit pito jaws, adjust long arm
194847	29-Mar-12	DAILY SERVICE & INSPECTION
195230	29-Mar-12	Repairs to long arm, accumulator and replace bolts.
195396	2-Apr-12	find a loose neutral connection on S34 in the R3 box
194883	3-Apr-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
195667	5-Apr-12	DAILY SERVICE & INSPECTION
195702	10-Apr-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
195703	10-Apr-12	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
196083	10-Apr-12	repairs to zoom wear pieces
196247	11-Apr-12	order grease line fittings
196376	12-Apr-12	DAILY SERVICE & INSPECTION
196516	12-Apr-12	Replace pito jaws and broken strapping bolt
196621	15-Apr-12	LHS joystick rapid button not working, no spare joysticks in
196408	17-Apr-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
197053	18-Apr-12	Replace worn pito jaws
196888	19-Apr-12	DAILY SERVICE & INSPECTION
197209	20-Apr-12	Pito jaw assem u/s
197289	22-Apr-12	replace 2 x hyd fittings on long arm, tension strapping
196923	24-Apr-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
197512	24-Apr-12	fit pito jaws and new adjusting bolts
197638	25-Apr-12	change long arm cyl and bushes and pins
197450	26-Apr-12	DAILY SERVICE & INSPECTION
197876	29-Apr-12	Pito jaws not gripping
197486	1-May-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
198023	1-May-12	called to lh04 reports it would not count rods found green
198285	2-May-12	Fit rotatable pito unit
198359	2-May-12	repairs to flushing head
198219	3-May-12	DAILY SERVICE & INSPECTION
198424	3-May-12	replace grease pump, tighten pito jaws
197667	4-May-12	Auto drill not working wont pick up rods
198546	4-May-12	replace flushing head front cover bolts
198564	5-May-12	blown hose blown accumulator o-ring
198744	7-May-12	fill up hydraulic tank, check for leak
198749	7-May-12	tighten strapping bolts, replace broken fitting
198254	8-May-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
198255	8-May-12	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
198998	10-May-12	DAILY SERVICE & INSPECTION
199201	10-May-12	Replace damaged ropes.
199039	12-May-12	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
199068	15-May-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
199855	15-May-12	Asked to install JBS in C4540 SFW for long hole. Found that

199774	17-May-12	DAILY SERVICE & INSPECTION
199917	17-May-12	park brake not releasing check coil
199923	18-May-12	C4902 LH04 park brake fault assit fitter.
199951	18-May-12	lids to suit hyd oil drums
199988	19-May-12	drifter lube fault bleed up
197210	20-May-12	Front stinger button missing
200015	20-May-12	fit flushing head water inlet flange. repair grease line
200024	21-May-12	R4660 LH04 had a shank lube error, found the shank lube unit
199495	22-May-12	replace front CAN cable and hose
199804	22-May-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
200110	22-May-12	check zoom wear button boss, replace drifter flushing head
200127	23-May-12	Chair need to be fixed
200198	23-May-12	no power to gui panel top up hyd oil
200276	24-May-12	DAILY SERVICE & INSPECTION
200531	24-May-12	replace hyd fitting
200133	25-May-12	Weld repairs to zoom button boss
200296	25-May-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
200602	25-May-12	broken hyd fitting
200612	25-May-12	L/h joy stick broken
200626	25-May-12	Boom repairs LH04
200630	25-May-12	replace faulty flushing valve
200684	28-May-12	replace blown hose
201092	30-May-12	Shank lube fault
201014	31-May-12	DAILY SERVICE & INSPECTION
201179	31-May-12	replace bent shank, fit front wiper
201035	1-Jun-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
201417	3-Jun-12	cap off water thermostat over flow relief u/s order new
201252	4-Jun-12	Front window wiper
201566	5-Jun-12	replace angle sensor cable
201640	7-Jun-12	DAILY SERVICE & INSPECTION
201660	7-Jun-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
201852	7-Jun-12	repair replace pito jaw assy. General repairs
201870	7-Jun-12	check out low side accumulater
201908	9-Jun-12	fit new shroda valves and regas accumalaters
201984	11-Jun-12	N/S operator reported drill cutting out on shank lube level,
202399	14-Jun-12	DAILY SERVICE & INSPECTION
202419	15-Jun-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
202420	15-Jun-12	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
202718	15-Jun-12	Replace Zoom tube extension as per Sandvik safety Bulliten
202746	15-Jun-12	water reducing valve needs replacing (leaking)
202747	15-Jun-12	replace window wiper blades
202748	15-Jun-12	repalce worn pito jaws
202788	16-Jun-12	EXHAUST AND MUFFLER NEED REPLACING
202790	16-Jun-12	pressure washer reel needs replaceing
202825	17-Jun-12	retension drifter straping bolts
203453	19-Jun-12	needs two work lights
203488	19-Jun-12	calibrate linear sensor
202449	20-Jun-12	Replace accumulator on pito cylinder in store see coxey

203693	20-Jun-12	replace lh (drill) joystick
203567	21-Jun-12	DAILY SERVICE & INSPECTION
203727	21-Jun-12	replace brocken bolt in acummilator
203587	22-Jun-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
203847	25-Jun-12	called to rig with Electrical disturbance, but could not
204300	27-Jun-12	stripped fitting to feed cylinder
204221	28-Jun-12	DAILY SERVICE & INSPECTION
204241	29-Jun-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
204431	29-Jun-12	air leak near drifter
204463	1-Jul-12	drifter lube fault needed bleeding.
204478	1-Jul-12	a/c u/s comp u/s bent piston rod
204623	2-Jul-12	a/c u/s evaporator leaking and tx valve blocked
204865	4-Jul-12	calibrate boom angles
204779	5-Jul-12	DAILY SERVICE & INSPECTION
204897	5-Jul-12	LH 04 could not use water or air.
204898	5-Jul-12	Flushing fault. No air or water to drifter
204802	6-Jul-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
204985	8-Jul-12	blown hose , broken fitting and daily
205363	11-Jul-12	Replace positioning laser on LH04
205324	12-Jul-12	DAILY SERVICE & INSPECTION
205460	12-Jul-12	was reported as having to use bypass button when coupling a
205471	12-Jul-12	tension strapping bolts
205341	13-Jul-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
205479	13-Jul-12	r/h door window cracked
205541	14-Jul-12	adjust rod alignment and feed ropes
205553	15-Jul-12	repalce blown water hose under cab
205571	15-Jul-12	replace bolt on rear plate of drifter and bolts and o-rings
205862	17-Jul-12	fill hyd oil
205961	19-Jul-12	DAILY SERVICE & INSPECTION
205980	20-Jul-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
206145	20-Jul-12	blown HP accumulator
206171	21-Jul-12	Replace leaking accumulator diaphragm
206001	23-Jul-12	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
206530	25-Jul-12	Replace feed rope
206452	26-Jul-12	DAILY SERVICE & INSPECTION
205981	27-Jul-12	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
206470	27-Jul-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
206729	27-Jul-12	fit feed rope and battery isolator
206740	27-Jul-12	replace leaking injector line
206867	30-Jul-12	feed rope come off pulley refit.
207055	31-Jul-12	replace bolts on gripper jaws
207225	1-Aug-12	adjust feed rope, blown hose on long arms.
207235	1-Aug-12	rear cover of drifter u/s
207145	2-Aug-12	DAILY SERVICE & INSPECTION
207167	3-Aug-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
207508	5-Aug-12	replace damaged feed rope
207556	6-Aug-12	Replace pito jaw bolts
207775	9-Aug-12	DAILY SERVICE & INSPECTION

207797	10-Aug-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
207820	12-Aug-12	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
208133	13-Aug-12	remove broken bolt in acculater
208391	16-Aug-12	DAILY SERVICE & INSPECTION
208635	16-Aug-12	sensor fault.
208411	17-Aug-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
208412	17-Aug-12	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
208761	19-Aug-12	Front stinger leakng oil.
208910	22-Aug-12	Repairs to water fitting
209091	23-Aug-12	DAILY SERVICE & INSPECTION
209185	23-Aug-12	got called down powerpacks cut out, lost all boom fuctions..
209190	23-Aug-12	repairs to rod handeler
209238	23-Aug-12	adjust gripper arms
209113	24-Aug-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
209425	26-Aug-12	oil leak top up hyd oil
209471	27-Aug-12	recalibrate clino and fill hyd oil leak drifter and loose
209618	28-Aug-12	replace blown hyd hose pirtek
209758	30-Aug-12	DAILY SERVICE & INSPECTION
209909	30-Aug-12	Repair leaking accumulator
209778	31-Aug-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
209943	31-Aug-12	general repairs
210191	3-Sep-12	hyd oil leak in front of boom. Blown O rings
210205	3-Sep-12	Repair oil leak
210265	4-Sep-12	daily and replace 2 x hoses
210281	4-Sep-12	top up hydraulic oil
210530	5-Sep-12	replace pito jaws and daily
210561	5-Sep-12	replace rock lube sensor
210358	6-Sep-12	DAILY SERVICE & INSPECTION
210592	6-Sep-12	replace shank
210380	7-Sep-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
210705	9-Sep-12	C4516 LH 04 It was reported that the Hole Depth counter
210711	9-Sep-12	replace hyd fittings on pito jaws
211050	13-Sep-12	DAILY SERVICE & INSPECTION
211221	13-Sep-12	repair oil leak hydraulic fitting loose
211072	14-Sep-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
211289	14-Sep-12	repairs to oil leaks on valve bank on front of boom
211548	18-Sep-12	Lost 24volt power
211732	20-Sep-12	DAILY SERVICE & INSPECTION
211863	20-Sep-12	replace leaking water oing on the flushing head
211753	21-Sep-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
211754	21-Sep-12	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
211887	21-Sep-12	fit front led work lights
211953	23-Sep-12	Gripper arms not finding its position when in drill center
212329	27-Sep-12	DAILY SERVICE & INSPECTION
212347	28-Sep-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
212677	28-Sep-12	general repairs and feed cylinder replacment
212691	28-Sep-12	Repair leaking feed cylinder fitting
212966	4-Oct-12	DAILY SERVICE & INSPECTION

212988	5-Oct-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
213343	8-Oct-12	replace led light, tidy up hoses
213530	8-Oct-12	fit pito jaw bolts and replace hose
213591	10-Oct-12	repair air flushing valve sticking on pull apart and unsieze
213656	11-Oct-12	DAILY SERVICE & INSPECTION
213677	12-Oct-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
213982	15-Oct-12	flat batteries . Jump start
213990	15-Oct-12	check trickel charger for operation as the batteries were
214301	18-Oct-12	DAILY SERVICE & INSPECTION
214319	19-Oct-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
214320	19-Oct-12	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
214643	19-Oct-12	replace bushes and pins in rod handler
214687	20-Oct-12	blown hose and daily
214705	21-Oct-12	air flush valve stuck on clean valve
214810	22-Oct-12	fit water hose and fitting on drifter flushing head
214885	23-Oct-12	rod alignment and top stinger creeping
214949	25-Oct-12	DAILY SERVICE & INSPECTION
214784	26-Oct-12	Top stinger has oil leak not holding
214969	26-Oct-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
215290	28-Oct-12	Daily and repairs to ropes.
215389	29-Oct-12	replace pito joystick
215537	1-Nov-12	DAILY SERVICE & INSPECTION
215556	2-Nov-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
215995	2-Nov-12	rehose a/c and regas air cond test replace fans
216213	6-Nov-12	replace grease line and adjust rod alignment.
216345	8-Nov-12	DAILY SERVICE & INSPECTION
216366	9-Nov-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
216668	10-Nov-12	called to drill with reports of no rapid feed, not counting
216391	12-Nov-12	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
216710	12-Nov-12	told to check drill at start of shift as Joe thinks sensor
217224	14-Nov-12	replace blown hose
217043	15-Nov-12	DAILY SERVICE & INSPECTION
217219	15-Nov-12	called to a electrical disturbance fault... found
217258	15-Nov-12	broken drifter bolts in rear plate, water flushing not
217075	16-Nov-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
217083	16-Nov-12	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
217316	16-Nov-12	re-seal feed cyl (leaking)
217330	16-Nov-12	need to change out 4 x jack legs (all leaking bad)
217357	17-Nov-12	replace water flushing valve not shutting off.
217369	17-Nov-12	oil leak in front control box on carasuel
217619	20-Nov-12	replace rear drifter bolts
217907	21-Nov-12	check and adjust rod alignment
217713	22-Nov-12	DAILY SERVICE & INSPECTION
217954	22-Nov-12	Long arms and rapid feed fault (Being investigated)
217733	23-Nov-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
217973	23-Nov-12	general repairs to boom. And nut&bolt restock
218437	28-Nov-12	Slid in to drain . Some damage to hand rail and door
218221	29-Nov-12	DAILY SERVICE & INSPECTION

218241	30-Nov-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
218639	30-Nov-12	blown hose, replace front wiper, replace bolts on front work
218641	1-Dec-12	fit rollover over centre valves
219141	5-Dec-12	inner zoom tube cracked u/s ordered new on from tamrock
218935	6-Dec-12	DAILY SERVICE & INSPECTION
218968	7-Dec-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
219256	7-Dec-12	Lt Ft jack creaping . Reseal check valve assy
219863	13-Dec-12	DAILY SERVICE & INSPECTION
220064	13-Dec-12	repair lh work light, replace rear drifter bolts, refit
219882	14-Dec-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
220106	14-Dec-12	replace wiper washer pumps
220180	16-Dec-12	adjust rod alignment
220494	18-Dec-12	replace wiper blade
220502	19-Dec-12	H4535- Clean dirty trailing cable plug.
220563	20-Dec-12	DAILY SERVICE & INSPECTION
220364	21-Dec-12	Inspect long arms for slop. Adjust if possible. Bushes?
220587	21-Dec-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
220589	21-Dec-12	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
220762	22-Dec-12	replace blown hose
220768	22-Dec-12	daily , rod handeler and adjustments to feed via GUIE
220792	23-Dec-12	Long arms out of adjustment/creaping. Adjust and repair oil
220831	27-Dec-12	DAILY SERVICE & INSPECTION
220850	28-Dec-12	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
221202	31-Dec-12	replace danfoss valve and coil
221259	1-Jan-13	blown hose.
221582	2-Jan-13	tension strapping bolts.
221329	3-Jan-13	DAILY SERVICE & INSPECTION
221352	4-Jan-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
221720	6-Jan-13	repair all accumulators and bearings in cylinders that where
222177	10-Jan-13	DAILY SERVICE & INSPECTION
222200	11-Jan-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
222989	16-Jan-13	no start fault and flat batteries,jump start and prime up
222908	17-Jan-13	DAILY SERVICE & INSPECTION
222928	18-Jan-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
223127	18-Jan-13	broken fitting in stinger
223161	19-Jan-13	replace high side accumulator
223481	22-Jan-13	broken strapping bolt there was nill in stock we have taken
223487	22-Jan-13	blown hose hyd hose
223678	23-Jan-13	Replace blown hose
223539	24-Jan-13	DAILY SERVICE & INSPECTION
223749	24-Jan-13	rear gripper arm bracket need replacing on service day
223779	24-Jan-13	weld up rear gripper arm bracket and repair pito jaw
222929	25-Jan-13	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
223558	25-Jan-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
223902	28-Jan-13	C4540 change out trailing cable due to red phase being
223954	29-Jan-13	replace R HSide joystick.
224522	30-Jan-13	replace 2 x blown hoses
224355	31-Jan-13	DAILY SERVICE & INSPECTION

224605	31-Jan-13	Replace feed cyl - leaking bad.
223814	1-Feb-13	Change out the carousel on LH04.
224374	1-Feb-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
224632	1-Feb-13	Check and bleed up SLU.
224647	2-Feb-13	replace broken bolts in accumulator
224671	3-Feb-13	all boom movements fast
223568	4-Feb-13	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
224767	4-Feb-13	repairs to water/air flush valves. Sticking on.
224949	5-Feb-13	Repairs to grease gun and hoses
225020	7-Feb-13	DAILY SERVICE & INSPECTION
225208	7-Feb-13	blown carrier hose percussion put 6m hose on till service da
225038	8-Feb-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
225299	9-Feb-13	blown hose in boom loom back to carrier
225315	10-Feb-13	hole depth counter not working found S33 sensor (long arms
225321	10-Feb-13	water fault low pressure - pull valve solenoid apart clean
225504	11-Feb-13	refit feed rope
225518	11-Feb-13	fit new fitting and replace blown hose
225075	12-Feb-13	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
225521	12-Feb-13	H 4660 O/S LH 04 Would not power up, Found dirty pilot circ
225523	12-Feb-13	Sensor lead was broken at bottom of Carasell.
225848	13-Feb-13	oring replaced on accum on drifter
225728	14-Feb-13	DAILY SERVICE & INSPECTION
225913	14-Feb-13	Replace high side accumulator.
225745	15-Feb-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
225746	15-Feb-13	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
225958	16-Feb-13	Front wiper flogged out
225979	16-Feb-13	Replace strapping bolt
226007	18-Feb-13	LH04 @04660sfw tripping O/L power pack rated 40 amps found
226087	18-Feb-13	water pressure fault
226103	18-Feb-13	replace accumulator low side
226327	19-Feb-13	Called to lights not working, found K401 relay U/S, replaced
226346	19-Feb-13	charge both accumulators
226498	20-Feb-13	fitted reco low side accumulator to drifter
226412	21-Feb-13	DAILY SERVICE & INSPECTION
226566	21-Feb-13	pilot fault. brush come off pilot slip ring.
226570	21-Feb-13	check work light operation
226431	22-Feb-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
226451	22-Feb-13	BATTERY ISOLATOR CHANGE OUT
226633	22-Feb-13	replace pitto jaws assembly bad alignment
226640	22-Feb-13	replace complete pitto assembly
226653	22-Feb-13	H4580 NFW LH04 kept shutting down on low water
226667	23-Feb-13	check water fault found low header pressure water in mine
226678	23-Feb-13	replace worn pitto jaws
226776	25-Feb-13	repair faulty light relay in A cabinet.
226791	26-Feb-13	H4580NFW boom tilt & rotation cylinder fault
226812	26-Feb-13	replace grease pump
226813	26-Feb-13	replace clino sensor
226923	28-Feb-13	DAILY SERVICE & INSPECTION

226942	28-Feb-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
227192	28-Feb-13	change out flat pos 1 tyre
227294	5-Mar-13	rear tail pipe section needs replacing
227549	5-Mar-13	Replaced faulty B6 sensor cable and hose .
227574	5-Mar-13	top up oil's
227634	7-Mar-13	DAILY SERVICE & INSPECTION
227654	8-Mar-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
228100	8-Mar-13	replace carousel proximity switch and cable.
228127	8-Mar-13	replace broken engine fan belt
228154	9-Mar-13	repalace broken fitting on boom
228184	10-Mar-13	Replace shroder valve, charge accumulator.
228241	12-Mar-13	replace eng fan belt and tensioner
228255	12-Mar-13	front stinger creeping replace overcentre valve and
228530	13-Mar-13	Accumulator us, change out high side.
228446	14-Mar-13	DAILY SERVICE & INSPECTION
228466	15-Mar-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
228467	15-Mar-13	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
228650	15-Mar-13	service general repairs
228834	17-Mar-13	overload on power pack is intermitentally tripping, tong
228841	17-Mar-13	refit feed ropes to pulleys
228843	17-Mar-13	regas accumulators
228992	19-Mar-13	called to H4600 as Lh04 had no pilot. found loose wire on
229034	21-Mar-13	DAILY SERVICE & INSPECTION
229052	22-Mar-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
229318	22-Mar-13	replace alternator not charging
229391	23-Mar-13	replace faulty light relay
229492	25-Mar-13	blown percussion hose.
229726	28-Mar-13	DAILY SERVICE & INSPECTION
227295	29-Mar-13	pos 1 duo seal leaking
229744	29-Mar-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
229964	29-Mar-13	called to an intermittant sensor coms fault, we waited with
230001	30-Mar-13	blown hose
230011	31-Mar-13	repair flickeringwork lights on Long hole
230059	1-Apr-13	charge accumilators low and high side
230203	2-Apr-13	check drilling fault loosing percusion
230380	3-Apr-13	short arm sensor fail. replace cable and proxy sensor
230287	4-Apr-13	DAILY SERVICE & INSPECTION
230443	4-Apr-13	check no air mist
230308	5-Apr-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
230471	5-Apr-13	replace air mist flushing valve.
230503	6-Apr-13	Air /Water Flushing was air only
230512	6-Apr-13	depth counter fault calibrate linear sensor ok, air mist
231037	9-Apr-13	replace broken shratter valve and gas acc
231103	11-Apr-13	DAILY SERVICE & INSPECTION
231126	12-Apr-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
231481	12-Apr-13	weekly repairs ans parts from Pirtek
231859	16-Apr-13	replace K402 relay
232036	17-Apr-13	REPLACE BROKEN BOLTS IN ACCUMILATOR

231938	18-Apr-13	DAILY SERVICE & INSPECTION
232067	18-Apr-13	repair high pressure accumulator
231956	19-Apr-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
231957	19-Apr-13	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
232090	19-Apr-13	C4516 L/H/S work light faulty
232094	19-Apr-13	check air con
232098	19-Apr-13	water hose reel chain broken
232107	19-Apr-13	replace wiper blade and flushing head housing
232118	19-Apr-13	jump start.
232124	20-Apr-13	water pump low pressure possibly caused by air in line
232293	22-Apr-13	replace broken fitting on drifter
232444	25-Apr-13	DAILY SERVICE & INSPECTION
232560	25-Apr-13	replace high side accumulator
232461	26-Apr-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
232657	26-Apr-13	blown carrier hose
233259	1-May-13	water head needs repair
233194	2-May-13	DAILY SERVICE & INSPECTION
233211	3-May-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
233481	3-May-13	replace feed ropes.
233493	3-May-13	replace diaphragm in pito jaw accumulator.
233502	3-May-13	check for any rags or flammable materials around engine bay
233523	4-May-13	angle sensor on LH04 had cable severed inside hydraulic
233683	7-May-13	replace worn pito jaws as req
233860	9-May-13	DAILY SERVICE & INSPECTION
233877	10-May-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
234153	10-May-13	General repairs
234169	10-May-13	replace hyd fitting
234189	10-May-13	pilot fault, there was a problem with the jumbo box, changed
233898	12-May-13	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
234583	16-May-13	DAILY SERVICE & INSPECTION
234694	16-May-13	replace shroder valve -regas accum
234729	16-May-13	a/c fault not getting cold.
234600	17-May-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
234601	17-May-13	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
234726	17-May-13	Cancelled during entry
234727	17-May-13	a/c fault not getting cold. DUPLICATE W/O. SEE 234729.
234738	17-May-13	air cond not cold - blown a/c hose regas
234834	19-May-13	regas accumulator check drilling
235157	23-May-13	DAILY SERVICE & INSPECTION
235175	24-May-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
235474	26-May-13	called to LH04 with shank lube fault found flow switch
235475	26-May-13	Replace missing bolts in drifter, operator repaired himself
235576	27-May-13	reported that operator couldnt turn his flushing water off
235611	30-May-13	Inspect Engine bay & clean if required
235742	30-May-13	DAILY SERVICE & INSPECTION
235759	31-May-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
236140	31-May-13	replace return ropes and park brake valve.
236152	31-May-13	change out pito jaws and check -tension feed ropes

236523	6-Jun-13	DAILY SERVICE & INSPECTION
236679	6-Jun-13	replace pito jaws and bolts
236543	7-Jun-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
236725	7-Jun-13	Replace pito jaws and general repairs
237082	11-Jun-13	charge accumulators
237396	12-Jun-13	carsoul locking up
237405	12-Jun-13	chane over center valve on feed tilt cylinder
237154	13-Jun-13	DAILY SERVICE & INSPECTION
237172	14-Jun-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
237497	14-Jun-13	check / tension all wheel nuts
237499	14-Jun-13	hit wall while tramming up for service day damage to abox/
237576	16-Jun-13	R4660- Drilling Joystickwas sloppy in console
237585	16-Jun-13	replace blown hose.
237790	17-Jun-13	recharge hp accumulator.
238042	19-Jun-13	blown hose.
237939	20-Jun-13	DAILY SERVICE & INSPECTION
237958	21-Jun-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
237959	21-Jun-13	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
238165	21-Jun-13	no air getting to low pressure switch
238141	22-Jun-13	called to the drill with reports of low air... found a block
238159	22-Jun-13	Oil leak . Broken fittings @ pito jaws
238341	25-Jun-13	replace bendigo valve
238535	27-Jun-13	DAILY SERVICE & INSPECTION
238554	28-Jun-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
238904	28-Jun-13	replace boom swing pin (worn out).
238945	29-Jun-13	blown hose and broken fitting - ezy out fitting
239082	2-Jul-13	gripper alignment out, and flushing valve staying on.
239385	2-Jul-13	Adjust rod alignment
239457	4-Jul-13	DAILY SERVICE & INSPECTION
239479	5-Jul-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
239694	6-Jul-13	change accumulator high side
239902	11-Jul-13	DAILY SERVICE & INSPECTION
239721	12-Jul-13	Arms need to be rebushed.
239926	12-Jul-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
240120	12-Jul-13	replace faulty hyd fitting
240494	16-Jul-13	replace front wiper.
240565	18-Jul-13	DAILY SERVICE & INSPECTION
240584	19-Jul-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
240585	19-Jul-13	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
240765	19-Jul-13	Smoke and sparks coming from engine bay , set AFFF off.
240789	21-Jul-13	blown hose
241276	24-Jul-13	blown hose and oil
241187	25-Jul-13	DAILY SERVICE & INSPECTION
241206	26-Jul-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
241341	26-Jul-13	replace front feed pulley and ropes, and return ropes.
241358	26-Jul-13	low air fault / fit new pressure switch
241367	27-Jul-13	LH 04 stopped on "Low Air Pressure" On arrival the operator
241421	28-Jul-13	repair faulty work lights.

241426	28-Jul-13	blown water hose - hook mine water straight to rig
241463	29-Jul-13	blown hose and fitting.
242030	31-Jul-13	check water pump out. reported to be cutting in and out.
241926	1-Aug-13	DAILY SERVICE & INSPECTION
240453	2-Aug-13	LH04 install Bramco pilot relay
241944	2-Aug-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
242092	3-Aug-13	Pressure washer not working. Repair needed hosing and change
242102	3-Aug-13	Check tilt creeping
242118	3-Aug-13	low side accumulator regas
242149	4-Aug-13	no water pressure
242211	5-Aug-13	tighten joy stick
241973	6-Aug-13	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
242672	7-Aug-13	replace S33 and cable, Replace lighting relay and base
242547	8-Aug-13	DAILY SERVICE & INSPECTION
242564	9-Aug-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
242964	9-Aug-13	low air pressure fault tried to fault find but seemed
242975	10-Aug-13	lhs rear jack leg leaking oil - no chrome on shaft needs
243002	11-Aug-13	replace pressure washer reel and hose assembly
243021	11-Aug-13	blown hose.
242593	12-Aug-13	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
243287	15-Aug-13	DAILY SERVICE & INSPECTION
243390	15-Aug-13	replace u/s joystick
243304	16-Aug-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
243305	16-Aug-13	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
243409	16-Aug-13	called to lh04 with reports of no hole depth displayed found
243496	18-Aug-13	find main switch auxillarys had fallen off during tramming
243573	19-Aug-13	blown feed hose
243784	22-Aug-13	DAILY SERVICE & INSPECTION
243878	22-Aug-13	Low air fault . Blown header down the drive.
244138	22-Aug-13	replace water hose
244170	22-Aug-13	charge drifter accumulator.
243802	23-Aug-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
244205	23-Aug-13	replace feed tilt cylinder. creeping.
244237	24-Aug-13	replace water flushing valve.
244258	24-Aug-13	inner tube cracked replaced assy
244261	24-Aug-13	free up air mist valve
244267	25-Aug-13	clean up old air flushing valve, and replace, not shutting
244307	26-Aug-13	blown hose.
244312	26-Aug-13	C4440 SFW replace light relay/base k402 (workin lights)
244779	28-Aug-13	adjust gripper arms.
244798	28-Aug-13	rod alignment and blown hose fitting
244685	29-Aug-13	DAILY SERVICE & INSPECTION
244703	30-Aug-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
245296	4-Sep-13	replaceb pito jaws
245204	5-Sep-13	DAILY SERVICE & INSPECTION
245222	6-Sep-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
245396	6-Sep-13	replace rod gripper jaws and realign as req
245493	9-Sep-13	replace 2 drifter hoses

245518	10-Sep-13	stuck in drain guide out
246087	11-Sep-13	replace drifter bolts
245102	12-Sep-13	radio not working oin some channels
245960	12-Sep-13	DAILY SERVICE & INSPECTION
246131	12-Sep-13	charge low side accumalator
246142	12-Sep-13	check accumulators and rebuild spare one
245977	13-Sep-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
246231	15-Sep-13	Low oil , blown hoses X 2
246555	19-Sep-13	DAILY SERVICE & INSPECTION
246702	19-Sep-13	blown hose.
246573	20-Sep-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
246574	20-Sep-13	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
246759	20-Sep-13	replace pressure washer on/off valve, leaking
246795	21-Sep-13	replace feed rope
246816	22-Sep-13	bolts in end plate on drifter replaced
246994	24-Sep-13	replace blown main hose under cab
246615	25-Sep-13	Gear motor in a/c unit leaking
247419	25-Sep-13	top up hyd oil
247061	26-Sep-13	DAILY SERVICE & INSPECTION
247078	27-Sep-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
247816	3-Oct-13	DAILY SERVICE & INSPECTION
248008	3-Oct-13	Disparity fault on GUI "shank lube error" found green
247838	4-Oct-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
248062	5-Oct-13	replace 4 x blown hoses
248305	8-Oct-13	replace pito jaws
247937	9-Oct-13	replace tilt cylinder check valves when they are in stock
248549	9-Oct-13	order grease hose and fitting from pirtek
248471	10-Oct-13	DAILY SERVICE & INSPECTION
248492	11-Oct-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
248757	14-Oct-13	replace bolts to drifter end cap
248945	15-Oct-13	C/O tilt ram over centre valve
249049	17-Oct-13	DAILY SERVICE & INSPECTION
248676	18-Oct-13	replace turbo waste gate sized
249067	18-Oct-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
249068	18-Oct-13	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
249461	20-Oct-13	nostart prime fuel
249503	21-Oct-13	no start fault ,found loose filter ,tighten filter cap
249527	21-Oct-13	O4660 NFW B8 sensor fault replace linear sensor
249535	21-Oct-13	low accumulator replaced drill fault and fix oil leak under
249659	22-Oct-13	replace faulty front wiper blade
249756	22-Oct-13	no start prime fuel
249906	23-Oct-13	no start, fuel charge pump u/s.
249825	24-Oct-13	DAILY SERVICE & INSPECTION
249843	25-Oct-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
249976	25-Oct-13	Adjust up zoom and general repairs
250498	30-Oct-13	change pito jaws
250501	30-Oct-13	blown hose on boom
250331	31-Oct-13	DAILY SERVICE & INSPECTION

250351	1-Nov-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
250995	3-Nov-13	check and regas accumulators
251168	5-Nov-13	C4460 SFW Rig has a damaged CAN Cable
251358	6-Nov-13	C4480 NHW called to rig due to tripping E/L @ JBox tested
251434	7-Nov-13	DAILY SERVICE & INSPECTION
251582	7-Nov-13	C4480NHW Called to rig tripped out on E/L tested cable tests
251454	8-Nov-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
251615	8-Nov-13	Top up oil and repair leaks
251629	8-Nov-13	500HR DRIFTER CHANGE OUT - WRONG PLANT ITEM. SEE HISTORY
251768	9-Nov-13	SLU unit light on . Bleed up system
251492	12-Nov-13	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
251957	12-Nov-13	called to rig with reports of no pilot, found a wet
251980	12-Nov-13	Order hydraulic hose for can cable see Russle
251983	12-Nov-13	rock lub flow switch broken
251657	14-Nov-13	DAILY SERVICE & INSPECTION
251675	15-Nov-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
251676	15-Nov-13	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
252180	15-Nov-13	check rear diff for overfilling and report.
252204	16-Nov-13	replace muffler.
252247	17-Nov-13	grind weld off clip on autodrill not working drifter wont
252623	20-Nov-13	replace pito jaws.
251733	21-Nov-13	DAILY SERVICE & INSPECTION
252666	21-Nov-13	Check engine fault light . No fault found . Clear codes.
252537	22-Nov-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
252741	23-Nov-13	replace blown hyd hose
252936	26-Nov-13	jack leg fault rear
253183	27-Nov-13	Jack leg and pito jaws
253081	28-Nov-13	DAILY SERVICE & INSPECTION
253099	29-Nov-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
253248	29-Nov-13	pito jaws not holding pressure on rods, replace accumulator
253500	3-Dec-13	top up hyd oil.
253748	4-Dec-13	replace hyd fitting.
253831	5-Dec-13	DAILY SERVICE & INSPECTION
253936	5-Dec-13	blown hose on pito jaws.
253849	6-Dec-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
254226	7-Dec-13	blown water hose to pump
254248	8-Dec-13	called to longhole @ H4560 with reports of lost power...
254255	8-Dec-13	repair fuel leak . Replace copper washer
254265	8-Dec-13	Tilt cylinder creeping
254276	9-Dec-13	No front wiper . Rags fell down behind dash and got caught
254282	9-Dec-13	remove a rag that had wrapped around the windscreen
254422	10-Dec-13	repairs to oil leak
254474	10-Dec-13	blown carrier hose
254492	11-Dec-13	inspect rig as dayshift reported that it was loosing pilot
254556	12-Dec-13	DAILY SERVICE & INSPECTION
254651	12-Dec-13	repairs to oil leak
254706	12-Dec-13	check rig for pilot fault @ H4560. 111-jtc-07 hasa 10ohm
254578	13-Dec-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

254786	14-Dec-13	replace front wiper blade.
254829	15-Dec-13	C4460 SFW Called to rig sensor com error fault was coming up
254885	16-Dec-13	change out tilt sensor.
254887	16-Dec-13	replace tilt angle sensor probe and arm.
255173	17-Dec-13	blown perc hose
255334	18-Dec-13	rod alignment
255238	19-Dec-13	DAILY SERVICE & INSPECTION
255369	19-Dec-13	replace flushing seals
255049	20-Dec-13	Check LH04 drill rig as per Sandvic warranty
255255	20-Dec-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
255256	20-Dec-13	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
255395	20-Dec-13	general repairs
255454	21-Dec-13	no stinger retraced damaged to electrical bax
255471	22-Dec-13	E/L on jumbo box tripped, checked cables ok, reset ok,
255538	26-Dec-13	DAILY SERVICE & INSPECTION
255556	27-Dec-13	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
255980	27-Dec-13	replace rotation danfoss coil u/s no rotation.
255988	27-Dec-13	C4461 NFW replace rotation solinoid lost rotation
256006	28-Dec-13	blown hose.
256229	30-Dec-13	replacement valve and adaptor ordered for water drain valve
256164	2-Jan-14	DAILY SERVICE & INSPECTION
256185	3-Jan-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
256516	5-Jan-14	Adjust long arms
256520	5-Jan-14	called to the long hole rig at the C4460 as the
256546	6-Jan-14	Blown carrier hose
256966	9-Jan-14	DAILY SERVICE & INSPECTION
256983	10-Jan-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
257289	10-Jan-14	fit new wiper blade
257324	12-Jan-14	C4461 NFW Comms radio receiving but not transmitting,
257547	13-Jan-14	replace a/c condensor.
257564	13-Jan-14	C4461 SHW LH04 fault S35 cable (sensor cable) was
257679	16-Jan-14	DAILY SERVICE & INSPECTION
257702	17-Jan-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
257703	17-Jan-14	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
258085	19-Jan-14	Engine start, but wouldn't run for long
258099	20-Jan-14	called to LH04 at C4475 as the rig lights were flickering
258243	20-Jan-14	replace blown rollover hoses
258365	23-Jan-14	DAILY SERVICE & INSPECTION
258383	24-Jan-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
258560	25-Jan-14	adjust rod handler.
258568	25-Jan-14	O4660 LH04 Shank lube fault coming up on guai panel found
258575	25-Jan-14	feed cylinder cracked around base dead end leaking oil
258581	25-Jan-14	disconnect then re-connect linear sensor for fitters to
258594	26-Jan-14	repair rock lube fault and check rod alignment
258649	28-Jan-14	shank lube fault, replace circuit board.
258657	28-Jan-14	C4480 NFW assit fitter with the shank lube fault
259014	30-Jan-14	DAILY SERVICE & INSPECTION
259033	31-Jan-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

259049	3-Feb-14	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
259682	6-Feb-14	DAILY SERVICE & INSPECTION
260373	6-Feb-14	replace hyd hoses x 3.
260379	6-Feb-14	blown hose drifter in boom loom
259185	7-Feb-14	Replace rubber deflector on boom
259701	7-Feb-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
260419	7-Feb-14	a/c blown hose and fitted new cells to a/c unit regas and
260450	8-Feb-14	no power to LH04 @ PHX4440 JBS26 had faulty control cct.
260484	9-Feb-14	top up hyd oil check for leaks
260564	10-Feb-14	check shank lube fault
260674	11-Feb-14	replace feed ropes x 2.
260694	11-Feb-14	electric motor overloading, make sure water cooler drains
260695	11-Feb-14	rock lube fault bleed up system.
260697	11-Feb-14	drifter lube fault, keeps shutting down.
260698	11-Feb-14	tripping on Power Pack O/L fault. found no water going thru
260708	11-Feb-14	oil leak replace fitting and top up hyd oil
259742	12-Feb-14	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
260872	12-Feb-14	replace diaphragm in the pito accumulator.
260899	12-Feb-14	blown hose under cab
260901	12-Feb-14	replace pito jaws
259793	13-Feb-14	DAILY SERVICE & INSPECTION
260801	13-Feb-14	DAILY SERVICE & INSPECTION
260821	14-Feb-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
261088	17-Feb-14	Replace broken bolt in accumulator
261099	17-Feb-14	replace blown -6 hose
261402	20-Feb-14	DAILY SERVICE & INSPECTION
258017	21-Feb-14	Fit valves and seal kit to compressor as per Mark Hoben
260517	21-Feb-14	Change rear axle - making oil.
261420	21-Feb-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
261421	21-Feb-14	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
261938	24-Feb-14	install new k425 relay as per sandvik warranty
261959	24-Feb-14	blown hose.
261977	24-Feb-14	oil coming out between drifter near strapping bolt (monitor)
262137	26-Feb-14	oil coming out between drifter near strapping bolt (monitor)
262329	26-Feb-14	check /adjust rod alignment and cut drill bit of drill rod
262211	27-Feb-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
262360	27-Feb-14	broken hyd fitting
262228	28-Feb-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
262558	4-Mar-14	recalibrate the longhole rig as it was 4.6 degree
262772	6-Mar-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
262960	6-Mar-14	top up hyd oil check for leak
262638	7-Mar-14	Clean up the ID Plate on LH04, it has been Reported that it
262790	7-Mar-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
262986	7-Mar-14	a/c not getting cold, hose leaking.
263037	8-Mar-14	replace pito jaws, repair gripper frame mount, replace front
263044	8-Mar-14	check oil leak on drifter and regas pito accumulator
263068	9-Mar-14	check pito jaws creeping, by-pass test cyl ok, adjust
263110	10-Mar-14	replace feed ropes.

263248	11-Mar-14	change out pito jaw assy. worn and snapped arm.
263308	12-Mar-14	replace cab door struts. and gripper arm bracket.
263331	13-Mar-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
263348	14-Mar-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
263580	15-Mar-14	Tighten/replace drifterbolts as required.
263639	17-Mar-14	blown hose
263704	18-Mar-14	change LHS joystick
263711	18-Mar-14	broken accumulator bolts
263888	20-Mar-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
264077	20-Mar-14	oil leak - blown hose
264097	20-Mar-14	engine alarm coming on, eng temp, eng oil level.
263907	21-Mar-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
263908	21-Mar-14	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
264119	21-Mar-14	fit new front wiper assembly and motor
264283	23-Mar-14	C4461sfw LH04 lost power to rig both 1000v and 24v
264658	26-Mar-14	gripper cyl & pins broke u/g
264673	26-Mar-14	comms error on GUI. Found 24V can supply out on X2-20 in R3
264542	27-Mar-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
264561	28-Mar-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
264977	28-Mar-14	blown hose
264978	28-Mar-14	pin fell out of jaws ???
265035	30-Mar-14	got called to sensor comm and electrical disturbance errors,
265038	30-Mar-14	blown hose
265054	31-Mar-14	Reseal cassette drive motor
265435	3-Apr-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
265456	4-Apr-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
265640	4-Apr-14	rod alignment
265651	5-Apr-14	check and adjust rod alignment.
265652	5-Apr-14	replace cabin a/c blower fan.
265653	5-Apr-14	rod counter not counting, adjust pito pressure switch.
265657	5-Apr-14	replace faulty aircon fan motor
265659	5-Apr-14	Check over linear sensor as reported not working. we
265743	7-Apr-14	rod alignment
265764	8-Apr-14	replace front wiper blade.
265870	10-Apr-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
266017	10-Apr-14	Charge high side accumulator
265887	11-Apr-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
266237	13-Apr-14	replace feed tilt over center valve
266469	14-Apr-14	ROD ALIGNMENT AND JAWS.
266543	17-Apr-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
266847	17-Apr-14	broken fitting on gripper jaws
266561	18-Apr-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
266562	18-Apr-14	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
266866	18-Apr-14	fit new fuel primer pump -
266953	21-Apr-14	Phx 4400 SHW called to rig had a E/L fault tested trailing
266984	21-Apr-14	hose
266990	21-Apr-14	PHX4400 SHW repaired CAN cable hosing
266960	22-Apr-14	rods not pulling on auto

267214	22-Apr-14	Blown hose x2
267369	23-Apr-14	adjust rod alignment and replace front wiper blade
267293	24-Apr-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
267429	24-Apr-14	Repair crack on dpw swing arm
267269	25-Apr-14	Replace the CAN cable and protective hose on LH04 during
267311	25-Apr-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
267538	25-Apr-14	CLINO NOT WORKING. B6 SENSOR BROKEN INSIDE HOSE. REPLACED.
267521	27-Apr-14	trailing cable DTE, changed cable 14 with cable 04
267856	1-May-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
268008	1-May-14	replace S35 lead and sensor.
267806	2-May-14	On LH04 service replace the retaining ring (Aluminium) on
267874	2-May-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
268364	3-May-14	Called to LH04 for sensor fault, Found S34 to be faulty,
268369	3-May-14	replace S34 sensor cable.
268781	8-May-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
268801	9-May-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
269208	11-May-14	change S41 sensor and cable
269215	11-May-14	replace wipper blade
268834	12-May-14	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
269278	12-May-14	top up hydraulic oil
269284	13-May-14	Replace stereo speakers
269391	15-May-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
264106	16-May-14	need new sender engine oil temp/pressure ordered from
266861	16-May-14	need new engine air filter housing end cap u/s
269412	16-May-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
269413	16-May-14	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
269692	16-May-14	Phx4400SHW top R/H/S work light wasnt working found broken
269715	16-May-14	pirtek made new pressure washer hose and top up grease
269723	16-May-14	need to replace hyd motor on a/c drive as shaft worn and
269739	17-May-14	PH4400SHW would not count rods or metres found S41 proxy
269858	19-May-14	window washers not working
270167	21-May-14	front window smashed by rock
270090	22-May-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
270223	22-May-14	Flushing head seals
270109	23-May-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
270231	23-May-14	called to LH04 as it wouldnt count meters... found there to
270301	24-May-14	Long arm pin fell out . Needs boss welding on
270326	25-May-14	Broken fitting to hyd manifold on front of boom.
270880	28-May-14	replace blown hose and broken shank.
270771	29-May-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
270930	29-May-14	park stuck on in decline - check coil and wiring
270791	30-May-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
270944	30-May-14	replace water hose reel chain. 10b1 chain
270967	30-May-14	replace park brake coil.
271182	1-Jun-14	repair spare parts, flushing head, and gripper cylinders.
271262	2-Jun-14	fix air flush valve and top up oil
271733	4-Jun-14	fit new lance on pressure washer
271622	5-Jun-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197

271642	6-Jun-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
271799	6-Jun-14	Broken return ropes and drifter Jumped over rail/feed cyl.
271888	9-Jun-14	adjust contrast on LCD screen on gui panel at P4400
271910	9-Jun-14	wiper blade and daily
271967	11-Jun-14	LCD screen went blank on gui panel traced short on linear
272125	12-Jun-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
272144	13-Jun-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
272187	13-Jun-14	Replace linear sensor on LH04
272296	13-Jun-14	a/c motor flex drive spacer ring needs replacing ordered
272491	16-Jun-14	front rhs jack leg directional valve u/s have ordered asap
272738	19-Jun-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
272756	20-Jun-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
272757	20-Jun-14	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
272989	22-Jun-14	called to LH-04 to bleed the rock lube flow switch.
273308	26-Jun-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
273326	27-Jun-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
273539	28-Jun-14	Repair faulty lights on LH04.
273547	28-Jun-14	replace isolator, not switching off.
273576	29-Jun-14	clean water flushing valve, adjust feed ropes, align drifter
273992	1-Jul-14	air flushing staying on, blockage.
273999	1-Jul-14	replace blown hose and fitting on boom
274090	3-Jul-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
274113	4-Jul-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
274294	5-Jul-14	check air con not working
274310	6-Jul-14	Repair A/C. Bunt out plug to rear unit.
274909	7-Jul-14	Reline drifter slides.
274671	10-Jul-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
274689	11-Jul-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
274861	11-Jul-14	Phx4400 SHW called to rig lost dump and rotation angle
274949	11-Jul-14	repair service day
274955	12-Jul-14	replace e-stop. rear stinger not retracting, din plug off
274962	12-Jul-14	Phx4400 SHW called to rig had error up for angle on guai
274971	12-Jul-14	replace blown boom hose
274983	13-Jul-14	calibrate angle sensors
274990	13-Jul-14	Phx 4380NFW LH04 lost angles again found the tilt sensor
275187	14-Jul-14	auto not working
275223	14-Jul-14	check lube fault
275237	15-Jul-14	Phx4400 NHW LH04 tilt sensor cable damaged
275559	17-Jul-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
275578	18-Jul-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
275579	18-Jul-14	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
275769	18-Jul-14	Blown carrier hose
275793	19-Jul-14	blown carier hose
275801	19-Jul-14	Blown carrier hoses X 3 . Bleed up SLU unit.
275819	20-Jul-14	check auto drill
275835	20-Jul-14	check and adjust long arms as required
275917	21-Jul-14	replace missing bolt out of long arm
275935	21-Jul-14	replace 2 X blown hoses

275978	22-Jul-14	change out rope.
276291	23-Jul-14	change pressuer wash pump
276301	23-Jul-14	blown hose
276103	24-Jul-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
276122	25-Jul-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
276368	25-Jul-14	replace pito cylinder, leaking.
276369	25-Jul-14	replace zoom wear plate.
276375	25-Jul-14	air cond not working - relay
276393	26-Jul-14	blown hose.
276783	30-Jul-14	replace S35 on carosoul. Proxy switch U/S
276683	31-Jul-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
276702	1-Aug-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
277133	2-Aug-14	Free up zoom and blown hose
277146	2-Aug-14	blown hydruilic hose
277165	3-Aug-14	dump sensor cable was broken, and old cable was jammed
276721	4-Aug-14	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
277240	4-Aug-14	Replace angle sensor cable on Longhole as it had snagged on
277393	6-Aug-14	damage found on trailing cable 20m from plug megered ok but
277699	6-Aug-14	replace missing jack leg foot
277558	7-Aug-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
277577	8-Aug-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
277810	8-Aug-14	Cancelled during entry
277811	8-Aug-14	short arm cylinder clevis snapped off weld up. replace
277928	10-Aug-14	replace B26 sensor as it has corroded around the supply
265532	11-Aug-14	DPU Cracked requires new unit.
275194	11-Aug-14	BOOM MAIN PIVOT (REAR PART).
275195	11-Aug-14	BOOM MODULE. B14UG05A.
275196	11-Aug-14	ROTARY ACTUATOR. B14UG05A.
275197	11-Aug-14	BOOM HEAD CYLINDER.
275198	11-Aug-14	FRONT STINGER. B14UG05A.
275199	11-Aug-14	FRONT JACK EXTENSION BEAM PINS & BUSHES.
275200	11-Aug-14	ZOOM ASSY INNER TUBE. B14UG05A.
275201	11-Aug-14	ZOOM CYLINDER. B14UG05A.
275202	11-Aug-14	ROD CHANGER. B14UG05A.
275203	11-Aug-14	PITO ASSY.
275204	11-Aug-14	FEED RAIL. B14UG05A.
275205	11-Aug-14	FEED CYLINDER. B14UG05A.
275208	11-Aug-14	FEED TILT CYLINDER.
275209	11-Aug-14	BOOM LIFT CYLINDER.
275210	11-Aug-14	ZOOM CYLINDER. - DUPLICATE. SEE 275201.
275211	11-Aug-14	BOOM SWING CYLINDER.
275213	11-Aug-14	SUPPORT CYLINDER.
275214	11-Aug-14	FEED EXTENSION CYLINDER.
276362	11-Aug-14	REBUILD CENTRE HITCH WHEN BOOM IS OVERHAULED. NOT REQUIRED
276838	11-Aug-14	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
277620	11-Aug-14	Boom Repairs for LH04 B14ug05a
278331	14-Aug-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
278352	15-Aug-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

278353	15-Aug-14	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
278898	21-Aug-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
278918	22-Aug-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
279221	25-Aug-14	fit overcentre valves to dump cyl (creeping bad) and fix oil
279429	27-Aug-14	LH04 whent out on sensor comms error
279603	27-Aug-14	blown carrier hose
279507	28-Aug-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
279528	29-Aug-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
279716	30-Aug-14	blown carrier hose
279785	1-Sep-14	replaced din plug Y35 (short arms in) in R3 box.
278763	2-Sep-14	fit exhaust lagging
280198	4-Sep-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
280350	4-Sep-14	replace snapped drifter shank.
280226	5-Sep-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
280416	6-Sep-14	broken wire on L34 sensor
280430	7-Sep-14	O4520 SFW Fault with gripper arms
280440	7-Sep-14	S32 sensor not working. fitter (Irves) found loose wire
280450	7-Sep-14	feed rope kinked jumped off
280599	8-Sep-14	replace blown hose
280720	11-Sep-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
280866	11-Sep-14	change wiper blade
280891	11-Sep-14	Broken accumulator bolts
280741	12-Sep-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
280968	13-Sep-14	Charge up pito jaw accumulator.
281721	18-Sep-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
281912	18-Sep-14	bottom feed rope came off and check/adjust rod alignment
281743	19-Sep-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
281744	19-Sep-14	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
281979	19-Sep-14	air /water fault check -clean valve
282002	20-Sep-14	a/c not cold - 2 condensor fans -u/s and cuts in/out
282014	21-Sep-14	Damage to trailing cable, clean break near bananna clamp
282069	22-Sep-14	auto drill fault, penetration adjustment out and tube count
282202	23-Sep-14	replace gripper jaw cylinder.
282210	23-Sep-14	check a/c not cold compressor very hot
282464	24-Sep-14	water strainer fitting u/s.
282364	25-Sep-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
279225	26-Sep-14	Make new rod holder tray for front of rig
279767	26-Sep-14	Wiper washers U/S. Hole in bottle , 3 out 4 motors U/S.
282384	26-Sep-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
282571	26-Sep-14	blown carrier hose
282693	30-Sep-14	water fault
283070	2-Oct-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
283228	2-Oct-14	change gripper jaws not grabbing rods
283246	2-Oct-14	replace faulty brake gauge as req
283096	3-Oct-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
283285	3-Oct-14	replace lube fitting on drifter
283911	9-Oct-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
283933	10-Oct-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

284234	15-Oct-14	Hose needs replacing service day. Has joiner in it near
284679	15-Oct-14	Blown hose.
284483	16-Oct-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
284504	17-Oct-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
284505	17-Oct-14	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
284796	19-Oct-14	replace grease pump
284807	20-Oct-14	H4580 LOH 04 Shut down with only GUI panel functions
285052	23-Oct-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
285075	24-Oct-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
285410	26-Oct-14	repairs to rod gripper . Pin fell out.
285509	27-Oct-14	replace front wiper
285763	29-Oct-14	replace strapping bolt
285557	30-Oct-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
285579	31-Oct-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
285645	31-Oct-14	make up new ID plate for LH04
285907	2-Nov-14	drifter alignment and pito jaws loose fix up and realign
286480	6-Nov-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
286503	7-Nov-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
286923	10-Nov-14	reseal flushing head
286547	12-Nov-14	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
287296	12-Nov-14	Replaced broken stinger bolts
287224	13-Nov-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
287249	14-Nov-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
287443	15-Nov-14	strapping bolt missing nut, and accumulator bolt broken.
287455	15-Nov-14	Change out pito jaws
287622	17-Nov-14	replace 1 x strapping bolt and nuts. tension other 3 bolts.
287795	20-Nov-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
287941	20-Nov-14	Replace broken flow switch on SLU
287959	20-Nov-14	Blown o ring on pito jaw accumulator
288001	21-Nov-14	Blown rear jack leg hose
288066	23-Nov-14	Coming up with Electrical disturbance
288070	23-Nov-14	blown high side accumulator
287818	25-Nov-14	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
287841	25-Nov-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
288515	26-Nov-14	regas accumulators
288381	27-Nov-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
288571	27-Nov-14	replace o-ring on drifter accumulator.
288568	28-Nov-14	check implement locking pins ok nothing found.ACTUALLY IT10
288614	28-Nov-14	tighten pito jaw bolts.
288680	30-Nov-14	rods not going into the carousel, jamming. adjust plate
288435	2-Dec-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
289194	4-Dec-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
289396	4-Dec-14	replace blown hoses
289486	6-Dec-14	low side accumilator
289567	8-Dec-14	Lights and park brake shorting out. park brake fault
289959	8-Dec-14	called to the LH as it was broken down in the decline with
289255	9-Dec-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
289957	9-Dec-14	Repairs toFront wiper motor

290041	11-Dec-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
290278	12-Dec-14	fix front wiper arm stuck
290085	16-Dec-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
290358	16-Dec-14	front & rear wipers u/s (Rear done 16/12/2014)
290693	17-Dec-14	replace water hose on reel.
290723	17-Dec-14	Power packs not starting because of O/L fault
290596	18-Dec-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
290853	21-Dec-14	Bolt broken off in pito jaw . Replace jaw
290641	23-Dec-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
291160	23-Dec-14	General repairs service day
291213	24-Dec-14	Daily and oil leak at rear of machine
290980	25-Dec-14	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
291289	27-Dec-14	LH 04 Trailing Cable was run over. Megger Cable All OK
291021	30-Dec-14	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
291760	1-Jan-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
292274	5-Jan-15	replace oil transfer pump
291810	6-Jan-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
292566	8-Jan-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
292721	8-Jan-15	3 x broken bolts back of drifter and fit-fix bush in gripper
292794	9-Jan-15	air mist valve stuck on
292856	11-Jan-15	H4540 LH 04 Not working on Auto.
292618	13-Jan-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
293466	15-Jan-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
293722	16-Jan-15	pito cylinder bushes worn
293788	18-Jan-15	feed rope come off pully
293840	19-Jan-15	blown hose
293844	19-Jan-15	2x blown hoses
293512	20-Jan-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
293513	20-Jan-15	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
294153	21-Jan-15	general repairs service day
294176	21-Jan-15	blown hose
294025	22-Jan-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
294287	24-Jan-15	long arm cyl u/s
294068	27-Jan-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
294507	27-Jan-15	needs a fuel line replaced braid damaged
294519	27-Jan-15	needs new exhaust muffler fitting rotted out
294610	29-Jan-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
294756	29-Jan-15	Replace broken fitting.
295218	1-Feb-15	drifter wont feed when long arms in ???
295342	2-Feb-15	Feed fault repair lub line to slides replace wiper
294656	3-Feb-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
295489	5-Feb-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
295794	5-Feb-15	check drifter slides
295352	7-Feb-15	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
286835	8-Feb-15	front diff over full check next service day
295930	9-Feb-15	auto drill not working will not stop
295537	10-Feb-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
296409	11-Feb-15	retension pos 1 and 2 wheels.

295741	12-Feb-15	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
296320	12-Feb-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
296514	13-Feb-15	Replace blown hose
296537	14-Feb-15	replace blown hose
296561	15-Feb-15	Blown accumulator
296370	17-Feb-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
296371	17-Feb-15	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
296823	17-Feb-15	Replace rear sections where rusted out
296833	17-Feb-15	replace schraeder valve and hoses on drifter that was broken
297000	18-Feb-15	2 blown hoses
296916	19-Feb-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
297049	19-Feb-15	replace long arm cyl
296944	22-Feb-15	BATTERY ISOLATOR CHANGE OUT
297152	22-Feb-15	oil leak near cable reel blown hose
297173	22-Feb-15	replace worn pito jaws and top up hyd oil
296958	24-Feb-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
297430	24-Feb-15	C/B 451.6 tripping on Diesel. mains POWER OK.
297598	25-Feb-15	new pressure washer reel ordered old one swivel base and
297519	26-Feb-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
297663	26-Feb-15	check air flushing
297830	28-Feb-15	replace blown hose
297860	1-Mar-15	oil leak . Top stinger let go. tram to surface
295810	3-Mar-15	pressure washer hose reel u/s - SEE 297598
297580	3-Mar-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
298121	3-Mar-15	blown hose -6
298431	4-Mar-15	Replace SLU filler cap and blown hose
298219	5-Mar-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
298692	7-Mar-15	replace feed rope
298718	8-Mar-15	fit strapping nuts
298735	9-Mar-15	2 x blown hoses.
298740	9-Mar-15	check clino on LH04 reported to be giving incorrect
298745	9-Mar-15	replace blown hose in loom
298264	10-Mar-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
298973	12-Mar-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
299123	12-Mar-15	Knocked and broke hyd fittings to main controll boxx under
299135	12-Mar-15	Fast boom movments
299157	13-Mar-15	repair and realighn long arms
299015	17-Mar-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
299016	17-Mar-15	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
299521	17-Mar-15	Rebuild pito jaws service day
299617	19-Mar-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
299782	19-Mar-15	2 x blown hoses.
299792	20-Mar-15	Interior work lights both u/s.
299807	20-Mar-15	check interior lights
299666	24-Mar-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
300033	24-Mar-15	replace hose and fitting.
300198	26-Mar-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
300356	27-Mar-15	Blown hose , top up oil

300669	27-Mar-15	replace blown hoses x2
301103	30-Mar-15	check drill angel
300238	31-Mar-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
301284	2-Apr-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
301386	2-Apr-15	oil leak
301509	4-Apr-15	park brake coil u/s
301516	5-Apr-15	P4350 LH 04 would stop when on deisel when PARK BRAKE was
301526	5-Apr-15	repair water leak near park brake coil.
301535	5-Apr-15	replace feed rope
301338	7-Apr-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
301798	9-Apr-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
301850	14-Apr-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
302826	15-Apr-15	order safety signs for the rear of the drills
302850	16-Apr-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
302896	17-Apr-15	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
303095	20-Apr-15	blown hose x 1.
302895	21-Apr-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
303272	23-Apr-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
302002	24-Apr-15	window washers u/s
303508	25-Apr-15	LH04 tripping e/l on jumbo box @ P4380 sfw adjusted e/l to
302261	27-Apr-15	Order spare Elephants ears for Solo's
303584	27-Apr-15	Blown hose under cab
303311	28-Apr-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
303678	29-Apr-15	blown hose
303865	30-Apr-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
304046	30-Apr-15	repair wiring on radio - cutting out
304095	1-May-15	gripper arm bush fell out repair and top up oil
304122	2-May-15	a/c not working, tx valve blocked replace comp and dryer.
304213	4-May-15	needs horse shoe pipe of water hose reel ordered (rusted
303910	5-May-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
304703	6-May-15	replace grease pump and shank
304514	7-May-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
304756	7-May-15	Replace feed tilt cylinder check valve
304849	11-May-15	Inspection of Rig found rusty water fitting on hose reel
304577	12-May-15	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
304578	12-May-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
305235	14-May-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
305602	15-May-15	blown hose on carrier
305275	19-May-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
305276	19-May-15	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
306071	21-May-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
306114	26-May-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
306688	28-May-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
306956	31-May-15	broken feed rope and flushing head seal and broken shank
306738	2-Jun-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
307197	2-Jun-15	main boom creeps
307312	2-Jun-15	tighten drifter bolts and pito cylinders replaced
307410	4-Jun-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197

307609	5-Jun-15	Charge accumulator
307696	8-Jun-15	Broken fitting and tidy up hoses
307705	8-Jun-15	Feed rope come off
307470	9-Jun-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
307868	9-Jun-15	general repairs service day
307969	11-Jun-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
308283	12-Jun-15	replace bolts in pito jaws.
308352	14-Jun-15	tighten pito jaws.
308015	16-Jun-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
308016	16-Jun-15	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
308433	16-Jun-15	change pito cylinder and pins
308541	16-Jun-15	blown hose
308626	18-Jun-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
308975	19-Jun-15	replace pito jaw , wiper blade , and gas accumulators
308667	23-Jun-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
309359	25-Jun-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
309490	25-Jun-15	FEED TILT CYLINDER. WORK ORDER COPIED FROM 275208 TO ALLOW
309527	25-Jun-15	replace bung in drifter - oil leak
309590	27-Jun-15	blown hose.
309751	29-Jun-15	keeps on blowing flushing head seals
309833	29-Jun-15	broken shank and pin came out of cylinder
308942	30-Jun-15	Centre hitch reported as flogged. Please inspect and provide
309400	30-Jun-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
310137	2-Jul-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
310402	5-Jul-15	Rock lub fault change valve
310191	7-Jul-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
310819	8-Jul-15	parts for service day
310726	9-Jul-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
310774	14-Jul-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
311349	14-Jul-15	C4380 NHWA Linear sensor issue
312109	16-Jul-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
312274	16-Jul-15	Gas up accumulator
312323	18-Jul-15	repairs to pito jaws
312158	21-Jul-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
312159	21-Jul-15	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
312532	21-Jul-15	Replace overcenter valve
312602	23-Jul-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
312746	23-Jul-15	blown hose
312883	26-Jul-15	blown hose.
312895	26-Jul-15	change pito jaw bolts and cylinder u/s - rod alignment
312934	27-Jul-15	blown hose.
312644	28-Jul-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
313100	30-Jul-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
313451	1-Aug-15	blown hyd hose
313466	2-Aug-15	carrier hose and daily
313646	3-Aug-15	blown hose hyd
313147	4-Aug-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
313705	4-Aug-15	Parts service day for LH04

313909	5-Aug-15	replace grease pump . and daily
313794	6-Aug-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
314019	7-Aug-15	tighten pito jaws.
313169	10-Aug-15	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
314105	10-Aug-15	replace flushing head seals.
314166	10-Aug-15	oil leak.
313843	11-Aug-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
314193	11-Aug-15	need new exhaust manifold and gaskets fitted - fit new turbo
313866	12-Aug-15	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
314462	13-Aug-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
314620	14-Aug-15	repairs to hose tree
314713	17-Aug-15	Replace low side accumulator
314501	18-Aug-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
314502	18-Aug-15	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
314740	18-Aug-15	Replace feed cylinder leaking
314797	18-Aug-15	Replace a/c compressor drive motor leaking oil
314819	18-Aug-15	New cylinder fitted service day cracked and leaking
314890	20-Aug-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
314594	21-Aug-15	rear hose bracket on rail broken
314595	21-Aug-15	feed cylinder leaking
315192	21-Aug-15	replace blown hose
315243	23-Aug-15	replace pito jaws
315395	24-Aug-15	replace flushing head seals.
314939	25-Aug-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
315562	25-Aug-15	blown hose - regas accumulator
315750	26-Aug-15	blown hose in boom boom x 3
315634	27-Aug-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
313423	31-Aug-15	Replace feed ropes replace pito jaws
315681	1-Sep-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
316325	3-Sep-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
317146	7-Sep-15	loose strapping bolts and replace nuts
316373	8-Sep-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
316507	8-Sep-15	On LH04 replace the perished anaconda with 241.1 cable from
317205	8-Sep-15	change out pito assembly next service day - see hobs or
317416	9-Sep-15	replace hp accumulator.
317300	10-Sep-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
317472	10-Sep-15	tightened RHS joystick
317520	11-Sep-15	Broken fitting on boom control box
313183	15-Sep-15	replace bearings in operator seat pivot arm.
317348	15-Sep-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
317349	15-Sep-15	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
318091	16-Sep-15	top up hyd oil and check for leaks . OK
318011	17-Sep-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
318212	18-Sep-15	P4320 SFW Reset gui by turning power on and off to A-Cabinet
318214	18-Sep-15	blown hose and top up hyd oil
318244	19-Sep-15	blown hose and orings in box on boom
318051	22-Sep-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
318521	22-Sep-15	change broken shank

318597	24-Sep-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
318794	26-Sep-15	daily and inspect damage to motor cover
318801	26-Sep-15	blown hyd hose
318807	26-Sep-15	replace feed rope
317187	29-Sep-15	front wiper arm on order - replace when here
318638	29-Sep-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
319049	29-Sep-15	Pressure washer hose not long enough. Pirtek to make new
319133	1-Oct-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
319358	3-Oct-15	check oil leak on drifter, lube coming from tell tale holes
319380	4-Oct-15	replace highside accumulator & blown hose
319399	4-Oct-15	grease pump fault. by-pass air regulator.
319182	6-Oct-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
319724	6-Oct-15	repairs service day
319817	8-Oct-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
319869	13-Oct-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
319932	13-Oct-15	Replace front window gas struts
320425	13-Oct-15	Replace two door latches
320448	13-Oct-15	air leak . Tap and fitting under step U/S
320641	14-Oct-15	blown carrier hose
320513	15-Oct-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
320679	15-Oct-15	replace lube hose
320718	16-Oct-15	replace hose & feed cyl fitting
320554	20-Oct-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
320555	20-Oct-15	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
321128	22-Oct-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
321341	24-Oct-15	rehose CAN cable
321168	27-Oct-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
322190	28-Oct-15	Check all jack leg operation . All working correctly.
322048	29-Oct-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
322270	30-Oct-15	feed rope changed
321383	3-Nov-15	Replace front window hard to see through
322090	3-Nov-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
322977	4-Nov-15	C4350 SHW LH04 reset clino
323058	5-Nov-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
323206	5-Nov-15	blown hose
323311	7-Nov-15	blown hose
321180	10-Nov-15	replace engine oil temp/pressure sensor
323105	10-Nov-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
323441	10-Nov-15	Fit new selector switch to GUI isolator on PLC box
323544	12-Nov-15	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
323545	12-Nov-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
323625	17-Nov-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
323626	17-Nov-15	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
323985	17-Nov-15	jack leg out rigger wont come out
324030	18-Nov-15	Front right hand side Jack leg would not slide out sideways,
324064	19-Nov-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
324195	19-Nov-15	dropping rods and daily
324209	19-Nov-15	re heli coil short arm mounting bolts

324212	19-Nov-15	Replace angle sensor as the old one had ceased up this will
324295	22-Nov-15	blown hose
324116	24-Nov-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
324535	24-Nov-15	repairs to long arms , general repairs
324828	26-Nov-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
324987	26-Nov-15	blown hose.
325019	27-Nov-15	replace 2 x blown hoses
325027	27-Nov-15	bottom stinger not extending
324878	1-Dec-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
325372	3-Dec-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
325777	4-Dec-15	Blown hyd hose
325419	8-Dec-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
325912	8-Dec-15	replace door latch
326008	10-Dec-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
326135	10-Dec-15	LH out rigger jammed and won't move . Believed to have been
326171	10-Dec-15	replace gripper arm jaws.
326235	11-Dec-15	adjust feed ropes
326302	13-Dec-15	blown hose under floor and check rod alignment
326431	14-Dec-15	refit feed rope. blown hose.
325902	15-Dec-15	Change rod handler over center valve
326058	15-Dec-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
326059	15-Dec-15	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
326517	15-Dec-15	depth counter not counting right- air comp tripping out -
326566	16-Dec-15	re-stamp serial number on drifter so47251.
326670	16-Dec-15	Tong compressor as its tripping on O/L Full Load Amps 5.7 is
326691	16-Dec-15	calibrate linear sensor.
326607	17-Dec-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
325252	22-Dec-15	replace overcentre valve and fit new door latch and struts
326648	22-Dec-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
327126	22-Dec-15	general repairs and pito cylinder
327139	22-Dec-15	blown hose
327143	22-Dec-15	no throttle
327233	24-Dec-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
327368	26-Dec-15	a/c fault and water hose leaking
327275	29-Dec-15	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
328109	31-Dec-15	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
328582	1-Jan-16	A/C . U/S . Blowing hot . Check basics under ground .
328599	2-Jan-16	repair air con wiring fault
328615	3-Jan-16	Replace strapping bolt & air con
328639	3-Jan-16	loose strapping bolts
328164	5-Jan-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
328839	5-Jan-16	front wiper U/S
328932	7-Jan-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
329071	7-Jan-16	auto drill fault
329152	9-Jan-16	oil leak on hyd motor on a/c
329302	11-Jan-16	oil leak hose. percussion fault, recharge accumulator.
328981	12-Jan-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
329598	13-Jan-16	RHS Joystick U/S broken.

329621	13-Jan-16	adjust gripper arms.
329640	13-Jan-16	replace blown hose
329517	14-Jan-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
329642	14-Jan-16	C4350 SHW Jumbo box isolator handle not engaging.
329693	14-Jan-16	refit feed rope
329565	19-Jan-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
329566	19-Jan-16	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
330105	21-Jan-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
330347	22-Jan-16	refit feed rope, replace drifter strapping bolt. replace
330378	23-Jan-16	replace grease gun and hose on gripper jaws.
330401	24-Jan-16	fit long arm frame and pin
330592	25-Jan-16	LH 04 had smoke coming out of canopy light.
330153	26-Jan-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
330644	26-Jan-16	water in fuel lines and tank - drain and bleed to get going
330743	28-Jan-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
330855	28-Jan-16	Out riggers not going out
330880	28-Jan-16	blown hose
331455	30-Jan-16	Blown carrier hose
331460	30-Jan-16	grease pump not working
331574	1-Feb-16	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
330787	2-Feb-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
331565	2-Feb-16	LH04 GUI panel fault
331650	2-Feb-16	Calibrate angle sensor
331644	3-Feb-16	recalibrate angle sensors and check A/C . Wash out condensor
331839	3-Feb-16	Tilt cylinder and linier sensor not working
331861	3-Feb-16	re-calibrated LH04 at the P4340.
331726	4-Feb-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
332092	6-Feb-16	blown jack leg hose
331768	9-Feb-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
332383	9-Feb-16	P4380 NFW Rig lost power, cleaned pilot circuit contacts (pl
332394	9-Feb-16	no drilling on auto
332405	9-Feb-16	replace pressure washer reel seized.
332420	9-Feb-16	repair components. hyd fill pumps and gripper cylinders.
332424	9-Feb-16	adjust rod alignment
332608	10-Feb-16	adjust rod alignment
332500	11-Feb-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
331797	12-Feb-16	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
332826	15-Feb-16	Low engine power
332551	16-Feb-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
332552	16-Feb-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
332852	16-Feb-16	low engine power . engine missing
333035	17-Feb-16	fuel leak loose fitting
332954	18-Feb-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
333078	18-Feb-16	replace gripper arm cylinder.
333080	18-Feb-16	replace and tighten strapping bolts.
333171	20-Feb-16	repair hyd oil leak.
333181	20-Feb-16	replace strapping bolts
333199	21-Feb-16	replace shank, snapped. replace strapping bolt.

332998	23-Feb-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
333649	24-Feb-16	E4310 LH04 lost pilot found trailing cable to be at fault
333861	24-Feb-16	blown hose oil leak
333738	25-Feb-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
333903	25-Feb-16	blown hose
334096	26-Feb-16	blown hose
334098	26-Feb-16	feed and return rope came off pullys
334136	28-Feb-16	Hydraulic oil leak
333781	1-Mar-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
334306	1-Mar-16	leaking flushing head seals. incorrectly fitted
334391	3-Mar-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
334512	3-Mar-16	LH04 rod counter fault
334559	3-Mar-16	LH04 was reported to not be counting the rods or the depth.
334749	5-Mar-16	rod changer bracket broken replaced with new one
334771	6-Mar-16	replace air/water flushing.
334435	8-Mar-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
334910	8-Mar-16	Power pack dropping out without any fault lights on QN panel
334905	9-Mar-16	pressure washer valve cracked - oil leak
335101	9-Mar-16	adjust grippers arm not grabbing rods on auto drill
334995	10-Mar-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
335045	12-Mar-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
335378	13-Mar-16	rebuild worn carosell .
335388	13-Mar-16	blown hose
335411	14-Mar-16	daily and check A/C . A/C U/S
335044	15-Mar-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
335700	17-Mar-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
335959	18-Mar-16	check water fault
335969	18-Mar-16	change out a/c hydraulic motor.
335987	19-Mar-16	replace wiper blade
336000	19-Mar-16	refit pito jaws.
336014	20-Mar-16	book out tilt cyl nil stock
336017	20-Mar-16	Power Pack wouldn't start. Lose plug in QN Panell.
336031	20-Mar-16	check feed fault
335750	22-Mar-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
336201	23-Mar-16	replace rhs front jack leg
336227	24-Mar-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
336373	24-Mar-16	Change tilt cylinder relief valve
336275	29-Mar-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
336838	29-Mar-16	Rig coming up with shank lube error. no boom
337022	30-Mar-16	Rock lub fault
336357	31-Mar-16	tilt cylinder creeping
336908	31-Mar-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
337105	31-Mar-16	blown hose.
337163	2-Apr-16	refurbish spare parts cylinders hose reels etc.
337355	4-Apr-16	slipped in drain - check for damage
336963	5-Apr-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
337613	6-Apr-16	blown hose in boom loom
337483	7-Apr-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197

338208	8-Apr-16	Jack leg oil leak
337534	12-Apr-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
338665	13-Apr-16	Top stinger cylinder let go
338673	13-Apr-16	no fast feed on LHS joystick, replaced joystick with a
338573	14-Apr-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
338802	15-Apr-16	pito jaws not opening, din plug u/s.
338815	16-Apr-16	rod alignment
338618	19-Apr-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
338619	19-Apr-16	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
339226	21-Apr-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
339612	23-Apr-16	repair oil leak
337092	26-Apr-16	replace exhaust piping.
339268	26-Apr-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
339307	26-Apr-16	Change out front axle. Making oil in the diff.
339756	26-Apr-16	replace LF1500 valve
339874	28-Apr-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
339997	28-Apr-16	blown hose
340646	30-Apr-16	blown hose on boom
340653	30-Apr-16	LH04 was coming up intermittantly with "sensor comms error".
340725	2-May-16	Was having issues with penetration rate and hole depth count
336048	3-May-16	Order parts for air-con
339920	3-May-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
341014	4-May-16	rock lube fault, din plug dirty. retension pos 2 wheel.
340861	5-May-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
341253	6-May-16	daily , wiper blade and blown hose
341287	7-May-16	replace boot wash hose
340905	10-May-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
341676	11-May-16	Reported that the depth counter not working. Operator said
340931	12-May-16	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
341532	12-May-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
341740	13-May-16	Phx4350 SHW called to rig it has no hole depth reading &
339288	14-May-16	Replace DPW & DI08 modules Adrian O'Rourke
341807	14-May-16	CHECK FUEL TANK BREATHER
341888	16-May-16	Holes in hose reel
341977	16-May-16	recalibrate sensor and check drilling faults
341583	17-May-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
341584	17-May-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
342034	17-May-16	remove broken shank
342144	19-May-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
342323	20-May-16	Replace flushing head seals
342186	21-May-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
342390	22-May-16	Fit air mist valve repair water flushing
342428	23-May-16	Ajust lf1500 valve
342994	24-May-16	Blown hose carier
343111	26-May-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
343282	26-May-16	refit pito jaws.
343350	27-May-16	refit feed rope. replace bolts in gripper jaws.
343139	28-May-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

343384	28-May-16	air cond fault - hole in condensor - needs replacing ordered
343401	29-May-16	a/c fault. thermostat u/s.
342440	30-May-16	replace seat runners
343579	30-May-16	replace intake pipe.
343602	30-May-16	a/c fault, replace thermostat and relay for condensor fans.
343154	31-May-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
343736	31-May-16	locate thermostat probe into evaporator.
343864	2-Jun-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
344006	2-Jun-16	feed ropes
344021	2-Jun-16	Replace low side accumulator
344023	2-Jun-16	Replace flushing head seals
344053	3-Jun-16	daily and repairs to long arm pin retainers
343895	4-Jun-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
344292	6-Jun-16	replace water hose
344475	9-Jun-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
344627	9-Jun-16	Replace strapping bolts
344503	11-Jun-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
344674	11-Jun-16	replace main water hose fitting
344694	11-Jun-16	repairs to boom on service day - welding and replace diff
344710	11-Jun-16	Blown Pec hose
345045	14-Jun-16	oil leak blown -6 hose.
345230	15-Jun-16	repair front wiper
345134	16-Jun-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
345266	16-Jun-16	Hydraulic temp high
345275	16-Jun-16	Replace water flushing valve
345297	17-Jun-16	blown carrier hose
345162	18-Jun-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
345163	18-Jun-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
345381	18-Jun-16	no Air/Mist, checked all electrical and it was working as
345375	19-Jun-16	repairs to air mist . kit water valve
345666	21-Jun-16	P4240 drifter doesn't go up when you need to drill. You
345848	22-Jun-16	P4340, loose joystick. Missing screws. Replaced all good.
345749	23-Jun-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
345917	24-Jun-16	P4240 LH 04 Gui Panel would not register FEED,PRECUSSON &
345945	24-Jun-16	tighten pito jaws.
341889	25-Jun-16	replace middle tube on rod handler
345780	25-Jun-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
345981	25-Jun-16	replace feed rail cracking on slides.
346024	26-Jun-16	front stinger not working
346272	27-Jun-16	replace top stinger coil and din plug. a/c fault. calibrate
346640	29-Jun-16	blown hose.
346660	29-Jun-16	refit feed rope
346524	30-Jun-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
346695	30-Jun-16	rod alignment and daily
346711	30-Jun-16	No rotation on carousel
346870	1-Jul-16	blown hose
346558	2-Jul-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
346905	2-Jul-16	blown hose

347127	7-Jul-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
347412	8-Jul-16	r/h door latch u/s - DONE ON 349524
347626	8-Jul-16	replace broken shank
347155	9-Jul-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
347645	9-Jul-16	blown hose.
347658	9-Jul-16	joystick fell apart grub screw came out
347742	11-Jul-16	out riggers stuck wont come out
345638	12-Jul-16	Replace cab fan
347757	12-Jul-16	blown hose.
347823	12-Jul-16	hyd over temp fault
347934	14-Jul-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
348371	15-Jul-16	replace missing bolts in rear of drifter
345395	16-Jul-16	water reel needs replacing rusted out
347963	16-Jul-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
347964	16-Jul-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
347992	16-Jul-16	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
348637	20-Jul-16	hose not rolling up . Door not shut properly !
348747	21-Jul-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
349101	21-Jul-16	blown hose
348774	23-Jul-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
349972	27-Jul-16	feed rope came off
349862	28-Jul-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
350010	28-Jul-16	replace feed ropes
349889	30-Jul-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
350059	30-Jul-16	blown hoses x 2
350080	30-Jul-16	replace low side accumulator
350172	30-Jul-16	Repair ropes
350119	31-Jul-16	Rod gripper pin
349902	1-Aug-16	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
350202	1-Aug-16	rope came off
350321	3-Aug-16	general repairs service day
350373	4-Aug-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
350400	6-Aug-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
350616	7-Aug-16	rotation fault - change danfoss valve and jack leg stuck
350685	8-Aug-16	water fault - check boost pump and change coil under step
350701	9-Aug-16	Phx4310 LH04 had water and air mist fault
350893	9-Aug-16	start fault, nothing found.
350994	11-Aug-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
351207	11-Aug-16	jump start
351213	11-Aug-16	Got called to the battery going flat / trickle charger not
351044	12-Aug-16	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
351261	12-Aug-16	no water flushing
351086	13-Aug-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
351322	14-Aug-16	replace blown hose
351330	15-Aug-16	Rod gripper U/S. Pin fell out , frame bent.
351643	16-Aug-16	grease pump not working and find oil leak
351779	18-Aug-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
352197	19-Aug-16	replace pito jaw assy, pins and bushes worn out.

352198	19-Aug-16	replace operators seat.
349524	20-Aug-16	replace door latches.
351809	20-Aug-16	WEEKLY SERVICE - OPENED IN ERROR. CLOSED DUE TO TRANSACTIONS
351810	20-Aug-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
352225	20-Aug-16	Trialing cable plugged had some moisture in it.
352267	21-Aug-16	pito alignment.
352399	23-Aug-16	hyd filler pump no power.
352407	23-Aug-16	E4280 ACC loose din plug on gripper jaws. Re-tighten and O/K
352628	24-Aug-16	oil leak at feed cyl parked at u/g bay EOS
352493	25-Aug-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
352525	27-Aug-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
352762	28-Aug-16	general repairs service day
352844	29-Aug-16	feed rope
353213	31-Aug-16	Replace feed rope
353126	1-Sep-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
353157	3-Sep-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
353366	5-Sep-16	air mist fault.
353627	6-Sep-16	replace feed rope.
353758	8-Sep-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
353786	10-Sep-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
354050	10-Sep-16	Blown hose.
354015	11-Sep-16	Not starting bad earth to frame
354335	12-Sep-16	replace blown hose
354357	12-Sep-16	called to rig as he had to use his bypass button to load]
354495	13-Sep-16	Change getting water in the air
354511	13-Sep-16	fit reconditioned flushing head gettig water in air
354525	13-Sep-16	broken shank
354629	15-Sep-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
354792	16-Sep-16	blown hose.
354654	17-Sep-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
354655	17-Sep-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
354866	18-Sep-16	feed rope u/s.
354875	18-Sep-16	blown hose on pito cylinder
355344	21-Sep-16	steel plate behind elephant ear obstructing gripper arms.
355380	21-Sep-16	replace blown hose
355243	22-Sep-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
355702	22-Sep-16	general repairs
355746	23-Sep-16	daily , check liar sensor and adjust ropes
355751	23-Sep-16	Was told at the start of shift that the rig needed a fitter
355759	23-Sep-16	change work light
355776	24-Sep-16	Feed rope pully wheel bearing faild
355788	24-Sep-16	faulty angle sensor. keeps going out of calibration.
355288	27-Sep-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
355896	27-Sep-16	flushing seals
355928	27-Sep-16	general repairs service day
356038	29-Sep-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
356400	1-Oct-16	repair rear rail sprays. hose blocked.
356413	2-Oct-16	replace blown drifter lube hose

356078	4-Oct-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
356899	5-Oct-16	pressure washer reel need replacing
356934	5-Oct-16	top up oil and check for hyd leak. front stinger cylinder
356837	6-Oct-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
357044	7-Oct-16	repairs to rod grippers and accumulators
357067	9-Oct-16	Blown hose hyd
357074	10-Oct-16	oil leaks . broken fittings .
357103	10-Oct-16	fix auto drill adjust ropes back off slides
356886	11-Oct-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
357496	13-Oct-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
357620	13-Oct-16	free up tight stinger
357677	13-Oct-16	check front stinger
357709	14-Oct-16	wash out front stinger tube.
357762	16-Oct-16	blown hose.
357773	16-Oct-16	replace 2 x blown hoses
358094	17-Oct-16	replace water tap, for rail sprays.
357533	18-Oct-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
357534	18-Oct-16	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
358766	19-Oct-16	re-furbish rotatable a/c unit.
358713	20-Oct-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
359232	21-Oct-16	daily , broken fittings . bolts missing out of drifter
359282	23-Oct-16	2 x blown hoses and daily
359295	23-Oct-16	check strapping bolts on daily
359338	24-Oct-16	Blown hose
358752	25-Oct-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
359475	25-Oct-16	repair to boom on service -= parts booked out
359380	27-Oct-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
359664	27-Oct-16	check e-stops working - shuts down engine as per check sheet
359679	27-Oct-16	repair oil leak & tighten strapping bolts
359705	28-Oct-16	rig not measuring right & no auto drill
359719	28-Oct-16	adjust rod alignment
359792	31-Oct-16	replace drifter strapping bolts.
359839	31-Oct-16	replace blown hose
359417	1-Nov-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
360035	3-Nov-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
360197	4-Nov-16	blown hose
360254	5-Nov-16	blown hoses and broken fittings
360256	5-Nov-16	Lh04 couldnt get pilot at E4240, cleaned plug and B2B
360278	6-Nov-16	bad oil leaks
360279	6-Nov-16	blown hose
360299	6-Nov-16	blown carrier hose
360075	8-Nov-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
360564	8-Nov-16	REPLACE FLOW SWITCH FLUSHING
360781	9-Nov-16	replace air filter housing
360789	9-Nov-16	Replace tilt cylinder check valve
360683	10-Nov-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
360821	10-Nov-16	front wiper blade u/s
360893	11-Nov-16	Replace DPW & DI08 modules Adrian O'Rourke

360729	12-Nov-16	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
360949	12-Nov-16	pos 1 puncture.
361019	14-Nov-16	replace rollover.
360770	15-Nov-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
360771	15-Nov-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
361225	15-Nov-16	Gripper cover missing.
361379	15-Nov-16	replace pos 4 wheel & replace wiper blade
361471	17-Nov-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
361628	18-Nov-16	replace tilt cylinder valve
361677	19-Nov-16	Hydraulic leak at drifter
361686	20-Nov-16	sensor com error
361709	20-Nov-16	replace blown grease hose
361716	20-Nov-16	replace grease pump
361729	21-Nov-16	blown water hose on reel
361785	21-Nov-16	Ph4200 sord, err tilt and err rot coming up on gui. also
361506	22-Nov-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
361980	24-Nov-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
362126	24-Nov-16	replace bolts in drifter plate
362196	26-Nov-16	shaft broken on long arm
362251	26-Nov-16	Broken bolts in rear of drifter.
362244	28-Nov-16	rh jack leg extension jammed. water flushing valve stuck on,
362279	28-Nov-16	air/water valve faulty - change service day
362014	29-Nov-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
362067	29-Nov-16	Replace clear rubber flap on A cabinet, and have boiler
362718	1-Dec-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
362848	1-Dec-16	blown hose
362934	4-Dec-16	gripper jaws pin cam out replaced with new pin
362754	6-Dec-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
363675	6-Dec-16	Workorder to capture strip & Quote costs for Water Reel
363728	7-Dec-16	P4240 SFW LH04 Trailing cable split in half.
363813	8-Dec-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
364074	8-Dec-16	Recalibrate flow sensors and reset.
364086	8-Dec-16	E4240 RECALIBRATE LINEAR SENSOR
364121	8-Dec-16	Called to some electrical issues with LH-04 @ the E-4240.
364190	10-Dec-16	repair /weld sensor bracket on long arm
364205	11-Dec-16	boost pump bleed fitting u/s remove and plug.
364216	11-Dec-16	sensor wiring fault
363615	12-Dec-16	Work order to order spare Elephant ears for front of rig
364222	12-Dec-16	E4240 - Pito jaws not responding.
364259	12-Dec-16	blown hose.
358771	13-Dec-16	replace fan belt tensioner.
363847	13-Dec-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
364512	14-Dec-16	water leak
364333	15-Dec-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
364520	15-Dec-16	P4240 Pitto Jaws would not work
364554	15-Dec-16	GUI panell was giving "!" symbol, in PLC cabinet found one
364673	18-Dec-16	P4220 X-cut, rig was shutting down on no lube. When I got
364368	20-Dec-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

364369	20-Dec-16	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
364913	20-Dec-16	Cancelled during entry
364924	20-Dec-16	Pito jaw solenoid control valve
365118	21-Dec-16	Repair hosing to jack leg
365141	21-Dec-16	replace S41 sensor cable
365002	22-Dec-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
365474	23-Dec-16	LH04 Rod handler not working.
365523	26-Dec-16	adjust sensor on long arms
365539	26-Dec-16	rh front jack leg extension jammed.
365038	27-Dec-16	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
365639	27-Dec-16	replace feed rope and adjust sensor bracket
365642	27-Dec-16	repair service day
365587	29-Dec-16	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
365971	31-Dec-16	blown hose
365999	1-Jan-17	repairs to pito jaws
366035	1-Jan-17	water fitting
366050	2-Jan-17	replace bent shank
366052	2-Jan-17	Replace wiper blad
365620	3-Jan-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
366261	4-Jan-17	GUI displaying <<<< >>>> see history notes.
366359	5-Jan-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
366461	5-Jan-17	this w/o is to capture the parts used on W/O 366254
366665	7-Jan-17	sensor fault on short arms.
366683	7-Jan-17	blown hose under carrier
366717	8-Jan-17	start fault keep shutting down - check engine oil - top up
366749	9-Jan-17	r/h/f jack leg wont extend out
366400	10-Jan-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
366941	10-Jan-17	Checked out linear sensor and found to be not working. Will
366948	10-Jan-17	replace gripper arm pin and plate
366949	10-Jan-17	gripper arm jaws replaced
366952	10-Jan-17	replace pin and plate in gripper arm
367153	11-Jan-17	replace linear sensor, sparkies.
367167	11-Jan-17	replace boom zoom plate and gripper jaws
367060	12-Jan-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
367227	12-Jan-17	Right hand side out riger stuck
367253	13-Jan-17	water hose , air fault and daily
367317	15-Jan-17	Replace o-rings on control valve
367538	16-Jan-17	water hose on reel has a hole , daily , blown hose
367100	17-Jan-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
367101	17-Jan-17	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
367576	17-Jan-17	repairs to main water inlet hose
367844	17-Jan-17	repairs to rod gripper arms and general repairs
367869	18-Jan-17	sensor com error. Long hole had no boom movement start of
367927	19-Jan-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
368100	20-Jan-17	nut on long arm came loose
368159	22-Jan-17	jack leg stuck out
367961	24-Jan-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
368362	25-Jan-17	blown hose.

368533	25-Jan-17	change front diff oil as per bad sample
368467	26-Jan-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
368722	29-Jan-17	Pito jaw movement
368497	31-Jan-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
369301	1-Feb-17	Checked Lineal sensor, sensor is u/s Checked cable is ok,
369198	2-Feb-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
369199	2-Feb-17	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
369413	3-Feb-17	System 130 fault (Can Cable) Checked resistance of cable all
369433	4-Feb-17	1W Electrical service.
369474	5-Feb-17	lube fault, replace slu control unit.
369728	6-Feb-17	blown hose x 2.
369240	7-Feb-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
369747	7-Feb-17	Data display error for B6 sensor
369969	8-Feb-17	LH 04 Stopping intermittently with a SYSTEM COMMS ERROR 130.
370136	8-Feb-17	feed rope jumped off refit and adjust
370029	9-Feb-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
370275	11-Feb-17	daily , grease pump and shank lube fault
370310	12-Feb-17	repairs to ropes and daily
370324	12-Feb-17	replace stapping bolts
370345	13-Feb-17	top stinger needs repairs
370354	13-Feb-17	feed rope
370397	13-Feb-17	Blown hoses
370071	14-Feb-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
370402	14-Feb-17	P4200 System error 130 lost all functions. Checked over rig
370433	14-Feb-17	blown hose under step. general repairs service day
370675	15-Feb-17	Called to Longhole as it was having issues with Comms
370556	16-Feb-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
370846	17-Feb-17	tighten stinger, check water pump leaking , replace blown
370853	17-Feb-17	replace top seal on water booster pump
370610	20-Feb-17	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
370639	21-Feb-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
370640	21-Feb-17	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
371252	23-Feb-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
371406	23-Feb-17	Replace window wiper
371421	24-Feb-17	repairs to water hose bracket
371450	24-Feb-17	check auto drill
371281	25-Feb-17	BATTERY ISOLATOR CHANGE OUT
371523	26-Feb-17	Top up hyd oil and get hyd pump working
371526	26-Feb-17	Top up hyd oil and get hyd pump working
371682	27-Feb-17	Flat tyre po'4
371290	28-Feb-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
371945	1-Mar-17	blown hose , repairs to stinger and wiper
372032	2-Mar-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
371433	3-Mar-17	air seat not working
372458	5-Mar-17	replace strapping bolt - retension
372466	6-Mar-17	Air con vents in cab need replacing
372499	6-Mar-17	replace strapping bolts drifter.
372071	7-Mar-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

372879	7-Mar-17	replace front wiper blade
373062	8-Mar-17	oil leak on rod handler directional valve. replace o-rings.
372984	9-Mar-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
373021	14-Mar-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
373439	14-Mar-17	general repairs service day
373566	16-Mar-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
373801	18-Mar-17	Check out why E/L tripping at JBS. Found problem in JBS 15
373808	18-Mar-17	replace broken bolts in drifter slides.
373860	20-Mar-17	boom repairs and to rotatable drill parts
373603	21-Mar-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
373604	21-Mar-17	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
373976	21-Mar-17	air flush valve fault
374202	23-Mar-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
374341	23-Mar-17	Replace water hose
374386	25-Mar-17	repair oil leak
374233	26-Mar-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
374465	27-Mar-17	Cab Repairs - B17UG08A
374466	27-Mar-17	Rehose Carrier - B17UG08A
374606	28-Mar-17	Called to Rig as operator lost rotation, see history notes
374740	30-Mar-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
375035	30-Mar-17	park brake fault - replace coil
375083	1-Apr-17	Replace pito jaws.
375094	1-Apr-17	park brake stuck on
375102	2-Apr-17	Park brake would not release @ P4220 SFW
374780	4-Apr-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
375567	5-Apr-17	Blown hose
375439	6-Apr-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
375896	7-Apr-17	daily , replace missing bolts in drifter and feed ropes
375914	7-Apr-17	check acumulaters for pressure
375944	8-Apr-17	pito bushes sloppy
375487	11-Apr-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
376134	11-Apr-17	change out worn pito jaw assy
376159	11-Apr-17	blown hose
376160	11-Apr-17	blown rotation hose
376330	12-Apr-17	blown hose and daily
376246	13-Apr-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
376372	13-Apr-17	check oil leak
376388	13-Apr-17	replace oil filler pump
374464	17-Apr-17	Boom repairs - B17UG08A
376283	18-Apr-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
376284	18-Apr-17	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
377115	18-Apr-17	repairs service day
377412	19-Apr-17	System 130 fault (can cable fault)
377307	20-Apr-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
377375	20-Apr-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
377830	21-Apr-17	Check and gas accumilators
377851	22-Apr-17	weld up boss to long arms to carasell
377894	22-Apr-17	blown hose

373693	24-Apr-17	Change air con unit.
374461	24-Apr-17	Feed rail upper wear strip to be replaced
374692	24-Apr-17	make up new battery box lid
377341	25-Apr-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
378294	27-Apr-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
378557	30-Apr-17	Resample POS 1 and 2
378337	2-May-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
379033	4-May-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
379070	9-May-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
379515	11-May-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
379551	16-May-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
379552	16-May-17	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
379840	16-May-17	replace led map light and dome light in cabin.
379609	18-May-17	change out hyd cooler - part orderd 11/5/17
380127	18-May-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
379667	19-May-17	Workorder to capture new tyres & wheels fitted during
380174	20-May-17	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
380210	22-May-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
381075	24-May-17	oil pump not transferring from aux tank to main
380991	25-May-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
381117	25-May-17	Checked the linear sensor on LH 04 and its U/S
381182	26-May-17	Replaced the Lineal sensor Underground because of
381197	26-May-17	front outrigger fitting replaced
381238	27-May-17	radio aerial fitting replaced
381244	27-May-17	strapping bolts loose - retension
381246	28-May-17	No comms, Replaced U/S antenna lead
381252	28-May-17	tension drifter strapping bolts.
381299	29-May-17	Window washers not working
381022	30-May-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
381831	31-May-17	tension strapping bolts
381708	1-Jun-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
381992	3-Jun-17	repair wiper washers
382184	5-Jun-17	R4 box bracket bent up - hitting drifter.
381751	6-Jun-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
382362	6-Jun-17	threads pulled out of rod gripper jaws
381076	8-Jun-17	Repair taps on oil transfer pump service day
382465	8-Jun-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
382620	8-Jun-17	retension strapping bolts
382625	8-Jun-17	retension strapping bolts.
382640	8-Jun-17	Relaced faulty wiring harness on LHS drilling lights.ONE
382643	9-Jun-17	retension strapping bolts
382773	9-Jun-17	Replaced the RHS drilling joystick because not latching.
382725	10-Jun-17	auto drill fault - adjust restrictor on pito jaws
382781	11-Jun-17	auto drill fault - adjust rod sensor
382782	11-Jun-17	retension strapping bolts
382799	11-Jun-17	blown hose.
382810	12-Jun-17	check operation of pressure washer runs for 10mins and cuts
382509	13-Jun-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL

383193	15-Jun-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
383233	20-Jun-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
384085	22-Jun-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
384260	23-Jun-17	broken hp accumulator bolts.
384304	24-Jun-17	bleed drifter lube system - check air mist
384329	25-Jun-17	air mist valve fault, full of rocks, clean out.
384357	26-Jun-17	P4180 Comms Radio not working
384636	26-Jun-17	blown hose gripper arm.
383234	27-Jun-17	MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
384118	27-Jun-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
384702	27-Jun-17	repair u/g radio and stereo wiring.
384711	27-Jun-17	fix broken operator seat locking pin pedal
384779	28-Jun-17	water hose reel hard to move.
384948	28-Jun-17	no percussion - coil u/s
384834	29-Jun-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
385061	30-Jun-17	replace tilt cylinder check valve
385062	30-Jun-17	replace tilt cylinder check valve
385086	1-Jul-17	refit feed rope
384870	4-Jul-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
385590	4-Jul-17	Repair/replace exhaust
385726	6-Jul-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
386237	9-Jul-17	Systes 130 drilling fault
386267	10-Jul-17	replace blown hose
385765	11-Jul-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
386562	12-Jul-17	tighten strapping bolts
386563	12-Jul-17	pressure washer reel u/s check service day
386564	12-Jul-17	check return ropes service day
386338	13-Jul-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
386382	18-Jul-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
386383	18-Jul-17	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
386542	18-Jul-17	WEEKLY SERVICE OF TAMROCK LONGHOLE DRILL
387641	20-Jul-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
387853	21-Jul-17	Replace feed rope
387950	23-Jul-17	Return rope. Rear drifter bolts
387667	25-Jul-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
388450	25-Jul-17	drivers door needs anchor pin on cab replaced/repared next
388558	27-Jul-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
388841	30-Jul-17	drifter missing bolts and daily service
388868	30-Jul-17	hp accumulator bolts broken replace bolts and orings
388872	30-Jul-17	blown percussion hose
389001	31-Jul-17	smashed windscreen from rocks from the backs
389349	3-Aug-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
389730	7-Aug-17	boost leak.
389386	8-Aug-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
389387	8-Aug-17	FOUR WEEKLY COMPRESSOR SERVICE ON SANDVIK DRILLS
389419	8-Aug-17	inspect rear diff as per attached sos report
389911	10-Aug-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
390210	13-Aug-17	replace oring at jack leg switch

390211	13-Aug-17	replace -6 hose
390254	14-Aug-17	drifter feed cylinder leaking
390563	16-Aug-17	tighten loose feed ropes
390662	17-Aug-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
391029	19-Aug-17	replace flushing head seals.
391051	19-Aug-17	top up hyd oil - blown hose
390710	20-Aug-17	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
391113	21-Aug-17	P4220 SFW LH04 reported pilot dropping out, found dirty B2B,
391298	21-Aug-17	rod counter proxi switch loose, tighten.
389381	22-Aug-17	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
390741	22-Aug-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
391383	22-Aug-17	wont tram in second gear change fuel filters. check boost.
391421	22-Aug-17	replace front wiper blade
391507	24-Aug-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
391650	24-Aug-17	P4220 LH 04 stopped with a "SYSTEM 130" error.
391697	24-Aug-17	replace strapping bolts
391767	26-Aug-17	check oil leak . feed cylinder leaking , needs replacing
391792	26-Aug-17	high side accluator bolts pooped off
391786	27-Aug-17	high side acculator came off
392209	29-Aug-17	loose strapping bolts and nuts missing
392237	29-Aug-17	replace a fitting on the gripper arms
392431	30-Aug-17	Strapping nuts keep coming loose , may need new
392443	30-Aug-17	drilling slow , check accumulators , change shank
392355	31-Aug-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
392480	31-Aug-17	Zoom tube needs tensioning
392481	31-Aug-17	Rail cradle needs tensioning
392690	4-Sep-17	top up hyd oil
391849	5-Sep-17	Stinger cylinder leaking.
392390	5-Sep-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
392391	5-Sep-17	FOUR WEEKLY COMPRESSOR SERVICE ON SANDVIK DRILLS
393043	6-Sep-17	lh front jacking leg has slight leak - Monitor
393326	6-Sep-17	Linear sensor fault may be BUP Modulal
393179	7-Sep-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
393752	9-Sep-17	oil leak
393822	10-Sep-17	damaged jack leg fittings and lost all the oil
393867	11-Sep-17	ajust feed cradle as requested
394185	13-Sep-17	blown grease line
394270	14-Sep-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
394408	14-Sep-17	asked by dayshift to replace a work lighrt on lh04
394473	14-Sep-17	blown hose
394542	16-Sep-17	front wiper not working.
394561	16-Sep-17	top up hyd oil
394637	18-Sep-17	Auto-drill U/S
394638	18-Sep-17	Rail sprays U/S
394639	18-Sep-17	Derates when tramming
394298	19-Sep-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
395127	20-Sep-17	spare magnet for feed cylinder.
395141	20-Sep-17	check auto drill - adjust feed ropes

395012	21-Sep-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
395273	22-Sep-17	feed cylinder leaking / change out
395279	22-Sep-17	lh04 stopped on decline at ph 4340
395335	23-Sep-17	check iner and outer zoom out of ajustment to be fixed on
395347	24-Sep-17	Check why rod counting and linear sensor not working.
395358	24-Sep-17	replace linear sensor
395526	25-Sep-17	replace linear sensor housing next service day
395535	25-Sep-17	repair flushing valve
395716	26-Sep-17	repair oil leak on boom
395732	26-Sep-17	blown hose
395734	26-Sep-17	regas accululators
395735	26-Sep-17	start fault cranking but no start
395917	27-Sep-17	adjust rod alignment
395935	27-Sep-17	replace pito hoses and fittings
395836	28-Sep-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
396129	29-Sep-17	hyd oil leak.
396234	1-Oct-17	Lost its drilling lights @ the E4240 SFW.
396344	2-Oct-17	top up engine oil
395872	3-Oct-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
395873	3-Oct-17	FOUR WEEKLY COMPRESSOR SERVICE ON SANDVIK DRILLS
396372	3-Oct-17	replace fan hub.
396577	4-Oct-17	pos 1 jack leg leaking, change out.
396580	4-Oct-17	pos 3 jack leg leaking, change out.
396581	4-Oct-17	rod end steering cylinder pins worn/frame worn.
396619	5-Oct-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
396861	5-Oct-17	adjust ropes and regas accumulators
396912	6-Oct-17	refit rotaion motor
396956	7-Oct-17	replace lube hose
396958	7-Oct-17	check no rotation
397352	10-Oct-17	repair leak on front jack leg
397383	10-Oct-17	replace blown hose
397558	11-Oct-17	repair flushing valve
397481	12-Oct-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
397608	12-Oct-17	rear bolts on drifter snapped x 3.
396663	17-Oct-17	replace water hose on water hose reel.
397515	17-Oct-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
397516	17-Oct-17	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
398357	18-Oct-17	replace compressor air filter housing next service.
398291	19-Oct-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
398534	21-Oct-17	repair flushing fault
398578	22-Oct-17	replace blown hose
398624	23-Oct-17	Perc. switch on GUI worn
398625	23-Oct-17	LH joystick sloppy
399059	23-Oct-17	refit ropes back on
399932	26-Oct-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
400077	26-Oct-17	Pressure washer hose U/S
400101	26-Oct-17	broken shank - change out
400164	27-Oct-17	air mist fault - broken wire in din on plug

400201	28-Oct-17	replace cab light
400257	29-Oct-17	blown hose. pump to filter.
400297	30-Oct-17	P4220 replaced faulty F32 proxy switch and lead
399967	31-Oct-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
399968	31-Oct-17	FOUR WEEKLY COMPRESSOR SERVICE ON SANDVIK DRILLS
400581	2-Nov-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
400770	3-Nov-17	Intermittant air-flush fault
400891	5-Nov-17	replace blown hose
400922	6-Nov-17	Bottom missing from front stinger cylinder
400957	6-Nov-17	hole in transfur tube in tilt cylinder
400992	7-Nov-17	Perc. not turning off properly
401003	7-Nov-17	fit new grease lines
401538	9-Nov-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
401650	9-Nov-17	Rail cradle needs tensioning
401570	14-Nov-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
401573	14-Nov-17	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
401965	14-Nov-17	replace bolts on drifter cable
402026	14-Nov-17	high eng oil temp engine derating. repair plug on temp
402027	14-Nov-17	top stinger creeping.
402028	14-Nov-17	lube hose on drifter replace.
402029	14-Nov-17	air seat not lifting.
402043	15-Nov-17	replace belt tensioner.
402045	15-Nov-17	replace belt.
402176	15-Nov-17	wiper blade u/s.
402078	16-Nov-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
402268	16-Nov-17	feed cradle cracked both sides
402447	18-Nov-17	repair oil leak
402490	19-Nov-17	replace gripper ass with s/h frame
402530	20-Nov-17	No reverse beeper
402558	20-Nov-17	replace rhf jack leg
402567	20-Nov-17	Cancelled during entry
402734	21-Nov-17	blown hose
402740	21-Nov-17	replace return ropes
402134	22-Nov-17	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
402852	23-Nov-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
402987	23-Nov-17	pos 3 wheelend oil plug needs replacing
402988	23-Nov-17	cracks in feed rail needs welding service day at front
402989	23-Nov-17	tilt cylinder leaking oil - check/change service day
403142	26-Nov-17	check water leaks at regulator and water hose reel
402878	28-Nov-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
402879	28-Nov-17	FOUR WEEKLY COMPRESSOR SERVICE ON SANDVIK DRILLS
403479	28-Nov-17	inner zoom tube cracked - changeout
403684	29-Nov-17	repaired seat mount runners and wiring in cab
403695	29-Nov-17	front wiper arm needs replacing
403624	30-Nov-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
404414	7-Dec-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
404453	12-Dec-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
405450	12-Dec-17	replace front stinger. cylinder creeping.

405451	12-Dec-17	replace lh rear jack leaking.
405483	12-Dec-17	replace drifter slinger and bolts loose
405494	13-Dec-17	No hole depth
405721	13-Dec-17	Called to the rig because of it had no penetration rate.
405592	14-Dec-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
405795	14-Dec-17	replace fitting on pito jaws
405908	16-Dec-17	replace return ropes
406175	18-Dec-17	replace over centre valves
406186	18-Dec-17	check a/c fault compressor u/s
406286	19-Dec-17	tighten rollover bolts
406323	21-Dec-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
406723	24-Dec-17	Cancelled during entry
406724	24-Dec-17	feed rope to be fitted, rope is ok.
406725	24-Dec-17	Replaced drilling joystick (LHS) as it was intermitently not
406354	26-Dec-17	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
406355	26-Dec-17	FOUR WEEKLY COMPRESSOR SERVICE ON SANDVIK DRILLS
407021	27-Dec-17	a/c not working. low on charge.
406933	28-Dec-17	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
407052	28-Dec-17	replace missing bolt in rear drifter plate
407053	28-Dec-17	replace bolt on rear stinger
407054	28-Dec-17	replace hinges on hyd tank
407169	28-Dec-17	replace hp accumulator
407170	28-Dec-17	replace blown hose
407172	28-Dec-17	Remove linear sensor and replace O Rings as it had a oil
407245	29-Dec-17	A/C not working
407268	30-Dec-17	replace flushing head seals and gaskets
407269	30-Dec-17	repair operators seat
407659	4-Jan-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
407795	4-Jan-18	bolts in rear of drifter snapped off.
407937	6-Jan-18	broken bracket on rod gripper for sensor
408335	8-Jan-18	replace feed ropes x 2
407071	9-Jan-18	A/C unit requires replacing with rotatable unit
407692	9-Jan-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
408397	9-Jan-18	replace feed rail stainless weld on wear strips.
408400	9-Jan-18	fit heli coils to feed cylinder front guide
408401	9-Jan-18	align drifter and tighten slides
408402	9-Jan-18	fit up drifter rail sprays
408403	9-Jan-18	Check air con temp and pressures, reassemble unit
408647	10-Jan-18	blown hose on long arms
408509	11-Jan-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
409016	15-Jan-18	park brake stuck on come good
408543	16-Jan-18	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
409049	16-Jan-18	Very low on engine power
409290	16-Jan-18	Check waste gate and boost pressure all in spec, need to
409458	17-Jan-18	Check brake system brakes stuck on this week
409404	18-Jan-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
410301	24-Jan-18	blown hose.
410202	25-Jan-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197

409440	26-Jan-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
410427	26-Jan-18	replace grease pump
410556	29-Jan-18	A/C fan only works on high
410557	29-Jan-18	Rail cradle needs tensioning
410941	1-Feb-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
411326	4-Feb-18	replace flushing head seals
411531	5-Feb-18	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
411597	5-Feb-18	check a/c noisy, replace compressor.
411818	5-Feb-18	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
410973	6-Feb-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
410974	6-Feb-18	FOUR WEEKLY COMPRESSOR SERVICE ON SANDVIK DRILLS
411965	6-Feb-18	oil leak under tredle valve
411966	6-Feb-18	tranny overfull drain 6 litres out
411967	6-Feb-18	fix front wiper not wiping full screen
412140	7-Feb-18	Cancelled during entry
412141	7-Feb-18	replace pito jaws.
412142	7-Feb-18	replace rod gripper hoses.
412055	8-Feb-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
412302	9-Feb-18	replace blown hose
412419	11-Feb-18	MOD 4, 5, 7 OFF BUS ERROR, found loose Can Cable on the X3
412444	12-Feb-18	Phx4200 called to LH04 with Electrical disturbance MOD 4,5,7
413181	15-Feb-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
413359	15-Feb-18	refit return rope.
413432	17-Feb-18	Replaced the percussion switch after reports it was coming
413219	20-Feb-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
413706	20-Feb-18	change out pressure filters and return filter
413956	21-Feb-18	repair stinger base plate and tighten rail extension bracket
413838	22-Feb-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
414603	27-Feb-18	replace broken fittings
414822	28-Feb-18	replace lube hose
414736	1-Mar-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
414870	1-Mar-18	replace rotation hose.
414951	3-Mar-18	Change flushing head seal and blown hose
414978	3-Mar-18	blown hose.
415033	4-Mar-18	long arms jamming up - adjust
415179	5-Mar-18	replace gripper jaws.
413336	6-Mar-18	Hyd. oil return filter upgrade - Bulletin 03/2013
414772	6-Mar-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
414773	6-Mar-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS
415327	7-Mar-18	a/c compressor noisy
415463	7-Mar-18	re-seal rod handler valves.
415483	7-Mar-18	adjust rod handler.
415414	8-Mar-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
415678	8-Mar-18	replace missing bolts in cradle
415803	11-Mar-18	replace grease line to long arms
415853	12-Mar-18	ajust feed ropes
415874	13-Mar-18	Pressure washer has low pressure
416070	13-Mar-18	replace flushing head seals

416089	13-Mar-18	replace fitting on pito cylinder
416179	15-Mar-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
416603	16-Mar-18	stinger front loose check mount and bolts
416613	16-Mar-18	Trans. breather update as per Sandvik Bulletin 2/2018
416640	16-Mar-18	repair damage to gripper arm frame.
416672	17-Mar-18	P4160 Depth counter was not working, replaced faulty
416712	18-Mar-18	Repair front wipper
416713	18-Mar-18	Check air con
416283	19-Mar-18	Continue on with making a spare can cable and see Josh
416215	20-Mar-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
417166	20-Mar-18	oil leak on rail - top up hyd oil
417379	21-Mar-18	reseal valves on boom
417211	22-Mar-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
417316	22-Mar-18	replace faulty front wiper motor
417339	22-Mar-18	replace pin retainer plate on long arms
417427	24-Mar-18	replace pito bushes and pins
417431	24-Mar-18	replace pito jaws
417497	25-Mar-18	repair oil leak
417837	27-Mar-18	refit feed ropes
417868	27-Mar-18	repair wiper blade
417872	27-Mar-18	repair water reel chain
418108	28-Mar-18	Blown hose and rod alignment
417965	28-Mar-18	rod alignment out when rotated to the right
418004	29-Mar-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
418146	29-Mar-18	water hose reel bearing collapsed.
418206	30-Mar-18	Feed ropes come off, re-fit
418226	31-Mar-18	change out flushing head seals.
418259	1-Apr-18	check a/c. not getting cold.
418268	1-Apr-18	rebuild rotatable a/c unit.
418285	1-Apr-18	Replace shank
418336	2-Apr-18	Blown gripper arm hose
418033	3-Apr-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
418034	3-Apr-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
418346	3-Apr-18	change out flushing head seal insert.
418347	3-Apr-18	bolts missing from stinger.
418348	3-Apr-18	check and repair pressure washer hose.
418658	5-Apr-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
418960	7-Apr-18	replace high side shroder valve and regas
419322	9-Apr-18	replace flushing head seals
419514	12-Apr-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
419644	12-Apr-18	cable roller bearings & chain need repair
419652	12-Apr-18	replace blown hose
419700	12-Apr-18	main earth lead of battery replaced and
419838	15-Apr-18	engine starting up on diesel when turning isolater on
419860	15-Apr-18	Investigated the rod counter issue at the C4405 W/Shop.
419867	15-Apr-18	a/c not working.
419883	16-Apr-18	engine derating
420174	16-Apr-18	blown hose on boom

420178	16-Apr-18	fit rotation valve
419539	17-Apr-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
419540	17-Apr-18	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
420536	17-Apr-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
420537	19-Apr-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
420694	20-Apr-18	replace cradle rail slides
420705	20-Apr-18	ajust ropes
420706	20-Apr-18	blown hose
420734	20-Apr-18	check long and short arms pins and bushes
420747	21-Apr-18	Rig dropping out intermittently...suspect CAN cable on
420787	21-Apr-18	top up hyd oil
420969	23-Apr-18	Adjust S30 proxy switch on LH 04 as Linear sensor wasnt
421229	24-Apr-18	replace grease line
421230	24-Apr-18	rock lube fault
421248	24-Apr-18	pin come out of gripper arm
421047	26-Apr-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
421423	26-Apr-18	feed rope jumped off and bolt jammed in rail
421425	26-Apr-18	blown hose
421451	27-Apr-18	action sos report attached
421482	27-Apr-18	gripper arm bush fell out
421651	30-Apr-18	replace water fitting in flushing head.
421072	1-May-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
421073	1-May-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
422055	2-May-18	trans pressure switch broken wire.
422098	2-May-18	Re-fit feed ropes
421833	3-May-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
422229	4-May-18	replace broken grease lines on rollover
422261	5-May-18	replace lube lube hose
421884	7-May-18	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
422311	7-May-18	ajust feed ropes and return ropes
422578	7-May-18	check trans leak and refit ropes and adjust as req
422758	8-May-18	Called to the P4200 as the phase rotation light was on,
422826	9-May-18	Transmission leak.
422880	10-May-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
423122	10-May-18	a/c not working, thermostat u/s.
423373	11-May-18	blown hoses on gripper arm
423438	13-May-18	a/c fault. compressor running as soon as ignition key turned
423439	13-May-18	repair exhaust.
423484	14-May-18	blown hose.
422942	15-May-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
422943	15-May-18	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
422944	17-May-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
424425	17-May-18	regas accumulators
424471	18-May-18	replace overcentre valve on tilt cylinder
424492	18-May-18	replace bush on rod gripper arms
424498	18-May-18	replace blown hose
424526	19-May-18	park brake stuck on in decline
424580	20-May-18	replace strapping bolts

424681	21-May-18	Check S41 repair and or replace sensor or cable.
424695	21-May-18	tighten strapping bolts
424700	21-May-18	repair oil leak on valve block
424803	22-May-18	replace strapping bolts
424805	22-May-18	regas accuulators
424756	24-May-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
424757	26-May-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
425149	27-May-18	replace cabin 4.5kg fire extinguisher.
425150	27-May-18	oil leak from front diff pinion seal.
425715	30-May-18	replace 3 x grease lines on boom
425466	31-May-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
425772	1-Jun-18	replace seal carrier in flushing head
425946	1-Jun-18	recharge accumulators
425467	2-Jun-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
425957	2-Jun-18	replace hp accumulator
425980	2-Jun-18	replace gripper jaw
425982	2-Jun-18	adjust front stinger
425991	2-Jun-18	replace blown hyd hose
426021	3-Jun-18	gripper pins & bushes
426047	3-Jun-18	regas accumulators
426117	4-Jun-18	replace flushing head seals
426118	4-Jun-18	replace blown hose
426136	4-Jun-18	regas accumulators
426496	5-Jun-18	park brake fault
426582	6-Jun-18	gripper pins & bushes
426329	7-Jun-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
426330	9-Jun-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
426839	9-Jun-18	front stinger mount u/s. threads u/s.
426873	10-Jun-18	no start, e-stop.
426884	10-Jun-18	air con not working. Unit needs to be changed
427446	13-Jun-18	blown hose.
427260	14-Jun-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
428950	14-Jun-18	tighten up straping bolts
432815	15-Jun-18	Comp. overheating and tripping out
432880	16-Jun-18	ajust feed ropes
432913	17-Jun-18	replace bolts in lhs accumulator
432937	17-Jun-18	blown jack leg hose
433063	19-Jun-18	Multiple grease lines broken
433064	19-Jun-18	Hoop under Pito missing
433171	19-Jun-18	CAN cable fault (History notes)
433317	20-Jun-18	replace pito jaws
433114	21-Jun-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
433365	21-Jun-18	top up hyd oil and fit new shank for operator
433115	23-Jun-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
433566	24-Jun-18	P4200 SHW - rig lost power
433627	25-Jun-18	No power to VME
433966	26-Jun-18	replace hp accumulator and gaskets
426631	27-Jun-18	repair oil leak & tighten strapping bolts

433865	28-Jun-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
434143	29-Jun-18	replace pito jaw pin & bushes
434167	29-Jun-18	regas low side accumulator
433866	30-Jun-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
434245	1-Jul-18	Repair damaged lineal sensor cable
434749	3-Jul-18	replace pito assy
434838	4-Jul-18	Grease lines U/S
434928	4-Jul-18	replace return rope
434096	5-Jul-18	replace broken bolt in low side accumulator
434687	5-Jul-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
434688	7-Jul-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
434889	7-Jul-18	LHO4 can cable has not been hard wired in? Apparently it
435063	7-Jul-18	fit 5 new led lights to cab and fix wiring on cab
435064	7-Jul-18	replace park brake pressure switch leaking oil
435132	9-Jul-18	front stinger creeping
435300	9-Jul-18	replace feed ropes and return ropes.
434722	10-Jul-18	water tap needs replacing at rear of machine
435891	11-Jul-18	replace blown percusion hose
435714	12-Jul-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
436065	12-Jul-18	reseal stringer valve
435097	15-Jul-18	feed valve u/s - oil leak patched up waiting for new one
436129	15-Jul-18	replace hoses and ajust long arms
436322	16-Jul-18	top up hyd oil
435743	17-Jul-18	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
436561	19-Jul-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
436959	21-Jul-18	rear jack legs wont come up - repaired wiring under a
437224	23-Jul-18	tighten strap bolt and accum bolts replaced and water box
437362	24-Jul-18	replace low side accum diaphragm u/s
437281	26-Jul-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
437282	28-Jul-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
437967	30-Jul-18	replace blown hose
438007	31-Jul-18	Compressor U/S
438264	1-Aug-18	replace h/p shroder valve and ajust feed ropes
438060	2-Aug-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
438061	4-Aug-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
438406	4-Aug-18	replace overcentre valves
438439	5-Aug-18	tighten driveline bolts front and rear during service
438466	5-Aug-18	calabrate sensors
438087	6-Aug-18	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
438531	6-Aug-18	stinger bolts replaced in mounts
438543	6-Aug-18	replace gripper arm cylinder
437929	7-Aug-18	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
439178	7-Aug-18	blown hose rotation
439127	9-Aug-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
440389	15-Aug-18	Compressor still U/S
440464	15-Aug-18	replace flushing head seals
440486	15-Aug-18	replace flushing head seals
438440	16-Aug-18	exhaust pipe and muffler need replacing on next service day

439988	16-Aug-18	Rail cradle need tensioning
440254	16-Aug-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
440255	18-Aug-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
440636	19-Aug-18	CAN fault
440861	23-Aug-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
441055	23-Aug-18	No pilot - dirty BTB
441172	24-Aug-18	replace water boost pump / leaking
441184	25-Aug-18	Called to LH04 as was not operating correctly on auto drill,
441185	25-Aug-18	Disconnect LH04 water u/s pump to be changed out, faulty
441240	26-Aug-18	Blown high side accumulator
441244	26-Aug-18	Blown hose
441245	26-Aug-18	blown hose
441267	26-Aug-18	adjust ropes and slides
441284	27-Aug-18	Brake pedal sticking
441447	27-Aug-18	check brake pedal
441695	28-Aug-18	replace guide plates
441696	28-Aug-18	repair wiring to 2nd gear solenoid
441699	28-Aug-18	replace broken fitting
441708	28-Aug-18	no reverse
441829	29-Aug-18	replace gripper hose
441648	30-Aug-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
441952	31-Aug-18	replace stinger mount assy bolts - remove broken ones
440862	1-Sep-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
441649	1-Sep-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
442018	1-Sep-18	blown hose.
442287	3-Sep-18	inspect and adjust rod handler.
442480	4-Sep-18	Change carousel out with new unit. PARTS RELEASED 12/09/18
442728	4-Sep-18	adjust rod alignment.
442657	6-Sep-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
443028	8-Sep-18	re shim gripper arms
443484	13-Sep-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
443785	13-Sep-18	replace batteries no start
443842	14-Sep-18	hose u/s on drifter rail lube.
442020	15-Sep-18	need new clip on welded boom rail
441283	15-Sep-18	Rail cradle needs tensioning
443485	15-Sep-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
443885	15-Sep-18	top gripper arm sloppy
443907	15-Sep-18	replace gripper arm assembly
443955	16-Sep-18	change broken shank
443993	16-Sep-18	fit rods and check alignment.
444060	17-Sep-18	replace water hose when required.
444235	18-Sep-18	Rebolt front stinger on.
444249	18-Sep-18	blown hose on back of drifter rail
444432	19-Sep-18	replace 2 x hoses on the drifter, hoses fitted to long.
444446	19-Sep-18	repair threads in front stinger, only holding on by two
444345	20-Sep-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
444502	20-Sep-18	air fault
444504	20-Sep-18	adjust feed ropes

444553	21-Sep-18	repair front stinger
444346	22-Sep-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
445019	25-Sep-18	refit feed rope
445146	26-Sep-18	replace oil transfer pump
444937	27-Sep-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
445219	27-Sep-18	fit feed rope
445272	28-Sep-18	Top up hyd oil
444938	29-Sep-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
445286	29-Sep-18	blown hose on grippers arm and rod alignment out and fault
445294	29-Sep-18	P4140SHW called to long hole as it tripped jumbo box on E/L.
445339	30-Sep-18	feed cylinder leaking - will need changing out
446486	3-Oct-18	Lube hose
446295	4-Oct-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
446518	4-Oct-18	Replace Feed Cylinder
446591	5-Oct-18	weld up guide hoop on front pito
446609	6-Oct-18	replace blown hoses
447032	9-Oct-18	replace feed cylinder leaking
447071	11-Oct-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
447346	11-Oct-18	C/O blown hydraulic hose
447375	12-Oct-18	Blown hose
447428	13-Oct-18	Hoses to be checked and replaced. Allow 18-24hr to complete.
447474	14-Oct-18	change out pito jaws
447098	16-Oct-18	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
447926	16-Oct-18	Air conditioner unit- hydraulic pump is a making weird noise
447880	18-Oct-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
448195	18-Oct-18	ELEC DISTURBANCE fault...check CAN cable and connections
448206	19-Oct-18	Long hole 4 linear sensor fault
448229	19-Oct-18	replace compressor belts
447881	20-Oct-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
448258	20-Oct-18	replace 3 x blown hoses
448457	22-Oct-18	check water pressure from boost pump
448458	22-Oct-18	replace low side accumulator
453422	23-Oct-18	replace water hose in loom
453309	25-Oct-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
453625	25-Oct-18	fix air seat wiring
442019	26-Oct-18	elephant ear needs replacing. SPARE PART ONLY
448025	26-Oct-18	a/c compressor hose leaking gas. painted yellow. to be
453310	27-Oct-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
453816	27-Oct-18	need air filter rain cap
453817	27-Oct-18	front pinion seal leaking due to diff over full
453818	27-Oct-18	weld cracks in boom
453881	28-Oct-18	P4160SFW longhole tripped on E/L back at DB tested and could
453477	29-Oct-18	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
454061	1-Nov-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
454583	3-Nov-18	park brake stuck on
454614	3-Nov-18	repair parkbrake fault
454621	4-Nov-18	Assist fitters with park brake fault
454668	4-Nov-18	replace shank & fix hoses

454832	5-Nov-18	top up hyd oil
454894	5-Nov-18	Adjust Drifter slides
455089	6-Nov-18	replace stereo unit and speakers
454105	8-Nov-18	replace elephant ear - has w/o 442019 on go bay in planned
455035	8-Nov-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
455036	10-Nov-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
455037	10-Nov-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
455038	10-Nov-18	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
455673	12-Nov-18	replace 2 x front work lights.
455905	15-Nov-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
456279	17-Nov-18	replace pito hose & fittings - 6 x 500mm & t fittings
456460	22-Nov-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
456461	24-Nov-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
456902	24-Nov-18	fitting on long arm u/s.
456926	24-Nov-18	C/O blown hose
456964	25-Nov-18	exhaust heat cover needs replacing
456965	25-Nov-18	replace grease lines in centre hitch
456969	25-Nov-18	no charge - alternator needs replacing
457197	29-Nov-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
458217	4-Dec-18	Replace U/S can cable and repair wiring in R3 Box
458550	5-Dec-18	replace blown lube hose
458311	6-Dec-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
458629	6-Dec-18	recalibrate clino settings
458312	7-Dec-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
458635	7-Dec-18	Tilt sensor
458313	8-Dec-18	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
458808	8-Dec-18	Cancelled during entry
458840	9-Dec-18	electrical box on bottom of boom damaged broken mount.
459391	12-Dec-18	front stinger cylinder u/s - changeout stinger assembly
458975	13-Dec-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
459467	13-Dec-18	replace broken fittings
459482	13-Dec-18	replace bolts on gaurd for rod handler
459881	20-Dec-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
459882	21-Dec-18	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
460475	22-Dec-18	tighten loose hose fittings. led light u/s.
460482	23-Dec-18	Rear diff over full, CHANGE REAR AXLE
460483	23-Dec-18	Front diff pinion seal leaking
460871	24-Dec-18	C/O blown hydraulic hose
460349	27-Dec-18	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
460971	27-Dec-18	blown hose.
461028	27-Dec-18	Pito cylinder pin fallen out
461608	1-Jan-19	regas accumulators
461611	1-Jan-19	no movement on long arms
461550	3-Jan-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
461963	3-Jan-19	Outriggers won retract
461551	4-Jan-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
462142	4-Jan-19	Replace pos 2 wheel end plug
461552	5-Jan-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.

462369	10-Jan-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
462698	11-Jan-19	bolts broken in gripper arm
462787	13-Jan-19	replace grease gun
463023	17-Jan-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
456972	18-Jan-19	water pressure reg valve leaking
462403	18-Jan-19	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
463777	19-Jan-19	gripper arm shaft bushes, and long arm cylinder bearings
464154	22-Jan-19	air tap on rear of machine to fit.
464080	24-Jan-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
464734	31-Jan-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
465211	31-Jan-19	H4460 No rod counter
464735	1-Feb-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
465278	1-Feb-19	repair broken/rotatable parts.
465301	1-Feb-19	replace broken bolts in carosel housing and mounting plate
464736	2-Feb-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
465151	7-Feb-19	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
465620	7-Feb-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
466058	7-Feb-19	water pressure reg valve leaking
465663	13-Feb-19	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
466993	13-Feb-19	sample engine oil
467036	13-Feb-19	top up hyd oil
466815	14-Feb-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
466816	15-Feb-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
467879	21-Feb-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
468330	25-Feb-19	Damaged can cable, tested cable will only need a deutch plug
468862	26-Feb-19	out rigger stuck out on rig
468956	27-Feb-19	replace carrier hose
468673	28-Feb-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
468674	1-Mar-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
468675	1-Mar-19	BATTERY ISOLATOR CHANGE OUT
468676	2-Mar-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
469216	2-Mar-19	all 4 jack legs pitted and leaking.
469217	2-Mar-19	drifter coupling showing signs of wear and damage monitor.
469301	3-Mar-19	adjust rod changer gripper arms
469442	7-Mar-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
469882	7-Mar-19	replace feed ropes
472214	10-Mar-19	adjust feed rope & check a/c
472838	13-Mar-19	replace blown hose
472900	13-Mar-19	replace rope
472672	14-Mar-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
472945	14-Mar-19	refit feed ropes
472673	15-Mar-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
473012	15-Mar-19	check turbo studs - check for any broken as per Josh Hancock
473076	16-Mar-19	fix oil leak and feed cylinder and refit feed rope
473102	17-Mar-19	hyd fitting on feed cylinder leaking. repair.
473119	17-Mar-19	blown hose
473135	18-Mar-19	no a/c broken wire in box.
473345	18-Mar-19	replace feed cylinder guide bushes

473385	21-Mar-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
474143	25-Mar-19	oil leak at boom
474715	27-Mar-19	blown hose
474394	28-Mar-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
474772	28-Mar-19	feed cylinder fittings u/s.
474395	29-Mar-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
474396	29-Mar-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
474861	29-Mar-19	blown hose in loom and tighten fittings on cylinder
475313	1-Apr-19	replace feed ropes
475438	2-Apr-19	replace gripper arm frame, cracked.
475617	3-Apr-19	blown hose.
475372	4-Apr-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
476678	8-Apr-19	e stop fault
476815	9-Apr-19	replace shank
476725	11-Apr-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
476765	12-Apr-19	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
477150	12-Apr-19	C/O rotation bush
477198	13-Apr-19	repair LHS outrigger
477657	18-Apr-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
477928	18-Apr-19	replace - 12 hose
478019	19-Apr-19	air mist fault
478111	21-Apr-19	Cut off siezed drill rods
478113	21-Apr-19	feed rope U/S
478122	22-Apr-19	replace feed ropes
478167	22-Apr-19	Replace water fitting and accumulator
478169	22-Apr-19	Repair grease gun
478171	22-Apr-19	Replace broken hyd fitting
478538	23-Apr-19	replace grease pump
478541	23-Apr-19	repair joy sticks
478569	23-Apr-19	Repair lights
478486	25-Apr-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
478771	25-Apr-19	L/H out-rigger getting stuck
478487	26-Apr-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
478488	26-Apr-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
478822	26-Apr-19	replace hyd drive motor out off rotatable a/c unit
479367	2-May-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
479919	5-May-19	replace blown hose
479925	5-May-19	check brakes dragging
480243	6-May-19	check top stinger not holding
479438	7-May-19	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
480652	9-May-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
480653	10-May-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
480654	10-May-19	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
481833	14-May-19	lh front jack leg extension jamming up.
481978	15-May-19	check linear sensor
481758	16-May-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
482211	19-May-19	Comms serial comms error fault, found the B07 sensor was U/S
482220	19-May-19	check & adjust alignment

482269	20-May-19	blown hose
482305	21-May-19	Called to LHo4 @ H4395 as the operator lost power after
482401	23-May-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
482402	24-May-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
482403	24-May-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
483277	30-May-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
484241	6-Jun-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
484242	7-Jun-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
485544	13-Jun-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
486510	20-Jun-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
486511	21-Jun-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
486850	21-Jun-19	Replace compressor fan
486878	22-Jun-19	change out rear diff oil due to being overfull with hyd oil.
487423	27-Jun-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
486877	29-Jun-19	transmission mount rubber soft.
488297	4-Jul-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
488298	5-Jul-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
489255	11-Jul-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
489292	16-Jul-19	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
490186	18-Jul-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
490448	18-Jul-19	blown hose.
491018	25-Jul-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
491692	1-Aug-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
491693	2-Aug-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
492266	3-Aug-19	Replace front flushing head bush
491764	7-Aug-19	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
492775	8-Aug-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
493881	15-Aug-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
493882	16-Aug-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
493925	18-Aug-19	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
494663	22-Aug-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
496120	27-Aug-19	replace blown hose
496114	28-Aug-19	Called to LH04 at P4050 swan as he repoted machine having
495873	29-Aug-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
495874	30-Aug-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
496410	31-Aug-19	Rollover needs changing out
496411	31-Aug-19	Wiper arm assembly needs replacing
496412	31-Aug-19	Door strut u/s - NEED REPLACING
496413	31-Aug-19	RH rear frame bent
496724	5-Sep-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
498243	12-Sep-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
498244	13-Sep-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
498245	13-Sep-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
498680	15-Sep-19	lh rear jack leg u/s. change out.
498751	16-Sep-19	check brake accumulator pressure. change out 1 x accumulator
498752	16-Sep-19	Hyd cabinet door latch not holding.
499128	19-Sep-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
499494	20-Sep-19	replace blown hose

499534	21-Sep-19	replace smashed front window
500254	25-Sep-19	repair zoom fitting leak
499861	26-Sep-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
499862	27-Sep-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
500468	28-Sep-19	Zoom wiper seal
500617	30-Sep-19	Lube fault
500726	30-Sep-19	Lube fault
500819	3-Oct-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
500467	5-Oct-19	Lift cyl weeping
500469	5-Oct-19	cable reel needs repair.
500470	5-Oct-19	Replace rear drive shaft
500471	5-Oct-19	Replace centre drive shaft
500472	5-Oct-19	All 4 steer pins and bushes to be replaced.
502214	9-Oct-19	replace broken fitting
502215	9-Oct-19	repair oil leak
501961	10-Oct-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
501962	11-Oct-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
501963	11-Oct-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
502457	12-Oct-19	hyd oil milky. need to replace cooler
502575	14-Oct-19	Replace bush on carousel long arm
502576	14-Oct-19	Replace bonnet hinges above compressor
502700	15-Oct-19	engine low power tramming up.
502650	17-Oct-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
503329	18-Oct-19	stopped on the decline afff gone off
503331	18-Oct-19	drill feed fault
502610	22-Oct-19	reseal spare hydraulic cooler.
502701	22-Oct-19	replace feed extension cylinder leaking and badly pitted.
503650	24-Oct-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
503651	25-Oct-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
504984	31-Oct-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
505714	1-Nov-19	jump start
505748	2-Nov-19	replace pito jaws
505749	2-Nov-19	replace hyd oil and pressure filter
505538	7-Nov-19	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
506132	7-Nov-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
506133	8-Nov-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
506134	8-Nov-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
506173	10-Nov-19	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
506675	11-Nov-19	CHANGE SHANK LUBE WATER SEPARATOR ASSEMBLY
507035	14-Nov-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
507075	19-Nov-19	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
507822	21-Nov-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
508214	21-Nov-19	System 130 fault @ P3990 swan
507823	22-Nov-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
508684	28-Nov-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
508914	28-Nov-19	replace "6 hose
509090	29-Nov-19	replace blown hose on rail
509093	29-Nov-19	Called to LH 04 at P4140 as it had a fault with CAN BUS

509556	5-Dec-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
510583	12-Dec-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
510584	13-Dec-19	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
510585	13-Dec-19	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
511448	15-Dec-19	Check threading speed, too fast
511499	15-Dec-19	replace blown hose
511714	17-Dec-19	replace shank
511747	17-Dec-19	REPLACE ROD GRIPPER ARM PIN
511808	18-Dec-19	S Sensor not working
511809	18-Dec-19	Rod count not working
511909	18-Dec-19	Feed fault
511932	18-Dec-19	Replaced LH joystick. but did not fix issue with fast feedin
511650	19-Dec-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
512135	20-Dec-19	feed fault
512230	20-Dec-19	replace pressure switch
511610	24-Dec-19	replace drilling joystick service day.
512429	26-Dec-19	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
513127	28-Dec-19	ceased water boost pump
513141	28-Dec-19	Water pump tripping on O/L
513142	28-Dec-19	Coming up with B6 and B7 error fault, found S 35 sensor to
513763	1-Jan-20	stuck in gutter blocked decline @p4140
513765	1-Jan-20	adjust water pump pressure
513501	2-Jan-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
513502	3-Jan-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
514171	3-Jan-20	replace air filter top hat cover
514482	7-Jan-20	Rear RH bonnet strut to be replaced.
514520	9-Jan-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
515680	16-Jan-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
515681	17-Jan-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
515682	17-Jan-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
516040	17-Jan-20	Replace rope pulleys and bearings
516083	17-Jan-20	engine can fault.
516616	21-Jan-20	powerpack won't start 130 CAN fault.
516628	22-Jan-20	P4010 System fault 130 as soon as rig is powered up
516772	22-Jan-20	replace blown hose on the fast feed
516545	23-Jan-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
517724	28-Jan-20	check fuel leak on quick fill
517604	30-Jan-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
518234	30-Jan-20	blown hose gripper arm
517605	31-Jan-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
518304	31-Jan-20	pos 2 hub seal leaking.
518364	1-Feb-20	dash 6 fitting u/s on pito, replace.
518424	2-Feb-20	blown hose.
518428	2-Feb-20	refit drifter slide. snapped and missing bolts.
514985	4-Feb-20	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
518796	4-Feb-20	refit feed ropes and adjust.
518048	6-Feb-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
519139	6-Feb-20	nylons slides missing on rail

519140	6-Feb-20	pos 2 hub seal leaking
519226	7-Feb-20	gas hp side accumulator
519227	7-Feb-20	check front axle levels
519286	8-Feb-20	rebuild lh04 parts
519957	13-Feb-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
519958	14-Feb-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
519959	14-Feb-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
521125	14-Feb-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
520007	18-Feb-20	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
521164	20-Feb-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
521771	24-Feb-20	change pos 2 tyre
521818	24-Feb-20	replace broken shank
522118	27-Feb-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
519216	28-Feb-20	monitor pos 1 jack leg badly pitted / not leaking
522119	28-Feb-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
522666	28-Feb-20	front diff pinion seal change out required.
522667	28-Feb-20	fir suppression delivery line rubbed through in
522668	28-Feb-20	replace driveshaft bolts front of tranny.
522669	28-Feb-20	replace rocker cover gasket.
523262	5-Mar-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
523851	9-Mar-20	LH04 CAN cable fault System Error 130
524377	12-Mar-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
524378	13-Mar-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
524379	13-Mar-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
525412	19-Mar-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
526186	26-Mar-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
526187	27-Mar-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
527538	2-Apr-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
528566	9-Apr-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
528567	10-Apr-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
528568	10-Apr-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
529261	16-Apr-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
530137	19-Apr-20	blown hoses on boom
530500	23-Apr-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
530501	24-Apr-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
531793	30-Apr-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
531864	4-May-20	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
533138	7-May-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
533139	8-May-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
533140	8-May-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
533508	8-May-20	blown hose gripper arms.
533180	10-May-20	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
534262	14-May-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
534308	19-May-20	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
535021	21-May-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
535711	28-May-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
537151	4-Jun-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
537152	5-Jun-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL

537153	5-Jun-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
537599	6-Jun-20	Oil leak on top front gripper arm
538077	11-Jun-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
539036	18-Jun-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
539037	19-Jun-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
540171	23-Jun-20	SLU fault
539991	25-Jun-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
540507	26-Jun-20	Front wiper motor U/S - N Sinclair
541041	2-Jul-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
541042	3-Jul-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
541043	3-Jul-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
542207	9-Jul-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
543561	16-Jul-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
543562	17-Jul-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
544057	17-Jul-20	check rod alignment and drifter alignment
544445	23-Jul-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
544056	24-Jul-20	replaced 4.5kg fire ext - from ext rack on surface
545467	27-Jul-20	Install Mobilaris hardware
545617	30-Jul-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
546526	30-Jul-20	replace hyd oil. looked milky.
544055	31-Jul-20	front axle diff pinion seal weeping
545618	31-Jul-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
545619	31-Jul-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
545698	4-Aug-20	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
547434	6-Aug-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
547922	8-Aug-20	gripper jaws loose replaced damaged bolts
548426	13-Aug-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
548467	18-Aug-20	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
549272	20-Aug-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
549273	27-Aug-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
550283	27-Aug-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
550284	27-Aug-20	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04
550500	27-Aug-20	Carry out audit of machine for worn components
550726	27-Aug-20	replace rear jack leg hose and fitting
550285	28-Aug-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
550728	28-Aug-20	drivers side door inner panel rusted - repair or replace
553648	28-Aug-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
551075	3-Sep-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
550725	4-Sep-20	LHS door needs new lock and door needs straightening
551889	5-Sep-20	replace blown hose
552698	10-Sep-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
552699	10-Sep-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
553686	17-Sep-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
554121	17-Sep-20	water in hyd oil ???
554426	21-Sep-20	Replace blown hose
554446	21-Sep-20	water on hyd oil
554797	22-Sep-20	replace hyd pressure filter sensor
554799	22-Sep-20	shut down on decline

554846	23-Sep-20	P41280 continued on with LH04 fault F450 C/B apparently kept
554924	23-Sep-20	500HR HL710 DRIFTER CHANGE OUT FOR DRILLS
554013	24-Sep-20	No radio handpiece - M Ryan
554499	24-Sep-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
554500	24-Sep-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
554780	24-Sep-20	Change out Carousel
554501	25-Sep-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
554816	29-Sep-20	electrical fault ?? Tripping f450 circuit breaker
555813	29-Sep-20	drain and refill hyd oil tank water in oil.
555814	29-Sep-20	change out led cabin light.
555815	29-Sep-20	change out battery terminals and protectors on terminals,
555699	1-Oct-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
555816	6-Oct-20	rear brake gauge not working. diagnosis required.
555817	6-Oct-20	fuel gauge u/s missing glass. replacement required.
555819	6-Oct-20	replace centre bearing, mounting foot cracked off bearing
556873	8-Oct-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
556874	8-Oct-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
557975	15-Oct-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
557361	15-Oct-20	S30 & S41 sensors u/s
557362	15-Oct-20	Angle sensors u/s
557363	15-Oct-20	Auto u/s
557364	15-Oct-20	New carousel alignment poor
557365	15-Oct-20	Rod counter issues
557366	15-Oct-20	Linear sensor issues
557407	16-Oct-20	front diff pinion seal leaking new yoke required.
570931	23-Oct-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
560162	29-Oct-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
560694	31-Oct-20	remove broken stinger cylinder left down in paste cuddy
560245	4-Nov-20	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
560910	5-Nov-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
561345	5-Nov-20	Mobilaris Round 2 - BLE Adapter Kit Install
560950	10-Nov-20	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
569953	12-Nov-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
570932	17-Nov-20	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
569954	19-Nov-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
569963	19-Nov-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
570933	20-Nov-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
564635	24-Nov-20	Flush Hydraulic circuit - water contamination
569955	26-Nov-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
569956	3-Dec-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
569964	3-Dec-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
569957	10-Dec-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
569958	17-Dec-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
569965	17-Dec-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
570934	18-Dec-20	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
569959	24-Dec-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
569960	31-Dec-20	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
569966	31-Dec-20	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL

570138	1-Jan-21	replace grease gun.
570981	7-Jan-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
571369	8-Jan-21	Replace flushing head seals
571396	9-Jan-21	Fit flushing head bolts
571455	10-Jan-21	replace blown hose
572083	14-Jan-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
572084	14-Jan-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
572085	14-Jan-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
572515	15-Jan-21	Repair blown hose on boom
572516	15-Jan-21	Fit and adjust feed ropes
573110	21-Jan-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
574256	24-Jan-21	jump start
575254	27-Jan-21	Circuit breaker tripped at console
574953	28-Jan-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
574954	29-Jan-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
575595	4-Feb-21	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
576553	7-Feb-21	H4280 called to LH04 had the Electrical disturbance fault,
576637	7-Feb-21	blown hoses on boom
577393	9-Feb-21	Called to LH04 at H4280 as his GUI panel was indicating
577394	10-Feb-21	CAN cable fault
576788	11-Feb-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
576789	11-Feb-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
576833	16-Feb-21	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
577399	17-Feb-21	Pressure washer U/S - N Sinclair
578019	18-Feb-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
578434	18-Feb-21	tighten up pito jaws
578445	18-Feb-21	Tidy up drifter hoses
578520	19-Feb-21	Broken fitting on gripper arm
578558	20-Feb-21	replace batteries
578564	20-Feb-21	replace 2 hoses in main loom to drifter
578783	25-Feb-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
578784	26-Feb-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
579813	28-Feb-21	R/H jack leg hoses blown
578827	1-Mar-21	BATTERY ISOLATOR CHANGE OUT
580145	2-Mar-21	Replace pito jaws
580057	4-Mar-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
579567	11-Mar-21	Investigate water contamination of hydraulic system
581207	11-Mar-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
581208	11-Mar-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
581209	12-Mar-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
581831	12-Mar-21	SEAT DOESN'T LOCK IN PROPERLY
581832	12-Mar-21	DERATES BADLY WHEN TRAMMING
581981	14-Mar-21	2 x blown hoses.
582250	18-Mar-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
583517	25-Mar-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
583518	26-Mar-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
584132	26-Mar-21	Replace shank
584133	26-Mar-21	Replace pito jaw bolts

584181	27-Mar-21	water leak pressure washer gauge.
584220	28-Mar-21	pressure washer lance u/s.
584242	28-Mar-21	shank change.
584251	28-Mar-21	reverse feed fault.
584429	29-Mar-21	replace pressure washer.
584483	29-Mar-21	dropped rods. Replaced B6 sensor and cable.
584755	30-Mar-21	repair grease lines.
584958	31-Mar-21	Blown gripper arm hose
584649	1-Apr-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
585011	1-Apr-21	refit flushing head
585208	4-Apr-21	replace blown hose
584403	5-Apr-21	replace cartridge valve in the feed double over centre valve
583904	7-Apr-21	Carry out repairs as per Safety Bulletin 14/2016
584866	7-Apr-21	check and replace grease lines to boom.
586395	7-Apr-21	boom sensor fault
586104	8-Apr-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
586105	8-Apr-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
586106	9-Apr-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
584148	10-Apr-21	Cracked RH side rear window
586571	10-Apr-21	replace needed lights service day by sparkies
586636	10-Apr-21	Called to LH04 at PHX4120 had comms sensor fault .Found B7
587239	15-Apr-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
587670	16-Apr-21	replace damaged grease line
587328	20-Apr-21	Pos 2 inner hub seal leaking
587329	20-Apr-21	Muffler rusted out
587330	20-Apr-21	Rollover has movement - ASSESS IF REPLACEMENT IS REQUIRED
587331	20-Apr-21	Pos 4 jack leg leaking
587332	20-Apr-21	Pitting on tilt cylinder - ASSESS
587333	20-Apr-21	Crack in rail - BOILY
589041	22-Apr-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
589042	23-Apr-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
589823	27-Apr-21	Check seat
589869	29-Apr-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
590281	30-Apr-21	LH04 at P4120 to check tilt sensor not reading
590505	30-Apr-21	no power to cable reels coils?
590506	30-Apr-21	rhr jackleg not working
590642	2-May-21	rhr jackleg not going up
589334	4-May-21	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
590842	6-May-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
590843	6-May-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
590844	7-May-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
590882	10-May-21	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
592011	13-May-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
592053	18-May-21	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
593026	18-May-21	gripper arms broken
592912	20-May-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
593408	21-May-21	bent lh step.
593459	22-May-21	pito jaws u/s.

593503	23-May-21	engine fan belt tensioner and belt u/s.
593530	23-May-21	Coolant leak from header tank
593597	24-May-21	adjust gripper arms.
593628	24-May-21	Shank lube fault
593930	25-May-21	check operation of hyd transfer pump.
594040	26-May-21	pin came out of gripper assy. replace gripper assy.
593833	27-May-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
594268	27-May-21	bottom stinger come off
594294	27-May-21	blown hose in center hitch
594295	27-May-21	repair oil leak in lh cabinet
594302	27-May-21	replace carrier hose
594279	28-May-21	din plug lhs pressure filter / grease hand piece
594342	28-May-21	replace grease gun
594368	28-May-21	feed ropes u/s
594425	29-May-21	adjust carrousel alignment
594427	29-May-21	replace main pump hose - pirtek
594463	30-May-21	H4280, had intermittant fault turning power pack off and
594527	30-May-21	linear senor fault
594552	31-May-21	Installed new Retaining clip for Consol cable under cab as
594554	31-May-21	Callled to LH04 to check linear sensor as it was reading
594883	31-May-21	repair stinger
594912	31-May-21	changed shank
595198	1-Jun-21	SOS - COMPRESSOR - VERY HIGH WATER INGRESS
595208	1-Jun-21	repair pito jaws
595410	2-Jun-21	replace pito jaws
595103	3-Jun-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
595104	3-Jun-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
592913	4-Jun-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
595105	4-Jun-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
595613	4-Jun-21	no air flushing or lube air.
595644	5-Jun-21	Repair stinger foot
595645	5-Jun-21	Hydraulic fault
595705	6-Jun-21	Repair flushing head
595719	6-Jun-21	Replace compressor belts
595720	6-Jun-21	Replace roll-over overcentre valves
595721	6-Jun-21	Repair pito jaw accumulator
595726	6-Jun-21	Replace seat belt
596239	10-Jun-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
597353	17-Jun-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
597354	18-Jun-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
598673	24-Jun-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
599929	1-Jul-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
599930	1-Jul-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
601107	1-Jul-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
602577	1-Jul-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
604236	1-Jul-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
605171	1-Jul-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
599931	2-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL

601108	2-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
602578	2-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
604237	2-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
605172	2-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
601139	8-Jul-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
602610	15-Jul-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
602611	16-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
604238	16-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
605173	16-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
604401	20-Jul-21	Jump start
604619	21-Jul-21	Replace fitting and hose on drifter
604271	22-Jul-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
605205	29-Jul-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
605206	29-Jul-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
605207	30-Jul-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
605915	31-Jul-21	blown hose in hose loom.
605295	4-Aug-21	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
606322	5-Aug-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
608255	11-Aug-21	reset park brake circuit breaker
607911	12-Aug-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
608269	12-Aug-21	Park brake issues
608591	14-Aug-21	oil leaks around hyd pump assess and repair.
608597	14-Aug-21	repair oil leak.
607951	17-Aug-21	6 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
608861	19-Aug-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
608590	21-Aug-21	feed rail weld on clip on to be replaced.
608592	21-Aug-21	cabin light needs replacing.
609715	26-Aug-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
609716	26-Aug-21	6 MONTHLY AIR COMPRESSOR SERVICE - LH02, LH04 .
609717	26-Aug-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
610809	26-Aug-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
609718	27-Aug-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
610353	28-Aug-21	LH rear door hinge bent
610354	28-Aug-21	Oil leak from a/c compressor box
610355	28-Aug-21	seat cover u/s
610356	28-Aug-21	windscreen washers motors x 3 U/S
610357	28-Aug-21	engine oil level sensor u/s
610842	2-Sep-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
610352	4-Sep-21	Rear top bonnet hinge broken
611942	9-Sep-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
611943	10-Sep-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
612387	10-Sep-21	BATTERY ISOLATOR CHANGE OUT
612446	11-Sep-21	linear sensor not working. check and repair.
612820	16-Sep-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
614874	23-Sep-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
614875	23-Sep-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
614876	24-Sep-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
615291	25-Sep-21	Hard to start

615600	27-Sep-21	low flushing pressure fault.
615933	30-Sep-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
615300	2-Oct-21	Rail weld on U/S
615301	2-Oct-21	Oil leak under LHF jack leg
615302	2-Oct-21	Air flushing valve stuck open
617093	7-Oct-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
617524	7-Oct-21	Jump start
617094	8-Oct-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
618227	14-Oct-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
617543	15-Oct-21	Batteries dying needs jump start all the time
619897	21-Oct-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
619898	21-Oct-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
620569	21-Oct-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
622368	21-Oct-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
624068	21-Oct-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
626069	21-Oct-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
619899	22-Oct-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
620570	22-Oct-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
622369	22-Oct-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
624069	22-Oct-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
626070	22-Oct-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
620594	28-Oct-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
620259	4-Nov-21	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
621341	4-Nov-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
621342	5-Nov-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
622370	5-Nov-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
624070	5-Nov-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
626072	5-Nov-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
621387	10-Nov-21	6 MONTHLY STEERING COLUMN SPLINE INSPECTION
622396	11-Nov-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
623332	18-Nov-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
623333	18-Nov-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
626073	18-Nov-21	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
623334	19-Nov-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
626074	19-Nov-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
624105	25-Nov-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
624992	2-Dec-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
624993	3-Dec-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
626075	3-Dec-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
626025	6-Dec-21	change out batteries.
626044	6-Dec-21	Blown hose on boom
626047	6-Dec-21	Blown jack leg hose
626108	9-Dec-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
627244	16-Dec-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
628614	23-Dec-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
629550	30-Dec-21	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
629551	31-Dec-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
630366	31-Dec-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL

633082	31-Dec-21	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
630397	6-Jan-22	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
631481	13-Jan-22	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197
631482	14-Jan-22	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
631483	14-Jan-22	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
633084	14-Jan-22	2 WEEKLY SERVICE OF SANDVIK LONGHOLE DRILL
633085	14-Jan-22	4 WEEKLY COMP. SERVICE & HYD. FILTER'S ON SANDVIK DRILLS.
631529	18-Jan-22	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
633114	18-Jan-22	3 MONTHLY SERVICE OF TAMROCK LONGHOLE DRILL
633115	20-Jan-22	DAILY SERVICE & INSPECTION - DOCUMENT HELD ON PM 2197