



# Vehicle History Summary



Fleet #	XN29CM			
Registration	XN29CM			
Make	DAF			
Model	XF105			
VIN / Chassis #	XLRTT47MSJG200037			
Build Date	2018			

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-2665	02/11/2022	860440	0	A - Fortnightly		
S-2644	25/10/2022	854432	0	B - 50k		Jack
S-2633	27/09/2022	0	0	A - Fortnightly		
R-1757	27/09/2022	0	0	Add Coolant		
R-1755	27/09/2022	0	0	Power Steering		
S-2607	22/08/2022	780000	0	D - 300k		
R-1684	17/08/2022	0	0	Exhaust Brake	Oil leak out of oil filter tube Exhaust brake air fitting damaged Removed Header Tank to fit new oil filter&piping Refit Header Tank fill with coolant Remove Old exhaust brake solenoid and refit new one Replace Exhaust brake solenoid air line and Banjo bolt	
R-1642	12/07/2022	0	0	Mirrors	REPLACED MIRROR COVER	Jack
S-2575	04/06/2022	0	0	A - Fortnightly	A SERVICE - TOP UP ENGINE OIL 6LTRS REPLACED BATTERY TERMINALS	
R-1571	16/05/2022			Electronic Diary	NAVMAN REMOVED	
S-2524	08/04/2022	756001	0	D - 300k	motor was just rebuilt and truck was gone over in melbourne no cost on this service because costs are on a invoice against a different repair number	Jack
S-2523	01/04/2022	756000	0	A - Fortnightly	truck has just been locked over top to bottom in melbourne after motor rebuild which is all on invoice from them which is on another repair number	Dylan
R-1324	22/12/2021	0	0	Power Steering		

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-1825	28/10/2021			Engine	CORRECTION: INVESTIGATED THE COMPRESSOR AND FOUND COMPRESSOR HAD FAILED. CHECKED AND FOUND METAL FROM COMPRESSOR HAS MADE ITS WAY INTO THE MOTOR. UNBOLT COMPRESSOR AND INSPECT AND FOUND A LOT OF METAL IN THE TIMING CHEST. DRAINED OIL, REMOVED SUMP AND STIFFNER PLATE. REMOVED MAIN BEARING AND FOUND EXCESSIVE METAL GONE THROUGH THE MOTOR. WILL NEED SHORT BLOCK REPLACEMENT AND CHARGE AIR COOLER REPLACED. UNBOLT GEARBOX AND ENGINE MOUNTING POINTS. REMOVE MOTOR AS REQUIRED FROM CHASSIS. REMOVED INTERCOOLER AND REPLACED WITH NEW. UNBOLT ALL ACCESSORIES AND FIT NEW TO BLOCK. REMOVED ROCKER COVER AND ASSEMBLIES AND UNBOLT HEAD. FIT HEAD TO NEW BLOCK AND TENSIONED. REFIT OVERHEADS AND ROCKER COVER WITH NEW GASKET. FIT STIFFNER PLATE. HAD A LOT OF DIFFICULTY REMOVING OLD GASKET OF SUMP- ONCE OF SUMP AS REQUIRED AND REFIT MOTR AND BOX TO VEHICLE. CHECKED AND ROAD TESTED. DURING ROAD TEST EXHAUST WARNING AND COOLANT WARNING CAME ON INVESTIGATED AND COMPLETED ON OTHER JOBS.	
S-2365	16/09/2021	0	0	A - Fortnightly		
O-154	13/09/2021	0	0	Registration		Transport NSW (Service NSW)
O-155	13/09/2021	0	0	CTP		NRMA Insurance
S-2364	03/09/2021	0	0	A - Fortnightly		
S-2336	20/08/2021	749832		B - 50k		Kobi
T-386	09/08/2021	0	0	New	2x bridgestone 1x truck tyre disposal	
R-1295	06/07/2021	0	0	Fuel Cap	replaced fuel cap with new fuel cap	
R-1293	05/07/2021	0	0	Wiper Blades	fit new wiper blades	
S-2284	24/06/2021	701362	0	B - 50k	b service truck replaced power steering hose and oil filter and oil	
S-2236	03/06/2021	684687	0	A - Fortnightly		
R-1223	28/05/2021	0	0	Electrical	remounted screen	

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-2115	10/04/2021	648462	0	B - 50k	carried out b service Replaced belts found leaking water pump	Kobi
T-316	31/03/2021	0	0	Cap	8x multi D caps 8x truck tyre disposal	
T-275	22/03/2021	0	0	New - Drives	Amberstone 11R22.5 Drive	
R-1044	20/03/2021			Tail Lights	Replace blown globes (x3) 24v tail light globes 1hr Labour	
T-295	12/03/2021	0	0	Balance , Strip & Fit, Tyre Pressures	2x strip fit and balance steers plus pressure	
R-1070	12/03/2021	627779	0	Mirrors		
T-294	11/03/2021	0	0	Strip & Fit	1x strip and fit	
R-1027	25/02/2021	0	0	Battery	Fitted with 2x batteries 25/2/21 Torque & Diesel attend call out and jump start. Found okay - Arndell Park 25/2/21	
R-963	11/02/2021			Defect, Number Plate		
R-766	11/02/2021	605242	0	Mirrors	third new mirror fitted, problem still present??? Investigation ongoing	
R-1004	11/02/2021	606226	20	Electrical	job done by jack	
S-1933	10/02/2021	606226	0	A - Fortnightly		
R-969	09/02/2021	606226	0	Exhaust Brake	Booked in to Inland tue 16/2/21. repairs carried out by Inland 9/2/21	
S-1889	23/01/2021	595380	0	C - 150k		
S-1864	23/01/2021	0	0	A - Fortnightly		
S-1482	29/12/2020	578770	0	A - Fortnightly	3ltr engine oil	
R-836	28/12/2020	577275	0	Add Oil		
R-737	03/12/2020	559419	0	Electrical	New window control unit fitted	
T-204	28/11/2020	0	0	Call out fee, Fitting, New, Road Service	1x Michelin 1x truck tyre disposal 1x fitting 1x call out fee 2x road service (after hours) 2x per kilometre	
R-706	19/11/2020	549224		Indicators		
S-866	14/11/2020	546712	0	B - 50k		
R-639	13/11/2020	530964		Engine, Mirrors	New mirror housing and glass fitted. Truck was serviced	
R-690	10/11/2020	542324	0	Dash - Gauges, EBS	Not the Prime Mover problem, its the Trailer	
T-180	05/11/2020	0	0	New	2x Michelin 2x truck tyre disposal	
R-649	28/10/2020	533599	0	Windscreen Washers		
R-650	27/10/2020	532563	0	Headlights		
R-615	20/10/2020	528524		Tail Lights		
R-626	19/10/2020	528524	0	Mirrors		

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-731	17/10/2020	526421	0	A - Fortnightly		
R-611	14/10/2020	524004		Wheel Alignment		
R-610	14/10/2020	524954	0	Tail Lights		
S-770	22/09/2020	508770	0	A - Fortnightly		
R-572	17/09/2020			Alternator, Battery		
O-95	11/09/2020	0	0	CTP		
O-94	11/09/2020	0	0	Registration		
S-593	06/09/2020	497200	0	B - 50k		
S-551	28/07/2020	478054	0	A - Fortnightly		
S-385	14/07/2020	466330	0	A - Fortnightly	Completed A Service	
R-348	24/06/2020			Electrical		
S-268	23/06/2020	448595	0	C - 150k	Completed "C" service.Replaced L/H outer fog light globe repair air fitting	
S-299	23/06/2020	448595	0	C - 150k	Duplicated job with #268 check wheel bearing replaced l/h outer fog light globe repair air fitting	
R-323	19/06/2020			Top Up Oil - Driver	Driver topped up engine oil	
S-689	02/06/2020	430495	0	A - Fortnightly	4ltr oil	
O-73	30/05/2020	0	0	Toll		
S-212	18/05/2020	420459	0	A - Fortnightly	duplicated job card	
T-58	21/04/2020	0	0	Rotate	Rotate on rims	
T-46	21/04/2020	399853	0	Rotate - Steers	steers rotated	
S-147	21/04/2020	399853	0	B - 50k	Steer tyres rotated - HTS 1 x 1922496 oil spinner 1 x 1948921 oil filter 2 x 1699168 fuel filters 1 x 1819795 adblue filter Done by Michael and Dylan	
R-147	03/04/2020	0	0	Battery	Anderson plug fitted by Jack	
S-495	01/04/2020	0	0	A - Fortnightly		
R-142	01/04/2020	388253	0	Air Leak	Air leak located & rectified on r/h/R (small) air tank	
R-60	03/03/2020	366340	0	Drive belts, Lights	Replaced 2 drive belts , Replaced 2 tensioner idler pulley . replaced drivers side head light globe .refit fan & hub .	d
S-16	26/02/2020	361478	0	B - 50k	RH park/indicator lamp in bullbar replaced 2 x steer tyres HTS	
T-14	26/02/2020	0	0	New		
R-291	21/02/2020	333939		Battery, Fog Lights		
S-431	05/02/2020	345253	0	A - Fortnightly		

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-53	05/01/2020	322455	0	D - 300k	completed Interior globes X3 lhs headlight fuse	Yard
S-972	18/12/2019	306508	0	A - Fortnightly	3ltr engine oil	
S-1030	20/11/2019	283982	0	B - 50k		
S-1031	13/11/2019	279262	0	A - Fortnightly	Top up cool + 1.5ltr oil	
R-486	04/11/2019			Defect, Self Clearing	Changed signs to comply DEFECT CLEARED	Yard
S-1032	04/11/2019	271513	0	A - Fortnightly		
R-799	30/10/2019	268039		Lights	Replace rear light bar. Replace LHR guard	
S-1033	30/10/2019	268039	0	A - Fortnightly		
S-1029	16/10/2019	257147	0	A - Fortnightly	Tighten all connections in electrical suzi coils. Replace all tensioners/ idlers & belts ( parts not entered, no part numbers)	
S-1027	23/09/2019	241862	0	B - 50k		
S-1028	06/09/2019	232101	0	A - Fortnightly	3ltr oil	
S-1247	20/08/2019	219333	0	A - Fortnightly		
S-1245	30/07/2019	207484	0	A - Fortnightly	RH headlight globe	
S-1246	22/07/2019	202312	0	B - 50k	LH low beam bulb. Adjust low beam	
S-1598	03/07/2019	188700	0	A - Fortnightly		
S-1599	12/04/2019	130985	0	A - Fortnightly	Replace RH headlight globe Replace LR taillight globe	
S-1600	05/04/2019	126258	0	A - Fortnightly		
S-1652	29/03/2019	120438	0	B - 50k		

Signed: \_\_\_\_\_  
 Name: \_\_\_\_\_  
 Date: \_\_\_\_\_