

Work Order History

Work Order ID	Equipment ID	Material Cost	Trade Cost	Service Cost	Other Costs	Tax Cost	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R140-0110742	1534	0.00	2553.60	0.00	0.00	0.00	2553.60				RENEW CAMSHAFT	25/05/2023	30/06/2023
R140-0110174	1534	311.82	104.40	0.00	0.00	0.00	416.22	1650.21	2143812		LOCATE AND REPAIR COOLANT LEAK	13/05/2023	15/05/2023
R140-0110174	1534	59.26	38.40	0.00	0.00	0.00	97.66				CAMERA MISALIGN	13/05/2023	15/05/2023
R140-0110174	1534	553.13	585.60	0.00	0.00	0.00	1138.73				RENEW NOISEY ALT	13/05/2023	15/05/2023
R155-0020664	1534	589.61	0.00	0.00	0.00	58.96	648.57	648.57	2141060		SERVICE ON 17254771 ADEL DEPOT 10.05.2023 HUBO 2,139,933 01 11006520 - 295/80R22.5 152/148M BS R154 CC 10.0 Retread (recap) Tread Cut or Chunking Qty SERVICES/ACCESSORIES REMARKS / SIZE: 1 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1) 1 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 1) 1 EA Tyre Removed - (Pos: 1) -1 EA Case Condition REPLACE RADIATOR	10/05/2023	18/05/2023
R155-0020589	1534	2063.28	2575.20	0.00	0.00	0.00	4638.48	10175.60	2140388		REPLACE RADIATOR	3/05/2023	16/05/2023
R155-0020589	1534	2742.44	1020.00	0.00	0.00	0.00	3762.44				EXHAUST MANIFOLD GASKETS LEAKING	3/05/2023	16/05/2023
R155-0020589	1534	607.34	252.00	0.00	0.00	0.00	859.34				REPLACE FRONT CAB MOUNTS	3/05/2023	16/05/2023
R155-0020589	1534	198.60	96.00	0.00	0.00	0.00	294.60				REPLACE DRIVERS SIDE WEATHER SHIELD	3/05/2023	16/05/2023
R155-0020589	1534	0.00	48.00	0.00	0.00	0.00	48.00				ALIGN GUARDIAN	3/05/2023	16/05/2023
R155-0020589	1534	572.74	0.00	0.00	0.00	0.00	572.74				REPLACE DAMAGED HEATER VALVE	3/05/2023	16/05/2023
R155-0020462	1534	22.35	590.40	0.00	0.00	0.00	612.75	605.56	2136434		DRIVER REPORTS OF CLUNKING NOISE WHEN TURNING WITH TRAILER	20/04/2023	15/05/2023
R155-0020449	1534	16.58	57.60	0.00	0.00	0.00	74.18	16.58	2136434		SUZI COIL LEAKING AIR	19/04/2023	20/04/2023
R155-0020381	1534	397.25	273.60	0.00	0.00	0.00	670.85	670.85	2130232		AIR BAG LEAKING	13/04/2023	14/04/2023
R155-0020340	1534	58.37	146.40	0.00	0.00	0.00	204.77	204.77	2130232		ENGINE DE-RATING	8/04/2023	4/05/2023
R155-0020060	1534	248.05	252.00	0.00	0.00	0.00	500.05	623.85	2111100		CHECK BRAKE ADJUSTMENT / OPERATION	15/03/2023	23/03/2023
R155-0020060	1534	26.60	100.80	0.00	0.00	0.00	127.40				TRAILER PLUG BROKEN	15/03/2023	23/03/2023
R155-0020048	1534	587.41	0.00	0.00	0.00	58.74	646.15	646.15	2110114		SERVICE ON 17042535 ADEL DEPOT 14-03-2023 HUBO 1 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 02 11006520 - 295/80R22.5 152/148M BS R154 CC 8.0 Not Worth Retreading (NWR Sidewall Cut or Staked Qty SERVICES/ACCESSORIES REMARKS / SIZE: 1 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 2) 1 EA Tyre Removed REPLACE FRONT STEER TYRE	14/03/2023	17/03/2023
R155-0020039	1534	0.00	96.00	0.00	0.00	0.00	96.00	232.96	2108500		REPLACE FRONT STEER TYRE	11/03/2023	16/03/2023
R155-0020039	1534	100.96	36.00	0.00	0.00	0.00	136.96				DRIVERS WINDOW OPERATION INTERMITTANT	11/03/2023	16/03/2023
R155-0019800	1534	474.23	506.40	0.00	0.00	0.00	980.63	626.63	2090625		REPLACE STARTER MOTOR	17/02/2023	21/02/2023
R155-0019728	1534	639.93	1395.60	0.00	0.00	0.00	2035.53	2035.53	2087196		B SERVICE	10/02/2023	14/02/2023

R155-0019734	1534	2221.40	0.00	0.00	0.00	222.14	2443.54	2443.54	2087196	SERVICE ON 16925550 ADEL DEPOT 10-02-2023 HUBO 2116627 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 09 11003134 - 11R22.5 148/145L BS M749II EC CC 6.0 Runout Held by Customer Match Tread Depth or Pattern 10 11003134 - 11R22.5 148/145L BS M749II EC CC 6.0 Runout Held by Customer Match Tread Depth or Pattern 11 11003134 - 11R22.5 148/145L BS M749II EC CC 1.0 Retread (recap) Irregular Wear or Alignment 12 11003134 - 11R22.5 148/145L BS M749II EC CC 6.0 Runout Held by Customer Match Tread Depth or Pattern Qty	10/02/2023	14/02/2023
R155-0019644	1534	241.85	1704.00	12.48	0.00	0.00	1958.33	1958.33	2080096	FRONT DIFF LEAKING	2/02/2023	6/02/2023
R155-0019556	1534	325.00	675.60	0.00	0.00	0.00	1000.60	1823.64	2075060	STOP ENGINE LIGHT DISPLAYED - BREAKDOWN	24/01/2023	25/01/2023
R155-0019556	1534	823.04	0.00	0.00	0.00	0.00	823.04			CAB AIR BAGS LEAKING	24/01/2023	25/01/2023
R155-0019471	1534	0.00	36.00	0.00	0.00	0.00	36.00	0.00	2070241	R/H window not working	18/01/2023	23/01/2023
R155-0019359	1534	20.10	151.20	0.00	0.00	0.00	171.30	162.86	2064060	VOLTMETER NOT WORKING	9/01/2023	11/01/2023
R155-0019338	1534	0.00	60.00	0.00	0.00	0.00	60.00	0.00	2061372	ADJUST ALL BRAKES	5/01/2023	6/01/2023
R155-0019254	1534	0.00	0.00	173.00	0.00	17.30	190.30	190.30	2054276	CAB A/C FAN TRIPPING CIRCUIT BREAKER	23/12/2022	27/01/2023
R155-0019112	1534	250.65	240.00	0.00	0.00	0.00	490.65	486.43	2046713	HEATER CORE LEAKING	10/12/2022	13/12/2022
R155-0018922	1534	0.00	189.60	0.00	0.00	0.00	189.60	821.59	2035805	Release pin is hard to pull and headlights are too high	22/11/2022	5/12/2022
R155-0018922	1534	309.19	322.80	0.00	0.00	0.00	631.99			REPORTED A/C & HEATER FAN NOT WORKING	22/11/2022	5/12/2022
R155-0018788	1534	593.33	1038.00	0.00	0.00	0.00	1631.33	5823.35	2023314	B SERVICE	8/11/2022	18/11/2022
R155-0018788	1534	766.50	300.00	0.00	0.00	0.00	1066.50			INSPECT REAR BRAKES	8/11/2022	18/11/2022
R155-0018788	1534	508.24	807.60	0.00	0.00	0.00	1315.84			REPLACE TORQUE ROD BUSHES	8/11/2022	18/11/2022
R155-0018788	1534	693.68	426.00	690.01	0.00	0.00	1809.69			REPAIR DAMAGED TURNTABLE	8/11/2022	18/11/2022
R155-0018800	1534	22.00	0.00	0.00	0.00	2.20	24.20	24.20	2023314	SERVICE ON 16600024 ADEL DEPOT 08-11-2022 HUBO 10238738 4 EA Torque 33000114 - RE-TORQUE TRUCK WHEEL EA WHEEL (Pos: 5, 8, 9, 12) 2 EA Tyre Rotation TRAILER PLUG BROKEN	8/11/2022	9/11/2022
R155-0018678	1534	8.35	126.00	0.00	0.00	0.00	134.35	126.00	2012327	TRAILER PLUG BROKEN	27/10/2022	28/10/2022
R155-0018615	1534	180.91	30.00	0.00	0.00	0.00	210.91	210.91	2007371	REPLACE HEADLIGHT PROTECTOR	20/10/2022	24/10/2022
R155-0018534	1534	15.95	62.40	0.00	0.00	0.00	78.35	78.35	2001452	Exhaust manifold is leaking	12/10/2022	13/10/2022
R155-0018392	1534	657.80	351.60	0.00	0.00	0.00	1009.40	2294.65	1990203	DRIVERS WINDOW INOPERATIVE	26/09/2022	31/10/2022
R155-0018392	1534	0.00	240.00	0.00	0.00	0.00	240.00			Won't change gears sometimes, Gl light flashing	26/09/2022	31/10/2022
R155-0018392	1534	37.25	84.00	0.00	0.00	0.00	121.25			Fill auto greaser	26/09/2022	31/10/2022
R155-0018392	1534	0.00	30.00	0.00	0.00	0.00	30.00			2 x CAC clamps broken	26/09/2022	31/10/2022
R155-0018392	1534	0.00	894.00	0.00	0.00	0.00	894.00			Driver reported check engine light coming on and when it does the ESC and transmission service lights start flashing VEHICLE WILL NOT SHUTDOWN	26/09/2022	31/10/2022
R155-0018118	1534	21.08	374.40	0.00	0.00	0.00	395.48	609.25	1985173	REPLACE REVERSE SWITCH	24/08/2022	31/08/2022
R155-0018118	1534	85.37	128.40	0.00	0.00	0.00	213.77			VEHICLE WILL NOT SHUTDOWN	24/08/2022	31/08/2022
R155-0018031	1534	0.00	30.00	0.00	0.00	0.00	30.00	0.00	1981232	Brake lights on prime mover are not working	15/08/2022	15/08/2022
R155-0018010	1534	0.00	0.00	750.00	0.00	75.00	825.00	825.00	1978604	Unit 1534 was towed for a coolant leak TOWED FROM PARKING BAY LEAWOOD GARDENS TO DIREK WORKSHOP HEAVY TRADE TOW CHARGE 750.00 75.00 TOTAL: GST TOTAL: 750.00 TOTAL AMOUNT PAYABLE: TOTAL GST INCLUDED: 825.00	11/08/2022	11/08/2022
R155-0017996	1534	176.91	138.90	0.00	0.00	0.00	315.81	587.46	1978556	VEHICLE WILL NOT START	9/08/2022	18/08/2022

R155-0017996	1534	0.00	271.65	0.00	0.00	0.00	271.65			FUEL GAUGE NOT WORKING	9/08/2022	18/08/2022
R155-0017944	1534	29.92	76.50	0.00	0.00	0.00	106.42	29.92	1976644	RADIATOR CAP MISSING	3/08/2022	4/08/2022
R155-0017895	1534	1129.36	0.00	0.00	0.00	112.94	1242.30	1242.29	1976209	SERVICE ON 16213867 ADEL DEPOT 27.07.2022 HUBO 976733	27/07/2022	4/08/2022
										01 11004496 - 295/80R22.5 152/148M BS R154 CC 4.0 Retread (recap) Customer Pull Point 02 11004496 - 295/80R22.5 152/148M BS R154 CC 4.0 Retread (recap) Customer Pull Point 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 1, 2) 2 EA Tyre Removed - (Pos: 1, 2) 2 EA Labour - STANDARD 33000118 - SCHEDULED DEPOT SERVICE 15MIN -2 EA		
R155-0017865	1534	414.18	337.50	0.00	0.00	0.00	751.68	1203.00	1976092	RADIATOR LEAKING	25/07/2022	29/07/2022
R155-0017865	1534	0.00	0.00	451.32	0.00	0.00	451.32			REPAIR SEAT BASE	25/07/2022	29/07/2022
R155-0017821	1534	3.66	39.75	0.00	0.00	0.00	43.41	3.66	1972279	TOP UP COOLANT	19/07/2022	20/07/2022
R155-0017765	1534	22.00	0.00	0.00	0.00	2.20	24.20	24.20	1968486	SERVICE ON 16112995 ADEL DEPOT 04.07.2022 HUBO 963625	12/07/2022	14/07/2022
										2 EA Tyre Rotation 33000085 - ROTATE TBR TYRE (Pos: 2-1, 1-2) 1 EA Labour - STANDARD		
R155-0017710	1534	68.29	11.25	0.00	0.00	0.00	79.54	79.54	1962989	ELECTRICAL SUZI COIL INOPERATIVE	6/07/2022	8/07/2022
R155-0017684	1534	703.01	614.25	0.00	0.00	0.00	1317.26	1317.26	1962989	B SERVICE	4/07/2022	6/07/2022
R155-0017646	1534	75.15	0.00	0.00	0.00	0.00	75.15	75.15	1959165	ELECTRICAL SUZI COIL INOPERATIVE	27/06/2022	27/06/2022
R155-0017571	1534	264.16	84.00	0.00	0.00	0.00	348.16	264.16	1955572	REPAIR DRIVERS AIR SEAT CONTROLS	20/06/2022	20/06/2022
R155-0017361	1534	451.45	116.25	0.00	0.00	0.00	567.70	899.29	1938472	HEATER NOT WORKING	25/05/2022	26/05/2022
R155-0017361	1534	0.00	335.25	0.00	0.00	0.00	335.25			REPORTED SPEED ALARM GOING OFF AT 99 KPH	25/05/2022	26/05/2022
R155-0017324	1534	0.00	0.00	509.09	0.00	50.91	560.00	560.00	1936221	REPLACE BOTH WINDSCREENS	20/05/2022	20/06/2022
R155-0017274	1534	15.00	18.75	0.00	0.00	0.00	33.75	33.75	1931426	TABLET MOUNT BROKEN	13/05/2022	16/05/2022
R155-0017221	1534	93.06	547.50	0.00	0.00	0.00	640.56	378.06	1929041	VEHICLE STOPPED ON SE FREEWAY OUT OF FUEL - CALLOUT	7/05/2022	20/05/2022
R155-0017126	1534	0.00	76.50	0.00	0.00	0.00	76.50	1.50	1923678	FAULT LIGHT ON DASH - DIFFICULTY SELECTING GEARS	26/04/2022	29/04/2022
R155-0017084	1534	239.76	92.25	0.00	0.00	0.00	332.01	329.76	1923197	VEHICLE WILL NOT START - CALL BACK	17/04/2022	20/04/2022
R155-0017072	1534	21.96	20.25	0.00	0.00	0.00	42.21	23.46	1923049	REPLACE WIPER BLADES	13/04/2022	14/04/2022
R140-0096591	1534	273.01	0.00	0.00	0.00	0.00	273.01	273.01	1922456	Re-kit air drier	11/04/2022	13/04/2022
R140-0095928	1534	54.33	264.00	0.00	0.00	0.00	318.33	615.28	1913795	REPLACE HOSE	25/03/2022	25/03/2022
R140-0095928	1534	30.70	266.25	0.00	0.00	0.00	296.95			Replaced reverse alarm to suit COLES spec	25/03/2022	25/03/2022
R140-0095891	1534	9.19	0.00	0.00	0.00	0.00	9.19	9.19	1912842	REPLACE WALK PLATE	24/03/2022	25/03/2022
R140-0095794	1534	2631.97	187.50	0.00	0.00	0.00	2819.47	2819.47	1911193	INSPECT COMPRESSOR OPERATION	22/03/2022	23/03/2022
R122-0050494	1534	0.00	186.00	0.00	0.00	0.00	186.00	0.00	1910444	Truck has air leaks and will not build up air	21/03/2022	21/03/2022
R140-0095120	1534	527.94	937.50	0.00	0.00	0.00	1465.44	750.69	1901550	B SERVICE ES CUMMINS 60,000 KM	11/03/2022	11/03/2022
R140-0095205	1534	3975.60	0.00	0.00	0.00	397.56	4373.16	4373.16	1901550	SERVICE ON 15746169 BRIS DEPOT 10.03.2022 HUBO 903059	10/03/2022	11/03/2022
										11002831 - 11R22.5 146/143L BS M766 POS 5-12 33000084 - FIT TBR TYRE (Pos: 5, 6, 7, 8, 9, 10, 11, 12) 33000241 - SCRAP TYRES TBR (Pos: 10, 11) 33000118 - SCHEDULED DEPOT SERVICE 15MIN		
R140-0094145	1534	0.00	2.25	0.00	0.00	0.00	2.25	2.25	1882952	GUARDIAN DFC MISALIGNED DUE TO DRIVER ABUSE	15/02/2022	15/02/2022
R140-0094145	1534	0.00	177.75	0.00	0.00	0.00	177.75			LOW AIR/INDICATOR AUDIBLE ALARM NOT WORKING	15/02/2022	15/02/2022
R140-0094146	1534	0.00	3.75	0.00	0.00	0.00	3.75	0.00	1882952	Air con is not working	15/02/2022	15/02/2022
R140-0093317	1534	72.99	78.75	0.00	0.00	0.00	151.74	72.99	1865918	RENEW GOV VALVE	27/01/2022	27/01/2022
R122-0048045	1534	0.00	420.00	0.00	0.00	0.00	420.00	0.00	1858455	TRANSMISSION WILL OPERATE CORRECTLY BROKE DOWN AT SUTTONS FOREST ON SATURDAY HAD TO SWAP TRUCKS	17/01/2022	22/01/2022
R130-0036667	1534	112.97	63.75	0.00	0.00	0.00	176.72	538.97	1854422	REPALCED WEAR PADS	10/01/2022	11/01/2022

R130-0036667	1534	0.00	362.25	0.00	0.00	0.00	0.00	362.25			CHECK CODES FLUSH AD BLUE SYSTEM ROAD TEST AFTER AFTERTREATMENT FAULT (FINISHED HOT FLUSH FOR DANIEL)	10/01/2022	11/01/2022
R122-0047632	1534	35.00	0.00	0.00	0.00	0.00	3.50	38.50	38.50	1846353	SERVICE ORDER 15505577 SYDN DEPOT 22.12.2021 ODO 560354	29/12/2021	10/01/2022
R120-0036457	1534	852.58	675.00	0.00	0.00	0.00	0.00	1527.58	1601.08	1841978	3300006 - PLINCTIRF REPAIR TRR (Proc: 10) WATER PUMP LEAKING	22/12/2021	31/12/2021
R120-0036457	1534	62.00	0.00	0.00	0.00	0.00	0.00	62.00			REPLACE TRANSMISSION OIL COOLER LINES	22/12/2021	31/12/2021
R120-0036457	1534	0.00	73.50	0.00	0.00	0.00	0.00	73.50			REPLACE ODD TYRES	22/12/2021	31/12/2021
R122-0047486	1534	481.22	442.50	0.00	0.00	0.00	0.00	923.72	1766.74	1841116	B SERVICE	21/12/2021	22/12/2021
R122-0047486	1534	328.00	103.50	0.00	0.00	0.00	0.00	431.50			REPLACE DRIVE BRAKE SHOES ALL WHEELS	21/12/2021	22/12/2021
R122-0047486	1534	440.02	75.00	0.00	0.00	0.00	0.00	515.02			REPLACE ENGINE MOUNTS	21/12/2021	22/12/2021
R130-0036198	1534	87.64	75.00	0.00	0.00	0.00	0.00	162.64	126.40	1834991	COOLANT LEAK AT COMPRESSOR HEAD FOUND COOLANT LEAK AT COMPRESSOR HEAD FITTING / TIGHTENED FITTING / WASHED / ROADTESTED ALL GOOD TOP UP OIL	13/12/2021	14/12/2021
R122-0046342	1534	798.22	376.50	0.00	0.00	0.00	0.00	1174.72	798.22	1818103	GREASED IMBUSHCHAFT + CLEANED CLIGHT Air con is not working	24/11/2021	24/11/2021
R140-0089514	1534	13.78	0.00	0.00	0.00	0.00	0.00	13.78	13.78	1790761	SUPPLY HUB CAP	14/10/2021	15/10/2021
R122-0044614	1534	335.45	140.25	0.00	0.00	0.00	0.00	475.70	335.45	1786114	replace a/c fan motor	8/10/2021	9/10/2021
R140-0089059	1534	614.92	870.75	0.00	0.00	0.00	0.00	1485.67	2804.78	1780790	B SERVICE E5 CUMMINS 60,000 KM	1/10/2021	6/10/2021
R140-0089059	1534	227.03	2.25	0.00	0.00	0.00	0.00	229.28			REPLACE GEARBOX OILS AND FILTERS	1/10/2021	6/10/2021
R140-0089059	1534	246.46	1.50	0.00	0.00	0.00	0.00	247.96			REPLACE DIFF OILS AND FILTERS	1/10/2021	6/10/2021
R140-0089059	1534	180.91	22.50	0.00	0.00	0.00	0.00	203.41			C SERVICE	1/10/2021	6/10/2021
R140-0089059	1534	36.03	126.00	0.00	0.00	0.00	0.00	162.03			NUMBER PLATE LAMP N/W VARIOUS DASH LIGHTS	1/10/2021	6/10/2021
R140-0089059	1534	480.00	290.25	0.00	0.00	0.00	0.00	770.25			RENEW LEAKING AIR BAGS	1/10/2021	6/10/2021
R140-0089059	1534	118.68	258.75	0.00	0.00	0.00	0.00	377.43			THROUGH SHAFT SEAL LEAKING FRONT INPUT YOKE NUT LOOSE	1/10/2021	6/10/2021
R120-0035454	1534	1281.41	231.00	0.00	0.00	0.00	0.00	1512.41	1281.41	1772447	REPLACE TYRES	21/09/2021	21/09/2021
R140-0088569	1534	295.76	234.00	0.00	0.00	0.00	0.00	529.76	772.24	1771145	REPAIR R/H HCV	18/09/2021	20/09/2021
R140-0088569	1534	275.48	201.00	0.00	0.00	0.00	0.00	476.48			RENEW R/H MUD GUARDS	18/09/2021	20/09/2021
R140-0087641	1534	164.23	18.75	0.00	0.00	0.00	0.00	182.98	182.98	1756049	Headlight lens cover cracked	27/08/2021	27/08/2021
R140-0087645	1534	7.25	27.75	0.00	0.00	0.00	0.00	35.00	7.25	1756049	7 pin plug pins falling out	27/08/2021	28/08/2021
R120-0035242	1534	(461.08)	0.00	0.00	0.00	0.00	(46.11)	(507.19)	(507.19)	1756049	CLAIM 01107 3 UNITS FAILED LOAD TEST AND 1 UNIT DROPPED CELL TMN70ZZ x 4 RFFFR INVOICF 04801513903 (P120-0019674) 4.8.2020	26/08/2021	1/09/2021
R130-0034024	1534	175.28	15.00	0.00	0.00	0.00	0.00	190.28	190.28	1754261	HEADLIGHT COVER BROKEN	23/08/2021	23/08/2021
R120-0034597	1534	6375.81	1905.75	0.00	0.00	0.00	0.00	8281.56	8281.56	1723054	SPARE COOLANT AND REPLACED L/S HEADLAMP PROTECTOR CHECK FOR BOOST LEAK, FOUND FAILED INTERCOOLER, REPLACED WITH NEW, FOUND POOR ENGINE BRAKES, REPLACED SOLENOIDS, WELD UP PRE CLEANER FINS, ROAD TESTED, STILL MAKING NOISE, REPLACED TURBO, TESTED AGAIN, ALL OK, FOUND DOOR WIRING DAMAGED, REMOVED DOOR SKIN AND REPAIR, REASSEMBLED AND TESTED ALL OK	10/07/2021	16/07/2021
R122-0041657	1534	0.00	336.00	0.00	0.00	0.00	0.00	336.00	0.00	1722991	Turbo is making a bad noise like a flutter, left hand sun visor needs new screw in it	9/07/2021	13/07/2021
R140-0085354	1534	988.32	657.00	0.00	0.00	0.00	0.00	1645.32	1416.57	1720300	B SERVICE E5 CUMMINS 60,000 KM	5/07/2021	6/07/2021
R140-0083700	1534	29.80	226.50	0.00	0.00	0.00	0.00	256.30	29.80	1690952	Air con doesn't work	28/05/2021	28/05/2021
R130-0032168	1534	6.75	578.25	0.00	0.00	0.00	0.00	585.00	585.00	1672103	CONNECT TO TECH TOOL, CHECK FOR FAULT CODES CHECK ALL WIRING AND PLUGS FROM FIREWALL TO ECM REPAIR WIRING FOR NOX SENSOR POSITIVE REPLACE RELAY	3/05/2021	4/05/2021
R140-0082305	1534	291.28	112.50	0.00	0.00	0.00	0.00	403.78	291.28	1663059		24/04/2021	24/04/2021
R120-0033755	1534	461.08	0.00	0.00	0.00	0.00	0.00	461.08	0.00	1660957	REPLACE BATTERIES	19/04/2021	20/04/2021
R122-0038292	1534	392.43	481.50	0.00	0.00	0.00	0.00	873.93	2327.49	1658133	serviced	7/04/2021	8/04/2021
R122-0038292	1534	61.49	405.00	0.00	0.00	0.00	0.00	466.49			REPLACE THRUSHAFT SEAL	7/04/2021	8/04/2021
R122-0038292	1534	573.74	144.75	0.00	0.00	0.00	0.00	718.49			REPLACE REAR BRAKE SHOES 2 AXLES	7/04/2021	8/04/2021
R122-0038292	1534	9.83	258.75	0.00	0.00	0.00	0.00	268.58			REPLACED CHECKERPLATE BRACKET	7/04/2021	8/04/2021

R140-0081283	1534	5614.35	0.00	2141.50	0.00	775.59	8531.44	8531.44	1656540	APPROVED BH 1.4.21 PRICE AS PER WORKSHOP PROPOSAL 6510621 Hi Nox faults. Drove vehicle into workshop - Downloaded ECM & carried out pre-checks - T/S fault code 2773 - checked doser pump operation to find dosing at 100ml each time - in spec - Run up on dyno & attempted High Nox reset- failed both times - Completed supply line restriction test. Found line to have 1 PSI of restriction when DEF fluid started to flow - spec is 3 PSI or less - Checked air supply lines to doser pump for damage, kinks or leaks - none found - Checked DEF injector after high idle for 60 seconds for build up or blockages- none found - Checked exhaust restriction. Found it to have 4 PSI. Spec is 9 PSI - Checked truck still had air pressure to complete purge after truck was shut off for 30 seconds - Checked ECM cal & found it to be up to date - Set up exhaust restriction gauge where DEF nozzle is inserted - Carried out SCR catalyst efficiency test & measured exhaust restriction - catalyst failed test - Removed & installed new catalyst - Run up on dyno to confirm correct operation of new catalyst - carried out high Nox reset x3 times- passed each time - Cleared now inactive codes <i>Worked on 8. inserted engine oil etc.</i> CALLOUT FOR HOLE IN AIR TANK	31/03/2021	1/04/2021
R140-0080579	1534	0.00	18.75	0.00	0.00	0.00	18.75	56.32	1646257		18/03/2021	19/03/2021
R140-0080579	1534	0.00	17.25	0.00	0.00	0.00	17.25			GI light flashing on dash	18/03/2021	19/03/2021
R140-0080579	1534	1.57	18.75	0.00	0.00	0.00	20.32			LH indicator light in dash cluster N/W Lights N/W is gauges	18/03/2021	19/03/2021
R140-0080364	1534	1168.53	1824.00	0.00	0.00	0.00	2992.53	2745.03	1646025	LOW BOOST PRESSURES	16/03/2021	18/03/2021
R122-0037738	1534	0.00	114.75	0.00	0.00	0.00	114.75	0.00	1645088	LOSS OF POWER CODE 25	15/03/2021	16/03/2021
R140-0079199	1534	9.52	114.00	0.00	0.00	0.00	123.52	9.52	1629571	HIGH BEAM NOT WORKING	22/02/2021	23/02/2021
R140-0078836	1534	722.25	485.25	0.00	0.00	0.00	1207.50	1207.50	1624430	Right hand windscreen is cracked	16/02/2021	17/02/2021
R120-0033107	1534	0.00	108.75	0.00	0.00	0.00	108.75	0.00	1624025	REPLACE STEER TYRES	15/02/2021	16/02/2021
R130-0030748	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	1613885	DUE FOR A B SERVICE	2/02/2021	2/02/2021
R150-0000040	1534	0.00	0.00	2076.96	0.00	200.10	2277.06	2277.06	1608537	APPRO BH 25.01.21 RO: R510753 16.01.21 CHECK AND REPAIR DEFECT REPORT ***** POSITION THE TRUCK INTO THE WORKSHOP AND INSPECTED THE LISTED DEFECTS. REMOVED THE TEFLON PADS FROM THE TURNTABLE AND REMOVED THE TURNTABLE. REMOVED AND REPLACED THE FEET BUSHES AND LOWERED IT DOWN. REMOVED AND REPLACED THE TURNTABLE JAW. INSTALLED NEW TEFLON PLATES. REMOVED AND REPLACED THE AIR SUZI COIL AS ONE HAD A JOINER IN IT. REMOVED AND REPLACED THE 3RD AXLE GUARDS AS THEY WERE BROKEN. DELIVERED THE TRUCK TO THE RMS FOR INSPECTION. THE TRUCK WAS DEFECTED. REMOVED AND REPLACED THE LEFT HAND DRIVE BOOSTER ON THE SECOND AXLE AS IT WAS LEAKING. CLEARED THE RMS DEFECT. CLEANED UP, CARRIED OUT PAPERWORK AND RETURN THE TRUCK TO SERVICE. ***** Labour LABOUR CHARGES FOR THE FOLLOWING WORK 1,045.73 Parts K127-1116-08A FENDER RED SPRAYSAFE 2 86.36 SK3106/007 *KIT-REPAIR, GREASELESS 6 1 244.65 SK1259 CUSHION-UPPER RUBBER ** 2 109.00 SK2105-25 LOWER-RUBBER CUSHION 2 48.76 SK3221/52Z REPAIR KIT 1 149.56 SK3105/94 GREASELESS WEAR RING KI 1 194.97 SC3MTSTSET SUZI COIL 3MT SHORT TAI 1 50.30 SB3030CCAUS CHAMBER-BRAKE,30/30 TRP 1 48.14 Others WORKSHOP SUPPLIES 1 23.50 Sub Total ExGST: 2,000.97 CHECK AND REPAIR DEFECT REPORT ***** POSITION THE TRUCK INTO THE WORKSHOP AND INSPECTED THE LISTED DEFECTS. REMOVED THE TEFLON PADS FROM THE TURNTABLE AND REMOVED THE TURNTABLE.	25/01/2021	28/01/2021
R120-0032673	1534	80.40	32.25	0.00	0.00	0.00	112.65	80.40	1600366	GUARDIAN ICS LOOSE IN CABIN	12/01/2021	12/01/2021
R130-0030229	1534	588.02	420.00	0.00	0.00	0.00	1008.02	1111.80	1594752	B SERVICE	30/12/2020	4/01/2021
R130-0030229	1534	13.44	99.00	0.00	0.00	0.00	112.44			REPAIR AD BLUE FITTINGS AND LINES	30/12/2020	4/01/2021
R120-0032506	1534	582.58	384.75	0.00	0.00	0.00	967.33	945.48	1589099	A/C COMPRESSOR FAILED	22/12/2020	23/12/2020
R120-0032477	1534	3920.00	159.00	0.00	0.00	0.00	4079.00	3920.00	1587947	REPLACE WORN TYRES	19/12/2020	21/12/2020
R120-0032481	1534	36.32	219.00	0.00	0.00	0.00	255.32	142.82	1587947	AIR CON ONLY WORKS SOMETIMES, NOT COLD - REPLACE WIPERS - ADJUST WASHERS	19/12/2020	21/12/2020
R191-0000168	1534	0.00	0.00	599.09	0.00	59.91	659.00	659.00	1580913	APPROVED BH 11.12.20 13.11.20 CARRY OUT SERVICE	11/12/2020	11/12/2020
R120-0032303	1534	117.14	309.75	0.00	0.00	0.00	426.89	426.89	1573590	REPAIR PARK BRAKE ALARM	3/12/2020	7/12/2020
R120-0032281	1534	120.00	198.75	0.00	0.00	0.00	318.75	159.75	1572728		1/12/2020	2/12/2020
R130-0029402	1534	420.82	153.00	1.28	0.00	0.00	575.10	575.10	1559921	REPLACE REAR TANK	11/11/2020	17/06/2021
R120-0031835	1534	0.00	279.75	0.00	0.00	0.00	279.75	279.75	1541376	CHECK ENGINE LIGHT ON	17/10/2020	20/10/2020

R140-0073849	1534	61.03	0.00	0.00	0.00	0.00	61.03	204.60	1536632		Gearbox oil pressure switch leaking	9/10/2020	10/10/2020
R140-0073849	1534	36.32	107.25	0.00	0.00	0.00	143.57				Replace l.h wiper blade	9/10/2020	10/10/2020
R131-0001426	1534	4.50	0.00	0.00	0.00	0.45	4.95	4.95	1534406		APPROVED BH 8.10.20 \cf0\fs22 wiper head for 1534 please (MTC) \cf1\fs16	8/10/2020	9/10/2020
R122-0033711	1534	417.62	189.75	0.00	0.00	0.00	607.37	1355.04	1534406	13583.00	REPLACE ROCKER COVER GASKET	7/10/2020	8/10/2020
R122-0033711	1534	434.17	313.50	0.00	0.00	0.00	747.67				B-SERVICE E5 CUMMINS	7/10/2020	8/10/2020
R122-0033726	1534	(40.00)	0.00	0.00	0.00	(4.00)	(44.00)	(44.00)	1533920		SERVICE ORDER 13733687 SYDN DDEPOT 07.10.2020 ODO 538066 RUNOUT TYRE 0.0MM - 5-6 33000084 - FIT TBR TYRE - POS 5-6 77000180 SIZE: CASE STOCK 11-22.5 - POS	7/10/2020	8/10/2020
R122-0033342	1534	0.00	16.50	0.00	0.00	0.00	16.50	16.50	1519734		ALIGN CAMERA	17/09/2020	17/09/2020
R120-0031301	1534	0.00	0.00	210.00	0.00	0.00	210.00	210.00	1505404		SIGNWRITING NOT CHARGED ON ORIGINAL JOB REFER - R120-0030902	29/08/2020	31/08/2020
R120-0031251	1534	(461.08)	(507.19)	0.00	0.00	(46.11)	(507.19)	(507.19)	1502100		CLAIM 01159- WARRANTY 3 x BATTERIES WON'T HOLD CHARGE, 1 x BATTERY FAILED LOAD TEST FITTED: 7.5.19 REMOVED 3.8.20	25/08/2020	25/08/2020
R120-0030902	1534	7559.48	13267.50	207.00	0.00	0.00	21033.98	47161.15	1483405	12923.00	C SERVICE \ang1033 SERVICE VIESA. CHANGE STEER OILS. ENGINE TUNE. KIT HORTON. A/C BEARING. KIT AIR DRYER. CHANGE POWER STEER OIL/FILTER. REMOVE RADIATOR STRIP AND CLEAN INHOUSE. REPLACE COOLANT. REPLACE COOLANT FILTER. PRESSURE TEST INTERCOOLER. REPLACE DOSER PUMP. WHEEL ALIGNMENT. WATER PUMP. TURBO. OIL THERMOSTAT. ENGINE BRAKE KIT. STARTER. ALTERNATOR. COMPRESSOR - GOVERNOR VALVE. IDLERS AND TENSIONERS. CLUTCH ECA AND INPUT SHAFT. UPGRADE MUFFLER. TAILSHAFT UNIS. REPLACE STEERING WHEEL. REPLACE STEERING COLUMN. RELOCATE TRANSTECH. REPLACE PHONE MIC. RESECURE COBRA SHIFT ASSEMBLY. REPLACE FLOOR MATS. RESECURE DRIVERS WEATHERSHIELD. RESECURE CAB INNER DOOR SEALS. CLEAN OUT FRIDGE. DETAIL CAB BEHIND SEATS. RESECURE CAB EXTINGUISHER. REPLACE A.C ROUND VENTS. REPLACE FAILED DASH GLOBES AND TELL TAILS. DRIVERS SEAT NEEDS REPAIRS. CLEAN OUT DOG BOXES. TIGHTEN GRAB HANDLES. REPLACE WIPER ARMS & BLADES. BOMB CAB - SMOKE SMELL BAD. REPAIR SIGN WRITING. REPLACE FIRST AID KIT. FRONT GRILL MESH NEEDS REPLACING. RH GRILL PIECE NEEDS REPLACING. REMOUNT HEADLIGHT SURROUND RINGS. CLEAN HEADLIGHT PROTECTORS. HORTON NEEDS REKITTING. ROCKER COVER GASKET LEAKING. RADIATOR FILLER NECK CRACKED. REPAIR ALTERNATOR CABLES CHAFFING CHASSIS. RESECURE ESOC HOSE. REPLACE EXCHANGE PIPE ORINGS. REPLACE DUMP PIPE RUBBERS. GEARBOX COOLER HOSES LEAKING. BONNET CRACKED. ACCESS STEPS CRACKED. RADIATOR CORE LEAKING. REPLACE STEER PINCH BOLT PITMAN ARM. RESECURE TOP HEATER STEER PIPE MOUNT. REPLACE BONNET MOUNT BUSHES. REPLACE TOP STEER PINCH BOLT. REPLACE COOLANT BLEED HOSE. RESECURE HARNESS AROUND FRONT OF ENGINE. RESECURE POWER STEER SUCTION HOSE. REPLACE HOT PIPE P CLAMPS. SEAL UP CRANK SPEED SENSOR. INSPECT FIRE WALL HARNESS AT DOG COLLAR. RESECURE A/C HOSES. RESECURE OEM HARNESS. TIDY HARNESS BELOW INTAKE. REPLACE SUMP GASKET. RESEAL BLOCK SIDE COVER BESIDE DUMP PIPE. POLISH BUMPER REMOVE DG STICKER. TIGHTEN STEER MUDFLAPS. REPLACE MISSING BUMPER BOLTS AND REALIGN. RETENSION STEER BOLTS. REPLACE FRONT ENGINE MOUNTS. POWERSTEER GASKET LEAKING. REPLACE HEADLIGHT PROTECTORS. REPAIR INTAKE ON BONNET (RUBBER). AIR LEAKS: TREDLE VALVE BLACK & RED HOSE FITTINGS. DASH 12 COMP HOSE FAILED. HORTON SOLENOID 90DEG JOINER FITTING LEAKING. CAB BAG LH INLET T FITTING. SPRING BRAKE PPV VALVE. PPV REAR VALVE LEAKING. FRONT DRIVE RH REAR BAG LEAKING. RH DRAIN COCK (DOUBLE CHECK TANK) LEAKING. RESEAL DOUBLE CHECK VALVE. REAR TANK SUPPLY HOSE FITTING. RH RIDE HEIGHT VAVLE SUPPLY T & SPACER LEAKING. STEER ABS VALVE LH OUTLET 90 DEG FITTING. AUTO GREASER LEAK. REMOUNT AUTO GREASER AWAY FROM CAB. REPLACE TANK STRAP RUBBERS. POLISH FUEL TANKS.	23/07/2020	7/08/2020
R120-0030902	1534	2375.64	894.75	0.00	0.00	0.00	3270.39				REPLACE DOSER PUMP AND FILTERS	23/07/2020	7/08/2020
R120-0030902	1534	1576.44	0.00	0.00	0.00	0.00	1576.44				REPLACE POWER STEERING OIL & FILTER. REPLACE STEER HUB OILS. REPLACE PITMAN ARM PINCH BOLT AND TENSION	23/07/2020	7/08/2020
R120-0030902	1534	726.27	0.00	0.00	0.00	0.00	726.27				CARRY OUT ENGINE TUNE. REPLACE ENGINE BRAKE KIT. INSPECT ROCKER SHAFTS AND CAMSHAFT FOR WEAR	23/07/2020	7/08/2020
R120-0030902	1534	2096.18	0.00	0.00	0.00	0.00	2096.18				REKIT HORTON FAN REPLACE ALL BELTS & TENSIONERS	23/07/2020	7/08/2020
R120-0030902	1534	26.51	0.00	0.00	0.00	0.00	26.51				REPLACE A/C COMPRESSOR	23/07/2020	7/08/2020
R120-0030902	1534	273.01	0.00	0.00	0.00	0.00	273.01				REKIT AIR DRYER	23/07/2020	7/08/2020
R120-0030902	1534	251.02	0.00	0.00	0.00	0.00	251.02				REPLACE OIL & COOLANT THERMOSTATS	23/07/2020	7/08/2020
R120-0030902	1534	443.31	0.00	0.00	0.00	0.00	443.31				R/R RADIATOR STRIP AND CLEAN IN HOUSE. REPLACE COOLANT AND FILTER. PRESSURE TEST INTERCOOLER	23/07/2020	7/08/2020
R120-0030902	1534	1039.25	0.00	0.00	0.00	0.00	1039.25				REPLACE WATER PUMP	23/07/2020	7/08/2020
R120-0030902	1534	765.70	54.75	0.00	0.00	0.00	820.45				REPLACE STARTER MOTOR	23/07/2020	7/08/2020
R120-0030902	1534	2605.45	0.00	0.00	0.00	0.00	2605.45				REPLACE AIR COMPRESSOR & D2 GOVERNOR VALVE	23/07/2020	7/08/2020
R120-0030902	1534	3784.45	0.00	0.00	0.00	0.00	3784.45				REPLACE TURBO	23/07/2020	7/08/2020
R120-0030902	1534	3220.21	522.75	0.00	0.00	0.00	3742.96				INSPECT BONNET AND GRILLE FOR DAMAGE REPLACE WORN BONNET MOUNTS	23/07/2020	7/08/2020
R120-0030902	1534	32.92	519.75	0.00	0.00	0.00	552.67				POLISH WHEELS	23/07/2020	7/08/2020
R120-0030902	1534	4918.81	0.00	0.00	0.00	0.00	4918.81					23/07/2020	7/08/2020
R122-0032073	1534	45.00	31.50	0.00	0.00	0.00	76.50	76.50	1475602		REPLACE SUZY COILS	15/07/2020	15/07/2020
R140-0070787	1534	785.21	813.75	0.00	0.00	0.00	1598.96	1598.96	1474774	12805.00		13/07/2020	14/07/2020
R140-0070798	1534	0.00	0.00	288.61	0.00	28.86	317.47	317.47	1474773		REPLACE FITTINGS	13/07/2020	13/07/2020
R140-0070654	1534	140.00	277.50	0.00	0.00	0.00	417.50	417.50	1470921		CHECK OVER REAR SUSPENSION	8/07/2020	9/07/2020
R140-0069609	1534	3.51	0.00	0.00	0.00	0.00	3.51	3.51	1453130		RENEW WIPER BLADES	11/06/2020	12/06/2020
R140-0069543	1534	1010.00	0.00	0.00	0.00	101.00	1111.00	1111.00	1451389		SERVICE ORDER 13005135 BRIS DEPOT 09.06.2020 ODO 456178 11001553 - 295/80R22.5 152/148M BS R150 POS 1-2 33000051 - BALANCE TBR - POS 1-2 33000084 - FIT TBR TYRE POS 1-2 33000370 - TYRE HELD FOR RUNOUT POS 1-2	9/06/2020	10/06/2020
R140-0069250	1534	70.00	24.00	0.00	0.00	0.00	94.00	94.00	1448641		RENEW SD CARD	3/06/2020	3/06/2020
R140-0069047	1534	54.24	84.75	0.00	0.00	0.00	138.99	138.99	1448641		KEY SNAPPED OFF	29/05/2020	29/05/2020
R140-0067070	1534	6233.85	2813.25	0.00	0.00	0.00	9047.10	9047.10	1419216	12070.00		9/04/2020	16/04/2020
R140-0067070	1534	0.00	0.00	0.00	0.00	0.00	0.00				REPAIR AIR LEAKS	9/04/2020	16/04/2020
R140-0066278	1534	63.50	96.00	0.00	0.00	0.00	159.50	159.50	1402051		7 PIN LEAD	19/03/2020	20/03/2020
R122-0029329	1534	3520.00	0.00	0.00	0.00	352.00	3872.00	3872.00	1392502		SERVICE ORDER 12873319 SYDNEY DEPOT 06.03.2020 ODO 387208 POS 5-12	6/03/2020	10/03/2020
R140-0065560	1534	72.71	60.00	0.00	0.00	0.00	132.71	132.71	1387640		CHECK OVER COOLING SYSTEM	29/02/2020	2/03/2020
R140-0065313	1534	45.00	75.00	0.00	0.00	0.00	120.00	120.00	1383707		RENEW SUZI LEADS	24/02/2020	25/02/2020
R140-0065075	1534	25.00	201.75	0.00	0.00	0.00	226.75	226.75	1381490		ENGINE LIGHT ON DASH	18/02/2020	18/02/2020

R122-0028969	1534	860.00	0.00	0.00	0.00	86.00	946.00	946.00	1378704	2 X 295/80R22.5 R150 POSITION 1,2 2 X FIT 2 X TRADES FTSD-12797705	13/02/2020	14/02/2020
R122-0028971	1534	50.00	0.00	0.00	0.00	5.00	55.00	55.00	1378704	2 X BALANCE POSITION 1,2 FTSD-12797786	13/02/2020	14/02/2020
R122-0028942	1534	13.34	241.50	0.00	0.00	0.00	254.84	254.84	1378183	CAB COOLER NOT COLD	12/02/2020	12/02/2020
R140-0063990	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	1368264	CANT LOG INTO SENTINEL	30/01/2020	30/01/2020
R122-0028573	1534	398.32	165.00	0.00	0.00	0.00	563.32	1219.68	1361904	11303.00 RELINE ALL DRIVE BRAKES & REPLACE R/H/R BRAKE DRUM	22/01/2020	23/01/2020
R122-0028573	1534	455.26	151.50	0.00	0.00	0.00	606.76			B-SERVICE E5 CUMMINS	22/01/2020	23/01/2020
R122-0028573	1534	13.60	36.00	0.00	0.00	0.00	49.60			REPLACE HEADLIGHT GLOBES	22/01/2020	23/01/2020
R156-0008515	1534	142.34	122.25	0.00	0.00	0.00	264.59	264.59	1356824	Replace turntable pads	17/01/2020	19/01/2020
R122-0028388	1534	18.10	57.75	0.00	0.00	0.00	75.85	75.85	1354674	BUNK COOLER NOT WORKING	14/01/2020	14/01/2020
R130-0024189	1534	210.37	0.00	0.00	0.00	0.00	210.37	210.37	1351521	SUZIE COILS	10/01/2020	10/01/2020
R130-0024154	1534	0.00	0.00	638.30	0.00	63.83	702.13	702.13	1350375	8.1.20 APPROVED BH 043 \cf0 BREAKDOWN BREAKDOWN AFTER HOURS CALLOUT \b \$560.00\b0 The following breakdown repair for Lindsay Transport, to T409SAR Kenworth Truck, Chassis# 6F500000FA455323, Rego#XN92HC included: . * Technician received a call from Lindsay Transport reporting breakdown * Customer advised of broken exhaust * Technician advised driver to continue to dealership * Technician travelled to breakdown location at United Service Station, Wodonga, Vic * Inspect vehicle to diagnose repair * Located that exhaust had fallen off but clamp still intact * Loosen components & install exhaust * Tension, test, confirm & quality check * Return vehicle to service * Technician returned to dealership . TRAVEL: NO TRAVEL REQUIRED . 000kms @ \$1.40p/km (excluding gst) . AH CALLOUT TECHNICIAN (JWL) \b \$50.00 \b0 . \b \$10.00 \$18.30 \b18 Sub Total for All: Rounding: GST: Total: \b0 \$0.00 \$63.83 \$702.13 \cf1\2\516	8/01/2020	12/02/2020
R130-0024105	1534	59.64	107.25	0.00	0.00	0.00	166.89	166.89	1349595	check for exhaust leak	7/01/2020	8/01/2020
R130-0023986	1534	(45.00)	0.00	0.00	0.00	(4.50)	(49.50)	(49.50)	1347375	1 X RUNOUT POSITION 10 1 X FIT 1 X TRADES FTSD-12618083	30/12/2019	7/01/2020
R130-0023839	1534	0.00	216.00	0.00	0.00	0.00	216.00	216.00	1338236	service light flashing	16/12/2019	16/12/2019
R155-0010097	1534	0.00	54.75	0.00	0.00	0.00	54.75	54.75	1335320	DRIVERS SEAT BELT DAMAGED	13/12/2019	17/12/2019
R130-0023730	1534	0.00	16.50	0.00	0.00	0.00	16.50	78.00	1332792	Driving seat doesn't lock in just keeps rockin	10/12/2019	11/12/2019
R130-0023730	1534	0.00	61.50	0.00	0.00	0.00	61.50			GUARDIAN SYSTEMS	10/12/2019	11/12/2019
R130-0023467	1534	388.53	381.00	242.51	0.00	0.00	1012.04	1012.04	1322900	LOW BOOST	25/11/2019	28/11/2019
R140-0061810	1534	24.37	176.25	0.00	0.00	0.00	200.62	200.62	1319634	CAC CHECK OVER	22/11/2019	22/11/2019
R140-0061753	1534	0.00	331.50	9.52	0.00	0.00	341.02	341.02	1318778	AIR CON NOT BLOWING COLD AIR	21/11/2019	22/11/2019
R140-0061479	1534	0.00	0.00	3111.35	0.00	3111.12	34222.47	34222.47	1314947	APPROVED JB 13.11.19 ENGINE REBUILD DUE TO AGE AND KLMS-FUEL IN COOLANT-OIL LEAK AT REAR REGO: 222VOK KLMS: 1297119 HRS: 18185	13/11/2019	20/11/2019
R140-0061098	1534	917.90	429.75	0.00	0.00	0.00	1347.65	1347.65	1310984	AC NOT WORKING, VISA UNIT LEAKING WATER WHEN TURNED ON - SOAKING THE MATTRESS	1/11/2019	4/11/2019
R122-0026787	1534	0.00	37.50	0.00	0.00	0.00	37.50	37.50	1303739	CHECK ENGINE LIGHT IS ON AND TRUCK IS DE RATING	21/10/2019	22/10/2019
R140-0060406	1534	466.82	355.50	0.00	0.00	0.00	822.32	2074.48	1302419	10448.00 ENGINE MOUNT REPLACED BY CUMMINS WACOL	15/10/2019	19/10/2019
R140-0060406	1534	755.66	496.50	0.00	0.00	0.00	1252.16				15/10/2019	19/10/2019
R140-0060353	1534	25.76	37.50	0.00	0.00	0.00	63.26	63.26	1301532	TRUCK SHUTTING DOWN - NO EXHAUST BRAKE	12/10/2019	12/10/2019
R149-0000816	1534	0.00	0.00	1482.38	0.00	148.24	1630.62	1630.62	1299597	4.10.19 1534 REGO 222VQK KLMS 1288365 BREAKDOWN OVERHEATING WATER PUMP & BELTS REMOVED AND REPLACED THE COOLANT THERMOSTAT REPLACED RADIATOR CAP AND MAIN DRIVE BELT RENEW 7 PIN PLUG	10/10/2019	11/10/2019
R140-0059681	1534	6.53	15.00	0.00	0.00	0.00	21.53	21.53	1287100	UHF MIC NOT WORKING TO WELL	24/09/2019	24/09/2019
R122-0026248	1534	0.00	37.50	0.00	0.00	0.00	37.50	37.50	1286139	COOLANT LEAKS	23/09/2019	23/09/2019
R140-0059379	1534	32.22	228.00	0.00	0.00	0.00	260.22	951.51	1280056	LEAKING COOLANT	16/09/2019	17/09/2019
R140-0059379	1534	691.29	0.00	0.00	0.00	0.00	691.29			COOLANT IN FUEL SYSTEM	16/09/2019	17/09/2019
R140-0059284	1534	140.28	129.75	0.00	0.00	0.00	270.03	270.03	1276847	L/H STEER HUB CAP LEAK	12/09/2019	13/09/2019
R140-0059163	1534	5.25	1.50	0.00	0.00	0.00	6.75	6.75	1275068	R/H INDICATOR NOT WORKING	10/09/2019	10/09/2019
R140-0058675	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	1265480	25.8.19 1534 REGO 222VQK KLMS 257388 \cf0\520 Repair accident damage caused by driver overshooting trailer when coupling up. Replaced 7 pin trailer plug and shorten lead to removed damaged wiring Replaced fitting at end of red suzi coil and shorten to remove damaged air line Remove damaged turntable pull bar and replace with 2nd hand item Test coupled trailer to verify repairs. \cf1\2\516	29/08/2019	30/08/2019
R306-0000114	1534	0.00	0.00	250.50	0.00	25.05	275.55	275.55	1263713	L/H STEER HUB LEAKING	27/08/2019	28/08/2019
R140-0058484	1534	531.11	737.25	0.00	0.00	0.00	1268.36	1268.36	1263155	RENEW HEADLIGT PROTECTOR	26/08/2019	28/08/2019
R140-0058235	1534	161.91	69.75	0.00	0.00	0.00	231.66	231.66	1257326	7 pin socket needs replacing	19/08/2019	20/08/2019
R140-0057847	1534	5.96	54.00	0.00	0.00	0.00	59.96	59.96	1247406	RENEW R/H WINDSCREEN	7/08/2019	13/08/2019
R140-0057692	1534	508.64	96.00	0.00	0.00	0.00	604.64	604.64	1245350	REPLACE GEARBOX OILS AND FILTERS	3/08/2019	5/08/2019
R140-0057388	1534	6549.84	2020.50	25.27	0.00	0.00	8595.61	9957.72	1242701	9548.00 REPLACE DIFF OILS AND FILTERS	29/07/2019	1/08/2019
R140-0057388	1534	262.26	0.00	0.00	0.00	0.00	262.26			RENEW LEAKING RADIATOR	29/07/2019	1/08/2019
R140-0057388	1534	334.10	24.75	0.00	0.00	0.00	358.85			SERVICE ON 12175459 BRIS DEP 29.7.19 HUBO 237749 POS 1-2	29/07/2019	30/07/2019
R140-0057388	1534	0.00	741.00	0.00	0.00	0.00	741.00			REPLACE BLOWN HEADLIGHT - A LOT OFF TELL TAILS IN THE DASH NOT WORKING - CHECK ALL DASH LIGHTS	29/07/2019	1/08/2019
R140-0057421	1534	960.00	0.00	0.00	0.00	96.00	1056.00	1056.00	1242466	CHECK ENGINE LIGHT COMING ON - ENGINE SURGING	22/07/2019	22/07/2019
R140-0057117	1534	54.23	17.25	0.00	0.00	0.00	71.48	71.48	1236698	RENEW WIPER BLADES	15/07/2019	16/07/2019
R140-0056825	1534	117.28	177.75	0.00	0.00	0.00	295.03	295.03	1231276	RENEW HOOD STRUT	10/07/2019	11/07/2019
R140-0056702	1534	22.51	0.00	0.00	0.00	0.00	22.51	22.51	1226907	SERVICE ON 12068555 BRIS DEP 28.6.19 HUBO 213700 POS 5-8	5/07/2019	6/07/2019
R140-0056537	1534	36.32	0.00	0.00	0.00	0.00	36.32	36.32	1223478	RENEW WIPER BLADES	1/07/2019	2/07/2019
R140-0056269	1534	326.73	0.00	0.00	0.00	0.00	326.73	326.73	1220011	RENEW HOOD STRUT	28/06/2019	2/07/2019
R140-0056220	1534	1760.00	0.00	0.00	0.00	176.00	1936.00	1936.00	1217771	24.6.19 1534 SERIAL NO AND SIM TBA AS PER BILLY GUARDIAN INSTALLATION	26/06/2019	26/06/2019
R140-0056074	1534	219.80	240.00	0.00	0.00	0.00	459.80	459.80	1215853		24/06/2019	26/06/2019
R140-0055980	1534	0.00	0.00	500.00	0.00	50.00	550.00	550.00	1214583		24/06/2019	8/07/2019
R140-0055991	1534	22.51	0.00	0.00	0.00	0.00	22.51	22.51	1214583		24/06/2019	25/06/2019
R140-0055890	1534	32.52	0.00	0.00	0.00	0.00	32.52	32.52	1210507		20/06/2019	21/06/2019
R140-0055090	1534	45.35	62.25	0.00	0.00	0.00	107.60	107.60	1193543	TOP UP ENGINE OIL	29/05/2019	30/05/2019
R140-0054640	1534	25.62	101.25	0.00	0.00	0.00	126.87	126.87	1184695	LEAKING COOLANT OUT OF HEATER CORE	17/05/2019	17/05/2019
R140-0054661	1534	16.75	0.00	0.00	0.00	0.00	16.75	16.75	1184695	top up coolant bottle	17/05/2019	18/05/2019

R140-0054548	1534	0.00	81.00	0.00	0.00	0.00	0.00	81.00	81.00	1183255	GEARBOX IS HAVING TROUBLE CHANGING GEARS UNDER LOAD, ,DOWN ON POWER, CHECK CODES	15/05/2019	15/05/2019
R140-0054414	1534	78.00	0.00	0.00	0.00	7.80	85.80	85.80	1180525	2 X WHEEL BALANCE POSITION 1,2 2 X FLIP ON RIM FTSD-11891706	10/05/2019	13/05/2019	
R122-0023899	1534	0.00	27.75	0.00	0.00	0.00	27.75	27.75	1177749	OVESPEED ALARM NOT WORKING	9/05/2019	10/05/2019	
R140-0054242	1534	1780.00	0.00	0.00	0.00	178.00	1958.00	1958.00	1177749	SERVICE ON 11883008. BRIS DEP 8.5.19 HUBO 2133660 POS 9-12	8/05/2019	9/05/2019	
R140-0054135	1534	1450.17	793.50	1018.49	0.00	0.00	3262.16	4550.87	1182189	8709.00 FLAT BATTERIES - TOOK 7LTRS OF COOLANT	7/05/2019	14/05/2019	
R140-0054135	1534	275.46	974.25	0.00	0.00	0.00	1249.71				7/05/2019	14/05/2019	
R140-0054135	1534	0.00	39.00	0.00	0.00	0.00	39.00				7/05/2019	14/05/2019	
R140-0053701	1534	0.00	0.00	200.00	0.00	20.00	220.00	220.00	1168367	IGNITION IS PLAYING UP THE TRUCK WON'T SHUT DOWN	23/04/2019	23/05/2019	
R140-0053348	1534	200.99	585.75	0.00	0.00	0.00	786.74	786.74	1159700	PO REQUESTED BY BH 23.4.19 - CODE: 036-008-030 \cf0\fs22 IPA inspections-\cf1\fs16 \f2	11/04/2019	13/04/2019	
R140-0052354	1534	23.35	0.00	0.00	0.00	0.00	23.35	23.35	1141072	RENEW WALK PLATE BRACKET	19/03/2019	19/03/2019	
R140-0052143	1534	850.00	0.00	0.00	0.00	85.00	935.00	935.00	1135512	1 X ETA 74715 1 X 295/80R22.5 R150 POSITION 2 1 X FIT 1 X SCRAP	13/03/2019	14/03/2019	
R140-0051973	1534	75.62	507.00	0.00	0.00	0.00	582.62	605.97	1133743	BRIDGESTONE SALISBURY-74715 TRUCK HAS BAD AIR LEAK CAUSING BRAKE AND GEARBOX ISSUES	9/03/2019	12/03/2019	
R140-0051973	1534	23.35	0.00	0.00	0.00	0.00	23.35				9/03/2019	12/03/2019	
R140-0051921	1534	0.00	47.25	0.00	0.00	0.00	47.25	47.25	1133003	a/c not working	8/03/2019	8/03/2019	
R140-0051852	1534	505.00	0.00	0.00	0.00	50.50	555.50	555.50	1130802	SERVICE ON 11704281 BRIS DEP 6.3.19 HUBO 10127660 POS 1	6/03/2019	8/03/2019	
R120-0023890	1534	126.90	1315.50	0.00	0.00	0.00	1442.40	3381.96	1119703	7855.00 GEARBOX ISSUES	18/02/2019	19/02/2019	
R120-0023890	1534	786.65	745.50	0.00	0.00	0.00	1532.15			CARRY OUT C SERVICE CHECKLIST	18/02/2019	19/02/2019	
R120-0023890	1534	407.41	0.00	0.00	0.00	0.00	407.41			B SERVICE - CUMMINS E5	18/02/2019	19/02/2019	
R156-0006157	1534	0.00	0.00	234.73	0.00	23.47	258.20	258.20	1119609	APPROVED BY BH 18.2.19 CODE: 026 \cf0 Transmission service light on Connected laptop and read fault codes in Service Ranger. Found one inactive code for ABS CAN message. Followed trouble shooting and checked ABS codes. No active. Checked hill start assist switch operation. Switch okay. Inspected transmission harness. Found water in plugs. Cleaned out water and refitted. No faults found. Returned to service. REGO: 222VQK KLMS: 110,562 \cf1\fs2	18/02/2019	18/02/2019	
R140-0050871	1534	0.00	48.75	0.00	0.00	0.00	48.75	48.75	1114495	SERVICE LIGHT ON GEARBOX -	12/02/2019	12/02/2019	
R140-0050730	1534	55.76	45.00	0.00	0.00	0.00	100.76	100.76	1109807	CHECK TRANS FLUID LEVEL	8/02/2019	8/02/2019	
R140-0050591	1534	11.27	0.00	0.00	0.00	0.00	11.27	11.27	1107067	RENEW HUB CAP	6/02/2019	6/02/2019	
R120-0023686	1534	424.84	140.25	0.00	0.00	0.00	565.09	565.09	1103713	CAN NOT TURN WIPERS OFF	1/02/2019	4/02/2019	
R140-0050199	1534	0.00	191.25	0.00	0.00	0.00	191.25	232.75	1101504	AIR CON BLOWNS HOT AIR	29/01/2019	30/01/2019	
R140-0050199	1534	41.50	0.00	0.00	0.00	0.00	41.50			10 LTS OIL	29/01/2019	30/01/2019	
R140-0050159	1534	5.72	20.25	0.00	0.00	0.00	25.97	25.97	1097987	park brake alarm fault	25/01/2019	25/01/2019	
R140-0049853	1534	0.00	132.00	0.00	0.00	0.00	132.00	690.64	1093977	LOSING AIR QUICKLY - AIR CON NOT WORKING AFTER HALF HOUR	21/01/2019	24/01/2019	
R140-0049853	1534	89.89	468.75	0.00	0.00	0.00	558.64			INSPECT A/C OP	21/01/2019	24/01/2019	
R140-0049808	1534	7.12	0.00	0.00	0.00	0.00	7.12	7.12	1091891		18/01/2019	18/01/2019	
R122-0021805	1534	490.97	78.75	0.00	0.00	0.00	569.72	569.72	1088924	FAN MOTOR INOPERATIVE	15/01/2019	16/01/2019	
R140-0049475	1534	529.50	1104.75	208.65	0.00	0.00	1842.90	2253.90	1085560	CENTRE CONSOLE LOOSE - WILL SHAKE INTO NETURAL - CHECK FAN BELTS	9/01/2019	11/01/2019	
R140-0049475	1534	34.50	201.75	0.00	0.00	0.00	236.25			RENEW HEATER TAP	9/01/2019	11/01/2019	
R140-0049475	1534	0.00	174.75	0.00	0.00	0.00	174.75			REPAIR AUTO GREASER LINES	9/01/2019	11/01/2019	
R140-0049292	1534	0.00	37.50	0.00	0.00	0.00	37.50	37.50	1084134	OIL LEAK L.H SIDE ENGINE	4/01/2019	7/01/2019	
R140-0049263	1534	33.63	0.00	0.00	0.00	0.00	33.63	33.63	1083426	RENEW TANK STRAINER	3/01/2019	3/01/2019	
R140-0048981	1534	20.75	0.00	0.00	0.00	0.00	20.75	20.75	1076215		21/12/2018	21/12/2018	
R122-0021458	1534	364.99	88.50	0.00	0.00	0.00	453.49	775.24	1075661	REPLACE A/C COMPRESSOR + RECIEVER DRIER	20/12/2018	21/12/2018	
R122-0021458	1534	0.00	0.00	321.75	0.00	0.00	321.75			GUYS AUTO ELECTRICS TO REGAS AIR CON AFTER SEIZED COMPRESSOR	20/12/2018	21/12/2018	
R122-0021393	1534	920.00	0.00	0.00	0.00	92.00	1012.00	1012.00	1073332	2 X 295/80R22.5 R150 POSITION 1,2 2 X FIT 2 X TRADES 2 X RTT EQUAL FTSD-11485320	17/12/2018	18/12/2018	
R130-0018085	1534	11.27	0.00	0.00	0.00	0.00	11.27	11.27	1073332	AIR CON IS NOT WORKING DUE TO A/C CLUTCH HAS FAILED	17/12/2018	17/12/2018	
R122-0021346	0.00	18.75	18.75	0.00	0.00	0.00	18.75	18.75	1069573	REPLACE STEER TYRES	13/12/2018	15/12/2018	
R130-0017977	1534	5.30	18.75	0.00	0.00	0.00	24.05	24.05	1067395	REPLACED TRAILER PLUG	11/12/2018	11/12/2018	
R122-0021223	1534	34.00	0.00	0.00	0.00	3.40	37.40	37.40	1063417	1 X FLIP ON RIM POSITION 1 2 X ROTATION POSITION 2-1 1-2 FTSD-11458667	7/12/2018	12/12/2018	
R122-0021188	1534	551.26	159.00	0.00	0.00	0.00	710.26			B-SERVICE E5 CUMMINS	6/12/2018	6/12/2018	
R122-0021188	1534	152.94	196.50	0.00	0.00	0.00	349.44			N/S/F RELINE	6/12/2018	6/12/2018	
R122-0021188	1534	184.10	36.00	0.00	0.00	0.00	220.10			REPLACE R/H/R AIR BAG	6/12/2018	6/12/2018	
R130-0017827	1534	152.51	54.00	0.00	0.00	0.00	206.51	870.26	1059759	REPLACE EXHAUST FLEX	3/12/2018	3/12/2018	
R130-0017827	1534	540.00	123.75	0.00	0.00	0.00	663.75			NAVIGATION SYSTEM - GPS	3/12/2018	3/12/2018	
R130-0017695	1534	10.45	127.50	0.00	0.00	0.00	137.95	219.60	1053875	CHECK AIR LEAKS	26/11/2018	28/11/2018	
R130-0017695	1534	81.65	0.00	0.00	0.00	0.00	81.65			CHECK SPEED AND OVSPEED ALARM	26/11/2018	28/11/2018	
R130-0017695	1534	0.00	0.00	0.00	0.00	0.00	0.00			BAD AIR LEAKS	26/11/2018	28/11/2018	
R122-0020842	1534	43.22	56.25	0.00	0.00	0.00	99.47	99.47	1043625	REPLACE BONNET LATCH	15/11/2018	16/11/2018	
R130-0017513	1534	116.52	13.50	0.00	0.00	0.00	130.02	130.02	1040988	CHECK TRAILER LIGHTS	12/11/2018	13/11/2018	
R140-0047052	1534	394.88	668.25	177.55	0.00	0.00	1240.68	1466.90	1038733	CHECK ENG FAULT CODES	9/11/2018	15/11/2018	
R140-0047052	1534	226.22	0.00	0.00	0.00	0.00	226.22				9/11/2018	15/11/2018	
R122-0020621	1534	1760.00	0.00	0.00	0.00	176.00	1936.00	1936.00	1032169	4 X 11R22.5 M749 POSITION 5,6,7,8 4 X FIT 4 X TRADES FTSD-11343213	2/11/2018	5/11/2018	
R140-0046497	1534	1925.00	0.00	0.00	0.00	192.50	2117.50	2117.50	1028167	4 X 11R22.5 M749 POSITION 9,10,11,12 4 X FIT 1 X SCRAP 2 X RUNOUT 1 X TRADES FTSD-11324300	29/10/2018	2/11/2018	
R122-0020457	1534	43.33	2.25	0.00	0.00	0.00	45.58	45.58	1025519	BRAKE LIGHTS INOP	25/10/2018	25/10/2018	
R122-0020312	1534	20.00	0.00	0.00	0.00	2.00	22.00	22.00	1017890	2 X TYRE ROTATION POSITION 2-1 1-2 FTSD-11287045	17/10/2018	19/10/2018	
R130-0016875	1534	340.11	78.75	0.00	0.00	0.00	418.86	418.86	1004350	flickering	2/10/2018	2/10/2018	
R122-0020003	1534	510.54	288.75	0.00	0.00	0.00	799.29	2097.43	1001187	B-SERVICE E5 CUMMINS	27/09/2018	27/09/2018	
R122-0020003	1534	227.62	151.50	0.00	0.00	0.00	379.12			RELINE BOTH R/H DRIVE BRAKE	27/09/2018	27/09/2018	
R122-0020003	1534	643.77	170.25	0.00	0.00	0.00	814.02			O/HAUL HORTON FAN	27/09/2018	27/09/2018	
R122-0020003	1534	0.00	105.00	0.00	0.00	0.00	105.00			REPAIR VARIOUS LIGHTS	27/09/2018	27/09/2018	
R140-0045286	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	1001187	HORTON FAN IS STUCK ON ALL THE TIME	27/09/2018	27/09/2018	

R122-0019981	1534	0.00	0.00	463.64	0.00	46.36	510.00	510.00	1000000	20.9.18 1534 KLMS 991395 \cf0\fs17 Service call to check engine fan on constantly with air conditioner operation. Check pressures and engine fan switch operation. Degas and check gas amount in system. Regas with minimal amount and fan still operating frequently. Remove dash and combo Remove evaporator core and replace faulty TX valve. Reassemble unit and replace receiver drier. Regas and check operation. TX VALVE \$85.00 LABOUR X 5 \$425.00 \cf1\fs16	25/09/2018	26/09/2018
R130-0016797	1534	19.94	75.00	0.00	0.00	0.00	94.94	94.94	1000000	COOLANT ON LH FLOOR	24/09/2018	26/09/2018
R122-0019895	1534	16.29	114.00	0.00	0.00	0.00	130.29	188.04	1000000	REPLACE DASH GLOBES	20/09/2018	20/09/2018
R122-0019895	1534	0.00	57.75	0.00	0.00	0.00	57.75			CHECK FRONT SUSPENSION	20/09/2018	20/09/2018
R130-0016721	1534	0.00	63.75	0.00	0.00	0.00	63.75	63.75	1000000	CHECK LIGHTS	17/09/2018	17/09/2018
R122-0019762	1534	112.20	123.75	0.00	0.00	0.00	235.95	235.95	1000000	REPLACE A/C PRESSURE SWITCH	13/09/2018	13/09/2018
R130-0016622	1534	0.00	18.75	0.00	0.00	0.00	18.75	130.01	1000000	SENTINEL DEVICE IS NOT WORKING	10/09/2018	10/09/2018
R130-0016622	1534	111.26	0.00	0.00	0.00	0.00	111.26			REPLACE ABS LEAD	10/09/2018	10/09/2018
R122-0019663	1534	7.44	157.50	0.00	0.00	0.00	164.94	239.94	1000000	REPLACE LOOSE EXHAUST BUSCHS	6/09/2018	7/09/2018
R122-0019663	1534	0.00	75.00	0.00	0.00	0.00	75.00			N/S HEADLIGHT LED	6/09/2018	7/09/2018
R120-0021400	1534	0.00	0.00	3976.12	0.00	397.61	4373.73	4373.73	1000000		3/09/2018	3/09/2018
R120-0021401	1534	0.00	0.00	(3976.12)	0.00	(397.61)	(4373.73)	(4373.73)	1000000	APPROVED BILLY 03.09.18 ALSO REFER R140-0021400 WARRANTY \cf0\fs20 REVERSE INVOICE:7878860 REASON:TO BE CHARGED TO WARRANTY APPROVAL NUMBER:189614 Air compressor head gasket broken ----- Complaint:Won't build up air Cause:Air compressor head gasket broken Coverage:Retail Hrs/Klms:916148klm Correction: Northstar Motors Tamworth carried out repair with parts supplied by Cummins Tamworth. Travel from Tamworth to breakdown at Murrunud. Connected to ECM and carried out download. Test run engine with compressor discharge unplumbed. No Air from discharge. Flushed cylinder head, no change. Removed compressor and removed head. Found Removed compressor head gasket broken damaging piston and head. Fitted RECON compressor. Test run to verify and return to service. Travel back to Tamworth. \b\fs3 Description Operation Unit price Qty Extension Material \b0\fs2 185848 GASKET AIR COMPRESSOR 10.61 1- 10.61- 3690864RX RECON AIR COMPRESSOR ISX 2192.44 1- 2192.44- 4988280 GASKET HYDRAULIC PUMP 10.85 1- 10.85- 3102109 SEAL O RING 13.21 2- 26.42- \fs8 1 \fs20 3678786 SEAL O RING PLUG 8.24 2- 16.48- 3685614 GASKET ACC DRIVE SUPPORT 43.43 1- 43.43- 3627695 SEAL O RING 20.76 2- 41.52- \b\fs3 MATERIAL TOTAL 2341.75- Subcontract \b0\fs2 5110551 Attend breakdown 980.63 1- 1634.37- \b\fs3 SUBCONTRACT TOTAL 1634.37- SUB-TOTAL 3976.12- G.S.T 397.61- CREDIT 4373.73- \b0\fs16 All goods \cf1	3/09/2018	3/09/2018
R122-0019479	1534	161.12	75.00	0.00	0.00	0.00	236.12	236.12	1000000	REPLACE L/H INDICATOR ON BONNET	28/08/2018	28/08/2018
R140-0042917	1534	39.72	2.25	0.00	0.00	0.00	41.97	41.97	1000000	AIR BLOWER IN CAB LEAKING	26/07/2018	27/07/2018
R120-0020734	1534	40.72	0.00	1.16	0.00	0.00	41.88	6549.14	1000000	5380.00 CLUTCH REPLACED UNDER WARRANTY B&H COFFS	19/07/2018	1/08/2018
R120-0020734	1534	1399.06	863.25	498.31	0.00	0.00	2760.62			CARRY OUT INSPECTION BEFORE RETURN TO STANTHORPE	19/07/2018	1/08/2018
R120-0020734	1534	1026.03	489.75	495.00	0.00	0.00	2010.78			LEAKING RADIATOR	19/07/2018	1/08/2018
R120-0020734	1534	572.53	327.75	0.00	0.00	0.00	900.28			B SERVICE - CUMMINS E5	19/07/2018	1/08/2018
R120-0020734	1534	513.08	322.50	0.00	0.00	0.00	835.58			REPLACE GEARBOX OILS REPLACE DIFF OILS	19/07/2018	1/08/2018
R140-0041780	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	925187	BAD AIR LEAKS	29/06/2018	29/06/2018
R140-0041533	1534	65.69	0.00	0.00	0.00	0.00	65.69	65.69	921458	SUPPLY DRIVER WITH SUZI LEADS	25/06/2018	25/06/2018
R122-0018441	1534	160.52	7.50	0.00	0.00	0.00	168.02	168.02	917414	REPLACE FLOOR MATS	21/06/2018	22/06/2018
R130-0015240	1534	85.22	312.75	0.00	0.00	0.00	397.97	457.11	915110	INSPECT FOR COOLANT LEAKS	18/06/2018	19/06/2018
R130-0015240	1534	59.14	0.00	0.00	0.00	0.00	59.14			REPLACE RAD DRAIN PLUG	18/06/2018	19/06/2018
R122-0018118	1534	0.00	0.00	821.25	0.00	82.13	903.38	903.38	897507	1534 - 28.5.18 KLMS 891233 REGO 222VQK NOX SENSOR REWIRING TO BATTERIES NOX SENSOR WIRING TO BATTERIES IS FAULTY PO REQUESTED BY BH 29.5.18 \cf0 ATTEND AFTER HOURS CALLOUT FOR TRANSMISSION STUCK IN GEAR AND FAULT LIGHT APPEARING ON DASH. CONNECT LAPTOP AND INSPECT FOR FAULTS. FOUND CLUTCH DISENGAGEMENT FAULTS. START TRUCK AND FOUND UNABLE TO SHIFT INTO GEAR. SHUT DOWN AND INSPECT CLUTCH THROUGH BELL HOUSING. FOUND EXCESSIVE AMOUNTS OF METAL IN BELL HOUSING, SUSPECT FAILED CLUTCH. VEHICLE REQUIRES TOWING. ASSIST WITH REMOVAL AND INSTALLATION OF GEARBOX AND CLUTCH ASSEMBLIES. TEST DRIVE TRUCK UPON COMPLETION OF REPAIR SUBLET DUNNS RECOVERY SERVICE. - TOW B DOUBLE VEHICLE FROM TOP OF MOONBI TO GLEN ARTNEY WORKSHOP \cf1\fs2	30/05/2018	30/05/2018
R120-0019918	1534	0.00	0.00	8801.05	0.00	880.11	9681.16	9681.16	896410		29/05/2018	30/05/2018
R122-0018074	1534	447.64	300.00	0.00	0.00	0.00	747.64	747.64	896410	A/HOURS CALL TO YARD REPLACE BATTERIES	29/05/2018	29/05/2018
R130-0014958	1534	77.50	0.00	0.00	0.00	0.00	77.50	77.50	896088	FILL BOTTLES	28/05/2018	28/05/2018
R122-0017989	1534	0.00	174.00	0.00	0.00	0.00	174.00	731.52	895264	TRUCK HAS NO POWER	24/05/2018	24/05/2018
R122-0017989	1534	191.52	131.25	0.00	0.00	0.00	322.77			RELIN L/H/H + L/H/R DRIVE BRAKES	24/05/2018	24/05/2018
R122-0017989	1534	45.75	189.00	0.00	0.00	0.00	234.75			REPLACE HOT AIR HOSE	24/05/2018	24/05/2018
R122-0018018	1534	47.20	0.00	0.00	0.00	0.00	47.20	47.20	895264		24/05/2018	24/05/2018
R122-0017896	1534	507.71	262.50	0.00	0.00	0.00	770.21	770.21	894218		18/05/2018	23/05/2018
R120-0019620	1534	0.00	0.00	4376.74	5.00	438.17	4819.91	4819.91	884741	4678.00 B-SERVICE E5 CUMMINS 1534 - 11.5.18 REGO 222VQK \cf0 k002 STRIP & PRICE DIFF FOR REBUILDING Carried out diff rebuild stamped R/O number on diff housing. \b \$1,270.00 \b0 Part Number Part Description Quantity Total Cost K1T4423 BRG KIT 160 1.00 707.80 A1-329751605 INPUT SHAFT 1.00 372.17 122954985 THRUST WASHER 1.00 22.14 A3-3235A2393 CASE AND NEST 1.00 1,411.61 229755349 SNAP RING 1.00 13.85 K1T2825 SHIFT ASSY KIT 1.00 52.10 1229L3002 WASHER -SIDE GE 2.00 30.24 1229K3001 WASHER - THRUST 4.00 11.56 A3303P1030 OIL PUMP ASSEMB 1.00 357.72 FREIGHT FREIGHT 1.00 38.50 1243070 FLANGE BOLT 5.00 14.80 1/2"X1"NYLOC NUT 15.00 1.75 1/2"HDWASHER WASHER 1/2 x 27.00 x 3.0mm 8.00 4.00 5/8"X1" NYLOC NUT 1.00 1.10 LOC44279 LOCITTE 263 STUD LOCK 1.00 9.73 LOC34238 LOCITTE 5699 GREY MAXX 1.00 12.82 A2297D5334 FLTR SCRIN & PLG 1.00 39.85 \b Parts Totals: 46.00 \$3,106.74 \cf1\b0\fs2	11/05/2018	15/05/2018

R122-0017645	1534	3520.00	0.00	0.00	0.00	352.00	3872.00	3872.00	878246	8 X 11R22.5 M749 POSITION 5,6,7,8,9,10,11,12 8 X FIT 8 X TRADES FTSD-10857716	4/05/2018	8/05/2018
R122-0017221	1534	184.10	46.50	0.00	0.00	0.00	230.60	361.35	852437	REPLACE 3RD AIR BAG ON L/H/S	5/04/2018	5/04/2018
R122-0017221	1534	0.00	9.75	0.00	0.00	0.00	9.75			REPLACE DASH LIGHTS	5/04/2018	5/04/2018
R122-0017221	1534	91.00	30.00	0.00	0.00	0.00	121.00			REPLACE WIPER BLADES	5/04/2018	5/04/2018
R122-0017181	1534	974.40	0.00	0.00	0.00	97.44	1071.84	1071.84	850871	2 X 295/22.5 R150 POSITION 1,2 2 X RUNOUT 8 X PRESSURE CHECK 2 X FIT FTSD-1608038	3/04/2018	6/04/2018
R122-0017144	1534	0.00	1.50	0.00	0.00	0.00	1.50	191.79	846347	TRUCK PULLS TO THE RIGHT	29/03/2018	31/03/2018
R122-0017144	1534	109.29	81.00	0.00	0.00	0.00	190.29			REPLACE R/H HEADLIGHT COVER	29/03/2018	31/03/2018
R140-0037651	1534	16.48	448.50	0.00	0.00	0.00	464.98	464.98	833952	RENEW FRONT DIFF HEAD	16/03/2018	27/03/2018
R122-0016905	1534	320.59	262.50	0.00	0.00	0.00	583.09	583.09	833952	R/R POWER DIVIDER ASSY & INSPECT FOREIGN MATERIAL FOUND IN OIL	15/03/2018	16/03/2018
R131-0000569	1534	60.00	0.00	0.00	0.00	6.00	66.00	66.00	833952	2 X ROTATION POSITION 1,2 2 X BALANCE FTSD-1507063	15/03/2018	21/03/2018
R122-0016880	1534	0.00	0.00	593.50	0.00	59.35	652.85	652.85	832165	1534 - 8.3.18 KLMS 823662 SERVICE CALL TO WORKSHOP PRESSURE TEST COMPRESSOR TO CONDENSOR REPLACE FAULTY HOSE AND REGAS FOREIGN MATERIAL FOUND AT OIL DRAIN CHECKED AGAIN & FOUND MORE DEBRI REPORTED TO BILL	14/03/2018	14/03/2018
R122-0016828	1534	151.05	1.50	0.00	0.00	0.00	152.55	152.55	830842	2 X ROTATION POSITION 1,2 FTSD-1478614	12/03/2018	15/03/2018
R122-0016801	1534	38.00	0.00	0.00	0.00	3.80	41.80	41.80	827679		9/03/2018	16/03/2018
R122-0016769	1534	547.68	249.75	0.00	0.00	0.00	797.43	1278.36	827679	B-SERVICE E5 CUMMINS	8/03/2018	9/03/2018
R122-0016769	1534	5.34	18.75	0.00	0.00	0.00	24.09			REPAIR A/C GUYS AUTO	8/03/2018	9/03/2018
R122-0016769	1534	0.00	37.50	0.00	0.00	0.00	37.50			SEND TO BIG WHEELS FOR WHEEL ALIGNMENT	8/03/2018	9/03/2018
R122-0016769	1534	325.59	93.75	0.00	0.00	0.00	419.34			REPLACE DIFF OIL & FILTER	8/03/2018	9/03/2018
R122-0016781	1534	0.00	0.00	580.88	0.00	58.09	638.97	638.97	827244	1534 8.3.18 REGO 222-VQK WHEEL ALIGNMENT	8/03/2018	8/03/2018
R122-0016752	1534	170.79	37.50	0.00	0.00	0.00	208.29	208.29	824792	REPLACE EXHAUST FLEX	6/03/2018	7/03/2018
R122-0016548	1534	18.00	0.00	0.00	0.00	1.80	19.80	19.80	815155	SERVICE ORDER NO 10643785 SYDNEY DEP 23.218 HUBO 743667 POS 1,2,5-12	23/02/2018	9/03/2018
R122-0016530	1534	333.64	197.25	0.00	0.00	0.00	530.89	574.53	813936	REPLACE DAYTIME RUNNING LIGHTS	22/02/2018	23/02/2018
R122-0016530	1534	24.89	18.75	0.00	0.00	0.00	43.64			REPLACE AIR VENT	22/02/2018	23/02/2018
R122-0016331	1534	0.00	0.00	1379.79	0.00	137.98	1517.77	1517.77	807010	14.2.18 PO REQUESTED BY BILLY PRICES AS PER PROFORMA R106750 REGO: 222VQK KLMS: 801486 FOUND KNOW SENSOR FAULTY REMOVED AND REPLACED CLEARED CODES AND FOIIND A11 OK	14/02/2018	23/02/2018
R122-0015820	1534	0.00	15.00	0.00	0.00	0.00	15.00	200.29	781731	REPLACE L/H/F & L/H/R AIR BAG	16/01/2018	19/01/2018
R122-0015820	1534	55.54	129.75	0.00	0.00	0.00	185.29			REPLACE SUZY COILS	16/01/2018	19/01/2018
R122-0015827	1534	194.32	47.25	330.55	0.00	0.00	572.12	572.12	781731	TRUCK HAS SOME BAD AIR LEAKS	16/01/2018	17/01/2018
R130-0012562	1534	266.35	181.50	0.00	0.00	0.00	447.85	447.85	781729	CHECK FOR AIR BAGS LEAKING	15/01/2018	16/01/2018
R122-0015729	1534	661.10	107.25	0.00	0.00	0.00	768.35	869.60	778049	REPLACE EXHAUST FLEX UNDER TRANSMISSION	11/01/2018	13/01/2018
R122-0015729	1534	0.00	101.25	0.00	0.00	0.00	101.25			REPLACE DRIVE AIR BAG	11/01/2018	13/01/2018
R140-0034729	1534	0.00	1012.50	0.00	0.00	0.00	1012.50	1012.50	769263	INSPECT TRANS FAULT CODES	29/12/2017	3/01/2018
R122-0015511	1534	446.03	225.00	0.00	0.00	0.00	671.03	671.03	769263	PM for 000-002 Last Done: 23/10/2017 Interval: 60000 Utilization: 56988	28/12/2017	2/01/2018
R122-0015455	1534	712.92	311.25	0.00	0.00	0.00	1024.17	1024.17	763721	RELINE ALL DRIVE BRAKES + REPLACE WHEEL BEARINGS	21/12/2017	22/12/2017
R122-0015409	1534	860.00	0.00	0.00	0.00	86.00	946.00	946.00	761458	2 X 295/80 R150 POSITION 1,2 2 X TRADES 2 X FIT FTSD-1502740	19/12/2017	22/12/2017
R122-0015368	1534	0.00	69.75	0.00	0.00	0.00	69.75	69.75	761132	CHECK SPEEDO AS SPEED ALARM ISN'T GOING OFF UNTIL 105	18/12/2017	18/12/2017
R122-0015369	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	761132	TRUCK IS OVERHEATING	18/12/2017	18/12/2017
R122-0015370	1534	0.00	146.25	0.00	0.00	0.00	146.25	146.25	761132	FRIDGE IS NOT WORKING	18/12/2017	18/12/2017
R122-0015371	1534	0.00	80.25	0.00	0.00	0.00	80.25	80.25	761132	CHECK ALL LIGHTS	18/12/2017	18/12/2017
R122-0015372	1534	5.12	30.00	0.00	0.00	0.00	35.12	35.12	761132	CHECK TELL TALES AND GAUGES	18/12/2017	18/12/2017
R122-0015373	1534	0.00	97.50	0.00	0.00	0.00	97.50	97.50	761132	STEERING WHEEL IS NOT STRAIGHT	18/12/2017	18/12/2017
R140-0034162	1534	1760.00	0.00	0.00	0.00	176.00	1936.00	1936.00	756736	B/STONE 4X 11R22.5 M749 4X FIT 4X SCRAP FTSD 1552435	14/12/2017	14/12/2017
R130-0012053	1534	996.30	339.00	0.00	0.00	0.00	1335.30	1335.30	755876	REPLACE STEERING WHEEL AND CONTROL MODULE	12/12/2017	14/12/2017
R122-0015254	1534	1810.00	0.00	0.00	0.00	181.00	1991.00	1991.00	752592	4 X 11R22.5 M749 POSITION 5,6,7,8 3 X TRADES 1 X RENOUT 4 X FIT FTSD-1502300	8/12/2017	11/12/2017
R140-0033705	1534	10.80	0.00	0.00	0.00	1.08	11.88	11.88	749506	B/STONE 6X PRESSURE CHECK ORDER NUMBER 10288877	5/12/2017	18/12/2017
R140-0033422	1534	91.00	114.00	0.00	0.00	0.00	205.00	205.00	744028	RENEW WIPER BLADES	29/11/2017	29/11/2017
R122-0014988	1534	49.50	75.00	0.00	0.00	0.00	124.50	124.50	739568	A/HOURS CALL TO W/SHOP REPLACE SUZY COILS	24/11/2017	24/11/2017
R140-0031942	1534	0.00	0.00	39.50	0.00	3.95	43.45	43.45	714571	REPAIR COOLANT LEAK	26/10/2017	2/11/2017
R130-0011187	1534	365.69	189.00	0.00	0.00	0.00	554.69	554.69	711886	B SERVICE. SIF 21752567	23/10/2017	24/10/2017
R122-0014161	1534	463.80	225.00	0.00	0.00	0.00	688.80	688.80	706215	REPLACE STARTER MOTOR	17/10/2017	18/10/2017
R122-0014055	1534	0.00	51.00	0.00	0.00	0.00	51.00	51.00	702299	TAKE TO CUMMINS FOR WARRANTY COOLANT PIPE LEAKING UNDER TURBO	12/10/2017	13/10/2017
R122-0013663	1534	51.73	78.75	0.00	0.00	0.00	130.48	130.48	680265	INSTALL CALFA BAG	19/09/2017	19/09/2017
R140-0029964	1534	41.02	75.00	0.00	0.00	0.00	116.02	116.02	676896	REPLACE SUZI COILS	15/09/2017	15/09/2017
R122-0013491	1534	0.00	0.00	443.00	0.00	44.30	487.30	487.30	670867	GUY AUTO... REPAIR CRUISE CONTROL, STRIP ENGINE HARNESS & REPAIR DAMAGE.	8/09/2017	11/09/2017
R122-0013428	1534	0.00	101.25	0.00	0.00	0.00	101.25	233.67	667395	STRAIGHTEN FRONT BAR	5/09/2017	5/09/2017
R122-0013428	1534	88.92	43.50	0.00	0.00	0.00	132.42			REPLACE WIPER BLADES	5/09/2017	5/09/2017
R122-0013279	1534	860.00	0.00	0.00	0.00	86.00	946.00	946.00	657039	replace steer tyres with 295 r150, 2 X trade-in, ftsd-1556644	25/08/2017	28/08/2017
R122-0013249	1534	98.67	76.50	0.00	0.00	0.00	175.17	175.17	656483	RELINE L/H/R DRIVE BRAKE BLOWN HUB SEAL	24/08/2017	25/08/2017
R122-0013086	1534	494.36	86.25	0.00	0.00	0.00	580.61	693.11	649606	B-SERVICE ES CUMMINS	17/08/2017	17/08/2017
R122-0013086	1534	0.00	112.50	0.00	0.00	0.00	112.50			SECURE REAR DIFF YOKE	17/08/2017	17/08/2017
R140-0028167	1534	0.00	1.50	217.53	0.00	0.00	219.03	219.03	642554	REPAIR A/C SYSTEM	9/08/2017	11/08/2017
R122-0012724	1534	330.00	0.00	497.50	0.00	49.75	877.25	877.25	631683	GUYS AUTO... CHECK A/C SYSTEM, REPLACE FAULTY COMPRESSOR & RE-GAS A/C.	28/07/2017	31/07/2017
R122-0012659	1534	284.62	92.25	0.00	0.00	0.00	376.87	376.87	628959	LEAKING HEATER HOSE OUT OF THE FIRE WALL	25/07/2017	26/07/2017
R122-0012661	1534	33.10	121.50	0.00	0.00	0.00	154.60	154.60	628959	YELLOW BUTTON LEAKING AIR	25/07/2017	26/07/2017
R120-0014333	1534	0.00	0.00	376.45	0.00	37.65	414.10	414.10	623297	CALLOUT TO CITY GATE SERVICE STATION TAMWORTH.REMOVE & REPLACE BROKEN EXHAUST CLAMP OFF BACK OF TURBO.FIT NEW GASKET.CHECK FOR LEAKS. ALL OK.	19/07/2017	19/07/2017

R120-0014342	1534	0.00	0.00	46.72	0.00	4.67	51.39	51.39	623297	ITEMS NOT COVERED DURNING ENGINE DERATE FAULT.FOUND AFTERTREATMENT ADBLUE NOZZLE TIP MISSING.FIT NEW PART NOT CLAIMABLE UNDER CUMMINS WARRANTY.(FOLLOWED T/R FOR FAULT CODE.3575.-R&R DEF DOSING UNIT.COMPLETE T/R STEP-REPAIR CUMPI FTF REPLACE MISSING CLAMP	19/07/2017	19/07/2017
R122-0012276	1534	20.42	18.75	0.00	0.00	0.00	39.17	39.17	611218		6/07/2017	7/07/2017
R122-0012097	1534	304.67	0.00	0.00	0.00	0.00	304.67	304.67	602525	JOB MADE TO BOOK OUT PARTS, see P122-0004463	26/06/2017	26/06/2017
R122-0011887	1534	35.00	0.00	0.00	0.00	3.50	38.50	38.50	592237	P-REPAIR POS# 11 FTSD- 1406327	16/06/2017	6/07/2017
R122-0011816	1534	1880.00	0.00	0.00	0.00	188.00	2068.00	2068.00	590334	11R 'M749' POS# 5-6-7-8 TRADE-IN x 4 FTSD- 1406317	14/06/2017	19/06/2017
R122-0011804	1534	490.48	189.00	0.00	0.00	0.00	679.48	996.48	590334	TRAILER SERVICE	13/06/2017	14/06/2017
R122-0011804	1534	146.00	171.00	0.00	0.00	0.00	317.00			RELINE 1ST DRIVE AXLE BRAKES	13/06/2017	14/06/2017
R122-0011475	1534	103.97	0.00	0.00	0.00	0.00	103.97	103.97	572248	REDO JOB TO BOOK OUT PARTS SEE **R122-0005275**	25/05/2017	26/05/2017
R140-0024204	1534	0.00	142.50	0.00	0.00	0.00	142.50	142.50	565656	WINDOWS WONT GO DOWN	17/05/2017	19/05/2017
R140-0024193	1534	1839.00	0.00	0.00	0.00	183.90	2022.90	2022.90	565655	B/STONE FIT 4X 11R/22.5 M749 POS 9-12 FIT 1X OWN STOCK R/O POS 6 SX TRADE PRESSURE CHECK ALL POS X5 FTSD 1335943	16/05/2017	18/05/2017
R140-0024155	1534	136.88	264.00	0.00	0.00	0.00	400.88	400.88	564807	USING OIL	15/05/2017	16/05/2017
R140-0022964	1534	0.00	0.00	341.80	0.00	34.15	375.95	375.95	536436	REPAIR WIRING TO HILL START ASSIST- SUBLET TO B&H	19/04/2017	21/04/2017
R122-0010658	1534	49.11	187.50	0.00	0.00	0.00	236.61	236.61	531831	REPLACE MAIN COMPRESSOR AIR LINE	11/04/2017	11/04/2017
R122-0010546	1534	67.42	87.75	0.00	0.00	0.00	155.17	155.17	525926	REPLACED DAMAGED SUZI COILS	4/04/2017	5/04/2017
R122-0010469	1534	452.98	296.25	0.00	0.00	0.00	749.23	749.23	523300	B SERVICE	30/03/2017	31/03/2017
R122-0010207	1534	30.26	0.00	555.00	0.00	55.50	640.76	640.76	511821	GUY AUTO... CHECK & RREPAIR A/C, REPLACE HOSE & RE-GAS.	17/03/2017	20/03/2017
R122-0010202	1534	0.00	87.75	0.00	0.00	0.00	87.75	87.75	511043	AIR CON NOT WORKING	16/03/2017	17/03/2017
R120-0011795	1534	0.00	0.00	1100.00	0.00	110.00	1210.00	1210.00	504776	NOT COVERED UNDER WARRANTY. CHECK AUTO SHIFT NOT GOING INTO GERA.CONNECT ELECTRIC DIAGNOSTIC TOOL.CHECK CODES.FOUND CODES 14 & 21.REMOVE GUARD & STEP TO ACCESS.TRANSMISSION ECU.CHECK ECU & WIRING.CHECK CLUTCH ACTUATOR & WIRING. TRACE WIRING.LOCATE & REPAIR OPEN CIRCUIT IN HARNESS BETWEEN ECU & CLUTCH ACTUATOR.REFIT GUARD & STEP.CLEAR CODES & CHECK OPERATION.	9/03/2017	13/03/2017
R120-0011586	1534	1439.96	2226.75	0.00	0.00	0.00	3666.71	21923.48	509003	C-SERVICE	28/02/2017	16/03/2017
R120-0011586	1534	661.28	550.50	300.00	0.00	0.00	1511.78			REMOVE RADIATOR AND SEND TO NATRAD	28/02/2017	16/03/2017
R120-0011586	1534	2351.62	0.00	0.00	0.00	0.00	2351.62			REPLACE DOSER PUMP REPLACE FILTERS	28/02/2017	16/03/2017
R120-0011586	1534	0.00	0.00	0.00	0.00	0.00	0.00			WARRANTY- MANIFOLD GASKETS	28/02/2017	16/03/2017
R120-0011586	1534	41.46	39.00	0.00	0.00	0.00	80.46			EXHAUST MOUNTS AT BLOCK EXHAUST CLAMP LEAKING AT MUFFLER	28/02/2017	16/03/2017
R120-0011586	1534	2980.06	187.50	0.00	0.00	0.00	3167.56			REPLACE TURBO	28/02/2017	16/03/2017
R120-0011586	1534	1736.71	103.50	0.00	0.00	0.00	1840.21			KIT HORTON REPLACE IDLERS AND TENSIONERS BELTS	28/02/2017	16/03/2017
R120-0011586	1534	720.43	82.50	0.00	0.00	0.00	802.93			REPLACE WATER PUMP	28/02/2017	16/03/2017
R120-0011586	1534	228.15	39.00	0.00	0.00	0.00	267.15			REPLACE THERMOSTAT	28/02/2017	16/03/2017
R120-0011586	1534	17.93	24.00	0.00	0.00	0.00	41.93			SERVICE VIESA	28/02/2017	16/03/2017
R120-0011586	1534	0.00	0.00	0.00	0.00	0.00	0.00			REPLACE A/C BEARING	28/02/2017	16/03/2017
R120-0011586	1534	0.00	144.00	0.00	0.00	0.00	144.00			STEER OILS	28/02/2017	16/03/2017
R120-0011586	1534	575.76	51.00	0.00	0.00	0.00	626.76			WARRANTY- REPLACE ROCKER SHAFTS AND TUNE ENGINE -TIMING COVER BUNG LEAKING	28/02/2017	16/03/2017
R120-0011586	1534	0.00	120.00	0.00	0.00	0.00	120.00			KIT AIR DRIER	28/02/2017	16/03/2017
R120-0011586	1534	266.02	31.50	0.00	0.00	0.00	297.52			REPLACE POWER STEER OIL AND FILTER	28/02/2017	16/03/2017
R120-0011586	1534	216.92	13.50	0.00	0.00	0.00	230.42			REPLACE OIL THERMOSTAT	28/02/2017	16/03/2017
R120-0011586	1534	51.74	234.00	0.00	0.00	0.00	285.74			HEADLIGHTS SURROUNDS MISSING BONNET AIR INTAKE RUBBER WARPED	28/02/2017	16/03/2017
R120-0011586	1534	92.88	43.50	0.00	0.00	0.00	136.38			VARIOUS TANK STRAP RUBBERS	28/02/2017	16/03/2017
R120-0011586	1534	0.00	9.75	0.00	0.00	0.00	9.75			FRONG SPRINGS CLUNKING TENSION UBOLTS	28/02/2017	16/03/2017
R120-0011586	1534	139.05	282.75	0.00	0.00	0.00	421.80			REPLACE HEATER TAPS REPLACE HEATER HOSES	28/02/2017	16/03/2017
R120-0011586	1534	1002.86	162.75	0.00	0.00	0.00	1165.61			REPLACE STEER UNIS	28/02/2017	16/03/2017
R120-0011586	1534	441.25	108.75	0.00	0.00	0.00	550.00			REPLACE FRONT CAB MOUNTS REAR BUMP STOP	28/02/2017	16/03/2017
R120-0011586	1534	0.00	12.75	0.00	0.00	0.00	12.75			AIR LEAK AT MANIFOLD	28/02/2017	16/03/2017
R120-0011586	1534	0.00	0.00	0.00	0.00	0.00	0.00			WARRANTY- X-Y RAIL SENSOR LEAKING	28/02/2017	16/03/2017
R120-0011586	1534	32.20	181.50	0.00	0.00	0.00	213.70			DETAIL CAB WEATHER SHEILD CLIPS MISSING	28/02/2017	16/03/2017
R120-0011586	1534	82.48	20.25	0.00	0.00	0.00	102.73			REPLACE WIPER BLADES	28/02/2017	16/03/2017
R120-0011586	1534	256.96	357.75	0.00	0.00	0.00	614.71			REPLACE REAR GAURDS	28/02/2017	16/03/2017
R120-0011586	1534	976.35	107.25	0.00	0.00	0.00	1083.60			TIDY SUZI COILS AND FITTINGS-FIT STEER BRAKES AND DRUMS AND DUST SHIELDS	28/02/2017	16/03/2017
R120-0011586	1534	7.58	0.00	0.00	0.00	0.00	7.58			WARRANTY - RESEAL FRONT DIFF	28/02/2017	16/03/2017
R120-0011586	1534	250.12	96.75	0.00	0.00	0.00	346.87			REPLACE FRONT TORQUE ROD BUSHES	28/02/2017	16/03/2017
R120-0011586	1534	462.50	65.25	0.00	0.00	0.00	527.75			REPLACE ALTERNATOR	28/02/2017	16/03/2017
R120-0011586	1534	981.96	313.50	0.00	0.00	0.00	1295.46			POLISH ALL OUTTER RIMS	28/02/2017	16/03/2017
R122-0009759	1534	0.00	0.00	570.40	0.00	57.04	627.44	627.44	498135	BIG WHEELS , WHEEL ALIGNMENT, 14-2-17, 496874 KMS	23/02/2017	23/02/2017
R140-0020543	1534	0.00	0.00	282.34	0.00	28.23	310.57	310.57	498135	REMOVED FAILED EXHAUST FLEX.FIT NEW FLEX & GASKET.TIGHTEN CLAMPS & CHECK FOR EXHAUST LEAKS.NO FURTHER FAULT	23/02/2017	23/02/2017
R122-0009582	1534	34.40	0.00	0.00	0.00	3.44	37.84	37.84	490872	STEER ROTATION, TURNED ON RIMS, 8 x P-CHECK, FTSD-1294731	15/02/2017	20/02/2017
R122-0009543	1534	0.00	24.00	0.00	0.00	0.00	24.00	24.00	490092	WHEEL ALIGN AT BIG WHEELS	14/02/2017	15/02/2017
R122-0009188	1534	37.83	147.75	0.00	0.00	0.00	185.58	292.08	478244	REPLACE YELLOW PARK BRAKE VALVE	31/01/2017	1/02/2017
R122-0009188	1534	0.00	106.50	0.00	0.00	0.00	106.50			REPAIR OIL LEAK AT L/H STEER HUB CAP	31/01/2017	1/02/2017
R122-0008922	1534	0.00	77.25	0.00	0.00	0.00	77.25	77.25	466124	MISSING AN INSPECTION PLATE ON THE DRIVE BRAKES	17/01/2017	18/01/2017
R122-0008842	1534	773.28	174.00	0.00	0.00	0.00	947.28	1575.52	462407	B SERVICE + TRANS OIL	12/01/2017	13/01/2017
R122-0008842	1534	464.74	163.50	0.00	0.00	0.00	628.24			RELINE ALL DRIVE BRAKES + REPLACE REARAXLE BRAKE DRUMS	12/01/2017	13/01/2017
R122-0008393	1534	0.00	37.50	0.00	0.00	0.00	37.50	37.50	449593	SHAKING IN THE STEERING	16/12/2016	17/12/2016
R120-0009960	1534	0.00	0.00	323.09	0.00	32.31	355.40	355.40	446285	CALLOUT TO REPAIR THERMOSTAT HOUSING & FIT NEW FITTING & 8MM ALLTACK HOSE	12/12/2016	13/12/2016
R122-0008160	1534	0.00	234.75	0.00	0.00	0.00	234.75	234.75	440785	TRAILER ABS LIGHT IS STAYING ON ON THE DASH	7/12/2016	9/12/2016
R122-0008016	1534	0.00	82.50	0.00	0.00	0.00	82.50	82.50	436576	CANT GET REVERSE	30/11/2016	1/12/2016
R122-0007940	1534	421.47	217.50	0.00	0.00	0.00	638.97	638.97	435684	REPLACE STARTER MOTOR	28/11/2016	28/11/2016
R122-0007891	1534	4160.00	0.00	0.00	0.00	416.00	4576.00	4576.00	432553	REPLACE DRIVE TYRES WITH 11R M749, 8 x CASES, FTSD-1180494	24/11/2016	21/12/2016

R122-0007848	1534	2315.31	182.25	0.00	0.00	0.00	2497.56	2497.56	430505	REPLACE AIR COMPRESSOR + GOVENOR VALVE	22/11/2016	1/12/2016
R120-0009321	1534	390.00	0.00	0.00	0.00	39.00	429.00	429.00	424046	1 X PUNCTURE REPAIR 1 X ETA FEE NO 49073 FTSD-1306003	15/11/2016	15/11/2016
R122-0007699	1534	241.79	93.75	0.00	0.00	0.00	335.54	335.54	424046	O/HAUL AIR DRIER	15/11/2016	17/11/2016
R122-0007321	1534	539.18	261.00	0.00	0.00	0.00	800.18	800.18	415109	2007.00 B SERVICE	1/11/2016	2/11/2016
R120-0008981	1534	0.00	0.00	735.45	0.00	73.54	808.99	808.99	413624	TOWED TO SAFETY CUMMUNGHAMS GAP. AFTER FAILED ALTERNATOR	31/10/2016	31/10/2016
R140-0015486	1534	1171.91	453.75	0.00	0.00	0.00	1625.66	1625.66	411665	BREAKDOWN - REPLACE ALTERNATOR	29/10/2016	1/11/2016
R122-0006886	1534	950.00	0.00	0.00	0.00	95.00	1045.00	1045.00	397115	REPLACE STEER TYRES WITH 295 R150, 2 x CASE FTSD-1071882	14/10/2016	17/10/2016
R122-0006650	1534	17.14	165.00	0.00	0.00	0.00	182.14	182.14	389650	REPLACE AIR BLEED HOSE & FITTINGS	6/10/2016	17/10/2016
R122-0006354	1534	0.00	61.50	0.00	0.00	0.00	61.50	61.50	376700	ELECTRONIC FJACE GIVING A LOT OF DIFFERENT SPEEDS	22/09/2016	23/09/2016
R122-0006355	1534	0.00	96.00	0.00	0.00	0.00	96.00	219.75	376700	BAD AIR LEAK NEAR DRIVERS DOOR	22/09/2016	23/09/2016
R122-0006355	1534	24.00	99.75	0.00	0.00	0.00	123.75			REPLACE WORK LIGHT	22/09/2016	23/09/2016
R122-0006184	1534	0.00	0.00	200.00	0.00	20.00	220.00	220.00	369844	JENNINGS GLASS... REPLACE L/H WINDSCREEN.	15/09/2016	26/09/2016
R122-0006187	1534	0.00	1.50	0.00	0.00	0.00	1.50	1.50	369844	NEEDS NEW PASSANGER WINDSCREEN CRACKED BADLY	15/09/2016	15/09/2016
R122-0005657	1534	457.73	159.75	0.00	0.00	0.00	617.48	771.93	350914	1144.00 B SERVICE	25/08/2016	26/08/2016
R122-0005657	1534	70.45	84.00	0.00	0.00	0.00	154.45			RELIN R/H/F DRIVE BRAKE	25/08/2016	26/08/2016
R122-0005290	1534	0.00	174.00	0.00	0.00	0.00	174.00	174.00	337794	SPEEDO NEEDS CHECKING	12/08/2016	13/08/2016
R122-0005275	1534	0.00	71.25	0.00	0.00	0.00	71.25	71.25	337020	NEEDS NEW DRIVERS SIDE HEADLIGHT COVER	11/08/2016	13/08/2016
R140-0011682	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	328163	PULLING TO THE LEFT	4/08/2016	4/08/2016
R140-0011683	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	328163	NEEDS NEW STEER TYRES	4/08/2016	4/08/2016
R122-0004891	1534	57.96	84.75	0.00	0.00	0.00	142.71	142.71	321968	REPLACE SUZY COILS	26/07/2016	26/07/2016
R122-0004795	1534	0.00	27.75	0.00	0.00	0.00	27.75	27.75	317816	END OF WARRANTY AT G&R ERRATIC PYRO GAUGE	21/07/2016	21/07/2016
R122-0004293	1534	0.00	69.00	0.00	0.00	0.00	69.00	281.17	293946	BOOST GAUGE NOT WORKING	28/06/2016	28/06/2016
R122-0004293	1534	101.62	9.00	0.00	0.00	0.00	110.62			REPLACE FIRE EXTINGUISHER	28/06/2016	28/06/2016
R122-0004293	1534	99.30	2.25	0.00	0.00	0.00	101.55			REPLACE WIPER ASSY	28/06/2016	28/06/2016
R122-0004154	1534	0.00	0.00	511.20	0.00	51.12	562.32	562.32	290385	SUBLET REPAIR BY BIG WHEELS... WHEEL ALIGNMENT.	22/06/2016	22/06/2016
R122-0004137	1534	856.88	207.75	0.00	0.00	0.00	1064.63	1119.38	290385	316.00 b service	21/06/2016	22/06/2016
R122-0004137	1534	0.00	54.75	0.00	0.00	0.00	54.75			WHEEL ALIGN AT BIG WHEELS	21/06/2016	22/06/2016
R122-0004031	1534	0.00	63.75	0.00	0.00	0.00	63.75	63.75	285289	DROP AT GIL ROA COMPRESSOR OUTLET HOSE LEAK	16/06/2016	17/06/2016
R140-0009142	1534	0.00	0.00	163.64	0.00	16.36	180.00	180.00	281469	REPLACE STEER TYRES	15/06/2016	30/06/2016
R122-0003969	1534	0.00	3.75	0.00	0.00	0.00	3.75	3.75	281469	SEAT BELT WONT RETRACT	14/06/2016	15/06/2016
R122-0003796	1534	3910.00	0.00	0.00	0.00	391.00	4301.00	4301.00	273052	B/STONE... REPLACE DRIVE TYRES WITH 11R M749, 3 x KEPT FOR RUN OUTS, 5 x 11R TRADE-IN. FTSD-1185541	2/06/2016	7/06/2016
R122-0003419	1534	3.59	202.50	0.00	0.00	0.00	206.09	267.34	263627	REPLACE R/H/R DRAIVE AXLE GASKET	17/05/2016	17/05/2016
R122-0003419	1534	35.00	26.25	0.00	0.00	0.00	61.25			FIT OVERSPEED ALERT	17/05/2016	17/05/2016
R122-0003302	1534	(100.00)	0.00	0.00	0.00	(10.00)	(110.00)	(110.00)	257998	B/STONE... REPLACE POS#4,8 WITH 11R RUN OUTS, 2 x 11R TRADE-IN, FTSD-1022646	11/05/2016	12/05/2016
R122-0003263	1534	448.33	129.75	0.00	0.00	0.00	578.08	578.08	265549	B SERVICE	10/05/2016	19/05/2016
R122-0002977	1534	0.00	0.00	213.00	0.00	21.30	234.30	234.30	245060	SUBLET REPAIR BY GUY AUTO... REPAIR WORK LIGHT.	27/04/2016	4/05/2016
R120-0003828	1534	51.20	0.00	0.00	0.00	5.12	56.32	56.32	239878	PUNCHER REPAIR POS.4	21/04/2016	28/04/2016
R122-0002847	1534	65.94	77.25	0.00	0.00	0.00	143.19	143.19	237836	REPLACE NFD DRIVE BRAKE LININGS	19/04/2016	20/04/2016
R122-0002455	1534	486.30	84.75	0.00	0.00	0.00	571.05	571.05	220135	B SERVICE	29/03/2016	31/03/2016
R120-0002563	1534	0.00	0.00	62.00	0.00	6.20	68.20	68.20	200017	REPAIR HOLE IN EXHAUST & ALSO OIL LEAK.	9/03/2016	21/03/2016
R122-0002088	1534	0.00	20.25	0.00	0.00	0.00	20.25	20.25	199222	FLEX UNDER THE TRUCK HAS BROKEN (WARRANTY) DROP OFF AT G&R FOR REPAIR\Ø	8/03/2016	9/03/2016
R122-0002094	1534	18.00	0.00	0.00	0.00	1.80	19.80	19.80	199222	B/STONE... P-CHECK, FTSD-1012769	8/03/2016	10/03/2016
R140-0003727	1534	964.40	0.00	0.00	0.00	96.44	1060.84	1060.84	184851	BALANCE BY 2 POS-1,2 295/80/22.5 R150 BY 2 POS-1,2 PRESSURE CHECKS BY 8 POS-3-10 FTSD-1037123	23/02/2016	17/03/2016
R140-0003456	1534	0.00	60.00	0.00	0.00	0.00	60.00	60.00	179921	Steering Wheel Not Staright	17/02/2016	18/02/2016
R140-0003385	1534	34.65	0.00	80.00	0.00	8.00	122.65	122.65	179003	FIT TURNABLE WORKLIGHT- SUBLET TO PTE. \Ø AND REPAIR LIGHTS	16/02/2016	1/03/2016
R140-0003215	1534	709.53	138.75	0.00	0.00	0.00	848.28	848.28	176670	B SERVICE E5 CUMMINS	12/02/2016	16/02/2016
R140-0002915	1534	68.57	42.75	0.00	0.00	0.00	111.32	111.32	173290	R/H/S TURNABLE WEAR PAD MISSING	7/02/2016	19/02/2016
R108-0000001	1534	70.00	0.00	0.00	0.00	7.00	77.00	77.00	169054	2 X ROTATE 2 X BALANCE	5/02/2016	5/02/2016
R120-0000888	1534	0.00	54.00	0.00	0.00	0.00	54.00	54.00	153926	ADJUST RELEASE PIN FOR ROLL BACK SYSTEM	16/01/2016	6/02/2016
R122-0000739	1534	0.00	0.00	0.00	0.00	0.00	0.00	0.00	150537	1 X CROSSFIRE FITTED FTSD 872533	13/01/2016	29/01/2016
R122-0000561	1534	0.00	33.75	0.00	0.00	0.00	33.75	33.75	142985	CHECK SPEEDO	5/01/2016	5/01/2016
R122-0000469	1534	3760.00	0.00	0.00	0.00	376.00	4136.00	4136.00	139162	8 X FIT 11R M749 POS 3-10 8 X TRADE FTSD 872494	30/12/2015	7/01/2016
R122-0000455	1534	32.70	22.50	0.00	0.00	0.00	55.20	55.20	138942	LEAKING COOLANT INSIDE CAB	29/12/2015	29/12/2015
R122-0000284	1534	0.00	37.50	0.00	0.00	0.00	37.50	75.00	131991	AIR CON NOT WORKING REPAIRED BY G@R WARRANT YREFER RO 122 257 \Ø	18/12/2015	18/12/2015
R122-0000284	1534	0.00	37.50	0.00	0.00	0.00	37.50			A/C NOT WORKING REPAIRED BY G@R REFER RO 122/257\Ø	18/12/2015	18/12/2015
R122-0000257	1534	501.17	169.50	0.00	0.00	0.00	670.67	704.42	125981	SERVICE 40 000 E 5	17/12/2015	17/12/2015
R122-0000257	1534	0.00	33.75	0.00	0.00	0.00	33.75			DROPPED OFF AT G&R FOR A/C REPAIRS	17/12/2015	17/12/2015
R122-0000189	1534	0.00	86.25	0.00	0.00	0.00	86.25	86.25	125981	DROP AT G&R FOR AIRCON REPAIR AND BRAKE MOD	15/12/2015	17/12/2015