



## Vehicle History Detail



Fleet #	XN70EE
Registration	XN70EE
Make	KENWORTH
Model	K200
VIN / Chassis #	6F5000000JA463587

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1818	13/12/2022			Clutch		GREASE CLUTCH		\$126.50
S-2669	02/11/2022	830474		A - Fortnightly				\$165.00
R-1765	11/10/2022			Air intake scoop		fix air intake scoop		\$126.50
S-2632	27/09/2022			A - Fortnightly	Dylan	A SERVICE		\$165.00
T-568	08/09/2022			Strip & Fit		1x strip and fit 1x truck tyre disposal	108168	\$110.00
R-1607	23/08/2022	748000	0	Speedometer				\$475.68
T-553	09/08/2022			New		4x haulmax tyres 2x truck tyre disposal	107903	\$2,690.00

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1694	03/08/2022			Clutch		CLUTCH; TRUCK PRESENTED WITH CLUTCH PROBLEMS REMOVE GEARBOX REMOVE CLUTCH AND PRESSURE PLATE REMOVE FLYWHEEL AND SEND FOR MACHINING CLEAN BACK OF ENGINE AND BELHOUSING FIT FLYWHEEL FIT NEW CLUTCH KIT AND SPIGGOT AND THROW OUT BEARING KIT FRONT OF GEARBOX FIT GEARBOX TEST DRIVE		\$10,935.14
T-549	26/07/2022			Call out fee, Fitting, Road Service, Second hand tyre		1x call out fee 1x road service 1x second hand tyre 1x fitting 1x truck tyre disposal	107765	\$880.00
R-1605	01/07/2022	1	0	Power Steering	al	fit new steering box ADJUSTED STEERING BOX THAT WAS FITTED10/08/2022		\$3,582.04
S-2577	20/06/2022	756500	51559	B - 50k	Dylan			\$878.09
R-1606	17/06/2022	1	0	Bushes	Dylan, Jack, jacob	replace all torque rod bushes		\$1,111.00
R-1568	10/05/2022			Electronic Diary		NAVMAN REMOVED		\$35.75
R-1432	19/04/2022			Coolant Leak				\$0.00
T-505	05/04/2022			Strip & Fit		1x strip and fit	106609	\$75.00
S-2530	26/03/2022	0	0	C - 150k + RTA Insp.	Dylan			\$653.39
R-1498	26/03/2022			Hubs				\$24.48
S-2511	26/03/2022	706018	0	D - 300k	Yard	D service and repair front left HUB seal		\$1,391.87
T-497	11/03/2022			Strip & Fit		1 x strip & fit on truck 1 x truck tyre disposal 2 x strip fit & balance steers plus pressure check	106348	\$317.00

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1479	19/01/2022			Shock Absorbers	Dylan	replace leaking shocks		\$726.00
R-1433	17/12/2021	751915	0	Wiper Blades	Jack	JR1062 CANBERRA TRUCKS		\$306.50
T-452	07/12/2021			New		2x michelins	105241	\$1,540.00
T-446	25/11/2021			Puncture		1x puncture repair	105116	\$85.00
O-176	05/10/2021	0	0	CTP				\$1,776.86
O-175	05/10/2021	0	0	Registration			SN-362666400	\$4,703.60
S-2342	29/09/2021	689891		B - 50k	Dylan, Jack			
S-2340	20/09/2021	689891		B - 50k	Dylan, Jack			
R-1346	03/09/2021	680507	0	Power Steering		TIGHTEN HOSE AND REFILL POWER STEERING FLUID		\$71.50
R-1333	29/08/2021			boost leak	Jack	intercooler piping not fitted properly by dylan had to come refit v band on inter cooler piping		
R-1328	25/08/2021			Electrical	Jack	remove engine harness, check for broken and damaged wires and repair as needed refit repaired engine harness		
R-1288	19/07/2021	0	0	Pedal	Kobi	replaced brake foot valve Replaced accelerator potentiometer Still faulting inspected twin city trucks moved wiring hasnt faulted again		
R-1299	19/07/2021	647309	0	Ad Blue Tank	Kobi	fix broken ad blue line		\$0.00
R-1273	28/06/2021	638398	0	ABS, Dash - Gauges				

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1260	21/06/2021	633503	0	Ad Blue Tank	Kobi	Truck presented with aftertreat light on plugged in scan tool check codes code for adblue return pressure too high clean area clean supply and return line run adblue test still fail fitted new doser pump completed adblue test completed test codes inactive light off return to driver		\$1,512.50
S-2255	15/06/2021	630385		A - Fortnightly	Jack			\$165.00
R-1245	13/06/2021	628896		Battery	Jack	replace 4 batteries	103573	\$780.00
R-1217	25/05/2021	617081	0	Exhaust Brake		problem resolved it self		
S-2169	08/05/2021	605348	0	B - 50k	Jack, Kobi	Driver spoke to mechanic about truck feels like ass end is sliding out around corners inspected rear end bushes knock in LHF inspected Greased clutch Topped up fluids		\$670.98
T-328	27/04/2021			Cap and case		8x cap and case	103057	\$3,720.00
R-1136	23/04/2021	595382		Exhaust	Jack	extend exhaust		\$209.00
R-1118	12/04/2021	587821	0	Windscreen Washers		replace windscreen wiper blades		\$134.93
R-1107	08/04/2021	584639	0	Add Oil	Driver			\$28.90
T-312	24/03/2021			Call out fee, Cap and case, Road Service		1x Call out fee 2x road service - after hours 1x recamic cap and case 1x truck tyre disposal	102659	\$1,051.50
T-303	22/03/2021			Strip & Fit		1x strip and fit 1x truck tyre disposal	102633	\$88.50
S-2038	19/03/2021	575323	0	A - Fortnightly	Dylan, Kobi			\$165.00
R-974	17/03/2021	543784	0	Suspension		inspected suspension nothing found wrong with suspension		\$71.50

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-585	17/03/2021	519282		Bunk Air Con		after treat check engine lights on again NO AC FOR SLEEPING CUSTOM AIR DUS NOT START RUN OR DO ANYTHING F#530 21/12/20 Same as #R616. Investigation on going Truck to custom air 9/2/21 Delayed through Cost		\$0.00
R-1062	15/03/2021	566157		Steering	Steve T	Steering column inspected, new gas strut ordered. Arrived 11/3/21 Replace gas strut part no 499080c		\$760.10
T-270	03/03/2021			New		1x strip and fit	102411	\$72.00
S-1957	19/02/2021	556018	0	D - 300k	Dylan			\$979.57
S-1947	13/02/2021	551653	0	A - Fortnightly	Dylan			\$165.00
S-1941	13/02/2021	551653	0	A - Fortnightly	Dylan	D service due in 4000 kms		\$165.00
R-938	15/01/2021	611784	0	Ad Blue Tank		New fault logged 8/1 Inspected on 18/5/21 no leak present driver said not leaking		\$93.50
R-780	13/01/2021	517998	0	Turbo		Vehicle test driven, suspect waste gate issue .Monitoring. New waste gate diaphragm fitted by Inland - Check and repair Ad Blue leak around exhaust upright turbo watergate clip		\$1,433.99
S-1636	05/01/2021	527071	0	A - Fortnightly	Kobi	Front drive shocks need replacing at next service Needs hot wash Exhaust clamp and gasket broken and leaking add blue Refitted turbo waste gate fixed turbo boost issue		\$890.14
R-848	29/12/2020	523561	0	Ad Blue Tank	Kobi	New elbow fitted		\$80.12

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-747	09/12/2020	510967		Defect, Marker Lights, Windscreen Cracked	n	Offending marker lights removed. Windscreens replaced DEFECT CLEARED		\$484.00
S-902	01/12/2020	505097	0	B - 50k	Dylan, Jack			\$764.28
T-192	20/11/2020			Strip & Fit		2x strip and fit	101133	\$132.00
R-654	07/11/2020	48921	0	Shock Absorbers	Dylan, Steve T	New shock absorbers fitted to both front steer wheels and both rear drive wheels		\$1,462.69
T-178	03/11/2020			New, Strip & Fit		2x Michelin 1x truck tyre disposal 1x strip and fit	100917	\$1,622.50
R-673	02/11/2020	486357	0	Windscreen Chip		Vehicle was defected prior to replacement of new windscreen, which was booked in for 9/12/20		\$0.00
T-173	30/10/2020	481822	0	Cap		1 x Second hand tyre 1 x Tyre disposal	100882	\$261.50
R-641	27/10/2020	481110	0	Wiper Blades	Steve T			\$35.75
O-100	19/10/2020	0	0	Registration				\$4,599.15
O-101	19/10/2020	0	0	CTP				\$1,981.19
R-616	15/10/2020	473554	0	Bunk Air Con	Custom Air	Same job as #R585		
S-728	03/10/2020	465707	0	A - Fortnightly	Yard			\$165.00
R-540	01/10/2020	448750		Oil Leak, Power Steering		Went to Inland and be repaired under warranty Waiting on invoice		
S-741	22/09/2020	0	0	A - Fortnightly	Yard			\$165.00
R-580	19/09/2020			Speed Alert	Jack	Install Hummingbird Speed alert device		\$224.85



Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
T-150	18/09/2020			Rotate, Tyre Pressures		1x rotate tyres 1x drive rotation and pressure check	100441	\$200.00
S-637	05/09/2020	448750	0	B - 50k	Dylan, Jack, Kobi			\$609.51
R-541	28/07/2020	421890		Door Lock	Jack			\$424.34
S-635	25/07/2020	419952	0	A - Fortnightly	Yard			\$165.00
R-528	24/07/2020	419716		Clutch Adjustment		Greased clutch		\$58.76
R-529	18/07/2020	406537		Power Performance			162961	\$317.99
R-530	01/07/2020			Electrical	Jack			\$448.25
R-531	25/06/2020			Shock Absorbers	Dylan, Kobi	Replace shocks KWK374-38K1T labour 1.5 hrs Kobi & Dylan		\$382.92
S-639	20/06/2020	397678	0	C - 150k	Yard	Completed C Service		\$981.37
R-532	12/06/2020	391036		Wiper Blades	Yard			\$78.32
S-634	25/05/2020	377740	0	A - Fortnightly	Mick	Both LHD shocks leaking		\$165.00
S-641	08/05/2020	0	0	D - 300k	Yard	Completed		\$1,353.74
R-533	28/04/2020			Doors	Jack			\$287.42
R-534	22/04/2020	350295		Exhaust		Inland Truck Centre Repaired	162215	\$434.86
S-638	08/04/2020	345325	0	B - 50k	Dylan, Mick, Yard	1 x LF1400nn oil filter 1 x FF5776 fuel filter 1 x K37-1029 fuel/water separator 46 litres engine oil Bunk cooler serviced 1 x LF689 oil filter 2 litres engine oil Done By Gus, Michael, Dylan		\$604.73
R-535	07/04/2020	344945		Air Leak	Yard	Checked for external air leaks (no fault found)		\$35.75

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-536	27/03/2020	337097		Battery	Yard	4 x new batteries fitted		\$858.00
R-537	15/03/2020	327762		Oil Leak, Water Leak	Driver	Add 5.5lt of oil and 3lt of coolant		\$55.33
T-134	11/03/2020	0	0	New			140109	\$1,556.50
R-538	27/02/2020			Defect, Windscreen Cracked	n	Replaced windscreen & wiper blades DEFECT CLEARED		\$572.09
T-132	25/02/2020	0	0	Puncture			140067	\$187.00
R-527	20/02/2020			Clearance Lights, Lights	Jack	Reconnect electrical connector from accident repair		\$35.75
R-526	19/02/2020	290448		Body Repairs	Yard	Repaired		\$258.50
S-640	18/02/2020	309644	0	C - 150k	Yard			\$948.65
S-636	03/01/2020	277923	0	B - 50k	Yard	Topped up grease pot and battery water		\$981.35
S-1059	27/11/2019	0	0	A - Fortnightly		4ltr engine oil. Replace RF drive shock & LF drive shock, lower bushes (no part numbers)		\$183.04
S-1061	11/10/2019	240937	0	A - Fortnightly				\$165.00
S-1058	04/10/2019	235943	0	A - Fortnightly		Coolant & adblue filters replaced		\$244.99
S-1062	16/09/2019	225008	0	A - Fortnightly		Check underside of truck & tyres only		\$78.76
R-807	03/09/2019			Mud Guard		Replace RHR mudguard		\$159.30
S-1060	30/08/2019	214552	0	B - 50k		Shock rubber RHF drive		\$587.41
S-1256	12/08/2019	200735	0	A - Fortnightly				\$165.00
S-1633	05/04/2019	108740	0	B - 50k		Top up grease pot & batteries		\$587.41
S-1658	23/03/2019	99771	0	A - Fortnightly				\$165.00



Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-539	20/03/2019			Defect		Inland Invoice x2 Speedometers Marulan CLEARED DEFECT 20-03-19		
R-1766				Oil Leak	51693			\$0.00
R-1768				Windscreen Washers	817850			\$0.00
108 Records							TOTAL:	\$72,424.08