

Work Order History

Work Order ID	Equipment ID	Material Cost	Trade Cost	Service Cost	Other Costs	Tax Cost	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0042443	1388	0.00	374.40	0.00	0.00	0.00	374.40	\$68.40	639099		STRIP FOR TRADE	18/07/2023	24/07/2023
R122-0062360	1388	0.00	135.60	0.00	0.00	0.00	135.60	\$0.00	638579		DRIVERS WINDOW INOPERATIVE	10/07/2023	10/07/2023
R122-0062108	1388	231.76	0.00	0.00	0.00	0.00	231.76	\$231.76	638553		REPLACE SUZI COILS	29/06/2023	29/06/2023
R122-0062064	1388	444.52	354.00	0.00	0.00	0.00	798.52	\$444.52	638553		REFIT RADIATOR AFTER RETURNING FROM BRISBANE	27/06/2023	28/06/2023
R140-0111957	1388	1830.00	0.00	0.00	0.00	0.00	1830.00	\$1,830.00	638553		REPAIRED IN SYDNEY - SENT TO SYDNEY	23/06/2023	
R122-0061756	1388	0.00	111.60	0.00	0.00	0.00	111.60	\$225.60	638216		AXLE GASKET LEAKING	14/06/2023	15/06/2023
R122-0061756	1388	8.12	114.00	0.00	0.00	0.00	122.12				REPLACED 7 PIN	14/06/2023	15/06/2023
R122-0061605	1388	33.80	0.00	0.00	0.00	3.38	37.18	\$37.18	637502		SERVICE ON 17367795 SYDN DEPOT 07-06-2023 HUBO 697017 07 Runout Tyre 295/80R22.5 - RTD - 7.0mm RN 7.0 Not Worth Retreading (NWR Run Flat or Under Inflated Qty SERVICES/ACCESSORIES REMARKS / SIZE: 1 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 7) 1 EA Tyre Removed replace coolant filter, heater tap leaking	7/06/2023	9/06/2023
R122-0061553	1388	52.10	489.60	0.00	0.00	0.00	541.70	\$541.70	637360		DATE: 16.05.2023 CUMMINS UNIT 1388	6/06/2023	7/06/2023
R120-0041687	1388	3547.93	1122.00	0.00	0.00	466.99	5136.92	\$5,136.92	635635		EGR ISSUE EGR valve and crankshaft speed sensor internal faults resolution in fault codes	16/05/2023	16/05/2023
R122-0060554	1388	422.42	159.60	0.00	0.00	0.00	582.02	\$1,170.52	630922		REPAIR COOLANT LEAK	1/05/2023	1/05/2023
R122-0060554	1388	432.50	315.60	0.00	0.00	0.00	748.10				REPLACE SEAT CUSHION	1/05/2023	1/05/2023
R122-0060541	1388	0.00	204.00	0.00	0.00	0.00	204.00	\$0.00	630922		breakdown at arndell park. no trailer lights	28/04/2023	29/04/2023
R122-0060506	1388	0.00	216.00	0.00	0.00	0.00	216.00	\$0.00	630922		repair fuel tank strap	27/04/2023	28/04/2023
R122-0060239	1388	1133.20	0.00	0.00	0.00	113.32	1246.52	\$1,246.52	630275		SERVICE ON 17162257 SYDN DEPOT 15-04-2023 HUBO 689679 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 09 69000154 - 295/80R22.5 BDL3 BANDAG CUS CC 1 2.0 Retread (recap) Customer Pull Point 10 69000154 - 295/80R22.5 BDL3 BANDAG CUS CC 1 2.0 Retread (recap) Customer Pull Point 11 69000154 - 295/80R22.5 BDL3 BANDAG CUS CC 1 2.0 Retread (recap) Customer Pull Point 12 69000154 - 295/80R22.5 BDL3 BANDAG CUS CC 1	15/04/2023	18/04/2023
R122-0060193	1388	0.00	38.40	0.00	0.00	0.00	38.40	\$0.00	630080		driver side cab fairing mount broken	14/04/2023	15/04/2023
R122-0059973	1388	157.46	15.60	0.00	0.00	0.00	173.06	\$157.46	628187		REPAIR AIR LEAK AT G/KNOB	5/04/2023	6/04/2023
R122-0059847	1388	7.56	45.60	0.00	0.00	0.00	53.16	\$7.56	628080		replace 7 pin plug	31/03/2023	1/04/2023
R122-0059759	1388	259.39	195.60	0.00	0.00	0.00	454.99	\$259.39	627419		REPLACE THROTTLE POSITION SENSOR	29/03/2023	31/03/2023

R122-0059772	1388	272.30	0.00	0.00	0.00	27.23	299.53	\$299.53	627419	SERVICE ON 17103710 SYDN DEPOT 29-03-2023 HUBO 686000 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 09 69000154 - 295/80R22.5 BDL3 BANDAG CUS ST 17.0 Not Worth Retreading (NWR) Impact Damage Qty SERVICES/ACCESSORIES REMARKS / SIZE: 1 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 9) 1 EA Tyre Removed	29/03/2023	30/03/2023
R122-0059463	1388	0.00	63.60	0.00	0.00	0.00	63.60	\$63.60	625737	ENGINE DERATING sent to cummins	17/03/2023	18/03/2023
R122-0059357	1388	1111.20	0.00	0.00	0.00	111.12	1222.32	\$1,222.32	624993	SERVICE ON 17038192 SYDN DEPOT 13-03-2023 HUBO 684088 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 09 69000154 - 295/80R22.5 BDL3 BANDAG CUS ST 1 1.5 Retread (recap) Customer Pull Point 10 69000154 - 295/80R22.5 BDL3 BANDAG CUS ST 1 1.5 Retread (recap) Customer Pull Point 11 69000154 - 295/80R22.5 BDL3 BANDAG CUS ST 1 1.5 Retread (recap) Customer Pull Point 12 69000154 - 295/80R22.5 BDL3 BANDAG CUS ST	13/03/2023	14/03/2023
R122-0059013	1388	44.00	0.00	0.00	0.00	4.40	48.40	\$48.40	622460	SERVICE ON 16984884 SYDN DEPOT 27-02-2023 HUBO 681639 Qty SERVICES/ACCESSORIES REMARKS / SIZE: 4 EA Tyre Rotation	28/02/2023	1/03/2023
R122-0058942	1388	180.99	56.40	0.00	0.00	0.00	237.39	\$3,331.78	622288	check engine light on	25/02/2023	28/02/2023
R122-0058942	1388	0.00	483.60	0.00	0.00	0.00	483.60			replace broken & missing bolts in l/h/r engine mount bracket on flywheel housing	25/02/2023	28/02/2023
R122-0058942	1388	1133.00	210.00	0.00	0.00	0.00	1343.00			REPLACE VT102	25/02/2023	28/02/2023
R122-0058942	1388	538.62	420.00	0.00	0.00	0.00	958.62			B SERVICE	25/02/2023	28/02/2023
R122-0058942	1388	86.43	36.00	0.00	0.00	0.00	122.43			REPLACE TANK STRAP RUBBER	25/02/2023	28/02/2023
R122-0058942	1388	165.14	24.00	0.00	0.00	0.00	189.14			REPLACE TORQUE ROD BUSHES	25/02/2023	28/02/2023
R122-0058856	1388	225.05	354.00	0.00	0.00	0.00	579.05	\$579.05	621404	replace door handle	21/02/2023	22/02/2023
R122-0058633	1388	162.13	675.60	0.00	0.00	0.00	837.73	\$862.61	620409	CHECK AIR LEAKS	10/02/2023	11/02/2023
R122-0058633	1388	24.88	566.40	0.00	0.00	0.00	591.28			replace governor line	10/02/2023	11/02/2023
R122-0058642	1388	0.00	0.00	148.11	0.00	14.81	162.92	\$162.92	620409	REPLACE AUTO GREASE CANISTER	10/02/2023	13/02/2023
R122-0057968	1388	71.21	129.60	0.00	0.00	0.00	200.81	\$1,204.96	618755	REPLACE HEADLAMP COVER CLIPS	13/01/2023	21/01/2023
R122-0057968	1388	112.96	26.40	0.00	0.00	0.00	139.36			replace turntable pads	13/01/2023	21/01/2023
R122-0057968	1388	250.84	516.00	0.00	0.00	0.00	766.84			replace guards	13/01/2023	21/01/2023

R122-0057968	1388	0.00	436.80	0.00	0.00	0.00	436.80			front bar bent	13/01/2023	21/01/2023
R122-0057968	1388	11.55	6.00	0.00	0.00	0.00	17.55			replace globes	13/01/2023	21/01/2023
R122-0057716	1388	70.00	2.40	0.00	0.00	0.00	72.40	\$70.00	618008	REPAIR TRACKING	4/01/2023	5/01/2023
R122-0057448	1388	197.06	230.40	0.00	0.00	0.00	427.46	\$197.06	617896	REPLACE SUZI LEADS	21/12/2022	22/12/2022
R122-0057433	1388	80.65	638.40	0.00	0.00	0.00	719.05	\$719.05	617896	truck is derating with no engine light	20/12/2022	21/12/2022
R122-0056799	1388	1167.00	0.00	0.00	0.00	116.70	1283.70	\$1,283.70	617660	SERVICE ON 16672427 SYDNEY DEPOT 26.11.2022 HUBO 665504 01 11001550 - 295/80R22.5 152/148J BS G611 CC 2.0 Retread (recap) Customer Pull Point 02 11001550 - 295/80R22.5 152/148J BS G611 CC 2.0 Retread (recap) Customer Pull Point 8 EA Tyre Rotation 33000085 - ROTATE TBR TYRE (Pos: 12-5, 11-6, 10-7, 9-8, 8-9, 7-10, 6-11, 5-12) 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 1, 2) 2 EA Tyre Removed - (Pos: 1, 2) -2 EA Case Credit replace suzi coils and 7 pin plug	28/11/2022	29/11/2022
R122-0056762	1388	81.91	56.40	0.00	0.00	0.00	138.31	\$94.87	617660	REPLACED DAMAGED REAR BAR.	25/11/2022	26/11/2022
R122-0056145	1388	117.99	738.00	0.00	0.00	0.00	855.99	\$1,385.93	617660	LIGHTS MUDGUARDS. REPLACE REAR AIRBAGS	5/11/2022	7/11/2022
R122-0056145	1388	529.94	111.60	0.00	0.00	0.00	641.54			washers dont work	5/11/2022	7/11/2022
R122-0056116	1388	0.00	105.60	0.00	0.00	0.00	105.60	\$255.58	617660	replace marker plates	3/11/2022	4/11/2022
R122-0056116	1388	35.98	114.00	0.00	0.00	0.00	149.98			BRAKES SLOW TO RELEASE & DRAGGING AFTER BEING APPLIED	3/11/2022	4/11/2022
R122-0055803	1388	0.00	272.40	0.00	0.00	0.00	272.40	\$0.00	617660	FIT REVERSE ALARM	22/10/2022	24/10/2022
R122-0055568	1388	32.88	0.00	0.00	0.00	0.00	32.88	\$32.88	617660	suzi coils leaking	13/10/2022	13/10/2022
R122-0055486	1388	43.00	144.00	0.00	0.00	0.00	187.00	\$144.00	617660	replace 7 pin plug and suzi fittings	10/10/2022	11/10/2022
R122-0055280	1388	22.85	81.60	0.00	0.00	0.00	104.45	\$22.85	617660	turntable handle bent	30/09/2022	1/10/2022
R122-0054634	1388	144.89	36.00	0.00	0.00	0.00	180.89	\$144.89	617660	REPLACE FRONT DRIVE AIRBAGS	3/09/2022	3/09/2022
R122-0054453	1388	528.78	447.60	0.00	0.00	0.00	976.38	\$1,966.47	617660	REPLACE HOT AIR HOSE	29/08/2022	30/08/2022
R122-0054453	1388	372.09	618.00	0.00	0.00	0.00	990.09			REPLACE SUZI FITTINGS	29/08/2022	30/08/2022
R122-0054283	1388	11.31	158.40	0.00	0.00	0.00	169.71	\$11.31	617660		23/08/2022	23/08/2022

R122-0053653	1388	1210.80	0.00	0.00	0.00	121.08	1331.88	\$1,331.88	617660	SERVICE ON 16228617 SYDN DEPOT 30.07.2022 HUBO 648629 09 69000637 - 295/80R22.5 BDRHT BANDAG STK CC 2.0 Not Worth Retreading (NWR 2nd Cap - No Commercial Value 10 69000637 - 295/80R22.5 BDRHT BANDAG STK CC 2.0 Not Worth Retreading (NWR 2nd Cap - No Commercial Value 11 69000637 - 295/80R22.5 BDRHT BANDAG STK CC 2.0 Not Worth Retreading (NWR 2nd Cap - No Commercial Value 12 69000637 - 295/80R22.5 BDRHT BANDAG STK CC 2.0 Not Worth Retreading (NWR 2nd Cap - No Commercial Value 4 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 9, 10, 11, 12) 4 EA Tyre Removed 33000241 - SCRAP TYRES TBR (Pos: 9, 10, 11, 12) 6	1/08/2022	9/08/2022
R122-0053312	1388	0.00	114.75	55.42	0.00	0.00	170.17	\$55.42	617660	REPLACE VOLTMETER	15/07/2022	16/07/2022
R122-0053298	1388	263.59	240.00	0.00	0.00	0.00	503.59	\$480.97	617660	turntable jaw bent	14/07/2022	15/07/2022
R122-0053227	1388	133.09	191.25	0.00	0.00	0.00	324.34	\$191.25	617660	replace RHR height control valve	11/07/2022	12/07/2022
R122-0052697	1388	629.52	210.00	0.00	0.00	0.00	839.52	\$2,127.85	617660	B SERVICE	22/06/2022	25/06/2022
R122-0052697	1388	471.80	62.25	0.00	0.00	0.00	534.05			REPLACE ENGINE MOUNTS	22/06/2022	25/06/2022
R122-0052697	1388	108.32	88.50	0.00	0.00	0.00	196.82			REPLACE FUEL TANK CROSSOVER BUSHES	22/06/2022	25/06/2022
R122-0052697	1388	107.42	42.75	0.00	0.00	0.00	150.17			REPLACE L/H/R BRAKE SHOES	22/06/2022	25/06/2022
R122-0052697	1388	261.04	146.25	0.00	0.00	0.00	407.29			REPLACE L/H/F AIRBAG	22/06/2022	25/06/2022
R122-0052697	1388	0.00	76.50	0.00	0.00	0.00	76.50			REPLACE TURNTABLE HANDLE	22/06/2022	25/06/2022
R122-0052650	1388	137.80	0.00	0.00	0.00	0.00	137.80	\$137.80	617660	turntable arm bent	21/06/2022	21/06/2022
R122-0052300	1388	90.18	594.00	0.00	0.00	0.00	684.18	\$626.72	617660	whistle noise under load	3/06/2022	4/06/2022
R122-0052145	1388	7.24	112.50	0.00	0.00	0.00	119.74	\$7.24	617660	REPLACE ELECTRICAL PLUG	31/05/2022	31/05/2022
R122-0052194	1388	1169.20	0.00	0.00	0.00	116.92	1286.12	\$1,286.12	617660	SERVICE ON 15902187 SYDN DEPOT 30-05-2022 HUBO: 637304 05 69000637 - 295/80R22.5 BDRHT BANDAG STK CC 2.0 Not Worth Retreading (NWR End of tyre life 06 69000637 - 295/80R22.5 BDRHT BANDAG STK CC 2.0 Not Worth Retreading (NWR End of tyre life 07 69000637 - 295/80R22.5 BDRHT BANDAG STK CC 2.0 Not Worth Retreading (NWR End of tyre life 08 69000637 - 295/80R22.5 BDRHT BANDAG STK CC 2.0 Not Worth Retreading (NWR End of tyre life Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 FA	31/05/2022	3/06/2022
R122-0051929	1388	0.00	69.75	0.00	0.00	0.00	69.75	\$0.00	617660	fuel tank has shifted	18/05/2022	19/05/2022
R122-0051775	1388	43.87	152.25	0.00	0.00	0.00	196.12	\$1,265.22	617660	replace guards	11/05/2022	12/05/2022
R122-0051775	1388	452.52	444.75	0.00	0.00	0.00	897.27			torque rod bushes	11/05/2022	12/05/2022
R122-0051775	1388	27.08	144.75	0.00	0.00	0.00	171.83			fuel tank strap	11/05/2022	12/05/2022

R122-0051682	1388	0.00	65.25	0.00	0.00	0.00	65.25	\$0.00	617660	STRAIGHTEN TURNTABLE HANDLE	9/05/2022	10/05/2022
R122-0051159	1388	130.70	192.75	0.00	0.00	0.00	323.45	\$130.70	617660	REPLACE TURNTABLE HANDLE	14/04/2022	19/04/2022
R122-0050607	1388	0.00	87.75	0.00	0.00	0.00	87.75	\$0.00	617660	CHECK BRAKE PEDAL	24/03/2022	24/03/2022
R122-0050499	1388	0.00	0.00	9.19	0.00	0.92	10.11	\$10.11	617660	BOLTS FOR ENGINE MOUNTS	21/03/2022	22/03/2022
R122-0050480	1388	0.00	15.00	0.00	0.00	0.00	15.00	\$0.00	617660	engine mount missing bolts	18/03/2022	23/03/2022
R122-0050165	1388	0.00	47.25	0.00	0.00	0.00	47.25	\$0.00	617660	adjusting bolt bent	11/03/2022	12/03/2022
R122-0049833	1388	94.40	256.50	0.00	0.00	0.00	350.90	\$350.90	617660	DRIVER REPORTED HARD STEERING FOUND AUTO GREASER INOPERATIVE GREASE FRONT END MANUALLY REPLACE STEERING SHAFT UNIVERSAL JOINTS	5/03/2022	7/03/2022
R122-0049833	1388	0.00	170.25	0.00	0.00	0.00	170.25				5/03/2022	7/03/2022
R122-0049292	1388	0.00	18.75	0.00	0.00	0.00	18.75	\$18.75	617660	Clutch needs adjusting, Turntable needs adjusting	19/02/2022	21/02/2022
R122-0049292	1388	0.00	15.00	0.00	0.00	0.00	15.00			Clutch needs adjusting, Turntable needs adjusting	19/02/2022	21/02/2022
R122-0048662	1388	65.00	72.75	0.00	0.00	0.00	137.75	\$65.00	617660	REPLACE GPS AERIAL	3/02/2022	4/02/2022
R122-0048225	1388	1320.00	50.25	0.00	0.00	0.00	1370.25	\$1,320.00	574616	REPLACE IVU	22/01/2022	22/01/2022
R122-0048180	1388	3.35	57.75	0.00	0.00	0.00	61.10	\$59.60	574546	CHECK GUARDIAN SYSTEM	20/01/2022	24/01/2022
R122-0047981	1388	145.24	65.25	0.00	0.00	0.00	210.49	\$258.03	574030	REPLACE PRESSURE SENSOR	13/01/2022	14/01/2022
R122-0047981	1388	47.54	90.00	0.00	0.00	0.00	137.54			REPLACE HOOD LATCH	13/01/2022	14/01/2022
R122-0047967	1388	1058.00	0.00	0.00	0.00	105.80	1163.80	\$1,163.80	574012	SERVICE ORDER 15557679 SYDN DEPOT 12.01.2022 ODO 618107 P1722-0010745	12/01/2022	18/01/2022
R122-0047637	1388	0.00	122.25	0.00	0.00	0.00	122.25	\$308.25	572534	Clutch doesn't feel right, Turntable doesn't always lock in	30/12/2021	30/12/2021
R122-0047637	1388	0.00	186.00	0.00	0.00	0.00	186.00			Clutch doesn't feel right, Turntable doesn't always lock in	30/12/2021	30/12/2021
R122-0047554	1388	127.01	81.00	0.00	0.00	0.00	208.01	\$127.01	572170	EBS lead missing	23/12/2021	23/12/2021
R122-0046546	1388	0.00	77.25	0.00	0.00	0.00	77.25	\$0.00	570174	fuel tank shifted	29/11/2021	30/11/2021
R122-0046313	1388	1010.00	0.00	0.00	0.00	101.00	1111.00	\$1,111.00	610000	SERVICE ORDER 15394062 SYDN DEPOT 23.11.2021 ODO 609711	23/11/2021	25/11/2021
R122-0046274	1388	387.19	16.50	0.00	0.00	0.00	403.69	\$1,790.41	610000	11001550 - 295/80R22.5 152/148J BS G611 01-02 33000051 - BALANCE TBR (Pos: 1, 2) 33000084 - FIT TBR TYRE (Pos: 1, 2) 33000085 - ROTATE TBR TYRE (Pos: 2-1, 12-5, 11-6, 10-7, 9-8, 8-9, 7-10, 6-11, 5-12) 33000050 - FLIP TRUCK TYRE OR RETREAD (Pos: 1) 77000194 SIZE: CASE STOCK 295/80-22.5 (Pos: 2)	22/11/2021	24/11/2021
R122-0046274	1388	463.51	435.00	0.00	0.00	0.00	898.51			seat base	22/11/2021	24/11/2021
R122-0046274	1388	160.22	138.75	0.00	0.00	0.00	298.97			B-SERVICE ISX EGR CUMMINS	22/11/2021	24/11/2021
R122-0046274	1388	54.24	135.00	0.00	0.00	0.00	189.24			REPLACE HEADLAMP PROTECTOR	22/11/2021	24/11/2021
R122-0046036	1388	96.15	328.50	0.00	0.00	0.00	424.65	\$328.50	569262	REPLACE FRONT DRIVE AXLE SHOCK BUSHES	22/11/2021	24/11/2021
R122-0045902	1388	72.69	5.25	0.00	0.00	0.00	77.94	\$77.94	568909	turntable handle bent	17/11/2021	18/11/2021
R122-0045466	1388	0.00	171.00	0.00	0.00	0.00	171.00	\$0.00	567961	suzi connection leaking	15/11/2021	16/11/2021
R122-0045172	1388	21.61	395.25	0.00	0.00	0.00	416.86	\$21.61	567041	fuel tank has shifted	3/11/2021	4/11/2021
R122-0044504	1388	0.00	13.50	0.00	0.00	0.00	13.50	\$0.00	565151	REPLACE TURBO MOUNT GASKET & STUDS	26/10/2021	27/10/2021
R122-0043508	1388	393.46	107.25	0.00	0.00	0.00	500.71	\$393.46	561534	TRAILER LIGHTS NOT WORKING	6/10/2021	6/10/2021
R122-0043427	1388	159.00	0.00	0.00	0.00	15.90	174.90	\$174.90	561375	REPLACE UHF	2/09/2021	3/09/2021
R122-0043129	1388	56.48	112.50	0.00	0.00	0.00	168.98	\$56.48	560994	SERVICE ORDER 15048302 SYDN DEPOT 31.08.20212 ODO 595160	31/08/2021	2/09/2021
R122-0042755	1388	13.82	213.75	0.00	0.00	0.00	227.57	\$183.08	559879	Runout Tyre 295/80R22.5 - RTD - 6.0mm 02 33000085 - ROTATE TBR TYRE (Pos: 2-1, 12-5, 11-6, 10-7, 9-8, 8-9, 7-10, 6-11, 5-12) 33000051 - BALANCE TBR (Pos: 1, 2) 33000084 - FIT TBR TYRE (Pos: 2) 33000050 - FLIP TRUCK TYRE OR RETREAD (Pos: 1) 77000194 SIZE: CASE STOCK 295/80-22.5 (Pos: 2)	23/08/2021	24/08/2021
R122-0042755	1388	51.51	117.75	0.00	0.00	0.00	169.26			REPLACE TURNTABLE WEAR PAD	10/08/2021	11/08/2021
R122-0042187	1388	461.08	172.50	0.00	0.00	0.00	633.58	\$461.08	557904	REPLACE TRAILER FITTINGS	10/08/2021	11/08/2021
R122-0041646	1388	0.00	121.50	0.00	0.00	0.00	121.50	\$121.50	556502	REPLACE PP7 VALVE	22/07/2021	23/07/2021
R122-0041527	1388	0.00	149.25	0.00	0.00	0.00	149.25	\$369.72	556370	Call out to Pacific National Chullora Check engine no start - Possible battery fault	8/07/2021	9/07/2021
R122-0041527	1388	125.93	84.75	0.00	0.00	0.00	210.68			REPLACE RIGHT HAND REAR BRAKE LIGHT ASSEMBLY (used 2nd hand parts)	6/07/2021	8/07/2021
R122-0041527	1388	9.79	189.00	0.00	0.00	0.00	198.79			SUSPENSION	6/07/2021	8/07/2021
R122-0041475	1388	27.26	91.50	0.00	0.00	0.00	118.76	\$27.26	556268	TURNTABLE HANDLE BENT	6/07/2021	8/07/2021
R122-0041388	1388	35.20	131.25	0.00	0.00	0.00	166.45	\$35.20	556032	REPLACE AIR FITTING	5/07/2021	6/07/2021
R122-0040993	1388	42.24	117.75	0.00	0.00	0.00	159.99	\$42.24	555046	REPLACE TANK STRAP RUBBER	2/07/2021	2/07/2021
R122-0041032	1388	0.00	54.75	0.00	0.00	0.00	54.75	\$0.00	555046	LEAKING COOLANT OUT IF THE HEATER TAP	23/06/2021	24/06/2021
R122-0040675	1388	8.57	106.50	0.00	0.00	0.00	115.07	\$272.57	554115	REPLACE ISOLATOR	23/06/2021	24/06/2021
R122-0040675	1388	0.00	264.00	0.00	0.00	0.00	264.00			CLUTCH	12/06/2021	19/06/2021
R122-0040556	1388	174.92	45.00	0.00	0.00	0.00	219.92	\$328.25	553707	suzi coils leaking SECURE FITTINGS	12/06/2021	19/06/2021
R122-0040556	1388	39.33	69.00	0.00	0.00	0.00	108.33			REPLACED BENT HANDLE WITH 2ND HAND STRAIGHTENED HANDLE	9/06/2021	17/06/2021
R122-0040264	1388	0.00	2.25	0.00	0.00	0.00	2.25	\$0.00	553331	DOOR HANDLE FAULTY	9/06/2021	17/06/2021
R122-0039836	1388	0.00	253.50	0.00	0.00	0.00	253.50	\$123.75	552523	DASH GLOBES OUT	3/06/2021	4/06/2021
										Truck needs to be fogged	21/05/2021	22/05/2021
										HANDLE AND BAR BENT		

R122-0039632	1388	2103.00	0.00	0.00	0.00	210.30	2313.30	\$2,313.30	551892	SERVICE ORDER 14607719 SYDN DEPOT 14.05.2021 ODO 580179 69000637 - 295/80R22.5 BDRHT BANDAG STK 5-9 69000155 - 295/80R22.5 BDRHT BANDAG CUS 10-12 33000051 - BALANCE TBR (Pos: 1, 2) 33000540 - FLIP TRUCK TYRE OR RETREAD (Pos: 1, 2)	17/05/2021	18/05/2021
R122-0039430	1388	0.00	42.75	0.00	0.00	0.00	42.75	\$0.00	551295	HANDLE BENT	10/05/2021	11/05/2021
R122-0039379	1388	20.92	66.00	0.00	0.00	0.00	86.92	\$66.00	551151	FUEL FILTER LEAKING	7/05/2021	8/05/2021
R122-0039228	1388	20.92	90.00	0.00	0.00	0.00	110.92	\$20.92	550477	REPLACE FUEL FILTER	4/05/2021	5/05/2021
R122-0039071	1388	0.00	186.00	0.00	0.00	0.00	186.00	\$0.00	550123	BRAKE LIGHTS NOT WORKING	29/04/2021	30/04/2021
R122-0038994	1388	0.00	87.75	0.00	0.00	0.00	87.75	\$0.00	549867	Brake lights are not working	27/04/2021	27/04/2021
R122-0038947	1388	18.15	87.75	0.00	0.00	0.00	105.90	\$865.07	549693	REPLACE MAIN AIR LINE COMPRESSOR TO AIR DRYER	23/04/2021	26/04/2021
R122-0038947	1388	0.00	130.50	0.00	0.00	0.00	130.50			CHASSIS CROSS BAR	23/04/2021	26/04/2021
R122-0038947	1388	360.91	297.75	0.00	0.00	0.00	658.66			B SERVICE	23/04/2021	26/04/2021
R122-0038568	1388	0.00	41.25	0.00	0.00	0.00	41.25	\$0.00	548873	TRAILER LIGHTS NW	14/04/2021	16/04/2021
R122-0037470	1388	0.00	111.00	0.00	0.00	0.00	111.00	\$0.00	544332	COOLANT LEAK	4/03/2021	6/03/2021
R122-0037491	1388	54.05	0.00	0.00	0.00	5.41	59.46	\$59.46	544332		4/03/2021	10/03/2021
R122-0037398	1388	36.83	0.00	0.00	0.00	0.00	36.83	\$172.99	544105	REFER- R122-0037053	2/03/2021	4/03/2021
R122-0037398	1388	55.91	80.25	0.00	0.00	0.00	136.16				2/03/2021	4/03/2021
R122-0037398	1388	0.00	212.25	0.00	0.00	0.00	212.25				2/03/2021	4/03/2021
R122-0037372	1388	55.91	75.00	0.00	0.00	0.00	130.91	\$75.00	544105	rear guards rubbed through	1/03/2021	2/03/2021
R122-0037380	1388	500.00	0.00	0.00	0.00	50.00	550.00	\$550.00	544105	SERVICE ORDER 14298677 SYDN DEPOT 01.02.2021 ODO 566832 11001550 - 295/80R22.5 152/1483 BS G611 02 33000051 - BALANCE TBR (Pos: 2) 33000084 - FIT TBR TYRE (Pos: 2) 77000194 - CASE STOCK 295/80-22.5 - POS	1/03/2021	4/03/2021
R122-0037053	1388	7603.60	3292.50	0.00	0.00	0.00	10896.10	\$14,198.59	543915	REPLACE CYLINDER HEAD FOUND FUEL IN COOLING SYSTEM	18/02/2021	26/02/2021
R122-0037053	1388	1011.69	189.00	0.00	0.00	0.00	1200.69			O/HAUL HORTON FAN	18/02/2021	26/02/2021
R122-0037053	1388	1174.73	234.00	0.00	0.00	0.00	1408.73			REPLACE OIL & COOLANT THERMOSTATS	18/02/2021	26/02/2021
R122-0037053	1388	177.72	2.25	0.00	0.00	0.00	179.97			CLEAN RADIATOR & INTERCOOLER CORES	18/02/2021	26/02/2021
R122-0037053	1388	302.81	111.00	0.00	0.00	0.00	413.81			REPLACED ALTERNATOR	18/02/2021	26/02/2021
R122-0037053	1388	45.29	54.00	0.00	0.00	0.00	99.29			REPLACED FUEL FILTERS	18/02/2021	26/02/2021
R122-0036895	1388	0.00	81.00	0.00	0.00	0.00	81.00	\$0.00	543660	Diesel leak around the motor	15/02/2021	15/02/2021
R122-0036818	1388	0.00	39.75	0.00	0.00	0.00	39.75	\$0.00	543577	apn config	12/02/2021	16/03/2021
R122-0036682	1388	14.81	0.00	0.00	0.00	0.00	14.81				8/02/2021	11/02/2021
R122-0036682	1388	176.27	0.00	0.00	0.00	0.00	176.27			REPLACE FLOOR MATS	8/02/2021	11/02/2021
R122-0035546	1388	57.23	136.50	0.00	0.00	0.00	193.73	\$57.23	538477	WEAR PAD MISSING ON TURNTABLE	29/12/2020	30/12/2020
R122-0035187	1388	100.94	176.25	0.00	0.00	0.00	277.19	\$100.94	536811	refer transmission job- r122-0035044	11/12/2020	14/12/2020
R122-0035143	1388	272.25	0.00	0.00	0.00	27.23	299.48	\$299.48	536811	R/R TRANSMISSION JUMPING OUT OF DIRECT OR 17TH GEAR REFER REPAIR ORDER- R122-0035044	10/12/2020	11/12/2020
R122-0035150	1388	980.00	0.00	0.00	0.00	98.00	1078.00	\$1,078.00	536811	SERVICE ORDER 14007913 SYDN DEPOT 10.12.2020 ODO 554082	10/12/2020	11/12/2020
R122-0035091	1388	1282.00	0.00	0.00	0.00	155.70	1437.70	\$1,437.70	536811	R/R TRANSMISSION JUMPING OUT OF DIRECT OR 17TH GEAR \lang1033 REFER JOB- R122-0035044 \10	8/12/2020	10/12/2020
R122-0035044	1388	2100.16	2917.50	0.00	0.00	0.00	5017.66	\$5,841.72	536736	R/R TRANSMISSION JUMPING OUT OF DIRECT OR 17TH GEAR	5/12/2020	11/12/2020
R122-0035044	1388	201.03	201.00	0.00	0.00	0.00	402.03			REPLACE GUARDS & MUDFLAPS	5/12/2020	11/12/2020
R122-0035044	1388	0.00	151.50	0.00	0.00	0.00	151.50			R/R L/H FUEL TANK LEAKING	5/12/2020	11/12/2020
R122-0035044	1388	41.55	172.50	0.00	0.00	0.00	214.05			REPAIR A/C	5/12/2020	11/12/2020
R122-0035044	1388	56.48	167.25	0.00	0.00	0.00	223.73				5/12/2020	11/12/2020
R122-0035046	1388	0.00	178.50	0.00	0.00	0.00	178.50	\$0.00	536736	A/C NOT WORKING	5/12/2020	11/12/2020
R122-0034455	1388	14.50	234.00	0.00	0.00	0.00	248.50	\$248.50	533646	SHORT IN TRAILER WIRING @ STAR TRACK	11/11/2020	12/11/2020
R122-0034367	1388	85.05	138.75	0.00	0.00	0.00	223.80	\$223.80	533428	LED heallight replaced	9/11/2020	9/11/2020
R122-0034318	1388	400.50	483.00	0.00	0.00	0.00	883.50	\$883.50	533128	B-SERVICE ISX EGR CUMMINS	6/11/2020	6/11/2020
R122-0034086	1388	75.10	37.50	0.00	0.00	0.00	112.60	\$112.60	532598	REPLACE SUZY COILS	27/10/2020	28/10/2020
R122-0033889	1388	7.25	37.50	0.00	0.00	0.00	44.75	\$44.75	531989	C/A CLUTCH	17/10/2020	20/10/2020
R140-0073706	1388	2200.00	0.00	0.00	0.00	0.00	2200.00	\$2,200.00	530827		6/10/2020	6/10/2020
R122-0033317	1388	0.00	37.50	0.00	0.00	0.00	37.50	\$559.98	528757	ADJUST CLUTCH - TOP UP THE OIL	16/09/2020	17/09/2020
R122-0033317	1388	54.78	425.25	0.00	0.00	0.00	480.03			REPLACE MISSING BOLTS IN ENGINE MOUNT BRACKETS	16/09/2020	17/09/2020
R122-0033317	1388	4.95	37.50	0.00	0.00	0.00	42.45			REPLACE HEADLIGHT GLOBE	16/09/2020	17/09/2020
R122-0033088	1388	505.00	0.00	0.00	0.00	50.50	555.50	\$555.50	527762	SERVICE ORDER 13589376 SYDN DEPOT 04.09.2020 ODO 538047 11001550 - 295/80R22.5 152/1483 BS G611 POS 1 33000051 - BALANCE TBR 1 33000084 - FIT TBR TYRE - POS 1 77000194 SIZE: CASE STOCK 295/80-22.5 - POS	4/09/2020	9/09/2020
R122-0032800	1388	34.63	192.75	0.00	0.00	0.00	227.38	\$227.38	526220	REPLACE LH FUEL TANK STRAP RUBBER	20/08/2020	21/08/2020
R122-0032641	1388	0.00	86.25	0.00	0.00	0.00	86.25	\$86.25	525876	Clutch needs to be adjusted	13/08/2020	13/08/2020
R122-0032315	1388	7.18	150.00	0.00	0.00	0.00	157.18	\$157.18	524435	CHECK COOLANT LEAK	27/07/2020	28/07/2020
R122-0032287	1388	0.00	111.00	0.00	0.00	0.00	111.00	\$111.00	524428	L/H FRONT INDICATOR NOT WORKING	25/07/2020	25/07/2020
R122-0032169	1388	22.50	37.50	0.00	0.00	0.00	60.00	\$1,362.16	523872	CHECK AND ADJ CLUTCH AND SECURE GEAR KNOB	20/07/2020	23/07/2020
R122-0032169	1388	244.05	155.25	0.00	0.00	0.00	399.30			REPLACE RHR TORQUE ROD BUSH	20/07/2020	23/07/2020
R122-0032169	1388	722.86	180.00	0.00	0.00	0.00	902.86			REPLACE LHR AUTOMATIC SLACK ADJUSTER	20/07/2020	23/07/2020
R122-0031989	1388	4.95	51.00	0.00	0.00	0.00	55.95	\$55.95	523003	REPLACE LH HEADLIGHT GLOBE	10/07/2020	11/07/2020
R122-0031884	1388	43.22	62.25	0.00	0.00	0.00	105.47	\$105.47	522232	REPLACE RH HOOD LATCH	6/07/2020	7/07/2020
R122-0031162	1388	25.00	52.50	0.00	0.00	0.00	77.50	\$77.50	519879	REPLACED SD CARD	4/06/2020	4/06/2020

R122-0031143	1388	264.28	150.00	0.00	0.00	0.00	414.28	\$414.28	519860	ROAD SERVICE TO COSTCO EASTERN CREEK RETURN TO W/SHOP & REPLACE GFARSTICK	3/06/2020	4/06/2020
R122-0031136	1388	3.07	140.25	0.00	0.00	0.00	143.32	\$143.32	519860	REPLACE RHF DRIVE AXLE GASKET	2/06/2020	4/06/2020
R122-0030986	1388	68.00	37.50	0.00	0.00	0.00	105.50	\$105.50	519860	REPLACE SUZY COILS	27/05/2020	29/05/2020
R122-0030364	1388	0.00	1.50	0.00	0.00	0.00	1.50	\$1.50	517825	BOOK OUT PARTS	29/04/2020	30/04/2020
R122-0030187	1388	49.84	82.50	0.00	0.00	0.00	132.34	\$1,158.38	517823	SECURE REAR ENGINE MOUNTS	20/04/2020	22/04/2020
R122-0030187	1388	166.57	227.25	0.00	0.00	0.00	393.82			RELINE REAR DRIVE AXLE BRAKES	20/04/2020	22/04/2020
R122-0030187	1388	412.47	219.75	0.00	0.00	0.00	632.22			B-SERVICE ISX EGR CUMMINS	20/04/2020	22/04/2020
R122-0029913	1388	42.39	15.00	0.00	0.00	0.00	57.39	\$57.39	516167	Battery cover is missing	6/04/2020	8/04/2020
R120-0029620	1388	0.00	116.25	0.00	0.00	0.00	116.25	\$116.25	515817	MAKE BATTERY BOX	1/04/2020	1/04/2020
R122-0029459	1388	24.81	43.50	0.00	0.00	0.00	68.31	\$68.31	512002	REPLACE SD CARD AS REQUESTED	14/03/2020	16/03/2020
R122-0029293	1388	35.42	108.75	0.00	0.00	0.00	144.17	\$533.92	511894	REPLACE R/H/R GUARD	5/03/2020	10/03/2020
R122-0029293	1388	0.00	52.50	0.00	0.00	0.00	52.50			REPAIR FIRE EXTINGUISHER	5/03/2020	10/03/2020
R122-0029293	1388	230.00	107.25	0.00	0.00	0.00	337.25			REPLACE CUSHION	5/03/2020	10/03/2020
R122-0029306	1388	455.00	0.00	0.00	0.00	45.50	500.50	\$500.50	511894	SERVICE ORDER 12869063 SYDNEY DEPOT 05.03.2020 ODO 515446 POS 2	5/03/2020	10/03/2020
R122-0029117	1388	0.00	167.25	0.00	0.00	0.00	167.25	\$167.25	510491	Sentinel tablet keeps turning itself off	21/02/2020	22/02/2020
R122-0029122	1388	2360.00	0.00	0.00	0.00	236.00	2596.00	\$2,596.00	510491	8 X 295/80R22.5 BDL3 POSITION 5,6,7,8,9,10,11,12 8 X FIT 8 X SCRAP 8 X CHARGE FTSD-12826990	21/02/2020	24/02/2020
R122-0028889	1388	39.69	123.75	0.00	0.00	0.00	163.44	\$240.01	509224	Mirror light not working, stereo is not working	8/02/2020	12/02/2020
R122-0028889	1388	37.57	39.00	0.00	0.00	0.00	76.57			repair radio	8/02/2020	12/02/2020
R122-0028712	1388	0.00	247.50	0.00	0.00	0.00	247.50	\$247.50	507368	NO AIR CON	30/01/2020	30/01/2020
R122-0028656	1388	85.63	52.50	0.00	0.00	0.00	138.13	\$138.13	507204	Sentinel device is not getting power, air con is not workingSentinel device is not getting power, air con is not working	28/01/2020	28/01/2020
R122-0028642	1388	6.70	300.00	0.00	0.00	0.00	306.70	\$306.70	507204	A/HOURS CALL TO YARD REPAIR PARK LIGHTS	25/01/2020	25/01/2020
R122-0028548	1388	83.06	60.00	0.00	0.00	0.00	143.06	\$143.06	506373	replace t/table pad	21/01/2020	23/01/2020
R122-0028337	1388	116.37	77.25	0.00	0.00	0.00	193.62	\$193.62	505047	replace t/table handle bent by driver	10/01/2020	13/01/2020
R122-0027975	1388	0.00	148.50	0.00	0.00	0.00	148.50	\$148.50	502024	Sentinel device has no power	18/12/2019	19/12/2019
R122-0027976	1388	0.00	95.25	0.00	0.00	0.00	95.25	\$95.25	502024	NO TRAILER LIGHTS	18/12/2019	19/12/2019
R122-0027736	1388	0.00	187.50	0.00	0.00	0.00	187.50	\$816.72	500577	REPAIR MISSING ENGINE MOUNT BOLTS	5/12/2019	5/12/2019
R122-0027736	1388	40.67	159.75	0.00	0.00	0.00	200.42			REPLACE CAB SHOCK	5/12/2019	5/12/2019
R122-0027736	1388	75.34	147.75	0.00	0.00	0.00	223.09			REPLACE TOP RADIATOR HOSE	5/12/2019	5/12/2019
R122-0027736	1388	96.96	108.75	0.00	0.00	0.00	205.71			REPLACE TANK RUBBERS	5/12/2019	5/12/2019
R122-0027438	1388	87.74	107.25	0.00	0.00	0.00	194.99	\$468.07	498871	GUARDS ARE WORN OUT	22/11/2019	25/11/2019
R122-0027438	1388	198.08	75.00	0.00	0.00	0.00	273.08			REPLACE T/TABLE PAD	22/11/2019	25/11/2019
R122-0026907	1388	20.21	75.00	0.00	0.00	0.00	95.21	\$95.21	494660	DIESEL LEAK	28/10/2019	28/10/2019
R122-0026829	1388	0.00	51.00	0.00	0.00	0.00	51.00	\$51.00	494187	CANT GET SENTINEL DEVICE TO TURN ON	23/10/2019	24/10/2019
R122-0026788	1388	0.00	45.00	0.00	0.00	0.00	45.00	\$45.00	494022	SENTINEL DEVICE DOESN'T HAVE A PROGRAM IN IT	21/10/2019	22/10/2019
R122-0026792	1388	0.00	66.00	0.00	0.00	0.00	66.00	\$66.00	494022	DRIVERS SEATS DOESN'T GO UP HIGH ENOUGH,SENTINEL DOESN'T TURN ON,CRUISE CONTROL DOESN'T WORK,NO LEFT HAND INDICATORS,SEATBELT NOT RETRACTING properly	21/10/2019	24/10/2019
R122-0026634	1388	115.43	69.75	0.00	0.00	0.00	185.18	\$2,755.73	492668	ARM FOR TURNABLE IS BENT	12/10/2019	19/10/2019
R122-0026634	1388	540.00	122.25	0.00	0.00	0.00	662.25			replace l/face with new type	12/10/2019	19/10/2019
R122-0026634	1388	0.00	122.25	0.00	0.00	0.00	122.25			REPLACE ROOF LIGHT	12/10/2019	19/10/2019
R122-0026634	1388	433.01	174.00	0.00	0.00	0.00	607.01			B-SERVICE ISX EGR CUMMINS	12/10/2019	19/10/2019
R122-0026634	1388	483.32	294.00	0.00	0.00	0.00	777.32			REPLACE REAR ENGINE MOUNTS	12/10/2019	19/10/2019
R122-0026634	1388	0.00	125.25	0.00	0.00	0.00	125.25			REPLACE MAIN COMPRESSOR HOSE	12/10/2019	19/10/2019
R122-0026634	1388	276.47	0.00	0.00	0.00	0.00	276.47			REPAIR LEAK AT HEARER HOSES/VALVE	12/10/2019	19/10/2019
R122-0026120	1388	0.00	88.50	0.00	0.00	0.00	88.50	\$88.50	490158	REPAIR/REPLACE BENT T-TABLE HANDLE	16/09/2019	16/09/2019
R122-0026125	1388	0.00	0.00	6147.12	0.00	614.71	6761.83	\$6,761.83	490158	13.9.19 13	16/09/2019	17/09/2019
R122-0025920	1388	134.19	157.50	0.00	0.00	0.00	291.69	\$291.69	488463	REPLACE MISSING T-TABLE PAD	3/09/2019	3/09/2019
R122-0025419	1388	117.99	9.75	0.00	0.00	0.00	127.74	\$127.74	483387	L/H HEADLIGHT BLOWN	8/08/2019	8/08/2019
R122-0025278	1388	16.29	60.00	0.00	0.00	0.00	76.29	\$107.79	481706	12 volt socket not working, speed alarm not working	31/07/2019	1/08/2019
R122-0025278	1388	0.00	31.50	0.00	0.00	0.00	31.50			CHECK & REPAIR SPEED ALERT	31/07/2019	1/08/2019
R122-0025306	1388	(700.00)	0.00	0.00	0.00	(70.00)	(770.00)	-\$770.00	481706	REFER ORIGINAL INVOICE 8249994 (P122-0011692) REFUND CORE DEPOSIT	31/07/2019	31/07/2019
R122-0025265	1388	0.00	0.00	500.00	0.00	50.00	550.00	\$550.00	481377	18.7.19 1387 INSTALLATION OF GUARDIAN SERIAL NUMBER \cd0\522 P1001229-50001 0444\2 \cd0\11\16\16	30/07/2019	31/07/2019
R122-0025122	1388	3033.26	294.00	0.00	0.00	0.00	3327.26	\$4,119.01	480931	REPLACE AIR COMPRESSOR	23/07/2019	26/07/2019
R122-0025122	1388	182.75	182.25	0.00	0.00	0.00	365.00			REPLACE DRIVERS DOOR SEAL	23/07/2019	26/07/2019
R122-0025122	1388	0.00	177.75	0.00	0.00	0.00	177.75			STRAIGHTEN TRACK ROD	23/07/2019	26/07/2019
R122-0025122	1388	138.00	111.00	0.00	0.00	0.00	249.00			REPLACE R/H/R MUDGUARD	23/07/2019	26/07/2019
R122-0024809	1388	48.72	114.00	0.00	0.00	0.00	162.72	\$260.40	478254	REPLACE DOOR LATCH	3/07/2019	4/07/2019
R122-0024809	1388	97.68	0.00	0.00	0.00	0.00	97.68			REPLACE DOOR LATCH AND STRIKER	3/07/2019	4/07/2019
R122-0024531	1388	11.25	136.50	0.00	0.00	0.00	147.75	\$147.75	476815	REPLACE BRAKE LIGHT RELAY SWITCH	17/06/2019	20/06/2019
R122-0024437	1388	860.00	0.00	0.00	0.00	86.00	946.00	\$946.00	476074	2 X 295/80R22.5 G611 POSITION 1,2 2 X FIT 2 X TRADES FTSD-12001635	12/06/2019	13/06/2019
R122-0023878	1388	172.91	150.00	2.57	0.00	0.00	325.48	\$325.48	470851	DRIVERS DOOR COMING OPEN WHEEL DRIVING - SEAT CANT BE ADJUSTED	8/05/2019	16/05/2019
R122-0023833	1388	453.60	35.25	0.00	0.00	0.00	488.85	\$488.85	470784	REPLACE BATTERIES	6/05/2019	7/05/2019
R122-0023717	1388	1214.50	0.00	0.00	0.00	121.45	1335.95	\$1,335.95	470222	4 X 295/80R22.5 BDL3 POSITION 9,10,11,12 2 X ROTATE POSITION 2-1 1-2 4 X FIT 4 X SCRAP 4 X CHARGE 1 X VALVE FTSD-11855799	30/04/2019	1/05/2019
R122-0023516	1388	0.00	135.00	0.00	0.00	0.00	135.00	\$135.00	469077	CHECK BATTERIES TRUCK WILL NOT START	16/04/2019	16/04/2019
R122-0023069	1388	42.21	37.50	0.00	0.00	0.00	79.71	\$79.71	466789	Hand piece on uhf is not working	23/03/2019	25/03/2019
R122-0022635	1388	50.46	99.75	0.00	0.00	0.00	150.21	\$150.21	464607	REPLACE GOVERNOR VALVE	4/03/2019	4/03/2019
R122-0022561	1388	145.19	176.25	0.00	0.00	0.00	321.44	\$705.34	463936	B-SERVICE ISX EGR CUMMINS	26/02/2019	28/02/2019

R122-0022561	1388	0.00	0.00	383.90	0.00	0.00	383.90			GUYS AUTO ELECTRICS TO CHECK ABS LAMP ON AND FAULT CODES NO FAULT FOUND IN REAR SENSORS ADJUST ALL SPEED SENSORS LOCATE FAULTY CONNECTION IN CABIN FOR DATA TO ABS MODULE REPLACE ALL PANELS CLEAR CODES AND CHECK	26/02/2019	28/02/2019
R122-0022471	1388	0.00	123.75	0.00	0.00	0.00	123.75	\$123.75	463077	STRAIGHTEN T/TABLE HANDLE	20/02/2019	22/02/2019
R122-0022023	1388	0.00	0.00	2404.14	0.00	240.41	2644.55	\$2,644.55	459113	APPROVED BY BH 24.1.19 CODE:043-004-095 VGT ACTUATOR NOT COMMUNICATING- INTERNAL COMMUNICATION FAILURE FROM VGT ACTUATOR TO ECM-CAPPED COOLANT LINES AND CHANGED OUT VGT ACTUATOR AND CALIBRATED. REGO: BU36VK KLMS: 459 307	24/01/2019	24/01/2019
R122-0021907	1388	0.00	69.75	0.00	0.00	0.00	69.75	\$69.75	458632	CHECK ENGINE LIGHT ON TAKE TO CUMMINS FOR REPAIR	19/01/2019	21/01/2019
R122-0021804	1388	52.16	91.50	0.00	0.00	0.00	143.66	\$251.92	458241	REPLACE L/H/R LIGHT ASSY	15/01/2019	15/01/2019
R122-0021804	1388	55.76	52.50	0.00	0.00	0.00	108.26			REPLACE TRANS OIL PRESSURE SENSOR	15/01/2019	15/01/2019
R122-0021711	1388	1200.00	0.00	0.00	0.00	120.00	1320.00	\$1,320.00	457271	4 X 295/80 BDL3 POSITION 5,6,7,8 2 X ROTATE 4 X FIT 4 X SCRAP 4 X CHARGE FTSD-11542903	9/01/2019	10/01/2019
R122-0021076	1388	0.00	417.75	0.00	0.00	0.00	417.75	\$417.75	451525	REPAIR WIRING TO TRAILER PARK LIGHTS	29/11/2018	29/11/2018
R122-0020949	1388	0.00	142.50	0.00	0.00	0.00	142.50	\$142.50	450356	STRAIGHTEN T/TABLE HANDLE	22/11/2018	22/11/2018
R122-0020776	1388	171.84	37.50	0.00	0.00	0.00	209.34	\$209.34	448474	REPLACE TURNTABLE PADS	12/11/2018	13/11/2018
R122-0020669	1388	0.00	101.25	0.00	0.00	0.00	101.25	\$219.46	447620	CHECK ENGINE CODES LOW COOLANT	6/11/2018	7/11/2018
R122-0020669	1388	16.96	101.25	0.00	0.00	0.00	118.21			C/A CLUTCH	6/11/2018	7/11/2018
R122-0020572	1388	860.00	0.00	0.00	0.00	86.00	946.00	\$946.00	446814	2 X 295/80R22.5 G611 POSITION 1,2 2 X FIT 2 X TRADES FTSD-11334937	31/10/2018	1/11/2018
R122-0020364	1388	139.01	99.75	0.00	0.00	0.00	238.76	\$238.76	445288	REPLACE L/H/HEADLIGHT COVER	19/10/2018	20/10/2018
R122-0019938	1388	610.00	0.00	0.00	0.00	61.00	671.00	\$671.00	441132	SERVICE ON 112156525 SYDNEY DEP 21.9.18 HUBO 4409965 POS 9-10	24/09/2018	26/09/2018
R122-0019628	1388	0.00	0.00	455.00	0.00	45.50	500.50	\$500.50	437919	3.9.18 1388 KLMS 437622 \d0\fs17 Service call to workshop to check air conditioner system. Pressure test and locate damaged pipe on front radiator. Remove pipe and silver solder. Replace receiver drier and regas system. Check operation. PRESSURE TEST \$38.50 REGAS \$181.50 LABOUR X 3 \$ \d1\fs16	5/09/2018	5/09/2018
R122-0019588	1388	28.95	24.00	0.00	0.00	0.00	52.95	\$52.95	437629	REPLACE RECIEVER DRIER	3/09/2018	3/09/2018
R122-0019596	1388	72.20	0.00	0.00	0.00	0.00	72.20	\$72.20	437629	BOOK PARK BRAKE VALVE	3/09/2018	5/09/2018
R122-0019571	1388	75.70	492.75	0.00	0.00	0.00	568.45	\$568.45	437628	REPLACE PARK BRAKE VALVE REPAIR AIR LEAKS @ FIRE WALL AND AIR TANKS	1/09/2018	3/09/2018
R122-0019537	1388	0.00	87.75	0.00	0.00	0.00	87.75	\$170.62	437535	BAD AIR LEAK	31/08/2018	31/08/2018
R122-0019537	1388	24.37	58.50	0.00	0.00	0.00	82.87			REPLACED FUEL FILTER	31/08/2018	31/08/2018
R122-0019381	1388	423.79	7.50	0.00	0.00	0.00	431.29	\$431.29	432695	SUPPLY PARTS AS PARTS NOT BOOKED OUT ON PREVIOUS JOB	22/08/2018	22/08/2018
R122-0019361	1388	460.32	187.50	0.00	0.00	0.00	647.82	\$647.82	432695	B-SERVICE 1SX EGR CUMMINS	21/08/2018	22/08/2018
R122-0019294	1388	637.95	264.00	2710.57	0.00	0.00	3612.52	\$7,975.99	672289	REPLACE FLYWHEEL HOUSING	16/08/2018	22/08/2018
R122-0019294	1388	1525.33	1946.25	0.00	0.00	0.00	3471.58			REPLACE CLUTCH & FLYWHEEL	16/08/2018	22/08/2018
R122-0019294	1388	7.29	118.50	0.00	0.00	0.00	125.79			REPLACE PUMP GASKET	16/08/2018	22/08/2018
R122-0019294	1388	424.90	39.75	0.00	0.00	0.00	464.65			REPLACE CAB SHOCK	16/08/2018	22/08/2018
R122-0019294	1388	147.70	153.75	0.00	0.00	0.00	301.45			replace t/table pads	16/08/2018	22/08/2018
R122-0019175	1388	0.00	0.00	308.00	0.00	0.00	308.00	\$308.00	671427	ECM WON'T START. SENT ONE TO CUMMINS TO TRANSFER OVER	9/08/2018	10/08/2018
R122-0019146	1388	0.00	0.00	267.75	0.00	26.78	294.53	\$294.53	432695		8/08/2018	8/08/2018
R122-0019124	1388	20.48	201.00	0.00	0.00	0.00	221.48	\$221.48	432695	CHECK WIRING TO STARTER FINFOOUND ECM HAS FAILED 2ND HAND UNIT FROM BRISBANE EX1005 TAKEN TO CUMMINS WITH OLD ECM & ALL PARAMETERS SWAPPED TO NFW UNIT	6/08/2018	10/08/2018
R122-0019050	1388	0.00	152.25	0.00	0.00	0.00	152.25	\$152.25	431995	GEARBOX ISSUES - HARD TO SELECT GEARS	31/07/2018	31/07/2018
R122-0018932	1388	57.64	13.50	0.00	0.00	0.00	71.14	\$71.14	430601	REPLACE SUZY COILS	23/07/2018	24/07/2018
R122-0018506	1388	610.00	0.00	0.00	0.00	61.00	671.00	\$671.00	426137	2 X 295/80R22.5 BDL3 POSITION 11,12 2 X FIT 2 X SCRAP 2 X ROTATION 2 X CHARGE FTSD-10966802	25/06/2018	26/06/2018
R122-0018469	1388	348.16	285.75	0.00	0.00	0.00	633.91	\$870.54	425834	REPLACE L/H/R GUARD + STRAIGHTEN LIGHT BAR & REPAIR LIGHTS	22/06/2018	23/06/2018
R122-0018469	1388	137.63	99.00	0.00	0.00	0.00	236.63			REPLCE CAB SHOCK	22/06/2018	23/06/2018
R122-0018273	1388	0.00	231.00	0.00	0.00	0.00	231.00	\$231.00	423705	STRAIGHTEN REAR BUMPER	9/06/2018	9/06/2018
R122-0018197	1388	64.81	106.50	0.00	0.00	0.00	171.31	\$171.31	422678	REPAIR DAMAGE TO REAR LIGHT BAR & REPLACE INDICATOR	5/06/2018	5/06/2018
R122-0017931	1388	2135.00	15.00	551.10	0.00	0.00	2701.10	\$2,701.10	420537	SUPPLY PARTS	21/05/2018	22/05/2018
R122-0017849	1388	0.00	147.75	0.00	0.00	0.00	147.75	\$1,302.25	419735	REPLACE T/TABLE	16/05/2018	21/05/2018
R122-0017849	1388	260.00	178.50	0.00	0.00	0.00	438.50			REPLACE FRONT DIFF TORQUE ROD BUSHES	16/05/2018	21/05/2018
R122-0017849	1388	605.00	111.00	0.00	0.00	0.00	716.00			REPLACE I FACE	16/05/2018	21/05/2018
R122-0017731	1388	122.31	48.75	0.00	0.00	0.00	171.06	\$171.06	418403	FIT O/S T-TABLE PAD	9/05/2018	10/05/2018
R122-0017536	1388	0.00	45.00	0.00	0.00	0.00	45.00	\$45.00	416813	REFIT L/H/R MUDEFLAP	27/04/2018	27/04/2018
R122-0017508	1388	75.39	52.50	0.00	0.00	0.00	127.89	\$127.89	416307	REPLACE SUZY COIL SET	24/04/2018	26/04/2018
R122-0017392	1388	168.83	41.25	0.00	0.00	0.00	210.08	\$210.08	415007	WEAR PAD MISSING	17/04/2018	17/04/2018
R122-0017277	1388	0.00	0.00	3924.00	0.00	392.40	4316.40	\$4,316.40	412531	1388 - 9.4.18 BU36VK KLMS 413738 FAULT CODES - REMOVED AND REPLACED DPF AND DOSING INJECTOR AS A PART OF CAP PRICE 5292265 - INSULATOR THERMAL 3684355 - GASKET EXH OUT CONNECTION 4309454RX - RECON INJECTOR KIT APTREA 3684355 - GASKET EXH OUT CONNECTION 2871453 - GASKET ADAPT Q312533 4388409RX JFI-0704A - 7/6 IIC FEMALE FITTING 3 RSHT-04 - R5 BLUE HI TEM 3/16 HOS 4936622 - HOSE PLAIN Q667912 2866337 - GASKET AFM DEVICE	9/04/2018	13/04/2018
R122-0017257	1388	192.03	67.50	0.00	0.00	0.00	259.53	\$334.53	412473	REPLACE ENGINE BRAKE SWITCH	7/04/2018	7/04/2018
R122-0017257	1388	0.00	75.00	0.00	0.00	0.00	75.00			TAKE TO CUMMINS ENGINE LIGHT ON REPLACE DPF & CLEAN DOC	7/04/2018	7/04/2018
R122-0017056	1388	76.43	52.50	0.00	0.00	0.00	128.93	\$128.93	411374	REPLACE T/TABLE PAD	24/03/2018	26/03/2018
R122-0016948	1388	752.70	187.50	0.00	0.00	0.00	940.20	\$1,502.17	410209	B-SERVICE 1SX EGR CUMMINS	19/03/2018	20/03/2018
R122-0016948	1388	277.44	114.00	0.00	0.00	0.00	391.44			RELINSTEER BRAKES	19/03/2018	20/03/2018
R122-0016948	1388	71.53	99.00	0.00	0.00	0.00	170.53			RELIN L/H/R BRAKES	19/03/2018	20/03/2018
R122-0016755	1388	125.43	131.25	0.00	0.00	0.00	256.68	\$256.68	407301	REPLACE R/H T/TABLE PAD	7/03/2018	7/03/2018
R122-0016582	1388	0.00	69.75	0.00	0.00	0.00	69.75	\$69.75	405028	REPLACE GOVERNOR VALVE	26/02/2018	26/02/2018
R122-0016421	1388	12.11	50.25	0.00	0.00	0.00	62.36	\$62.36	403030	ENGINE LIGHT COMING ON CHECK CODES FIT CORRECT RADIATOR CAP	20/02/2018	22/02/2018
R122-0016313	1388	2240.00	0.00	0.00	0.00	224.00	2464.00	\$2,464.00	401451	8 X 295/80 BDLE POSITION 5,6,7,8,9,10,11,12 8 X FIT 8 X CHARGE FTSD-1495422	14/02/2018	14/02/2018

R122-0016227	1388	55.52	156.00	0.00	0.00	0.00	211.52	\$211.52	400272	REPLACE SUZY COILS	8/02/2018	8/02/2018
R122-0015687	1388	0.00	54.00	0.00	0.00	0.00	54.00	\$174.81	393833	STEERING WHEEL IS NOT STRAIGHT,	9/01/2018	10/01/2018
R122-0015687	1388	55.56	65.25	0.00	0.00	0.00	120.81			REPLACE SUZY COILS AFTER TRAILER WAS DROPPED	9/01/2018	10/01/2018
R122-0015688	1388	232.08	37.50	0.00	0.00	0.00	269.58	\$269.58	393833	SEAT IS FALLING APART	9/01/2018	9/01/2018
R120-0017056	1388	0.00	0.00	240.00	0.00	24.00	264.00	\$264.00	389106	SIGNWRITING TO FLEET NO: 1388 DAY CAB	14/12/2017	14/12/2017
R122-0014946	1388	0.00	77.25	0.00	0.00	0.00	77.25	\$223.29	384421	STRAIGHTEN STEERING WHEEL	22/11/2017	22/11/2017
R122-0014946	1388	0.00	13.50	0.00	0.00	0.00	13.50			REPAIR PARK LIGHTS	22/11/2017	22/11/2017
R122-0014946	1388	23.79	108.75	0.00	0.00	0.00	132.54			REPAIR OIL LEAK AT R/H STEER HUB	22/11/2017	22/11/2017
R120-0016455	1388	443.56	0.00	0.00	0.00	0.00	443.56	\$443.56	383292	REPLACE ALTERNATOR - JOB R120-0015982	14/11/2017	14/11/2017
R122-0014624	1388	0.00	58.50	0.00	0.00	0.00	58.50	\$58.50	382015	TRUCK WONT START	7/11/2017	8/11/2017
R120-0015982	1388	1071.33	0.00	196.12	0.00	0.00	1267.45	\$18,735.18	379834	ELECTRIC MIRRORS DONT WORK	23/10/2017	6/11/2017
R120-0015982	1388	1471.41	3801.00	11.89	0.00	0.00	5284.30			C-SERVICE	23/10/2017	6/11/2017
R120-0015982	1388	225.00	0.00	0.00	0.00	0.00	225.00			RELOCATE I FACE I FACE DAMAGED.	23/10/2017	6/11/2017
R120-0015982	1388	0.00	487.50	0.00	0.00	0.00	487.50			REMOVE RADIATOR AND CLEAN HEATER TAPS HEATER HOSES	23/10/2017	6/11/2017
R120-0015982	1388	63.40	0.00	0.00	0.00	0.00	63.40			fuel tank rubbers	23/10/2017	6/11/2017
R120-0015982	1388	124.66	180.00	0.00	0.00	0.00	304.66			A/C BEARING	23/10/2017	6/11/2017
R120-0015982	1388	0.00	146.25	0.00	0.00	0.00	146.25			AIR LEAK AT MANIFOLD	23/10/2017	6/11/2017
R120-0015982	1388	0.00	0.00	0.00	0.00	0.00	0.00			WARRANTY- AIR COMPRESSOR MOUNT LEAK	23/10/2017	6/11/2017
R120-0015982	1388	0.00	0.00	0.00	0.00	0.00	0.00			WARRANTY- HEAD GASKET LEAKING- REPLACE CAM SHAFT AND ROCKERS	23/10/2017	6/11/2017
R120-0015982	1388	226.50	290.25	0.00	0.00	0.00	516.75			POWER STEER OIL + FILTER REPLACE SUCTION HOSE STEER UNIS STEER	23/10/2017	6/11/2017
R120-0015982	1388	633.62	217.50	0.00	0.00	0.00	851.12			BEARING OILS STEER BEARINGS LOOSE	23/10/2017	6/11/2017
R120-0015982	1388	0.00	24.00	0.00	0.00	0.00	24.00			REPLACE CAB MOUNTS	23/10/2017	6/11/2017
R120-0015982	1388	1628.06	155.25	0.00	0.00	0.00	1783.31			KIT HORTON IDLERS AND TENSIONERS	23/10/2017	6/11/2017
R120-0015982	1388	950.00	257.25	0.00	0.00	0.00	1207.25			FIT POLISH RIMS	23/10/2017	6/11/2017
R120-0015982	1388	0.00	317.25	0.00	0.00	0.00	317.25			POLISH BUMPER	23/10/2017	6/11/2017
R120-0015982	1388	31.97	183.75	0.00	0.00	0.00	215.72			REPLACE SUZI COILS + UPGRADE	23/10/2017	6/11/2017
R120-0015982	1388	259.64	448.50	0.00	0.00	0.00	708.14			REPLACE DRIVE GAUARDS STRAIGHTEN REAR BAR	23/10/2017	6/11/2017
R120-0015982	1388	326.74	600.00	0.00	0.00	0.00	926.74			WARRANTY- REAR MAIN SEAL LEAKING, REMOVE GEARBOX AND CLUTCH	23/10/2017	6/11/2017
R120-0015982	1388	254.52	0.00	0.00	0.00	0.00	254.52			KIT AIR DRIER	23/10/2017	6/11/2017
R120-0015982	1388	158.32	151.50	0.00	0.00	0.00	309.82			LHF DRIVE BRAKE LOW	23/10/2017	6/11/2017
R120-0015982	1388	242.55	225.00	0.00	0.00	0.00	467.55			TORQUE ROD BUSHES	23/10/2017	6/11/2017
R120-0015982	1388	135.82	0.00	0.00	0.00	0.00	135.82			clutch pivot bearings	23/10/2017	6/11/2017
R120-0015982	1388	144.68	493.50	0.00	0.00	0.00	638.18			DASH LIGHTS GAUGES LOOSE DOOR ALARM NOT WORK	23/10/2017	6/11/2017
R120-0015982	1388	224.58	281.25	0.00	0.00	0.00	505.83			DETAIL SIGN WRITE WIPER BLADES REPLACE IGN BARREL CAB FIRE EXT A/C	23/10/2017	6/11/2017
R120-0015982	1388	325.20	174.00	0.00	0.00	0.00	499.20			VENTS CLUTCH RUBBER INT LIGHTS	23/10/2017	6/11/2017
R120-0015982	1388	0.00	437.25	0.00	0.00	0.00	437.25			B SERVICE ISX EGR CUMMINS	23/10/2017	6/11/2017
R120-0015982	1388	42.02	0.00	0.00	0.00	0.00	42.02			buff and signwrite	23/10/2017	6/11/2017
R120-0015982	1388	435.28	140.25	0.00	0.00	0.00	575.53			repair, buff and signwrite	23/10/2017	6/11/2017
R120-0015982	1388	540.62	0.00	0.00	0.00	0.00	540.62			BATTERY & CABLES	23/10/2017	6/11/2017
R120-0015982	1388	0.00	0.00	0.00	0.00	0.00	0.00			ENGINE TUNE- B&H TUNED ENGINE WHEN REPLACING CAM	23/10/2017	6/11/2017
R120-0015982	1388	0.00	0.00	0.00	0.00	0.00	0.00			WARRANTY-REPLACE THERMOSTAT	23/10/2017	6/11/2017
R122-0014087	1388	0.00	0.00	174.00	0.00	17.40	191.40	\$191.40	376687	GUYS AUTO... REPAIR HORTON FAN CIRCUIT, REPAIR DAMAGED HARNESS ON	12/10/2017	13/10/2017
R122-0013675	1388	2600.00	66.00	0.00	0.00	0.00	2666.00	\$2,666.00	371293	ROCKER COVER	19/09/2017	20/09/2017
R122-0013633	1388	170.70	138.75	0.00	0.00	0.00	309.45	\$490.45	370890	REPLACE T/TABLE	16/09/2017	18/09/2017
R122-0013633	1388	89.50	91.50	0.00	0.00	0.00	181.00			RELIN REAR DRIVE AXLE BRAKES	16/09/2017	18/09/2017
R122-0013483	1388	960.00	0.00	0.00	0.00	96.00	1056.00	\$1,056.00	368305	REPLACE MAIN COMPRESSOR AIR LINE	16/09/2017	18/09/2017
R122-0013448	1388	127.05	86.25	0.00	0.00	0.00	213.30	\$330.36	368077	REPLACE STEER TYRES WITH G611, 2 x KEPT FOR RUN OUTS, FTSD-1535463	7/09/2017	8/09/2017
R122-0013448	1388	38.31	78.75	0.00	0.00	0.00	117.06			AIR LEAKS AT CAB - REAR TURNTABLE PADS	6/09/2017	6/09/2017
R122-0013281	1388	128.73	13.50	0.00	0.00	0.00	142.23	\$142.23	365662	REPLACE AIR BLOWER	6/09/2017	6/09/2017
R122-0013055	1388	74.53	97.50	0.00	0.00	0.00	172.03	\$172.03	362942	REPLACE T/TABLE PAD + HELICOIL BOLTS	25/08/2017	26/08/2017
R122-0012879	1388	128.73	99.00	0.00	0.00	0.00	227.73	\$356.10	360475	REPLACE A/C BELT + FAN BELT + TENSIONER BEARINGS	16/08/2017	16/08/2017
R122-0012879	1388	4.62	123.75	0.00	0.00	0.00	128.37			TURNTABLE PAD HAS BEEN RIPPED OFF	7/08/2017	8/08/2017
R122-0012848	1388	23.21	0.00	0.00	0.00	0.00	23.21	\$23.21	359913	REPLACED O/S HEADLIGHT GLOBE	7/08/2017	8/08/2017
R122-0012808	1388	128.73	62.25	0.00	0.00	0.00	190.98	\$190.98	359648	JOB MADE TO BOOK OUT PARTS, APPROVED BY STEPHEN,A	4/08/2017	4/08/2017
R122-0012609	1388	418.32	141.00	0.00	0.00	0.00	559.32	\$1,335.45	356089	REPLACE T/TABLE PAD + HELI/COIL THREADS	3/08/2017	3/08/2017
R122-0012609	1388	58.30	156.00	0.00	0.00	0.00	214.30			B SERVICE	22/07/2017	24/07/2017
R122-0012609	1388	69.13	106.50	0.00	0.00	0.00	175.63			REPLACE TOOLBOX LOCKS	22/07/2017	24/07/2017
R122-0012609	1388	144.70	241.50	0.00	0.00	0.00	386.20			REPLACE L/H/R GUARD & BRACKET	22/07/2017	24/07/2017
R122-0012477	1388	215.66	114.75	0.00	0.00	0.00	330.41	\$330.41	348745	RELIN BOTH R/H DRIVE BRAKES	22/07/2017	24/07/2017
R122-0012392	1388	0.00	77.25	0.00	0.00	0.00	77.25	\$77.25	347517	REPLACE T/TABLE PADS	15/07/2017	17/07/2017
R120-0013972	1388	0.00	0.00	536.00	0.00	53.60	589.60	\$589.60	342262	C/A CLUTCH	12/07/2017	12/07/2017
R122-0012070	1388	218.81	131.25	0.00	0.00	0.00	350.06	\$350.06	341872	CALLOUT TO TEA GARDENS TURN OFF TO TOW START DUE TO FAULTY STARTER.	28/06/2017	29/06/2017
R122-0011903	1388	0.00	67.50	0.00	0.00	0.00	67.50	\$67.50	340301	CHECK ENGINE LIGHT ON - DE RATED	26/06/2017	27/06/2017
R122-0011899	1388	432.58	225.00	0.00	0.00	0.00	657.58	\$657.58	340080	GAUGES HAVE BEEN GOING UP AND DOWN	19/06/2017	19/06/2017
R122-0010991	1388	8.25	42.75	0.00	0.00	0.00	51.00	\$51.00	327534	CHECK CHARGE RATE BATTERIES FLAT	17/06/2017	19/06/2017
R122-0010722	1388	951.52	0.00	0.00	0.00	0.00	951.52	\$951.52	324843	REPLACE CIGARETTE LIGHTER	3/05/2017	3/05/2017
R122-0010616	1388	0.00	75.00	0.00	0.00	0.00	75.00	\$202.50	322328	BDL3 POS# 5-6-7-8 CASES TO COFFS- 4 FTSD- 1362129	18/04/2017	19/04/2017
R122-0010616	1388	0.00	69.75	0.00	0.00	0.00	69.75			replace reverse lamp	7/04/2017	8/04/2017
R122-0010616	1388	0.00	57.75	0.00	0.00	0.00	57.75			REPAIR WIRING TO BASE	7/04/2017	8/04/2017
R122-0010535	1388	337.34	37.50	0.00	0.00	0.00	374.84	\$374.84	321169	REPAIR MIRROR SWITCH	7/04/2017	8/04/2017
										REPLACE REAR ENGINE MOUNTS	4/04/2017	4/04/2017

R122-0010482	1388	453.10	384.00	0.00	0.00	0.00	837.10	\$837.10	321011	PM for 000-002 Last Done: 8/12/2016 Interval: 30000 Vibration: 26515 MIRROR HEAT AND 12V SOCKET NOT WORKING	1/04/2017	3/04/2017
R122-0010485	1388	0.00	80.25	0.00	0.00	0.00	80.25	\$80.25	320711		1/04/2017	3/04/2017
R122-0010486	1388	0.00	28.50	0.00	0.00	0.00	28.50	\$28.50	320711	SPEEDO ERRATIC	1/04/2017	3/04/2017
R122-0010328	1388	34.37	112.50	0.00	0.00	0.00	146.87	\$146.87	317850	REPLACE L/H/R GUARD	23/03/2017	24/03/2017
R120-0011998	1388	0.00	0.00	918.81	0.00	91.88	1010.69	\$1,010.69	317039	CALLOUT M1 SOUTH BOUND WEIGHT STATION. MT WHITE.TEST OUT PUT ON TRUCK OK.NONE ON TRAILER LEAD,INSPECT PLUGS ALL OK.SUSPECT OPEN CIRCUIT IN CAB R FTY NEW IFAD HAVE BAK 11FT OFFCT REPLACE CLUTCH BROKEN INTERMEDIATE PLATE	21/03/2017	22/03/2017
R122-0009813	1388	1358.04	807.00	0.00	0.00	0.00	2165.04	\$2,165.04	310495		27/02/2017	2/03/2017
R122-0009794	1388	526.72	122.25	0.00	0.00	0.00	648.97	\$729.97	310257	REPLACE BATTERIES	25/02/2017	28/02/2017
R122-0009794	1388	0.00	81.00	0.00	0.00	0.00	81.00			REPLACE CLUTCH PIVOT	25/02/2017	28/02/2017
R122-0009568	1388	8.25	107.25	0.00	0.00	0.00	115.50	\$424.00	307223	REPAIR POWER SUPPLY TO LIGHTER	15/02/2017	17/02/2017
R122-0009568	1388	201.25	107.25	0.00	0.00	0.00	308.50			REPLACE T/TABLE PADS	15/02/2017	17/02/2017
R122-0009251	1388	0.00	42.75	0.00	0.00	0.00	42.75	\$42.75	304247	REPAIR INTERIOR LIGHTS	2/02/2017	2/02/2017
R122-0009229	1388	115.03	51.00	0.00	0.00	0.00	166.03	\$166.03	303734	REPLACE ABS LEAD	1/02/2017	2/02/2017
R122-0009235	1388	46.78	46.50	0.00	0.00	0.00	93.28	\$93.28	303734	REPLACE SUZY COILS	1/02/2017	2/02/2017
R122-0008980	1388	0.00	108.75	0.00	0.00	0.00	108.75	\$197.25	300367	REPAIR WIPER LINKAGES	19/01/2017	20/01/2017
R122-0008980	1388	0.00	88.50	0.00	0.00	0.00	88.50			STRAIGHTEN REAR BUMPER	19/01/2017	20/01/2017
R122-0008222	1388	0.00	22.50	0.00	0.00	0.00	22.50	\$22.50	291196	CHECK TURN TABLE DOESNT ALL WAYS LOCK IN	9/12/2016	9/12/2016
R122-0008178	1388	91.39	58.50	0.00	0.00	0.00	149.89	\$940.80	290981	REPLACE T /TABLE JAW	8/12/2016	8/12/2016
R122-0008178	1388	508.16	282.75	0.00	0.00	0.00	790.91			B SERVICE + DIFF OILS	8/12/2016	8/12/2016
R122-0008081	1388	1877.28	0.00	0.00	0.00	95.00	1972.28	\$1,972.28	289342	REPLACE STEER TYRES WITH 295 G611, 2 x CASE, REPLACE POS#9-10-11-12 WITH 295 BDL3, 3 x CASES, 1 x KEPT FOR RUN OUT, FTSD-No.1297517	2/12/2016	6/12/2016
R122-0008001	1388	73.85	63.75	0.00	0.00	0.00	137.60	\$137.60	288606	REPLACE T/TABLE PAD	29/11/2016	1/12/2016
R122-0007361	1388	9.50	16.50	0.00	0.00	0.00	26.00	\$26.00	283485	HEAD LIGHTS OUT	3/11/2016	3/11/2016
R122-0007129	1388	18.19	39.75	0.00	0.00	0.00	57.94	\$89.44	280530	REPLACE L/H HEADLIGHT GLOBE	24/10/2016	25/10/2016
R122-0007129	1388	0.00	31.50	0.00	0.00	0.00	31.50			C/A CLUTCH	24/10/2016	25/10/2016
R122-0007078	1388	70.63	90.00	0.00	0.00	0.00	160.63	\$160.63	279723	REPLACE T/TABLE PAD & HELICOIL DAMAGED THREADS	21/10/2016	22/10/2016
R122-0006838	1388	339.26	69.75	0.00	0.00	0.00	409.01	\$409.01	277710	REPLACE FAN BELT TENSIONER + ALT PULLEY BEARINGS	13/10/2016	14/10/2016
R122-0006691	1388	3.68	69.00	0.00	0.00	0.00	72.68	\$72.68	276901	REPLACE L/H/F AXLE GASKET	10/10/2016	11/10/2016
R122-0006613	1388	73.85	65.25	0.00	0.00	0.00	139.10	\$139.10	275689	REPLACE T/TABLE PAD	4/10/2016	5/10/2016
R122-0005314	1388	368.82	264.00	0.00	0.00	0.00	632.82	\$632.82	261735	765.00 B SERVICE	12/08/2016	13/08/2016
R122-0005037	1388	0.00	35.25	0.00	0.00	0.00	35.25	\$35.25	258026	POSSIBLE BROKEN ENGINE MOUNT	2/08/2016	2/08/2016
R122-0004813	1388	0.00	46.50	0.00	0.00	0.00	46.50	\$46.50	255208	C/A CLUTCH & ADJUST ENGINE BRAKE SWITCH	21/07/2016	21/07/2016
R122-0004765	1388	33.70	84.00	0.00	0.00	0.00	117.70	\$226.20	254918	REPLACE R/H/R GUARD	20/07/2016	20/07/2016
R122-0004765	1388	35.00	73.50	0.00	0.00	0.00	108.50			Install overspeed alert	20/07/2016	20/07/2016
R122-0004709	1388	0.00	50.25	0.00	0.00	0.00	50.25	\$95.25	254535	REPLACE L/H/RUNNING LIGHT	19/07/2016	20/07/2016
R122-0004709	1388	0.00	45.00	0.00	0.00	0.00	45.00			C/A CLUTCH	19/07/2016	20/07/2016
R122-0004363	1388	535.68	138.75	0.00	0.00	0.00	674.43	\$674.43	250352	REPLACE BATTERIES	1/07/2016	2/07/2016
R122-0004298	1388	369.00	13.50	0.00	0.00	0.00	382.50	\$382.50	249200	replace daytime light	28/06/2016	28/06/2016
R120-0005778	1388	0.00	0.00	161.79	0.00	16.18	177.97	\$177.97	249200	ASH RESTRICTION TEST & REPLACE RADIATOR CAP.DOWNLOAD ECM IMAGE.WHILE STATIONARY REGEN FOUND COOLANT PRESSURISING FROM THE RADIATOR CAP.REMOVE RADIATOR & FOUND SEAL WORN & COOLANT OVER FILLED.SMALL CRACK NEAR THE OVERFLOW PIPE ON THE HEADER TANK.REPLACE CAP.CARRY OUT DPF STATIONERY REGAN & ASH RESTRICTION & FOUND ALL VALVES WITHIN SPEC.	27/06/2016	4/07/2016
R122-0004088	1388	0.00	251.25	0.00	0.00	0.00	251.25	\$251.25	247830	REPLACE L/H DAYTIME LIGHT	18/06/2016	22/06/2016
R122-0003838	1388	0.00	99.00	0.00	0.00	0.00	99.00	\$99.00	244612	TAKE TO CUMMINS FOR DPF HEALTH CHECK	6/06/2016	6/06/2016
R122-0003833	1388	439.97	208.50	0.00	0.00	0.00	648.47	\$648.47	244391	REPLACE HEATER CORE	4/06/2016	7/06/2016
R122-0003465	1388	105.20	0.00	0.00	0.00	0.00	105.20	\$105.20	241325	THIS IS A REDO JOB TO BOOK OUT PARTS	18/05/2016	19/05/2016
R122-0003172	1388	33.90	73.50	0.00	0.00	0.00	107.40	\$178.65	239290	replace l/h/r guard	6/05/2016	6/05/2016
R122-0003172	1388	0.00	71.25	0.00	0.00	0.00	71.25			replace dash globes	6/05/2016	6/05/2016
R122-0003182	1388	2505.04	0.00	0.00	0.00	250.54	2755.58	\$2,755.58	239290	B/STONE... REPLACE DRIVE TYRES WITH 295 'BDL3, 8 x NWR, FTSD-1022639	6/05/2016	11/05/2016
R122-0002946	1388	644.69	0.00	0.00	0.00	0.00	644.69	\$644.69	236627	THIS IS A REDO JOB TO RECEIVE IN INVOICE	26/04/2016	26/04/2016
R122-0002913	1388	65.40	50.25	0.00	0.00	0.00	115.65	\$115.65	236177	REPAIR LEAK AT HEATER CORE	22/04/2016	22/04/2016
R122-0002906	1388	850.00	0.00	0.00	0.00	85.00	935.00	\$935.00	236052	B/STONE... REPLACE STEER TYRES WITH 295 'R150, 2 x 295 TRADE-IN, FTSD-1012797	21/04/2016	26/04/2016
R120-0003512	1388	0.00	0.00	2720.00	0.00	272.00	2992.00	\$2,992.00	234423	REPLACE DPF	11/04/2016	26/04/2016
R122-0002555	1388	0.00	112.50	0.00	0.00	0.00	112.50	\$112.50	233666	CHECK ENGINE LIGHT ON TAKE TO CUMMINS FOR REPAIR	4/04/2016	5/04/2016
R122-0002546	1388	487.14	80.25	0.00	0.00	0.00	567.39	\$567.39	233680	B SERVICE DO NOT CLOSE WAITING TO BOOK OUT FUEL FILTER	2/04/2016	13/05/2016
R122-0002234	1388	0.00	0.00	0.00	0.00	0.00	0.00	\$0.00	229825	B/STONE... REPLACE POS#7,8 WITH 295 BDL3 RUN OUTS, 2 x 295 CASES TO COFFS FTSD-1013977	15/03/2016	17/03/2016
R122-0002241	1388	21.74	78.75	0.00	0.00	0.00	100.49	\$100.49	229825	REPLACE UHF AERIAL	15/03/2016	17/03/2016
R122-0002195	1388	23.90	37.50	0.00	0.00	0.00	61.40	\$61.40	229425	SUZI COILS NEEDS TO BE REPLACED	12/03/2016	14/03/2016
R122-0001985	1388	0.00	73.50	0.00	0.00	0.00	73.50	\$161.18	226877	NEEDS CLUTCH ADJUSTMENT	2/03/2016	7/03/2016
R122-0001985	1388	3.68	84.00	0.00	0.00	0.00	87.68			REPLACE R/H/F AXLE GASKET	2/03/2016	7/03/2016
R122-0001367	1388	0.00	60.00	0.00	0.00	0.00	60.00	\$120.00	221683	WATER LEAKING THROUGH THE ROOF	8/02/2016	7/03/2016
R122-0001367	1388	0.00	60.00	0.00	0.00	0.00	60.00			REPAIR SEAT CUSHION	8/02/2016	7/03/2016
R122-0000979	1388	448.76	66.00	0.00	0.00	0.00	514.76	\$830.69	218704	B SERVICE	23/01/2016	27/01/2016
R122-0000979	1388	197.43	118.50	0.00	0.00	0.00	315.93			RELINE DRIVE BRAKES	23/01/2016	27/01/2016
R122-0000750	1388	0.00	187.50	0.00	0.00	0.00	187.50	\$751.47	216065	REPLACE HOT AIR HOSE FROM COMPRESSOR	14/01/2016	8/02/2016
R122-0000750	1388	8.83	91.50	0.00	0.00	0.00	100.33			ADJ CLUTCH REPLACE CLUTCH PEDAL RUBBER	14/01/2016	8/02/2016
R122-0000750	1388	271.24	82.50	0.00	0.00	0.00	353.74			REPLACED HEATER TAP	14/01/2016	8/02/2016

R122-0000750	1388	0.00	0.00	109.90	0.00	0.00	109.90			REPLACE MIRROR SWITCH	14/01/2016	8/02/2016
R122-0000442	1388	35.00	0.00	0.00	0.00	3.50	38.50	\$38.50	212556	1 X PUNCTURE REPAIR POS 10 FTSD 859772	29/12/2015	18/01/2016
R122-0000382	1388	0.00	35.25	0.00	0.00	0.00	35.25	\$35.25	211901	REPLACED P.B.R FITTINGS PUMPED UP L/H/R DRIVE TYRE	23/12/2015	29/12/2015
R122-0000188	1388	70.47	27.75	0.00	0.00	0.00	98.22	\$98.22	209635	REPLACE TURN TABLE PAD	15/12/2015	15/12/2015