

Make: MITSUBISHI Yr: - 2008 Rego Plate: - N/A  
 Model: FD40KL Serial Num: F19C51030

## Maintenance Record - Forklift (F12)

Date	Repair Description	Repaired By	Comments	Invoice #	Cost
27.09.2016	DRAIN PETROL FROM FUEL TANK WHILST ON FLOAT. REFIL WITH DIESEL. PRIME BLEED AND START.	ON TRAK EARTHMOVING REPAIRS PTY LTD		00001018	\$475.00
07.02.2017	CARRIED OUT SERVICE	ON TRAK EARTHMOVING		00001175	\$493.27
09.03.2017	MITSUBISHI FORKLIFT. SUPPLY AAND FIT 2X MAST HOSES	ON TRAK EARTHMOVING		00001240	\$449.09
20.03.2017	SUPPLY AND FIT 2X MAST HOSES AS REQUESTED BY STEF	ON TRAK EARTHMOVING		1240	449.09
13.09.2017	REMOVE ROTATOR CYCLINDERS, STRIP, REBUILD AND PRESSURE TEST, REFIT ROTATOR CYLINDERS AND TEST.	ON TRAK EARTHMOVING REPAIRS PTY LTD		00001532	1418.95
04.05.2018	INSPECT, NEEDS FULL SERVICE	J&B EXCAVATIONS		00000438	\$49.50
12.05.2018	12544.8 HRS. ENGINE SERVICE, REPLACE COOLANT, GREASE.	J&B EXCAVATIONS		00000448	\$476.74
13.07.2018	12580HRS. FRONT PIVOT NIPPLE BROKEN	J&B EXCAVATIONS		00000541	\$148.50
03.09.2018	GREASE AND INSPECT	J&B EXCAVATIONS		00000638	\$75.00
21.09.2018	GREASE AND INSPECT	J&B EXCAVATIONS		00000642	\$75.00
13.05.2020	NEW BATTERY	RJ BATTERIES		17A012870	\$250.00
27.06.2023	CARRY OUT ENGINE SERVICE AS REQUESTED BY STEF	ON TRAK EARTHMOVING	LABOUR X2 HOURS	00004215	\$264.00
27.07.2023	TRAVEL TO ARTARMON, REPAIR LEAK ON RADIATOR HOSE OVER EXTENSION ROLLARS AS REQUESTED BY STEF	ON TRAK EARTHMOVING REPAIRS PTY LTD	LABOUR X6.5 HOURS, SERVICE CALL, PARTS HOSE AND FITTINGS	00004241	\$1,883.15
15.09.2023	TRAVEL TO SITE. CAP OFF SIDE SHIFT LINES ON FORKLIFT, AS REQUESTED BY STEF.	ON TRAK EARTHMOVING REPAIRS PTY LTD	LABOUR X1.5 HOURS, SERVICE CALL, PARTS	00004322	\$346.45
05.02.2024	DRAIN AND LUSH FUEL TANK. REFILL, BLEED FUEL SYSTEM, START AND TEST. AS REQUESTED BY STEF	ON TRAK EARTHMOVING REPAIRS	LABOUR X4HRS	00004601	\$572.00
22.02.2024	TRAVEL TO SITE. SUPPY HIOSE AND FITTING TO REPLACE BURST HOSE, AS REQUESTED BY STEF	ON TRAJK EARTHMOVING REPAIRS	LABOUR X3 HRS	00004632	\$905.60