




# Vehicle History Summary

Fleet #	54540
Registration	XV04MZ
Make	Scania
Model	G480
VIN / Chassis #	YS2G6X40005406044
Build Date	2016/03

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-11872	28/01/2022	1051793	700	B - Oils & Filters		GTM - Gippsland Truck Mechanic
R-20317	06/01/2022	0	0	Minor Repairs	06/01 : REPLACE WORN TIE ROD WITH NEW ASSY REPLACE U/S NOX SENSOR AT EXHAUST OUT S/F # 68235 CONNECT SCAN TOOL TO CHECK RETARDER MALFUNCTION - ( ** TO DO : REPLACE U/S RETARDER SENSOR ) CHECK TRAILER EBS FAULT - CONNECT SCAN TOOL TO CHECK. NO ACTIVE CODES, CLEAR & RESET ECM. TEST DRIVE - OK.	GTM - Gippsland Truck Mechanic
S-11634	04/01/2022	1041931	690	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
R-20091	04/01/2022			Minor Repairs	29/12/21 : REPLACE LEAKING FITTING AT DRIVERS SEAT CHANGE STEER TYRES CONNECT SCAN TOOL TO CHECK FAULTS - CLEAR & MONITOR. CHARGE UP HALF FLAT BATTERY	GTM - Gippsland Truck Mechanic
T-5896	30/12/2021	0	0	Direct Fit	295/80 R22.5 154/149J MICHELIN X INCITY Z POS 1,2 8.25x22.5 JOST 10/335 DRIVE POLISHED ISO POS 1,2	TTS - Traralgon Tyre Service
R-19950	22/12/2021	1036830	0	Minor Repairs	CONNECT SCAN TOOL TO CHECK ACTIVE EBS FAULTS FOR LUNDY, ISSUE FOUND BROKEN WIRE. CLEAR FAULTS AND RECHECK, OK	GTM - Gippsland Truck Mechanic
R-19750	07/12/2021	1027224	0	Minor Repairs	REPLACE MISSING LH FUEL TANK STRAP REFIT RH MIRROR SWITCH	GTM - Gippsland Truck Mechanic

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-19672	03/12/2021	1024184	0	Minor Repairs	REMOVE & REPAIR BROKEN EXHAUST TAILPIPE OUTLET HOUSING REPLACE LEAKING AIR LINE TO FRONT DIFF LOCK	GTM - Gippsland Truck Mechanic
R-20008	29/11/2021	0	0	Minor Repairs	CHECK LH HEADLIGHT AND FIT NEW GLOBE	Lunds Auto Electrical
S-11230	26/11/2021	1017597	0	B - Oils & Filters	B SERVICE REPLACE MISSING BATTERY BOX COVER RESEAL LEAKING FRONT DIFF CENTRE - FIT NEW GASKET. REPLACE LEAKING THRU SHAFT SEAL & NUT	GTM - Gippsland Truck Mechanic
R-19473	22/11/2021	0	0	Minor Repairs	CHECK BLUE SUZI COIL U/S REMOVE & REPLACE SUZI COILS - (SET )	GTM - Gippsland Truck Mechanic
R-19997	19/11/2021	0	0	Minor Repairs	REPAIR FAULT IN FUEL GAUGE	Lunds Auto Electrical
S-10996	09/11/2021	1007285	651	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
T-5529	03/11/2021	0	0	Direct Fit	295/80 R22.5 152M TOYO M144A POS 1,2 11R22.5 148/145L MICHELIN MULTI D+ POS 3,4,5,6,7,8,9,10	TTS - Traralgon Tyre Service
R-19981	03/11/2021	0	0	Minor Repairs	CHECK FAULT IN HEADLIGHT AND FIT NEW GLOBE	Lunds Auto Electrical
R-19808	01/11/2021			Breakdown	all out to Mcdonald road and boundary road brooklyn inspected for fault to find broken fitting at suzie leads Removed suzie leads and replaced broken fitting Refitted suzie coils Tested all ok	PTS - Progress Transport Services
R-19286	31/10/2021	0	0	Parts Only	1 X 5W37C CAST Z-LINE	CMV Truck & Bus - Dandenong
T-5403	20/10/2021	0	0	Direct Fit	REMOVE FLAT LHR INNER DRIVE TYRE & HAVE REPAIRED. REFIT	GTM - Gippsland Truck Mechanic
R-19711	13/10/2021	0	0	Minor Repairs	CHECK AND REPAIR FAULT IN GEOTAB	Lunds Auto Electrical

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-10576	04/10/2021	987597	0	C - Diffs & G'Box Oils	C SERVICE FRONT CAB MOUNTS U/S - REPLACE BUSHES & SIDE WASHERS AS REQUIRED. REPLACE TOP CAB SHOCK ABSORBER BUSHES REPLACE RUPTURED RH CAB LIFT HOSE REPLACE U/S-LEAKING RHR DRIVE AIRBAG REMOVE T/TABLE TO CLEAN & INSPECT. FOUND CRACKS THRU FOOT BUSH BOLT HOLES. REPLACE WITH NEW ASSY ( SUPPLIED BY PST ) CLEAN ALL OLD GREASE FROM AROUND BALL RACE & RE GREASE TOP UP HYDRAULIC TANK	GTM - Gippsland Truck Mechanic
R-18542	02/10/2021			Minor Repairs	ADJUST T/TABLE JAW CHECK NOISE IN LH FRONT CAB	GTM - Gippsland Truck Mechanic
S-10310	10/09/2021	984385	0	B - Oils & Filters	B SERVICE REPAIRED AIR LEAK REPLACED REAR UNI GREASE NIPPLE TOPPED UP FRONT DIFF & HYDRAULIC OIL	GTM - Gippsland Truck Mechanic
R-17641	01/09/2021	969221	0	Major Repair	 <p>CHECK ENGINE COOLANT LEAKS - FOUND # 3 &amp; 4 CYLINDERS LEAKING AROUND HEAD GASKET AREA. DRAIN COOLANT &amp; REMOVE 3 &amp; 4 CYL HEAD - SIGN OF LEAKING AROUND TOP LINER ORING. DRAIN ENGINE &amp; REMOVE SUMP. REMOVE PISTON &amp; LINERS- FOUND ORINGS LEAKING. REMOVE ALL CYL HEADS, PISTONS &amp; LINERS. REPLACE PISTON &amp; LINERS-KIT REPLACE No 2 CYL HEAD - CRACKED REFIT ALL. REFILL OIL &amp; COOLANT START &amp; CHECK REPLACE REAR MUDFLAPS &amp; LHF DRIVE REPAIR BROKEN RHR TAIL LIGHT POLE MOUNTING FIT NEW OIL COOLER FILTER &amp; CLEAN UNIT RECONNECT TO TANKER T7029 &amp; TEST DRIVE</p>	GTM - Gippsland Truck Mechanic
R-17636	31/08/2021			Parts Only	3 x HP Filter Element 10 micron t/s HPM281 189mm Housing (D) 1 x Oil Cooler 18ltr Complete Filter Unit 1 x HD 069 - filter element v3.0510-08 2 x W17 - 25 CC Seal Kit (C) 1 x Sight glass-oil level G1" thread hex head level indicators	THS - Transport Hydraulic Solutions

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-9759	03/08/2021	967717	614	A - Grease & Brake Adj	A SERVICE REPLACE MISSING GREASE NIPPLE IN TAILSHAFT UNI TOP UP COOLANT REPLACE U/S HYDRAULIC COUPLING O RINGS REPAIR & MAKE UP NEW MOUNTING FOR RH DOOR GRAB HANDLE REPLACE RHR CAB CUSHION MOUNT	GTM - Gippsland Truck Mechanic
R-17196	03/08/2021	967717	0	Minor Repairs	Replace grab handle	GTM - Gippsland Truck Mechanic
R-17853	20/07/2021	0	0	Minor Repairs	REPAIR FAULT IN INTERIOR LIGHTS X 2. REPAIRED WIRING TO LIGHTS	Lunds Auto Electrical
R-16747	14/07/2021	0	0	Minor Repairs	09/07 : REPAIR SPARE SEAT BASE. REPLACE SCISSOR BUSHES & SLEEVES ( MADE TO SAMPLE ) REMOVE SEAT TO CHANGE OVER ALL PARTS. REFIT TO VEHICLE	GTM - Gippsland Truck Mechanic
R-17823	30/06/2021	0	0	Minor Repairs	MOUNT NEW LIGHTS TO SCANIA BULLBAR AND FIR REAR LIGHTS. REPAIR WIRING AT REAR	Lunds Auto Electrical
R-16383	30/06/2021			Minor Repairs	REPLACE U/S DRIVERS SEAT BELT WITH NEW ASSY. FIT NEW SEAT COVER	GTM - Gippsland Truck Mechanic
T-4649	23/06/2021	0	0	Direct Fit	295/80R22.5 152M TOYO M144A CR POS 1 & 2	TTS - Traralgon Tyre Service
S-9255	23/06/2021	955176	0	B - Oils & Filters		GTM - Gippsland Truck Mechanic
R-15804	01/06/2021			Minor Repairs	REMOVE RH SIDE DOOR TRIM TO ACCESS & REFIT DETACHED WINDOW FROM REGULATOR SLIDE	GTM - Gippsland Truck Mechanic
T-4564	28/05/2021	0	0	Stock	4 x BDE	TTS - Traralgon Tyre Service
T-4469	28/05/2021	0	0	Fitting Fee	FITTING 4 POS 3,4,5,6 - FIT CUSTOMER OWNED BDE CAPS WITH 11R22.5 CASES ZTSCRAP TRUCK TYRE DISPOSAL	TTS - Traralgon Tyre Service
T-4468	28/05/2021	0	0	Stock	POS 3,4,5,6 - FIT CUSTOMER OWNED BDE CAPS WITH 11R22.5 CASES	TTS - Traralgon Tyre Service

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-8993	27/05/2021	942890	588	A - Grease & Brake Adj	NOTE: VARIOUS LIGHTS N/W - LUNDY FRONT DIFF OUTPUT SEAL LEAKING **RH TAIL LIGHT MOUNTING POLE U/S TIGHTENED RH GRAB RAIL TOP UP FRONT DIFF OIL REPAIRS TO RH TAIL LIGHT MOUNTING POLE **	GTM - Gippsland Truck Mechanic
R-16396	17/05/2021			Minor Repairs	replace rear worklight on scania truck	Lunds Auto Electrical
S-8769	11/05/2021	935361	579	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
R-15412	11/05/2021	935732	0	Minor Repairs	HIGH EXHAUST EMISSION WARNING Job Details CONNECT SCAN TOOL TO CHECK FAULT AND RUN SCR TEST, FOUND BLOCKED INJECTOR, CLEAR AND RE-CHECK AND TEST DRIVE, OK.	GTM - Gippsland Truck Mechanic
T-4435	06/05/2021	933487	0	Call out	ROADSIDE ASSIST - AFTER HOURS (FIRST 355.00 TWO HOURS) WMCALLOUTAH 1 TTS 355.00 WMFIT FITTING 4 TTS 40.00 160.00 POS 7,8,9,10 - FIT CUSTOMER OWNED 295/80 CASES WITH XMD 240 CAPS	TTS - Traralgon Tyre Service
T-4435	06/05/2021	0	0	Stock	ROADSIDE ASSIST - AFTER HOURS (FIRST 355.00 TWO HOURS) WMCALLOUTAH 1 TTS 355.00 WMFIT FITTING 4 TTS 40.00 160.00 POS 7,8,9,10 - FIT CUSTOMER OWNED 295/80 CASES WITH XMD 240 CAPS Includes GST of \$46.82 515.00 DIRECT CREDIT	TTS - Traralgon Tyre Service
R-14971	22/04/2021	0	0	Minor Repairs	CHECK EXHAUST EMISSION FAULT- REPAIR KINKED AIR LINE TO SCR UNIT	GTM - Gippsland Truck Mechanic
R-15090	16/04/2021	0	0	Minor Repairs	CHECK AIR SYSTEM NOT CHARGING UP CORRECTLY. REPLACE U/S AIR DRYER UNIT WITH SCANIA C/OVER UNIT CONNECT SCAN TOOL TO PROGRAM UNIT FIT NEW HOSE CLAMPS TO LHS RETARDER COOLER HOSE	GTM - Gippsland Truck Mechanic
R-16379	14/04/2021			Minor Repairs	TRAVEL TO THE TOP OF LOCH HILL AND REPAIR LIGHT IN TRUCK	Lunds Auto Electrical
R-14521	01/04/2021	0	0	Minor Repairs		Lunds Auto Electrical

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-8264	30/03/2021	925033	0	B - Oils & Filters	"B" CLASS {p/mover/dual} SECURE LOOSE L/H FRONT MUDGUARD REPLACE BROKEN BONNET RELEASE LEVER. REPLACE MISSING R/H FRONT CAB SUSPENSION CUSHION. CONNECT SCAN TOOL TO CHECK SUSPENSION MALFUNCTION AND REFER TO LUNDY TO CHECK AND REPAIR WIRING AT VALVE NEAR GEARBOX	GTM - Gippsland Truck Mechanic
R-14741	29/03/2021	924411		Minor Repairs	REMOVE RH DOOR TO RE-WELD BROKEN LOWER DOOR HINGE BRACKET	GTM - Gippsland Truck Mechanic
R-14987	25/03/2021			Minor Repairs	"A" CLASS {tanker, pm, tray A SERVICE CARRIED OUT IN ERROR AT TIME OF BRAKE REPAIRS. VEHICLE SERVICE & FAULT REPORT # 65419 03/03 @ 914727 KMS CARRIED OUT 19/02 - @ 912029KM FAULT/SERV REPORT # 65415 REF: BMC / JC	GTM - Gippsland Truck Mechanic
R-16543	24/03/2021	0	0	Minor Repairs	repair fault in worklight wiring, repaired wiring at rear of truck and in trailer plug wiring	Lunds Auto Electrical
R-14210	18/03/2021	920710	0	Minor Repairs	completed 18/3/21 See inv: 49296, entry 14199	GTM - Gippsland Truck Mechanic
R-14199	09/03/2021	920710		Minor Repairs	REMOVE U/S LH REAR LIGHT POLE & REPAIR. REFIT TO VEHICLE	GTM - Gippsland Truck Mechanic
R-14479	09/03/2021			Minor Repairs	REMOVE U/S LH REAR LIGHT POLE & REPAIR. REFIT TO VEHICLE	GTM - Gippsland Truck Mechanic
R-13684	05/03/2021	0	0	Minor Repairs	OVERHAUL ALL BRAKES - REMOVE ALL WHEELS & BRAKE CALIPERS REMOVE ALL HUBS & ROTORS REMOVE ALL GUARDS & BOOSTERS REPAIR 4X BRAKE PAD SHIELDS REFIT ALL WITH NEW BRAKE ROTORS & PADS. CLEAN, CHECK & REPACK ALL WHEEL BEARINGS. FIT NEW HUB SEALS ( KITS ) REFIT ALL GUARDS & WHEELS. ADJUST ALL BRAKES & TEST DRIVE. REPLACE LH MUDGUARD BRACKET	GTM - Gippsland Truck Mechanic
S-8028	04/03/2021	914727	0	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-8238	03/03/2021	914727	0	A - Grease & Brake Adj	"A" CLASS {tanker, pm, tray} TOP UP ENGINE OIL & COOLANT Comment ** VEHICLE CURRENTLY HAVING OTHER JOBS COMPLETED IN W/SHOP	GTM - Gippsland Truck Mechanic
S-7767	19/02/2021	912029	0	A - Grease & Brake Adj	a service	GTM - Gippsland Truck Mechanic
R-15366	08/02/2021			Minor Repairs	repair reverse wiring for trailer. had to run wiring in truck and repair wiring in trailer short	Lunds Auto Electrical
R-13528	08/02/2021	906093		Minor Repairs	Repair damaged air line - supply to rear tank	GTM - Gippsland Truck Mechanic
T-3739	05/02/2021	0	0	Direct Fit	295/80R22.5 BRIDGESTONE R150 position 1 and 2	Latrobe Valley Bandag Pty Ltd
R-13522	01/02/2021	0	0	Parts Only	Fuel filler cap	GTM - Gippsland Truck Mechanic
R-13542	01/02/2021			Parts Only	filler cap	GTM - Gippsland Truck Mechanic
S-7360	13/01/2021	894749	0	B - Oils & Filters	B SERVICE Replace fan belt, fit new cab air filter, top up diff oil	GTM - Gippsland Truck Mechanic
S-7193	31/12/2020	887395	0	A - Grease & Brake Adj	A SERVICE Replace RH fog light globe Tightened loose mudguard pole Secure RHF lower plastic guard	GTM - Gippsland Truck Mechanic
R-12836	30/12/2020	0	0	Minor Repairs	Replace LH low beam headlight globe	GTM - Gippsland Truck Mechanic
T-4154	18/12/2020	0	0	Stock	8 x BDE	Latrobe Valley Bandag Pty Ltd
T-4154	18/12/2020	0	0	Disposal Fee	Disposal fee	Latrobe Valley Bandag Pty Ltd
T-4148	17/12/2020	0	0	Puncture	Puncture repair	Latrobe Valley Bandag Pty Ltd

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-14015	09/12/2020	0	0	Minor Repairs	RH headlight fault and repair and fit new globe	Lunds Auto Electrical
R-14033	09/12/2020	0	0	Minor Repairs	replace headlight globe	Lunds Auto Electrical
R-12583	09/12/2020	879994		Minor Repairs	Reset correct odometer reading	GTM - Gippsland Truck Mechanic
R-14014	07/12/2020	0	0	Minor Repairs	fit GPS to truck	Lunds Auto Electrical
R-12232	25/11/2020	866942	0	Minor Repairs	Check PTO dropping out sometimes. Exchange solenoid & check - made issue worse. Check plug at RH gearbox - found corroded terminal in plug. Clean & check plug at RH gearbox - found corroded terminal in plug. Clean and recheck - ok	GTM - Gippsland Truck Mechanic
S-6727	16/11/2020	862496	0	C - Diffs & G'Box Oils	C SERVICE & VALVE ADJUSTMENT Replaced contaminated coolant - flush system & refill with new coolant. Test drive and recheck. Tightened leaking sight glass at hyd cooler. Mechanical notes: Rear left drive brake at 20%, RH inner fog light no power, rear LH brake light N/W	GTM - Gippsland Truck Mechanic
R-11979	03/11/2020	856201	0	Minor Repairs	Replace retarder temp sensor, replace broken RH inner light in bumper	GTM - Gippsland Truck Mechanic
R-11823	31/10/2020			Minor Repairs	Repair suzi coil end - blue line	GTM - Gippsland Truck Mechanic
S-6376	30/10/2020	854047	0	A - Grease & Brake Adj	A SERVICE Replace broken RHR fuel tank strap, replace cab filter. Mechanical notes: Retarder temp sensor N/W, RH inner spot light in bumper broken (both parts on order), LH brake light N/W, indicator light at front steps N/W.	GTM - Gippsland Truck Mechanic
T-3277	22/10/2020			Fitting Fee	2 x tyres	Latrobe Valley Bandag Pty Ltd
T-3278	22/10/2020			Stock fit by Other	2 x RTE	Latrobe Valley Bandag Pty Ltd



Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
T-3259	20/10/2020			Puncture	Puncture repair	Latrobe Valley Bandag Pty Ltd
R-12446	12/10/2020			Minor Repairs	Repair fault in no brake lights	Lunds Auto Electrical
R-12440	09/10/2020			Minor Repairs	Repair faults in headlights	Lunds Auto Electrical
T-3072	05/10/2020			Non Stock	2 x Bridgestone R150	Latrobe Valley Bandag Pty Ltd
R-11688	02/10/2020	838065	0	Minor Repairs	Check clutch - U/S, remove gearbox and clutch assy. Remove and machine flywheel, repair rear main seal and bolts. Rekit clutch release fork assy. Replace rear engine/gearbox mounts. Replace leaking cab jack pump assy, replace front gearbox front oil pump cover (update) Drain gearbox and retarder oils, pressure clean gearbox, dismantle retarder unit to replace damaged shaft seal. Clean and check all valves and housing for wear, all ok. Re assemble retarder and refit back onto gearbox, replace output seal, refit gearbox back into truck and reconnect. Replace two coolant hoses at retarder cooler and refill with coolant. Fit new oil filters and refill with oil. Start and check. Connect scan tool to reset new clutch and clear all fault codes. Test drive to check retarder operations. ok.	GTM - Gippsland Truck Mechanic
R-10640	29/09/2020	0	0	Minor Repairs	Tow from Poowong to GTM Leongatha	Ingers Transport
R-10388	28/09/2020	837901	0	Minor Repairs	Remove RHF wheel, guard, brake booster and air cleaner housing to access and replace worn drag link with new assy. Refit all Check steering pulling to LHS, check toe in - all ok Check all front end - ok Check leaking air line to rear tank	GTM - Gippsland Truck Mechanic
R-11753	28/09/2020			Minor Repairs	Replace batteries	Lunds Auto Electrical
T-3232	21/09/2020			Fitting Fee	Fitting Fee	Latrobe Valley Bandag Pty Ltd

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
T-2331	21/09/2020			Call out	Call out & fitting fee	Latrobe Valley Bandag Pty Ltd
T-3233	21/09/2020			Stock fit by Other	1 x BDE	Latrobe Valley Bandag Pty Ltd
T-2871	16/09/2020			Puncture, Call Out	POS 8	Latrobe Valley Bandag Pty Ltd
R-9896	15/09/2020			Minor Repairs	Purchase of GPS Unit	Bestrane Pty Ltd
S-5938	10/09/2020	832094	0	B - Oils & Filters	B SERVICE Replaced RHR mudguard & mudflap	GTM - Gippsland Truck Mechanic
R-9744	08/09/2020	830771	0	Minor Repairs	Repair suzi coil end - service line	GTM - Gippsland Truck Mechanic
S-5805	24/08/2020	822204	0	A - Grease & Brake Adj	A SERVICE Remove and repair RH tail light bracket	GTM - Gippsland Truck Mechanic
S-5605	07/08/2020	814147	0	A - Grease & Brake Adj	A SERVICE Replace T80 retarder pressure sensor and top up oil Remove and repair RH tail light bracket Tightened loose LH turn table light bracket Secure hydraulic hoses Tightened loose LHF mudguard poles	GTM - Gippsland Truck Mechanic
T-2714	01/08/2020			Breakdown		Latrobe Valley Bandag Pty Ltd
R-9553	20/07/2020	0	0	Minor Repairs	CHECK AND FIT NEW GLOBE. 1 x 24V H7 70W GLOBE	Lunds Auto Electrical
S-5348	16/07/2020	801761	0	B - Oils & Filters	Mechanical Report NOTE: RH INDICATOR & LH BRAKE LIGHT N/W RH KING PIN 2mm MOVEMENT FRONT DIFF OUTPUT SEAL LEAKING DRAGLINK U/S 1 B SERVICE "B" CLASS {p/mover/dual} \$490.00 \$490.00 1 SC-2277578 FILTER KIT \$134.00 \$134.00 1 EV-3414145 GREASE SPHEEROL ULTRATAK 2 180 \$8.70 \$8.70	GTM - Gippsland Truck Mechanic
R-11085	15/07/2020			Minor Repairs	Mass Management	Mass Management

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-8687	10/07/2020	798475	0	Minor Repairs	Top up retarder with oil	GTM - Gippsland Truck Mechanic
R-8686	09/07/2020	797837	0	Minor Repairs	Replace broken Height control valve rod	GTM - Gippsland Truck Mechanic
R-9105	30/06/2020	0	0	Minor Repairs	Repair RHS headlight fault	Lunds Auto Electrical
R-8246	27/06/2020	793763	0	Minor Repairs	Top up with oil, Check ESP fault - refer to Lundy	GTM - Gippsland Truck Mechanic
R-9104	27/06/2020	0	0	Minor Repairs	Repair EBS wiring. Locate fault in EBS wiring and repair broken wiring	Lunds Auto Electrical
S-5027	25/06/2020	793008	0	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
T-2579	19/06/2020	0	0	Puncture	Puncture repair	Latrobe Valley Bandag Pty Ltd
T-2571	19/06/2020	0	0	Call Out, Puncture	Call out POS 8	Latrobe Valley Bandag Pty Ltd
R-8113	15/06/2020	789256	0	Minor Repairs	Remove drivers seat to access and replace seat pan./metal base plate. Tightened steering wheel tilt lock mechanism. Replace broken RH headlight glass lens.	GTM - Gippsland Truck Mechanic
T-2486	10/06/2020	0	0	Stock		Latrobe Valley Bandag Pty Ltd
T-2486	10/06/2020		0	Balance	Wheel balance	Latrobe Valley Bandag Pty Ltd
S-4910	09/06/2020	786102	0	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
R-7621	19/05/2020	777264	0	Minor Repairs	Replace number plates	GTM - Gippsland Truck Mechanic

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-4518	06/05/2020	771040	0	B - Oils & Filters	B SERVICE Replace globe in LH outer fog light. Repaired air line - fit joiner	GTM - Gippsland Truck Mechanic
R-7834	14/04/2020			Minor Repairs	Fit new batteries supplied by PST	Lunds Auto Electrical
S-4321	07/04/2020	758564	0	A - Grease & Brake Adj	A SERVICE Replace RHF steer lower shocker bushes	GTM - Gippsland Truck Mechanic
R-7180	06/04/2020	0	0	Minor Repairs	RWC Inspection: RHF shocker bush, No 2 axle diff centre leak	Korumburra Mechanical Repairs
R-6894	26/03/2020	0	0	Minor Repairs	Fit new unit for fan cooler on PTO	Lunds Auto Electrical
R-6923	23/03/2020	0	0	Parts Only	Fan to suit 15L oil cooler - 24VDC Oil cooler 18ltr fuse box Oil cooler thermo switch	THS - Transport Hydraulic Solutions
R-6916	21/03/2020	0	0	Minor Repairs	Repair wiring fault to reducer for trailer lights	Lunds Auto Electrical
R-6910	17/03/2020	0	0	Minor Repairs	2 x batteries	Lunds Auto Electrical
R-6274	13/03/2020	751573	0	Minor Repairs	Remove and replace injector Orings. Adjust all valves and injectors. Replace flat batteries.	GTM - Gippsland Truck Mechanic
S-3991	11/03/2020	751201	0	A - Grease & Brake Adj	A SERVICE Replace leaking LHF air bag. Drain engine oil - 20L to high and refill with new oil - monitor.	GTM - Gippsland Truck Mechanic
S-3500	14/02/2020	738697	0	C - Diffs & G'Box Oils	C SERVICE Replace globe in RH roof driving light Replace low RHR brake pads	GTM - Gippsland Truck Mechanic
T-2104	13/02/2020	738061	0	Non Stock	POS 1+2+7+8+9+10	Latrobe Valley Bandag Pty Ltd
R-5661	30/01/2020	733071	0	Minor Repairs	Call out to Wattlebank to bypass leaking air bag. Charge up RHR and follow truck back to Burra to unload. Return truck to workshop to replace air bag.	GTM - Gippsland Truck Mechanic
R-5437	16/01/2020	728458	0	Minor Repairs	Repair leaking air line to rear air tank LH side	GTM - Gippsland Truck Mechanic

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-3118	10/01/2020	725590	0	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
R-5651	04/01/2020	735133	0	Minor Repairs	Carry out repairs to RHR light bar pole	GTM - Gippsland Truck Mechanic
R-5132	24/12/2019	718857	0	Minor Repairs	Rekit leaking power divider shift cylinder	GTM - Gippsland Truck Mechanic
R-5123	19/12/2019	717002	0	Minor Repairs	Replace both suzi coils	GTM - Gippsland Truck Mechanic
T-1722	13/12/2019	714027	0	Stock	POS 3+4+5+6	Latrobe Valley Bandag Pty Ltd
S-2930	12/12/2019	713552	0	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
R-5022	09/12/2019	711708	0	Minor Repairs	Call out to replace leaking coolant hose LHR of engine. Refill with water.	GTM - Gippsland Truck Mechanic
R-4856	09/12/2019	711708	0	Minor Repairs	Call out to replace leaking coolant hose LHR of engine. Refill with water	GTM - Gippsland Truck Mechanic
R-5530	02/12/2019	0	0	Minor Repairs	Repair headlight wiring	Lunds Auto Electrical
S-2647	22/11/2019	703239	0	B - Oils & Filters	B SERVICE Topped up retainer fluid Replaced leaking LHR drive air bag Replaced wiper blades	GTM - Gippsland Truck Mechanic
R-4847	18/11/2019	701126	0	Minor Repairs	Replace LH headlight globe	GTM - Gippsland Truck Mechanic
T-1542	18/11/2019	701394	0	Non Stock	POS 1+2+7+8+9+10	Latrobe Valley Bandag Pty Ltd
R-4842	12/11/2019	0	0	Parts Only	Hub cap	GTM - Gippsland Truck Mechanic

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-2396	31/10/2019	691568	0	A - Grease & Brake Adj	A SERVICE Replace coolant hose LH side rear of engine with new hose Refill with new coolant	GTM - Gippsland Truck Mechanic
R-4497	26/10/2019	690103	0	Minor Repairs	Make temporary repair leaking coolant hose LHS rear of engine to gearbox retarder	GTM - Gippsland Truck Mechanic
R-4486	17/10/2019	686960	0	Minor Repairs	Remove all drive mudguards & tyres & replace all pivot bushes. Remove turn table to clean & replaced loose bolts. Weld bolts as required. Greased & tightened loose ring bolts & tightened ball race bolts. Remove steer tyres, remove axle to overhaul king pins. Replaced RH tie rod end. Remove LHR shackle pins & bushes. Replace all front spring shackle pins & bushes. Retension all wheel nuts & fit indicators back to wheel nuts. Replace rear signs & cut down rear light brackets for guards. Drain coolant to replace thermostat. Replace belt tensioner, RHF cab shocker & Adblue doser pump (taken to fit to 1IE3JA)	GTM - Gippsland Truck Mechanic
R-4487	17/10/2019	0	0	Parts Only	Adblue Doser Pump	GTM - Gippsland Truck Mechanic
R-4358	15/10/2019			Parts Only	Cab Compression Spring Assy	GTM - Gippsland Truck Mechanic
R-4289	15/10/2019	0	0	Parts Only	Belt Tensioner	GTM - Gippsland Truck Mechanic
S-1870	19/09/2019	679558	0	A - Grease & Brake Adj	A SERVICE Cleaned radiator and test drive - thermostat may be an issue Tightened loose LHF mudguard pole Mechanical note: Rear pivot bushes u/s Front sway bar D bushes worn All front shackles worn RH tie rod end Front diff centre leaking oil	GTM - Gippsland Truck Mechanic
S-1748	03/09/2019	671929	0	B - Oils & Filters	B SERVICE Top up diff & gearbox oils Top up cab lift ram fluid Mechanical note; Strg axle king pins u/s LHR air bag perished & RHF u/s Rear of front diff seal leaking RH tie rod end u/s	GTM - Gippsland Truck Mechanic

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-4404	02/09/2019	0	0	Minor Repairs	Repair fault in truck EBS. Removed loom from left hand side under chassis and repaired broken power and data wiring from ECU	Lunds Auto Electrical
R-3741	22/08/2019	0	0	Minor Repairs	Replace batteries	Lunds Auto Electrical
R-3768	22/08/2019	0	0	Minor Repairs	Fit new batteries Repair ESC warning faults. Removed wiring loom and repaired wiring fault between dash and module on RHS	Lunds Auto Electrical
R-2930	07/08/2019	0	0	Minor Repairs	Fit new coolant hose to retarder to replace temporary repair hose. Fill with coolant	GTM - Gippsland Truck Mechanic
T-885	06/08/2019	660279	0	Non Stock	M50 POS 1+2	Latrobe Valley Bandag Pty Ltd
R-3744	06/08/2019	0	0	Minor Repairs	Locate and repair fault in high beam. Fit new globe	Lunds Auto Electrical
S-1521	01/08/2019	658050	0	A - Grease & Brake Adj	A SERVICE Adjust RH door catch Mechanical note; Output shaft seal on front diff leaking	GTM - Gippsland Truck Mechanic
R-3211	23/07/2019	0	0	Minor Repairs	Go to Korumburra at 5am and get truck going. Driver stated "Not my fault someone left the key on when they moved it."	Lunds Auto Electrical
R-2773	20/07/2019	652765	0	Minor Repairs	Replace leaking main hydraulic hose from pump to pressure filter, top up tank	GTM - Gippsland Truck Mechanic
S-1301	11/07/2019	649208	0	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
T-800	11/07/2019	649006	0	Stock	POS 3+4+5+6	Latrobe Valley Bandag Pty Ltd
R-3191	09/07/2019	648532	0	Minor Repairs	Repair fault in head light	Lunds Auto Electrical
R-2617	05/07/2019	646033	0	Minor Repairs	Call out to Mirboo Nth Coolant leak - broken pipe mounts, made a temporary repair, refilled with water and returned to workshop Removed and fit new mounts and add more protection to hose	GTM - Gippsland Truck Mechanic
R-3184	04/07/2019	0	0	Minor Repairs	Replace globe and check lights	Lunds Auto Electrical

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
T-793	04/07/2019	645298	0	Stock	POS 7+8+9+10	Latrobe Valley Bandag Pty Ltd
R-2260	01/07/2019	633642	0	Minor Repairs	Repair broken RHR tail light mounting bracket Replace missing RHF drive hub cap	GTM - Gippsland Truck Mechanic
S-1137	26/06/2019	640893	0	B - Oils & Filters	B SERVICE Sublet - replace u/s windscreen Replace worn turn table foot bushes Mechanical note; Front drive tyres low	GTM - Gippsland Truck Mechanic
S-1067	06/06/2019	630640	0	A - Grease & Brake Adj	A SERVICE	GTM - Gippsland Truck Mechanic
R-2227	05/06/2019	0	0	Minor Repairs	Perform brake test Inspected pins and bushes Inspect King pins	G&R Maintenance
S-653	09/05/2019	620202	0	A - Grease & Brake Adj	Replaced RHR light pole bushing Replace LHF shocker bush	GTM - Gippsland Truck Mechanic
R-2379	03/05/2019	0	0	Minor Repairs	Locate and repair fault in EBS wiring. Repaired wiring under truck on RH side, loom was rubbed through and had broken wiring.	Lunds Auto Electrical
R-1339	02/05/2019	613000	0	Minor Repairs	Connect scan tool to check EBS faults Front EBS control unit issue Repair leaking air line at LH side air valve box	GTM - Gippsland Truck Mechanic
T-433	29/04/2019	616454	0	New		Latrobe Valley Bandag Pty Ltd
R-2189	21/04/2019	0	0	Minor Repairs	Repair PTO fan wiring	Lunds Auto Electrical
R-986	17/04/2019	0	0	Minor Repairs	Repair cracks in fuel tank	Hulls Engineering
S-518	16/04/2019	611456	0	B - Oils & Filters	Tightened mudguards Repairs to cracks Replaced LH fog light globe	GTM - Gippsland Truck Mechanic
R-2179	09/04/2019	0	0	Minor Repairs	Replace batteries.	Lunds Auto Electrical
R-779	02/04/2019	0	0	Parts Only	Marker Lamp Roof Clear	GTM - Gippsland Truck Mechanic



Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-2170	02/04/2019	0	0	Minor Repairs	Repair fault in roof lights. Replace reducer. Repair fault in park light. Reducer was faulty, found short which caused reducer to fail.	Lunds Auto Electrical
R-936	29/03/2019	0	0	Minor Repairs	Repair fault in brake lights on truck. Bypass reducer and repair short	Lunds Auto Electrical
R-649	29/03/2019	0	0	Minor Repairs, Parts Only		Scania
R-748	22/03/2019	602726	0	Minor Repairs	Replace U/S tie rod assy - adjust toe in Replace worn brake pads	GTM - Gippsland Truck Mechanic
S-277	19/03/2019	602129	0	A - Grease & Brake Adj	Tightened loose LHR mudguard brackets	GTM - Gippsland Truck Mechanic
R-422	13/03/2019	0	0	Minor Repairs	SUPPLY ONLY	GTM - Gippsland Truck Mechanic
R-896	08/03/2019	0	0	Minor Repairs	Repair worklight wiring	Lunds Auto Electrical
T-237	28/02/2019	594724	0	Own	POS 7+8+9+10	Latrobe Valley Bandag Pty Ltd
R-626	28/02/2019	0	0	Minor Repairs	Replace headlight globe	Lunds Auto Electrical
T-207	08/02/2019	586927	0	New		Latrobe Valley Bandag Pty Ltd
R-592	07/02/2019	0	0	Minor Repairs	Replace thermo control unit in scania for hydraulic fan	Lunds Auto Electrical
S-830	14/01/2019	577843	0	B - Oils & Filters	Mechanical note Tie rod ends worn ( on order)	GTM - Gippsland Truck Mechanic
S-2149	14/01/2019	577843	0	C - Diffs & G'Box Oils	C SERVICE	GTM - Gippsland Truck Mechanic
S-2146	20/12/2018	566266	0	A - Grease & Brake Adj	A SERVICE Replaced missing LHF drive mud flap Secure number plate light Top up hydraulic oil	GTM - Gippsland Truck Mechanic

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-4122	19/12/2018			Minor Repairs	Credit for call out to Leongatha Depot to connect computer to check EBS fault Check and test circuit - confirm with tech support Replace EBS ECM. Connect SDP3 to clear fault codes and reprogram new unit	GTM - Gippsland Truck Mechanic
S-2107	05/12/2018	557176	0	A - Grease & Brake Adj	A SERVICE Replace adblue doser unit Repair broken wire to RH rear indicator RHF mud flap falling off Top up leaking cab lift pump	GTM - Gippsland Truck Mechanic
R-40	26/11/2018	554790	0	Minor Repairs	replace leaking air dryer filter (split)	GTM - Gippsland Truck Mechanic
R-1575	12/11/2018	0	0	Parts Only	Rear Reflective Mounting Bracket	GTM - Gippsland Truck Mechanic
S-795	12/11/2018	547401	0	B - Oils & Filters	Replace missing LHR reflective sign bracket and sign	GTM - Gippsland Truck Mechanic
R-706	09/11/2018	546221	0	Minor Repairs	Tightened grill bolts & refit into position	GTM - Gippsland Truck Mechanic
R-698	05/11/2018	544299	0	Minor Repairs	Replace LHR mudguard Supplied air bags to Good Car to fit	GTM - Gippsland Truck Mechanic
R-23	05/11/2018	544230	0	Minor Repairs	Replace rear RH drive air bag	Goodcar Pty Ltd
R-118	29/10/2018	0	0	Minor Repairs	fit new batteries into scania and check	Lunds Auto Electrical
R-291	23/10/2018	521871	0	Minor Repairs	Replace cracked exhaust manifolds ALL PARTS COVERED BY WARRANTY, NO LABOUR COVER	GTM - Gippsland Truck Mechanic
R-107	23/10/2018	0	0	Minor Repairs	go to yard and jump start scania truck check battery drain check batteries	Lunds Auto Electrical
S-152	19/10/2018	539826	0	A - Grease & Brake Adj	A Service Replace Exhaust pipe (removed to put onto another truck) connect scan tool to check suspension fault replace unsatisfactory rear height control solenoid	GTM - Gippsland Truck Mechanic
R-216	14/10/2018	0	0	Minor Repairs		
R-215	12/10/2018	0	0	Minor Repairs		

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
T-106	11/10/2018	0	0	Puncture	Work done by Stewarts	Latrobe Valley Bandag Pty Ltd
R-264	11/10/2018	537207	0	Minor Repairs	connect scan tool to check retarder faults - 2 faults with not engaging and disengaging run test to check with computer remove tread plate to check solenoids - ok check supply to shift cylinder - found leaking air fitting. tighten and test drive - ok monitor replace cooler line mounting insulator	GTM - Gippsland Truck Mechanic
R-101	09/10/2018	0	0	Minor Repairs	fit new battery to truck batteries supplied by Stoitse	Lunds Auto Electrical
S-110	01/10/2018	529190	0	A - Grease & Brake Adj	tightened LHF mudguard pole A service	GTM - Gippsland Truck Mechanic
R-157	20/09/2018	521871	0	Minor Repairs	call out to Leongatha depot to check EBS warning display, unable to clear faults, recheck next day and trouble shoot circuits, all other system ok. replace failed ECU BMS unit an dreprogram, test drive - Ok	GTM - Gippsland Truck Mechanic
R-154	18/09/2018	521871	0	Minor Repairs	replaced damaged LHR light pole replaced exhaust manifolds x 3 (warranty) call out to Leongatha depot to connect computer to check EBS fault re check 19/09 and test circuit - confirm with tech support replace EBS ECM. connect SDP3 to clear fault codes and reprogram new unit	GTM - Gippsland Truck Mechanic
S-86	14/09/2018	519158	0	B - Oils & Filters	B service change over LHR mudguard pole replace O ring in return Hyd coupling replace wiper blades replace mounting bolts on Hyd tank adjust turn table repairs to front mudguard	GTM - Gippsland Truck Mechanic
T-4	05/09/2018	0	0	New	295/80R22.5 x 2	Latrobe Valley Bandag Pty Ltd
T-7	03/09/2018	511425	0	Own	295/80 R 22.5 152M Toyo M144A Balanced rear drive tyres	Latrobe Valley Bandag Pty Ltd

Signed: \_\_\_\_\_

Name: \_\_\_\_\_