



Vehicle Service Records (VSR Explorer)

Repair history D-200793

Registration nr: FH16A64T **Chassis nr:** D-200793 **VIN nr:** YV5RP90D3ED200793
Market type: **Country:** AUS **Delivery date:** 2014-12-31

PC	Type	Code	Description (Original)	#
2022-08-22 - Mileage: 1251551 - Order nr: 2231267				
		SHIFT	DAY	
		VO-8740200	Evaporator, replace	4
			evaporator. Check and repair as required.	
		VO-82348991	EVAPORATOR	1
		VO-23847736	DECAL	1
		VO-23858694	ACCUMULATOR	1
		VO-82356754	O-RING	1
		VO-82356760	O-RING	2
		VO-82386482	O-RING	1
		OTH-TXX2619	ORIFICE TUBE RED 0.062IN FORD	1
		VO-23515329	VENTILATION FILTER	1
		VO-23515346	VENTILATION FILTER	1
		VO-978999	BLADE FUSE 20A	1
		VO-6781769	SPLICE-RED(22-18)	8
		VO-82356756	O-RING	1
			Connected test equipment. Found no gas in system.	
			Pressure tested. Found leak in evaporator. Carried out	
			P & A to replace. All OK. Disassembled dash and	
			removed A/c unit. Removed and replaced evaporator. Refit	
			A/c unit and secure. Removed and replaced orifice tube	
			and filters. Vac system for 40 mins. All OK. Gas	

PC	Type	Code	Description (Original)	#
	📄		system. Ran and tested. All OK. Refit and secure dash	
	📄		panels. Road tested. All OK.	
🟢	*	97	AIR COND. GAS	
🟢	*	91	CONSUMABLES	
🔍 2022-07-25 - Mileage: 1236847 - Order nr: 2230840				
🟡	*	2630800	Fan belt tensioner, replace	
🟡	📄	VO-21631484	BELT TENSIONER	1
	📄		*** POSSIBLE POLICY CLAIM ***	
🔍 2022-07-04 - Mileage: 1227196 - Order nr: 2230366				
🟢	*	SHIFT	DAY	
🟢	🕒	LO-360	ELECTRICAL FAILURE IN DASH	1
	📄		INSTRUMENTS ARE NOT WORKING	
🟢	📄	OTH-F	FREIGHT	10
	📄		AIR FREIGHT ESTIMATE	
	📄		EX-EAST DEALER	
🟢	🕒	LO-365	REPLACE HMIOM MODULE	3
	📄		Remove and replace HMIOM module as required and program	
🟢	📄	VO-22282682	CONTROL UNIT	1
	📄		Brought vehicle into workshop. Connected lap top.	
	📄		as required. Cleared codes. Checked over. All OK.	
	📄		Download and read DTCs. Went through parameter	
	📄		programming for vehicle time and date setting Found to be	
	📄		maxed out. Carried out hardware replace and reprogrammed	
	📄		HMIOM but still reading incorrectly. Quoted repair as	
	📄		required.	
🟢	*	91	CONSUMABLES	
🔍 2022-05-12 - Mileage: 1209157 - Order nr: 2229181				
🟢	*	SHIFT	DAY - 12/05/2022.	

PC	Type	Code	Description (Original)	#
		LO-725	RH SIDE SUSPENSION SITTING LOW	5.35
			- CHECK AND RECTIFY.	
			Connect laptop and check fault codes - none related to	
			suspension. Check over for leaks - none found. Carry out	
			pressure sensor tests - RH lower than the LH by 10-20 KPA.	
			Carry out level sensor test - RH constantly lower by 3 MM.	
			Attempt to calibrate - no go. Test power and earth to the	
			level sensor - OK. Run accessory kit 85143339. Carry out	
			level sensor calibration - OK. Re-test level and pressure	
			sensors - all OK.	
 2022-04-27 - Mileage: 1202949 - Order nr: 2228916				
		SHIFT	DAY	
		LO-363	WIPERS WILL NOT TURN OFF	5
			DRIVER HAS PULLED K05 RELAY TO STOP WIPERS.	
		VO-23796624	BASE PLATE	1
		VO-22860372	SWITCH	1
		VO-22943668	INDICATOR STALK FH4	1
		VO-22860391	SWITCH - ENGINE/TRALIER BRAKE	1
		VO-972007	SCREW	1
			Connected lap top. Download and read DTCs. Carried out GD	
			on logged faults. Traced fault to internal failure in	
			base plate and stalks. Removed shrouds. Removed air bag.	
			Removed steering wheel. Unclip and disconnected harness.	
			Removed and replaced base plate and stalks. Connect and	
			secure harness'. Refit steering wheel, Air bag, etc and	
			secure. Connected lap top. Calibrated system. Cleared	
			codes. Road tested. Checked all stalk functions. All OK.	
		91	CONSUMABLES	

PC	Type	Code	Description (Original)	#
----	------	------	------------------------	---

2022-04-23 - Mileage: 1203962 - Order nr: 2228874

	*	SHIFT	WEEKEND - 23/04/2022.	
		LO-560	COMPRESSOR OVER USE WARNING ON DASH	6
			- INTERNAL FAULT IN THE APM.	
		VO-85023466	EXCH AIR DRIER	1
		VO-991972	NIPPLE	2
		VO-992249	ELBOW NIPPLE	1
		VO-981380	VIPS NIPPLE 16MM	1
		VO-981235	VIPS NIPPLE 16MM	1
		VO-20733172	SILENCER	1
			NEW UNIT SN: 10R 036239 22082 00208	
			Mark airlines and remove all attachments from the APM.	
			Fit new APM. Swap over required fittings. Connect all	
			airlines and attachments. Fit new silencer. Connect laptop	
			and reprogram the APM control unit and software. Attempt	
			to carry out lane keeping and forward looking	
			calibrations - would not complete. Report to customer.	
	*	91	CONSUMABLES	

2022-04-14 - Mileage: 1201962 - Order nr: 2228706

	*	SHIFT	DAY -	
		LO-510	DIAGNOSE ELECTRONIC PARK BRAKE FAULT	5
			Customer informed they drove into the shed and park brake	
		VO-20733172	SILENCER	1
		VO-980833	PLASTIC PIPE 12MM	1
		VO-991075	NIPPLE	4
		LO-551	TRAILER MODULATOR & VALVE - REPLACE	4
		VO-23166657	MODULATOR	1
		VO-85104850	VALVE	2

PC	Type	Code	Description (Original)	#
®	■	VO-3173150	RELAY VALVE	1
®	■	VO-20467891	SILENCER	1
	☒		NEW UNIT SN: 2148 00251.	
	☒		NOTE: NO TIME CHARGED FOR THE REMOVAL AND REFITMENT	
	☒		INTERNAL LEAK FOUND BETWEEN TRAILER MODULATOR AND	
	☒		PARK BRAKE RELAY VALVE.	
	☒		Carry out hardware replace on laptop. Read data from old	
	☒		APM. Connect new APM and program. Reset the filter. Start	
	☒		truck. Build up air and release the park brake - OK.	
	☒		Attempt to apply the park brake - would not apply. Failure	
	☒		warning appeared on the dash. Connect laptop - found	
	☒		active code for park brake fluid leakage or seal failure.	
	☒		Carry out diagnostic checks. Fit new silencer to the APM -	
	☒		still faulting. Check trailer brake modulator and relay	
	☒		valve - OK. Check lines for the APM - OK. Remove the park	
	☒		brake relay valve. Individually inspect all lines to	
	☒		boosters and blow air through to remove any possible	
	☒		debris. Blank off lines to supply the park brake and	
	☒		remove the lines at the booster. Supply air to the service	
	☒		brake side of the booster to check for internal leakage or	
	☒		backfeeding to the park brake side - no fault found.	
	☒		Individually plug each booster back in, release and apply	
	☒		one at a time - none fault. Reassemble all removed	
	☒		components. Road test - unable to get vehicle to fault.	
	☒		Customer to take and monitor.	
	☒		would not come on, they hit the emergency park brake and	
	☒		it applied park brake. Also has APM - C102668 on dash.	
	☒		OF APM AS THIS DID NOT RECTIFY FAULT.	

PC	Type	Code	Description (Original)	#
	🔍		Truck returned. Use air pressure gauges to read the park	
	🔍		and service brake lines - found a slight leak from the	
	🔍		trailer brake modulator. Remove the APM and refit the	
	🔍		original unit. Road test - unable to get vehicle to fault.	
	🔍		Replace the trailer modulator, relay valve and 2x check	
	🔍		valves with new. Relay o'rings were cracked internally.	
	🔍		Road test - all OK.	
🟢	*	91	CONSUMABLES	
🔍 2022-04-07 - Mileage: 1201934 - Order nr: 2228484				
🟢	*	SHIFT	DAY	
🟢	🟡	LO-720	REAR SUSPENSION LEANS TO ONE SIDE	6.5
	🔍		WHEN LOADED, IT SCRAPES ON THE GUARDS	
🟢	🔍	VO-22058741	AIR SPRING, SMALL, STD LIFT	4
🟢	🔍	VO-22058737	AIR SPRING	4
	🔍		Measure ride height. Found truck sitting level.	
	🔍		Connected lap top. Download and read DTCs. No related	
	🔍		codes noted. carried out pressure sensor test and confirm	
	🔍		all is plumbed correctly. All readings in spec. Carry	
	🔍		out level sensor test. All OK. Checked control rods.	
	🔍		Found secure. Spray air bags with soapy water. No leaks	
	🔍		noted. Note: truck is no loaded. Checked history.	
	🔍		Truck has had replacement load level sensor, mega valve	
	🔍		etc. Suspect airbags are leaking when truck is loaded.	
	🔍		Carried out P & A to replace airbags. All OK. Removed	
	🔍		and replaced all air bags. Checked over. All OK.	
🟢	*	91	CONSUMABLES	
🔍 2022-03-24 - Mileage: 1195728 - Order nr: 2228281				
🟢	🟡	LO-560	PARK BRAKE CODE C101D7A	4

PC	Type	Code	Description (Original)	#
		LO-711	WHEN GOING UP GREEN MOUNT	2.5
			AT 50KS THE TRAILER STARTS BOUNCING, IF THE DRIVER LIFTS	
		VO-991089	NIPPLE	1
		VO-3173150	RELAY VALVE	1
		VO-20467891	SILENCER	1
		VO-991084	SWIVEL FITTING	2
		VO-991083	SWIVEL	2
		VO-992247	SWIVEL	1
			THE RIDE HEIGHT IT STOPS - CHECK	
			Connected lap top. Download and read DTCs. Carried out	
			GD. Checked for air leaks. Found park brake release valve	
			leaking air from both solenoids at front of cab and near	
			APM. Fit test solenoid. Found fault still present.	
			Followed airline to where it was back feeding. Found	
			fault in relay valve. Removed and replaced relay valve.	
			Re tested. All OK.	
			Checked over vehicle for air leaks. All OK. Checked all	
			rear air bags. All OK. Checked sensor readings. All OK.	
			Carried out load sensor calibration. Customer to monitor.	
		91	CONSUMABLES	

2022-02-04 - Mileage: 1170403 - Order nr: 2226905

		SHIFT	DAY - 04/02/2022.	
		LO-562	PNUEMATIC PARK BRAKE MODIFICATION	8
		VO-1078322	SOLENOID VALVE	1
		VO-1190557	SWITCH GUARD ONLY	1
		VO-20517988	ADAPTER	2
		VO-20566049	FITTING	2
		VO-21365502	BRACKET	1

PC	Type	Code	Description (Original)	#
®	☒	VO-21455792	BRACKET	1
®	☒	VO-22154054	WIRES	1
®	☒	VO-22287251	BRACKET	1
®	☒	VO-22431789	CLAMPING PLATE	1
®	☒	VO-22783257	PLATE	1
®	☒	VO-22783263	MOUNTING PLATE	1
®	☒	VO-22783265	DECAL	1
®	☒	VO-22821617	WIRES	1
®	☒	VO-22911321	WIRES	1
®	☒	VO-22992967	BRACKET	1
®	☒	VO-25161152	VALVE	1
®	☒	VO-25162736	1/4 BLACK AIRLINE	5
®	☒	VO-25572748	AIR DISTRIBUTOR	1
®	☒	VO-25617877	CABLE SEAL	4
®	☒	OTH-5823TW	TWIN CORE CABLE 3MM	5
®	☒	VO-60111728	SIX POINT SOCKET S	1
®	☒	VO-946577	LOCK NUT	2
®	☒	VO-948211	CABLE TIE	20
®	☒	VO-965768	PLUG	1
®	☒	VO-966458	ADAPT/16MM-12MM	2
®	☒	VO-977931	GASKET	1
®	☒	VO-980464	STRIP CLAMP - CABLE TIE	50
®	☒	VO-980831	PLASTIC PIPE 6MM	19
®	☒	VO-983014	CABLE TERMINAL	2
®	☒	VO-983017	CABLE SEAL	2
®	☒	VO-984724	M6*12 FL BOLT	7
®	☒	VO-984735	M8*25 FL BOLT	2
®	☒	VO-984814	M12*25 FL BOLT	1

PC	Type	Code	Description (Original)	#
®	☒	VO-990828	PLUG	1
®	☒	VO-990938	FLANGE NUT	2
®	☒	VO-990950	M8 FLANGE LOCK NUT	2
®	☒	VO-991073	NIPPLE	1
®	☒	VO-991089	NIPPLE	5
®	☒	VO-991185	T-NIPPLE	1
®	☒	VO-991970	NIPPLE	1
®	☒	VO-992016	SWIVEL	2
®	☒	VO-992017	SWIVEL	1
®	☒	VO-992023	TEST NIPPLE	1
®	☒	VO-992024	ELBOW NIPPLE	3
®	☒	VO-992231	NIPPLE	2
®	☒	VO-992257	NIPPLE	1
®	☒	VO-992298	NIPPLE	1
®	☒	VO-992308	NIPPLE	1
®	☒	VO-992951	NIPPLE	2
®	☒	VO-992953	SIX POINT SOCKET S	3
®	☒	VO-993222	NIPPLE	2
®	☒	VO-993247	ELBOW NIPPLE	2
®	☒	VO-993248	ELBOW NIPPLE	1
®	☒	VO-993360	HOUSING	1
®	☒	VO-993364	HOUSING	1
®	☒	VO-993750	CABLE TERMINAL	2
®	☒	VO-995627	PLUG	1
®	☒	VO-996110	PLUG	1
®	☒	OTH-QNC12	NYLON CONDUIT 9.9mm	5
®	☒	VO-993360	HOUSING	2
®	☒	VO-992303	PIPE RETAINER 8mm	1

PC	Type	Code	Description (Original)	#
Ⓡ	✘	VO-991971	NIPPLE	2
	📄		Install emergency park brake system as required. Test - OK.	
🔍 2021-12-20 - Mileage: 1147310 - Order nr: 2226403				
Ⓡ	*	SHIFT	DAY	
Ⓡ	👤	LO-725	Rear suspension sitting	6.3
	📄		too low and rubbing on guards - Investigate, report and	
Ⓡ	✘	VO-21133934	CONTROL VALVE FH4	1
	📄		21252 0018	
Ⓡ	✘	VO-991084	SWIVEL FITTING	1
Ⓡ	✘	VO-991083	SWIVEL	4
Ⓡ	✘	VO-991062	PLUG	2
Ⓡ	✘	VO-991075	NIPPLE	5
Ⓡ	✘	VO-993859	ELBOW NIPPLE	4
Ⓡ	✘	VO-20393945	PLUG	2
Ⓡ	✘	VO-993376	HOUSING	1
	📄		Inspected. Found suspension control valve faulting	
	📄		rectify	
	📄		internally. Removed and replaced control valve. Tested.	
	📄		Found fittings leaking air. Removed and replaced fitting	
	📄		as required. Re calibrated suspension. Test drive. All	
	📄		OK.	
Ⓡ	*	91	CONSUMABLES	
🔍 2021-12-15 - Mileage: 1146300 - Order nr: 2226325				
Ⓡ	*	SHIFT	DAY - 15/16.12.2021.	
Ⓡ	👤	LO-764	RIDE HEIGHT HIGHER ON ONE SIDE	2.5
Ⓡ	👤	LO-210	ENGINE OIL LEAKS - CHECK AND REPORT	0.5
Ⓡ	✘	VO-22194741	SENSOR	2
	📄		- LEVEL SENSORS NOT READING CORRECTLY.	

PC	Type	Code	Description (Original)	#
	🔧		Connect laptop - no related fault codes. Carry out ride	
	🔧		height calibration - failed. Check level sensor readings	
	🔧		and found RHS incorrect. Replace the RH side sensor with	
	🔧		new. Re-check sensor readings and found LHS now incorrect.	
	🔧		Replace the LH side sensor with new. Carry out calibration	
	🔧		all OK and sensors bot now reading correctly. All OK.	
	🔧		Inspect and found multiple oil leaks; timing plate, oil	
	🔧		filler pipe, 1st drive through shaft and compressor dis-	
	🔧		charge pipe fittings. Remove the pipe and check inside the	
	🔧		compressor - found full of carbon and moist from oil.	
🟢	*	91	CONSUMABLES	
🔍 2021-11-29 - Mileage: 1136148 - Order nr: 2225755				
🟢	*	SHIFT	DAY - 29/30.11.2021.	
🟢	🔧	LO-720	FRONT SPRINGS & SHACKLES - REPLACE	14
🟢	🔧	VO-257940	FRONT SPRING	2
🟢	🔧	VO-22281780	U-BOLT	2
🟢	🔧	VO-22935391	U-BOLT	2
🟢	🔧	VO-22944256	FLANGE NUT	8
🟢	🔧	VO-21960567	FLANGE SCREW	4
🟢	🔧	VO-21960568	FLANGE SCREW	2
🟢	🔧	VO-21376743	SLEEVE	2
🟢	🔧	VO-992347	FLANGE SCREW	2
🟢	🔧	OTH-F	FREIGHT	10
🟢	🔧	VO-21175831	BUSHING	2
	🔧		Replace front springs, shackles and u-bolts with new.	
	🔧		- INC. TIME TO REMOVE AND REFIT	
	🔧		FUEL TANKS FOR ACCESS.	
🟢	*	91	CONSUMABLES	

PC	Type	Code	Description (Original)	#
🔍 2021-11-11 - Mileage: 1129923 - Order nr: 2225391				
Ⓡ	*	SHIFT	DAY	
Ⓡ	🔧	LO-214	VALVE MECHANISM	3.5
Ⓡ	🔧	LO-258	REPLACE AD BLUE FILTERS	0.75
Ⓡ	🔧	LO-561	REPLACE AIR DRIER FILTER	1.25
	📄		ALSO APM LEAKING AIR FROM BOTTOM VALVE - SEE ATTACHED	
Ⓡ	🔧	LO-640	FIT STEERING LINK ARM - PARTS IN VPW -	2
	📄		CUSTOMER REQUEST	
Ⓡ	🔧	VO-82269261	FILTER/MAGNET	1
Ⓡ	🔧	VO-20733172	SILENCER	1
Ⓡ	🔧	VO-23690622	APM DRYER FILTER KIT	1
	📄		*** POSSIBLE POLICY CLAIM ***	
Ⓡ	🔧	VO-23381562	ADBLUE FILTER	1
Ⓡ	🔧	VO-21954674	STRAINER	1
Ⓡ	🔧	VO-23834388	LINK ROD	1
	📄		Removed intakes etc. Removed rocker cover. Carried out	
	📄		top set to spec. Record all measurements. Refit rocker	
	📄		cover and secure. Refit intakes etc. Checked over. All	
	📄		OK.	
	📄		Removed and replaced air drier filter and silencer.	
	📄		Connected lap top. Calibrated and tested. All OK. No	
	📄		leaks noted.	
	📄		Removed and replaced both Adblue filters as strainer.	
	📄		Checked over. All OK.	
	📄		HISTORY	
	📄		Removed and replaced steer drag link as requested by	
	📄		Customer. Checked over. All OK.	
Ⓡ	*	91	CONSUMABLES	

PC	Type	Code	Description (Original)	#
2021-10-25 - Mileage: 1119807 - Order nr: 2225085				
	*	SHIFT	DAY - 25/10/2021.	
		LO-560	FOOTBRAKE VALVE FAULT C107149	6
			- WATER LEAKING FROM TOP RH	
		VO-20544196	ELBOW NIPPLE	2
		VO-22085772	MODULATOR	1
		OTH-F	FREIGHT	3
		VO-992303	PIPE RETAINER 8mm	1
			762556	
			FOG LAMP DOWN INTO THE VALVE.	
			COURIER CHARGE.	
			Connect laptop and carry out GD on active fault code;	
			check over for air leaks around the air drier - found both	
			90 degree air fittings on the TECU leaking. Replace the	
			fittings with new. Strip out required dash panels and dis-	
			connect airlines from the valve. Remove the valve, found	
			water present. Clean the firewall and valve mating	
			surfaces. Fit new valve. Connect airlines and reassemble	
			the dash. Clear fault codes. Road test - all OK.	
	*	91	CONSUMABLES	
2021-10-04 - Mileage: 1106693 - Order nr: 2224401				
	*	SHIFT	DAY - 04/10/2021.	
		VO-1774400	Basic service. Chassis lubrication and o	3.5
	*	94	WASTE DISPOSAL	
		VO-24122024	SERVICE KIT	1
		AU2-CAL85121795	VDS4 BULK	43
		AU2-CAL85131754PO	VOLVO GEAR OIL 1LT(97315)75/90	2
		VO-60110514	OBD PLUG BLUE	1

PC	Type	Code	Description (Original)	#
		VO-20716774	TERMINAL	2
			Carried out basic service as per specifications.	
			Top up gearbox oil to max level.	
		LO-371	OBD PINS DAMAGED - REPLACE	0.2
			Replace the OBD plug and terminals with new.	
		91	CONSUMABLES	

 **2021-09-24 - Mileage: 1102742 - Order nr: 2224030**

		SHIFT	DAY - 24/09/2021.	
		LO-511	FRONT STEER CALIPERS - REKIT	5
		VO-85109890	REPAIR KIT	2
		VO-22783548	^^REPAIR KIT	1
			Jack up axle. Remove wheels. Remove calipers. Strip and	
			rekit with new parts. Reassemble in reverse order. Refit	
			wheels and torque wheel nuts. Lower axle to ground.	
		91	CONSUMABLES	

 **2021-08-14 - Mileage: 1077886 - Order nr: 2223307**

		SHIFT	DAY	
		LO-258	Adblue fault on dash	1.5
			Investigate, report and rectify	
		VO-22851845	PUMP UNIT	1
			S/N#0444042156	
			17031	
			Connected lap top. Download and read DTCs. Found Adblue	
			Pump fault logged. Carried out pressure test. Found	
			Adblue pump not building pressure. Carried out P & A for	
			New pump. All OK. Removed and replaced pump. Pressure	
			Tested. Pump now building pressure. Cleared codes. All	
			OK.	

PC	Type	Code	Description (Original)	#
	*	91	CONSUMABLES	
2021-07-29 - Mileage: 1068569 - Order nr: 7722570				
	*	DETAILS	DETAILS	
			CONTACT PERSON:	
		LO-330	STARTING ISSUE	1
			FEELS LIKE STUCK IN GEAR WHEN TRYING TO START	
		LO-330	STARTER FAULT	4
		VO-85020793	EXCH STARTER MOTOR	1
		VO-984481	CABLE TERMINAL	2
		VO-948211	STRIP CLAMP	10
		VO-980464	STRIP CLAMP	5
			VEH KM: 1068569	
			ENG HRS: 15280	
			FUEL BURN: 815047	
			testing start motor, couldn't start	
			tilt cab, inspect starter motor	
			notice power cable brittle & exposed	
			inspected starter terminals, solenoid contacts cracked	
			quote parts	
			removed starter & cable	
			make up new cable	
			fit starter & cable - OK	
			time added as aftermarket hose got in the way	
			tested - OK	
		OTH-5803BK	CABLE BATTERY	1
	*	91	CONSUMABLES	
2021-07-06 - Mileage: 1053852 - Order nr: 2222159				
	*	SHIFT	DAY	

PC	Type	Code	Description (Original)	#
		LO-711	Suspension sitting un even and adjusting	2.5
			by itself, causing the trailer to be thrown from side to	
		LO-410	MEASURE CLUTCH THICKNESS	0.25
			Carried out clutch wear test. No wear noted.	
			Connected lap top. Download and read DTCs. No suspension	
			faults noted. Checked air bags. All inflated equally.	
			Checked control rods. All secure. Carried out pressure	
			and level sensor checks with lap top. All pass OK.	
			Recalibrated ride height. Checked suspension height.	
			Found sitting level. Deleted codes. Test drive. All OK.	
			side	

2021-06-09 - Mileage: 1037242 - Order nr: 2221272

		SHIFT	DAY - 09/10.06.2021.	
		258	ONGOING NOX SENSOR FAULTS - RECTIFY	
		VO-2141300	Valves and unit injectors, adjust	3.5
		VO-5612600	Air drier, drier insert, replace	1
		VO-2582200	Filter, AdBlue, replace	0.75
		OTH-5813WE	WHITE CABLE	5
		OTH-5813RD	RED CABLE	5
		VO-6781769	SPLICE-RED(22-18)	6
		MK-NARV57424BL	4 WAY DEUTSCH CON.	1
		VO-990051	HOUSING	1
		VO-20734499	ANTI-TAMPER SEALIN	4
		VO-984524	CABLE TERMINAL	4
		OTH-F	FREIGHT	2
		OTH-5813OR	CABLE 3MM ORANGE	5
		OTH-5813PU	CABLE 3MM PURPLE	5
		OTH-56710	CONV TUBE 10mm PER METER	5

PC	Type	Code	Description (Original)	#
Ⓡ	Ⓜ	VO-990060	CABLE TERMINAL	4
Ⓡ	Ⓜ	VO-20734499	ANTI-TAMPER SEALIN	16
Ⓡ	Ⓜ	VO-984524	CABLE TERMINAL	4
Ⓡ	Ⓜ	VO-984977	CABLE TERMINAL	4
Ⓡ	Ⓜ	OTH-EC5102619	LOOMING TAPE	1
Ⓡ	Ⓜ	OTH-9115	INSULATING TAPE	1
Ⓡ	Ⓜ	OTH-DT2-2	2 CIRC DEUTSCH PLUG	1
Ⓡ	Ⓜ	VO-990051	HOUSING	1
Ⓡ	Ⓜ	VO-20734499	ANTI-TAMPER SEALIN	4
Ⓡ	Ⓜ	VO-984524	CABLE TERMINAL	4
Ⓡ	Ⓜ	VO-23690622	APM DRYER FILTER KIT	1
Ⓡ	Ⓜ	VO-23381562	ADBLUE FILTER	1
Ⓡ	Ⓜ	VO-21954674	STRAINER	1
	Ⓜ		Carried out top set adjustment as per specifications.	
	Ⓜ		Replace the air drier filter with new. Connect laptop and	
	Ⓜ		reset/calibrate as required.	
	Ⓜ		Replace the main adblue filter and pump strainer with new.	
	Ⓜ		- WIRING FAULT, DROPPING POWER FEED TO SENSOR.	
	Ⓜ		NOTE: NO LABOUR CHARGE FOR NOX SENSOR WIRING REPAIRS	
	Ⓜ		AS GESTURE OF GOODWILL (REFER SERVICE MANAGER - RG).	
	Ⓜ		Connect laptop and read fault codes - NOX fault, no	
	Ⓜ		communication. Test power and earth to sensor - OK. Test	
	Ⓜ		datalinks to sensor - OK. Strip open exhaust loom and	
	Ⓜ		found chaffed wiring but not down to copper. Check XC302	
	Ⓜ		exhaust plug - OK. Cut open back side of plug - OK. Remove	
	Ⓜ		covers from CCIOM and ACM. Inspect plugs and wiring -	
	Ⓜ		found a small amount of water in plug. Clean out. Strip off	
	Ⓜ		conduit near CCIOM and ACM. Inspect wiring - OK. Customer	

PC	Type	Code	Description (Original)	#
			required vehicle. Refit conduit, tape up loom and fit all	
			plugs. Clear fault codes. Road test - OK. Park out.	
			Vehicle returned to w/shop. Re-wire the NOX sensor; power,	
			earth and datalinks. Test - all OK, no faults occurred.	

W 2021-05-25 - Mileage: 1033861 - Order nr: 2221115

		SHIFT	EVENING - 25/05/2021.	
		VO-2583700	NOX sensor, replace	0.3
		VO-22827995	SENSOR	1
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
			Connect-disconnect of diagnostic tool included	
		VO-2840700	Sensor values, check	0.2
		VO-2500600	Inlet and exhaust systems, check	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-2584600	SCR system, test	0.5

2021-05-18 - Mileage: 1030493 - Order nr: 2220952

		SHIFT	EVENING - 18.05.2021.	
		LO-258	ENGINE DERATED - CHECK AND REPORT	3
			- SUSPECT ADBLUE TANK EMPTY.	
			No active faults on the dash. Connect laptop and inspect	
			fault codes - only 1x code of concern with correct time	
			stamp is for empty adblue tank. Tank has been filled to	
			max level. Program EMS with latest software. Clear fault	
			codes. Road test up hill - no derate or faults present.	

W 2021-04-26 - Mileage: 1015202 - Order nr: 2220440

		SHIFT	PUBLIC HOLIDAY - 26.04.2021.	
		VO-2583700	NOX sensor, replace	0.3
		VO-22827995	SENSOR	1
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5

PC	Type	Code	Description (Original)	#
	🔧		Connect-disconnect of diagnostic tool included	
🔌	🔧	VO-3710200	Electric wires and connections, check	0.4
🔌	🔧	VO-3717300	Data links, fault tracing with oscillosc	0.5
	🔧		NEW UNIT SN: A2C9378290003.	
🔍 2021-04-14 - Mileage: 1012344 - Order nr: 2219989				
🔧	🔧	LO-773	WHEEL BEARINGS - REPLACE (ALL)	24
	🔧		- 3x AXLES.	
🔧	🔧	VO-20967831	BEARING	2
🔧	🔧	VO-21671923	LOCK NUT	2
🔧	🔧	VO-21036050	BEARING	4
🔧	🔧	VO-3199066	REAR 1/2 SHAFT SEAL	1
🔧	🔧	VO-22537018	SENSOR WHEEL	4
🔧	🔧	VO-3092340	SEALANT (GREY)	1
🔧	🔧	VO-21912834	KIT	4
🔧	🔧	VO-22371700	SIX POINT SOCKET	4
🔧	🔧	VO-982108	O-RING	4
🔧	✳️	SHIFT	DAY - 14/15/16/17.04.2021.	
🔧	🔧	VO-3092277	BOLT	6
🔧	🔧	VO-23637090	WHEEL SPEED SENSOR	1
🔧	🔧	OTH-ABS PROTECTOR	ABS PROTECTOR	4
🔧	🔧	VO-23740261	SENSOR	1
	🔧		- AS PER CUSTOMER REQUEST.	
	🔧		Remove all wheels, boosters, callipers and hubs for	
	🔧		access. Replace front wheel bearings with new. Reassemble	
	🔧		in reverse and torque to specs. Replace rear wheel	
	🔧		bearings with new. Replace 4x pole wheel sensors with new	
	🔧		including fitment of protection guards. Reassemble in	
	🔧		reverse order and torque to specs. Lower vehicle. All OK.	

PC	Type	Code	Description (Original)	#
	*	593	LH REAR MOST ABS SENSOR - REPLACE	
			- FOUND TO BE BROKEN.	
	*	593	RH 1ST DR LINING WEAR SENSOR - REPLACE	
			- FOUND TO BE BROKEN.	
		AU2-CAL85121715	85W140 205L PUMPOU	4
	*	91	CONSUMABLES	

2021-03-22 - Mileage: 999030 - Order nr: 2219422

	*	SHIFT	DAY - 22.03.2021.	
		LO-395	RADIO DISPLAY UNIT - REPLACE	1.5
		VO-22148423	DISPLAY	1
		OTH-F	FREIGHT	2
			NEW UNIT SN: 21055-286.	
			Replace the display unit with new and program.	
			Test operations - all OK.	
	*	91	CONSUMABLES	

2021-03-15 - Mileage: 995665 - Order nr: 2219281

	*	SHIFT	DAY - 15.03.2021.	
		LO-350	LH HIGH BEAM GLOBE - REPLACE	1
			- CUSTOMER REPORTS IT KEEPS BLOWING	
		LO-430	AIR LEAKS - CHECK & REPORT	0.5
		VO-943904	GLOBE H1 24V70W	1
		VO-20544196	ELBOW NIPPLE	1
		VO-991092	NIPPLE	1
			FUSE AND GLOBE.	
			Replace the globe with new. Check terminal tightness on	
			pins - OK. Check holder to ensure no vibration - OK.	
			- CUSTOMER REPORTS LEAK FROM REAR	
			AIR BAG.	

PC	Type	Code	Description (Original)	#
	🔧		Check the rear suspension for leaks - none found. Notice	
	🔧		air leaking from gearbox air fitting. Replace fitting with	
	🔧		new. Build up air and check over - no further leaks found.	

🔍 **2021-03-09 - Mileage: 992303 - Order nr: 2219189**

🟢	*	SHIFT	EVENING - 09.03.2021.	
🟢	🕒	VO-1774400	Basic service. Chassis lubrication and o	3.5
🟢	*	94	WASTE DISPOSAL	
🟢	*	310	RADIO SCREEN DISPLAY NOT WORKING	
🟢	🔧	VO-85136742	FILTER KIT (18B)	1
🟢	🔧	VO-23260134	APM DRYER FILTER KIT	1
🟢	🕒	LO-561	DEFECT: AIR DRIER FILTER - REPLACE	1
	🔧		- FOUND TO BE DIRTY ON SERVICE.	
	🔧		*ORDERED ON NEW R/O 2219281	
🟢	🔧	AU2-CAL85121795	VDS4 BULK	41
	🔧		Carried out basic service as per specifications.	
	🔧		Inspect and confirm fault. Order new radio for fitment.	
	🔧		R&R the air drier filter with new. Connect laptop and	
	🔧		reset/calibrate as required.	
🟢	*	91	CONSUMABLES	

🔍 **2021-02-09 - Mileage: 975373 - Order nr: 2218520**

🟢	*	SHIFT	EVENING - 09.02.2021.	
🟢	🕒	LO-350	RH INDICATOR MALFUNCTION ON DASH	1
	🔧		- FAULTY LAMP ASSY.	
🟢	🔧	VO-23354973	TAIL LAMP CLUSTER	1
	🔧		Replace the RH side rear tail lamp assy with new. All OK.	

🔍 **2021-01-18 - Mileage: 965305 - Order nr: 2217996**

🟢	*	SHIFT	DAY	
🟢	🕒	LO-310	CUSTOMER ADVISE TRUCK HAS ALTERNATOR	1

PC	Type	Code	Description (Original)	#
	🔧		WIRING FAULT, AND ISOLATOR FAULT	
	🔧		Load Ute. Travel to site. Inspect. Found truck already	
	🔧		apart. Discussed work with Auto sparky. Checked how	
	🔧		truck is fitted up. Traced wiring back to cab. Tested	
	🔧		relay in cab. All OK. Reassembled and tested. All OK.	
	🔧		Suspect Auto Sparky had repaired wiring for isolator field	
	🔧		isolation. Pack up and travel back to workshop.	

2021-01-11 - Mileage: 965249 - Order nr: 2217814

🟢	🟡	LO-257	OIL LEAK AROUND THE TURBOCHARGER	1
🟢	🟡	LO-263	FAN BELT, SHREDDED - CHECK AND REPORT	0.5
🟢	🔧	AU2-CAL85121795	VDS4 BULK	3
🟢	🔧	VO-22822667	FAN SHROUD	1
🟢	🟡	LO-263	FAN SHROUD - REPLACE	4
🟢	🔧	VO-980881	CABLE TIE	6
	🔧		- CHECK AND REPORT.	
	🔧		Inspect and found oil stainage against the side cover, oil	
	🔧		leak looks to be coming from CCV pipe on the turbo inlet	
	🔧		pipe elbow, found to be over full with oil. Correct oil to	
	🔧		spec. Wash down around the area. Road test - no leaks.	
	🔧		Drain coolant. Remove pipework around the shroud. Replace	
	🔧		the shroud with new. Reassemble in reverse and fill coolant.	
	🔧		Tilt the cab. Check belts, OK. Fan shroud that screws to	
	🔧		the radiator has cracked on the fan ring edge and has	
	🔧		plastic hanging down near the fan blades. Quote new shroud.	
🟢	✳️	91	CONSUMABLES	

2020-12-29 - Mileage: 959123 - Order nr: 2217410

🟢	🔧	VO-990950	M8 FLANGE LOCK NUT	4
🟢	🔧	VO-3979639	PRE HEAT GSK	2

PC	Type	Code	Description (Original)	#
		OTH-F	FREIGHT	10
		LO-263	ENGINE FAN - REPLACE	4
			PART 85003294 X1 EX GERALDTON PART ORDERED SATURDAY DELIVERY DUE	
			SATURDAY OR MONDAY.	
		VO-85003294	EXCH THERMO FAN	1
		SHIFT	DAY	
		LO-870	Customer informed Air con keeps	1.5
			freezing up - Investigate and report with P&A	
			NEW SERIALÄ 14072020 00848	
		VO-23515329	VENTILATION FILTER	1
		VO-23515346	VENTILATION FILTER	1
			Drained coolant. Disassembled front of engine. Removed	
			thermostat and compressor pipe for access. Removed and	
			replaced fan. Secure with new nuts to spec. Reassembled	
			and secure all removed parts. Fill coolant. Tested.	
			All OK.	
			Connected test equipment. Reclaim gas and check qty. All	
			OK. Inspected filters. Found dirty/blocked. Removed and	
			replaced both filters. Vac and gas system to 0.65kg. Re	
			tested. AI OK.	
		91	CONSUMABLES	

2020-12-18 - Mileage: 956370 - Order nr: 2217315

		LO-210	DIAGNOSE ENGINE LIGHT / ACTIVE FAULTS	1.5
			- ENGINE FAN SHORTED TO HIGH/CONSTANTLY LOCKED IN.	
			- CUSTOMER TO REBOOK FOR FAN REPLACEMENT DUE TO NIL PARTS	
			IN STOCK.	
			Connect laptop and read fault codes, engine fan speed code	
			occurring. Carry out GD; run engine fan test, found fan	

PC	Type	Code	Description (Original)	#
	🔍		constantly engaged. Check wiring and connections to the	
	🔍		fan - no fault. Fan internally shorted. Quote replacement.	
🔍 2020-12-16 - Mileage: 953687 - Order nr: 7721204				
🟢	*	DETAILS	DETAILS	
	🔍		CONTACT PERSON: AUTHORITY : 0478 641 541	
🟢	🟡	LO-252	TRUCK IS DERATING	3.5
	🔍		PO52612 U029D00 P2BAE96	
	🔍		Pull truck into workshop	
	🔍		DRIVER : LOUIE	
	🔍		VEH KM: 954731kms	
	🔍		ENG HRS:13577hrs	
	🔍		FUEL BURN:727737ltrs	
	🔍		Connect Lap top	
	🔍		Check codes	
	🔍		All codes inactive	
	🔍		Truck will be derating due to no codes	
	🔍		Inspect wiring around DR shields	
	🔍		All ok	
	🔍		Check faults	
	🔍		All good	
	🔍		Trace back wiring	
	🔍		Test voltage at five sesnor ok 240 ok	
	🔍		Missing 2.5V can supply	
	🔍		Wiring Issue between sensor and ECU	
	🔍		Informed customer	
	🔍		They want to take the truck and fix in Perth	
	🔍		Cleaned codes	
	🔍		Put cab down and parked truck out	

PC	Type	Code	Description (Original)	#
	🔧		No further action taken	
🟢	*	91	CONSUMABLES	
🔍 2020-12-11 - Mileage: 952970 - Order nr: 2217152				
🟢	🔧	LO-284	ENGINE WARNING LIGHT ON THE DASH	1
🟢	🔧	LO-870	DIAGNOSE A/C BLOWING WARM AIR	1
	🔧		- NO FAULT FOUND, POSSIBLE COMPRESSOR.	
🟢	🔧	VO-22827995	SENSOR	1
🟢	🔧	LO-284	NOX SENSOR - REPLACE	2
	🔧		- CHECK AND REPORT.	
	🔧		Connect laptop and read fault codes, NOX sensor fault	
	🔧		present. Check and test wiring, all OK. Faulty sensor.	
	🔧		- ADDITIONAL TIME TAKE TO REMOVE DG COVERS.	
	🔧		Remove the muffler cover for access. Replace the NOX sensor	
	🔧		with new. Refit the muffler cover. Clear fault codes, OK.	
	🔧		Connect up gauge set and test the A/C, vent temp at 8 deg	
	🔧		C. All operating correctly. Suspect intermittant fault with	
	🔧		the compressor. Customer to monitor issue and report back.	
🟢	*	91	CONSUMABLES	
🔍 2020-11-06 - Mileage: 935798 - Order nr: 2216359				
🟢	*	210	ENGINE TICKING - CHECK AND REPORT	
🟢	🔧	VO-85022268	EXH CYL HEAD 16L	1
🟢	🔧	VO-1161963	RUBBER GREASE	1
🟢	🔧	VO-1547252	SEALING RING	1
🟢	🔧	VO-1677370	VEB SEAL	2
🟢	🔧	VO-20526428	VEB SEAL	2
🟢	🔧	VO-20563945	INTAKE MANIFOLD SEAL	1
🟢	🔧	VO-20736230	D16C R/C GKT	1
🟢	🔧	VO-20784537	GASKET	1

PC	Type	Code	Description (Original)	#
R	■	VO-20799996	SEALING RING	1
R	■	VO-20815558	SEALING STRIP	1
R	■	VO-20852765	GASKET	4
R	■	VO-21006103	BEARING SHELL KIT	6
R	■	VO-21006109	BEARING SHELL KIT	1
R	■	VO-21015266	SCREW	6
R	■	VO-21185132	SEALING	2
R	■	VO-21344774	FLANGE SCREW	6
R	■	VO-21352841	GASKET	6
R	■	VO-21420336	CONNECTING PIPE	1
R	■	VO-21423788	SEALING RING	1
R	■	VO-21503575	SEALING RING	1
R	■	VO-21575727	HEAD GASKET	1
R	■	VO-21801388	YOKE	6
R	■	VO-21940615	SEALING RING	1
R	■	VO-22206133	GASKET	1
R	■	VO-23385975	VALVE CALIPER	6
R	■	VO-276948	D12 INJ/SEAL KIT	6
R	■	VO-3092340	SEALANT (GREY)	1
R	■	VO-3979639	PRE HEAT GSK	2
R	■	VO-420643	TURBO DRAIN GASKET	1
R	■	VO-469601	TURBO DRAIN SEAL	1
R	■	VO-470993	TRBO RETURN GSK	1
R	■	VO-8131154	SEALING RING	1
R	■	VO-8148729	CONNECTOR	1
R	■	VO-8192804	SCREW	8
R	■	VO-85103205	GREEN PAINT	1
R	■	VO-944126	O-RING INJ HARNESS	1

PC	Type	Code	Description (Original)	#
		VO-983472	D12 LOOM TIE	8
		VO-993811	FLANGE SCREW	4
		VO-994447	FLANGE SCREW	6
		LO-211	CYLINDER HEAD - REPLACE	22
		94	WASTE DISPOSAL	
		91	CONSUMABLES	
		251	EXHAUST MANIFOLD, CENTRE - REPLACE	
		VO-23639642	EXHAUST MANIFOLD	1
		VO-21695684	SEALING RING	2
		VO-20938964	SEAL	1
		VO-467310	EXHAUST CLAMP	1
		VO-990950	M8 FLANGE LOCK NUT	1
		VO-994441	M8*50 FLANGE SCREW	1
			- FOUND TO BE CRACKED.	
			- NO ADDITIONAL LABOUR CHARGE.	
			- NO. 5 EXHAUST VALVE STEM SEAL RIPPED.	
			Drain coolant. Remove the rocker cover, rocker shaft and	
			injectors. Remove the cylinder head. Clean the block	
			surface. Swap required parts from old to new head. Fit new	
			head with new gasket. Reassemble in reverse order. Carry	
			out top set adjustment. Fill coolant. Start and run the	
			engine. Road test and carry out final check over.	
			Replace the centre manifold section with new.	
			NEW UNIT SN:	
2020-08-26 - Mileage: 896554 - Order nr: 2214596				
		LO-870	AIR CON FAN INOPERABLE	0.55
			- CHECK AND REPORT.	
		VO-84223451	FAN MOTOR	1

PC	Type	Code	Description (Original)	#
		LO-873	AIR CON FAN MOTOR - REPLACE	3
			- INTERNAL SHORT.	
			Test the air con fan - confirm fault. Remove dash panels.	
			Test power to the fan - OK. Internal fault in the fan motor.	
			Replace the fan motor with new. Reassemble in reverse.	
			Test operation - all OK.	
		91	CONSUMABLES	
2020-06-15 - Mileage: 868867 - Order nr: 7720032				
		DETAILS	DETAILS	
			CONTACT PERSON: JOHN 0400 511 807	
		LO-430	NOT SELECTING GEARS	15
			CUSTOMER REPORTS CRUNCHING NOISE, METAL IN OIL	
		LO-560	COOLANT LINES, REPLACE	2.5
			CUSTOMER REQUEST	
		LO-311	BATTERY AND MOUNTING PARTS - BATTERY	1
		LO-218	REPLACE REAR ENGINE MOUNTS	5
		VO-1075753	CLAMP, COMPRESSOR INLET PIPE	1
		VO-984733	FLANGE SCREW	1
		VO-85002016	EXCH GEARBOX, ATO3112D	1
		VO-1652986	SPIGOT BEARING	1
		VO-85108352	CRANKSHAFT SEAL	1
			*** POSSIBLE POLICY CLAIM ***	
		VO-21339891	RUBBER HOSE	2
		VO-21052612	CONNECTOR	1
		VO-21380391	CONNECTOR	1
		VO-20915849	HOSE CLAMP	4
		VO-20940702	CONNECTOR	1
		VO-20938685	CONNECTOR	1

PC	Type	Code	Description (Original)	#
®	☒	VO-21416525	RUBBER CUSHION	2
®	☒	VO-995906	HEXAGON SCREW	8
®	☒	VO-25339078	HEXAGON NUT	8
®	☒	VO-23701845	OIL HOSE	1
®	☒	VO-23701846	OIL HOSE	1
®	☒	VO-11998	COPPER WASHER	2
®	☒	VO-967343	ORING OIL COOLR	2
®	☒	VO-992347	FLANGE SCREW	2
®	☒	VO-984672	V-NIPPLE	2
®	☒	AU2-CAL85131754L	VOLVO SYNTHETIC GEARBOX OIL	17
®	☒	OTH-CAL85108914L	VCS COOLANT PER LITRE	4
®	☒	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
	☒		Drained coolant.	
	☒		Removed air intake/filter housing for access.	
	☒		Replaced missing compressor inlet pipe clamop.	
	☒		Removed and replaced rear engine mounts.	
	☒		Replaced 2 bolts and nuts with new.	
	☒		Torque to spec.	
	☒		Checked - All ok.	
	☒		Removed and replaced transmission coolant hoses and	
	☒		Jump start truck.	
	☒		Washed off batteries free of dirt and corrosion.	
	☒		Topped up battery cells.	
	☒		Refit covers and tested batteries.	
	☒		Checked - All ok.	
	☒		VEH KM: 868867	
	☒		ENG HRS: 12323	
	☒		FUEL BURN: 661487	

PC	Type	Code	Description (Original)	#
	🔧		Removed driveshaft and disconnected air/coolant lines.	
	🔧		Lifted truck.	
	🔧		Lifted gearbox out of place.	
	🔧		Removed rear main seal, cleaned and inspected surfaces.	
	🔧		Installed rear main seal.	
	🔧		Cleaned and inspected clutch and installed clutch.	
	🔧		Swap over transmission cooler and new oil hoses and	
	🔧		fittings.	
	🔧		Swap oil filter upper housing.	
	🔧		Installed gearbox and filled with oil.	
	🔧		Fit propshaft with new nuts and bolts and torqued to specs.	
	🔧		Fit new coolant hoses.	
	🔧		Fit wiring harness and chassis cover.	
	🔧		Conencted tech tool and programmed transmission.	
	🔧		Attempted to calibrate - Failed.	
	🔧		Unplugged transmission and plug in comms unit and	
	🔧		calibrate.	
	🔧		Carried out Gear, clutch and engagement calibration.	
	🔧		Fill cooling system.	
	🔧		Washed off and road tested.	
	🔧		Checked - All ok.	
	🔧		fittings with rubber hose.	
	🔧		Secured into position in chassis.	
	🔧		Pressure tested and Checked - All ok.	
🟢	*	91	CONSUMABLES	

🔍 **2020-06-10 - Mileage: 867215 - Order nr: 2212673**

🟢	🔧	LO-255	DIAGNOSE REPORTED LOSS OF POWER	2
🟢	🔧	VO-1674223	T BOLT CLAMP	1

PC	Type	Code	Description (Original)	#
Ⓡ	🔧	LO-255	TURBOCHARGER - REPLACE	5
Ⓡ	🔧	VO-85000622	EXCH TURBO	1
Ⓡ	🔧	VO-20573472	SPACER SLEEVE	4
Ⓡ	🔧	VO-20784537	GASKET	1
Ⓡ	🔧	VO-21940615	SEALING RING	1
Ⓡ	🔧	VO-22206133	GASKET	1
Ⓡ	🔧	VO-420643	TURBO DRAIN GASKET	1
Ⓡ	🔧	VO-469601	TURBO DRAIN SEAL	1
Ⓡ	🔧	VO-8148729	CONNECTOR	1
Ⓡ	🔧	VO-993811	FLANGE SCREW	4
Ⓡ	🔧	VO-2141300	Valves and unit injectors, adjust	4
Ⓡ	🔧	LO-260	DEFECT: COOLANT PIPE BRACKET BROKEN	0.5
	🔧		- REPAIR AS REQUIRED.	
Ⓡ	🔧	VO-1547252	SEALING RING	1
Ⓡ	🔧	MK-HS004	HOSECLAMP 6/16	2
Ⓡ	🔧	MK-160AX568F	SILICON HOSE	1
	🔧		NEW UNIT SN: H191133157.	
	🔧		Carried out top set adjustment as per specifications.	
	🔧		Remove the pipe. Clean up and re-weld the bracket. Prime	
	🔧		and paint. Refit the pipe with new o'rings. All OK.	
	🔧		Jack over the cab. Remove intake pipe, oil pipes, exhaust	
	🔧		Connect laptop and read fault codes, inactive code for low	
	🔧		boost. Tilt the cab. Remove intake pipe from the turbo.	
	🔧		Pressure test the boost system, no leaks. Remove exhaust	
	🔧		side from the turbo. Check wastegate, OK. Reassemble. Road	
	🔧		test and monitor sensor values, only getting 130 KPA of	
	🔧		boost. Engine making a loud ticking noise also. Tilt the	
	🔧		cab. Remove rocker cover and inspect cam shaft and rocker	

PC	Type	Code	Description (Original)	#
	🔧		gear, OK. Recommend top set adjustment be carried out.	
	🔧		- PREVENTATIVE MAINTENANCE.	
	🔧		flex, back pressure sensor pipe, turbo and manifold assy.	
	🔧		Strip apart and clean the mating surfaces. Install new	
	🔧		turbo and reassemble to the truck with the manifold.	
	🔧		Torque to spec. Reassemble. Replace rubber turbo actuator	
	🔧		hose and clamps with new. Clear fault codes. Road test	
	🔧		after all repairs and monitor, truck getting full boost.	
🟢	*	91	CONSUMABLES	
🔍 2020-04-16 - Mileage: 840884 - Order nr: 2211304				
🟢	🟡	LO-870	AIR CON FAULT - INSPECT & REPORT	0.75
🟢	🟡	LO-810	PROGRAM SPARE KEYS TO TRUCK	0.17
	🔧		- CUSTOMER SUPPLIED KEYS.	
🟢	🔧	VO-85003041	EXCH COMPRESSOR	1
🟢	🔧	VO-20443759	O-RING	1
🟢	🔧	VO-20708247	O-RING	1
🟢	🔧	VO-82693739	ACCUMULATOR	1
🟢	🟡	LO-874	AIR CON COMPRESSOR - REPLACE	3
🟢	*	97	AIR COND. GAS - 0.65 KGS	
🟢	🔧	VO-984734	M8*20 FL BOLT	2
	🔧		2x spare keys supplied. Spare keys are different cut to	
	🔧		main key. Unable to unlock door with them but can be	
	🔧		programmed to start. Informed customer.	
	🔧		Run the A/C, not cooling. Connect gauges, good pressure but	
	🔧		compressor not engaging. Tilt the cab. Check for power at	
	🔧		the compressor, OK. Remove the belt, compressor seized.	
	🔧		Degas the system. Remove guard under the chassis rail for	
	🔧		access. Remove pipes and bolts. R&R the compressor with	

PC	Type	Code	Description (Original)	#
	📄		new. Reassemble in reverse order. R&R the accumulator with	
	📄		new. Vac the system for 30 MINS and charge with 0.65 KGS	
	📄		gas. Run the air con, cold and cycling correctly. All OK.	
🟢	*	91	CONSUMABLES	

🔍 **2020-03-25 - Mileage: 825722 - Order nr: 2210897**

🟢	*	MARSUE	M KEWDALE SHIFT	
🟢	🕒	LO-3000	SET SPEED WHEN USING CRUSIE TO 100KM	1
🟢	🕒	LO-170	TURN SERVICE REMINDER OFF	0.3
	📄		Set speed. Connect laptop and set speed cruise to 100	
	📄		km/ph. Road test to confirm correct speed was set. All ok.	
	📄		Connect laptop and set service internals to 100,000 klm as	
	📄		per customer request.	

🔍 **2020-03-20 - Mileage: 822874 - Order nr: 2210680**

🟢	🕒	LO-383	CHANGE SPEED LIMIT FROM 90KM TO 100KM	1
🟢	🕒	VO-5611100	Compressor, replace	2
🟢	🕒	VO-5611600	Air drier, replace	1.5
🟢	🕒	VO-5611700	Air drier, overhaul. Removed	1.5
🟢	🕒	VO-5610000	Compressor, regulator, anti-freeze unit.	1
🟢	📦	VO-85013941	EXCH COMPRESSOR	1
🟢	📦	VO-992065	O-RING	1
🟢	📦	VO-471708	SEALING RING	1
🟢	📦	AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
🟢	📦	VO-21339891	HOSE,COOLANT	1
🟢	📦	VO-977639	12*12 VIPS	2
🟢	🕒	VO-2170600	Oil sump, remove	1.5
🟢	🕒	VO-2160300	Main bearings, replace (all). Oil sump r	3
🟢	🕒	VO-2161100	Connecting rod bearings, replace (all).	3
🟢	🕒	VO-2170800	Oil sump, install	1.5

PC	Type	Code	Description (Original)	#
R	W	VO-1751200	Oil and filter, engine, change (on floor)	1
R	R	VO-20578851	D16C2 MAIN BRG SHELL	6
R	R	VO-20578853	D16C2 MAIN BRG SHELL	1
R	R	VO-20586602	BIG-END BEARING KI	6
R	R	VO-21948268	THRUST WASHER KIT	1
R	R	VO-20734156	SEALING STRIP	1
R	R	VO-21780376	SEALING RING	1
R	R	VO-944126	O-RING INJ HARNESS	1
R	R	VO-984816	M12*40 FL BOLT	13
R	R	VO-21780376	SEALING RING	2
R	R	VO-1543578	F16 SEAL (OIL P	2
R	*	93	ENGINE OIL & GREASE	
	W		- CUSTOMER REQUEST.	
R	R	VO-85136742	FILTER KIT (18B)	1
	W		- PREVENTATIVE MAINTENANCE.	
	W		- PLEASE REPLACE FUEL FILTERS AS	
	W		WELL AS PER CUSTOMER REQUEST.	
R	W	LO-350	INTERIOR LIGHT FITTING - INSTALL NEW	0.5
R	R	VO-23397898	WIRES	1
R	R	VO-84810916	INTERIOR LAMP	1
	W		SERIALÄ 2518512899 / 412704027	
R	R	VO-23260134	APM DRYER FILTER KIT	1
	W		- CUSTOMER REQUEST.	
	W		- MISSING.	
	W		MANAGER SPECIAL	
	W		Connect laptop and change road speed limit parameter from	
	W		90 KLM/HR to 100 KLM/HR. Road test and monitor, all OK.	
	W		Fit up new light as required. Test operation, all OK.	

PC	Type	Code	Description (Original)	#
			NOTE: new light superseded from original.	
			Drain coolant. Tilt the cab. Remove discharge pipe, oil	
			lines, intake and compressor. Swap over fittings and drive	
			gear to new compressor, fit and torque to spec. Reassemble	
			in reverse order. Remove the air drier. Replace drier	
			filter and plastic inserts. Refit the air drier. Build up	
			air and check over, all OK. Refill coolant. Connect laptop	
			and reset air usage.	
			Drain engine ol. Remove the sump and stiffening plate.	
			Carry out bottom end bearing roll. Reassemble in reverse	
			order. Replace oil and fuel filters as requested. Fill	
			with new engine oil. Wash down. Road test. All OK.	
			SPECIAL	
		91	CONSUMABLES	
2019-11-05 - Mileage: 1 - Order nr: 8800507				
			GLOBETROTTER SIGN & PANEL	
		810	SUPPLY GLOBETROTTER SIGN & PANEL	
		VO-84162956	TRIM PANEL	1
		VO-82367858	DECAL	1
2019-04-30 - Mileage: 822539 - Order nr: 2202688				
			S0589 TGW2 (NOT COMMUNICATING), SW. FH/FM (4)?/ FL/FE (3)	
		VO-3982500	TGW2, SW update (incl. refresh). Campaig	0.8
			Campaign only	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-3979200	Telematic gateway, replace	0.5
		VO-3982500	TGW2, SW update (incl. refresh). Campaig	0.8
			Campaign only	
		VO-22555751	TELEMATICS CONTROL	1

PC	Type	Code	Description (Original)	#
			ser 923093582680649	
 2018-07-10 - Mileage: 0 - Order nr: 2195636				
		CARD	NOT REQUIRED	
 2018-06-18 - Mileage: 822490 - Order nr: 2195053				
		LO-177P1US	USED TRUCK SALES SERVICE/INSPECTION	5
		LO-257	OIL SEPARATOR, LEAKING - REPLACE	1.5
		LO-645	POWER STEERING PUMP, LEAKING - REPLACE	3.5
		LO-726	AIR BAGS, LEAKING - REPLACE	7
		LO-251	MUFFLER/SHROUD VIBRATES - CHECK & REPORT	2
		LO-410	CLUTCH & CLUTCH CYLINDER - REPLACE	14
		VO-21488833	STEERING PUMP	1
		VO-977030	O-RING	1
		VO-25559715	SEALING RING	2
		VO-20852764	GASKET	4
		VO-20852765	GASKET	4
		VO-85122800	1L DEXRON3 ATF	2
		VO-21392404	FILTER	1
		VO-20532891	CCV GASKET	1
		VO-21122541	OIL SEPARATOR	1
		VO-22058737	AIR SPRING	4
		VO-22058741	AIR SPRING, SMALL, STD LIFT	4
		OTH-F	FREIGHT	8
		UNK-P68711	93210044 RIVET	1
		VO-21648793	CLUTCH	1
		VO-23020379	DISC	1
		VO-1652986	SPIGOT BEARING	1
		VO-85013166	EXCH CYLINDER	1
		VO-20992763	AIR HOSE	1

PC	Type	Code	Description (Original)	#
		VO-20483426	SEALING RING	1
		VO-20497205	GASKET	1
		VO-3192614	PISTON SEAL	2
		VO-983472	D12 LOOM TIE	2
		VO-20860677	SEALING RING	1
		OTH-F	FREIGHT	4
		VO-85108352	CRANKSHAFT SEAL	1
		VO-993240	HOSE CLAMP	1
		VO-20593252	PLUG FLYWHEEL HOUSING	1
		VO-961968	PROTECTING PLUG	1
			NEW UNIT SN: 7684955626.	
			NEW UNIT SN: 666482000262.	
			Carried out mechanical inspection and service as required.	
		LO-430	CLUTCH FAULTS - CHECK & REPORT	1
			- INC RESEAL THE FRONT OF THE TRANSMISSION	
			Drain coolant. Strip all components for access. Remove the	
			gearbox and clutch. R&R the nose cone seal and axle brake	
			piston seals. R&R the clutch cylinder and PWM air hose.	
			Remove the flywheel. R&R the rear main seal. R&R the spigot	
			bearing. Refit the flywheel. Install new clutch. Refit the	
			gearbox. Reassemble in reverse. Calibrate as required.	
			Remove pipes. Swap fuel pump and gear from old to new power	
			steering pump, torque to specs. Install new power steering	
			pump and plumb up. R&R P/S filter with new. Top up ATF and	
			bleed the system. Run and check over - no further leaks.	
			Connect laptop and read fault codes. Carry out GD over the	
			clutch system - all OK. Road test - no faults occurred.	
			Return to workshop. Gearbox to come out for further diag.	

PC	Type	Code	Description (Original)	#
	🔧		Drill out rivets holding top hat on muffler. Remove top	
	🔧		shroud assy and inspect muffler - OK. Shroud is vibrating/	
	🔧		noisy as engine is running rough. Carry out compression	
	🔧		test and cylinder balancing test - no change. Reassemble	
	🔧		with new rivets. Further diag into vibration issue required.	
	🔧		R&R 8x air bags as required. Test operation - all OK.	
	🔧		R&R the oil seperator and gasket with new. Wash down.	
🔍 2018-05-08 - Mileage: 0 - Order nr: 2193813				
🟢	*	CARD	NOT REQUIRED	
🔍 2018-05-01 - Mileage: 818746 - Order nr: 2193691				
🟢	🕒	VO-3668400	LKS (Lane Keeping System), calibration	2
	🔧		Performed LKS calibration on newly fitted w/screen as req.	
🔍 2018-04-30 - Mileage: 818746 - Order nr: 2193668				
🟢	🕒	LO-370	WATER IN PLUG WITH NO SEAL/VOLT DROP	3
🟢	🔧	MK-NARV57424BL	4 WAY DEUTSCH CON.	1
🟢	*	80	DROPPED TRUCK BACK TO LINFOX YARD	
	🔧		SUBLET COSTS.	
	🔧		Connect laptop and read fault codes - U029D00. Run SCR	
	🔧		pump pressure test - OK. Run dosage test - OK. Check ad-	
	🔧		blue quality - OK. Check NOX sensor datalinks to ground -	
	🔧		2.3 v and 2.6 v. Check voltage at NOX sensor - 7 v, should	
	🔧		be 25 v. Inspect wiring at plug by muffler - no seal and	
	🔧		corrosion evident in plug. R&R plug and repair wiring.	
	🔧		Secure the harness. Clear fault codes.	
	🔧		Note: NOX sensor wiring has extension harness fitted as	
	🔧		exhaust shroud, Non-Gen. This harness has the corroded	
	🔧		wiring.	
🟢	*	91	CONSUMABLES	

PC	Type	Code	Description (Original)	#
2018-04-02 - Mileage: 815927 - Order nr: 200793				
		96000		0
2018-03-26 - Mileage: 795529 - Order nr: 2192727				
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	1
			For Volvo vehicles under Service Agreement	
		3310	STARTER MOTOR SOLENOID SCREWS - CHECK	
		VO-4658400	Differential carrier oil sample, take (o	0.2
		VO-1774600	Annual service	2.4
			oil changes included only in some models.	
		VO-1707300	Service alert system, configuration and	0.4
		VO-2582200	Filter, AdBlue, replace	0.2
		VO-2341400	Filter for fuel tank ventilation, replac	0.1
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2335400	Fuel and water separator filter, replace	0.6
		VO-7714500	Wheel nuts, check tightening (all)	0.3
		VO-6452500	Oil filter, power steering, replace	0.1
		80	SUBLET - CARRY OUT WHEEL ALIGNMENT	
		VO-2583700	NOX sensor, replace	0.3
		VO-8740000	Cooling unit	0.52
		VO-82356760	O-RING	0.4
		VO-82356754	O-RING	0.4
		VO-82348995	VENTILATION FILTER	1
		VO-82354791	VENTILATION FILTER	1
		VO-23177268	CONDENSER	0.4
		VO-82693739	ACCUMULATOR	0.4
		VO-84437717	HOSE	0.4
		VO-984723	FLANGE SCREW	2
		VO-22827995	SENSOR	1

PC	Type	Code	Description (Original)	#
		VO-941269	GROMMET DRAINPI	1
		VO-21392404	FILTER	1
		VO-21743197	AIR CLEANER	2
		VO-FK18B	FILTER KIT	1
		VO-8394887	OIL TEST KIT	2
		VO-21516229	FILTER	1
		VO-21954674	STRAINER	1
		VO-3110200	Batteries, replace (all)	0.4
		AU2-20935640	VOLVO MAINT N200	2
		VO-8181600	Cab shock absorber, rear horizontal, rep	0.3
		VO-22128971	SHOCK ABSORBER	1
		80	DROPPED TRUCK BACK TO LINFOX YARD	
			SUBLET COSTS.	
		93	42 LTS ENGINE OIL & GREASE	
		VO-2584800	Strainer, replace. Pump unit	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-2840700	Sensor values, check	0.2
		VO-3116800	Battery system, test. Battery tester	0.3
		VO-3200200	Charging test, in vehicle	0.4
		6010000	ANNUAL WHEEL ALIGNMENT	
			*BIG WHEELS TRUCK ALIGNMENT. INVOICE 22786. 28.03.2018.	
			LH SIDE.	
		VO-8181600	Cab shock absorber, rear horizontal, rep	0.3
			RH SIDE.	
		VO-22128971	SHOCK ABSORBER	1
		VO-8740000	Cooling unit	0.78

PC	Type	Code	Description (Original)	#
		VO-82356760	O-RING	0.6
		VO-82356754	O-RING	0.6
		VO-23177268	CONDENSER	0.6
		VO-82693739	ACCUMULATOR	0.6
		VO-84437717	HOSE	0.6
		97	AIR COND. GAS	
			8740800 Condenser, replace.	
			8700700 Refrigerant filling.	
			8740500 Dryer, replace.	
			= 1.30 HOURS TOTAL. 40% = 0.52 HOURS.	
			8740800 Condenser, replace.	
			8700700 Refrigerant filling.	
			8740500 Dryer, replace.	
			= 1.30 HOURS TOTAL. 60% = 0.78 HOURS.	
		VO-8721400	Air filter air conditioning, replace (in	0.1
			(inside)	
		VO-8720800	Air conditioning air filter, replace	0.1
			as requested by customer.	
			VO/22128971 WAS FITTED BY BRANCH 1	
			.- ON REPAIR ORDER 2183957 - DATE 2017-05-31 MILEAGE - 549652	

2018-03-21 - Mileage: 792844 - Order nr: 2192678

		VO-2530400	Solenoid valve exhaust brake, replace	0.5
		VO-21991157	AIR VALVE	1
			00244129 S/NO. 171204.	
		VO-21312239	CHARGE AIR HOSE	1
		VO-20592783	CLAMP	2
		VO-2652200	Charge air hose, replace	0.3
		VO-2501200	Intercooler system, leakage test	0.6

PC	Type	Code	Description (Original)	#
		VO-2500600	Inlet and exhaust systems, check	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2533600	Engine brake function, test	0.4
		VO-2558500	Actuator by-pass valve, test	0.4
		VO-2500300	Boost pressure, test drive	0.4
			VO/21312239 WAS FITTED BY BRANCH 7	
			.- ON REPAIR ORDER 7715160 - DATE 2018-02-10 MILEAGE - 758304	

2018-03-19 - Mileage: 792299 - Order nr: 2191762

		VO-2563200	Air filter housing, replace	0.5
		VO-20478756	AIR CLEANER HOUSIN	1
		VO-8842000	Airbag module, replace	0.3
		VO-22900843	ççAIRBAG MODULE, RAVEN	1
		VO-8740000	Cooling unit	2
		VO-20478824	COVER	1
		VO-979972	SCREW	6
		VO-21716424	AIR FILTER	1
		VO-20411816	FH INNER FILTER	1
		VO-82356760	O-RING	1
		VO-82348995	VENTILATION FILTER	1
		VO-5600000	Air pressure brake, general. Secondary o	0.5
		VO-980833	PLASTIC PIPE 12MM	1
		VO-991075	NIPPLE	1
		MK-FT1162X12M	BRASS PUSH-CONNECT	1
		80	DROPPED TRUCK BACK TO LINFOX YARD	
		VO-22889891	ACTUATOR SERVICE KIT	1
		LO-251	EXHAUST MANIFOLD GASKETS - REPLACE	2.98
		VO-21352841	GASKET	6
		VO-2500600	Inlet and exhaust systems, check	0.2

PC	Type	Code	Description (Original)	#
		VO-2562700	Filter insert, air cleaner, replace. Onl	0.4
		VO-2562500	Secondary air filter, replace. Air filte	0.2
			AIRBAG MODULE, REPLACE. FH/FM (4)	
		VO-2531400	Control cylinder exhaust brake, replace	0.6
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2534000	Warm hold function, test	0.2
		VO-8721400	Air filter air conditioning, replace (in	0.1
			(inside)	
			SUBLET COSTS.	
		VO-8741400	Cooling unit, performance test	0.3
		VO-8701100	Refrigerant, draining for re-using	0.2
		VO-8700700	Refrigerant, filling	0.3
	*	97	AIR COND. GAS - 0.15 KGS	
		VO-5600100	Pressure drop in compressed air system,	0.5
2018-03-01 - Mileage: 789779 - Order nr: 200793				
		96000		0
2018-02-19 - Mileage: 769529 - Order nr: 2191794				
		VO-2373600	Unit injector, replace (all)	3.6
	*	92	TRAVEL 30 KM Ö Å0.98CTS PER KM	
		VO-1921200	Transfer time to breakdown site and back	0.5
			LINFOX YARD HAZELMERE.	
		VO-21351717	INJECTOR SLEEVE	6
		VO-21261987	GASKET	6
		VO-21801388	YOKE	6
		VO-21344774	FLANGE SCREW	6
		VO-1677370	VEB SEAL	2
		VO-20526428	VEB SEAL	1
		VO-20852765	GASKET	4

PC	Type	Code	Description (Original)	#
		VO-947281	*COPPER WASHER	2
		VO-2373300	Sleeve, unit injector, replace. Unit inj	0.3
		VO-2373100	Sleeve, unit injector, replace (Others e	0.4
			each). Coolant drained and unit injectors removed.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-2300300	Fuel system, bleeding	0.2
		VO-2301000	Air in the fuel system, check	0.4
		VO-1820200	Localised wash for fault tracing	0.3
		VO-2500500	Response, test drive	0.4
			to repairing dealer. Breakdown, call-out service.	
2018-02-12 - Mileage: 766011 - Order nr: 2191533				
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
	*	93	42 LTS ENGINE OIL & GREASE	
		VO-1707300	Service alert system, configuration and	0.4
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2335400	Fuel and water separator filter, replace	0.6
		VO-5616600	Air drier cassette, replace	0.3
		VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
		VO-2141300	Valves and unit injectors, adjust	1.7
	*	3300	STARTER SOLENOID HOUSING SCREWS - CHECK	
		VO-1706800	36 Months ECU download and oil sample. O	0.9
		VO-FK18B	FILTER KIT	1
		VO-22223804	KIT	1
		VO-20531103	AIR FILTER	1
		VO-20733172	SILENCER	1

PC	Type	Code	Description (Original)	#
		VO-8394887	OIL TEST KIT	4
		VO-20779040	G/BOX OIL FILTER KIT	1
		OTH-85131754L	GEAR OIL SYNTH 1 LITER SHC50	16
		VO-22064603	COVER	1
		4310000	GEARBOX FILTER COVER - REPLACE	
		80	DROPPED TRUCK BACK TO LINFOX YARD	
			as requested by customer.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-5619800	Air Drier, calibration	0.2
		VO-5618200	Air drier, silencer, replace	0.1
		VO-2373200	Yoke, injector, check. Valve cover remov	0.4
			SUBLET COSTS.	

2018-02-04 - Mileage: 758304 - Order nr: 7715160

		DETAILS	DETAILS	
			VEH KM:758304	
		LO-BREAKDO	BREAKDOWN	4
			OFFSITE WORK YES	
			ENG HRS:10727	
			FUEL BURN:582360	
		VO-2520000	Silencer and exhaust pipe. Secondary ope	1.5
		OTH-L-TCWA	TCWA LATE OPENING FEE	1
		VO-21412472	TEMPERATURE SENSOR	1
		VO-85000622	TURBOCHARGER, EXCH	1
		VO-20784537	GASKET	1
		VO-21352841	GASKET	6
		VO-21940615	SEALING RING	1
		VO-22206133	GASKET	1
		VO-420643	TURBO GKT	1

PC	Type	Code	Description (Original)	#
W	■	VO-469601	D12 TURBO SEAL	1
	☒		VO/21940615 WAS FITTED BY BRANCH 1	
	☒		.- ON REPAIR ORDER 2182588 - DATE 2017-02-28 MILEAGE - 515509	
	☒		VO/469601 WAS FITTED BY BRANCH 1	
	☒		.- ON REPAIR ORDER 2182588 - DATE 2017-02-28 MILEAGE - 515509	
G	■	VO-21969162	PIPE	1
G	■	VO-21312239	CHARGE AIR HOSE	1
G	■	VO-1161963	RUBBER GREASE	1
G	■	VO-20728609	INLET HOSE	1
	☒		DESTINATION: LINFOX YARD WEDGEFIELD	
	☒		AFTER HOURS: YES	
	☒		CALL OUT TIME 13.00	
	☒		DATE 04/02/2018	
	☒		CONTACT ON SITE IS: PETER HARDERS 0428 743 950	
	☒		CONTACT OFF SITE IS:	
G	■	VO-6781769	SPLICE-RED(22-18)	10
R	■	OTH-21E20BLK	TAPE PVC LEAD FREE 19MMX20M	1
	☒		VO/85000622 WAS FITTED BY BRANCH 1	
	☒		.- ON REPAIR ORDER 2182588 - DATE 2017-02-28 MILEAGE - 515509	
	☒		NEW S/N F25330	
	☒		OLD S/N H161033082	
W	🔧	VO-2551800	Engine turbocharger, replace. Chassis mo	1.8
	☒		mounted	
G	🔧	VO-2581500	Exhaust temperature sensor, replace	0.5
G	🔧	VO-3710200	Electric wires and connections, check	0.4
G	🔧	VO-1701000	Connect-disconnect of diagnostic tool	0.2
G	🔧	VO-1703700	Sensor and parameter values, monitoring	0.2
G	🔧	VO-2652200	Charge air hose, replace	0.3

PC	Type	Code	Description (Original)	#
		VO-2501200	Intercooler system, leakage test	0.6
		VO-2551600	Hose between air filter and turbocharger	0.2
			turbocharger, replace	
		VO-2500600	Inlet and exhaust systems, check	0.2
			Engine brake actuator to AVU valve	
		VO-2534000	Warm hold function, test	0.2
		VO-2533600	Engine brake function, test	0.4
		VO-2563000	Air filter housing, remove	0.1
		VO-2565100	Air filter housing, install	0.4
		VO-2500300	Boost pressure, test drive	0.4
		VO-2500600	Inlet and exhaust systems, check	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2500300	Boost pressure, test drive	0.4
	*	91	CONSUMABLES	

2018-01-31 - Mileage: 754349 - Order nr: 2191239

		VO-5600700	Trailer modulator, replace	0.7
		VO-3173150	RELAY VALVE	1
		VO-21114977	MODULATOR	1
		VO-20467891	SILENCER	1
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-5600100	Pressure drop in compressed air system,	0.5
		VO-2500500	Response, test drive	0.4
		VO-5618200	Air drier, silencer, replace	0.1

2018-01-30 - Mileage: 754286 - Order nr: 2191181

		LO-560	ELECTRIC BRAKE/APM FAULT C102668	2.2
	*	80	DROPPED TRUCK BACK TO LINFOX YARD	
			CHECK & REPORT.	

PC	Type	Code	Description (Original)	#
	📄		SUBLET COSTS.	
	📄		Electric brake/APM Fault - connect laptop, check fault codes	
	📄		check air drier - all ok, build up air in system and check	
	📄		all fittings and airbags for leaks - all ok. Road test - ok	
	📄		Suspect brake fault came up due to low air in the system.	
🟢	*	91	CONSUMABLES	

🔍 📄 **2018-01-22 - Mileage: 748991 - Order nr: 2189976**

🟢	🟡	LO-840	KERB MIRROR, CRACKED/DAMAGED - REPLACE	0.5
🟢	🟡	LO-851	LCS PANEL CLIPS BROKEN/MISSING - REPLACE	0.1
🟢	📄	VO-84167321	KERB OBSERVATION M	1
🟢	🟡	VO-2340000	Fuel tank, fuel lines, evaporator system	2
🟢	*	80	DROPPED TRUCK BACK TO LINFOX YARD	
🟢	📄	VO-82217702	ATTACHMENT KIT	2
🟢	📄	VO-20484075	AIR VENT PIPE	1
🟢	📄	VO-20852765	GASKET	2
🟢	📄	VO-20754813	OVERFLOW VALVE	1
🟢	📄	VO-968177	HOLLOW SCREW	1
🟢	📄	VO-18665	COP/WSR M10	3
🟢	📄	VO-946834	CLAMP 11.1mm	1
🟢	📄	VO-977755	NIPPLE	1
🟢	📄	VO-956984	NUT	1
🟢	📄	VO-960628	*PLUG	1
	📄		R&R the kerb mirror with new as required.	
	📄		Fit new clips and secure the panel. All OK.	
	📄		SUBLET COSTS.	
	📄		TSB V-23-127.	

🔍 📄 **2018-01-04 - Mileage: 736386 - Order nr: 2190632**

🟢	🟡	LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
---	---	------------	---------------------------------	-----

PC	Type	Code	Description (Original)	#
	📄		For Volvo vehicles under Service Agreement	
Ⓞ	🔧	VO-1774400	Basic service. Chassis lubrication and o	1.3
Ⓞ	*	93	42 LTS ENGINE OIL & GREASE	
Ⓞ	🔧	VO-1707300	Service alert system, configuration and	0.4
Ⓞ	🔧	VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
Ⓞ	🔧	VO-2335400	Fuel and water separator filter, replace	0.6
Ⓞ	🔧	VO-4658400	Differential carrier oil sample, take (o	0.2
Ⓞ	🔧	VO-4317700	Gearbox oil sample, take	0.2
Ⓞ	🔧	VO-1756100	Final drive with hub reduction, oil chan	0.8
Ⓞ	🔧	VO-2141300	Valves and unit injectors, adjust	1.7
📌	*	3300	STARTER SOLENOID HOUSING SCREWS - CHECK	
Ⓞ	🔧	VO-FK18B	FILTER KIT	1
Ⓞ	🔧	VO-8394887	OIL TEST KIT	2
Ⓞ	🔧	VO-8394887	OIL TEST KIT	1
📌	*	80	DROPPED TRUCK BACK TO LINFOX YARD	
Ⓞ	🔧	VO-949329	COPPER WASHER	8
Ⓞ	🔧	AU2-CAL85136279	SYNTH REAR AXLE OIL 20L(97312)	2
Ⓞ	🔧	OTH-CAL85136280L	SYNTH DIFF OIL(97312)PER LITRE	15
Ⓞ	🔧	VO-949329	COPPER WASHER	4
	📄		as requested by customer.	
Ⓞ	🔧	VO-2373200	Yoke, injector, check. Valve cover remov	0.4
	📄		SUBLET COSTS.	
🔍 Ⓞ 2018-01-01 - Mileage: 746662 - Order nr: 200793				
Ⓞ	🔧	96000		0
🔍 2017-12-11 - Mileage: 0 - Order nr: 2190049				
📌	*	8431	REMOVE AND REPLACE STONEGUARD	
	📄		DUE TO A BIRD STRIKE ON 8/12/17.	
📌	🔧	VO-22983410	BRACKET S/GUARD	2

PC	Type	Code	Description (Original)	#
		OTH-F	FREIGHT	3.6
		VO-22983970	STONE GUARD	1
			WINDSCREEN WAS REPLACED ON 8/12/17.	
			Note: Customer collected parts and fitted themselves as we	
			could not get it done this week - DC Ö 11:00 28/12/17.	
2017-12-08 - Mileage: 717978 - Order nr: 2190048				
		SHIFT	SHIFT : DAY	
		VO-3668400	LKS (Lane Keeping System), calibration	2
			VCR W149038	
			PO797-48571	
			Performed LKS calibration for new w/screen as req.	
2017-12-05 - Mileage: 715541 - Order nr: 2189808				
		VO-1820200	Localised wash for fault tracing	0.3
		VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
		LO-891	EXTERNAL SUNVISOR - REPLACEMENT	2.5
		80	DROPPED TRUCK BACK TO LINFOX YARD	
		VO-943904	GLOBE H1 24V70W	1
		VO-84014254	SUN VISOR	1
		VO-21177256	CONNECTOR	1
		VO-85122800	1L DEXRON3 ATF	2
		VO-21177259	CONNECTOR	1
		VO-82344857	COVER	1
		VO-82355612	COVER	1
		VO-2520000	Silencer and exhaust pipe. Secondary ope	1
		VO-1629499	CLAMP	1
		VO-990941	FLANGE NUT	1
		VO-994195	FLANGE SCREW	1
		VO-21095726	GASKET	1

PC	Type	Code	Description (Original)	#
		VO-6450000	Power steering equipment	1
			SUBLET COSTS.	
			LH SIDE.	
			R&R the external sunvisor with new.	
	*	91	CONSUMABLES	
2017-12-01 - Mileage: 726482 - Order nr: 200793				
		96000		0
2017-11-24 - Mileage: 706302 - Order nr: 2189624				
	*	SHIFT	SHIFT :	
			DATE IN : 24.11.2017 TIME IN : 12:00	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.54
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
	*	93	ENGINE OIL & GREASE	
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-1707300	Service alert system, configuration and	0.4
		VO-2335400	Fuel and water separator filter, replace	0.6
		VO-4658400	Differential carrier oil sample, take (o	0.2
	*	3300	CHECK STARTER SOLENOID HOUSING SCREWS	
	*	80	DROPPED TRUCK BACK TO LINFOX YARD	
		VO-FK18B	FILTER KIT	1
		VO-8394887	OIL TEST KIT	2
			DROPPED TRUCK BACK TO LINFOX YARD.	
			CONTACT PERSON : XXXXXXXXXX	
			CONTACT NUMBER : XXXXXXXXXX	
			VCR: W149034.	
			SUBLET COSTS.	
			as requested by customer.	

PC	Type	Code	Description (Original)	#
2017-11-01 - Mileage: 687576 - Order nr: 200793				
		96000		0
2017-10-31 - Mileage: 681925 - Order nr: 2188964				
	*	SHIFT	SHIFT : DAY	
			DATE IN : 31/10/17 TIME IN : 10:32 AM	
		VO-8740800	Condenser, replace	0.7
		VO-82693739	ACCUMULATOR	1
		VO-22768926	CONDENSER	1
	*	80	DROPPED TRUCK BACK TO LINFOX YARD	
		VO-82356754	O-RING	1
			DROPPED TRUCK BACK TO LINFOX YARD.	
			CONTACT PERSON : ██████████	
			CONTACT NUMBER : ████████████████████	
			██████████	
			SUBLET COSTS.	
		VO-8741400	Cooling unit, performance test	0.3
		VO-8701300	Air conditioning system, leakage check	0.2
		VO-8701100	Refrigerant, draining for re-using	0.2
		VO-8740500	Dryer, replace	0.2
		VO-8700700	Refrigerant, filling	0.3
	*	97	AIR COND. GAS - 0.65 KGS	
2017-10-30 - Mileage: 0 - Order nr: 2188960				
	*	1000	card not required	
2017-10-10 - Mileage: 676807 - Order nr: 2188505				
	*	SHIFT	SHIFT : DAY	
			DATE IN : 23.10.2017 TIME IN : 11:15 AM	
		LO-510	DRIVERS SIDE WHEEL ARCH TRIM - FIT NEW	1.5
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5

PC	Type	Code	Description (Original)	#
	☒		For Volvo vehicles under Service Agreement	
Ⓞ	🔧	VO-1774400	Basic service. Chassis lubrication and o	1.3
Ⓞ	*	93	42 LTS ENGINE OIL & GREASE	
Ⓞ	🔧	VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
Ⓞ	🔧	VO-2335400	Fuel and water separator filter, replace	0.6
Ⓞ	🔧	VO-1707300	Service alert system, configuration and	0.4
Ⓞ	🔧	VO-5616600	Air drier cassette, replace	0.3
Ⓞ	🔧	VO-4658400	Differential carrier oil sample, take (o	0.2
Ⓞ	🔧	VO-2200400	Engine oil sample, take	0.2
Ⓞ	🔧	VO-8720800	Air conditioning air filter, replace	0.1
Ⓞ	🔧	VO-8721400	Air filter air conditioning, replace (in	0.1
Ⓞ	🔧	VO-2631300	Fan belt tensioner, replace	0.5
	☒		PREVENTATIVE MAINTENANCE.	
Ⓞ	🔧	VO-FK18B	FILTER KIT	1
Ⓞ	🔧	VO-22223804	KIT	1
Ⓞ	🔧	VO-20733172	SILENCER	1
Ⓞ	🔧	VO-20531103	AIR FILTER	1
Ⓞ	🔧	VO-8394887	OIL TEST KIT	2
Ⓞ	🔧	VO-8394887	OIL TEST KIT	1
Ⓞ	🔧	VO-82354791	VENTILATION FILTER	1
Ⓞ	🔧	VO-82348995	VENTILATION FILTER	1
Ⓞ	🔧	VO-21631484	BELT TENSIONER	1
Ⓞ	🔧	LO-510	VIBRATION/WOBBLE AT HIGH SPEED - CHECK	0.5
Ⓞ	🔧	VO-2331200	Filter, water separator, replace	0.6
Ⓞ	🔧	VO-20870049	BOWL	1
Ⓞ	🔧	MK-9728-F100	SUPPRESANT SPRAY 1	2
Ⓞ	🔧	VO-980881	CABLE TIE	2
Ⓞ	*	80	DROPPED TRUCK BACK TO LINFOX YARD	

PC	Type	Code	Description (Original)	#
		VO-4320800	Gear selector, replace	0.6
		VO-22647973	GEAR SELECTOR	1
		VO-4680100	Diaphragm, differential lock, replace	0.4
		VO-20545485	DIFF LOCK DIAPHRAGM	1
		VO-82217705	ATTACHMENT KIT	1
		VO-82217702	ATTACHMENT KIT	2
			DROPPED TRUCK BACK TO LINFOX YARD.	
			CONTACT PERSON : ██████████	
			CONTACT NUMBER : ██████████	
			██████████	
			as requested by customer.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-5619800	Air Drier, calibration	0.2
		VO-5618200	Air drier, silencer, replace	0.1
			(inside)	
		VO-3710200	Electric wires and connections, check	0.4
			SUBLET COSTS.	
			Road test - detect a faint vibration at 100 KLM/HR.	
			Suggest wheels be re-balanced and monitor.	
			Tilt the cab. Fit new trim and cut to size as required.	
		91	CONSUMABLES	

2017-10-09 - Mileage: 667683 - Order nr: 2188444

		60	SUBLET ANNUAL WHEEL ALIGNMENT	
		6010000	WHEEL ALIGNMENT	
			BIG WHEELS TRUCK ALIGNMENT, INVOICE PE-21944. 10.10.2017.	

2017-10-06 - Mileage: 667931 - Order nr: 2188334

		SHIFT	SHIFT :DAY	
			ENG HRS: 9444. FUEL BURN: 514903.	

PC	Type	Code	Description (Original)	#
		VO-8743300	A/C compressor, replace	1.2
		VO-85003041	COMPRESSOR, EXCH	1
		VO-20443759	O-RING	1
		VO-20708247	O-RING	1
		VO-82693739	ACCUMULATOR	1
		VO-84180960	HOSE	1
		VO-21190817	V-RIBBED BELT	1
		VO-22306618	OIL FILLER PIPE	1
		VO-990950	M8 FLANGE LOCK NUT	2
			CONTACT PERSON : ██████████	
			CONTACT NUMBER : ██████████	
			VCR: W149024.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-8740500	Dryer, replace	0.2
		VO-8741400	Cooling unit, performance test	0.3
		VO-2630400	Drive belt, replace	0.4
		VO-2212300	Dipstick tube, replace	0.3
			VO/21190817 WAS FITTED BY BRANCH 1	
			.- ON REPAIR ORDER 2185796 - DATE 2017-07-06 MILEAGE - 590035	

2017-10-01 - Mileage: 666693 - Order nr: 200793

		96000		0
--	--	-------	--	---

2017-09-11 - Mileage: 667666 - Order nr: 2187730

	*	SHIFT	SHIFT : DAY	
			CONTACT PERSON : ██████████	
		VO-8341400	Door lock, replace (one side)	0.9
		VO-7610400	Rear shock absorber, replace (one)	0.6

PC	Type	Code	Description (Original)	#
		VO-20585556	SHOCK ABSORBER	1
		VO-22246022	DOOR LOCK	1
		VO-6526200	V-stay front, replace	2.3
		VO-22238525	V-STAY	1
		VO-8823700	Roller blind, side window, replace	0.3
		VO-84431057	ROLLER BLIND	1
		VO-984727	M6*25 FL BOLT	1
		VO-992023	TEST NIPPLE	1
		VO-991080	NIPPLE	1
		VO-991074	NIPPLE	1
		VO-991075	NIPPLE	1
		VO-991083	SWIVEL	1
		VO-991980	T NIPPLE	2
		80	DROPPED TRUCK BACK TO LINFOX YARD	
			CONTACT NUMBER : XXXXXXXXXX	
			VCR : W149018 / W149019	
			RH SIDE.	
			SUBLET COSTS.	
		VO-8180000	Cab mounting	1
		VO-8820000	Interior equipment	0.5
		VO-1820200	Localised wash for fault tracing	0.3

2017-09-11 - Mileage: 647085 - Order nr: 2187640

		SHIFT	SHIFT : DAY	
			DATE IN : 11/09/2017 TIME IN : 09:30AM	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.78
			For Volvo vehicles under Service Agreement	
		331	CHECK STARTER MOTOR SOLENOID SCREWS	
		VO-1774400	Basic service. Chassis lubrication and o	1.3

PC	Type	Code	Description (Original)	#
G	W	VO-1707300	Service alert system, configuration and	0.4
G	W	VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
G	W	VO-2335400	Fuel and water separator filter, replace	0.6
G	W	VO-4658400	Differential carrier oil sample, take (o	0.2
G	W	VO-2141300	Valves and unit injectors, adjust	1.7
G	W	VO-1756100	Final drive with hub reduction, oil chan	0.8
G	R	VO-8394887	OIL TEST KIT	2
G	R	VO-981281	DRAIN PLUG,MAGNETIC	1
G	R	VO-949329	COPPER WASHER	4
G	R	VO-20775507	HEX. SOCKET SCREW	12
G	R	VO-FK18B	FILTER KIT	1
G	R	OTH-CAL85136280L	SYNTH DIFF OIL(97312)PER LITRE	52
G	W	VO-2531400	Control cylinder exhaust brake, replace	0.6
G	R	VO-22823727	EXHAUST BRAKE	1
G	R	VO-467310	EXHAUST CLAMP	1
G	R	VO-994441	M8*50 FLANGE SCREW	1
G	R	VO-990950	M8 FLANGE LOCK NUT	1
G	R	VO-21719872	V-CLAMP	1
G	R	VO-942400	CLAMP B 6020	1
B	*	80	DROPPED TRUCK BACK TO LINFOX YARD	
	E		DROPPED TRUCK BACK TO LINFOX YARD - 11.09.2017.	
	E		CONTACT PERSON : ██████	
	E		CONTACT NUMBER : ██████████	
	E		VCR : W149018 / W149019.	
G	*	93	42 LTS ENGINE OIL & GREASE	
G	W	VO-2373200	Yoke, injector, check. Valve cover remov	0.4
	E		SUBLET COSTS.	
G	W	VO-1701000	Connect-disconnect of diagnostic tool	0.2

PC	Type	Code	Description (Original)	#
		VO-2500600	Inlet and exhaust systems, check	0.2
		VO-2533600	Engine brake function, test	0.4
			as requested by customer.	
2017-09-01 - Mileage: 618684 - Order nr: 200793				
		96000		0
2017-08-18 - Mileage: 0 - Order nr: 2187048				
	*	1000	card not required	
2017-08-08 - Mileage: 618683 - Order nr: 2186704				
	*	SHIFT	SHIFT : DAY	
			DATE IN : 08.08.2017 TIME IN : 07:15	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	1
			For Volvo vehicles under Service Agreement	
	*	330	STARTER MOTOR SOLENOID SCREWS - CHECK	
		VO-4658400	Differential carrier oil sample, take (o	0.2
		VO-1774400	Basic service. Chassis lubrication and o	1.3
		VO-1707300	Service alert system, configuration and	0.4
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2335400	Fuel and water separator filter, replace	0.6
		VO-FK18B	FILTER KIT	1
		VO-8394887	OIL TEST KIT	2
		VO-949329	COPPER WASHER	6
		OTH-85131754L	GEAR OIL SYNTH 1 LITER SHC50	4
		VO-1758600	Top up oil and fluid levels. Secondary o	0.5
		VO-6459800	Servo oil, top up. Campaign only	0.3
	*	80	DROP TRUCK BACK TO LINFOX YARD	
			DROP TRUCK BACK TO LINFOX YARD - 08.08.2017.	
			CONTACT PERSON : XXXXXXXXXX	
			CONTACT NUMBER : XXXXXXXXXX	

PC	Type	Code	Description (Original)	#
	☒		VCR : W149012	
Ⓞ	*	93	42 LTS ENGINE OIL & GREASE	
Ⓞ	*	93	500 ML ATF	
	☒		SUBLET COSTS.	
	☒		as requested by customer.	
🔍 Ⓞ 2017-08-01 - Mileage: 601598 - Order nr: 200793				
Ⓞ	🕒	96000		0
🔍 Ⓞ 2017-07-18 - Mileage: 601597 - Order nr: 2186239				
Ⓡ	*	SHIFT	SHIFT : NIGHT	
	☒		DATE IN : 18/07/17 TIME IN : 13:40	
Ⓞ	🕒	VO-2341400	Filter for fuel tank ventilation, replac	0.1
Ⓞ	☒	VO-3944785	BREATHER FILTER	1
	☒		CONTACT PERSON : J [REDACTED]	
	☒		CONTACT NUMBER : [REDACTED]	
	☒		[REDACTED]	
Ⓞ	🕒	VO-2500600	Inlet and exhaust systems, check	0.2
🔍 Ⓞ 📖 2017-07-11 - Mileage: 596042 - Order nr: 2185912				
Ⓡ	*	SHIFT	SHIFT : Day	
	☒		DATE IN : 11/07/17 TIME IN : 10:45	
Ⓞ	🕒	VO-2652200	Charge air hose, replace	0.1
Ⓞ	🕒	VO-8460100	Rear view mirror glass, replace	0.1
Ⓞ	🕒	VO-5119500	Bushings, seals and guide sleeves, repla	2
Ⓞ	🕒	VO-2520400	Silencer inlet pipe, replace	0.5
Ⓞ	☒	VO-21259899	CHARGE AIR HOSE	1
Ⓞ	☒	VO-82356808	HOUSING	1
Ⓞ	☒	VO-82359314	GLASS	1
Ⓞ	☒	VO-85109890	REPAIR KIT	2
Ⓞ	☒	VO-22821514	EXHAUST PIPE	1

PC	Type	Code	Description (Original)	#
		VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
		LO-350	LH TOP CAB REVERSE LIGHT - REPLACE	2
		VO-8313100	Door stop, replace	0.2
		2580700	Pump unit, replace	
		OTH-AB15	ADBLUE 15L	4
		VO-22406383	KIT	1
		VO-22225326	EXHAUST PIPE CLAMP	1
		VO-996180	RUBBER STOP	2
		VO-943904	GLOBE H1 24V70W	1
		VO-21496550	BRAKE PAD KIT	1
		OTH-29-SP120	LED LIGHT ROUND	1
		80	DROPPED TRUCK BACK TO LINFOX YARD	
			DROPPED TRUCK BACK TO LINFOX YARD.	
			CONTACT PERSON : XXXXXXXXXX	
			CONTACT NUMBER : XXXXXXXXXX	
			W149007.	
			Pump replaced on b/down INV 2185951.	
		VO-2580300	AdBlue tank, replace	1.3
		VO-2585800	AdBlue tank, clean. Urea tank removed	0.5
		VO-2580000	Emissions after-treatment. Secondary ope	0.2
		VO-2582800	Combined tank unit, replace. AdBlue tank	0.2
			(includes filter, replace)	
		VO-2653100	Charge air cooler, leakage test	0.6
			SUBLET COSTS.	
		VO-8400000	Outside trim parts, glass, sealing mould	0.5
			Wheel removed.	
		VO-7704000	Front wheels, remove-install (two sides)	0.9
		VO-5111500	Brake pads, front axle, check	0.1

PC	Type	Code	Description (Original)	#
		VO-5112100	Brake pads, replace (two front wheels).	0.8
			Wheels removed.	
		VO-1820200	Localised wash for fault tracing	0.3
		10	60 LTS ADBLUE	
			R&R the top cab reverse light with new. Test op - all OK.	
		91	CONSUMABLES	

2017-07-05 - Mileage: 590176 - Order nr: 2185951

		SHIFT	SHIFT : VOLVO BREAKDOWN	
			CONTACT PERSON : XXXXXXXXXX	
		92	TRAVEL 157 KM Ö Å0.98 CTS PER KM	
			CHITTERING ROADHOUSE.	
		VO-2580700	Pump unit, replace	0.8
		VO-22851845	PUMP UNIT	0.4
			CONTACT NUMBER : XXXXXXXXXX	
			W149005.	
		LO-194	TRAVELLING TIME	2.05
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2584600	SCR system, test	0.5
		VO-22851845	PUMP UNIT	0.6
		2580700	Pump unit, replace - JOB 2 - CGW	
			NEW UNIT SN: 38598.	
			NEW UNIT SN: 38598.	
		VO-2580000	Emissions after-treatment. Secondary ope	1
		VO-1702600	Program control unit	0.1
		VO-2584600	SCR system, test	0.5
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
			Connect-disconnect of diagnostic tool included.	

2017-07-04 - Mileage: 0 - Order nr: 2185937

PC	Type	Code	Description (Original)	#
	*	CARD	NOT REQUIRED	
   2017-07-03 - Mileage: 590035 - Order nr: 2185796				
	*	SHIFT	SHIFT : DAY	
			DATE IN : 03.07.2017 TIME IN : 08:30 AM	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	1
			For Volvo vehicles under Service Agreement	
		VO-1706700	30 Months ECU download and oil sample. O	0.9
		VO-1774600	Annual service. Chassis lubrication and	2.4
			oil changes included only in some models.	
		VO-1707300	Service alert system, configuration and	0.4
		VO-5616600	Air drier cassette, replace	0.3
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-7714500	Wheel nuts, check tightening (all)	0.3
		VO-2562700	Filter insert, air cleaner, replace. Onl	0.4
		VO-2331100	Filter, water separator, replace	0.5
		VO-2330600	Fuel filter, replace (one)	0.2
		VO-3210100	Alternator, replace	0.7
		VO-6452500	Oil filter, power steering, replace	0.1
		VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
	*	3110	CHECK STARTER SOLENOID HOUSING SCREWS	
		VO-8394887	OIL TEST KIT	4
		VO-FK18B	FILTER KIT	1
		VO-22223804	KIT	1
		VO-21716424	AIR FILTER	1
		VO-85020837	ALTERNATOR, EXCH	1
		VO-21392404	FILTER	1
		VO-20779040	G/BOX OIL FILTER KIT	1
		OTH-85131754L	GEAR OIL SYNTH 1 LITER SHC50	16

PC	Type	Code	Description (Original)	#
G	■	VO-21847501	V-RIBBED BELT LG1413mm	1
G	■	VO-21190817	V-RIBBED BELT	1
W	■	VO-21753149	IDLER PULLEY	1
W	■	VO-21454379	BELT TENSIONER	1
W	⦿	VO-2637500	Fan belt idler pulley, replace	0.5
G	⦿	VO-3212300	Alternator belt, replace	0.3
G	⦿	VO-2630700	Drive belts fan, replace	0.2
G	⦿	VO-2341300	Filler cap, replace	0.1
W	⦿	VO-2111000	Sealing strip, valve cover, replace	0.4
W	⦿	VO-2580000	Emissions after-treatment. Secondary ope	1
W	■	VO-20736230	D16C R/C GKT	1
W	■	VO-23121198	FILLER NECK	1
G	■	VO-22335632	FILLER CAP KIT	1
G	■	VO-22889891	ACTUATOR SERVICE KIT	1
G	⦿	VO-2531400	Control cylinder exhaust brake, replace	0.6
R	■	VO-82269261	FILTER/MAGNET	1
R	*	80	DROPPED TRUCK BACK TO LINFOX YARD	
W	⦿	VO-3213000	Belt tensioner, alternator, replace	0.5
	☒		DROPPED TRUCK BACK TO LINFOX YARD.	
	☒		CONTACT PERSON : ██████████	
	☒		CONTACT NUMBER : ██████████	
	☒		W149002.	
G	*	93	42 LTS ENGINE OIL & GREASE	
G	⦿	VO-1701000	Connect-disconnect of diagnostic tool	0.2
G	⦿	VO-5619800	Air Drier, calibration	0.2
W	⦿	VO-2115300	Valve cover, remove	0.2
W	⦿	VO-2115400	Valve cover, install	0.4
	☒		LH SIDE TANK.	

PC	Type	Code	Description (Original)	#
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2534000	Warm hold function, test	0.2
			NEW UNIT SN: 14938, 15-09-22.	
			SUBLET COSTS.	
			Preventative Maintenance.	
			VO/20736230 WAS FITTED BY BRANCH 1	
			.- ON REPAIR ORDER 2184212 - DATE 2017-05-02 MILEAGE - 556592	
			VO/21753149 WAS FITTED BY BRANCH 1	
			.- ON REPAIR ORDER 2181999 - DATE 2017-02-07 MILEAGE - 498009	
			VO/21454379 WAS FITTED BY BRANCH 1	
			.- ON REPAIR ORDER 2176806 - DATE 2016-07-22 MILEAGE - 344818	
		VO-2582200	Filter, AdBlue, replace	1
			- DAMAGED WHEN THE DRIVER INSERTED THE FILLER NOZZLE.	
			R&R adblue filter/magnet with new.	
			as requested by customer.	
2017-07-01 - Mileage: 525779 - Order nr: 200793				
		96000		0
2017-06-27 - Mileage: 549625 - Order nr: 9009537				
			EAST PILBARA MECHANICAL, INVOICE 2438. 14.05.2017.	
			ACTUAL REPAIR DATE = 12.04.2017.	
		LO-194	TRAVELLING TIME - 12.04.2017	7
			TRAVEL TO BREAKDOWN NORTH OF MEEKATHARA.	
			3.50 HOURS TRAVEL TIME & 310 KLMS.	
			TRAVEL BACK TO WORKSHOP.	
			3.50 HOURS TRAVEL TIME & 310 KLMS.	
	*	92	TRAVEL 620 KM Ö Å0.98 CTS PER KM	
		LO-194	TRAVELLING TIME - 14.04.2017	7
			TRAVEL TO BREAKDOWN NORTH OF MEEKATHARA.	

PC	Type	Code	Description (Original)	#
	📦		3.50 HOURS TRAVEL TIME & 310 KLMS.	
	📦		TRAVEL BACK TO WORKSHOP.	
	📦		3.50 HOURS TRAVEL TIME & 310 KLMS.	
🔧	*	92	TRAVEL 620 KM @ 0.98CTS PER KM	
🔧	🔧	VO-2522800	Flexible exhaust pipe, replace	0.3
🔧	🔧	VO-991075	NIPPLE	2
🔧	🔧	VO-991980	T NIPPLE	1
🔧	🔧	VO-22321908	EXHAUST PIPE	1
🔧	🔧	VO-21095726	GASKET	2
🔧	🔧	VO-1629499	CLAMP	2
🔧	🔧	VO-994195	FLANGE SCREW	2
🔧	🔧	VO-990941	FLANGE NUT	2
🔧	🔧	VO-991092	NIPPLE	1
🔧	*	10	AIR LINES AND FITTINGS FROM PIRTEK	
🔧	🔧	VO-980833	PLASTIC PIPE 12MM	1
🔧	🔧	VO-2500600	Inlet and exhaust systems, check	0.2
🔧	🔧	VO-2652200	Charge air hose, replace	0.1
🔧	🔧	VO-2520000	Silencer and exhaust pipe. Secondary ope	0.8
	📦		SECURE THE PIPE IN PLACE.	
🔧	🔧	VO-5610000	Compressor, regulator, anti-freeze unit.	1
	📦		AND FIT REPLACEMENT WITH JOINERS AS REQUIRED.	
🔧	🔧	VO-5600800	Compressed air system, filling	0.1
🔧	🔧	VO-5610000	Compressor, regulator, anti-freeze unit.	0.5
🔧	🔧	VO-5610000	Compressor, regulator, anti-freeze unit.	1
	📦		FOR THE CLUTCH AND GEARBOX.	
🔧	🔧	VO-5600800	Compressed air system, filling	0.1
🔧	🔧	VO-5600100	Pressure drop in compressed air system,	0.5
🔧	🔧	VO-2500600	Inlet and exhaust systems, check	0.2

PC	Type	Code	Description (Original)	#
		VO-5610000	Compressor, regulator, anti-freeze unit.	0.7
2017-06-01 - Mileage: 525778 - Order nr: 200793				
		96000		0
2017-05-01 - Mileage: 525777 - Order nr: 200793				
		96000		0
2017-04-28 - Mileage: 556592 - Order nr: 2184212				
		SHIFT	SHIFT : VOLVO DAY	
			DATE IN : 28/04/17 TIME IN : 08:50	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
		VO-1756100	Final drive with hub reduction, oil chan	0.8
			CASTROL SYNTRAX.	
		VO-2141300	Valves and unit injectors, adjust	1.7
		VO-2373200	Yoke, injector, check. Valve cover remov	0.4
		3310	CHECK STARTER MOTOR SOLENOID SCREWS	
		VO-4658400	Differential carrier oil sample, take (o	0.2
		VO-2335400	Fuel and water separator filter, replace	0.6
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-1707300	Service alert system, configuration and	0.4
		VO-20775507	HEX. SOCKET SCREW	12
		VO-20736230	D16C R/C GKT	1
		VO-FK18B	FILTER KIT	1
		MK-9727-3377738	SYNTRAX UNIV PLUS - 1L	10
		MK-9727-3373869	SYNTRAX UNIV PLUS - 20L	2
		VO-8394887	OIL TEST KIT	2
		VO-22282775	HOSE	1
		VO-22282785	HOSE	1

PC	Type	Code	Description (Original)	#
		VO-21716424	AIR FILTER	1
		VO-85122800	1L DEXRON3 ATF	2
		VO-6452600	Hydraulic hose power steering, replace	1
		VO-2562400	Filter insert, air cleaner, replace. Onl	0.5
		VO-21177272	SOCKET	1
		VO-979972	SCREW	1
		LO-9000	DROPPED TRUCK BACK TO LINFOX YARD	0.5
		92	Uber from Linfox yard to TCWA Kewdale	
			10:53pm ! 385 Bushmead Rd, Hazelmere WA 6055, Australia	
			11:09pm ! 507 Abernethy Rd, Kewdale WA 6105, Australia	
			You rode with William George 12.21 kilometers	
			DROPPED TRUCK BACK TO LINFOX YARD.	
			CONTACT PERSON : XXXXXXXXXX	
			CONTACT NUMBER : XXXXXXXXXX	
			W70039.	
			as requested by customer.	
		93	42 LTS ENGINE OIL & GREASE	
2017-04-18 - Mileage: 549652 - Order nr: 2183957				
		SHIFT	SHIFT : VOLVO DAY	
			CONTACT PERSON : XXXXXXXXXX	
		VO-2520000	Silencer and exhaust pipe. Secondary ope	1.5
		VO-5240800	Brake pedal, split pin, check/adjust. Ca	0.5
		VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
		VO-21873533	CABLE HARNESS	1
		VO-983472	D12 LOOM TIE	8
		VO-20478756	AIR CLEANER HOUSIN	1
		VO-20571135	SERVICE KIT	1
		VO-21133832	HOSE	1

PC	Type	Code	Description (Original)	#
		VO-995680	HOSE CLAMP	2
		VO-8131154	SEALING RING	1
		VO-21503575	SEALING RING	1
		VO-22128971	SHOCK ABSORBER	1
		VO-2610000	Radiator and connections. Secondary oper	0.5
		VO-993977	HOSE CLAMP	2
		VO-21905526	KIT	1
		VO-21019159	RELAY	1
		VO-85139619	PRESSURE SENSOR	1
		OTH-56710	CONV TUBE 10mm PER METER	1
		VO-944126	O-RING INJ HARNESS	1
		VO-983472	D12 LOOM TIE	10
			CONTACT NUMBER : XXXXXXXXXX	
			W70038	
			C0001 Brake pedal, split pin, check/adjust. FH/FM (4)	
			S0221 EMS and ACM, SW update. EU4/5. FH/FM (4)	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-3712000	Cable harness, engine control unit, repl	2.1
		VO-2563200	Air filter housing, replace	0.5
		VO-8182000	Cab shock absorber rear, replace (one)	0.4
		VO-2850800	Exhaust back pressure sensor, replace	0.2
		VO-3317000	Starter motor, remove	0.2
		VO-3317200	Starter motor, install	0.3
		VO-3310000	Starter motor. Secondary operation numbe	0.2
			INSPECT AND REPORT ON ALL DAMAGED WIRING AND COMPONENTS	
			ON THE RH SIDE OF THE ENGINE - EXHAUST FLEX FAILED CAUSING	
			CONSEQUENTIAL DAMGAGE.	
		VO-3710000	Cables. Secondary operation number	2

PC	Type	Code	Description (Original)	#
		VO-2601200	Cooling system, drain and refill	0.8
2017-04-12 - Mileage: 0 - Order nr: 9009538				
	*	CARD	NOT REQUIRED	
2017-04-01 - Mileage: 525776 - Order nr: 200793				
		96000		0
2017-03-14 - Mileage: 525775 - Order nr: 2183102				
	*	SHIFT	SHIFT : VOLVO DAY	
			DATE IN : 14/03/17 TIME IN : 09:07	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
			30,000 KLM INTERVAL.	
	*	3310	CHECK STARTER MOTOR SOLENOID SCREWS	
		VO-4658400	Differential carrier oil sample, take (o	0.2
		VO-2335400	Fuel and water separator filter, replace	0.6
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-1707300	Service alert system, configuration and	0.4
		VO-5616600	Air drier cassette, replace	0.3
		VO-2200400	Engine oil sample, take	0.2
		VO-FK18B	FILTER KIT	1
		VO-22223804	KIT	1
		VO-8394887	OIL TEST KIT	2
		VO-990037	H7 GLOBE L/L	2
		VO-8182200	Shock absorber front, replace (two sides	1.1
		VO-8182000	Cab shock absorber rear, replace (one)	0.4
		VO-21739591	SHOCK ABSORBER	2
		VO-21739593	SHOCK ABSORBER	1
		LO-350	LHR LIGHT COVER PANEL MISSING - FIT NEW	1

PC	Type	Code	Description (Original)	#
R	■	VO-84139886	PANEL	1
R	⌚	LO-9000	DROPPED TRUCK BACK TO LINFOX YARD	0.5
R	*	92	[REDACTED]	
	☒		DROPPED TRUCK BACK TO LINFOX YARD.	
	☒		CONTACT PERSON : [REDACTED]	
	☒		CONTACT NUMBER : [REDACTED]	
	☒		W70028.	
	☒		as requested by customer.	
G	■	VO-8394887	OIL TEST KIT	1
G	*	93	42 LTS ENGINE OIL & GREASE	
	☒		RH SIDE.	
G	⌚	VO-1701000	Connect-disconnect of diagnostic tool	0.2
G	⌚	VO-5619800	Air Drier, calibration	0.2
G	⌚	VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
R	*	91	CONSUMABLES	

🔍 🌐 📄 **2017-03-10 - Mileage: 522494 - Order nr: 2183038**

R	*	SHIFT	SHIFT : DAY	
	☒		DATE IN : 10/03/17 TIME IN : 10:31	
G	⌚	VO-2582800	Combined tank unit, replace. AdBlue tank	0.2
G	■	VO-22406383	KIT	1
G	■	OTH-85109697	ADBLUE 10L PACK	5
W	■	VO-21480006	FILLER NECK	1
W	■	VO-82269261	FILTER/MAGNET	1
G	■	VO-984735	M8*25 FL BOLT	2
R	⌚	LO-9000	DROPPED TRUCK BACK TO LINFOX YARD	0.5

PC	Type	Code	Description (Original)	#
	*	92	SUBLET - Uber cost Linfox Yard to TCWA	
			21:37 ! 385 Bushmead RD, Hazelmere	
			21:52 ! 507 Abernathy Road, Kewdale	
			You rode with Deepak 12.21 KM.	
			DROPPED TRUCK BACK TO LINFOX YARD.	
			CONTACT PERSON : ██████████	
			CONTACT NUMBER : ██████████	
			W70025.	
		VO-2580000	Emissions after-treatment. Secondary ope	1
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
			AdBlue tank removed.	
		VO-2580400	AdBlue tank, remove	0.8
		VO-2580500	AdBlue tank, install	0.7
		VO-2585800	AdBlue tank, clean. Urea tank removed	0.5
		VO-2580000	Emissions after-treatment. Secondary ope	0.4
		VO-1820200	Localised wash for fault tracing	0.3
		VO-2500600	Inlet and exhaust systems, check	0.2
			VO/21480006 WAS FITTED BY BRANCH 1	
			.- ON REPAIR ORDER 2176806 - DATE 2016-07-22 MILEAGE - 344818	

  **2017-03-01 - Mileage: 498010 - Order nr: 200793**

		96000		0
---	---	-------	--	---

  **2017-02-23 - Mileage: 515509 - Order nr: 2182588**

	*	SHIFT	SHIFT : VOLVO DAY	
			CONTACT PERSON : Jason	
		VO-2112600	Cylinder head, replace	8.6
	*	10	SUBLET - CLASS THREE TOW	
		VO-21539900	GASKET KIT	1

PC	Type	Code	Description (Original)	#
		VO-22302063	CYLINDER LINER KIT	1
		VO-20578851	D16C2 MAIN BRG SHELL	6
		VO-20578853	D16C2 MAIN BRG SHELL	1
		VO-20586602	BIG-END BEARING KI	6
		VO-85000622	TURBOCHARGER	1
		VO-85000888	CYLINDER HEAD, EXCHANGE	1
		VO-22326082	VALVE BRIDGE	6
		VO-21948268	THRUST WASHER KIT	1
		AU2-9770-3331	EXTREME PRESSURE ANTI-SEIZE	1
		VO-22718181	KIT	1
		VO-1677370	VEB SEAL	2
		VO-20526428	VEB SEAL	1
		VO-21780376	SEALING RING	2
		VO-20734156	SEALING STRIP	1
		VO-1543578	F16 SEAL (OIL P	2
		VO-469601	TURBO DRAIN SEAL	1
		VO-21940615	SEALING RING	1
		VO-470993	TRBO RETURN GSK	1
		VO-21707133	OIL FILTER	2
		VO-21707132	BYPASS OIL FILTER	1
		AU2-CAL8394800	VOLVO VCS COOLANT	2
		VO-1161277	LINER SEALANT	1
		VO-955982	O-RING	1
		VO-994445	FLANGE SCREW	1
		VO-984816	M12*40 FL BOLT	13
		VO-949656	O-RING 19MM ID	1
		VO-948610	O RING COOLER	2
		VO-20852765	GASKET	4

PC	Type	Code	Description (Original)	#
		VO-469601	TURBO DRAIN SEAL	1
		VO-420641	TURBO FEED GASKET	1
		VO-20741911	O-RING	1
		VO-983472	D12 LOOM TIE	12
		VO-21271982	SENSOR	1
		VO-20579690	SUMP PLUG DOWTY WASHER	1
		VO-21707133	OIL FILTER	2
		VO-21707132	BYPASS OIL FILTER	1
		LO-9000	DROPPED TRUCK BACK TO LINFOX YARD	1
		VO-2611800	Expansion tank, replace	0.9
		VO-21883433	EXPANSION TANK	1
			NEW UNIT SN: 140921705.	
			OLD UNIT SN: 142731743.	
			CONTACT NUMBER : 0428 913 574	
			FROM GT NORTHRN HWAY, MOUNT MAGNET.	
		10	SUBLET - TOWING CHARGE - CUSTOMER	
			TO TRUCK CENTRE WA, KEWDALE.	
			FROM GT NORTHRN HWAY, MOUNT MAGNET.	
		2110000	BREAKDOWN - ENGINE MISFIRE	
			SWAN TOWING, INVOICE 185629. 21.02.2017.	
		VO-2600600	Cooling system, pressure test	0.4
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-2100600	Cylinder Compression, test	0.2
		VO-2110000	Cylinder head. Secondary operation numbe	2
		VO-1820200	Localised wash for fault tracing	0.3
		VO-2161100	Connecting rod bearings, replace (all).	1.3
			Oil sump removed.	

PC	Type	Code	Description (Original)	#
		VO-2160300	Main bearings, replace (all). Oil sump r	2.1
			Oil sump removed.	
		VO-2131100	Cylinder liners and pistons, replace (Al	6.9
			Cylinder heads and oil pan removed.	
		VO-2100000	Engine, general. Secondary operation num	2
		VO-2117700	Cylinder head, transfer parts	0.5
		VO-2558100	Turbocharger, replace	0.6
		VO-2600700	Cooling system, clean	2.1
		VO-2610400	Coolant level sensor, expansion tank, re	0.4
		VO-2301600	Cylinder balancing, check	0.2
		VO-1703700	Sensor and parameter values, monitoring	0.2
		VO-2500300	Boost pressure, test drive	0.4
			NEW UNIT SN: H161033082.	
			OLD UNIT SN: H140635765.	
			CLAIMING COSTS OF TOW FROM MOUNT MAGNET TO GERALDTON ONLY.	
			LINFOX TO PAY FOR ADDITIONAL COSTS, GERO TO PERTH.	
	*	93	84 LTS VDS4 ENGINE OIL	
			- REMOVE INJECTORS, FIT DUMMY INJECTOR TOOL & PRESSURISE	
			CYLINDERS INDIVIDUALLY	
		VO-2220700	Oil filter, engine, replace. Incl. by-pa	0.3
			by-pass filter, excl. oil change	
			TO TRUCK CENTRE WA, KEWDALE. NOTE: BALANCE OF TOW EQUIVALENT	
			TO THAT FROM GERALDTON TO KEWDALE, AS VCM ONLY COVERS TOWING	
			TO CLOSEST REPAIRING DEALER (MT MAGNET TO TCWA GERALDTON).	
			AS DISCUSSED WITH ██████████	

2017-02-01 - Mileage: 493532 - Order nr: 200793

		96000		0
--	--	-------	--	---

2017-01-31 - Mileage: 498009 - Order nr: 2181999

PC	Type	Code	Description (Original)	#
	*	SHIFT	SHIFT : Volvo Day	
			DATE IN : 30/01/17 TIME IN : 16:15	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
			30,000 KLM INTERVAL.	
	*	3310	CHECK STARTER MOTOR SOLENOID SCREWS	
		VO-4658400	Differential carrier oil sample, take (o	0.2
		VO-2330600	Fuel filter, replace (one)	0.2
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2331100	Filter, water separator, replace	0.5
		VO-1707300	Service alert system, configuration and	0.4
		VO-2632300	Fan hub, replace	1.8
			Preventative maintenance.	
		VO-2601000	Coolant, change	0.7
			Preventative maintenance.	
		VO-3525100	Headlamp complete, replace (left hand si	0.9
		VO-FK18B	FILTER KIT	1
		VO-8394887	OIL TEST KIT	2
		AU2-CAL8394800	VOLVO VCS COOLANT	2
		AU2-CAL85108913	VOLVO VCS COOLANT 5 LITRE	1
		VO-22031832	FAN HUB	1
		VO-953053	FAN STUD	4
		VO-990950	M8 FLANGE LOCK NUT	4
		VO-8180100	Tilt cylinder, replace	1.4
		VO-3110200	Batteries, replace (all)	0.4
		VO-22070283	CYLINDER	1
		AU2-20935640	VOLVO MAINT N200	2

PC	Type	Code	Description (Original)	#
		VO-85115159	HYDRAULIC FLUID	2
		VO-21753149	IDLER PULLEY	1
		VO-2637500	Fan belt idler pulley, replace	0.5
		VO-6455200	Power steering pipe, replace	1.1
		VO-21177272	SOCKET	1
		VO-85122800	1L DEXRON3 ATF	2
		VO-84055742	LAMP	1
		VO-84055744	LAMP	1
		VO-85142067	MOUNTING KIT	2
			DATE OUT: 01/02/17 TIME OUT: 15:00	
			CONTACT PERSON :	
			CONTACT NUMBER :	
			W70018 - VCR HELD BY SITE.	
			as requested by customer.	
		93	42 LTS ENGINE OIL	
		VO-3525200	Headlamp complete, replace (right hand s	0.9
		VO-3520000	Lighting, front. Secondary operation num	0.5
		VO-8102500	Hydraulic oil, cab tilt system, bleeder	0.4
		VO-3116800	Battery system, test. Battery tester	0.4
		VO-1820200	Localised wash for fault tracing	0.3
		VO-3200200	Charging test, in vehicle	0.4

2017-01-23 - Mileage: 493531 - Order nr: 7713326

		DETAILS	DETAILS	
			CONTACT PERSON:	
			ENG HRS: ECM KM:	
			FUEL BURN: VEH KM:	
			ENG REVOLUTION:	
			PROPOSED PICK UP DATE & TIME:	

PC	Type	Code	Description (Original)	#
	📄		CONTACT NUMBER: 0467 978 360	
🌐	*	BREAKDOWN	BREAKDOWN	
	📄		OFFSITE WORK	
	📄		DESTINATION: 720 KM South of Port Hedland	
	📄		AFTER HOURS: YES	
	📄		CALL OUT TIME 4:00am	
	📄		DATE 23/01/17	
	📄		CONTACT ON SITE IS: Jason	
	📄		CONTACT OFF SITE IS: Iain	
🌐	🕒	LO-194	TRAVELLING TIME	18
🌐	*	92	TRAVEL 1450 KM @ 0.98CTS PER KM	
🌐	🕒	VO-2620200	Coolant pump, replace	1.4
🌐	🔧	VO-85142305	WATER PUMP UNIT	1
🌐	🔧	AU2-CAL8394800	VOLVO VCS COOLANT	1
🌐	🕒	VO-2600600	Cooling system, pressure test	0.4
🔍 🌐 2017-01-01 - Mileage: 469153 - Order nr: 200793				
🌐	🕒	96000		0
🔍 2016-12-23 - Mileage: 472061 - Order nr: 2181191				
🌐	*	SHIFT	SHIFT : VOLVO DAY	
	📄		DATE IN : 23.12.2016 TIME IN : 15.40	
📄	🕒	LO-645	OIL LEAK FROM POWER STEERING PUMP	2.58
📄	🔧	VO-977030	O-RING	1
	📄		VO/977030 WAS FITTED BY BRANCH 1	
	📄		.- ON REPAIR ORDER 2171689 - DATE 2016-01-27 MILEAGE - 241353	
📄	🔧	VO-982724	STRG PUMP WASHER	2
📄	🔧	VO-20852764	GASKET	4
📄	🔧	VO-20852765	GASKET	4
📄	🔧	VO-85122800	1L DEXRON3 ATF	2

PC	Type	Code	Description (Original)	#
		LO-9000	DROP TRUCK BACK TO LINFOX YARD	0.64
			DROPPED TRUCK BACK TO LINFOX YARD.	
			CONTACT PERSON : ████████	
			CONTACT NUMBER : ██████████	
			W70014.	
			REWORK ON 2025, PUMP REPLACED ON 21.10.2016 Ö 421386 KLMS.	
			RO 2179568. WHEN THE PUMP WAS FITTED DIRT AND A SMALL STONE	
			WERE CAUGHT IN THE SEAL, THE SEAL SPLIT AND PUMP HOUSING/	
			SANDWHICH PLATE SCORED.	

2016-12-19 - Mileage: 469152 - Order nr: 2181041

		SHIFT	SHIFT : VOLVO DAY	
			DATE IN : 19/12/16 TIME IN : 08:30	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
			30,000 KLM INTERVAL.	
		VO-4658400	Differential carrier oil sample, take (o	0.2
		LO-3540800	Interior lights, cable harness, install	0.5
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2549400	ACM, SW, update. only campaign	0.2
		VO-2330600	Fuel filter, replace (one)	0.4
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2331100	Filter, water separator, replace	0.5
		VO-1707300	Service alert system, configuration and	0.4
		VO-FK18B	FILTER KIT	1
		VO-22935545	WIRES	8
		VO-8394887	OIL TEST KIT	2
		VO-2562400	Filter insert, air cleaner, replace. Onl	0.5

PC	Type	Code	Description (Original)	#
		VO-2560000	Air cleaner and throttle housing. Second	0.2
		VO-21716424	AIR FILTER	1
		VO-993240	HOSE CLAMP	1
		VO-979972	SCREW	2
		LO-9000	DROP TRUCK BACK TO LINFOX YARD	0.5
			DROPPED TRUCK BACK TO LINFOX YARD.	
			CONTACT PERSON : JASON	
			CONTACT NUMBER : 0428 913 574	
			W70013.	
			as requested by customer.	
			C3628 Cab, interior lights, cable harness, install. FH (4)	
			S3652 ACM, SW update. FH/FM (4)	
		93	42 LTS ENGINE OIL & 1 KG GREASE	

2016-12-08 - Mileage: 460714 - Order nr: 2180790

		SHIFT	SHIFT : VOLVO DAY	
			DATE IN : 8/12/16 TIME IN : 11:33	
		VO-6452600	Hydraulic hose power steering, replace	1
		VO-22260491	HOSE ASSEMBLY	1
		VO-22339790	SERVO PIPE	1
		VO-21380475	FUEL FILTER	1
		VO-21879886	FUEL FILTER	1
		VO-85122800	1L DEXRON3 ATF	2
			DATE OUT: 8/12/16 TIME OUT: 14:30	
			CONTACT PERSON : XXXXXXXXXX	
			CONTACT NUMBER XXXXXXXXXX	
			W70010.	
		VO-6455200	Power steering pipe, replace	1.1
		VO-2331100	Filter, water separator, replace	0.5

PC	Type	Code	Description (Original)	#
		VO-2330600	Fuel filter, replace (one)	0.4
2016-12-01 - Mileage: 438676 - Order nr: 200793				
		96000		0
2016-11-24 - Mileage: 447283 - Order nr: 2180414				
	*	SHIFT	SHIFT : VOLVO DAY	
			CONTACT PERSON : XXXXXXXXXX	
		VO-3668400	LKS (Lane Keeping System), calibration	2.15
			CONTACT NUMBER XXXXXXXXXX	
2016-11-14 - Mileage: 438675 - Order nr: 2180131				
	*	SHIFT	SHIFT : VOLVO DAY	
			DATE IN : 14/11/16 TIME IN : 09:42	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	1
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
			30,000 KLM INTERVAL.	
		VO-1756100	Final drive with hub reduction, oil chan	0.8
			SYNTRAX UNIVERSAL.	
		VO-2141300	Valves and unit injectors, adjust	1.7
		VO-2373200	Yoke, injector, check. Valve cover remov	0.4
		VO-4658400	Differential carrier oil sample, take (o	0.2
		VO-2330600	Fuel filter, replace (one)	0.4
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2331100	Filter, water separator, replace	0.5
		VO-5616600	Air drier cassette, replace	0.3
		VO-1707300	Service alert system, configuration and	0.4
		VO-2200400	Engine oil sample, take	0.2
		VO-8394887	OIL TEST KIT	2
		VO-FK18B	FILTER KIT	1

PC	Type	Code	Description (Original)	#
		VO-22223804	KIT	1
		MK-9727-3373869	SYNTRAX UNIV PLUS - 20L	2
		MK-9727-3377738	SYNTRAX UNIV PLUS - 1L	10
		LO-9000	DROP TRUCK BACK TO LINFOX YARD	1
		VO-8394887	OIL TEST KIT	1
			CONTACT PERSON :	
			CONTACT NUMBER :	
			W131131	
		93	42 LTS ENGINE OIL & 1 KG GREASE	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-5619800	Air Drier, calibration	0.2
			as requested by customer.	

2016-11-01 - Mileage: 421387 - Order nr: 200793

		96000		0
--	--	-------	--	---

2016-10-27 - Mileage: 423778 - Order nr: 2179673

		SHIFT	SHIFT :DAY	
			CONTACT PERSON :	
		92	TRAVEL 50 KM Ö Å0.98CTS PER KM	
			LINFOX YARD. RETURN.	
		VO-3310600	Starter motor, replace	0.4
		VO-85020793	STARTER MOTOR, EXC	1
			ser M009T663712X V47529	
		VO-21484099	SERVO PIPE	1
		VO-21349444	SOCKET	1
		VO-85122800	1L DEXRON3 ATF	2
		VO-6455200	Power steering pipe, replace	1.1
			CONTACT NUMBER :	
		LO-194	TRAVELLING TIME	0.6

PC	Type	Code	Description (Original)	#
		VO-1820200	Localised wash for fault tracing	0.3
		VO-3710200	Electric wires and connections, check	0.4
		VO-3116800	Battery system, test. Battery tester	0.4
		VO-3200200	Charging test, in vehicle	0.4

2016-10-24 - Mileage: 421386 - Order nr: 2179568

		SHIFT	SHIFT : VOLVO DAY	
			DATE IN : 24/10/16 TIME IN : 08.56	
		VO-6450800	Servo pump, replace	2.2
		VO-21488833	STEERING PUMP	1
		VO-85103703	O-RING	1
		VO-977030	O-RING	1
		VO-20367040	LÉNUT P/STEER	1
		VO-2582800	Combined tank unit, replace. AdBlue tank	0.2
		VO-982724	STRG PUMP WASHER	2
		VO-21349444	SOCKET	1
		LO-9000	DROP TRUCK BACK TO LINFOX YARD	0.5
		OTH-AB15	ADBLUE 15L	3
		VO-22406383	KIT	1
			TRUCK DROPPED BACK TO LINFOX YARD.	
			CONTACT PERSON :	
			CONTACT	
			W70005	
			PUMP & FILTER REPLACED ON RO 2179509.	
		VO-2580400	AdBlue tank, remove	0.8
		VO-2585800	AdBlue tank, clean. Urea tank removed	0.6
		VO-2580500	AdBlue tank, install	0.7
		VO-2580000	Emissions after-treatment. Secondary ope	0.4
			*MODIFICATION PREVIOUSLY CARRIED OUT ON RO 2172779.	

PC	Type	Code	Description (Original)	#
	📅		*08.02.2016 AT 247043 KLMS.	
Ⓞ	*	10	45 LTS ADBLUE	
	📅		VO/22406383 WAS FITTED BY BRANCH 1	
	📅		.- ON REPAIR ORDER 2172779 - DATE 2016-02-23 MILEAGE - 247043	
	📅		NEW UNIT SN:	
	📅		21488833	
	📅		012416 06-16	
	📅		7684955626	
Ⓞ	🔧	VO-1820200	Localised wash for fault tracing	0.3
🔍 Ⓞ 2016-10-20 - Mileage: 418964 - Order nr: 2179509				
Ⓢ	*	SHIFT	SHIFT : WEEKEND	
	📅		DATE IN : 20/10/16 TIME IN : 18:14	
Ⓞ	🔧	VO-2580700	Pump unit, replace	0.8
Ⓢ	🔧	LO-9000	DROP TRUCK BACK TO LINFOX YARD	0.5
Ⓞ	🔧	VO-5930000	Anti-lock brake (anti-skid). Secondary o	0.5
Ⓞ	🔧	VO-21574975	PUMP UNIT FH4	1
Ⓞ	🔧	VO-21574984	DOSAGE VALVE	1
Ⓞ	🔧	VO-2341300	Filler cap, replace	0.1
Ⓞ	🔧	VO-22335631	FILLER CAP	1
	📅		DATE OUT: 20/10/16 TIME OUT: 23:59	
	📅		CONTACT PERSON : ██████████	
	📅		CONTACT NUMBER : ██████████	
	📅		W70004.	
Ⓞ	🔧	VO-1701000	Connect-disconnect of diagnostic tool	0.2
Ⓞ	🔧	VO-1701200	Fault codes, reading	0.2
Ⓞ	🔧	VO-1790600	Diagnostic with Tech Tool/GD. Only valid	0.5
Ⓞ	🔧	VO-2584600	SCR system, test	0.5
Ⓞ	🔧	VO-2580000	Emissions after-treatment. Secondary ope	1

PC	Type	Code	Description (Original)	#
		VO-2581100	Dosage unit, replace	0.5
			NEW UNIT SN: 36916.	
			444 042 028-LW.	
		VO-3973300	Telematics system, SIM ID, calibration	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-2500500	Response, test drive	0.4
		VO-1790600	Diagnostic with Tech Tool/GD. Only valid	0.5

2016-10-11 - Mileage: 412873 - Order nr: 2179183

		SHIFT	SHIFT : VOLVO DAY	
			DATE IN : 11/10/16 TIME IN : 08.30	
		VO-4661800	Drive axle, overhaul (one axle). Campaig	4.9
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-3982500	TGW2, SW update (incl. Campaign only. Ca	0.8
		VO-6452600	Hydraulic hose power steering, replace	1
		VO-8182000	Cab shock absorber rear, replace (one)	0.4
		258	ADBLUE LEAK AT TANK - CHECK	
		430	GEARBOX HOSE RUBBING ON COOLER - CHECK	
		VO-22128971	SHOCK ABSORBER	1
		VO-984800	NIPPLE	1
		VO-85122800	1L DEXRON3 ATF	2
		VO-3191862	DRIVE SHAFT, L.H.	1
		VO-3191863	DRIVE SHAFT, R.H.	1
		VO-3191860	DRIVE SHAFT, L.H.	1
		VO-3191861	DRIVE SHAFT, R.H.	1
		VO-1522373	HUB/RED INNER SEAL	4
		VO-21036050	BEARING	2
		VO-3192819	HUB/RED END COVER	4

PC	Type	Code	Description (Original)	#
		VO-982108	O-RING	2
		VO-955891	WASHER	4
		VO-21912834	KIT	2
		VO-21496550	BRAKE PAD KIT	1
		VO-949329	COPPER WASHER	8
		MK-9727-3377738	SYNTRAX UNIV PLUS - 1L	15
		LO-170	DROP TRUCK BACK TO LINFOX YARD	0.5
			TRUCK DROPPED BACK TO LINFOX YARD.	
			CONTACT PERSON : ██████████	
			CONTACT NUMBER : ██████████	
			W129578.	
		VO-5132100	Brake pads, replace. Wheels removed	0.9
			S3570 Hub reduction, drive axle shaft, replace. FH/FH (4)	
			S3549 TGW2 (not communicating), SW update. FH/FM (4)	
		VO-1820200	Localised wash for fault tracing	0.3
		4660000	SYNTRAX OIL REQUIRED FOR CAMPAIGN S3570	

2016-10-03 - Mileage: 407253 - Order nr: 2178973

		SHIFT	SHIFT : DAY / NIGHT	
			ENG HRS : 5780. FUEL BURN: 324063.	
		VO-1774600	Annual service. Chassis lubrication and	2.4
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2330300	Fuel filter, replace (one)	0.6
		VO-2331100	Filter, water separator, replace	0.5
		VO-1707300	Service alert system, configuration and	0.4
		93	42 LTS ENGINE OIL & 2 KGS GREASE	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement	
		331	CHECK STARTER MOTOR SOLENOID SCREWS	

PC	Type	Code	Description (Original)	#
		VO-2341400	Filter for fuel tank ventilation, replac	0.1
		VO-7714500	Wheel nuts, check tightening (all)	0.3
		VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
		VO-1706600	24 Months ECU download and oil sample. O	0.9
		VO-8100500	24 Months cab inspection	0.4
	*	6010000	WHEEL ALIGNMENT	
	*	60	SUBLET - CARRY OUT WHEEL ALIGNMENT	
		VO-2582200	Filter, AdBlue, replace	0.2
		VO-FK18B	FILTER KIT	1
		VO-82354791	VENTILATION FILTER	1
		VO-21743197	AIR CLEANER	2
		VO-20779040	G/BOX OIL FILTER KIT	1
		VO-8394887	OIL TEST KIT	4
		OTH-85131754L	GEAR OIL SYNTH 1 LITER SHC50	16
		VO-21516229	FILTER	1
		LO-810	RESECURE DRIVERS CAM ON WINDOW	0.7
			DATE IN : 03/10/16 TIME IN : 08:00 AM	
			DATE OUT: 04/10/16 TIME OUT: 17:00 PM	
			W70002.	
			as requested by customer.	
			*BIG WHEELS TRUCK ALIGNMENT, INVOICE 19844. 04.10.2016.	
			Clean off old tape. Fit new double sided tape and secure	
			the drivers cam to the window. All OK.	

2016-10-01 - Mileage: 376312 - Order nr: 200793

		96000		0
--	--	-------	--	---

2016-09-01 - Mileage: 376311 - Order nr: 200793

		96000		0
--	--	-------	--	---

2016-08-29 - Mileage: 380073 - Order nr: 2178068

PC	Type	Code	Description (Original)	#
Ⓡ	*	SHIFT	SHIFT : VOLVO BREAKDOWN	
	📄		ENG HRS: 5412. FUEL BURN: 303918.	
Ⓡ	*	258	SUPPLY NEW ADBLUE CAP	
	📄		CUSTOMER REQUEST.	
Ⓡ	🔧	LO-3000	RECTIFY NON-START FAULT - E-STOP	10
Ⓡ	🔧	VO-21584844	FILLER CAP	1
Ⓡ	🔧	UNK-P53682	E STOP SWITCH	1
Ⓡ	🔧	LO-194	TRAVELLING TIME	0.5
	📄		Reports fault code b100092 on dash and saying impossible to	
	📄		CONTACT PERSON : ██████████	
	📄		CONTACT NUMBER : ██████████	
	📄		start also had gear selection fault flash on but no codes.	
	📄		Travel to truck. No start and "start prohibited - input	
	📄		from chassis" warning on dash. Connect laptop and check	
	📄		codes - none. Remove dash panels and inspect BBM - found	
	📄		+ feed on B1:17. Remove centre of dash and follow wiring	
	📄		to relay (aftermarket). Create diagram and found earth	
	📄		trigger to switch relay active. Remove earth wire - truck	
	📄		now starting and runs OK. Remove top of dash and follow	
	📄		earth wires through dash to firewall outside of truck.	
	📄		Follow wiring through chassis to junction box on rear of	
	📄		truck, wire spliced into 2x other wires. Followed those	
	📄		wires to LH and RH E-STOPS. Test - stil faulting. Noticed	
	📄		wiring harness rubbing on metal boost pipe from turbo.	
	📄		Opened and inspected wiring - OK. Re-sealed and tested E-	
	📄		STOPS - truck isolated OK. Truck no longer faulting and	
	📄		starting everytime. Uncable tie E-STOP wiring and inspect	
	📄		- OK. Pull wire through conduit - OK. Refit and tied up	

PC	Type	Code	Description (Original)	#
	🔍		harnesses. Test E-STOP resistance - OK. Suspect E-STOP	
	🔍		contacts sticking. R&R both E-STOP contacts. Test operation	
	🔍		- all OK. Road test - OK. Check over again - all OK.	
🟢	*	91	CONSUMABLES	

🔍 📄 **2016-08-22 - Mileage: 376310 - Order nr: 2177849**

🟢	*	SHIFT	SHIFT : VOLVO DAY	
	🔍		ENG HRS: 5355. FUEL BURN: 301630.	
🟢	🟡	LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
	🔍		For Volvo vehicles under Service Agreement	
🟢	🟡	VO-1774400	Basic service. Chassis lubrication and o	1.3
	🔍		30,000 KLM INTERVAL.	
🟡	*	3310	CHECK STARTER MOTOR SOLENOID SCREWS	
🟢	🟡	VO-4658400	Differential carrier oil sample, take (o	0.2
🟢	🟡	VO-2330600	Fuel filter, replace (one)	0.4
🟢	🟡	VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
🟢	🟡	VO-2331100	Filter, water separator, replace	0.5
🟢	🟡	VO-1707300	Service alert system, configuration and	0.4
🟢	🟡	LO-258	ADBLUE GAUGE READING FULL ALL THE TIME	1.5
🟢	🟡	VO-FK18B	FILTER KIT	1
🟢	🟡	VO-8394887	OIL TEST KIT	2
🟢	🟡	VO-990037	H7 GLOBE L/L	1
	🔍		as requested by customer.	
🟢	🟡	VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
🟢	*	93	42 LTS ENGINE OIL & 1 KG GREASE	
	🔍		Remove adblue breather hoses and filter - both OK. Remove	
	🔍		adblue pick-up - found foreign debris had jammed the level	
	🔍		float at full level. Remove debris. Refit adblue pick-up.	
	🔍		Adblue gauge now reading correctly. Adblue level low.	

PC	Type	Code	Description (Original)	#
2016-08-01 - Mileage: 350950 - Order nr: 200793				
		96000		0
2016-07-21 - Mileage: 350949 - Order nr: 2177046				
	*	SHIFT	SHIFT :MARK	
			ENG HRS : 5032 FUEL BURN : 283288	
		VO-5619800	Air Drier, calibration	0.2
		LO-258	ADBLUE GAUGE STUCK ON FULL - CHECK	1.62
		LO-9000	DROP TRUCK BACK TO LINFOX YARD	0.5
			DATE IN : 21/07/16 TIME IN : 12:03	
			CONTACT PERSON : █████	
			CONTACT NUMBER : ██████████	
			W131118.	
			Inspect adblue gauge - not sitting on full. Remove tread	
			plate. Remove level sensor and pick-up. Move float - not	
			stuck. Move float up and down and check gauge - moving up	
			and down in relation to float position, all OK. Note in	
			truck stating adblue tank empty. Adblue tank is full.	
			Check adblue filler - no blockages. Reassemble. All OK.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
2016-07-13 - Mileage: 344818 - Order nr: 2176806				
	*	SHIFT	SHIFT : VOLVO DAY	
			ENG HRS: 4959 FUEL BURN: 278855	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
			30,000 KLM INTERVAL.	
		VO-1756100	Final drive with hub reduction, oil chan	0.8

PC	Type	Code	Description (Original)	#
		VO-2141300	Valves and unit injectors, adjust	1.7
		VO-2373200	Yoke, injector, check. Valve cover remov	0.4
	*	3310	STARTER MOTOR SOLENOID SCREWS - CHECK	
		VO-2330600	Fuel filter, replace (one)	0.4
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2331100	Filter, water separator, replace	0.5
		VO-4658400	Differential carrier oil sample, take (o	0.2
		VO-8394887	OIL TEST KIT	2
		VO-FK18B	FILTER KIT	1
		MK-9727-3373869	SYNTRAX UNIV PLUS - 20L	2
		MK-9727-3377738	SYNTRAX UNIV PLUS - 1L	5
		VO-2580000	Emissions after-treatment. Secondary ope	1
		VO-3213000	Belt tensioner, alternator, replace	0.5
		VO-20775507	HEX. SOCKET SCREW	12
		VO-21454379	BELT TENSIONER	1
		VO-21480006	FILLER NECK	1
			CONTACT PERSON : ██████	
			CONTACT NUMBER : ██████████	
			as requested by customer.	
		VO-1707300	Service alert system, configuration and	0.4
	*	93	42 LTS ENGINE OIL & 1 KG GREASE	

2016-07-06 - Mileage: 339148 - Order nr: 2176657

	*	SHIFT	SHIFT : DAY	
			ENG HRS : 4889 FUEL BURN: 275130	
		VO-2610800	Radiator, replace	2.5
		VO-22062259	RADIATOR (85013015 EXCH)	1
		VO-20840154	HOSE CLAMP	1
		VO-21112140	CONNECTOR	1

PC	Type	Code	Description (Original)	#
		LO-9000	DROP TRUCK BACK TO LINFOX YARD	0.5
			DATE IN : 06/07/16 TIME IN : 11:00 AM	
			DATE OUT: 06/07/16 TIME OUT : 17:00 PM	
			CONTACT PERSON : ██████████	
			CONTACT NUMBER : ██████████	
			VCR: W131113.	
			NEW UNIT SN 01391518.	
		VO-2600600	Cooling system, pressure test	0.4
  2016-07-01 - Mileage: 329497 - Order nr: 200793				
		96000		0
  2016-06-27 - Mileage: 337589 - Order nr: 2176585				
	*	SHIFT	SHIFT :	
			ENG HRS : 4863. FUEL BURN : 337589.	
	*	10	AIR BRAKE RELAY VALVE, BLOCKED - CLEAN	
	*	5630000	LOCKING UP WITH SERVICE BRAKE APPLIED	
			LINFOX NEWMAN, INVOICE LFX05. 15.07.2016.	
  2016-06-19 - Mileage: 329496 - Order nr: 2176203				
	*	SHIFT	SHIFT : VOLVO DAY	
			ENG HRS : 4721 FUEL BURN : 267575	
		VO-5930000	Anti-lock brake (anti-skid). Secondary o	0.5
			DATE IN : 19/9/16 TIME IN : 09:00	
			DATE OUT: 19/6/16 TIME OUT : 12:00	
			CONTACT PERSON : ██████████	
			W131109.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
  2016-06-01 - Mileage: 312976 - Order nr: 200793				
		96000		0

PC	Type	Code	Description (Original)	#
   2016-05-18 - Mileage: 312975 - Order nr: 2175357				
		SHIFT	SHIFT : VOLVO DAY	
			ENG HRS : 4470 FUEL BURN : 257008	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement	
		VO-1774400	Basic service. Chassis lubrication and o	1.3
		3110	STARTER MOTOR SOLENOID SCREWS - CHECK	
		VO-1706500	18 Months ECU download and oil sample. O	0.9
		93	42 LTS ENGINE OIL & 1 KG GREASE	
		LO-8600100	Cab tilt pump, check	0.5
			30,000 KLM SERVICE INTERVAL.	
		VO-22861085	REPAIR KIT	1
		VO-8394887	OIL TEST KIT	4
		LO-9000	DROP TRUCK BACK TO LINFOX YARD	0.5
			18/5/16 11:30PM.	
		VO-FK18B	FILTER KIT	1
		LO-818	CAB STOPPERS CRACKED/FALLEN OUT	1
		VO-2631300	Fan belt tensioner, replace	0.5
		VO-2571000	Separator, crankcase ventilation, replac	0.4
		LO-640	TRUCK PULLING TO THE LEFT - CHECK	1
		VO-2860000	Engine wires and mounting parts. Seconda	2
		VO-21631484	BELT TENSIONER	1
		VO-20741911	O-RING	1
		VO-21833916	BUMP STOP	1
		VO-21333686	BUMP STOP	1
		VO-983472	D12 LOOM TIE	10
			DATE IN : 18/5/16 TIME IN : 10:00AM	
			VCR: W129566.	

PC	Type	Code	Description (Original)	#
			as requested by customer.	
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2330600	Fuel filter, replace (one)	0.4
		VO-2331100	Filter, water separator, replace	0.5
		VO-1707300	Service alert system, configuration and	0.4
			Check starter motor screws. All OK.	
			Check all tyre pressures - all drive tyres too high.	
			Adjust all to 100 PSI.	
			C3538 Cab tilt pump, filler plug, replace. FH (4)	
		VO-21475236	SPARE PART KIT	1
2016-05-11 - Mileage: 297000 - Order nr: 200793				
		VO-LnBOUR RnTE DIFFEREuCE		1
2016-05-09 - Mileage: 303758 - Order nr: 2175036				
		SHIFT	SHIFT :DAY	
			ENG HRS : 4376 FUEL BURN : 251059	
		VO-5612600	Air drier, drier insert, replace	0.4
		VO-22223804	KIT	1
		VO-20531103	AIR FILTER	1
		VO-20733172	SILENCER	1
			DATE IN : 09/05/16 TIME IN : 10:15 AM	
			DATE OUT: 09/05/16 TIME OUT : 15:37 PM	
			CONTACT PERSON : JASON	
			CONTACT NUMBER : 0428 913 574	
		VO-5618200	Air drier, silencer, replace	0.1
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-5619800	Air Drier, calibration	0.2

PC	Type	Code	Description (Original)	#
		VO-1705400	Accessory kit, programming	0.1
2016-05-01 - Mileage: 296414 - Order nr: 200793				
		96000		0
2016-04-28 - Mileage: 296413 - Order nr: 2174861				
		SHIFT	SHIFT :DAY	
			ENG HRS : 4769 FUEL BURN: 245176	
		VO-2510400	Gaskets, exhaust manifold, replace	2.4
		VO-20784537	GASKET	1
		VO-420641	TURBO FEED GASKET	1
		VO-470993	TRBO RETURN GSK	1
		VO-20901584	EXHAUST MANIFOLD	2
		VO-21345127	STUD	4
		VO-1543499	FLANGE NUT	4
		VO-21352841	GASKET	6
		VO-20578932	EXHAUST MANIFOLD	1
		VO-21344787	FLANGE SCREW	24
		VO-469601	TURBO DRAIN SEAL	1
		VO-2840000	Control system, fuel supply. Secondary o	1
		VO-942400	CLAMP B 6020	2
		VO-965540	PIPE BRKT	1
		VO-990950	M8 FLANGE LOCK NUT	1
		VO-984735	M8*25 FL BOLT	1
		VO-85139619	PRESSURE SENSOR	1
		VO-21582423	PLUG KIT	1
		OTH-NZEBRKLG	EX-BACK PRESSURE RELOC KIT	1
		VO-994195	FLANGE SCREW	1
		VO-990941	FLANGE NUT	1
		VO-994441	M8*50 FLANGE SCREW	1

PC	Type	Code	Description (Original)	#
		VO-990950	M8 FLANGE LOCK NUT	1
			DATE IN : 28/4/16 TIME IN : 09:30 AM	
			DATE OUT: 29/4/16 TIME OUT : 04:25 PM	
			CONTACT PERSON : ██████████	
			CONTACT NUMBER : ██████████	
		VO-2850800	Exhaust back pressure sensor, replace	0.2
		VO-3711700	Connector, replace (1-8 cables)	0.3
		10	EX-BACK PRESSURE RELOCATION KIT	
		VO-2500600	Inlet and exhaust systems, check	0.2
2016-04-27 - Mileage: 0 - Order nr: 2174850				
		CARD	NOT REQUIRED	
2016-04-14 - Mileage: 284542 - Order nr: 2174521				
		SHIFT	SHIFT : VOLVO DAY	
			ENG HRS : 4111 FUEL BURN: 235562	
		VO-1700400	Fault codes, test mode	0.5
		VO-2592200	Filler cap, AdBlue, replace	0.1
		LO-170	DROP TRUCK BACK TO LINFOX YARD	0.5
		VO-21584844	FILLER CAP	1
			DATE IN : 14/4/16 TIME IN : 08:00PM	
			DATE OUT: 14/4/16 TIME OUT : 23:00PM dropped back	
			CONTACT PERSON : ██████████	
			CONTACT NUMBER : ██████████	
			Connect laptop and read fault codes - no code for crane.	
			Clear fault codes.	
2016-04-14 - Mileage: 241353 - Order nr: 4510042				
		SHIFT	SHIFT : DAY	
			ENG HRS: 3503 FUEL BURN: 205575	
		20	SUBLET - MACHINE FLYWHEEL HOUSING	

PC	Type	Code	Description (Original)	#
	📄		CONTACT PERSON : ██████	
	📄		████████████████████	
	📄		CREDITING OF SUBLET COSTS FOR FLYWHEEL MACHINING FROM	
	📄		ORIGINAL RO 2171689/UHP CLAIM 139398-06/KG.	
	📄		COSTS TO BE RECHARGED TO VCM - OUTSIDE 12 MONTHS WARRANTY.	

  **2016-04-14 - Mileage: 241353 - Order nr: 2174553**

🌱	*	SHIFT	SHIFT : DAY	
	📄		ENG HRS: 3503 FUEL BURN: 205575	
🌱	*	20	SUBLET - MACHINE FLYWHEEL HOUSING	
	📄		CONTACT PERSON : JASON	
	📄		CONTACT NUMBER : 0428 913 574	
	📄		CREDITING OF SUBLET COSTS FOR FLYWHEEL MACHINING FROM	
	📄		ORIGINAL RO 2171689/UHP CLAIM 139398-06/KG.	
	📄		COSTS TO BE RECHARGED TO VCM - OUTSIDE 12 MONTHS WARRANTY.	
🌱	*	2120000	Cylinder block. Secondary operation	

  **2016-04-01 - Mileage: 252115 - Order nr: 200793**

🌱	🕒	96000		0
---	---	-------	--	---

  **2016-03-10 - Mileage: 280170 - Order nr: 2173654**

🌱	*	SHIFT	SHIFT :DAY	
	📄		ENG HRS : 4071 FUEL BURN: 233364	
🌱	🕒	VO-3645000	Cab lock contact, replace	0.4
🌱	🕒	LO-9000	DROP TRUCK BACK TO LINFOX YARD	0.5
🌱	📄	VO-3197873	CONTACT-CLOSED	1
🌱	🕒	VO-2341600	Fuel line, replace (one)	0.7
🌱	🕒	LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
	📄		For Volvo vehicles under Service Agreement	
🌱	🕒	VO-1774400	Basic service. Chassis lubrication and o	1.3
	📄		30,000 KLM SERVICE.	

PC	Type	Code	Description (Original)	#
	*	93	ENGINE OIL & GREASE	
		LO-1100	100 HOUR ICEPAK SERVICE	1
			CURRENT HOURS = 275.	
		VO-4658400	Differential carrier oil sample, take (o	0.2
	*	3300	STARTER MOTOR SOLENOID SCREWS - CHECK	
		VO-20737938	INTER CONNECT PIPE	1
		VO-FK18B	FILTER KIT	1
		VO-8394887	OIL TEST KIT	2
		CU-AF25221	AIR FILTER	1
		CU-FS1251	F/W/SEP (REPS FS1226)	1
		CU-LF3614	LUBE FILTER	1
		OTH-3380346L	RX MONO DD40 PER LITRE	1.5
		VO-20428158	CABLE TIE	6
			DATE IN : 08/4/16 TIME IN : 03:30PM	
			DATE OUT: 11/4/16 TIME OUT : 12:40PM	
			CONTACT PERSON : JASON	
			CONTACT NUMBER : 0428 913 574	
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
		VO-2330600	Fuel filter, replace (one)	0.4
		VO-2331100	Filter, water separator, replace	0.5
		VO-1707300	Service alert system, configuration and	0.4
			as requested by customer.	
		VO-3710200	Electric wires and connections, check	0.4
2016-03-01 - Mileage: 252114 - Order nr: 200793				
		96000		0
2016-02-17 - Mileage: 0 - Order nr: 2173054				
	*	CARD	NOT REQUIRED	
2016-02-16 - Mileage: 252113 - Order nr: 2172983				

PC	Type	Code	Description (Original)	#
	*	SHIFT	SHIFT : DAY	
			ENG HRS : 3706 FUEL BURN: 1324	
		VO-2341600	Fuel line, replace (one)	0.7
		VO-8461100	Wide view mirror glass, replace	0.5
		LO-820	ALLOY WATER TANK LEAKING	1
		VO-82356824	GLASS	1
			DATE IN : 16/2/16 TIME IN : 08:15 AM	
			DATE OUT: 16/2/16 TIME OUT : 17:57 PM	
			CONTACT PERSON : XXXXXXXXXX	
			CONTACT NUMBER : XXXXXXXXXX	
			Remove alloy water tank and seal up the cracked with	
			sealant, temp repair. Refit alloy water tank to truck.	
			R&R cracked RH spot mirror with new. All OK.	
	*	91	CONSUMABLES	
2016-02-16 - Mileage: 0 - Order nr: 2172985				
		LO-812	Carry out windscreen calibration after	2
			replacement	
			Performed calibration of LKS, adjusted camera & completed	
			road testing - all ok.	
2016-02-09 - Mileage: 247043 - Order nr: 2172779				
	*	SHIFT	SHIFT :DAY	
			ENG HRS : 3635 FUEL BURN: 212022	
		VO-8746800	High pressure hose, replace	2.6
	*	170	RESET SERVICE REMINDER	
			CHECK SERVICE REMINDER - ALREADY OFF.	
	*	2580000	SCR/Adblue system general operation	
		VO-85003294	FAN EXCH	1
		VO-953053	FAN STUD	4

PC	Type	Code	Description (Original)	#
		VO-990950	M8 FLANGE LOCK NUT	4
		VO-3979639	PRE HEAT GSK	2
		VO-21887528	ACTUATOR SERVICE K	1
		VO-82422923	ACCUMULATOR	1
		3310000	STARTER MOTOR SCREWS LOOSE - CHECK	
		VO-995680	HOSE CLAMP	2
		VO-992085	HOSE CLAMP (980131)	1
		VO-2555300	Actuator, check and adjust. waste gate	0.2
		VO-22406383	KIT	1
		AU2-CUMCC36059	ADBLUE 20LTR	2
		VO-21280355	CONNECTOR	1
		VO-2611800	Expansion tank, replace	0.9
			DATE IN : 08/9/16 TIME IN : 11:09AM	
			DATE OUT: 09/2/16 TIME OUT : 12:00AM DROPPED OFF.	
			CONTACT PERSON : JASON	
			CONTACT NUMBER : 0428 913 574	
		VO-2630600	Thermostat fan, replace	1.8
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-2632500	Engine cooling fan, test	0.2
		VO-2531400	Control cylinder exhaust brake, replace	0.6
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-2584600	SCR system, test	0.5
		VO-8741400	Cooling unit, performance test	0.3
		VO-2580400	AdBlue tank, remove	0.8
		VO-2580500	AdBlue tank, install	0.7

PC	Type	Code	Description (Original)	#
		VO-2585800	AdBlue tank, clean. Urea tank removed	0.7
		VO-2580000	Emissions after-treatment. Secondary ope	0.8
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-2582800	Combined tank unit, replace. AdBlue tank	0.2
		97	AIR COND. GAS	
		VO-84180960	HOSE	1
			AUTHORITY NUMBER: 200403472.	
			Tighten up loose starter screws.	
2016-02-01 - Mileage: 241354 - Order nr: 200793				
		96000		0
2016-01-12 - Mileage: 241353 - Order nr: 2172240				
		VO-3664500	Lane position camera, calibration	2
			CONNECT LAPTOP AND CALLIBRATE LKS SYSTEM FOR NEW WINDSCREEN.	
			TEST OPERATION ALL OK.	
2016-01-01 - Mileage: 219098 - Order nr: 200793				
		96000		0
2015-12-28 - Mileage: 241353 - Order nr: 2171689				
		SHIFT	SHIFT : DAY	
			ENG HRS: 3503 FUEL BURN: 205575	
		LO-17ALINF	LINFOX ACCREDITATION INSPECTION	0.5
			For Volvo vehicles under Service Agreement.	
		VO-1706400	12 Months ECU download and oil sample. O	0.9
		VO-8100300	12 Months cab inspection	0.5
		VO-1774600	Annual service. Chassis lubrication and	2.6
		VO-1752300	Gearbox oil and filter, replace. Lube ar	0.5
		VO-2141300	Valves and unit injectors, adjust	1.8

PC	Type	Code	Description (Original)	#
W	W	VO-2580000	Emissions after-treatment. Secondary ope	1.5
W	W	VO-2583200	Aftertreatment diesel exhaust fluid (DEF	0.2
W	W	VO-3520000	Lighting, front. Secondary operation num	1
R	W	LO-1100	100 HOUR ICEPAK SERVICE	1.5
	E		RECORD ENGINE HOURS ON R.O.	
R	W	LO-9000	RUBBER CAT WALK LUG - REPLACE	1.5
W	R	VO-20823440	FH DOOR RUBBER STOP	1
W	R	VO-3944785	BREATHER FILTER	1
I	R	OTH-FITTINGSCR	FITTING SCR STAINLESS STEEL	1
W	R	VO-20915849	HOSE CLAMP	2
W	R	VO-21429181	HOSE (urea)	3
I	R	OTH-QNC16	NYLON CONDUIT 16MM OD	3
W	R	VO-21032572	CLAMP,UREA HOSE	2
R	R	VO-8394348	RUBBER CATCH KIT	1
W	R	VO-21480006	FILLER NECK	1
W	W	VO-7736300	Rear wheel bearing and seal, replace	4
C	R	VO-FK18B	FILTER KIT	1
W	R	VO-8394887	OIL TEST KIT	4
C	R	VO-20779040	G/BOX OIL FILTER KIT	1
C	R	OTH-85131754L	GEAR OIL SYNTH 1 LITER SHC50	16
R	R	MK-9424-AF25221	ICEPACK A/FILTER	1
R	R	MK-9424-FS1251	ICEPACK FUEL/WAT SEPARATOR	1
R	R	MK-9424-LF3614	ICEPACK LUBE FILTER	1
R	R	OTH-3380346L	RX MONO DD40 PER LITRE	1.5
C	*	40	SUBLET - URGENT DIFF SAMPLES	
W	W	VO-2120600	Timing gear plate, replace. Timing gears	0.9
C	W	VO-2562500	Secondary air filter, replace. Air filte	0.2
W	W	VO-8820000	Interior equipment	0.5

PC	Type	Code	Description (Original)	#
		VO-21415409	ROCKER ARM	6
		VO-21716424	AIR FILTER	1
		VO-20411816	FH INNER FILTER	1
		MK-NARV84051BL	REFLECTOR 1=2PK	2
		VO-21506181	COURTESY HANDLE	1
		VO-22206111	TIMING GEAR PLATE	1
		VO-21557105	TIMING GEAR COVER	1
		VO-20815558	SEALING STRIP	1
		VO-994447	FLANGE SCREW	25
		VO-22081685	IDLER GEAR	1
		VO-20483919	HEX. SOCKET SCREW	6
		VO-21015266	SCREW	6
		VO-992065	O-RING	1
		VO-471708	SEALING RING	1
		VO-977030	O-RING	1
		VO-3092340	SEALANT (GREY)	1
		VO-20734156	SEALING STRIP	1
		VO-20736230	D16C R/C GKT	1
		VO-85020472	CLUTCH CYLINDER, (22429963)	1
		VO-949656	O-RING 19MM ID	1
		20	SUBLET - MACHINE FLYWHEEL HOUSING	
		VO-943177	O-RING	1
		VO-20775507	HEX. SOCKET SCREW	12
		VO-1677370	VEB SEAL	2
		VO-20526428	VEB SEAL	1
		VO-20775471	SPACER SLEEVE	1
		VO-2580500	AdBlue tank, install	0.7
		VO-2580400	AdBlue tank, remove	0.9

PC	Type	Code	Description (Original)	#
		VO-4653100	Differential carrier, first rear axle, o	11.2
		VO-4653200	Differential carrier, second rear axle,	8.7
		VO-21036050	BEARING	2
		VO-982108	O-RING	2
		VO-21940434	SEALING RING	2
		VO-21912834	KIT	2
		LO-9000	SWAP OVER REGO PLATES	0.25
		VO-1522345	DIFF GEAR NEEDL	324
		VO-1522347	THRUST WASHER	4
		VO-1524058	ROLLER BEARING	1
		VO-1524716	THRUST WASHER	6
		VO-1524857	ROLLER BEARING	1
		VO-1524881	RT NEEDLE BEARING	1
		VO-181632	BEARING EV87	1
		VO-184623	DIFF.ROLL BRG.	1
		VO-20565923	THRUST WASHER	4
		VO-20907634	DEFLECTOR	1
		VO-21448461	LIP SEAL	1
		VO-21793022	THRUST WASHER KIT	1
		VO-3192160	RT F/COVER GKT	1
		VO-8171334	PINION NUT	1
		VO-8171338	DIFF INPUT NUT	1
		VO-1522345	DIFF GEAR NEEDL	140
		VO-1522347	THRUST WASHER	4
		VO-1524716	THRUST WASHER	6
		VO-1524857	ROLLER BEARING	1
		VO-1524926	ROLLER BEARING	1
		VO-1673537	PINION BEARING	1

PC	Type	Code	Description (Original)	#
		VO-184623	DIFF.ROLL BRG.	1
		VO-20907634	DEFLECTOR	1
		VO-21448461	LIP SEAL	1
		VO-8171338	DIFF INPUT NUT	1
		VO-85108352	CRANKSHAFT SEAL	1
		VO-1652986	SPIGOT BEARING	1
		VO-8192804	SCREW	8
		VO-20852765	GASKET	4
		VO-85122800	1L DEXRON3 ATF	2
		VO-471708	SEALING RING	1
		VO-21532261	SEALING RING	1
		VO-20545485	DIFF LOCK DIAPHRAGM	1
		VO-1524931	SPACER SLEEVE	1
		VO-1523236	SPACER SLEEVE	1
		VO-1523232	SPACER SLEEVE	1
		VO-3092340	SEALANT (GREY)	1
		VO-1672273	BOLT,PROPSHAFT	16
		VO-990971	NUT,PROPSHAFT	16
		VO-1524838	RT THRU/SHAFT SEAL	1
		VO-1673393	NUT RT2610HV	1
		VO-981281	DRAIN PLUG,MAGNETIC	1
		VO-949329	COPPER WASHER	8
		OTH-CAL85136280L	SYNTH DIFF OIL(97312)PER LITRE	45
		VO-20870049	BOWL	1
		VO-1161963	RUBBER GREASE	1
		VO-3816800	Instrument complete, replace	0.6
		VO-22038172	INSTRUMENT CLUSTER	1
		VO-3815800	IC, SW update. Campaign only	0.3

PC	Type	Code	Description (Original)	#
		VO-84195505	TAIL LAMP CLUSTER	1
		LO-350	REAR TAIL LIGHT, BROKEN - REPLACE	0.75
		VO-21271982	SENSOR	1
		VO-3110200	Batteries, replace (all)	0.4
		AU2-20935640	VOLVO MAINT N200	2
		640	STEERING WHEEL NOT STRAIGHT - ADJUST	
			CONTACT PERSON : JASON	
			CONTACT NUMBER : 0428 913 574	
		1770000	ANNUAL SERVICE - OILS/FILTERS	
		93	42 LTS ENGINE OIL & 1 KG GREASE	
		VO-7714500	Wheel nuts, check tightening (all)	0.3
		VO-1707300	Service alert system, configuration and	0.4
		VO-2373200	Yoke, injector, check. Valve cover remov	0.4
		10	FITTING SCR STAINLESS STEEL	
		10	NYLON CONDUIT 16MM OD	
		VO-3525100	Headlamp complete, replace (left hand si	1.1
		VO-3525200	Headlamp complete, replace (right hand s	1.1
			Inspect cat walk retainer lugs - front LH rubber catch	
			missing. Install new rubber catch. All others OK.	
		VO-2157300	Sealant, timing gear casing and flywheel	6.7
		VO-2153100	Timing gears, replace (all). Casing and	1.4
		VO-2123500	Flywheel housing run-out, check. Clutch	0.4
		VO-2563000	Air filter housing, remove	0.2
		VO-2565100	Air filter housing, install	0.4
		VO-4110100	Clutch, replace	2.7
		VO-2162100	Flywheel, replace. Gearbox and clutch re	0.7
		VO-2170600	Oil sump, remove	0.3
		VO-2170800	Oil sump, install	0.7

PC	Type	Code	Description (Original)	#
		VO-1820200	Localised wash for fault tracing	0.3
		2150000	STEERING PUMP IDLER GEAR - REPLACE	
		VO-4132000	Clutch cylinder, replace. Gearbox remove	0.4
		VO-2562400	Filter insert, air cleaner, replace. Onl	0.5
		VO-3116800	Battery system, test. Battery tester	0.4
			Drill and pop rivet rego plates to truck.	
		LO-350	BROKEN/WEATHERED REFLECTORS - REPLACE	0.75
			R&R reflectors with new as required.	
			Adjust drag link and drive until steering wheel straight.	
			- STONE DAMAGE.	
			R&R LH tail lamp with new. All OK.	
			*NEW SN 14514-442.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-1702600	Program control unit	0.1
			S3485 Instrument cluster, SW update. FH/FM (4)	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2610400	Coolant level sensor, expansion tank, re	0.4
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-1820200	Localised wash for fault tracing	0.3
		VO-4650000	Final drive (front and rear). Secondary	1
		VO-1820200	Localised wash for fault tracing	0.3
		VO-4650000	Final drive (front and rear). Secondary	1
		VO-4653500	Output shaft, overhaul	2.2
		VO-2332700	Engine fuel filter housing, replace	1

PC	Type	Code	Description (Original)	#
		VO-2144400	Rocker arms, replace (all)	0.9
			AUTHORITY NUMBER: 200402526.	
			Performed Icepack service as per customer request.	
			casing, replace. Flywheel, air filter housing rem	
			removed and coolant drained	
			overhaul	
			overhaul	
		VO-9221500	Fifth wheel, remove	0.9
		VO-9221600	Fifth wheel, install	0.8
		40	SUBLET SYNTHETIC OIL USED IN DIFFS/HUBS	
			SUBLET 45 L DIFF/HUB OIL USED IN DIFF REPAIRS.	
			Å666.45 + GST.	
		91	CONSUMABLES	
  2015-12-01 - Mileage: 219097 - Order nr: 200793				
		96000		0
  2015-11-01 - Mileage: 219096 - Order nr: 200793				
		96000		0
  2015-10-12 - Mileage: 219095 - Order nr: RG9971				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		17073	Service alert system, configuration and reports	0
		23311	Filter, water separator, replace	0
		17513	Engine, oil and filter, replace	0
		87208	Air conditioning air filter, replace	0
		25624	Filter insert, air cleaner, replace. Only valid for primary filter	0
		23306	Fuel filter, replace (one)	0
		VO-FK18B	FILTER KIT	1
		VO-82354791	VENTILATION FILTER	1
		VO-21716424	AIR FILTER	1

PC	Type	Code	Description (Original)	#
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42
2015-10-01 - Mileage: 200537 - Order nr: 200793				
		96000		0
2015-09-26 - Mileage: 202720 - Order nr: RG9728				
		35104	Headlight bulb, replace (one). One unit, excluding headlight adjustment	0
		VO-990037	BULB	2
2015-09-26 - Mileage: 202720 - Order nr: RG9728				
		VO-21634021	PRESSURE SENSOR	1
		VO-21582423	KIT	1
			EXHAUST BACK PRESSURE FAULT. P047013	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-2850800	Exhaust back pressure sensor, replace	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-3649500	Switch steering wheel buttons, replace	0.4
		VO-22608061	BASE PLATE	1
		VO-6410400	Steering wheel, replace	0.4
			RECTIFY INDICATOR AND HIGH BEAM COME ON TOGETHER	
			LEFT HAND HEADLAMP SURROUND CRACKED	
		VO-3525100	Headlamp complete, replace (left hand side)	1.1
		VO-21874450	PANEL	1
		VO-82884080	AIR DUCT	1
		VO-3520000	gllued headlight surroung with duct	0.5
2015-09-23 - Mileage: 200536 - Order nr: RG9675				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		35000	Lighting, general. Secondary operation number	0
		17073	Service alert system, configuration and reports	0

PC	Type	Code	Description (Original)	#
		MK-4381-2919		1
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0
		VO-FK18B	FILTER KIT	1
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42
2015-09-09 - Mileage: 181462 - Order nr: RG9362				
		VO-3710200	Electric wires and connections, check	0.4
		VO-3310600	Starter motor, replace	0.6
		VO-85013089	STARTER MOTOR, EXC	1
			INTERMITTANT OPERATION OF STARTER MOTOR	
2015-09-05 - Mileage: 181462 - Order nr: RG9362				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		35140	Bulb, replace (climate control panel)	0
		17073	Service alert system, configuration and reports	0
		VO-990037	BULB	1
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0
		VO-FK18B	FILTER KIT	1
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	43
2015-09-01 - Mileage: 162352 - Order nr: 200793				
		96000		0
2015-08-21 - Mileage: 167843 - Order nr: RG9135				
			RIGHT HAND TANK WONT EQUALIZE WITH LEFT HAND SIDE	
		VO-2340000	removed exhaust fitting and drilled hole in plug	1
2015-08-15 - Mileage: 162351 - Order nr: RG9013				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0

PC	Type	Code	Description (Original)	#
		17073	Service alert system, configuration and reports	0
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0
		VO-FK18B	FILTER KIT	1
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42

2015-08-15 - Mileage: 162351 - Order nr: RG9013

			REPLACE RIGHT HAND HEAD LIGHT SURROUND CRACKED	
		VO-82884084	AIR DUCT	1
		VO-21874457	PANEL	1
		VO-3520000	glued pained headlight surround to air duct	0.5
		VO-3525100	Headlamp complete, replace (left hand side)	1.1

2015-08-03 - Mileage: 149052 - Order nr: RG8779

		56126	Air drier, drier insert, replace	0
		17012	Fault codes, reading	0
		17010	Connect-disconnect of diagnostic tool	0
		VO-22223804	KIT	1

2015-08-01 - Mileage: 142964 - Order nr: 200793

		96000		0
--	--	-------	--	---

2015-07-28 - Mileage: 142963 - Order nr: RG8676

		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		87208	Air conditioning air filter, replace	0
		35104	Headlight bulb, replace (one). 1 unit, excludes headlight adjustment	0
		35502	Side marking lamp complete, replace	0
		17073	Service alert system, configuration and reports	0
		VO-82354791	VENTILATION FILTER	1
		MK-unRV48702BL		1
		MK-4381-2922		1

PC	Type	Code	Description (Original)	#
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0
		VO-FK18B	FILTER KIT	1
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42
2015-07-07 - Mileage: 121400 - Order nr: RG8324				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		17073	Service alert system, configuration and reports	0
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0
		VO-FK18B	FILTER KIT	1
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42
2015-07-01 - Mileage: 99323 - Order nr: 200793				
		96000		0
2015-06-16 - Mileage: 99322 - Order nr: RG7920				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		56126	Air drier, drier insert, replace	0
		23414	Filter for fuel tank ventilation, replace	0
		35200	Lighting, front. Secondary operation number	0
		17073	Service alert system, configuration and reports	0
		VO-22223804	KIT	1
		VO-21743197	AIR CLEANER	1
		MK-4381-2922		1
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0
		VO-FK18B	FILTER KIT	1

PC	Type	Code	Description (Original)	#
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42
2015-06-16 - Mileage: 99322 - Order nr: RG7920				
		VO-1706300	6 Months ECU download and oil sample. Only valid for Australian market	0.9
		VO-8394887	OIL TEST KIT	4
		VO-948211	STRIP CLAMP	4
		VO-84081002	PUMP	1
		VO-82289560	LEVEL SENSOR	1
		VO-980464	STRIP CLAMP	1
			WIPER WASHER PUMP AND LEVEL SENSOR LEAKING	
		VO-3632400	Windscreen washer pump, replace	0.4
2015-06-01 - Mileage: 34767 - Order nr: 200793				
		96000		0
2015-05-23 - Mileage: 78304 - Order nr: RG7454				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		17073	Service alert system, configuration and reports	0
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0
		VO-FK18B	FILTER KIT	1
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42
2015-05-01 - Mileage: 34766 - Order nr: 200793				
		96000		0
2015-04-24 - Mileage: 56854 - Order nr: RG6873				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		17073	Service alert system, configuration and reports	0
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0

PC	Type	Code	Description (Original)	#
		VO-FK18B	FILTER KIT	1
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42
2015-04-01 - Mileage: 34765 - Order nr: 200793				
		96000		0
2015-03-19 - Mileage: 34764 - Order nr: RG6266				
		17744	Basic service. Chassis lubrication and oil changes included only in some models	0
		17073	Service alert system, configuration and reports	0
		23311	Filter, water separator, replace	0
		23306	Fuel filter, replace (one)	0
		17513	Engine, oil and filter, replace	0
		VO-FK18B	FILTER KIT	1
		nU2-CnL8394854	VDS3 ENG OIL 15W-4	42
2015-03-11 - Mileage: 11653 - Order nr: 200793				
		VO-nGREEMEuT COMMISSIOu		1
2015-03-01 - Mileage: 11652 - Order nr: 200793				
		96000		0
2015-02-01 - Mileage: 1 - Order nr: 200793				
		96000		0
2015-01-28 - Mileage: 11651 - Order nr: RG5352				
		VO-20779040	OIL FILTER KIT	1
		nU2-CnL85107476	VOLVO GEAR OIL 20L	1
		nU2-CnL85136280	VOLVO SYNTHETIC RE	0.2
2015-01-28 - Mileage: 11651 - Order nr: RG5352				
		VO-1721000	Warranty service. After 4 weeks or maximum 10 000 km.	2
2014-11-11 - Mileage: 72 - Order nr: 8053825				
		M	PLEASE FILL IN	
			Mileage:	

PC	Type	Code	Description (Original)	#
	☒		Hrs:	
	☒		Karl 32775590	
Ⓡ	Ⓞ	VO-1703000	Parameter, programming	2
Ⓡ	☒	VO-85142228	CONVERSION KIT	1
Ⓡ	*	91	WORKSHOP CONSUMABLES	
2014-08-18 - Mileage: 100 - Order nr: 8710734				
Ⓡ	Ⓞ	LO-843P43W	DRIVER & PASSENGER WEATHERSHIELDS	1
Ⓡ	Ⓞ	LO-396P43B	WIRE UP PARKBRAKE ALARM	6.95
Ⓡ	Ⓞ	LO-771P43N	WHEEL NUT INDICATORS	2.02
Ⓡ	Ⓞ	LO-395P43U	UHF TX4600 WITH REMOTE MIC	6.63
Ⓡ	Ⓞ	LO-890L43E	ENVIRONMENTAL LEVY	0.01
Ⓡ	Ⓞ	LO-890L43C	CONSUMABLES	0.01
Ⓡ	*	71	WINDOW TINT (SUBLET)	
Ⓡ	Ⓞ	LO-821P433	DRIVERS SIDE STEP PLATE	1.54
Ⓡ	Ⓞ	LO-852P43S	CANVAS SEAT COVERS	0.95
Ⓡ	Ⓞ	LO-356L43H	ACTIVATE DAYTIME RUNNING LIGHTS	1.09
Ⓡ	Ⓞ	LO-889P43B	BALLISTIC PHONE	6.04
Ⓡ	Ⓞ	LO-566P43C	AIR BLOWER UNDER DRIVERS SEAT	1.1
Ⓡ	Ⓞ	LO-356	REAR WORK LIGHTS MOUNTED ON AERO SIDE	4.21
	☒		SKIRTS	
Ⓡ	Ⓞ	LO-350	LED AMBER STROBE LIGHT TO FACTORY ROOF	4.5
Ⓡ	☒	VO-21675772	FRONT ROOF BAR MOU	2
Ⓡ	☒	VO-8152358	PLATE	8
Ⓡ	☒	VO-82402770	COVER	1
Ⓡ	☒	VO-82403550	COVER	1
Ⓡ	☒	VO-82862153	BAR	1
Ⓡ	☒	VO-992416	SIX POINT SOCKET S	8
Ⓡ	Ⓞ	LO-396P43R	ROAD TRAIN PARK BRAKE	12.39

PC	Type	Code	Description (Original)	#
			JOB-LINE ADDED PER RV EMAIL 30/9/14 3.21PM - MR	
		VO-1591263	BRACKET, SOLENOID MOUNT	1
		VO-20465214	SWITCH, TOGGLE	1
		VO-20465216	SWITCH,PUSH BUTTON	1
		VO-22287249	CLAMPING PLATE	1
		VO-22287251	BRACKET	1
		VO-22399983	PLATE	1
		VO-82420185	PLASTIC TRAY	1
		VO-85104850	VALVE	1
		VO-991090	PUSH-IN M8 - M12 MALE THREAD	4
		VO-992025	ELBOW, PUSH-IN M8 - FEM SMALL	2
		VO-992247	SWIVEL, M16M - MALE SMALL	2
		VO-1078316	SOLENOID VALVE, 24V PTO	1
		VO-1190557	SWITCH GUARD ONLY	1
		VO-20399313	SPEED NUT M5	1
		VO-21244697	RELAY 24V CHANGE OVER 5 PIN	1
		VO-968061	PLUG M12 AH	1
		VO-969439	BOLT M5*40 TORX - B	1
		VO-980832	SYNFLEX 8mm BLACK	4
		VO-984725	BOLT M6*16 FL	2
		VO-984735	BOLT M8*25 FL (was 945444)	1
		VO-990950	NUT M8 FL LOCK - B	1
		VO-991074	PUSH-IN M8 - MALE REG.	1
		VO-992017	SWIVEL, M12M - MALE SMALL	1
		VO-993251	NIPPLE	1
		OTH-CP33	YELLOW WHEEL NUT INDICATOR 33m	60
		MK-FT1864X4	TEE 1/4" TUBE 3 WAY	1
		OTH-VCANVASPAIR-FH4	VOLVO FH4 CANVAS PAIR	1

PC	Type	Code	Description (Original)	#
®	☒	VO-84165756	W/SHIELD KIT, FH4	1
®	☒	MK-9732-BG12	DUST BLOWER	1
®	☒	OTH-NARV56044EA	FEMALE SPADE TERMINAL BLUE SNG	5
®	☒	MK-NARV56306	CABLE TIE 1=25PK	1
®	☒	OTH-T110PMTR	CABLE 3MM TWIN CORE	10
®	☒	VO-21244697	RELAY 24V CHANGE OVER 5 PIN	1
®	☒	VO-22278479	DOOR SWITCH	2
®	☒	VO-25392050	RELAY RETAINER	1
®	☒	VO-25568155	TERMINAL	6
®	☒	VO-9456277	HOUSING	1
®	☒	VO-978304	TERMINAL, VECU CABLE	4
®	☒	VO-978309	INSULATOR	1
®	☒	OTH-T13WHT	CABLE 3MM WHITE SINGLE	2
®	☒	VO-20375162	CABLE TERMINAL	2
®	☒	VO-21244697	RELAY 24V CHANGE OVER 5 PIN	1
®	☒	VO-25095927	BOLT M5*15 TORX - S	2
®	☒	VO-25108594	WASHER M5 x 11mm FLAT	1
®	☒	MK-4381-4973	CONNECTOR RELAY UN	1
®	☒	VO-470467	SPACER M10x16x6	2
®	☒	VO-6781769	SPLICE RED	6
®	☒	VO-8141219	RUBBER GROMMET	1
®	☒	VO-948211	CABLE TIE 280MM	20
®	☒	VO-965545	BRACKET	1
®	☒	VO-970777	CABLE TERMINAL	2
®	☒	MK-9771-AE4012K1	ANTENNA KIT UHF GME	1
®	☒	MK-9771-LEM6P	MICROPHONE EXT LEA	1
®	☒	MK-9771-TX4500S	UHF RADIO	1
®	☒	VO-984726	BOLT M6*20 FL	2

PC	Type	Code	Description (Original)	#
®	☒	VO-990939	NUT M6 FL	3
®	☒	OTH-CD2195	ANTENNA HI GAIN NEXTG	1
®	☒	OTH-NARV56044EA	FEMALE SPADE TERMINAL BLUE SNG	3
®	☒	MK-NARV56306	CABLE TIE 1=25PK	1
®	☒	OTH-T110PMTR	CABLE 3MM TWIN CORE	3
®	☒	VO-20375162	CABLE TERMINAL	2
®	☒	VO-21244697	RELAY 24V CHANGE OVER 5 PIN	1
®	☒	MK-4381-4973	CONNECTOR RELAY UN	1
®	☒	VO-6781769	SPLICE RED	3
®	☒	VO-8141219	RUBBER GROMMET	1
®	☒	VO-9130476	SPLICE BLUE	3
®	☒	VO-970777	CABLE TERMINAL	3
®	☒	MK-EMEWP02K	W/PACK 2 WAY CONN	2
®	☒	MK-NARV56306	CABLE TIE 1=25PK	1
®	☒	MK-NARV56602	HEATSHRINK 1=1 150 L.	1
®	☒	MK-NARV56707	TUBING 7MM 1=10M	1
®	☒	MK-NARV72429	LED WORK LAMP	2
®	☒	OTH-T110PMTR	CABLE 3MM TWIN CORE	3
®	☒	VO-952625	P CLAMP M10	4
®	☒	MK-EMEWP02K	W/PACK 2 WAY CONN	2
®	☒	OTH-NARV56044EA	FEMALE SPADE TERMINAL BLUE SNG	2
®	☒	OTH-T110PMTR	CABLE 3MM TWIN CORE	2
®	☒	MK-4381-1611	LED AMBER BEACON, COMPACT	2
®	☒	OTH-5MG316NYLN	NUT M5 NYLOC STAINLESS	3
®	☒	VO-8142340	SEALING RING	4
®	☒	VO-8142342	FLANGE WASHER	4
®	☒	VO-994781	BOLT M5*20 TORX	3
®	☒	VO-994928	SCREW M8*20 TORX	4

PC	Type	Code	Description (Original)	#
®	☒	OTH-MC-FH4SPY1	FOOT-PLATE/HANDLE FH4	1
®	☒	VO-994436	BOLT M8*45 HEX	4
®	☒	VO-994868	WASHER M8X16MM	4
®	☒	MK-NARV56022BL	MALE SPADE TERMINAL BLUE	1
®	☒	MK-NARV56044BL	FEMALE SPADE TERMINAL BLUE	1
®	☒	MK-NARV56078BL	TERMINAL RING BLUE 5mm	1
®	☒	MK-NARV56602	HEATSHRINK 1=1 150 L.	1
®	☒	MK-NARV56820BK	TAPE NITTO BLACK	1
®	☒	OTH-1200100	CONDUIT 12MM NON SPLIT	6
®	☒	VO-20382270	DIODE	1
®	☒	VO-21244697	RELAY 24V CHANGE OVER 5 PIN	2
®	☒	VO-25392050	RELAY RETAINER	2
®	☒	VO-25568155	TERMINAL	12
®	☒	VO-3963410	CABLE SEAL	2
®	☒	VO-3985598	ADAPTER, 90 degree	1
®	☒	VO-948211	CABLE TIE 280MM	100
®	☒	VO-970771	SEALING PLUG	2
®	☒	VO-978304	TERMINAL, VECU CABLE	2
®	☒	VO-984846	CABLE TERMINAL	2
®	☒	VO-984849	4 PIN ROUND PLUG HSG, F THREAD	1
®	☒	VO-992016	SWIVEL, M10M - MALE SMALL	2
®	☒	VO-992025	ELBOW, PUSH-IN M8 - FEM SMALL	2
®	☒	OTH-OLB-CAL51	AERIAL EXT LEAD	1
®	☒	OTH-DW24BLK-300	300mm BLK HEAT SHRINK DUALWALL	1
®	☒	OTH-NARV56020EA	MALE SPADE TERM. RED SINGLE	2
®	☒	OTH-NARV56042EA	FEMALE SPADE RED - INDIV	3
®	☒	OTH-1200100	CONDUIT 12MM NON SPLIT	4
®	☒	VO-6781769	SPLICE RED	3

PC	Type	Code	Description (Original)	#
®	☒	VO-9130476	SPLICE BLUE	2
®	☒	VO-983014	CABLE TERMINAL	3
®	🔧	LO-390	REMOVE CIGARETTE LIGHTER /SOCKET & FIT	0.85
	☒		BLANKING PLUG/GROMMET	
®	*	10	SUPPLY WIRE FOR HARNESS	
®	☒	OTH-LINEHAUL247	TRUCKPHONE NEXTG FIXED	1
®	☒	OTH-MC-FH4RBB/G-LED	COMP. LED BEACON MOUNTING x1	2
®	☒	OTH-MC-LAB/HARN1	LABOUR PACKAGE PRE-FAB HARNESS	1
®	☒	OTH-MC-LABFH4G1	LOW AERIAL BRKT UHF G/TROT LH	1
®	☒	OTH-MC-LABFH4G2	LOW AERIAL BRKT PHONE G/TROT R	1
	☒		ADDED PER AL 23/10/14	
	☒		BAR	
	☒		PARTS ADDED PER MR EMAIL 1/10/14 4.35PM - ML	
®	*	91	WORKSHOP CONSUMABLES	