

BK Civil - Work Order Summary

Asset:
EX3004 (BK177) - 2019 Hitachi ZX225 Excavator

Location:

Current Tracker Hours:

Current Tracker Kms:

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
29970	5250 hours service	03/03/2023	5194	0		Routine Service	Open	Cracow Branch
29366	5000 hours service	20/01/2023	4946	0	28/01/2023	Routine Service		Cracow Branch
28982	4750 hours service	12/12/2022	4700	0	12/12/2022	Routine Service		Anthony Craft
28550	4500 hours service	06/11/2022	4444	0	15/11/2022	Routine Service		Anthony Craft
28208	4250 hours service	30/09/2022	4198	0	30/09/2022	Routine Service		Cracow Branch
27727	4000 hours service	14/08/2022	3949	0	29/08/2022	Routine Service		Cracow Branch
27212	fit hitch to machine	16/06/2022	3742	0	06/06/2022	Ask Supervisor		Justin Debney
27159	3750 hours service	13/06/2022	3701	0	13/06/2022	Routine Service		Anthony Craft
27042	Aeris checklist for Cracow	01/06/2022	3664	0	03/06/2022	Ask Supervisor		Morgan Holcombe
27016	Power tilt main seal leaking	31/05/2022	3657	0	03/06/2022	Ask Supervisor		Morgan Holcombe
26188	3500 hours service / first aid kit	26/02/2022	3449	0	01/06/2022	Routine Service		Saul Whaley
26172	cut wear pads	25/02/2022	3443	0	24/02/2022	Ask Supervisor		Jordan Humberdross
26173	finish welding bucket wear pads	25/02/2022	3443	0	25/02/2022	Ask Supervisor		Jordan Humberdross
26152	inspect, cut wear pads off and grind, straighten bucket	24/02/2022	3443	0	22/02/2022	Ask Supervisor		Jordan Humberdross
26154	cut and tack on wear pads	24/02/2022	3443	0	23/02/2022	Ask Supervisor		Jordan Humberdross
26095	Prestart Defect - GET Condition Failed	17/02/2022			01/06/2022	Repair Next Service		David Wood
25914	Prestart Defect - Check Hyd. Oil Level Failed	01/02/2022			22/02/2022	Ask Supervisor		
25770	Repair oil leak, remove broken toolbox	14/01/2022	3321	0	01/06/2022	Ask Supervisor		Stephen Ware
25363	3250 hours service	17/11/2021	3195	0	17/11/2021	Routine Service		
25153	Prestart Defect - Odometer/Hours Correct Failed 3037.9	23/10/2021			25/10/2021	Repair Next Service		Anthony Craft
25083	Prestart Defect - Odometer/Hours Correct Failed 3123.6h	18/10/2021			18/10/2021	Ask Supervisor		Anthony Craft
25046	Air-conditioning when working is struggling to stay cold	11/10/2021			09/10/2021	Ask Supervisor		Saul Whaley
24871	mirror broken on fuel tank	21/09/2021			01/11/2021	Repair Next Service		Morgan Holcombe
24787	Still coming up as prestarts are not getting done on this app	10/09/2021			10/09/2021	Ask Supervisor		Trevor Mortimer
24728	Aircon needs attention	02/09/2021			27/09/2021	Ask Supervisor		Morgan Holcombe
24697	Hours 2962.7	31/08/2021			31/08/2021	Ask Supervisor		Jay Becker
24693	Greese nipple needs fixing	30/08/2021			30/07/2021	Ask Supervisor		Morgan Holcombe
24688	3000 hours service	29/08/2021	2948	0	09/10/2021	Routine Service		Saul Whaley
24670	Prestart Defect - Next Service Correct Failed	27/08/2021			27/08/2021	Repair Next Service		Craig Van Beuzekom
24569	Hours 2922.6	20/08/2021			20/08/2021	Ask Supervisor		Jay Becker
24391	Change cutting edge	06/08/2021	2842	0	06/08/2021	Do Not Operate		Morgan Holcombe

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
24320	Repair grease line	30/07/2021	2792	0	30/07/2021	Ask Supervisor		Morgan Holcombe
23990	2750 hours service	08/07/2021	2697	0	15/07/2021	Routine Service		Morgan Holcombe
23978	Top up auto greaser	06/07/2021	2688	0	13/07/2021	Ask Supervisor		Morgan Holcombe
23926	Adjust tracks	02/07/2021	2676	0	02/07/2021	Ask Supervisor		Morgan Holcombe
23472	Prestart Defect - Check Hyd. Oil Level Failed	27/05/2021			10/06/2021	Ask Supervisor		Blair Batterham
23449	Top up auto grease	26/05/2021	2506	0	26/05/2021	Repair Next Service		Morgan Holcombe
23425	Prestart Defect - Odometer/Hours Correct Failed	24/05/2021			24/05/2021	Repair Next Service		
23234	2500 hours service	07/05/2021	2447	0	11/05/2021	Routine Service		Toowoomba Branch WSHOP - W
23210	Machine service due 2500 hrs	04/05/2021			11/05/2021	Repair Next Service		Toowoomba Branch WSHOP - W
22949	Power tilt leaking	08/04/2021	2392	0	11/05/2021	Ask Supervisor		Toowoomba Branch WSHOP - R
22418	oil leak at bucket hitch	10/03/2021	2316	0	10/03/2021	Routine Service		Toowoomba Branch WSHOP - W
20972	Cab has leak as dust inside cab when working	18/02/2021			11/05/2021	Repair Next Service		Toowoomba Branch WSHOP - R
20148	On Hire/ Off Hire - Check	03/02/2021			11/05/2021	Routine Service		Toowoomba Branch WSHOP - W
20019	A/c repair	02/02/2021	2278	0	28/01/2021	Ask Supervisor		Toowoomba Branch WSHOP - W
19995	quick hitch ram leaking, remove and get seal kit	01/02/2021	2277	0	16/02/2021	Routine Service		Toowoomba Branch WSHOP - W
19238	2250 hours service	17/01/2021	2203	0	11/05/2021	Routine Service		Toowoomba Branch WSHOP - R
19208	A/C not working efficiently	15/01/2021	2193	0	15/01/2021	Ask Supervisor		Toowoomba Branch WSHOP - W
17182	repair flashing light	27/11/2020	2122	0	26/11/2020	Do Not Operate		Toowoomba Branch WSHOP - W
17183	repair flashing light	27/11/2020	2122	0	26/11/2020	Do Not Operate		Toowoomba Branch WSHOP - W
16941	Remove spacers on bucket	24/11/2020	2092	0	23/11/2020	Do Not Operate		Toowoomba Branch WSHOP - W
14822	2000 hours service	22/10/2020	1945	0	24/11/2020	Routine Service		Toowoomba Branch WSHOP - R
13950	Fill Autogreaser	06/10/2020	1846	0	06/10/2020	Repair Next Service		Toowoomba Branch WSHOP - W
11869	1750 hours service	22/08/2020	1706		14/01/2021	Routine Service		Toowoomba Branch WSHOP - W
11855	CARRY OUT SERVICE	21/08/2020			27/08/2020	Routine Service		Toowoomba Branch WSHOP - W
11139	Turntable pins	03/08/2020			03/08/2020	Do Not Operate		Toowoomba Branch WSHOP - W
11141	New Hubs	03/08/2020			03/08/2020	Do Not Operate	Open	Toowoomba Branch WSHOP - W

Service Job History

Page 1

Fleet No	BK177	EXCAVATOR; HITACHI ZX225				S/N: HCMDCN21L00308082	
Job No	Date	Staff	Completed	Days	Meter	Last Hirer	Job Description
3031	6/05/2020	Saul	6/05/2020	1	1180	CROFT D	Service. Earthworks - 1000 Hr Service. Completed 1180HRS
2578	17/01/2020	Jason	23/01/2020	5		CROFT D	Repair. Track Roller - No Good. Organise parts - Service Kit - Track Roller Travel to Machine onsite Tomingley and Fit new track rollers. Travel to tomingley - Rail site. Fit new track roller and grease.
2584	17/01/2020	Jason	17/01/2020	1	758	CROFT D	Service. Earthworks - 750 Hr Service
2195	11/11/2019	DavidW	11/11/2019	1		CROFT D	Service. Earthworks - 500 Hr Service. Completed 478hrs. Fit stickers, wash buckets and set up spacers to be welded.
2175	8/11/2019	Will	11/11/2019	2		CROFT D	Repair. repair. parts
2113	4/11/2019	Clay	4/11/2019	1		CROFT D	Repair. repair. modify digger buckets to suit hitch. Welded 40mm spaces on to all attachments to suit. Welded BK numbers to attachments.
2100	1/11/2019	Luke	1/11/2019	1		CROFT D	Service. Earthworks - 500 Hr Service. Completed 177,478hrs.
1550	16/09/2019	Luke	16/09/2019	1		CROFT D	Service. Earthworks - 250 Hr Service. Completed 277hrs.