

# Service Job History

Fleet No BK067		TRUCK; MACK METROLINER			S/N: 6FME06B553D709024		
Job No	Date	Staff	Completed	Days	Meter	Last Hirer	Job Description
3219	19/06/2020	Raymond	22/06/2020	2	30632		Repair. Repairs to Fuel Pump.. Repairs to Fuel Pump.
3187	11/06/2020	Raymond	11/06/2020	1	30632		Repair. Diesel Leak. Inspect Diesel Leak, Fit wheel Chocks
3173	9/06/2020	DavidW	10/06/2020	2			Repair. 1. FRONT SHOCKS LEAKING. 2 - RH DOOR COURTESY CATCH NOT HOLDING. 3 - NO WHEEL CHOCKS. 4 - INJ PUMP LEKING. 5 - BEACON SWITCH INTERMITTENTLY NOT WORKING.. REPAIRED-1. FRONT SHOCKS LEAK. 2 - RH DOOR COURTESY CATCH . 3 - INSTALLED WHEEL CHOCKS. 4 - INJ PUMP LEAK. 5 - BEACON SWITCH. 6. RADIATOR LEAK HYDLEAK 7. FIXED DRIVERS DOOR WINDOW
3099	26/05/2020	DavidW	29/05/2020	4	30615		Repair. CARRY OUT PRE-MACHINERY INSPECTION. complete machinery inspection checklist-replaced headlight bulbs, replaced shackel bushes lhs & rhs side, install parker lense, lh side mirror, fitted new ignition solenoid, greases truck and adjusted brakes.
3078	22/05/2020	DavidW	22/05/2020	1			Repair. Yearly inspection. Replaced king pins, new brake linings and rear hub seals.
3081	22/05/2020	DavidW	22/05/2020	1			Repair. Header Tank. Fit new lower and main header tank, fitted new pos4 booster. Fitted new marker signs.
3063	14/05/2020	Gary	14/05/2020	1			Repair. Air leak. Fitted new LH axle booster fittings
2932	14/04/2020	Raymond	18/05/2020	25	30604		Repair. NO DOOR ALRM FITTED. TARP NOT WORKING.. fixed door alram, tarp, hydraulic leak and window.
2921	9/04/2020	Saul	9/04/2020	1	30567	FULTON	Repair. Worn Exhaust flex under cab. Replaced exhaust flex under cab.
2879	2/04/2020	Saul	9/04/2020	6		FULTON	Repair. repair. fit new radiator. Hook up hoses hook up intercoller. Replace air bag ride hieght valve rod and rose joints. Fix mud guard. Fit new exhaust flex under cab.
2830	19/03/2020	Saul	1/04/2020	10	30510	FULTON	Repair. REMOVE LEAKING RADIATOR TO REPAIR LEAK AT RH SIDE LOWER AREA. Replace old radiator with new radiator.
2673	3/02/2020	Luke	3/03/2020	22		FULTON	Repair. 1. LH Bonnet stop needs repairing. 2. Rear linings need replacing next service.. diagnose and repair starting fault.
2615	23/01/2020	DavidW	26/02/2020	25	3424	Wagners*	Service. Trucks - 500 hr Service. Previous 750Hr completed at 29982Hr 18.5.2019. Current odometer 831297 km. Run new wiring for parklights on LH door. Repair window winder on RH door. Replace bonnet mount rubber drain diff and reseal front cover.
2352	2/12/2019	Trevor	19/12/2019	14		FULTON	Repair. Replace faulty park brake module on dash. replace service trailer brake switch, fault find problem with air exhausting.
2307	27/11/2019	Will	27/11/2019	1		FULTON	Repair. parts. parts
2230	15/11/2019	Luke	18/11/2019	2		FULTON	Repair. hyd leak. repaired hyd leak on pto valve.
2198	11/11/2019	DavidW	13/11/2019	3		FULTON	Repair. repair. remove and replace 2 x steer tyres.

1492	3/09/2019	Will	16/09/2019	10	FULTON	Repair. REPAIR. PARTS
1446	30/08/2019	Luke	30/08/2019	1	FULTON	Repair. repair. replaced booster on tailgate locks.
1447	30/08/2019	Luke	30/08/2019	1	FULTON	Repair. repair. repair
1399	26/08/2019	Luke	26/08/2019	1	FULTON	Repair. repair. fitted new clutch cable, adjusted clutch, removed crosslock air control, replaced engine oil lube line to aux drive. Fitted power divider air piston and new housing, repaired air leaks in cab, washed diff and engine.
1415	26/08/2019	Luke	26/08/2019	1	Wagners*	Service. Earthworks - 2000 Hr Service. Completed 20/8/19. changed diff oils, removed and resealed engine sump, repaired wiring.
866	1/07/2019	Will	1/07/2019	1	FULTON	Repair. REPAIRS. Remove rear torque rod and repair damaged air for tail gate release.
731	10/06/2019	DavidW	12/06/2019	3	FULTON	Repair. Inspection for Machinery. Inspect truck for road worthy - Adjust brakes. Repair fuel pump diesel leak. Fault find and rewiring parker lights.
665	28/05/2019	PaulS	28/05/2019	1	FULTON	Repair. Door Repairs. Repaired drivers door not shutting properly.
624	20/05/2019	Luke	20/05/2019	1	29982 Wagners*	Service. Trucks - 750 Service
257	1/03/2019	Trevor	21/03/2019	15	FULTON	Repair. Install new king pin Bushes. Remove front hubs and stub axles, install new king pin bushes in Rh stub, ream out bushes to fit new king pin. Replace uni joint on lower steer shaft column above steering box, fit up brackets and clean hubs RHS
175	3/02/2019	PaulS	5/02/2019	2	29465 FULTON	Repair. carry out service as required, repair a/c not working when day gets hot, replace fan belt as required, reposition e-stop outside of cab and check hydraulic oil level. Carry out 500Hr Service, repair fan belt and A/C belt. Blow out radiator. Replaced L/H Air bag on front drive axle and tightened loose U Bolts. Top up Hydraulic oil, 20LTR. Clean out evaporator as it is full of mud. Start to wire up E-Stop outside of cab. Finish putting interior dash together after fixing A/C evaporator blocked. Wire up E-Stop on outside of cab as required. Replaced missing ride light as required.

## BK Civil - Work Order Summary

**Asset:**  
RTT5203 (BK067) - 2003 MACK METROLINER  
TIP TRUCK

**Location:**

**Current Tracker Hours:**

**Current Tracker Kms:**

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
29963	Manually generated 250 hours service	02/03/2023	0	0	06/03/2023	Routine Service		Anthony Craft
29935	Repair AC wiring, reroute clutch cable	01/03/2023	0	0	20/03/2023	Ask Supervisor		Justin Debney
29863	air leak adjust brakes	24/02/2023	0	0	17/02/2023	Repair Next Service		David Wood
29814	repair clearance lights	22/02/2023	0	0	27/02/2023	Ask Supervisor		William Keeley
29815	repair clearance lights	22/02/2023	0	0	20/02/2023	Ask Supervisor		William Keeley
29766	Drive tyres need replacing	20/02/2023	0	0	20/02/2023	Ask Supervisor		William Keeley
29681	repair exhaust	14/02/2023	0	0	14/02/2023	Routine Service		William Keeley
29487	Flat Tyre	01/02/2023	0	0	02/02/2023	Ask Supervisor		Juston Free
29314	Jumping out of gear	16/01/2023	0	0	21/01/2023	Ask Supervisor		Justin Debney David Wood
29206	Air bag	10/01/2023	0	0	06/01/2023	Repair Next Service		Clay Baran
29208	Exhaust clamp failing getting louder	10/01/2023			10/01/2023	On/Off Hire Inspection		
29193	Flat tyre	09/01/2023	0	0	09/01/2023	Do Not Operate		Juston Free
29129	Multiple Prestart Defects	04/01/2023			16/01/2023	Repair Next Service		
29144	Ac not blowing air can't keep up	04/01/2023			05/01/2023	Ask Supervisor		Juston Free
28843	Repairs and tires	02/12/2022	0	0	24/11/2022	Repair Next Service		Clay Baran
28762	Fire Extinguisher to be Checked	24/11/2022			30/01/2023	Routine Service		Clay Baran
28671	1000hr Service	16/11/2022	0	0	16/11/2022	Routine Service		Juston Free
28530	Prestart Defect - Check Engine Oil level Failed	04/11/2022			04/11/2022	Ask Supervisor		Joseph Giles
28410	Flat tyre	24/10/2022	0	0	19/10/2022	On/Off Hire Inspection		Clay Baran
28346	truck derating	16/10/2022	0	0	14/10/2022	Ask Supervisor		
28205	Prestart Defect - Air Conditioner functional (where fitted) F	29/09/2022			30/09/2022	Repair Next Service		
28125	Multiple Prestart Defects	20/09/2022			12/10/2022	Routine Service		Juston Free
28101	Driver side headlight is dim	16/09/2022			12/10/2022	Repair Next Service		Scott Debney
27967	Needs new tyres on drive	02/09/2022			12/09/2022	Repair Next Service		Scott Debney
27948	Multiple Prestart Defects	31/08/2022			31/08/2022	Routine Service		
27725	flat tire	12/08/2022	31945	876398	10/08/2022	Repair Next Service		
27578	Multiple Prestart Defects	26/07/2022			26/07/2022	Repair Next Service		Anthony Craft
27550	fit new cable for tarp	21/07/2022	31945	876398	19/07/2022	Ask Supervisor		Jordan Humberdross
27285	First Aid to be checked	24/06/2022			11/07/2022	Routine Service		Anthony Craft

Work Order	Description	Created	Created Hours	Created Km	Completed	Ask Supervisor Priority	Item Status	Assigned To/Completed By
26998	Exhaust brake doesn't appear to be working	28/05/2022			11/07/2022	Ask Supervisor		Justin Debney
26999	Either steering wheel or alignment is out	28/05/2022			02/06/2022	Repair Next Service		Justin Debney
26979	fix tarp pipes	26/05/2022	31945	876398	26/05/2022	Ask Supervisor		Jordan Humberdross
26957	Fire Extinguisher to be Checked	25/05/2022			02/06/2022	Routine Service		Justin Debney
26864	Inspection checkover	11/05/2022	31945	876398	11/05/2022	Ask Supervisor		
26810	Replace steer tyres	05/05/2022	31945	876398	28/04/2022	Do Not Operate		Justin Debney
26741	fix headlights	29/04/2022	31945	876398	29/04/2022	Ask Supervisor		Nicholas Radburn
26554	cut off rear hinge and weld new one on	08/04/2022	31945	876398	05/04/2022	Ask Supervisor		Jordan Humberdross
26513	Investigate engine oil leak	04/04/2022	31945	876398	05/05/2022	Ask Supervisor		Peter Lee
26453	Ac not cold	25/03/2022	31945	876398	23/03/2022	Repair Next Service		
26359	Repair wiring to blinker/headlamp replace LHR drive tyres	18/03/2022			09/03/2022	Repair Next Service		Justin Debney
26349	cut collar on rear tailgate and gate	17/03/2022	31945	876398	15/03/2022	Ask Supervisor		Jordan Humberdross
26328	back tail gate not closing	14/03/2022	31945	876398	16/03/2022	Ask Supervisor		Clay Baran Joseph Giles
25913	Drivers lower step.	01/02/2022			12/03/2022	Ask Supervisor		
25754	250 hr service	13/01/2022	31945	876398	05/01/2022	Repair Next Service		
25739	Replace front axle slack adjusters	12/01/2022	31945	876398	12/01/2022	Ask Supervisor		
25694	Replace front drive axle brakes and s-cams	06/01/2022	31945	876398	06/01/2022	Ask Supervisor		
25661	First Aid to be checked	25/12/2021			12/03/2022	Routine Service		Joseph Giles
25637	Prestart Defect - Air Conditioner functional (w here fitted) F	22/12/2021			23/12/2021	Ask Supervisor		Saul Whiley Justin Debney
25625	Side step damage right rear tyre leaking clutch needs adjusted	20/12/2021			04/01/2022	Repair Next Service		Clay Baran
25546	Shock in seat not working	10/12/2021			23/12/2021	Repair Next Service		Nicholas Radburn
25515	Prestart Defect - Power Steering Fluid Failed	06/12/2021			06/12/2021	Routine Service		Clay Baran
25426	Fire Extinguisher to be Checked	24/11/2021			12/03/2022	Routine Service		Anthony Craft
25415	Replace tyres	23/11/2021	31943	876280	23/11/2021	Repair Next Service		
25036	Engine Mssing	09/10/2021	31837	872568	12/10/2021	Repair Next Service		Toow oomba Branch WSHOP - W
24773	replace rear tyres rotate steer tyres straighten steering ar	08/09/2021	31721	870117	04/09/2021	Repair Next Service		David Wood
24720	31750 hours service	02/09/2021	31696	868801	12/10/2021	Routine Service		Saul Whiley
24692	Multiple Prestart Defects	30/08/2021			31/08/2021	Ask Supervisor		David Wood
24191	Lack of power	20/07/2021	31545	863937	20/07/2021	Repair Next Service		Toow oomba Branch WSHOP - R
23987	air leak at dash	07/07/2021	31505	862101	07/07/2021	Do Not Operate		Trevor Mortimer
23892	Truck not starting	29/06/2021	31464	860427	29/06/2021	Ask Supervisor		Morgan Holcombe
23872	Seat suspension and adjustments ok Failed	28/06/2021			10/07/2021	Repair Next Service		Morgan Holcombe
23839	31500 hours service	25/06/2021	31449	859995	16/07/2021	Routine Service		Morgan Holcombe
23832	First Aid to be checked	24/06/2021			07/07/2021	Routine Service		Trevor Mortimer
23718	Cracked exhaust Manifold	16/06/2021	31432	859603	15/06/2021	Repair Next Service		Clay Baran
23713	Inspection	15/06/2021	31432	859602	10/06/2021	Repair Next Service		Toow oomba Branch WSHOP - R

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority Service	Item Status	Assigned To/Completed By
23001	Fire Extinguisher to be Checked... test tag missing.4.5 kg 4 week Notice of Certificate of Inspection - 18/05	25/05/2021 13/04/2021			16/06/2021 17/06/2021	Ask Supervisor		Toow oomba Branch WSHOP - W Toow oomba Branch WSHOP - W
22076	31250 hours service	05/03/2021	31200	852864	05/06/2021	Routine Service		Toow oomba Branch WSHOP - W
22034	Fuel leak , Hydraulic Leak, tarp	04/03/2021			05/06/2021	Repair Next Service		Toow oomba Branch WSHOP - W
21950	Oil leak fuel injection sideKnock in engine. Also left bonne	03/03/2021			05/06/2021	Ask Supervisor		Toow oomba Branch WSHOP - W
20106	Crack in front guard /bonnet L/h side	03/02/2021			28/06/2021	Repair Next Service		Toow oomba Branch WSHOP - W
19990	Cab mounts are stuffedd	01/02/2021			06/02/2021	Repair Next Service		Toow oomba Branch WSHOP - W
19515	Cleanliness Failed, Shockies to be replaced see photos	25/01/2021			06/02/2021	Ask Supervisor		Toow oomba Branch WSHOP - W
18681	First Aid to be checked	25/12/2020			11/01/2021	Routine Service		Toow oomba Branch WSHOP - R
18001	Cab vents la	09/12/2020	30658	839016	09/12/2020	Do Not Operate		Toow oomba Branch WSHOP - W
17109	repair brakes not releasing	26/11/2020	30658	839016	26/11/2020	Do Not Operate		Toow oomba Branch WSHOP - W
16898	Prestart Defect - Check air, Oil & Water leaks Failed	23/11/2020			24/11/2020	Repair Next Service		Toow oomba Branch WSHOP - W
15767	Prestart Defect - Check lights and indicators Failed	06/11/2020			09/12/2020	Do Not Operate		Toow oomba Branch WSHOP - W
15687	Prestart Defect - Check Amber Flashing Beacon Failed	05/11/2020			26/11/2020	Do Not Operate		Toow oomba Branch WSHOP - W
15616	Broken headlight cover	04/11/2020			09/12/2020	Do Not Operate		Toow oomba Branch WSHOP - W
15025	Fire Extinguisher to be Checked	25/10/2020			09/12/2020	Routine Service		Flashpoint Fire Chad
14542	replace LH mirror	16/10/2020	839016	30658	21/10/2020	Routine Service		Toow oomba Branch WSHOP - W
13772	UHF Repair - Breakdown - 30658hrs	02/10/2020	30658	839016	02/10/2020	Repair Next Service		Toow oomba Branch WSHOP - R
13408	Bent Pble - Breakdown @ 30685hrs	25/09/2020	30658	839016	24/09/2020	Repair Next Service		Toow oomba Branch WSHOP - R
12931	service due	15/09/2020			26/11/2020	Routine Service		Toow oomba Branch WSHOP - W
12112	Breakdown - Coolant Leaks	27/08/2020	30735		21/08/2020	Do Not Operate		Toow oomba Branch WSHOP - W
11307	Prestart Defect - Check lights Failed no low beam	07/08/2020		839016	10/08/2020	Repair Next Service		Toow oomba Branch WSHOP - W
11155	Prestart Defect - Check lights and indicators Failed	03/08/2020		839016	10/08/2020	Do Not Operate		Toow oomba Branch WSHOP - W
10995	Breakdown - Brake Booster.	30/07/2020			30/07/2020	Repair Next Service		David Wood
10230	Cab Blower Doesn't Work PByrne	29/06/2020			09/12/2020	Do Not Operate		Toow oomba Branch WSHOP - W
10232	Bonnet Mbunt Left Mssing P Burne	29/06/2020			31/07/2020	Do Not Operate		Toow oomba Branch WSHOP - W
10080	Front Shockies need replacing Paul Byrne	18/06/2020	30669		03/08/2020	Repair Next Service		Toow oomba Branch WSHOP - W