

# Service Job History

Fleet No BK068		TRUCK; MACK METROLINER				S/N: 6FME06B214D710651	
Job No	Date	Staff	Completed	Days	Meter	Last Hirer	Job Description
3168	9/06/2020	Trevor	7/07/2020	21			Repair. POWER STEER LEAK AT BOX. PTO LEAK.. Inspected and no repair required.
3148	3/06/2020	Saul	9/06/2020	5	25700		Repair. CARRY OUT PRE DOT INSPECTION LIST. CHECK OVER- SHIMS KING PINS, WIRE LIGHTS, CLEAN AND REPAIR RELAY VALVES, FIX AIR LEAKS, REPLACE TORQUE ROD BUSHES, CAB MOUNTS, REPLACE REFLECTORS
3012	1/05/2020	Raymond	9/06/2020	28	25713	FULTON	Service. 250HR Service Completed 25713 HRS
2972	21/04/2020						Repair. ENGINE IS DE-RATING. A/C CUTTING OUT..
2934	14/04/2020	Saul	20/04/2020	5	25700		Repair. FIT NEW DNOT SIGNS TO REAR OF TIPPER BODY.. Flush A/c evaporator. Fit new Dnot signs, fix broken straps on airtank RHS. Fix fuel gauge
2791	5/03/2020	Luke	11/03/2020	5	25677	FULTON	Repair. REPLACE RH WINDSCREEN.. fitted new tip control box. Changed fuel sender in tank.RH windscreen replaced by Windscreen Works.
2758	27/02/2020	Saul	6/03/2020	7		FULTON	Repair. AIR LEAK IN CAB CONTROL BOX .. repair air leaks, fuel gauge not working, air pressure gauge mot working, fit air tank bracket, pto switch replaced.
2649	30/01/2020	Trevor	3/03/2020	24	25600	FULTON	Repair. Replace drivers side seat belt mechanism. Replaced drivers side seat belt assembly. Fitted new battery isolator. Fit GPS tracker.
2564	13/01/2020	Luke	3/03/2020	37		FULTON	Repair. Repair air leak in cab tipper control box. Repaired split hose in air box in cab. Raplced Batteries, Checked oils. Repaired air leak in tipper box. Fund split air lines.
2271	22/11/2019	Clay	25/11/2019	2		FULTON	Repair. bent tie down rail. fis bent tie down rail on side tipper bin weld back to bin. Fit new battery isolator as old one had been broken.
2064	28/10/2019	Saul	28/10/2019	1		FULTON	Service. Trucks - 1000 Service. Completed 20,493hrs. Fix tracker wiring, fix tarp, check voltage sensor.
1562	16/09/2019	Luke	17/09/2019	2		FULTON	Repair. repair. repaired broken rail on l/h side of body, cut and welded.
1418	27/08/2019	Will	13/09/2019	14		FULTON	Repair. REPAIR. REPAIRS
1102	16/07/2019	Luke	13/08/2019	21		FULTON	Repair. rpr. inspected truck for faults, completed parts list and ordered parts, replaced lower torque rod brushes. Repaired broken cross over bar under the cab, replaced centre bearing, greased and adjusted brakes, fitted upper torque rod bushges, replaced air manifold in firewall, replaced wiper motor, replaced bulb in head lights/indicators, replaced park brake button. Fit new mud flaps.
728	10/06/2019	DavidW	10/06/2019	1	25217	FULTON	Service. Trucks - 250 Service Check over truck for list with inspection
490	17/04/2019	Luke	17/04/2019	1		Wagners*	Repair. Tarp Repairs. Removed tarp motor

477	12/04/2019	PaulS	29/04/2019	12	Wagners*	Repair. Repairs. Change flat tyre. Carried out clutch adjustment. Replaced LH Rear Airbag, R&R Drive Tyres and reposition E-Stop. Repaired lights. Removed flashing light, ran new wiring up bin and made mounts. Repaired UHF mounts. Removed AM/FM aerial and waiting on new one. Repaired air leak over front diff. repaired tarp mount. Repaired excess signage and guading from rear of bin. Moved out of shed and cleaned bay. Repair holes in body, fabricate new pivot pin for rear and make rear door able to swing open and close easy. Fit new AM/FM aerial, Fit stickers for hoist control and cab switches. Reassemble cab.
429	8/04/2019	PaulS	12/04/2019	5	25002 FULTON	Repair. Repairs. R&R Electric Tarp motor as required. Fault find tarp not working - Found bad connection at rear anderson plug to tarp motor. Removed anderson plug and soldered wires.
398	27/03/2019	Luke	27/03/2019	1	FULTON	Repair. Repairs. Repaired wiring for tarp, welded block on to stop tarp jamming.
313	12/03/2019	Will	19/03/2019	6	25000 FULTON	Service. Trucks - 500 Service
304	11/03/2019	PaulS	19/03/2019	7	FULTON	Repair. Repairs to engine as required. R&R Exhaust manifold, R&R Front engine seal. Replae RH front drive booster and remove RH rear slack adj and free up. R&R front engine seal and harmonic balancer as required. R&R top radiator hose on radiator. Test drive truck for exhaust issue and straighten steering wheel.
98	11/01/2019	DavidW	5/02/2019	18	Newlands	Repair. ticking in motor, 3 shockies, a/c not blowing cold air.. 1. Replace crank angle censor & fuel temp sender use to check BK066.

# Service Job History

Fleet No BK068		TRUCK; MACK METROLINER				S/N: 6FME06B214D710651	
Job No	Date	Staff	Completed	Days	Meter	Last Hirer	Job Description
3168	9/06/2020	Trevor	7/07/2020	21			Repair. POWER STEER LEAK AT BOX. PTO LEAK.. Inspected and no repair required.
3148	3/06/2020	Saul	9/06/2020	5	25700		Repair. CARRY OUT PRE DOT INSPECTION LIST. CHECK OVER- SHIMS KING PINS, WIRE LIGHTS, CLEAN AND REPAIR RELAY VALVES, FIX AIR LEAKS, REPLACE TORQUE ROD BUSHES, CAB MOUNTS, REPLACE REFLECTORS
3012	1/05/2020	Raymond	9/06/2020	28	25713	FULTON	Service. 250HR Service Completed 25713 HRS
2972	21/04/2020						Repair. ENGINE IS DE-RATING. A/C CUTTING OUT..
2934	14/04/2020	Saul	20/04/2020	5	25700		Repair. FIT NEW DNOT SIGNS TO REAR OF TIPPER BODY.. Flush A/c evaporator. Fit new Dnot signs, fix broken straps on airtank RHS. Fix fuel gauge
2791	5/03/2020	Luke	11/03/2020	5	25677	FULTON	Repair. REPLACE RH WINDSCREEN.. fitted new tip control box. Changed fuel sender in tank.RH windscreen replaced by Windscreen Works.
2758	27/02/2020	Saul	6/03/2020	7		FULTON	Repair. AIR LEAK IN CAB CONTROL BOX .. repair air leaks, fuel gauge not working, air pressure gauge mot working, fit air tank bracket, pto switch replaced.
2649	30/01/2020	Trevor	3/03/2020	24	25600	FULTON	Repair. Replace drivers side seat belt mechanism. Replaced drivers side seat belt assembly. Fitted new battery isolator. Fit GPS tracker.
2564	13/01/2020	Luke	3/03/2020	37		FULTON	Repair. Repair air leak in cab tipper control box. Repaired split hose in air box in cab. Raplced Batteries, Checked oils. Repaired air leak in tipper box. Fund split air lines.
2271	22/11/2019	Clay	25/11/2019	2		FULTON	Repair. bent tie down rail. fis bent tie down rail on side tipper bin weld back to bin. Fit new battery isolator as old one had been broken.
2064	28/10/2019	Saul	28/10/2019	1		FULTON	Service. Trucks - 1000 Service. Completed 20,493hrs. Fix tracker wiring, fix tarp, check voltage sensor.
1562	16/09/2019	Luke	17/09/2019	2		FULTON	Repair. repair. repaired broken rail on l/h side of body, cut and welded.
1418	27/08/2019	Will	13/09/2019	14		FULTON	Repair. REPAIR. REPAIRS
1102	16/07/2019	Luke	13/08/2019	21		FULTON	Repair. rpr. inspected truck for faults, completed parts list and ordered parts, replaced lower torque rod brushes. Repaired broken cross over bar under the cab, replaced centre bearing, greased and adjusted brakes, fitted upper torque rod bushges, replaced air manifold in firewall, replaced wiper motor, replaced bulb in head lights/indicators, replaced park brake button. Fit new mud flaps.
728	10/06/2019	DavidW	10/06/2019	1	25217	FULTON	Service. Trucks - 250 Service Check over truck for list with inspection
490	17/04/2019	Luke	17/04/2019	1		Wagners*	Repair. Tarp Repairs. Removed tarp motor

477	12/04/2019	PaulS	29/04/2019	12	Wagners*	Repair. Repairs. Change flat tyre. Carried out clutch adjustment. Replaced LH Rear Airbag, R&R Drive Tyres and reposition E-Stop. Repaired lights. Removed flashing light, ran new wiring up bin and made mounts. Repaired UHF mounts. Removed AM/FM aerial and waiting on new one. Repaired air leak over front diff. repaired tarp mount. Repaired excess signage and guading from rear of bin. Moved out of shed and cleaned bay. Repair holes in body, fabricate new pivot pin for rear and make rear door able to swing open and close easy. Fit new AM/FM aerial, Fit stickers for hoist control and cab switches. Reassemble cab.
429	8/04/2019	PaulS	12/04/2019	5	25002 FULTON	Repair. Repairs. R&R Electric Tarp motor as required. Fault find tarp not working - Found bad connection at rear anderson plug to tarp motor. Removed anderson plug and soldered wires.
398	27/03/2019	Luke	27/03/2019	1	FULTON	Repair. Repairs. Repaired wiring for tarp, welded block on to stop tarp jamming.
313	12/03/2019	Will	19/03/2019	6	25000 FULTON	Service. Trucks - 500 Service
304	11/03/2019	PaulS	19/03/2019	7	FULTON	Repair. Repairs to engine as required. R&R Exhaust manifold, R&R Front engine seal. Replae RH front drive booster and remove RH rear slack adj and free up. R&R front engine seal and harmonic balancer as required. R&R top radiator hose on radiator. Test drive truck for exhaust issue and straighten steering wheel.
98	11/01/2019	DavidW	5/02/2019	18	Newlands	Repair. ticking in motor, 3 shockies, a/c not blowing cold air.. 1. Replace crank angle censor & fuel temp sender use to check BK066.

## BK Civil - Work Order Summary

**Asset:**  
RTT5204 (BK068) - 2004 MACK METROLINER  
TIP TRUCK

**Location:**

**Current Tracker Hours:**

**Current Tracker Kms:**

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
30538	rotate drive tyres	21/04/2023	28506	789552	27/04/2023	Routine Service		Corey Roseby
30058	Power Steering Fluid low	10/03/2023			10/03/2023	Routine Service		David Wood
29778	FAN IS NOISY	20/02/2023	28307	786988	20/02/2023	Routine Service		Justin Debney
29720	NEEDS REVERSE LIGHT AND BEEPER TO WORK	16/02/2023			27/02/2023	Ask Supervisor		David Wood
29700	Flat Batteries	15/02/2023	28285	785916	15/02/2023	Ask Supervisor		Justin Debney
29023	REPLACE SEAT BELT - NEW ONE ON PARTS RACK	15/12/2022			27/02/2023	Ask Supervisor		Juston Free
28799	Prestart Defect - Tailgate latch engaging correctly when rai	28/11/2022			01/12/2022	Repair Next Service		
28788	28500 hours service	26/11/2022	28442	46396	09/12/2022	Routine Service		David Wood
28610	Exhaust leak	10/11/2022	28326	45112	07/11/2022	Repair Next Service		Clay Baran
28564	Isolator	07/11/2022	28313	45108	24/10/2022	Repair Next Service		
28578	Clutch freeplay	07/11/2022	28313	45108	01/11/2022	Repair Next Service		
28472	weld plate on tailgate hinge	31/10/2022	28242	44669	29/10/2022	Ask Supervisor		Jordan Humberdross David Wood
28460	Prestart Defect - Cleanliness Failed	29/10/2022			31/10/2022	Repair Next Service		Anthony Craft
28416	Prestart Defect - cannot split gears	25/10/2022			25/10/2022	Ask Supervisor		Trevor Mbrtimer
28345	turbo leak and oil leak	16/10/2022	28225	44284	13/10/2022	Ask Supervisor		David Wood
28334	Exhaust leak and oil leak	14/10/2022	28215	43914	14/10/2022	Ask Supervisor		
28321	28250 hours service	13/10/2022	28203	43486	31/10/2022	Routine Service		Scott Debney
28005	Repair front bumper	07/09/2022	27982	38134	07/09/2022	Ask Supervisor		Juston Free
27938	replace drive tires	30/08/2022	27953	37425	20/09/2022	Ask Supervisor		Justin Debney
27883	28000 hours service	27/08/2022	27949	37328	20/09/2022	Routine Service		Clay Baran
27350	replace bearings	30/06/2022	27722	30615	11/07/2022	Ask Supervisor		Joseph Giles Justin Debney
27254	27750 hours service	22/06/2022	27696	29864	24/06/2022	Routine Service		Scott Debney
27188	Diff lock light not working on dashboard	15/06/2022			24/06/2022	Repair Next Service		David Wood
27052	Repair	01/06/2022	27569	28329	31/05/2022	Routine Service		Clay Baran
26968	Multiple Prestart Defects	26/05/2022			28/06/2022	Repair Next Service		David Wood
26982	Air bags	26/05/2022	27531	27971	24/05/2022	Repair Next Service		Clay Baran
26911	27500 hours service	20/05/2022	27461	27407	24/06/2022	Routine Service		Clay Baran
26926	Axle seal	20/05/2022	27458	27407	19/05/2022	Repair Next Service		
26443	Seat problem	25/03/2022	27330	26124	19/03/2022	Repair Next Service		

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority/Service	Item Status	Assigned To/Completed By
26049	Right front hub seal U/S	11/02/2022			16/02/2022	Ask Supervisor		
26029	Reported brakes not effective on circuit. Pedal going to flo	10/02/2022	27106	22416	10/02/2022	Ask Supervisor		
25772	Tie road ends	14/01/2022	26951	20787	14/01/2022	Repair Next Service		
25719	Nexus checkover	11/01/2022	26929	20571	04/01/2022	Repair Next Service		
25721	Evaporator clean	11/01/2022	26929	20571	07/01/2022	Repair Next Service		
25629	PTO not working	20/12/2021			21/12/2021	Ask Supervisor		Morgan Holcombe
25608	27000 hours service	17/12/2021	26944	19520	05/01/2022	Routine Service		Saul Whaley
25602	Tarp is in really bad condition	16/12/2021			11/01/2022	Repair Next Service		David Wood
25590	Drivers side speaker faulty	15/12/2021			21/02/2022	Repair Next Service		Stephen Ware
25569	Air Conditioner	13/12/2021			21/12/2021	Ask Supervisor		David Wood
25547	Multiple Prestart Defects	10/12/2021			21/12/2021	Ask Supervisor		Clay Baran
25548	Air cleaner	10/12/2021			10/12/2021	Repair Next Service		
25557	Tailgate latches	10/12/2021			13/12/2021	Repair Next Service		Scott Wiggins
25160	Drivers seat broken headrest	25/10/2021			26/10/2021	Repair Next Service		Saul Whaley
25146	Drivers seatbelt wont come out	22/10/2021			09/11/2021	Ask Supervisor		Saul Whaley
25125	P/s front inside drive tyre needs replacing and fuel gauge	21/10/2021			16/02/2022	Repair Next Service		David Wood
24885	ac not working, splitter stuck in low range	22/09/2021			09/10/2021	Repair Next Service		Saul Whaley
24868	26750 hours service	21/09/2021	26700	16282	30/11/2021	Routine Service		David Wood
24865	Check tracker , not reporting	20/09/2021	26691	16072	20/09/2021	Ask Supervisor		Trevor Mortimer
24848	PTO actuator	17/09/2021			11/10/2021	Ask Supervisor		David Wood
24832	Mudflaps	15/09/2021			15/09/2021	Repair Next Service		Clay Baran
24659	Prestart Defect - Load Secure Failed	26/08/2021			30/08/2021	Repair Next Service		Clay Baran
24660	Prestart Defect - Next Service Correct Failed	26/08/2021			27/08/2021	Ask Supervisor		David Wood
24518	Prestart Defect - Instrument operational and labelled Failed	17/08/2021			18/08/2021	Ask Supervisor		Sean McMonagle
24519	Prestart Defect - Air Conditioner functional (where fitted) F	17/08/2021			20/08/2021	Ask Supervisor		Morgan Holcombe
24526	Prestart Defect - Seat suspension and adjustments ok Failed	17/08/2021			18/08/2021	Ask Supervisor		Sean McMonagle
24395	26500 hours service	07/08/2021	26464	9732	17/08/2021	Routine Service		Clay Baran
24386	Door Alarm	06/08/2021			07/08/2021	Repair Next Service		David Wood
24289	PTO leaking	29/07/2021	26225	9004	29/07/2021	Ask Supervisor		Morgan Holcombe
24236	26250 hours service	25/07/2021	26201	7869	13/08/2021	Routine Service		David Wood
24047	Heater not working	13/07/2021			23/07/2021	Repair Next Service		David Wood
23875	repair tailgate hinges	28/06/2021	26064	2804	28/06/2021	Ask Supervisor		Scott Wiggins
23708	Truck not starting	15/06/2021	26059	2654	12/06/2021	Repair Next Service		Toowoomba Branch WSHOP - R
23400	250 hr service 26250hrs	21/05/2021	26039	2120	20/05/2021	Repair Next Service		Toowoomba Branch WSHOP - W
23373	noisy clutch	20/05/2021	26035	2111	04/06/2021	Routine Service		Toowoomba Branch WSHOP - W
23374	gear knob issues	20/05/2021	26035	2111	21/05/2021	Routine Service		Toowoomba Branch WSHOP - W

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Next Service	Item Status	Assigned To	Completed By
23203	Fuel pump leaking Break down	20/05/2021 02/05/2021	26035 26002	2111 825	19/05/2021 28/05/2021	Repair	Next Service Repair Next Service		Toowoomba Branch WSHOP - W	Toowoomba Branch WSHOP - W
23183	Exhaust collapsed needs repair asap	30/04/2021			12/05/2021		Ask Supervisor		Toowoomba Branch WSHOP - W	
23081	GPS tracker not working	22/04/2021	25984	4	21/04/2021		Repair Next Service		Toowoomba Branch WSHOP - W	
23047	26000 hours service	20/04/2021	25949	3	28/06/2021		Routine Service		Toowoomba Branch WSHOP - W	
22993	Replace steer tyres	13/04/2021	25700	2	13/04/2021		Routine Service		Toowoomba Branch WSHOP - W	
22957	Power steering box leak	09/04/2021	25700	2	13/04/2021		Ask Supervisor		Toowoomba Branch WSHOP - W	
20644	Check for connectfleet tracker/ inspect tarp/Quarter glasses	12/02/2021	25700	2	15/04/2021		Ask Supervisor		Toowoomba Branch WSHOP - W	
20324	check over for use on monday	06/02/2021	25700	2	06/02/2021		Repair Next Service		Toowoomba Branch WSHOP - W	
16966	fuel line	24/11/2020	25700	2	24/11/2020		Do Not Operate		Toowoomba Branch WSHOP - W	
16490	2000hr service	17/11/2020	25700	2	16/11/2020		Routine Service		Toowoomba Branch WSHOP - W	
16402	Aircon issue	16/11/2020	25700	2	06/11/2020		Repair Next Service		Toowoomba Branch WSHOP - W	
15692	Prestart Defect - Cleanliness Failed	05/11/2020			09/12/2020		Repair Next Service		Toowoomba Branch WSHOP - W	
15724	Gears won't select by the splitter just neutralizes gearbox	05/11/2020	25700	2	07/11/2020		Repair Next Service		Toowoomba Branch WSHOP - W	
13775	Electrical Repairs	02/10/2020	25700	2	06/10/2020		Do Not Operate		Toowoomba Branch WSHOP - W	
13404	Fuel pump, Starting electrical issue. Completed @ 25894hrs.	25/09/2020	25700	2	25/09/2020		Do Not Operate		Toowoomba Branch WSHOP - W	
13352	First Aid to be Checked	24/09/2020			20/10/2020		Routine Service		Toowoomba Branch WSHOP - W	
13353	Fire Extinguisher to be Checked	24/09/2020			20/10/2020		Routine Service		Flashpoint Fire Chad	
12329	Tracker not recording, to be swapped for an MMS one	02/09/2020			21/09/2020		Repair Next Service		Toowoomba Branch WSHOP - W	
12114	Breakdown. Fuel Leak.	27/08/2020	25894		01/09/2020		Repair Next Service		Toowoomba Branch WSHOP - R	
11438	Prestart Defect - Fuel level and leaks Failed	11/08/2020			14/09/2020		Do Not Operate		Toowoomba Branch WSHOP - W	
10913	25750 hours service	29/07/2020	25700	2	09/12/2020		Routine Service		Toowoomba Branch WSHOP - W	
10884	Prestart Defect - Power Steering Fluid Failed	28/07/2020	25894		02/09/2020		Repair Next Service		Toowoomba Branch WSHOP - W	
10338	TARP NOT WORKING	03/07/2020			07/07/2020		Routine Service			
10236	Tarp Needs replacing	29/06/2020			07/07/2020		Ask Supervisor			