

Fleet Number	Make	Model	Registration Number	Description	Phone 1
802	WESTERN ST	4864FXB	XQ53LN	B-DOUBLE	

Vehicle Notes

4/7/2013-Hardwire fridge-Brisbane Truck Centre
 3/7/2014-Repair small air leak and replace intake throttle valve warranty-Detco
 16/10/14 - 307622 - Replace belts on alternator - Brisbane Truck Centre
 2015
 13/04/15 - Cutout melted airline and reassemble - Brisbane Truck Centre
 06/05/15 - Replace Anderson plug, charge lead, smart solenoid, 2 x cable lugs and reset breaker - Truck Electrics
 30/06/15 - 476586 - Replace acc belt (supplied) and top up coolant - Central West Diesel
 01/07/15 - Change koolkat batteries - Briskair
 06/07/15 - 472159 - Repair melted airlines - Brisbane Truck Centre
 22/07/15 - Ash clean - Penske
 18/10/15 - 535247 - fit new tyre 295/80R22.5 - Bridgestone
 28/10/15- Replace tyre 295/80R22.5 - Beerwah Tyres
 07/11/15 - 551564 - Fit new tyre 11R22.5 - Bridgestone
 30/11/12 - Replace suzi coil fitting between truck & "A" trailer - North star Motors
 26/11/15 - diagnose koolkat a/c system fault - BRISKAIR
 19/11/15 - QV-10-QV - service call to yard indicators not flashing - fault found flasher unit incorrect - supply and fit flasher unit retest flashers ok - K & C INDUSTRIES
 4/02/16 - fit starter motor - prestige auto electrical
 15/03/16 - 295/80r22.5 hkookah33 152/148m - beerwah discount tyres
 27/07/18- Replace rear axle tyres l/h

 02/10/20- Painted rail chassis.
 02/10/20- Welded 4pcs s cam bracket
 12/10/20- Installed hoses and regassed. Mechanic: Sal
 13/10/20- Replaced engine, new engine oil. Rebuild gearbox, new gearbox oil. Clean our radiator, new coolant. Power steering filter and oil, new water seperator filter. New return fuel, cooler, line, new bottom coolant hose. New r/h rear mudguard, new front mudflaps. New suzi coil male and female fittings. Fix air leak. New starter motor, flushed bugs out of radiator. New drive tyres, hub cap covers, tighten rear reverse light. New front and rear engine mounts. New clutch, drive tyres. Mechanics: John Pukeroa, Lachlan Bartz
 15/01/2021- Weld broken mirror braket, Fix UHF braket, Install over speed buzzer - Sal/03/2021- Repair aircon add gas- Sal
 07/04/2021- replace 2x set king pin- 264861km- Nick, Tristan
 09/04/2021- Checked Turbo- 264861km- Jesse
 21/04/2021 - WESTAR INC WHCDH150434 - failed fan hub, replace major kit, belt, fan xd11 + fan belt 2700mm
 13/05/2021- Fixed/welded radiator support braket LH- Bayden, Arman Liam
 15/05/2021- Replace LH fuel tank strap, made new igniton key, radiator support braket previously repair- all okay- 281871km- Chris
 29/06/2021 - PENSKE INV DBCSB29520 - warranty New crate engine installed
 30/06/2021- check mirror heaters all okay, check spotter mirror all okay, replace mirror light bulb, replaced LH parker bulb, adjusted light bar, check air leak fixed 1x hose/ fitting near cross memeber under checker plate, new purge valve in air dryer fitted, intake braket broken,repair - 296207km- Lachlan
 01/07/2021- adjusted heater control cable, resealed windscreen, fit auxillary power socket- Lee
 02/07/2021- replace fittings on air tank x4, replace fitting near airbag x1 - Bayden
 26/07/2021- rebuilt turn table, cleaned front diff- 308617km- Hamish
 05/08/2021 - penske invoice DBCSB30839 - replace pipe hose and air filter
 05/08/2021- **** new a/c compressor**** chnage reciever dryer, regas- 316701km- Sal
 05/08/2021- Pipe hose air suction anf air filter radial seal- done at Penske-
 24/08/2021- **** New steering box**** replace auto greaser piston and look for problem in auto greaser system. replace auto greaser injector- 322178km- Jono
 30/08/2021- look for steering fault, remove drag link to check king pin . remove auto grease lines and grease king pins. remove steer tyres and replace/balance. look for knock in bonnet found missing bolt that needs helicoil. check auto greaser problem and replace protection valve. auto greaser now working. adjust heat control on a/cadditional fix heater- Jono/Sal
 31/08/2021- remove LH bonnet bracket and radiator stay. remove LH earth bank, ziptie wiring and heater core lines. cut out and tap out plate for bonnet bracket. refit bracket and wiring, reconnect batteries, fit indicator stalk- Jono.
 09/11/2021- front and back diff pinion seal, aircon regreased- Jake.c.
 10/11/2021- replace driver side window and regulator- 361348km- Arman, Jesse
 24/11/2021- mount sealreplaced on test drive. clean out breather- Jameson
 14/12/2021- replace front diff breather, tighten ubolt front end, were very loose. replace input pinion seal and top up FD- 382270km- Lachlan
 12/01/2022- repair indicator malfunction- Jake.c diff reseal FD and bearing cover reseal- Jono
 13/01/2022- chnage front spring pin & bushes- 396160km- Fernan
 18/01/2022- repair aircon add gas. chnage thermostat, check bunk cooler and gas- Sal
 04/02/2022- chnage front diff input seal, hosed ut radiator- Jesse

Vehicles

802

Fleet Number	Make	Model	Registration Number	Description	Phone 1
05/02/2022-				repair bunk cooler chnage reciver dryer and tx valve. truck repairs a/c reciver drier and regas- Sal	
09/02/2022-				fix new bunk cooler batteries- 410521km- Jake.c	
18/02/2022-				fixed uhf hanger tab, new book fleet maintance one. fixed 2x airleak on tank and dryer. tighten guard brackets. tighten steering arm pinch bolt- Hamish	
24/02/2022-				replace cab bunk aircon batteries- Liam	
14/04/2022-				turbo has minimal in-out movement. ty approval. FD pinion sela starting to leak- monitor.- 438541km Jake.P & Shaun	
20/04/2022-				removed EGR control moduel and fitted new one- 438542km- Shaun & jake	
01/06/2022-				greased turn table, filled auto greaser. repaired air leak on hose at relay valve. changed front diff pinion seal and nut. DPF burn to be done on night shift. - Jake.c	
21/06/2022-				fix heater, check demister. replace blown light bulb and check heating problems- Sal	
17/06/2022-				replaced FD input pinion seal, was leaking. checked for airleaks. replaced LH & RH rear engine mounts. put new brakes on LH rear drive and spring kit. replaced turn table to bigger one for the bigger king pins. - 453399mk- Liam	
23/06/2022-				found DPF issue, tested batteries - Lachlan	
30/06/2022-				fit LED lights, front diff oil leak. washed around diff. pinion seal leaking and plate & diff oil pump. removed tail shaft- removed yoke. replaced seals and gasket. chnage a/c stepper rotor- Jake.C & Sal	
11/07/2022-				fix dash and gauge. fix head light RH side. fix LH bonnet bracket- Sal	
12/07/2022-				repair driver seat and shocky bracket. fix and retite bonnet grill. fix side bonnet bracket- Sal	
12/07/2022-				swap turn table from 842 to 82. and swap 50mm turn table back on to the back of 802- Macka	
29/7/2020				- changed aircleaner - hjordy	
29/7/2022-				new stereo- sal.	
05/10/2022				- KLAAS DIESEL INVOCIE 8612 - REPLACE STARTER MOTOR	
11/10/2022				- replaced fan belt, front diff change - laim, euan	
4/11/2022				- replaced *GEARBOX,CLUTCH*525951KM - JAKE	
4/11/2022				- repalced GEARBOX, clutch, rear main seal - jake.c, lachlan - 252951km	
31/1/2023-				566,820kms - Replaced front cab mounts, fuel cooler bypassed, bonnet grill secured, replaced bonnet mounts, replaced LHS steer brakes , replaced pinion seal - Blaine, macka,michael Fernan	
23/02/2023				- 583,976kms - Replaced engine fan - Lachlan	
23/02/2023-				584,095kms - Swapped CPC module from 1055, cleared codes, swapped turbo timer from 1055, washed diff down - Jake, Euan	
2/03/2023				609,605kms Fixed front grill and fiber glassed - SAL/Brampton	
31/03/2023				609,605kms -, replaced DPF outlet sensor, replaced RHS ride height valve, repaired airleaks (Jake.C)	
30/03/2023				609,605kms Diagnosed DPF burn issue. Pressure tester intercooler(found leak). Replaced intercooler. Found DPF outlet temp sensor spring reading. Stereo fixed (SAL) . (jake.c)	
12/04/2023				- 615,605kms welded air compressor mount, Ran new line for brake booster, replaced pinon seal, welded header tank , put new brakets and bolts for back plate (Brampton/Johl)	
16/04/2023				605,459kms Replaced 4xbatteries (arman)	
04/05/2023				- 626,640kms -Fitted new alternator -Damo	
06/06/2023				- De registered	