

# Tyrepower Albany

119 Chester Pass Road

Albany WA 6331

Ph: 08 9842 1300

Fax: 08 9842 1130

E-mail: albany@tyrepower.com.au

Tyrepower Albany

ABN: 19 776 923 642 MRB6520



## Tax Invoice 167866 (Proforma)

Date: 27 Apr 23

Customer: CASH

Terms: Cash

ADCO HOLDING PTY LTD

Albany WA

Written By:   
Salesperson:

Contact:

Deliver To: Cash Sale

Mobile:

Home Ph:

Bus Ph:

Fax:

Email: No

Albany WA

Odometer In: 0

Out: 0

Customer PO#:

Vehicle Details:

Item	Description	QTY	Unit Price (Excl GST)	Unit Price (Incl GST)	Total (Incl GST)
1130273	Toyo 700R16 117N M131	4	290.91	320.00	1280.00
NTF	New Tyre Fitting	4	N/C	N/C	N/C
NTB	New Tyre Balancing	4	N/C	N/C	N/C
NTV	New Tyre Valve	4	N/C	N/C	N/C
T1607754	ONTRAKA 7.00/7.50 R16 15 Ontraka TR75	4	45.45	50.00	200.00

Direct deposit details -

Total includes GST of 134.54

Totals Items 8

Total \$ 1480.00

### Terms and Conditions of Trade

These goods are sold in accordance with the manufacturer's terms and conditions of sale as published from time to time. All payments are to be made in full, without any deduction of any nature, including by way of set-Off. Acceptance of these goods implies acceptance of such conditions.

Received by: Name \_\_\_\_\_ Signature \_\_\_\_\_ Date: / /

# TAX INVOICE

[REDACTED]

**Invoice Date**

15 Mar 2024

**Invoice Number**

INV-3259

**Reference**

Toyota Coaster 1GDE833  
171160km CEL on, no  
power

**ABN**

52 621 484 660

[REDACTED]

Description	Quantity	Unit Price	GST	Amount AUD
Arrange for vehicle to be towed in from Harvey Check on fault codes, found DPF soot level exceded Cleared all codes Carried out regen of DPF Replaced worn centre bearing before vehicle could be driven Added DPF cleaner to fuel tank Test drove vehicle extensively, all okay Repaired hand brake mechanism Suspect vehicle could not complete manual regen due to hand brake mechanism detached from body. Replace LH front glass Test drive again, all okay	6.00	130.00	10%	780.00
Centre bearing	1.00	330.00	10%	330.00
Nuts	2.00	13.64	10%	27.27
DPF cleaner	2.00	40.91	10%	81.82
Scan tool	1.00	72.73	10%	72.73
Towing Harvey-Perth	1.00	1,172.73	10%	1,172.73
Glass Replacement	1.00	568.18	10%	568.18
			Subtotal	3,032.73
			TOTAL GST 10%	303.27
			<b>TOTAL AUD</b>	<b>3,336.00</b>

**Due Date: 15 Apr 2024**

Banking Details

[REDACTED]

Satisfaction guarantee. If you have any questions about the work performed or any concerns please let me know personally and I'll be



## Sundown Automotive

0408961812

Sundownautos@outlook.com.au

ABN 49 610 112 289

### Tax Invoice

INVOICE TO



INVOICE

1071

DATE

26/11/2022

DUE DATE

26/11/2022

DATE		DESCRIPTION	GST	QTY	RATE	AMOUNT
	Parts	DPF Temp Sensor Genuine toyota	GST	1	945.00	945.00
	Labour	Remove and replace sensor	GST	1	90.00	90.00

1GDE833  
165000km

Dpf Temp sensor had failed causing limp mode and low power.

INCLUDES GST TOTAL


94.09

TOTAL

1,035.00

BALANCE DUE

**A\$1,035.00**





## Sundown Automotive

0408961812

Sundownautos@outlook.com.au

ABN 49 610 112 289

### Tax Invoice

INVOICE TO



INVOICE

1065

DATE

01/10/2022

DUE DATE

01/10/2022

DATE		DESCRIPTION	GST	QTY	RATE	AMOUNT
	Labour	Coaster Service (8l Oil and Filter)	GST	1	245.00	245.00
	Parts	h7 Globe	GST	1	17.00	17.00
	Parts	Parker Globes	GST	2	2.00	4.00

1GDE833  
162312km

Rh Rear tail light broken  
Have ordered a replacement

INCLUDES GST TOTAL

24.18

TOTAL

266.00

BALANCE DUE

**A\$266.00**





## Sundown Automotive

0408961812

Sundownautos@outlook.com.au

ABN 49 610 112 289

## Tax Invoice

INVOICE TO



INVOICE

1039

DATE

30/01/2022

DUE DATE

30/01/2022

DATE		DESCRIPTION	GST	QTY	RATE	AMOUNT
	Mobile Labour	Service on coaster bus (15w40 HD 8L + Oil filter)	GST	1	275.00	275.00
	Parts	Taillight globe	GST	2	3.50	7.00
	Mobile Labour	Repaired auto door mechanism Had a bent lever not locking in from auto to manual.	GST	1	90.00	90.00
	Parts	Air filter ryco	GST	1	49.00	49.00
	Parts	700r16 tyres maxxis	GST	2	277.00	554.00
	Parts	700r16 tube	GST	2	35.00	70.00
	Mobile Labour	Tyre fitting	GST	2	50.00	100.00

1GDE833 coaster bus  
139453km

New tyres fitted to rear right as inner had blown out  
Will require new batteries and terminals soon

INCLUDES GST TOTAL

104.08

TOTAL

1,145.00

BALANCE DUE

**A\$1,145.00**



## Sundown Automotive

0408961812

Sundownautos@outlook.com.au

ABN 49 610 112 289

### Tax Invoice

INVOICE TO



INVOICE

1046

DATE

06/03/2022

DUE DATE

06/03/2022

DATE		DESCRIPTION	GST	QTY	RATE	AMOUNT
	Parts	Upper ball joints	GST	2	178.00	356.00
	Labour	Remove and replace upper balljoints front	GST	2	90.00	180.00
	Parts	Tail light globes	GST	2	2.00	4.00
	Parts	Emergency exit globes	GST	4	2.00	8.00
	Labour	Reroute seat belts and fix seat belts throughout to retract correctly	GST	1	90.00	90.00
	Labour	Secured interior panels behind drivers seat	GST	1	45.00	45.00
	Labour	Remove tint from front windows And clean glue residue off	GST	2	90.00	180.00
	Parts	700r16 maxxix	GST	1	277.00	277.00
	Parts	700r16 tube	GST	1	35.00	35.00
	Mobile Labour	Tyre fitting on split rim	GST	1	50.00	50.00
	Parts	Pits inspection charge	GST	1	150.00	150.00
	Parts	Temporary move permit	GST	1	35.00	35.00

Coaster pits requirements  
1GDE833

Replacement throttle interlock on order

INCLUDES GST TOTAL

128.17

TOTAL

1,410.00

BALANCE DUE

**A\$1,410.00**



## Sundown Automotive

0408961812

Sundownautos@outlook.com.au

ABN 49 610 112 289

### Tax Invoice

INVOICE TO



INVOICE

1065

DATE

01/10/2022

DUE DATE

01/10/2022

DATE		DESCRIPTION	GST	QTY	RATE	AMOUNT
	Labour	Coaster Service (8l Oil and Filter)	GST	1	245.00	245.00
	Parts	h7 Globe	GST	1	17.00	17.00
	Parts	Parker Globes	GST	2	2.00	4.00

1GDE833  
162312km

Rh Rear tail light broken  
Have ordered a replacement

INCLUDES GST TOTAL

24.18

TOTAL

266.00

BALANCE DUE

**A\$266.00**



Complete Auto Care Bundaberg

Tax Invoice

2 Phoebe Crescent  
West Bundaberg, QLD 4670  
(07) 4152 2460  
accounts@completeautocarebundaberg.  
completeautocarebundaberg.com.au

A.B.N. 60660511295  
Date: 13/03/2025  
Job #: 55624

Ph: [REDACTED]	Registration	1GDE833
Mob: [REDACTED]	Make/Model	TOYOTA COASTER
	Colour	
	Odometer	180787
	VIN	

Item	Description	Quantity	Unit Price	GST	Total
LABOUR					
LABOUR SERVICE	Labour Charged For Log Book Service	1.15	\$170.00	\$17.77	\$195.50
Labour Total					\$195.50
PARTS					
DX 5W40	Magnatec Professional DX 5W40	8.50	\$17.00	\$13.14	\$144.50
Z777	OIL FILTER	1.00	\$46.00	\$4.18	\$46.00
Z699	FUEL FILTER	1.00	\$64.00	\$5.82	\$64.00
A340	AIR FILTER	1.00	\$59.00	\$5.36	\$59.00
WIPER	Wiper Blade Fitted	2.00	\$10.00	\$1.82	\$20.00
Parts Total					\$333.50
CONSUMABLES					
NPN01	Environmental Compliance Fee Oil Waste	1.00	\$12.00	\$1.09	\$12.00
CONS	General Consumables Used	1.00	\$15.00	\$1.36	\$15.00
Consumables Total					\$27.00
Subtotal					\$505.45
GST					\$50.55
Total					\$556.00
Balance Due					\$556.00

Invoice Notes

FRONT TYRES SWAPPED WITH 2 SPARES  
OIL LEAKING FROM INTERCOOLER - MINOR  
SUMP PLUG WAS LEAKING OIL OVER SUMP & AROUND BELL HOUSING - WASHER REPLACED  
RECOMMEND COOLANT FLUSH (ONLY WATER)  
FRONT BRAKES 50%+  
REAR BRAKES 60%+

PLEASE NOTE OUR BANK DETAILS HAVE RECENTLY CHANGED, PLEASE MAKE SURE YOU ARE PAYING INTO THE CORRECT ACCOUNT -----



Warranty on second hand parts are according to the suppliers warranty. The minimum warranty is 30 days unless, as stated on the invoice. warranty does not cover labour, freight and any additional repairs carried out at the time.



# Westrans Services WA Pty Ltd

Mrb 2711

15 valentine street  
Kewdale WA 6105  
ABN 85 099 451 591  
Tel: 08 9356 1333 Fax: 08 9356 1832  
Email: accounts@westranswa.com.au  
Website: www.westranswa.com.au

## Tax Invoice

Inv. No.	32,829	Date	19/7/24	Order No.	-	Sales ID	-
----------	--------	------	---------	-----------	---	----------	---

Client Details	Vehicle Details
	Rego: 1GDE833 Make/Model: TOYOTA COASTER Year: 2011 VIN#: JTGFP5184045

Account	-	Home	-	Work	-	Mobile	
---------	---	------	---	------	---	--------	--

### Work Done

Checked vehicle for suspension not level - jacked vehicle up, adjusted torsion bars and checked for vehicle sitting level - ok  
Replaced right hand head light assembly and polished left hand head light, replaced various blown light globes as required  
Replaced rear emergency door catch, handle and alarm switch, replaced missing trim onto back door - tested operation ok  
Checked operation of exhaust brake - found valve assembly seized, removed and replaced with new part, test drove and found system not operating, checked fuses, wiring and operation of all pedal switches - found faulty wiring to actuator and corroded fuse holders - repaired faults and tested ok  
Replaced missing windscreen washer tank and pump and motor assembly - tested operation ok  
Replaced missing throttle pedal lock out assembly - checked operation ok  
Removed 2 seat belt assemblies, straightened belts and lubricated mechanism - fitted back into seats and tested ok

### Services, Parts & Labour

#### Mechanical

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
2 hrs	Diagnose suspension fault	\$135.00	\$270.00	\$27.00 GST	\$297.00
1	Consumables	\$30.00	\$30.00	\$3.00 GST	\$33.00
1	Environmental	\$10.00	\$10.00	\$1.00 GST	\$11.00
2 hrs	Various light repairs	\$135.00	\$270.00	\$27.00 GST	\$297.00
2	Globe h7 12v 55w	\$10.88	\$21.76	\$2.18 GST	\$23.94
1	Globe wedge 12v 5w	\$0.87	\$0.87	\$0.09 GST	\$0.96
1	Headlamp rh	\$533.53	\$533.53	\$53.35 GST	\$586.88
1	Globe 12v 21w sp amber	\$3.92	\$3.92	\$0.39 GST	\$4.31
2	Oring	\$4.76	\$9.52	\$0.95 GST	\$10.47
4 hrs	Check/repair door handle operation	\$135.00	\$540.00	\$54.00 GST	\$594.00
1	Trim, back door	\$159.47	\$159.47	\$15.95 GST	\$175.42
1	Handle emergency	\$12.75	\$12.75	\$1.28 GST	\$14.03
1	Switch	\$49.45	\$49.45	\$4.95 GST	\$54.40
1	Catch back door	\$4.94	\$4.94	\$0.49 GST	\$5.43
6 hrs	Repair exhaust brake	\$135.00	\$810.00	\$81.00 GST	\$891.00
1	Wiring diagram	\$62.02	\$62.02	\$6.20 GST	\$68.22
1	Check/diagnose exhaust brake issue	\$788.87	\$788.87	\$78.89 GST	\$867.76
1	Valve assembly, exhaust	\$615.03	\$615.03	\$61.50 GST	\$676.53

8	M8 hardened flat washer	\$0.35	\$2.80	\$0.28 GST	\$3.08
4	M8 nyloc nut	\$0.07	\$0.28	\$0.03 GST	\$0.31
4	M8 X 50 Metric Bolt	\$2.00	\$8.00	\$0.80 GST	\$8.80
1.5 hrs	Check/repair wipers	\$135.00	\$202.50	\$20.25 GST	\$222.75
1	Motor and pump assembly	\$234.20	\$234.20	\$23.42 GST	\$257.62
1	Tank assembly, washer	\$45.00	\$45.00	\$4.50 GST	\$49.50
0 hrs	Inspect / repair / replace shock absorbers	\$135.00	\$0.00	\$0.00	\$0.00
2	Front shock absorber	\$0.00	\$0.00	\$0.00	\$0.00
2.5 hrs	Check/repair accelerator fault	\$135.00	\$337.50	\$33.75 GST	\$371.25
1	Actuator assembly, accel	\$1,611.14	\$1,611.14	\$161.11 GST	\$1,772.25
1 hr	Check/ repair replace seat belt	\$135.00	\$135.00	\$13.50 GST	\$148.50
1	Spray silicon gensil	\$9.54	\$9.54	\$0.95 GST	\$10.49
			<b>\$6,778.09</b>	<b>\$677.81</b>	<b>\$7,455.90</b>

#### Vehicle Report

Vehicle has oil leak from sump plug - recommend new plug and washer fitted at next service

Vehicle had rear main oil seal leak - recommend replacement if a clutch replacement is required in the future

#### Financial Summary

Total (Ex. Tax)	\$6,778.09	Terms	Cash on delivery
Tax Total	\$677.81	Paid	\$0.00
<b>Total (Inc. Tax)</b>	<b>\$7,455.90</b>	<b>Balance</b>	<b>\$7,455.90</b>

Thank you for your business

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_ c.o.d.

<b>Order No.</b>	OR13101593
<b>Page</b>	1
<b>Printed</b>	03/05/2023 11:04

<b>Customer</b>	CASHP
<b>Type</b>	Cash
<b>Customer P.O.</b>	AL464
<b>Sales Rep.</b>	SB

Quotation is valid for 14 business days from receival date

Ridgerack Pty Ltd  
 352-368 Albany Highway, ALBANY, WA 6330  
 T: (08) 9842 1772  
 admin@albanytoyota.com albanytoyota.com.au  
 ABN: 11 065 006 359 ACN: 065 006 359  
 DL9243 ARC: AU41302 MVRB: MRB8806

REPAIR ORDER No: JC14061082	PAGE: 1
C1 Customer (Cash)	

Guest: [REDACTED]		DATE: 21/06/2023	TIME IN: 8:00 AM	TIME OUT: 5:00 PM	KILOMETERS: 169267	ADVISER: HF
VEHICLE: Coaster STD 4.0L DIESEL Manual Bus 9301					MONTH/YEAR 01/2011	AIR:
REG. No: 1GDE833		STOCK No:		SELLING DEALER:		
GUEST No: 31429	VIN: JTGFP518404500813			ENGINE No: N04CUH13607		
CONTACT NAME: [REDACTED]		COLOUR/TRIM French Vanilla/Charcoal Grey			ORDER No:	
CONTACT NUMBERS: M: [REDACTED]		WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date: 18/05/2011

	PRICE	QTY/HRS	AMOUNT
<b>JOB DETAILS</b>			
JOB 1	CARRY OUT FURTHER INVESTIGATION INTO EGR CODE EVIDENT ON SYSTEM Carried out inspection into engine light on dash and found the following codes evident within the system:  P2BAC - Deactivation of the EGR P2BAB - NOx Exceedance incorrect EGR Flow P05804 - Brake switch "A"/"B" Correlation  Carried out inspection into P2BAC and P2BAB and found the EGR cooler to be blocked up and due to the size of the EGR and age of vehicle, recommend replacing the EGR assembly and EGR cooler.  Upon further inspection, found number 2 air hose to be split to the intake pipe number 1.  Recommend replacing the EGR assembly, EGR cooler and number 2 air hose with new coolant.  Will require further diagnosis into fault code P0504 - Brake Switch "A"/"B" correlation upon repair completion.		300.00
<b>JOB 1 SUBTOTAL</b>			<b>300.00</b>
<b>JOB DETAILS</b>			
JOB 2	REMOVE AND REPLACE EGR ASSEMBLY, EGR COOLER ASSEMBLY, NUMBER 2 AIR HOSE AND COOLANT Removed and replaced the EGR and EGR cooler assemblies and intake pipe number 2 as required.  Removed and replaced coolant as required.  Test drove with Toyota trade plates due to vehicle being un-registered, all okay at time of inspection.  Carried out further investigation into P0504 and was unable to fault at time of repairs. Suspect the minebar is causing fault codes to be evident due to water ingress through the harness.		1,500.00
PRT	TOY 0888980431	SUPER LL COOLANT 5L	1 37.73
***** CONTINUED *****			

## VEHICLE RELEASE

PREFERRED CONTACT METHOD

☐ WORK EXPLAINED   ☐ VEHICLE WASHED   ☐ FLOOR MAT SECURITY EXPLAINED   ☐ LETTER   ☐ PHONE   ☐ DO NOT CONTACT  
☐ COST EXPLAINED   ☐ ALL COURTESY ITEMS REMOVED   ☐ EMAIL   ☐ MOBILE/SMS

Ridgerack Pty Ltd  
352-368 Albany Highway, ALBANY, WA 6330  
T: (08) 9842 1772  
admin@albanytoyota.com    albanytoyota.com.au

ABN: 11 065 006 359    ACN: 065 006 359  
DL9243    ARC: AU41302    MVRB: MRB8806

REPAIR ORDER No: JC14061082	PAGE: 2
C1    Customer    (Cash)	

Guest: <div></div> <div></div> <div></div>	DATE: 21/06/2023	TIME IN: 8:00 AM	TIME OUT: 5:00 PM	KILOMETERS: 169267	ADVISER: HF
	VEHICLE: Coaster STD 4.0L DIESEL Manual Bus 9301			MONTH/YEAR 01/2011	AIR:
	REG. No: 1GDE833	STOCK No:	SELLING DEALER:		
GUEST No: 31429		VIN: JTGFP518404500813		ENGINE No: N04CUH13607	
CONTACT NAME: <div></div>		COLOUR/TRIM French Vanilla/Charcoal Grey			ORDER No:
CONTACT NUMBERS: M: <div></div>		WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:
					RDR Date: 18/05/2011

JOB DETAILS				PRICE	QTY/HRS	AMOUNT
PRT	TOY	1703078482	HOSE ASSY AIR		1	468.23
PRT	TOY	25608E0220	COOLER SUB-ASSY EGR		1	3,562.92
PRT	TOY	25620E0012	VALVE ASSY EGR		1	1,418.09
JOB 2 SUBTOTAL						6,986.97

JOB DETAILS		
JOB 3	REMOVE MINEBAR AND RE-SEAL HOLES	150.00
	Removed minebar wiring as required and re-sealed roof holes from mine bar.	
	Re-inspected, all okay at time of repairs.	
	JOB 3 SUBTOTAL	150.00

LABOUR	\$1,950.00
PARTS	\$5,486.97
SUBTOTAL	\$7,436.97
GST	\$743.70
TOTAL INCLUDES GST	\$8,180.67
DEPOSIT TAKEN	\$6,035.67

PRINTED 21/06/23 08:19:55

VEHICLE RELEASE		PREFERRED CONTACT METHOD		<input type="checkbox"/> LETTER	<input type="checkbox"/> PHONE	<input type="checkbox"/> DO NOT CONTACT
<input type="checkbox"/> WORK EXPLAINED	<input type="checkbox"/> VEHICLE WASHED	<input type="checkbox"/> FLOOR MAT SECURITY EXPLAINED	<input type="checkbox"/> EMAIL	<input type="checkbox"/> MOBILE/SMS		
<input type="checkbox"/> COST EXPLAINED	<input type="checkbox"/> ALL COURTESY ITEMS REMOVED					



## Sundown Automotive

0408961812

Sundownautos@outlook.com.au

ABN 49 610 112 289

## Tax Invoice

INVOICE TO



INVOICE

1050

DATE

24/04/2022

DUE DATE

24/04/2022

DATE	DESCRIPTION	GST	QTY	RATE	AMOUNT
	Mobile Labour	GST	3.50	90.00	315.00
	Call out to brookside, due to engine light reported to be on and engine in limp home mode.				
	Found dpf fault code as it needed a burn off, and it was shutdown prematurely not completing the cycle.				
	Tried to delete fault codes but was unable to, checked for blocked dpf, was clear. Checked wiring to pressure switch and lines were clear. Hard reseted the engine ecu.				
	Took for test drive, no fault codes. Back to full power.				
	Instructed bus drive about the dpf system and showed the check list to follow when dpf light flashes again.				

Brookside 1GDE833

INCLUDES GST TOTAL

28.64

TOTAL

315.00

BALANCE DUE

**A\$315.00**