

























09/12/2014	MPLHEQDZ238	Dozer 238
06/12/2014	MPLHEQDZ238	Dozer 238
04/12/2014	MPLHEQDZ238	Dozer 238
04/12/2014	MPLHEQDZ238	Dozer 238
03/12/2014	MPLHEQDZ238	Dozer 238
29/11/2014	MPLHEQDZ238	Dozer 238
26/11/2014	MPLHEQDZ238	Dozer 238
25/11/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
24/11/2014	MPLHEQDZ238	Dozer 238
23/11/2014	MPLHEQDZ238	Dozer 238
22/11/2014	MPLHEQDZ238	Dozer 238
22/11/2014	MPLHEQDZ238	Dozer 238
22/11/2014	MPLHEQDZ238	Dozer 238
21/11/2014	MPLHEQDZ238	Dozer 238
20/11/2014	MPLHEQDZ238	Dozer 238
16/11/2014	MPLHEQDZ238	Dozer 238
16/11/2014	MPLHEQDZ238	Dozer 238
11/11/2014	MPLHEQDZ238	Dozer 238
11/11/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
10/11/2014	MPLHEQDZ238	Dozer 238
10/11/2014	MPLHEQDZ238	Dozer 238
08/11/2014	MPLHEQDZ238	Dozer 238
06/11/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
03/11/2014	MPLHEQDZ238	Dozer 238
02/11/2014	MPLHEQDZ238	Dozer 238
31/10/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
26/10/2014	MPLHEQDZ238	Dozer 238
23/10/2014	MPLHEQDZ238	Dozer 238
19/10/2014	MPLHEQDZ238	Dozer 238
19/10/2014	MPLHEQDZ238	Dozer 238
18/10/2014	MPLHEQDZ238	Dozer 238
17/10/2014	MPLHEQDZ238	Dozer 238
14/10/2014	MPLHEQDZ238	Dozer 238
13/10/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
03/10/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
20/09/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
17/09/2014	MPLHEQDZ238	Dozer 238
16/09/2014	MPLHEQDZ238	Dozer 238
16/09/2014	MPLHEQDZ238	Dozer 238

13/09/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
07/09/2014	MPLHEQDZ238	Dozer 238
06/09/2014	MPLHEQDZ238	Dozer 238
05/09/2014	MPLHEQDZ238	Dozer 238
02/09/2014	MPLHEQDZ238	Dozer 238
01/09/2014	MPLHEQDZ238	Dozer 238
31/08/2014	MPLHEQDZ238	Dozer 238
31/08/2014	MPLHEQDZ238	Dozer 238
30/08/2014	MPLHEQDZ238	Dozer 238
28/08/2014	MPLHEQDZ238	Dozer 238
26/08/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
23/08/2014	MPLHEQDZ238	Dozer 238
21/08/2014	MPLHEQDZ238	Dozer 238
16/08/2014	MPLHEQDZ238	Dozer 238
15/08/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
06/08/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
03/08/2014	MPLHEQDZ238	Dozer 238
02/08/2014	MPLHEQDZ238	Dozer 238
02/08/2014	MPLHEQDZ238	Dozer 238
30/07/2014	MPLHEQDZ238	Dozer 238
25/07/2014	MPLHEQDZ238	Dozer 238
25/07/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
23/07/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
11/07/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
07/07/2014	MPLHEQDZ238	Dozer 238
05/07/2014	MPLHEQDZ238	Dozer 238
04/07/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
25/06/2014	MPLHEQDZ238	Dozer 238
	MPLHEQDZ238	Dozer 238
12/02/2013	MPLHEQDZ238	Dozer 238

**WO Description**

2 WAY SPEAKER

Start machine and relocate

RFQ motium dozer screen

PM Change Request

PMS-MBM-MPL-HEQDZ-FIRE-26W

PMS-MBM-MPL-HEQDZ-FIRE-26W

PMS-MBM-MPL-HEQDZ-FIRE-26W

PMS-MBM-MPL-HEQDZ-FIRE-26W

Thickness Test Blade Condition

REPLACE RHS TRACK

Repair Mc-i4

AM/FM RADIO NOT WORKING

AM/FM RADIO NOT WORKING AT AL

ALT LIGHT ON DASH

RETURN FREQUENCY LOW, ALARM

AM/FM RADIO SPEAKERS RE NOT W

REPAIR CRACKED WELD IN HANDRAI

DZR238 LADDER HANDRAIL HAS A B

250HR Service and Inspection

DOZER 238 BLOWN RADIATOR HOSE

BRAKE FAULT

Replace Implement ECM

BLADE CONTROL HYDRAULICS NON R

No Hydraulics

ELEC VIDS-EIC FAULT

Ladder hand rail loose

Take Coolant Sample

OIL TEMP SENSOR ERROR

NO DATA IN TELEMETRY

Overhaul A/C system

HEATER NOT WORKING

Leak at fuel sender

4000 hr cat extra

R/H AIR FILTER COVER BOLTS MIS

BLADE CONTROL NOT WORKING

1000 Hr Service and Inspection

NO BLADE CONTROL

VIDS/EIC ERROR CALL SHOP

HEATER NOT WORKING

LADDER WONT GO DOWN

Fuel leak on engine

Fit up ladder Isolator

DOZER HANDRAIL IS MISSING AND

REAR ACCESS WALK WAY HAND RAIL

250 Hr Service and Inspection

Re-seal trans filler tube

TRANSMISSION OIL LOW

Blade raise solenoid fault  
REPLACED BENT TILT LINE ON BAC  
Replace broken track on stock  
UHF NOT WORKING  
HEATER NOT WORKING  
Replace rain caps  
T/C OUTPUT SPEED SENSOR ABNORM  
500 Hr Service and Inspection  
GAUGES ON DASH NOT WORKING  
BLADE RAISE ERROR  
OIL LEAK UNDER MACHINE  
A/c not very cold  
Replace 4 x battery's  
Replace ID stickers  
Replace Ladders assy with cat  
COOLANT HOSE BLOWN  
Replace ladder powerpack  
4000 hr Service and Inspection  
Midlife Rebuild 2021  
WIPERS DONT WORK  
RIGHT HAND CABIN WIPER FAULTY  
NO POWER WHEN PUSHING  
repair hose truckfill.  
500HR SERVICE AND INSPECTION  
Replace bolts in hood lining  
FRONT LIGHTS NOT WORKING  
Broken LH track on stockpile  
CAT D11 7PZ 250HR SERVICE  
AM/FM RADIO NOT WORKING  
FAULTY FUEL GAUGE  
FUEL GUAGE SHOWING EMPTY WHEN  
Replace rear window  
FUEL GAUGE NOT READING CORRECT  
Number 8 coolant entry  
Radaitor cores leaking  
1000HR Service and Inspection  
CAB PRESSURIZER FAN NOT WORKIN  
LOW ON POWER  
Using Engine Oil Note Level  
Oil Leak Transmission Cooler  
LHS Lift Cylinder Leaking  
BLADE NOT TILTING PROPERLY  
ASSIST OPERATIONS WITH TASK  
PUSH ARM TILT CYLINDER EXCESSI  
LEFT HAND SIDE TILT CYLINDER,  
250 Hr Service and Inspection  
DOZER 238 DIESEL LEAK  
RT TILT SOLENOID FAULT

SHUDDER WITH DOZER BLADE  
BLADE WONT RAISE  
Coolant in engine oil  
500 Hr Service and Inspection  
TOPUP COOLANT  
FRONT LH LIGHT BLINKS  
TILT CYLINDER PUSH ARM. EXCESS  
FIT NEW BATTERIES  
BLADE WILL NOT TILT UNDER LOAD  
250 Hr Service and Inspection  
LEFT HAND TILT NOT WORKING  
INLET TEMP FAULT  
RIGHT EXHAUST TEMP ERROR  
2000 Hr Service and Inspection  
L/H TILT SOLENOID ERROR  
250 Hr Service and Inspection  
RTEXH ERROR  
REPLACE ETHERNET SWITCH OF TEL  
A/C FAN NOT WORKING AT ALL  
4000 hr Cat extra  
500 Hr Service and Inspection  
TELEMETRY AERIAL BROKEN  
LOW ENGINE OIL ABOUT 1 INCH BE  
GAUGES ON SCREEN NOT WORKING  
250 Hr Service and Inspection  
BLADE TILT FAULT  
COOLANT LEAK  
E/H FILTER PLUGGED  
1000 Hr Service and Inspection  
INNER AIR FILTERS NEED CHANGIN  
Replace walkways at rebuild  
Dozer 238 A/C Not Cooling  
250 Hr Service and Inspection  
LOW VOLTAGE  
Replace ID Stickers  
Replace LHS ROPS light  
500 Hr Service and Inspection  
TAKE ENG OIL SAMPLE  
Dozer 238 A/C Not Working  
250 Hr Service and Inspection  
TELEMETRY SCREEN BROKEN  
4000hr Service and Inspection  
250 Hr Service and Inspection  
500 Hr Service and Inspection  
REPAIR WIPER  
RHS LIGHT NOT WORKING  
250 Hr Service and Inspection  
AM/FM radio damaged

AM/FM RADIO NEEDS TO BE REPLAC  
ENG OIL OVER FULL  
REPLACE R/H TRACK  
1000 Hr Service and inspection  
2 WAY RADIO NOT WORKING CORREC  
250 Hr Service and inspection  
2 MISSING TRACK BOLTS RH SIDE  
RUBBER MISSING OFF BUTTON ON 2  
REPLACE HAT HOOK IN CABIN  
500 Hr Service and Inspection  
REPLACE BROKEN HELMET HOOK INS  
Repair A/C system  
HELMET HOOKS NEED REPLACING  
AIR CON NOT WORKING  
FLAP BELOW DOOR ON LADDER SIDE  
250 Hr Service and inspection  
C/O Hyd tank  
4000 Hr Cat extra  
BRAKES NEED ADJUSTING & BLADE  
2000 Hr Service and Inspection  
A/C FAN NOT WORKING  
DOZ 238 - I GROWSER BOLT MISSI  
AM/FM RADIO NOT WORKING  
Replace LHS E-bar grub screws  
STRG OIL TEMP ERROR  
250 Hr Service and Inspection  
Fit Bollards to top deck  
Fit Bollards to top of deck  
500 Hr Service and Inspection  
INSPECT COAL CANOPY  
250 Hr Service and Inspection  
NO GUAGES  
1000 Hr Service and Inspection  
LADDER SWIVEL MOUNT BOLTS LOOS  
R/H ROPS LIGHT FALLING OFF  
250 hr Service and Inspection  
RIGHT SIDE TILT CYLINDER HOSE  
AM/FM RADIO NOT WORKING  
BLOWN HYD HOSE ON TAG LINK  
DZ238 Fire Suppression Inspect  
AM/FM RADIO NOT WORKING . NEED  
Linebore rebuild items  
Change hyd tank evac point  
Replace cab mounts  
Replace Trans oil fill tube  
repair a/c in 238  
Replace all minor bogie pins  
Replace pilot accumulator

Move evac to counterweight  
RFQ from Major Rebuild  
AM/FM NOT WORKING  
BOLT MISSING FROM AIR CLEANER  
Overhaul Blade  
DOWN ON POWER WHEN UNDER LOAD  
TOP STEP RUSTY ON LADDER  
REAR ACCESS GATE MISSING  
DOWN ON POWER  
500 Hr Service and Inspection  
INSPECT AND REPLACE FAULTY TW  
INSPECT REPORTED LOW POWER ISS  
AM/FM RADIO FALLING OUT  
HYD. LEAK FROM LADDER  
LH Front bogie pin worn out  
LH arm rest worn out  
DOZER LOSING POWER  
AM FM RADIO NOT WORKING  
250 Hr Service and Inspection  
REPAIR CRACK IN BACK OF BLADE  
DOZ 238 IS LOW ON POWER.  
LADDER STUCK IN RAISED POSITIO  
Low power complaint  
L/H LOWER TILT BEARING U/S  
LOW ENGINE POWER  
4000hr service  
NO LADDER POWER  
ENGINE AND TRANSMISSION OVER F  
2000 Hr Cat extra  
LADDER NOT WORKING  
AIRCON NOT WORKING  
LADDER  
WONT START SEEMS TO BE BATTERY  
LADDER JAMMED IN DOWN POSITION  
250 hr Service and Inspection  
LOST POWER  
FIX LADDER FAULT- WONT RAISE  
Replace tilt pipe  
DAMAGE TO SEAT  
LONG DELAY CHANGING FROM FRWD  
NEEDS DOORS ADJUSTED RATTLING  
Replace leaking hydraulic hose  
Replace hyd hose  
Replace cracked out drive shaf  
T/C output shaft seal leaking  
COOLANT  
500 Hr Service and Inspection  
LOW COOLANT

REPORTED BLADE CRACKED

Fit neqw type LED light to rea

250 Hr service and Inspection

REPLACE MISSING BOLT FROM AIR

NO BLADE TILT

1000 Hr Service and Inspection

Fit cat Blinds to Side windows

DOZER 238 OIL FILLER CAP MISSI

MANUAL SELECT SWITCH ERR

238 air cond faulty

238 A/C not cool

DRIVING THROUGH STEERING CLUTC

STEERING CLUTCHES

Replace Final Drives and SCABS

250 Hr Service and Inspection

Crain and flush coolant system

Fit new type screen in dozer

Replace U/S hyd hose

INNER AIR FILTER CHANGE

500 hr Service and Inspection

Refurb/Replace Mc-i4

STERRING CLUTCHES NOT WORKING

Replace 2 way microphone

LADDER NOT WORKING

FEELING LIKE IT BRAKING BY ITS

MANUAL SELECT SWITCH ERROR

CAT D11 7PZ 250HR SERVICE

MAIN SELECT SWITCH ERROR

STEEL TUBE ON THE FRONT OF HYD

LHS brakes need adjusting

RHS light not working

ENG RUNNING ROUGH

TWO WAY RADIO NOT WORKING

HYD HOSE LEAK

2000 Hr Service and Inspection

Small weep at hyd filter

STEERING CLUTCH FAULT

REPLACE ENGINE OIL AND FILTERS

Replace RHS lift cylinder leak

250 Hr Service and Inspection

OIL LEAK LH LIFT CYLINDER

LADDER WONT RAISE FULLY

OIL LEAK L/H LIFT CYLINDER

2 WAY FAULTY

500 Hr Service and Inspection

FAN BELT SCREAMING

AC BLOWING HOT AIR

L/H DOOR NEEDS ADJUSTING

BRAKES NEED CHECKING

Repair leak at front of hyd

LADDER FAULT

250 Hr Service and inspection

Replace LHS Track

Replace leaking T/C output sea

2000 Hr Cat extra

SEAT BELT

TURBO NOISE

1000 Hr Service and inspection

REAR ACCESS RAIL JAMMED

DASH BOARD CRACKED

Loud clunking noise coming

RIGHT HAND STEERING CLUTCH NOT

DOZER 238 AIR CON NOT REAL G

250 Hr Service and Inspection

DOZER 238 - WELL DOWN ON POWER

DOWN ON POWER

CAT D11 7PZ 500HR SERVICE

INTERMITTENTLY LOW ON POWER, D

500 Hr Service and inspection

Replace leaking hyd hose

DOZER 238 AIRCON NOT WORKING

STEERING CLUTCHES NOT WORKING

Repair exhaust leak

LEFT DOOR JAMMED

250 hr Service and Inspection

Replace leaking hose under

EXHAUST LEAK

4000 Hr service and Inspection

AIR CON NOT WORKING

EXHAUST APPEARS TO BECOMING MO

INSPECT ABNORMAL NOISE COMING

Replace mother board

TELEMTRY FAULT

LOST HIS SCREEN, DASH HAS GONE

FAN BELTS SCREAMING

Repair leak under hyd tank

4000 Hr Cat Extra

Investigate oil usage

RIGHT HAND DOOR SEALS NEED REP

ENGINE OIL

CAT D11 7PZ 250HR SERVICE

LOW ENGINE OIL

BLADE TILT

LOW ENG OIL

LOW ENG OIL

LOW ENGINE OIL

Fit cat blinds to front window  
Replace PT pipes at coolers  
MANY TRACK BOLTS MISSING - 2 O  
CAT D11 7PZ 500HR SERVICE  
CAT D11 7PZ 500HR SERVICE  
AIR CON DUCTS FULL OF WATER  
MASTER LINK BOLTS BROKEN  
OIL LEAK UNDER HYD TANK  
TELEMETRY SCREEN NOT WORKING  
LADDER BOLT MISSING  
Check length of Engine suction  
Replace cracked out  
250 Hr Service and Inspection  
AIRCON NOT WORKING PROPERLY  
Door seal U/S RHS  
Complete brake touch ups  
SERVICE BRAKE ERROR  
BRAKE/STEERING CLUTCH  
DOZER BOGGED AT S/PILE 5.5.1  
BACK ACCESS GATE HAS BEEN BENT  
CAT D11 7PZ 1000HR SERVICE  
COOLANT LEAK FROM ENGINE BAY  
FUEL CAP VERY TIGHT.  
CRACKED REAR HANDRAIL  
250 hr Service and Inspection  
A/C BLOWING AIR BUT WON'T COOL  
BOLT MISSING FROM TOP OF LADDER  
BROKEN GUARD ON L/H TURBO  
DOZER 238 REAR BLIND MISSING  
Reseal Hyd tank sight glass  
FIX BROKEN BLIND FOR OPERATOR  
BOLTS MISSING IN HANDRAILS  
CAT D11 7PZ 500HR SERVICE  
250 Hr Service and Inspection  
R/H SIDE LIGHT NOT WORKING  
Replace coolant C sample  
E stop not working  
2000 Hr Service and Inspection  
BURNING SMELL INSIDE CAB  
LHS ARM REST  
CAT D11 7PZ 250HR SERVICE  
LADDER H/RAIL BROKEN  
ARM REST DAMAGED  
Repair O/Heating fault  
ACCESS LADDER HAND RAIL BENT  
500 Hr Service and Inspection  
Replace hoses at Midlife  
Replace ladder power pack

BLOWN TRANS HOSE  
Check after being bogged  
RESET DASH COMPUTER  
CAT D11 7PZ 250HR SERVICE  
Midlife Rebuild 2017  
LADDER WONT LIFT  
LOW POWER REPLACE INJECTOR #4  
LOW POWER  
WELD STEP REPAIR (DONE)  
Replace sight glass on power  
LOW POWER  
1000 Hr Service and Inspection  
LOSS OF POWER  
250 Hr Service and Inspection  
Hydraulics overheating  
Replace both lift cylinders  
MASTER LINK NEEDS ATT  
LOW POWER AND L/H SIDE TRACK H  
500 hr Service and Inspection  
no air flow from air cond  
Replace RH track  
Replace LH pre cleaner base  
JAMMED HAND RAIL  
250 Hr Service and Inspection  
BOLT MISSING FROM AIR CON COVE  
Replace RH Lift cylinder  
ENGINE OIL OVERFUL  
4000 Hr Service and Inspection  
GUARD RAIL ON LADDER BROKEN OF  
REPAIR HANDRAIL ON LADDER  
AM/FM RADIO NOT WORKING  
500 Hr Service and Inspection  
FM RADIO NOT WORKING  
LADDER HAND RAIL BROKEN  
250 HRS SERVICE & INSPECTION  
EIC ALARM CALL SHOP  
REPLACE R/H EXHAUST TOP HAT  
BOLTS MISSING OF AIR FILTER IN  
R/H SIDE FINAL DRIVE PLUG MISS  
1000 Hr Service and Inspection  
250 hr Service and Inspection  
CHANGE FILTERS  
ENGINE HAD A METTALIC NOISE  
BLOWING EXHAUST GASES OUT RADI  
Fit shims to quick drop valves  
500 Hr Service and Inspection  
BLOWING EXCESSIVE SMOKE  
REAR ACCESS GATE JAMMED

AM/FM RADIO NEEDS REPLACING DI  
250 hr Service and Inspection  
DOOR WIPER BLADE U/S  
LADDER NOT WORKING  
Initial valve set  
Filtergram on transmission  
Rebuild LH arm rest  
NO AIRCON FAN  
2000 Hr Cat extra  
2000 Hr Service and Inspection  
REAR WALKWAY GATE JAMMED  
LOW COOLANT ALARMING  
Investigate Hi Copper in engin  
low air flow on air con  
FUEL LEAK AT CAP - Replace cap  
DOZER 238 HAS NO REVERSE GEARS  
250 Hr Service and Inspection  
ENGINE ERROR FAULT  
Replace trans tank bung  
Replace tranny oil and filters  
500 Hr Service and Inspection  
BLINDS  
DOZER 238 DOOR RUBBER RIGHT SI  
REPAIR AM/FM RADIO  
TWO WAY CUTTING IN AND OUT  
LADDER NOT WORKING  
Replace both rear idlers  
238 air cond hot  
ENG OIL FILLER CAP OFF  
Replace engine oil and filters  
250 Hr Service and Inspection  
OVERFULL ENGINE OIL  
FUEL FILTERS  
1000 Hr Service and Inspection  
238 air cond belt missing  
UP SHIFT BUTTON STICKING  
L/H SIDE LIFT RAM HOSE LEAKING  
Sort Out Fibre Patches Cab 11V  
Rmove and repair engine  
NO BOOST  
Repair oil leak under implemen  
Dozer 238 a/c not working  
250 Hr Service and Inspection  
ADJUST RIGHT SIDE DOOR RATTLE  
Dozer 238 Pressuriser Faulty  
LOSS BLADE CONTROL  
4000 Hr cat Extra  
Weld up cheek plates

500 Hr Service and Inspection  
250 Hr Service and Inspection  
NO AIRCON  
Sample transmission oil  
Drain and flush coolant system  
REPAIR LADDER CONTROL BOX.  
Dozer 238 Aircon Faulty  
Repair ladder assy  
LADDER FAULT (DONE)  
4000 Hr Service and Inspection  
TRANSMISSION LEAK  
HYD OIL LEAK  
Bearing roll  
DAMAGED REAR GATE  
Replace RH arm rest  
PILOT FILTER PLUG ERROR  
REPLACE INNER AIR FILTERS  
R/H ARM REST ADJUSTMENT BOLTS  
REPLACE PILOT FILTER  
Replace leaking fan pump hose  
REPAIR DOOR TO LADDER POWER PA  
REPAIR LOOSE WIRES TO AM/FM RA  
250 Hr service and Inspection  
AM/FM RADIO NOT WORKING  
LADDER HYD BOX DOOR FALLEN OFF  
500 Hr Service and Inspection  
BOLT REQUIRED FOR HANDRAIL ACC  
250 Hr Service and Inspection  
Drain flush and replace coolan  
Replace LHR idler  
1000 Hr Service and Inspection  
REPLACE LEAKING DOOR SEALS BOT  
RAIL BROKEN ON LADDER  
Dozer 238 Cab Fan Not Working  
250Hr Service and Inspection  
500 Hr Service and Inspection  
RESET LADER  
Replace 2-way radio  
Hydraulic hoses rubbing along  
250 Hr Service and Inspection  
2000 Hr Caty extra  
Check equaliser bar  
REPAIR WALKWAY ON DOZER  
TWO WAY RADIO NEEDS REPLACING  
TWO - WAY RADIO FAULT  
2000 Hr Service and Inspection  
DOZ. 238 RADIO HAND PIECE  
REPLACE 2-WAY H/PEICE.

LOW ON POWER

4000 Cat extra Service

250 Hr Service and Inspection

CHECK OIL LEAK HYDRALIC TANK C

CHECK FILTER ALARM

LADDER CONTROL BOX DOOR LATCH

LADDER POWER PACK DOOR BROKEN

LADDER CONTROL CABINET DOOR WI

CHECK FILTER PLUG FAULT

DOZER 238

Rebuild ladder at Major

Replace tracks

Replace bent walkways

Overhaul blade

Rebuild spare hyd tank

Replace centre pin @ major

Reseal Track Adjusters @ Major

Convert tilt hoses to AMA

Fit L.E.D lights at Major

Seized Engine

Major Rebuild 2015

dozer 238 a/c not cooling .

FAULTY STARTER MOTORS

RESETAR DOZER

REPLACE LEAKING HOSE ON ACCESS

250 Hr Service and Insepction

CHECK BATTERY ACID SMELL IN CA

1000Hr service and inspection

REPLACE INNER AIR FILTERS DOZ

ADJUST BLADE TILT CONTROL

BLADE TILT VERY SLOW

NO TILT ON BLADE

ENGINE OIL OVERFULL

ENGINE MISFIRING

CHECK ANGLE TILT FAULT

250 Hr Service and Inspection

BRAKE GRABING/ PEDAL NEAR TO F

BRAKE FAULT ALARM

DOZ 38 SERVICE BRAKE SWITCH ER

REPORTS OF BLADE DROPPING

BRAKE SERVICE ERROR FAULT

500hr service and inspection

BRAKE ERROR ALARM

BRAKE FAULT

LOW COOLANT ALARM

REPLACE L/H REAR IDLER

238 air cond faulty

REPAIR REAR ACCESS GATE

FILTER FAULT ON DOZER238  
PUMP UP TRACK  
TRACK LOOSE NEEDS ADJUSTING  
PUMP UP SLACK TRACK  
HEDWELL LADDER PLAYS UP INTERM  
SLACK TRACK  
REPLACE R/H SIDE LIGHT  
AIR CON NET GETTING COLD.  
250 Hr Service and Inspection  
LADDER FAULT  
LOW COOLANT, TOP UP  
COOLANT ALARM FAULT  
REFIT LH INTAKE DUCT  
PUMP UP TRACK  
LADDER FAULT  
LOOSE TRACK  
PUMP UP TRACK  
BRAKE SENSOR FAULT  
TRANSMISSION TEMPTURE  
RESET LADDER  
Replace pirtek made hose  
PT OIL SENSOR FAULT (DONE)  
HYD OIL FAULT.  
2 WAY TURNS ITSELF OFF WHEN IN  
R/H TRACK LOOSE  
4000Hr Service and inspection  
238 AIR CON NOT WORK + LADDE  
REPAIR BRAKE FAULT.  
PUMP UP SLACK TRACK  
Repair 5 volt fault  
LADDER FAULT, EXHUST FUMES IN  
HIGH ENG OIL TEMP  
CHECK BELT TRACKING CC1H  
BROKEN MASTER LINK BOLT  
REPAIR LADDER DOZ 238  
RIGHT HAND TRACK RUNNING ON CA  
LADDER FAULT.  
FAN PRESSURE ERROR  
250 Hr Service and Inspection  
Repair ladder fault  
Replace Priority hose to trans  
DOWN RATING - RETURN TO WORKSH  
Replace LH tilt Cyl kit  
COOLANT ALARM FAULT  
500 Hr Service and Inspection  
Overhaul RHS Track  
BOLTS MISSING FROM BACK WALKWA  
LOW COOLANT ALARM

RIGHT HAND TRACK SLACK , FITTE  
Replace No.6 Injector  
SMALL FIRE IN ENGINE BAY AND D  
RIGHT HAND TRACK NEEDS PUMPING  
BOLT MISSING FROM AIR CLEANER  
RETENSION TRACK  
RESET LADDER FAULT  
LADDER FAULT + LOW POWER  
DOZ 238-REPAIR LADDER  
ACCESS LATCH AT REAR OF DOZER  
LEFT REAR IDLER LEAKING OIL  
SLACK RIGHT HAND TRACK  
250 Hr Service and Inspection  
RELOCATE TWO WAY RADIO TO OTHE  
LOOSE RIGHT HAND TRACK  
RIGHT HAND TRACK SLACK , FITTE  
REPORTED TO WORKSHOP RIGHT HAN  
238 air cond fan not running  
RHS TRACK LOOSE  
1000 Hr Service and Inspection  
TURBO TIMER FAULT  
ENGINE OIL OVERFULL  
TRACK HAD TO BE ADJUSTD  
AJUST SLACK TRACK (DONE)  
FAN RETURN FILTER FAULT  
FAN RETURN FILTER PLUG  
Replace Leaking Lift cylinders  
Reseal equiliser bar end pins  
Replace PT cooler hoses  
FAN RETURN FILTER  
Replace rusted bolts at Tag  
FINAL DRIVE SPROCKET FELL OFF  
250Hr service and inspection  
ADJUST TRACK  
DOZ 238 FAN RETURN FILTER PLUG  
FAN RETURN FAULT COMPLETED  
Replace main water pump  
Replace both lift cylinders at  
2000 Hr Cat Extra  
DZ238 Fire suppression inspect

## **Description 2**

2 WAY SPEAKER  
START MACHINE AND RELOCATE  
RFQ MOTIUM DOZER SCREEN  
PM CHANGE REQUEST - DOZER 238 - DELETE MODEL 128340 FIRE PM  
6M FIRE SYSTEMS SERVICE & INSPECTION  
6M FIRE SYSTEMS SERVICE & INSPECTION  
6M FIRE SYSTEMS SERVICE & INSPECTION  
6M FIRE SYSTEMS SERVICE & INSPECTION  
THICKNESS TEST BLADE CONDITION  
REPLACE RHS TRACK  
TELEMETRY  
AM/FM RADIO NOT WORKING  
AM/FM RADIO NOT WORKING AT ALL  
ALT LIGHT ON DASH  
RETURN FREQUENCY LOW, ALARM  
AM/FM RADIO SPEAKERS RE NOT WORKING AT ALL  
REPAIR CRACKED WELD IN HANDRAIL AS DISCUSSED  
DZR238 LADDER HANDRAIL HAS A BROKEN WELD  
250HR SERVICE AND INSPECTION  
DOZER 238 BLOWN RADIATOR HOSE  
BRAKE FAULT  
REPLACE IMPLEMENT ECM  
BLADE CONTROL HYDRAULICS NON RESPONSIVE  
NO HYDRAULICS  
ELEC VIDS-EIC FAULT  
BOLTS BROKEN OFF-DONE  
TAKE COOLANT SAMPLE  
OIL TEMP SENSOR ERROR  
NO DATA IN TELEMETRY  
OVERHAUL A/C SYSTEM  
HEATER NOT WORKING  
LEAK AT FUEL SENDER  
4000 HR CAT EXTRA  
R/H AIR FILTER COVER BOLTS MISSING  
BLADE CONTROL NOT WORKING  
1000 HR SERVICE AND INSPECTION  
NO BLADE CONTROL  
VIDS/EIC ERROR CALL SHOP  
HEATER NOT WORKING  
LADDER WONT GO DOWN  
FUEL LEAK ON ENGINE  
FIT UP LADDER ISOLATOR  
DOZER HANDRAIL IS MISSING AND LOCATED FUEL BAY 25  
REAR ACCESS WALK WAY HAND RAIL MISSING  
250 HR SERVICE AND INSPECTION  
1P-3708 SEAL-RECTANGULAR  
TRANSMISSION OIL LOW

BLADE RAISE SOLENOID FAULT  
REPLACED BENT TILT LINE ON BACK OF BLADE  
PILE  
UHF NOT WORKING  
HEATER NOT WORKING  
REPLACE RAIN CAPS  
T/C OUTPUT SPEED SENSOR ABNORMAL  
500 HR SERVICE AND INSPECTION  
GAUGES ON DASH NOT WORKING  
BLADE RAISE ERROR  
OIL LEAK UNDER MACHINE  
A/C NOT VERY COLD  
REPLACE 4 X BATTERY'S  
REPLACE ID STICKERS  
TYPE  
COOLANT HOSE BLOWN  
AT MID LIFE  
4000 HR SERVICE AND INSPECTION  
MIDLIFE REBUILD 2021  
WIPERS DONT WORK  
RIGHT HAND CABIN WIPER FAULTY  
NO POWER WHEN PUSHING  
REPAIR HOSE TRUCKFILL.  
500HR SERVICE AND INSPECTION  
REPLACE BOLTS IN HOOD LINING  
FRONT LIGHTS NOT WORKING  
BROKEN LH TRACK ON STOCKPILE  
CAT D11 7PZ 250HR SERVICE  
AM/FM RADIO NOT WORKING  
FAULTY FUEL GAUGE  
REPLACE FUEL SENSOR  
SHATTERED  
FUEL GAUGE NOT READING CORRECT, DOZER JUST FILLED UP AND ALARM SAYS NEEDS MORE  
NUMBER 8 COOLANT ENTRY  
RADAITOR CORES LEAKING  
1000HR SERVICE AND INSPECTION  
CAB PRESSURIZER FAN NOT WORKING  
LOW ON POWER  
PRIOR TO EVAC  
OIL LEAK TRANSMISSION COOLER  
MIDLIFE  
BLADE NOT TILTING PROPERLY  
ASSIST OPERATIONS WITH TASK  
PUSH ARM TILT CYLINDER EXCESSIVE WEAMIDLIFE  
LEFT HAND SIDE TILT CYLINDER, PUSH ARMS  
250 HR SERVICE AND INSPECTION  
DOZER 238 DIESEL LEAK  
RT TILT SOLENIOD FAULT

SHUDDER WITH DOZER BLADE  
BLADE WONT RAISE  
COOLANT IN ENGINE OIL  
500 HR SERVICE AND INSPECTION  
TOPUP COOLANT  
FRONT LH LIGHT BLINKS  
SEE ATTACHMENTS  
FIT NEW BATTERIES  
BLADE WILL NOT TILT UNDER LOAD  
250 HR SERVICE AND INSPECTION  
LEFT HAND TILT NOT WORKING  
INLET TEMP FAULT  
RIGHT EXHAUST TEMP ERROR  
2000 HR SERVICE AND INSPECTION  
L/H TILT SOLENOID ERROR  
250 HR SERVICE AND INSPECTION  
RTEXH ERROR  
REPLACE ETHERNET SWITCH OF TELEMETRY SYSTEM  
A/C FAN NOT WORKING AT ALL  
4000 HR CAT EXTRA  
500 HR SERVICE AND INSPECTION  
TELEMETRY AERIAL BROKEN  
LOW ENGINE OIL ABOUT 1 INCH BELOW ADD MARK  
GAUGES ON SCREEN NOT WORKING  
250 HR SERVICE AND INSPECTION  
BLADE TILT FAULT  
COOLANT LEAK  
E/H FILTER PLUGGED  
1000 HR SERVICE AND INSPECTION  
INNER AIR FILTERS NEED CHANGING  
REPLACE WALKWAYS AT REBUIL  
A/C NOT GETTING COLD  
250 HR SERVICE AND INSPECTION  
LOW VOLTAGE  
REPLACE ID STICKERS  
SHIELD  
500 HR SERVICE AND INSPECTION  
TAKE ENG OIL SAMPLE  
AIR CON NOT WORKING  
250 HR SERVICE AND INSPECTION  
TELEMETRY SCREEN BROKEN  
4000HR SERVICE AND INSPECTION  
250 HR SERVICE AND INSPECTION  
500 HR SERVICE AND INSPECTION  
REPAIR WIPER  
RHS LIGHT NOT WORKING  
250 HR SERVICE AND INSPECTION  
AM/FM RADIO DAMAGED

AM/FM RADIO NEEDS TO BE REPLACED NOT WORKING  
ENG OIL OVER FULL  
5 GROUSER BOLTS MISSING ON R/H SIDE  
1000 HR SERVICE AND INSPECTION  
2 WAY RADIO NOT WORKING CORRECTLY  
250 HR SERVICE AND INSPECTION  
2 MISSING TRACK BOLTS RH SIDE  
RUBBER MISSING OFF BUTTON ON 2 WAY HAND PIECE  
REPLACE HAT HOOK IN CABIN  
500 HR SERVICE AND INSPECTION  
REPLACE BROKEN HELMET HOOK INSIDE THE CAB PLEASE.  
REPAIR A/C SYSTEM  
HELMET HOOKS NEED REPLACING  
AIR CON NOT WORKING  
FLAP BELOW DOOR ON LADDER SIDE IS COMING OFF  
250 HR SERVICE AND INSPECTION  
C/O HYD TANK  
4000 HR CAT EXTRA  
BRAKES NEED ADJUSTING & BLADE LOWERS FASTER THAN NORMAL.  
2000 HR SERVICE AND INSPECTION  
A/C FAN NOT WORKING  
DOZ 238 - 1 GROUSER BOLT MISSING FROM R/H TRACK.  
AM/FM RADIO NOT WORKING  
REPLACE LHS E-BAR GRUB SCREWS  
STRG OIL TEMP ERROR  
250 HR SERVICE AND INSPECTION  
FIT BOLLARDS TO TOP DECK  
FIT BOLLARDS TO TOP OF DECK  
500 HR SERVICE AND INSPECTION  
INSPECT COAL CANOPY  
250 HR SERVICE AND INSPECTION  
NO GUAGES  
1000 HR SERVICE AND INSPECTION  
LADDER SWIVEL MOUNT BOLTS LOOSE  
R/H ROPS LIGHT FALLING OFF  
250 HR SERVICE AND INSPECTION  
RIGHT SIDE TILT CYLINDER HOSE LEAKING  
AM/FM RADIO NOT WORKING  
BLOWN HYD HOSE ON TAG LINK  
DZ238 FIRE SUPPRESSION INSPECT  
AM/FM RADIO NOT WORKING . NEEDS REPLACING  
AT MAJOR REBUILD  
CHANGE HYD TANK EVAC POINT  
AT MAJOR REBUILD  
AT MAJOR REBUILD  
REPAIR A/C IN 238  
REPLACE ALL MINOR BOGIE PINS  
AT MAJOR REBUILD

AT MAJOR REBUILD  
RFQ FROM MAJOR REBUILD  
AM/FM NOT WORKING  
BOLT MISSING FROM AIR CLEANER COVER  
@ MAJOR  
DOWN ON POWER WHEN UNDER LOAD DROPS TO 1500RPM  
TOP STEP RUSTY ON LADDER  
REAR ACCESS GATE MISSING  
DOWN ON POWER  
500 HR SERVICE AND INSPECTION  
INSPECT AND REPLACE FAULTY TWOWAY HANDPIECE  
INSPECT REPORTED LOW POWER ISSUE ( DONE )  
AM/FM RADIO FALLING OUT  
HYD. LEAK FROM LADDER  
LH FRONT BOGIE PIN WORN OUT  
DO AT MAJOR  
DOZER LOSING POWER  
AM FM RADIO NOT WORKING  
250 HR SERVICE AND INSPECTION  
LH SIDE TOP  
DOZ 238 IS LOW ON POWER.  
LADDER STUCK IN RAISED POSITION  
LOW POWER COMPLAINT  
L/H LOWER TILT BEARING U/S  
LOW ENGINE POWER  
4000HR SERVICE  
NO LADDER POWER  
ENGINE AND TRANSMISSION OVER FULL  
2000 HR CAT EXTRA  
LADDER NOT WORKING  
AIRCON NOT WORKING  
LADDER  
WONT START SEEMS TO BE BATTERY ISSUE  
LADDER JAMMED IN DOWN POSITION  
250 HR SERVICE AND INSPECTION  
LOST POWER  
FIX LADDER FAULT- WONT RAISE  
OIL LEAK  
DAMAGE TO SEAT  
LONG DELAY CHANGING FROM FRWD TO REVERSE  
NEEDS DOORS ADJUSTED RATTLING AND DOOR RUBBERS NEED REPLACING  
1801486  
P/N 1457316 IN BOX ALREADY  
COVER  
T/C OUTPUT SHAFT SEAL LEAKING  
COOLANT  
500 HR SERVICE AND INSPECTION  
LOW COOLANT

REPORTED BLADE CRACKED  
R OF MACHINE  
250 HR SERVICE AND INSPECTION  
REPLACE MISSING BOLT FROM AIR CLEANER  
NO BLADE TILT  
1000 HR SERVICE AND INSPECTION  
FIT CAT BLINDS TO SIDE WINDOWS  
DOZER 238 OIL FILLER CAP MISSING .  
MANUAL SELECT SWITCH ERR  
238 AIR COND FAULTY  
238 A/C NOT COOL  
DRIVING THROUGH STEERING CLUTCHES ONLY IN FIRST GEAR SECOND OK  
STEERING CLUTCHES  
STEER CLUTCHES NOT GOOD IN REVERSE  
250 HR SERVICE AND INSPECTION  
C SAMPLE  
FIT NEW TYPE SCREEN IN DOZER  
1373587  
INNER AIR FILTER CHANGE  
500 HR SERVICE AND INSPECTION  
TELEMETRY  
STERRING CLUTCHES NOT WORKING WELL IN REVERSE  
REPLACE 2 WAY MICROPHONE  
LADDER NOT WORKING  
FEELING LIKE IT BRAKING BY ITSELF  
MANUAL SELECT SWITCH ERROR  
CAT D11 7PZ 250HR SERVICE  
MAIN SELECT SWITCH ERROR  
STEEL TUBE ON THE FRONT OF HYDRAULIC TANK LEAKING  
LHS BRAKES NEED ADJUSTING  
RHS LIGHT NOT WORKING  
ENG RUNNING ROUGH  
TWO WAY RADIO NOT WORKING  
HYD HOSE LEAK  
2000 HR SERVICE AND INSPECTION  
REPAIR NEXT SERVICE  
BRAKE TOUCH UP  
REPLACE ENGINE OIL AND FILTERS  
REPLACE RHS LIFT CYLINDER LEAK  
250 HR SERVICE AND INSPECTION  
OIL LEAK LH LIFT CYLINDER  
LADDER WONT RAISE FULLY  
OIL LEAK L/H LIFT CYLINDER  
2 WAY FAULTY  
500 HR SERVICE AND INSPECTION  
FAN BELT SCREAMING  
AC BLOWING HOT AIR  
L/H DOOR NEEDS ADJUSTING

BRAKES NEED CHECKING  
TANK  
LADDER FAULT  
250 HR SERVICE AND INSPECTION  
REPLACE LHS TRACK  
REPLACE LEAKING T/C OUTPUT SEA  
2000 HR CAT EXTRA  
SEAT BELT  
TURBO NOISE  
1000 HR SERVICE AND INSPECTION  
REAR ACCESS RAIL JAMMED  
DASH BOARD CRACKED  
FROM RHS FINAL DRIVE AREA.  
RIGHT HAND STEERING CLUTCH NOT WORKING  
DOZER 238 AIR CON NOT REAL GOOD  
250 HR SERVICE AND INSPECTION  
DOZER 238 - WELL DOWN ON POWER.  
DOWN ON POWER  
CAT D11 7PZ 5000HR SERVICE  
INTERMITTENTLY LOW ON POWER, DOWN 90 DEGREES ON LEFT ENGINE BANK  
500 HR SERVICE AND INSPECTION  
P/N 1736115  
DOZER 238 AIRCON NOT WORKING  
STEERING CLUTCHES NOT WORKING WHEN REVERSING BACK DOWN STOCKPILE  
REPAIR EXHAUST LEAK  
LEFT DOOR JAMMED  
250 HR SERVICE AND INSPECTION  
FLOOR P/N 2965154  
EXHAUST LEAK  
4000 HR SERVICE AND INSPECTION  
AIR CON NOT WORKING  
EXHAUST APPEARS TO BECOMING MORE SMOKEY - PLEASE INSPECT.  
INSPECT ABNORMAL NOISE COMING FROM ENGINE (DONE)  
REPLACE MOTHER BOARD S/N 24188  
TELEMTRY FAULT  
LOST HIS SCREEN, DASH HAS GONE OUT  
FAN BELTS SCREAMING  
REPAIR LEAK UNDER HYD TAMK  
4000 HR CAT EXTRA  
INVESTIGATE OIL USAGE  
RIGHT HAND DOOR SEALS NEED REPLACING  
ENGINE OIL  
CAT D11 7PZ 250HR SERVICE  
LOW ENGINE OIL  
BLADE TILT  
LOW ENG OIL  
LOW ENG OIL  
LOW ENGINE OIL

AND DOORS  
RUSTED OUT  
MANY TRACK BOLTS MISSING - 2 ON ONE PLATE  
CAT D11 7PZ 5000HR SERVICE  
CAT D11 7PZ 5000HR SERVICE  
AIR CON DUCTS FULL OF WATER  
MASTER LINK BOLTS BROKEN  
OIL LEAK UNDER HYD TANK  
TELEMETRY SCREEN NOT WORKING  
LADDER BOLT MISSING  
TUBE  
DRIVE SHAFT COVER  
250 HR SERVICE AND INSPECTION  
AIRCON NOT WORKING PROPERLY  
DOOR SEAL U/S RHS  
REPORT RHS STICKING  
SERVICE BRAKE ERROR  
BRAKE/STEERING CLUTCH  
DOZER BOGGED AT S/PILE 5.5.1  
BACK ACCESS GATE HAS BEEN BENT AND CAN'T BE OPENED  
CAT D11 7PZ 1000HR SERVICE  
COOLANT LEAK FROM ENGINE BAY  
FUEL CAP VERY TIGHT.  
CRACKED REAR HANDRAIL  
250 HR SERVICE AND INSPECTION  
A/C BLOWING AIR BUT WON'T COOL  
BOLT MISSING FROM TOP OF LADDER  
BROKEN GUARD ON L/H TURBO  
DOZER 238 REAR BLIND MISSING  
AT 1000/2000 HR  
FIX BROKEN BLIND FOR OPERATOR POOR BUGGER  
BOLTS MISSING IN HANDRAILS  
CAT D11 7PZ 5000HR SERVICE  
250 HR SERVICE AND INSPECTION  
R/H SIDE LIGHT NOT WORKING  
REPLACE COOLANT C SAMPLE  
E STOP NOT WORKING  
2000 HR SERVICE AND INSPECTION  
BURNING SMELL INSIDE CAB  
LHS ARM REST  
CAT D11 7PZ 250HR SERVICE  
LADDER H/RAIL BROKEN  
ARM REST DAMAGED  
HASTINGS 01/12/16  
ACCESS LADDER HAND RAIL BENT  
500 HR SERVICE AND INSPECTION  
REPLACE HOSES AT MIDLIFE  
AT MIDLIFE REBUILD

BLOWN TRANS HOSE  
CHECK AFTER BEING BOGGED  
RESET DASH COMPUTER  
CAT D11 7PZ 250HR SERVICE  
MIDLIFE REBUILD 2017  
LADDER WONT LIFT  
LOW POWER REPLACE INJECTOR #4  
LOW POWER  
WELD STEP REPAIR (DONE)  
PAK LADDER  
LOW POWER  
1000 HR SERVICE AND INSPECTION  
LOSS OF POWER  
250 HR SERVICE AND INSPECTION  
HYDRAULICS OVERHEATING  
REPLACE BOTH LIFT CYLINDERS  
MASTER LINK NEEDS ATT  
LOW POWER AND L/H SIDE TRACK HAS MISSING BOLT ON TRACK JOIN  
500 HR SERVICE AND INSPECTION  
NO AIR FLOW FROM AIR COND  
REPLACE RH TRACK  
REPLACE LH PRE CLEANER BASE  
JAMMED HAND RAIL  
250 HR SERVICE AND INSPECTION  
BOLT MISSING FROM AIR CON COVER BEHIND SEAT CAUSING BAD RATTLE  
MIDLIFE  
ENGINE OIL OVERFUL  
4000 HR SERVICE AND INSPECTION  
GUARD RAIL ON LADDER BROKEN OFF  
REPAIR HANDRAIL ON LADDER  
AM/FM RADIO NOT WORKING  
500 HR SERVICE AND INSPECTION  
FM RADIO NOT WORKING  
LADDER HAND RAIL BROKEN  
250 HRS SERVICE & INSPECTION  
EIC ALARM CALL SHOP  
REPLACE R/H EXHAUST TOP HAT  
BOLTS MISSING OF AIR FILTER IN CAB FOR AIR CON ON DOZER 238  
R/H SIDE FINAL DRIVE PLUG MISSING - REPLACE. COMPLETE.  
1000 HR SERVICE AND INSPECTION  
250 HR SERVICE AND INSPECTION  
CHANGE FILTERS  
ENGINE HAD A METTALIC NOISE  
BLOWING EXHAUST GASES OUT RADIATOR  
LIFT  
500 HR SERVICE AND INSPECTION  
BLOWING EXCESSIVE SMOKE  
REAR ACCESS GATE JAMMED

AM/FM RADIO NEEDS REPLACING DISPLAY DAMAGED  
250 HR SERVICE AND INSPECTION  
DOOR WIPER BLADE U/S  
LADDER NOT WORKING  
INITIAL VALVE SET  
FILTERGRAM ON TRANSMISSION  
REBUILD LH ARM REST  
NO AIRCON FAN  
2000 HR CAT EXTRA  
2000 HR SERVICE AND INSPECTION  
REAR WALKWAY GATE JAMMED  
LOW COOLANT ALARMING  
INVESTIGATE HI COPPER  
LOW AIR FLOW ON AIR CON  
FUEL LEAK AT CAP  
DOZER 238 HAS NO REVERSE GEARS  
250 HR SERVICE AND INSPECTION  
ENGINE ERROR FAULT  
DO AT NEXT 1000HR SERVICE  
CARRY OUT FILTER GRAM  
500 HR SERVICE AND INSPECTION  
BLINDS  
DOZER 238 DOOR RUBBER RIGHT SIDE FALLING OFF  
REPAIR AM/FM RADIO  
TWO WAY CUTTING IN AND OUT  
LADDER NOT WORKING  
REPLACE BOTH REAR IDLERS  
238 AIR COND HOT  
ENG OIL FILLER CAP OFF  
REPLACE ENGINE OIL AND FILTERS  
250 HR SERVICE AND INSPECTION  
OVERFULL ENGINE OIL  
FUEL FILTERS  
1000 HR SERVICE AND INSPECTION  
238 AIR COND BELT MISSING  
UP SHIFT BUTTON STICKING  
L/H SIDE LIFT RAM HOSE LEAKING  
UNMARKED CABINETS,CABLES AND PATCHES  
WARRANTY  
NO BOOST  
PUMP  
AIRCON NOT WORKING PROPERLY  
250 HR SERVICE AND INSPECTION  
ADJUST RIGHT SIDE DOOR RATTLE  
CABIN PRESSURIZER FAN NOT WORKING  
LOSS BLADE CONTROL  
4000 HR CAT EXTRA  
WELD UP CHEEK PLATES

500 HR SERVICE AND INSPECTION  
250 HR SERVICE AND INSPECTION  
TIM BARKER TO INVESTIGATE  
& CHECK FOR POSSIBLE DIRT ENTRY  
FLUSH AT LEAST 3 TIMES  
REPAIR LADDER CONTROL BOX.  
AIRCON NOT GETTING COLD  
REPAIR LADDER ASSY  
LADDER FAULT (DONE)  
4000 HR SERVICE AND INSPECTION  
TRANSMISSION LEAK  
HYD OIL LEAK  
BEARING ROLL  
DAMAGED REAR GATE  
REPLACE RH ARM REST  
PILOT FILTER PLUG ERROR  
REPLACE INNER AIR FILTERS  
R/H ARM REST ADJUSTMENT BOLTS BROKEN  
REPLACE PILOT FILTER  
(CASE DRAIN)  
REPAIR DOOR TO LADDER POWER PACK  
REPAIR LOOSE WIRES TO AM/FM RADIO  
250 HR SERVICE AND INSPECTION  
AM/FM RADIO NOT WORKING  
LADDER HYD BOX DOOR FALLEN OFF  
500 HR SERVICE AND INSPECTION  
BOLT REQUIRED FOR HANDRAIL ACCESS AT REAR OF DOZER  
250 HR SERVICE AND INSPECTION  
C SAMPLE  
BAD VIBRATION  
1000 HR SERVICE AND INSPECTION  
REPLACE LEAKING DOOR SEALS BOTH SIDES  
RAIL BROKEN ON LADDER  
DOZER 238 CAB FAN NOT WORKING  
250HR SERVICE AND INSPECTION  
500 HR SERVICE AND INSPECTION  
RESET LADER  
REPLACE 2-WAY RADIO  
CHASSIS  
250 HR SERVICE AND INSPECTION  
2000 HR CATY EXTRA  
REPORT OF HARSH OEPRATION  
REPAIR WALKWAY ON DOZER  
TWO WAY RADIO NEEDS REPLACING  
TWO - WAY RADIO FAULT  
2000 HR SERVICE AND INSPECTION  
DOZ. 238 RADIO HAND PIECE  
REPLACE 2-WAY H/PEICE.

LOW ON POWER  
CAT EXTRA SERVICE  
250 HR SERVICE AND INSPECTION  
CHECK OIL LEAK HYDRALIC TANK CAP  
CHECK FILTER ALARM  
LADDER CONTROL BOX DOOR LATCH BROKEN.  
LADDER POWER PACK DOOR BROKEN  
LADDER CONTROL CABINET DOOR WILL NOT CLOSE  
CHECK FILTER PLUG FAULT  
DOZER 238  
REBUILD LADDER AT MAJOR  
REPLACE TRACKS  
REPLACE BENT WALKWAYS  
CUTTING EDGES AND LINEBORING  
REBUILD SPARE HYD TANK  
MAJOR REBUILD  
RESEAL TRACK ADJUSTERS @ MAJOR  
SAME AS AMA SETUP  
FIT L.E.D LIGHTS AT MAJOR  
ENGINE OIL LEAK  
MAJOR REBUILD 2015  
INSPECT A/CON - NOT GETTING VERY COLD.  
FAULTY STARTER MOTORS  
RESETAR DOZER  
REPLACE LEAKING HOSE ON ACCESS LADDER  
250 HR SERVICE AND INSEPCTION  
CHECK BATTERY ACID SMELL IN CABIN  
1000HR SERVICE AND INSPECTION  
REPLACE INNER AIR FILTERS DOZ 238  
ADJUST BLADE TILT CONTROL  
BLADE TILT VERY SLOW  
NO TILT ON BLADE  
ENGINE OIL OVERFULL  
ENGINE MISFIRING  
CHECK ANGLE TILT FAULT  
250 HR SERVICE AND INSPECTION  
BRAKE GRABING/ PEDAL NEAR TO FULL TRAVEL  
BRAKE FAULT ALARM  
DOZ 38 SERVICE BRAKE SWITCH ERROR  
REPORTS OF BLADE DROPPING  
BRAKE SERVICE ERROR FAULT  
500HR SERVICE AND INSPECTION  
BRAKE ERROR ALARM  
BRAKE FAULT  
LOW COOLANT ALARM  
REPLACE L/H REAR IDLER  
238 AIR COND FAULTY  
REPAIR REAR ACCESS GATE

FILTER FAULT ON DOZER238  
PUMP UP TRACK  
TRACK LOOSE NEEDS ADJUSTING  
PUMP UP SLACK TRACK  
HEDWELL LADDER PLAYS UP INTERMITTENTLY. L/H/S BLADE ARM GRAB RAIL BROKEN.  
SLACK TRACK  
REPLACE R/H SIDE LIGHT  
AIR CON NET GETTING COLD.  
250 HR SERVICE AND INSPECTION  
LADDER FAULT  
LOW COOLANT, TOP UP  
COOLANT ALARM FAULT  
REFIT LH INTAKE DUCT  
PUMP UP TRACK  
LADDER FAULT  
LOOSE TRACK  
PUMP UP TRACK  
BRAKE SENSOR FAULT  
TRANSMISSION TEMPTURE  
RESET LADDER  
P/N 1212812  
PT OIL SENSOR FAULT (DONE)  
HYD OIL FAULT.  
2 WAY TURNS ITSELF OFF WHEN IN USE.  
R/H TRACK LOOSE  
4000HR SERVICE AND INSPECTION  
AIR CON NOT WORK + LADDER NOT WORKING  
REPAIR BRAKE FAULT.  
PUMP UP SLACK TRACK  
REPAIR 5 VOLT FAULT  
LADDER FAULT, EXHUST FUMES IN CABIN AND MANY FAULT ALARMS  
HIGH ENG OIL TEMP  
CHECK BELT TRACKING CC1H  
BROKEN MASTER LINK BOLT  
REPAIR LADDER DOZ 238  
RIGHT HAND TRACK RUNNING ON CANNON. BLADE TILT VERY SLOW TO MOVE  
LADDER FAULT.  
FAN PRESSURE ERROR  
250 HR SERVICE AND INSPECTION  
REPAIR LADDER FAULT  
REPLACE PRIORITY HOSE TO TRANS  
DOWN RATING - RETURN TO WORKSHOP  
REPLACE LH TILT CYL KIT  
COOLANT ALARM FAULT  
500 HR SERVICE AND INSPECTION  
PUMP UP TRACK  
BOLTS MISSING FROM BACK WALKWAY  
LOW COOLANT ALARM

RIGHT HAND TRACK SLACK , FITTERS GOING TO PUMP IT UP  
LOW POWER COMPLAINT  
SMALL FIRE IN ENGINE BAY AND DOWN ON POWER  
RIGHT HAND TRACK NEEDS PUMPING UP  
BOLT MISSING FROM AIR CLEANER  
RETENSION TRACK  
RESET LADDER FAULT  
LADDER FAULT + LOW POWER  
DOZ 238-REPAIR LADDER  
ACCESS LATCH AT REAR OF DOZER BROKEN  
LEFT REAR IDLER LEAKING OIL  
SLACK RIGHT HAND TRACK  
250 HR SERVICE AND INSPECTION  
RELOCATE TWO WAY RADIO TO OTHER SIDE OF CAB FOR EASIER ACCESS  
LOOSE RIGHT HAND TRACK  
RIGHT HAND TRACK SLACK , FITTERS GOING TO PUMP IT UP AGAIN  
REPORTED TO WORKSHOP RIGHT HAND TRACK SLACK  
238 AIR COND FAN NOT RUNNING  
RHS TRACK LOOSE  
1000 HR SERVICE AND INSPECTION  
TURBO TIMER FAULT  
ENGINE OIL OVERFULL  
TRACK HAD TO BE ADJUSTD  
AJUST SLACK TRACK (DONE)  
FAN RETURN FILTER FAULT  
FAN RETURN FILTER PLUG  
REPLACE LEAKING LIFT CYLINDERS  
(MIDLIFE)  
REPAIR OIL LEAK AT T/C  
FAN RETURN FILTER  
LINK  
FINAL DRIVE HOUSING BROKEN  
250HR SERVICE AND INSPECTION  
ADJUST TRACK  
DOZ 238 FAN RETURN FILTER PLUG  
FAN RETURN FAULT COMPLETED  
REPLACE MAIN WATER PUMP  
REPLACE BOTH LIFT CYLINDERS AT  
2000 HR CAT EXTRA  
DZ238 FIRE SUPPRESSION INSPECT

**Actual Finish Date**

12/08/2025  
02/02/2024  
27/07/2023  
23/05/2023  
23/05/2023  
22/11/2022  
21/06/2022  
06/01/2022  
07/12/2021  
22/09/2021  
07/12/2021  
06/10/2021  
06/10/2021  
02/09/2021  
02/09/2021  
06/09/2021  
06/09/2021  
06/10/2021  
06/09/2021  
30/08/2021  
16/08/2021  
16/08/2021  
10/08/2021  
05/08/2021  
29/07/2021  
22/07/2021  
11/08/2021  
22/07/2021  
14/07/2021  
07/12/2021  
08/09/2021  
01/07/2021  
12/10/2021  
28/06/2021  
05/07/2021  
13/07/2021  
21/06/2021  
14/06/2021  
28/06/2021  
04/06/2021  
01/06/2021  
12/07/2021  
31/05/2021  
25/05/2021  
31/05/2021  
31/05/2021  
17/05/2021

17/05/2021  
13/05/2021  
16/09/2021  
04/05/2021  
12/10/2021  
28/04/2021  
30/04/2021  
10/05/2021  
04/05/2021  
21/04/2021  
19/04/2021  
15/04/2021  
13/04/2021  
20/04/2021  
07/12/2021  
12/03/2021  
30/03/2021  
02/03/2021  
19/08/2021  
10/02/2021  
02/03/2021  
02/03/2021  
04/02/2021  
28/01/2021  
28/01/2021  
21/01/2021  
19/08/2021  
04/01/2021  
22/12/2020  
16/12/2020  
22/12/2020  
16/12/2020  
22/12/2020  
10/12/2020  
18/11/2020  
04/11/2020  
04/11/2020  
12/10/2020  
04/11/2020  
04/11/2020  
28/01/2021  
06/10/2020  
29/09/2020  
28/01/2021  
04/11/2020  
06/10/2020  
16/09/2020  
01/09/2020

02/09/2020  
18/08/2020  
18/08/2020  
02/09/2020  
18/08/2020  
02/09/2020  
02/09/2020  
30/07/2020  
30/07/2020  
31/07/2020  
17/07/2020  
07/07/2020  
02/07/2020  
07/07/2020  
02/07/2020  
15/06/2020  
01/06/2020  
28/05/2020  
23/06/2020  
04/11/2020  
02/06/2020  
05/05/2020  
05/05/2020  
29/04/2020  
05/05/2020  
29/04/2020  
20/04/2020  
07/04/2020  
08/04/2020  
01/04/2020  
08/04/2020  
02/04/2020  
18/03/2020  
09/03/2020  
28/05/2020  
18/03/2020  
02/03/2020  
20/02/2020  
19/03/2020  
10/02/2020  
04/02/2020  
31/01/2020  
06/01/2020  
18/12/2019  
09/12/2019  
02/12/2019  
02/12/2019  
24/11/2019



10/11/2020  
31/01/2020  
07/05/2019  
07/05/2019  
01/07/2019  
05/03/2019  
07/05/2019  
26/02/2019  
26/02/2019  
04/03/2019  
12/02/2019  
12/02/2019  
04/03/2019  
28/01/2020  
07/05/2019  
07/05/2019  
04/02/2019  
04/02/2019  
04/02/2019  
28/02/2019  
22/01/2019  
15/01/2019  
15/01/2019  
15/01/2019  
15/01/2019  
16/01/2019  
15/01/2019  
24/01/2019  
07/05/2019  
02/01/2019  
04/12/2018  
03/12/2018  
26/11/2018  
26/11/2018  
10/01/2019  
15/01/2019  
22/11/2018  
22/11/2018  
15/01/2019  
02/01/2019  
17/12/2018  
17/12/2018  
02/01/2019  
17/12/2018  
17/12/2018  
12/11/2018  
13/11/2018  
12/11/2018

22/10/2018  
17/12/2018  
23/10/2018  
09/10/2018  
03/10/2018  
02/10/2018  
09/01/2019  
18/09/2018  
11/09/2018  
08/11/2018  
04/09/2018  
04/09/2018  
04/09/2018  
07/05/2019  
04/09/2018  
04/09/2018  
07/05/2019  
20/08/2018  
31/07/2018  
06/08/2018  
13/11/2019  
24/07/2018  
13/07/2018  
09/07/2018  
23/07/2018  
09/07/2018  
09/07/2018  
09/07/2018  
04/09/2018  
09/07/2018  
09/07/2018  
03/07/2018  
09/07/2018  
18/06/2018  
18/06/2018  
02/10/2018  
11/06/2018  
11/06/2018  
17/12/2018  
05/06/2018  
16/05/2018  
09/05/2018  
25/05/2018  
01/05/2018  
08/05/2018  
08/05/2018  
22/04/2018  
08/05/2018

18/06/2018  
08/05/2018  
08/05/2018  
10/04/2018  
12/11/2018  
03/04/2018  
12/11/2018  
21/03/2018  
22/03/2018  
19/03/2018  
08/03/2018  
15/01/2019  
19/03/2018  
19/02/2018  
14/02/2018  
19/02/2018  
30/01/2018  
15/01/2018  
11/01/2018  
11/01/2018  
30/01/2018  
11/01/2018  
16/01/2018  
30/01/2018  
19/12/2017  
19/12/2017  
19/12/2017  
19/12/2017  
21/11/2017  
11/12/2017  
17/11/2017  
27/11/2017  
21/11/2017  
19/12/2017  
19/02/2018  
14/11/2017  
07/11/2017  
19/12/2017  
08/05/2018  
10/05/2018  
08/11/2018  
11/10/2017  
02/11/2017  
04/10/2017  
02/11/2017  
29/09/2017  
29/09/2017  
03/10/2017

02/11/2017  
19/03/2018  
19/09/2017  
12/09/2017  
19/09/2017  
12/09/2017  
19/09/2017  
19/09/2017  
19/09/2017  
05/09/2017  
19/09/2017  
02/11/2017  
30/08/2017  
08/11/2018  
08/11/2018  
19/09/2017  
16/08/2017  
07/08/2017  
02/08/2017  
07/08/2017  
07/08/2017  
31/07/2017  
07/08/2017  
07/08/2017  
18/07/2017  
17/07/2017  
07/08/2017  
09/04/2018  
05/09/2018  
07/08/2017  
28/11/2017  
26/06/2017  
26/06/2017  
12/06/2017  
06/06/2017  
12/06/2017  
26/05/2017  
26/05/2017  
16/05/2017  
03/05/2017  
02/05/2017  
24/04/2017  
30/08/2017  
19/09/2017  
02/05/2017  
19/04/2017  
19/04/2017  
08/05/2018

23/03/2017  
21/02/2017  
21/02/2017  
02/05/2017  
28/11/2017  
08/02/2017  
19/04/2017  
03/02/2017  
21/02/2017  
08/05/2018  
16/01/2017  
23/01/2017  
12/01/2017  
28/12/2016  
12/01/2017  
21/02/2017  
07/12/2016  
07/12/2016  
12/01/2017  
01/12/2016  
21/02/2017  
09/05/2018  
16/11/2016  
09/04/2018  
15/11/2016  
21/02/2017  
25/10/2016  
25/10/2016  
25/10/2016  
30/09/2016  
04/10/2016  
04/10/2016  
20/09/2016  
04/10/2016  
14/09/2016  
20/09/2016  
04/10/2016  
25/10/2016  
24/08/2016  
24/08/2016  
03/08/2016  
26/07/2016  
28/07/2016  
26/07/2016  
14/07/2016  
14/07/2016  
27/06/2016  
27/06/2016

14/07/2016  
27/06/2016  
27/06/2016  
22/06/2016  
21/02/2017  
27/06/2016  
28/11/2017  
23/06/2016  
14/07/2016  
10/06/2016  
10/06/2016  
10/06/2016  
14/07/2016  
28/04/2016  
10/06/2016  
28/04/2016  
27/04/2016  
11/04/2016  
24/08/2016  
06/04/2016  
01/04/2016  
05/09/2018  
01/04/2016  
01/04/2016  
23/03/2016  
23/03/2016  
27/04/2016  
09/03/2016  
08/03/2016  
16/03/2016  
16/03/2016  
29/02/2016  
29/02/2016  
22/02/2016  
15/02/2016  
15/03/2016  
29/02/2016  
22/06/2018  
14/07/2016  
22/02/2016  
22/02/2016  
13/01/2016  
08/01/2016  
04/01/2016  
04/01/2016  
22/12/2015  
22/02/2016  
16/03/2016

21/12/2015  
30/11/2015  
08/01/2016  
07/06/2016  
07/06/2016  
07/06/2016  
13/01/2016  
09/04/2018  
12/11/2015  
13/11/2015  
05/11/2015  
05/11/2015  
10/06/2016  
12/11/2015  
09/04/2018  
05/11/2015  
05/11/2015  
27/10/2015  
05/11/2015  
05/11/2015  
21/10/2015  
21/10/2015  
21/10/2015  
21/10/2015  
21/10/2015  
06/10/2015  
06/10/2015  
14/09/2015  
14/09/2015  
26/08/2015  
26/08/2015  
26/08/2015  
26/08/2015  
18/08/2015  
10/08/2015  
22/07/2015  
20/07/2015  
28/09/2015  
26/08/2015  
07/07/2015  
22/02/2016  
07/07/2015  
10/08/2015  
28/09/2015  
22/06/2015  
22/06/2015  
22/06/2015  
07/07/2015

12/06/2015  
20/07/2015  
04/06/2015  
01/06/2015  
01/06/2015  
26/05/2015  
22/06/2015  
01/06/2015  
19/05/2015  
19/05/2015  
19/05/2015  
22/07/2015  
19/05/2015  
07/07/2015  
21/10/2015  
19/05/2015  
19/05/2015  
19/05/2015  
19/05/2015  
20/07/2015  
10/06/2016  
18/03/2015  
04/03/2015  
03/03/2015  
03/03/2015  
09/03/2015  
25/02/2015  
09/02/2015  
03/02/2015  
03/02/2015  
29/01/2015  
03/02/2015  
21/01/2015  
15/01/2015  
21/01/2015  
22/01/2015  
07/01/2015  
12/01/2015  
07/01/2015  
07/01/2015  
12/01/2015  
30/12/2014  
07/01/2015  
06/01/2015  
06/01/2015  
09/02/2015  
30/12/2014  
21/01/2015

10/12/2014  
10/12/2014  
04/12/2014  
04/12/2014  
04/12/2014  
04/12/2014  
04/12/2014  
02/12/2014  
01/12/2014  
24/11/2014  
24/11/2014  
24/11/2014  
24/11/2014  
24/11/2014  
24/11/2014  
24/11/2014  
24/11/2014  
24/11/2014  
24/11/2014  
12/01/2015  
12/11/2014  
21/01/2015  
12/11/2014  
12/11/2014  
06/01/2015  
12/11/2014  
11/11/2014  
19/11/2014  
12/11/2014  
04/11/2014  
21/01/2015  
25/11/2014  
30/10/2014  
20/10/2014  
21/10/2014  
21/10/2014  
21/10/2014  
21/10/2014  
14/10/2014  
21/10/2014  
12/01/2015  
21/10/2014  
07/10/2014  
21/01/2015  
23/09/2014  
07/10/2014  
29/09/2014  
17/09/2014  
17/09/2014

17/09/2014  
03/02/2015  
09/09/2014  
09/09/2014  
09/09/2014  
07/10/2014  
04/09/2014  
04/09/2014  
07/10/2014  
07/10/2014  
12/01/2015  
07/10/2014  
28/08/2014  
07/02/2017  
26/08/2014  
19/08/2014  
19/08/2014  
02/10/2014  
08/08/2014  
14/08/2014  
04/08/2014  
04/08/2014  
04/08/2014  
31/07/2014  
30/07/2014  
25/07/2014  
07/10/2014  
19/05/2015  
07/10/2014  
04/08/2014  
07/10/2014  
21/01/2015  
14/08/2014  
08/07/2014  
15/07/2014  
15/07/2014  
08/08/2014  
07/10/2014  
08/08/2014  
12/10/2018