



# Vehicle Service Records (VSR Explorer)

## Repair history D-201846

**Registration nr:** XQ93AJ  
**Market type:** FH13A64T

**Chassis nr:** D-201846  
**Country:** AUS

**VIN nr:** YV5RG40D8FD201846  
**Delivery date:** 2015-07-15

PC	Type	Code	Description (Original)	#
<b>2024-05-23 - Mileage: 1455883 - Order nr: 8189045</b>				
	*	M	PLEASE FILL IN	
		LO-255	Blown turbo	6
		VO-85020372	TURBOCHARGER, EXCH	1
		VO-20784537	GASKET TURBO BASE	1
		VO-21940615	SEALING RING - PURPLE	1
		VO-22206133	TURBO FEED GASKET	1
		VO-420643	TURBO DRAIN GKT	1
		VO-469601	O-RING TURBO - GREEN	1
		VO-990950	FLANGE NUT M8 CRIMP	1
		VO-993811	FLANGE BOLT M10 x 50mm TURBO	4
		VO-994441	FLANGE BOLT M8 x 50mm Black	1
		VO-21940610	SEALING RING - PURPLE	1
		VO-21834205	Air Fliter - Outer	1
		VO-23294956	AIR FILTER - INNER	1
		AU2-9718-240002743	BBC4 BRAKE CLEANER	1
		VO-20573472	SPACER 10mm x 20mm x 16mm	4
		VO-20855371	GASKET EXH/MANIFOLD	6
		AU2-WUR0673205010	Nylon Power LOC 2I	3
		OTH-FAB1	TAPE MASKING GREEN 48MM	1
		VO-85103205	GREEN PAINT	1
		OTH-WUR0674850240/MTR	EMERY CLOTH G240	1
		VO-20938963	SEAL	1
		VO-21433769	SEALING RING - MANIFOLD	2
		VO-21312238	CHARGE AIR HOSE	1
		VO-20883450	SEALING RING	1
		VO-21433769	SEALING RING - MANIFOLD	1
			Aaron:0417 631 673	
			COMPLETED	
			Removed intakes and found turbo siezed in housing, also	
	*	97	ENVIRONMENTAL CHARGE	

PC	Type	Code	Description (Original)	#
	🗄️		.	
	🗄️		Complete	
	🗄️		aaronm@nolanstransport.com.au	
	🗄️		Mileage:1455883	
	🗄️		Hrs:21079	
	🗄️		Parked: P15	
	🗄️		found exhaust manifold leaking at head. Removed failed	
	🗄️		turbo and manifold and inspected for any foreign material	
	🗄️		or oil in exhaust or intake and was all ok, turbo still all	
	🗄️		intact. Removed exhaust housing to inspect and found	
	🗄️		heat shield had bound up on exhaust wheel. Replaced	
	🗄️		manifold gaskets and slip joint seals and replaced turbo	
	🗄️		and associated gaskets and seals. Cleaned down and road	
	🗄️		tested to check.	
🟢	*	91	WORKSHOP CONSUMABLES	
🔍 <b>2022-02-24 - Mileage: 1303501 - Order nr: 8154897</b>				
🟢	*	M	PLEASE FILL IN	
	🗄️		Derek:54 662 903	
🟢	🟡	LO-874	Air conditioning not working Ref Luke.B	11.48
🟢	🟡	LO-873	Heater hoses about to blow off	1.52
🟢	🔧	VO-23847282	HOSE HEATER	1
🟢	🔧	VO-20722710	HOSE CLAMP 16-27mm	2
🟢	🔧	VO-85013654	COMPRESSOR, EXCH - AIR CON	1
🟢	🔧	VO-20443759	O-RING	2
🟢	🔧	VO-20708247	O-RING 3/4 A/C	2
🟢	🔧	OTH-TXX2631	ORIFICE TUBE FILTER A/CON	1
🟢	🔧	VO-23858694	ACCUMULATOR	1
🟢	🔧	VO-23847736	DECAL	1
🟢	🔧	VO-23515346	VENTILATION FILTER	1
🟢	🔧	VO-23515329	VENTILATION FILTER	1
🟢	🔧	VO-82348991	EVAPORATOR	1
🟢	🔧	VO-82356760	O-RING	1
🟢	🔧	VO-82386482	O-RING	1
🟢	🔧	VO-82356762	O-RING - A/CON	1
🟢	🔧	VO-82356754	O-RING	1
🟢	🔧	VO-82356756	O-RING	1
🟢	🔧	VO-21843360	SEALING ORING - AIR CON Orange	2
🟢	🔧	VO-3090885	O-RING KIT A/C	1

PC	Type	Code	Description (Original)	#
		VO-23437874	CONDENSER	1
			***IBT FROM NORTHSIDE 24/2***	
		LO-3000	FLS fault on dash	8
		VO-22302612	CONTROL UNIT - COLLISION WARN	1
		VO-21511728	HOUSING	1
		VO-11170332	CABLE TERMINAL	7
		VO-994718	SEALING	4
		VO-994719	PLUG	4
		VO-84055742	LAMP SPOT LH - FH(4)	1
		VO-84055744	LAMP SPOT RH - FH(4)	1
		VO-78614895	TRIM PANEL	1
		AU2- CBC310ML550FCBK	3M 550FC PU ADHESI	2
		LO-356	Globetrotter sign cracked & roof lights	6
			leaking	
			New Serial Number: 002543580170	
		97	ENVIRONMENTAL CHARGE	
			Removed coolant and replaced the heater hose.	
			Plug damaged from impact causing FLS sensor to failed.	
			Removed bulbar and steps. Removed grill and FLS sensor.	
			Replaced plug and fit new sensor and refit drill, steps,	
			and bull bar. Hooked up tech tool and pull codes. Clear	
			and calibrated FLS.	
			Note	
			Significant water leak in cab from RHS.	
			Removed and replaced the globetrotter sign and side	
			lights. Damaged caused by impact.	
			Old Serial Number: 002086481170	
			Tested the AC operation. Checked for leaks with UV light.	
			No obvious side of leak. Recovered 0.54kg of gas. Orifice	
			filter was damaged. Ordered condenser, evaporator,	
			compressor and filters. Removed and replaced all the	
			components listed. re gassed the system tested for	
			operation.	
		MTELEC17	4000- Air Con Gas mack/volvo classic	
		91	WORKSHOP CONSUMABLES	
<b>2020-02-14 - Mileage: 1039533 - Order nr: 7602859</b>				
		LO-510	A TRAILER , ONE BRAKE HAS	1.5

PC	Type	Code	Description (Original)	#
	🗑️		SMOKE COMING OUT OF IT	
🟢	*	1940100	TRAVEL TO PARKING BAY 2 KMS	
	🗑️		NORTH OF HEXHAM ROUND ABOUT	
	🗑️		DRIVER 0448 024 887	
	🗑️		MATT THE BOSS 0429 267 588	
	🗑️		P.A TRAILER , ONE BRAKE HAS SMOKE COMING OUT OF IT	
	🗑️		C.BOOSTER IN WRONG MOUNT POINT	
	🗑️		R.-TRAVELLED TO HEXHAM	
	🗑️		-REMOVED BOOSTER AND REPOSITION	
	🗑️		-TEMP REPAIR TO GET VEHICLE MOBILE AS BOOSTER ROD HAD	
	🗑️		RUBBED	
🟢	*	91	WORKSHOP CONSUMABLES	
<b>🔍 2019-10-02 - Mileage: 932869 - Order nr: 7259544</b>				
	🗑️		JIM 0417 631 673	
	🗑️		HRS 11896	
🟢	🟡	LO-210	DIAGNOSE AND REPORT ON ENGINE MISS	15
	🗑️		AND BLOWING SMOKE	
🟢	🔧	VO-21768034	VRS KIT	0.7
🟢	🔧	VO-85020372	TURBOCHARGER, EXCH	0.7
🟢	🔧	VO-994447	FLANGE SCREW	29
🟢	🔧	VO-8192804	SCREW	8
🟢	🔧	VO-990810	FLANGE SCREW	6
🟢	🔧	VO-21344774	FLANGE SCREW	6
🟢	🔧	VO-85013271	UNIT INJECTOR, EXC	0.7
🟢	🔧	AU2-9718-240002743	9718-BBC4 B/CLEANER	2
🟢	🔧	OTH-INTMX630	RUBBER GREASE	1
🟢	🔧	MK-342SX33	SILICOM DOW	1
🟢	🔧	VO-21503575	SEALING RING	1
🟢	🔧	VO-944126	O-RING	1
🟢	🔧	VO-993977	HOSE CLAMP	1
🟢	🔧	VO-993811	FLANGE SCREW	4
🟢	🔧	VO-20573472	SPACER SLEEVE	4
🟢	🔧	VO-994441	FLANGE SCREW	1
🟢	🔧	VO-990950	FLANGE LOCK NUT	1
	🗑️		Checked faults & found injector 6 faults, carry out	
	🗑️		compression test & found cylinder 6 low, remove all intake	
	🗑️		arrangements, tappet cover & all accessories required inc	
	🗑️		engine camshaft, rockers & injectors, remove intake &	

PC	Type	Code	Description (Original)	#
	🔧		exhaust manifolds, all wiring/hoses/clamps, drain coolant	
	🔧		from engine, remove head & found exhaust valve number 6	
	🔧		chipped & not sealing, clean all deck surfaces (cylinder	
	🔧		head/block/manifolds etc) & check all cylinder liner	
	🔧		heights & replace any hoses/clamps etc as required,	
	🔧		fit reman cylinder head & carry out tensioning procedures,	
	🔧		re-assembled with new injector 6 & turbo charger, replace	
	🔧		all seal & gaskets as listed below, carry out engine valve	
	🔧		& injector adjustments run up engine to operating	
	🔧		temperature, wash down & road testing, found exhaust back	
	🔧		pressure above spec on road test, quoted customer refer	
	🔧		job 254 for repairs.	
	🔧		30% of major parts and labour covered under goodwill	
🔧	🔧	VO-85022413	EXCH CLY HEAD	0.7
	🔧		*** POSSIBLE POLICY CLAIM ***	
	🔧		TW180236556	
	🔧		*** POSSIBLE POLICY CLAIM ***	
	🔧		Serial No; P21995790	
	🔧		162441807	
	🔧		*** POSSIBLE POLICY CLAIM ***	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 <b>2019-10-02 - Mileage: 932869 - Order nr: 2881725</b>				
	🔧		JIM 0417 631 673	
	🔧		HRS 11896	
🔧	🔧	LO-210	DIAGNOSE AND REPORT ON ENGINE MISS	15
	🔧		AND BLOWING SMOKE	
🔧	🔧	VO-85022413	EXCH CYL HEAD	0.7
🔧	🔧	VO-21768034	VRS KIT	0.7
🔧	🔧	VO-85020372	TURBOCHARGER, EXCH	0.7
🔧	🔧	VO-994447	FLANGE SCREW	29
🔧	🔧	VO-8192804	SCREW	8
🔧	🔧	VO-990810	FLANGE SCREW	6
🔧	🔧	VO-21344774	FLANGE SCREW	6
🔧	🔧	VO-85013271	UNIT INJECTOR, EXC	0.7
🔧	🔧	AU2-9718-240002743	9718-BBC4 B/CLEANER	2
🔧	🔧	OTH-INTMX630	RUBBER GREASE	1
🔧	🔧	MK-342SX33	SILICOM DOW	1
🔧	🔧	VO-21503575	SEALING RING	1

PC	Type	Code	Description (Original)	#
		VO-944126	O-RING	1
		VO-993977	HOSE CLAMP	1
		VO-993811	FLANGE SCREW	4
		VO-20573472	SPACER SLEEVE	4
		VO-994441	FLANGE SCREW	1
		VO-990950	FLANGE LOCK NUT	1
			Checked faults & found injector 6 faults, carry out	
			compression test & found cylinder 6 low, remove all intake	
			arrangements, tappet cover & all accessories required inc	
			engine camshaft, rockers & injectors, remove intake &	
			exhaust manifolds, all wiring/hoses/clamps, drain coolant	
			from engine, remove head & found exhaust valve number 6	
			chipped & not sealing, clean all deck surfaces (cylinder	
			head/block/manifolds etc) & check all cylinder liner	
			heights & replace any hoses/clamps etc as required,	
			fit reman cylinder head & carry out tensioning procedures,	
			re-assembled with new injector 6 & turbo charger, replace	
			all seal & gaskets as listed below, carry out engine valve	
			& injector adjustments run up engine to operating	
			temperature, wash down & road testing, found exhaust back	
			pressure above spec on road test, quoted customer refer	
			job 254 for repairs.	
			30% of major parts and labour covered under goodwill	
			Serial No; P21995790	
			162441807	
			TW180236556	
		91	WORKSHOP CONSUMABLES	
<b>2019-10-02 - Mileage: 0 - Order nr: 8122462</b>				
		214	Cylinder head, replace	
		20	Sublet VCV Sydney	
			210?DIAGNOSE AND REPORT ON ENGINE AND BLOWING	
			SMOKE?MISS???1800.00	
			Checked faults & found injector 6 faults, carry out	
			compression test & found cylinder 6 low, remove all intake	
			arrangements, tappet cover & all accessories required inc	
			engine camshaft, rockers & injectors, remove intake &	
			exhaust manifolds, all wiring/hoses/clamps, drain coolant	
			from engine, remove head & found exhaust valve number 6	

PC	Type	Code	Description (Original)	#
	🔧		chipped & not sealing, clean all deck surfaces (cylinder	
	🔧		head/block/manifolds etc) & check all cylinder liner	
	🔧		heights & replace any hoses/clamps etc as required,	
	🔧		fit reman cylinder head & carry out tensioning procedures,	
	🔧		re-assembled with new injector 6 & turbo charger, replace	
	🔧		all seal & gaskets as listed below, carry out engine valve	
	🔧		& injector adjustments run up engine to operating	
	🔧		temperature, wash down & road testing, found exhaust back	
	🔧		pressure above spec on road test, quoted customer refer	
	🔧		job 254 for repairs.	
	🔧		30% of major parts and labour covered under goodwill	
<b>🔍 2019-07-10 - Mileage: 932869 - Order nr: 7259277</b>				
	🔧		JIM 0417 631 673	
	🔧		HRS 11896	
🟢	🟡	LO-210	DIAGNOSE AND REPORT ON ENGINE MISS	15
	🔧		AND BLOWING SMOKE	
🟢	🔧	VO-85022413	EXCH CYL HEAD	0.7
🟢	🔧	VO-21768034	VRS KIT	0.7
🟢	🔧	VO-85020372	TURBOCHARGER, EXCH	0.7
🟢	🔧	VO-994447	FLANGE SCREW	29
🟢	🔧	VO-8192804	SCREW	8
🟢	🔧	VO-990810	FLANGE SCREW	6
🟢	🔧	VO-21344774	FLANGE SCREW	6
🟢	🔧	VO-85013271	UNIT INJECTOR, EXC	0.7
🟢	🔧	AU2-9718-240002743	9718-BBC4 B/CLEANER	2
🟢	🔧	OTH-INTMX630	RUBBER GREASE	1
🟢	🔧	MK-342SX33	SILICOM DOW	1
🟢	🔧	VO-21503575	SEALING RING	1
🟢	🔧	VO-944126	O-RING	1
🟢	🔧	VO-993977	HOSE CLAMP	1
🟢	🔧	VO-993811	FLANGE SCREW	4
🟢	🔧	VO-20573472	SPACER SLEEVE	4
🟢	🔧	VO-994441	FLANGE SCREW	1
🟢	🔧	VO-990950	FLANGE LOCK NUT	1
🟢	🟡	LO-254	RECTIFY MUFFLER HAS HIGH BACK PRESSURE	4
🟢	🔧	VO-21383182	SILENCER	1
	🔧		Checked faults & found injector 6 faults, carry out	
	🔧		Remove all muffler accessories & R&R muffler refitting all	

PC	Type	Code	Description (Original)	#
	🔧		accessories, check on 2nd road test ok.	
	🔧		compression test & found cylinder 6 low, remove all intake	
	🔧		arrangements, tappet cover & all accessories required inc	
	🔧		engine camshaft, rockers & injectors, remove intake &	
	🔧		exhaust manifolds, all wiring/hoses/clamps, drain coolant	
	🔧		from engine, remove head & found exhaust valve number 6	
	🔧		chipped & not sealing, clean all deck surfaces (cylinder	
	🔧		head/block/manifolds etc) & check all cylinder liner	
	🔧		heights & replace any hoses/clamps etc as required,	
	🔧		fit reman cylinder head & carry out tensioning procedures,	
	🔧		re-assembled with new injector 6 & turbo charger, replace	
	🔧		all seal & gaskets as listed below, carry out engine valve	
	🔧		& injector adjustments run up engine to operating	
	🔧		temperature, wash down & road testing, found exhaust back	
	🔧		pressure above spec on road test, quoted customer refer	
	🔧		job 254 for repairs.	
	🔧		30% of major parts and labour covered under goodwill	
	🔧		Serial No; P21995790	
	🔧		162441807	
🔧	🔧	VO-2140000	Valve mechanism. Secondary operation num	3.5
🔧	🔧	VO-85022413	EXCH CLY HEAD	0.3
🔧	🔧	VO-21768034	VRS KIT	0.3
🔧	🔧	VO-85020372	TURBOCHARGER, EXCH	0.3
🔧	🔧	VO-85013271	UNIT INJECTOR, EXC	0.3
	🔧		TW180236556	
	🔧		S/L TW180236556	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 <b>2019-03-06 - Mileage: 793994 - Order nr: 8113601</b>				
🔧	🔧	VO-84433698	AIRBAG MODULE	1
🔧	🔧	VO-8842000	Airbag module, replace	0.3
🔍 <b>2018-03-23 - Mileage: 592211 - Order nr: 8099527</b>				
🔧	*	818	Cab airbag covers	
🔧	🔧	MK-9739-16488479	CAB AIR BAG ISULAT	2
🔍 <b>2018-01-25 - Mileage: 565081 - Order nr: 8097161</b>				
🔧	*	818	Check headlight panels	
🔧	🔧	VO-21874450	PANEL H/LAMP LH	1
🔧	🔧	VO-21874457	PANEL H/LAMP RH	1
🔧	🔧	VO-82884080	AIR DUCT	1



PC	Type	Code	Description (Original)	#
		VO-82884084	AIR DUCT	1
			Ordered the panels and send it for fitments.	
<b>2018-01-25 - Mileage: 565081 - Order nr: 4085380</b>				
	*	M	PLEASE FILL IN	
			Contact:Jim 0417 631 673	
		LO-212	Cylinder head, replacement	16
			Mileage:	
			Hrs:	
		VO-85134750	SEALANT	1
		VO-1547254	SEALING RING	2
		VO-1677370	SEALING RING	2
		VO-20479636	SEALING STRIP	1
		VO-20526428	SEALING RING	1
		VO-20538793	SEAL STRIP, R/COVER GASKET	1
		VO-20852765	DOWDY WASHER O.D. 24mm	4
		VO-20855371	GASKET EXH/MANIFOLD	6
		VO-21282255	GASKET	1
		VO-21503575	SEALING RING	1
		VO-21510072	CYLINDER HEAD GASK	1
		VO-8192804	SCREW	2
		VO-85013933	CYL HEAD, EXC - FM(4) / FH(4)	1
		VO-944126	O-RING INJ HARNESSD9B/D12D/D13	1
	*	818	Check if rear cab airbags have covers	
		MK-9718-BBC4	Brake Cleaner 400G	2
		AU2-WUR0674850120	EMERY CLTH-ROLL-120	1
		AU2-WUR0674850240	EMERY CLOTH 240 GRIT	1
		VO-994447	FLANGE SCREW	6
		VO-990810	FLANGE BOLT M12 x 45mm	4
		VO-21344774	FLANGE BOLT M10 x 50mm Grey	6
		VO-276948	O-RING KIT	6
		VO-22343361	CABLE HARNESS - FM/FH(4)	1
		VO-21447682	GASKET	1
		AU2-PERM84101	PX POXY 5 MIN GENP	1
		VO-22206133	TURBO FEED GASKET	1
		VO-469601	TURBO O-RING	1
		VO-420643	TURBO DRAIN GKT	1
		VO-21940615	SEALING RING	1
		VO-984739	FLANGE BOLT M8 x 50mm	1

PC	Type	Code	Description (Original)	#
		VO-990950	FLANGE NUT CRIMP M8	1
		AU2-CAL85108913	VOLVO VCS COOLANT - 5LTR	1
		LO-210	replace injector harness	6
		LO-371	Check power lug	0.1
		LO-818	Check headlight panels	2
		VO-8131393	CAGE	4
		VO-983472	CABLE TIE, Injector Harness	8
		MK-NARV56306	CABLE TIE 1=25PK	1
		VO-3963413	ATTACHING RING	1
			AU2/CAL85108913 WAS FITTED BY BRANCH 2300	
			.- ON REPAIR ORDER 7575499 - DATE 2017-11-09 MILEAGE - 520894	
		VO-21874450	PANEL H/LAMP LH	1
			VO/21874450 WAS FITTED BY BRANCH 4000	
			.- ON REPAIR ORDER 8089634 - DATE 2017-10-06 MILEAGE - 500004	
		VO-21874457	PANEL H/LAMP RH	1
			VO/21874457 WAS FITTED BY BRANCH 4000	
			.- ON REPAIR ORDER 8089634 - DATE 2017-10-06 MILEAGE - 500004	
		20	paint panels	
		MTELEC85	Assembly Lube	
		VO-82884080	AIR DUCT	1
			VO/82884080 WAS FITTED BY BRANCH 4000	
			.- ON REPAIR ORDER 8089634 - DATE 2017-10-06 MILEAGE - 500004	
		VO-82884084	AIR DUCT	1
			VO/82884084 WAS FITTED BY BRANCH 4000	
			.- ON REPAIR ORDER 8089634 - DATE 2017-10-06 MILEAGE - 500004	
		97	ENVIRONMENTAL CHARGE	
			Ordered the panels and send it for fitments.	
			Inspected and the lug and found no issue.	
			Removed and replaced the injector harness.	
			Drained the coolant and removed all turbo piping. Pulled off	
			all electrical around head. Removed rocker cover and pulled	
			out injectors, rocker gear, and cam gear. Removed the head	
			and cleaned the mountings. Groomed the new head. Fitted the	
			head. Carried out back lash and cam timing. Reassembled with	
			the parts listed. Tested for operation.Ok.	
			and fit with reinforcements.	
		91	WORKSHOP CONSUMABLES	

**2018-01-24 - Mileage: 565081 - Order nr: 8097160**

PC	Type	Code	Description (Original)	#
		VO-2112600	Cylinder head, replace	8.4
		VO-85134750	SEALANT	1
		VO-1547254	SEALING RING	2
		VO-1677370	SEALING RING	2
		VO-20479636	SEALING STRIP	1
		VO-20526428	SEALING RING	1
		VO-20538793	SEAL STRIP, R/COVER GASKET	1
		VO-20852765	DOWDY WASHER O.D. 24mm	4
		VO-20855371	GASKET EXH/MANIFOLD	6
		VO-21282255	GASKET	1
		VO-21503575	SEALING RING	1
		VO-21510072	CYLINDER HEAD GASK	1
		VO-8192804	SCREW	2
		VO-85013933	CYL HEAD, EXC - FM(4) / FH(4)	1
		VO-944126	O-RING INJ HARNESSD9B/D12D/D13	1
		818	Check if rear cab airbags have covers	
		MK-9718-BBC4	Brake Cleaner 400G	2
		AU2-WUR0674850120	EMERY CLTH-ROLL-120	1
		AU2-WUR0674850240	EMERY CLOTH 240 GRIT	1
		VO-994447	FLANGE SCREW	6
		VO-990810	FLANGE BOLT M12 x 45mm	4
		VO-21344774	FLANGE BOLT M10 x 50mm Grey	6
		VO-276948	O-RING KIT	6
		VO-22343361	CABLE HARNESS - FM/FH(4)	1
		VO-21447682	GASKET	1
		AU2-PERM84101	PX EPOXY 5 MIN GENP *	1
		VO-22206133	TURBO FEED GASKET	1
		VO-469601	TURBO O-RING	1
		VO-420643	TURBO DRAIN GKT	1
		VO-21940615	SEALING RING	1
		VO-984739	FLANGE BOLT M8 x 50mm	1
		VO-990950	FLANGE NUT CRIMP M8	1
		AU2-CAL85108913	VOLVO VCS COOLANT - 5LTR	1
		VO-2860300	Wiring harness, replace. Unit injectors	1.2
		371	Check power lug	
		VO-8131393	CAGE	4
		VO-983472	CABLE TIE, Injector Harness	8
		MK-NARV56306	CABLE TIE 1=25PK	1

PC	Type	Code	Description (Original)	#
		VO-3963413	ATTACHING RING	1
			Inspected and the lug and found no issue.	
		VO-1820200	Localised wash for fault tracing	0.3
<b>2018-01-08 - Mileage: 565081 - Order nr: 8092994</b>				
		M	PLEASE FILL IN	
			Contact:Jim 0417 631 673	
		LO-212	Cylinder head, replacement	16
			Mileage:	
			Hrs:	
		VO-85134750	SEALANT	1
		VO-1547254	SEALING RING	2
		VO-1677370	SEALING RING	2
		VO-20479636	SEALING STRIP	1
		VO-20526428	SEALING RING	1
		VO-20538793	SEAL STRIP, R/COVER GASKET	1
		VO-20852765	DOWDY WASHER O.D. 24mm	4
		VO-20855371	GASKET EXH/MANIFOLD	6
		VO-21282255	GASKET	1
		VO-21503575	SEALING RING	1
		VO-21510072	CYLINDER HEAD GASK	1
		VO-8192804	SCREW	2
		VO-85013933	CYL HEAD, EXC - FM(4) / FH(4)	1
		VO-944126	O-RING INJ HARNESSD9B/D12D/D13	1
		818	Check if rear cab airbags have covers	
		MK-9718-BBC4	Brake Cleaner 400G	2
		AU2-WUR0674850120	EMERY CLTH-ROLL-120	1
		AU2-WUR0674850240	EMERY CLOTH 240 GRIT	1
		VO-994447	FLANGE SCREW	6
		VO-990810	FLANGE BOLT M12 x 45mm	4
		VO-21344774	FLANGE BOLT M10 x 50mm Grey	6
		VO-276948	O-RING KIT	6
		VO-22343361	CABLE HARNESS - FM/FH(4)	1
		VO-21447682	GASKET	1
		AU2-PERM84101	PX POXY 5 MIN GENP	1
		VO-22206133	TURBO FEED GASKET	1
		VO-469601	TURBO O-RING	1
		VO-420643	TURBO DRAIN GKT	1
		VO-21940615	SEALING RING	1

PC	Type	Code	Description (Original)	#
Ⓡ	■	VO-984739	FLANGE BOLT M8 x 50mm	1
Ⓡ	■	VO-990950	FLANGE NUT CRIMP M8	1
Ⓡ	■	AU2-CAL85108913	VOLVO VCS COOLANT - 5LTR	1
Ⓡ	⦿	LO-210	replace injector harness	6
Ⓡ	⦿	LO-371	Check power lug	0.1
Ⓡ	⦿	LO-818	Check headlight panels	2
Ⓡ	■	VO-8131393	CAGE	4
Ⓡ	■	VO-983472	CABLE TIE, Injector Harness	8
Ⓡ	■	MK-NARV56306	CABLE TIE 1=25PK	1
Ⓡ	■	VO-3963413	ATTACHING RING	1
	☒		AU2/CAL85108913 WAS FITTED BY BRANCH 2300	
	☒		.- ON REPAIR ORDER 7575499 - DATE 2017-11-09 MILEAGE - 520894	
Ⓡ	■	VO-21874450	PANEL H/LAMP LH	1
	☒		VO/21874450 WAS FITTED BY BRANCH 4000	
	☒		.- ON REPAIR ORDER 8089634 - DATE 2017-10-06 MILEAGE - 500004	
Ⓡ	■	VO-21874457	PANEL H/LAMP RH	1
	☒		VO/21874457 WAS FITTED BY BRANCH 4000	
	☒		.- ON REPAIR ORDER 8089634 - DATE 2017-10-06 MILEAGE - 500004	
Ⓡ	*	20	paint panels	
Ⓡ	*	MTELEC85	Assembly Lube	
Ⓡ	■	VO-82884080	AIR DUCT	1
	☒		VO/82884080 WAS FITTED BY BRANCH 4000	
	☒		.- ON REPAIR ORDER 8089634 - DATE 2017-10-06 MILEAGE - 500004	
Ⓡ	■	VO-82884084	AIR DUCT	1
	☒		VO/82884084 WAS FITTED BY BRANCH 4000	
	☒		.- ON REPAIR ORDER 8089634 - DATE 2017-10-06 MILEAGE - 500004	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	☒		Ordered the panels and send it for fitments.	
	☒		Inspected and the lug and found no issue.	
	☒		Removed and replaced the injector harness.	
	☒		Drained the coolant and removed all turbo piping. Pulled off	
	☒		all electrical around head. Removed rocker cover and pulled	
	☒		out injectors, rocker gear, and cam gear. Removed the head	
	☒		and cleaned the mountings. Groomed the new head. Fitted the	
	☒		head. Carried out back lash and cam timing. Reassembled with	
	☒		the parts listed. Tested for operation.Ok.	
	☒		and fit with reinforcements.	
Ⓡ	*	91	WORKSHOP CONSUMABLES	

PC	Type	Code	Description (Original)	#
 <b>2017-10-31 - Mileage: 520894 - Order nr: 7575499</b>				
			goodwill assistance sent to P.Moller G.R 01/11	
		VO-4112800	Clutch disc, pressure plate, clutch cyli	3.1
		LO-19400	Travel for WARRANTY breakdowns ONLY	3
		92	UTE MILEAGE	
		VO-85013766	CLUTCH KIT, EXCH	1
		VO-85020472	CLUTCH CYLINDER, E	1
		VO-20860677	SEALING RING	1
		VO-20992763	AIR HOSE	1
		VO-22327063	SOLENOID VALVE	1
		VO-1652986	BALL BEARING SPIGOT	1
		MK-5166-44279LOC	LOCTITE 10ML STUD	1
		MK-9718-BBC4	BRAKE CLEANER 400G	1
		VO-990818	STUD	2
		VO-990951	LOCK NUT M10 FLANGE	2
		20	Sublet CARTERS CLUTCHS	
		MK-NARV56306	CABLE TIE 1=25PK	1
		20	SUBLET TOW	
		VO-20483327	COVER	1
		VO-21666546	DISC	1
		VO-20497205	GASKET	1
		VO-995906	HEXAGON SCREW	8
		VO-25339078	HEXAGON NUT	8
		AU2-CAL85108913	COOLANT 5LTR VCS	1
			VEHICLE HAS LOST THROTTLE	
		VO-4008400	Clutch stroke length and wear, calibrati	0.2
			calibration	
		VO-4000300	Gearbox air leakage, test	0.2
		VO-4118000	Clutch sticking, test	0.1
		VO-4112600	Clutch wear, check. VCADS Pro operation	0.2
		VO-4001000	Clutch cylinder, test	0.2
		VO-2162100	Flywheel, replace. Gearbox and clutch re	0.6
			removed	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-4136100	Air hose, replace. CVU/CCA	0.5
		VO-4118300	Valve assembly, clutch, replace	0.5
		VO-4008300	PWM valves, clutch, test	0.2

PC	Type	Code	Description (Original)	#
		VO-4118200	PWM valves clutch, activation, test	0.2
			LOCATION BETWEEN NABIAC AND COLOONGALOOK	
<b>2017-09-22 - Mileage: 500004 - Order nr: 8089634</b>				
		352	LIGHTING - FRONT LIGHTS	
		VO-21874457	PANEL H/LAMP RH	1
		VO-21874450	PANEL H/LAMP LH	1
		VO-82884080	AIR DUCT	1
		VO-82884084	AIR DUCT	1
			SUPPLY RH & LH HEADLIGHT PANELS-GOODWILL REFER ROD BARRON	
			& MICHEAL GOMMERSAL	
<b>2017-07-31 - Mileage: 1234 - Order nr: 8091214</b>				
		LO-820	REINFORCE HEADLIGHT PANELS AND PAINT	7.77
			BONDING MATERIALS TO INNER FRAME WITH STIFFENERS TO SUIT-	
			Å400.00	
			PAINT TWO X HEADLIGHT PANELS NOLANS BLACK Å300.00	
<b>2017-07-05 - Mileage: 449410 - Order nr: 8089014</b>				
			EMS AND ACM, SW UPDATE. EU4/5. FH/FM (4)	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
		VO-2580700	Pump unit, replace	0.8
		VO-20915849	HOSE CLAMP 16-27mm	2
		VO-21032572	CLAMP	2
		VO-21429181	HOSE	3
		VO-22406383	KIT - ADBLUE GAUZE FILTER	1
		VO-22679934	T-PIPE	1
		VO-22681764	MANIFOLD - ADBLUE	1
		VO-3944785	AIR FILTER - COMP/ ADBLUE	1
		VO-4803748	HOSE - CORRUGATED	3
		VO-992081	HOSE CLAMP 12-22mm	2
		VO-22851845	PUMP UNIT- ADBLUE	1
		MK-NARV56410	CABLE TIE 1=100PK	1
		VO-984727	FLANGE BOLT M6 x 25mm Black	2
		VO-990949	FLANGE NUT CRIMP M6	2
		LO-258	EMISSIONS AFTER-TREATMENT	1.5
			Derated to 1500 rpm ad-blu issue	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2584600	SCR system, test	0.5
		2580700	Pump unit, replace	

PC	Type	Code	Description (Original)	#
	*	2580700	Pump unit, replace.	
		VO-2580300	AdBlue tank, replace	1.3
		VO-2585800	AdBlue tank, clean. Urea tank removed	0.5
		VO-2580000	Emissions after-treatment. Secondary ope	0.2
	*	20	80lt Ad-Blu	
<b>2017-05-12 - Mileage: 410060 - Order nr: 8087288</b>				
		VO-2580000	Emissions after-treatment. Secondary ope	0.1
		VO-21480006	FILLER NECK	1
		VO-994848	WASHER	2
<b>2017-04-18 - Mileage: 398871 - Order nr: 71791</b>				
		VO-85020789	STARTER MOTOR, EXC	1
		VO-3710000	CHECK BATTERY CABLES FROM BATTERIS TO STARTER AND BATTERY TO EARTH.	0.2
		VO-3116800	Battery system, test. Battery tester	0.4
			ATTEND TO CALL OUT, VEHICLE NOT STARTING	
		VO-3310600	Starter motor, replace	0.4
		1940000	TRAVEL, DEALERSHIP TO SOUTH OF CLYBUCCA AND RETURN	3
			ATTEND TO CALL OUT, VEHICLE NOT STARTING	
<b>2017-01-12 - Mileage: 338995 - Order nr: 8082361</b>				
			C3628 Cab, interior lights, cable harness, install. FH (4)	
			S3652 ACM, SW update. FH/FM (4)	
		LO-3540800	C3628 Interior light cable harness	0.5
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2510400	Gaskets, exhaust manifold, replace	1.8
		VO-22935545	WIRES	8
		VO-993811	FLANGE BOLT M10 x 50mm Black	4
		VO-20573472	SPACER SLEEVE	4
		VO-21344787	FLANGE BOLT M10 x 90mm Black	12
		VO-20855371	GASKET EXH/MANIFOLD	6
		VO-20784537	GASKET TURBO BASE	1
		VO-420643	TURBO DRAIN GKT	1
		VO-469601	TURBO O-RING	1
		VO-420641	TURBO FEED GKT	1
		VO-20938963	SEAL	1
		MK-9718-BBC4	CLEANER 400G BRAKE	1
	*	20	Sublet E/E Ä 4019122	
			MACHINE MANIFOLD	
		VO-2549400	ACM, SW, update. only campaign	0.2



PC	Type	Code	Description (Original)	#
<b>2016-09-05 - Mileage: 230327 - Order nr: 8077320</b>				
	*	761	Rear shockies leaking	
	■	VO-20585556	SHOCK ABSORBER	2
<b>2016-08-03 - Mileage: 232339 - Order nr: 8076241</b>				
	*	M	PLEASE FILL IN	
	☒		Name:Daryl	
	⚙	LO-372	Set speed limit to 100km/h	1.5
	☒		Phone:5466 2951	
	☒		Mileage:	
	☒		Hrs:	
	☒		Test drove the vehicle and compares the vehicle speed with	
	☒		GPS. Found vehicle doing 98km/h. Calculate new k factor and	
	☒		program.	
	*	91	WORKSHOP CONSUMABLES	
<b>2016-07-28 - Mileage: 228250 - Order nr: 8076026</b>				
	⚙	VO-1774600	Annual service. Chassis lubrication and	2.4
	⚙	VO-1706400	12 Months ECU download and oil sample. O	0.9
	⚙	LO-8600100	C3538 Cab tilt filler plug	0.5
	■	VO-22861085	REPAIR KIT	1
	■	VO-8394887	OIL TEST KIT	4
	■	VO-82354791	VENTILATION FILTER, V4	1
	■	VO-82348995	VENTILATION FILTER	1
	⚙	VO-8100300	12 Months cab inspection	0.4
<b>2016-07-18 - Mileage: 195111 - Order nr: 8075541</b>				
	*	252	SILENCER AND EXHAUST LINE	
	■	VO-22321908	EXHAUST PIPE	1
<b>2016-03-30 - Mileage: 150316 - Order nr: 8071401</b>				
	*	M	PLEASE FILL IN	
	☒		Mileage: 150316	
	⚙	VO-3970800	Display, replace	0.6
	⚙	LO-3000	Speedo needle jumps around.	1.35
	⚙	VO-3652400	Control unit BBM, replace	0.6
	⚙	LO-5000	BRAKE SYSTEM MALFUNCTION FAULT.	3.3
	■	VO-22148423	DISPLAY	1
	■	VO-22451940	CONTROL UNIT	1
	☒		Hrs: 1898	
	☒		Name: JIM	
	☒		Phone: 0754662818 0417631673	

PC	Type	Code	Description (Original)	#
			Radio screen is black.	
			Body builder fault this has been an issue since new.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		LO-365	Swap BBM from Donor truck	2.2
			No faults found during testing	
			No faults found during testing	
		VO-1709200	Replace control unit, programming	0.1
		VO-1709200	Replace control unit, programming	0.1
<b>2016-01-01 - Mileage: 6 - Order nr: 201846</b>				
		96000		0
<b>2015-12-03 - Mileage: 63095 - Order nr: 8067276</b>				
	*	M	PLEASE FILL IN	
			Mileage:63095	
		VO-8182700	Cab shock absorber air rear, replace (tw	1
		VO-21171976	AIR SPRING - REAR CAB FH(4)	2
			Hrs:1063	
			Name:	
			WAITING FOR THE TRUCK.	
			D/A CAB AIR BAG LEAKING	
<b>2015-12-01 - Mileage: 5 - Order nr: 201846</b>				
		96000		0
<b>2015-11-01 - Mileage: 4 - Order nr: 201846</b>				
		96000		0
<b>2015-10-01 - Mileage: 3 - Order nr: 201846</b>				
		96000		0
<b>2015-09-01 - Mileage: 2 - Order nr: 201846</b>				
		96000		0
<b>2015-08-27 - Mileage: 32085 - Order nr: 8063458</b>				
		VO-8430000	Glass and sealing moulding for windscree	3.4
		LO-170	CHECK ALL FAULT CODES	0.3
	*	845	CHECK BOTH MIRROR OPERATION	
	*	20	Alpha Glass - reseal windscreen	
<b>2015-08-03 - Mileage: 14377 - Order nr: 8062560</b>				
		LO-510	TRUCK BRAKE MALFUNCTION FAULT	1.5
		LO-593	ABS FAULT POSSIBLY FROM THE TRAILER	1.53
			CONNECTION LEADS ACCORDING TO JIM.	

PC	Type	Code	Description (Original)	#
		VO-20779040	SERVICE KIT, OIL F	1
		AU2-CAL85121714	SAE50 205L PUMPOUT	16
		AU2-CAL85121715	GEAR OIL 85W140 BULK	38
		384	BODY MODULAR FAULT.	
		VO-1721000	Warranty service. After 4 weeks or maxim	2
<b>2015-08-01 - Mileage: 1 - Order nr: 201846</b>				
		96000		0
<b>2015-07-30 - Mileage: 75 - Order nr: 8062495</b>				
		70	PAINT TURNTABLE	
<b>2015-07-09 - Mileage: 4321 - Order nr: 8061706</b>				
		LO-820	PAINT T/T BLACK	1
			- GENERAL	
		MTPAINT	PANELSHOP PAINT	
		91	PANELSHOP CONSUMABLES	
			REFER NEW TRUCK FIT UPS	
			ORDER NO;4013700	
<b>2015-07-09 - Mileage: 100 - Order nr: 8061991</b>				
		LO-170	REGISTRATION	3
<b>2015-06-15 - Mileage: 68 - Order nr: 8058623</b>				
		LO-171	PRE DELIVERY WITH PLATES	6.5
		MTELEC186	RIVETS	
		10	VEHICLE DETAIL	
		10	TARE WEIGHT	
		LO-810	FIT AEROFOIL	3
		10	CUSTOM BADGE	
		LO-350	3 X LED LIGHTS TO EACH MIRROR	3.1
		LO-350	3 X LED LIGHTS TO EACH SIDE OF CAB	3
		LO-852	DRIVERS SHEEP SKIN SEAT COVER	0.5
			NOLANS LOGO	
		860	NOLANS PARTS KIT	
			BELTS, RADIATOR HOSES, FILTERS N O AIR	
		LO-843	LEFT & RIGHT WEATHERSHIELDS	1.6
		LO-360	CALIBRATE LOAD SCALES SOFTWARE	1
			IN TRUCK FROM FACTORY	
		LO-350	RELOCATE EXISTING REASR OF CAB WORK	2.1
			LIGHTS TO THE AERO KIT SIDE WINGS	
		LO-610	IMEX FULL STAINLESS STEEL DRESS RING	0.9
			TO STEER AXLE	

PC	Type	Code	Description (Original)	#
		LO-360	PROGRAM 4 MINUTE IDLE SHUT DOWN	1
		LO-360	ENSURE 12 & 24 VOLT PLUTS ARE LED OK	1
		LO-712	S&F JOST JSK37 CZ GREASE TOP 185 FEET	2
			DRILL Ö CENTRE + 50 + 100	
		LO-826	CHANGE REAR PLASTIC GUARDS TO SMOOTH	5
			STAINLESS STEEL WITH ALLOY MOUNT CLAMPS	
		LO-360	CHECK K FACTOR WITH LOADED TEST TRAILER	1
			100KMH	
		LO-250	REPLACE EXHAUST TAIL PIPE	1.5
			SAME AS 200397	
	*	10	WINDOW TINT	
	*	10	POLISH FUEL TANKS	
	*	610	VOLVO POLISHED DURABRITE	
			AND R150 STEER TYRE	
	*	60	R150 TYRE	
	*	20	EXHAUST	
		LO-712	FRONT ALLOY DECK PLATE	3.7
		LO-360	FMS FIT UP	3.1
		VO-22011865	ELBOW	1
		MK-EMEWP02K	W/PACK 2 WAY CONN	2
		VO-3944972	HOUSING	2
		VO-3963046	TERMINAL - MALE	4
		VO-3963410	SEAL, CABLE - GREY	4
		VO-970771	CABLE SEAL	4
		OTH-AMB25B	STICKY PAD	5
		VO-1500600	RUBBER BUSH	2
		VO-21761590	WIRES	1
		OTH-26260CK	LUCIDITY MARKER WHITE STAINLES	6
		VO-25171459	TORX SCREW M4 x 18mm	24
		MK-NARV56406	CABLE TIE 1=100PK	1
		OTH-AMB25B	STICKY PAD	20
		OTH-26260AK	LUCIDITY MARKER AMBER STAINLES	6
		VO-21244697	RELAY	6
		VO-25392050	RELAY RETAINER	6
		VO-949597	SLEEVE LOCKING	30
		VO-979002	TERMINAL FEMALE	30
		VO-970771	CABLE SEAL	4
		VO-949746	P-CLAMP M12	4

PC	Type	Code	Description (Original)	#
		VO-9148085	CABLE TERMINAL	4
		MK-9750-SS11SINCNG	S/STEEL GRD NO RIB	4
		MK-9750-MMABPOL	BRACKET	16
		LO-810	air dryer elbow missing from factory	0.5
		MK-980AX26	TERMINAL, FEMALE V	8
		MTELEC6	4000- Twin Core Cable	
		MTELEC26	4000- 7mm conduit	
		MTELEC210	4000- Blue electrical terminal	
		OTH-VSHEEPNOLANSRH	SHEEPSKIN NOLANS	1
		VO-84165756	WEATHERSHIELD (FH4)	1
		MK-9711-4017RSVVS6S	DRESS DISC H/CAP	1
		VO-20464675	V-RIBBED BELT	1
		VO-22275091	V-RIBBED BELT	1
		VO-22273743	HOSE	1
		VO-21133830	HOSE	1
		VO-FK18B	FILTER KIT	1
		VO-21848341	DRAIN VALVE	1
		AU2-9703-JSK37CZ201TO	.JSK 37 CZ/185 C/W	1
		OTH-NPNC/PLATCH	E3-15-25 LATCH KEYLO	2
		OTH-NPNC/PKEY	E3-5-15 KEY KEYLOCK	2
		OTH-NPNC/PCOVER	90-3 COVER KEYLOCK	2
		VO-20393237	RUBBER MOULDING	2
		OTH-UES32752	ANTILUCE FASTENER 50MM THREAD	2
		OTH-25060	WEAR PLATE ANTI-VIB CLIP S/S	2
		VO-25087755	TORX SCREW M4 x 16mm Silver	12
		VO-990976	LOCK NUT	12
		MK-NARV56600	HEATSHRINK 1=1 150	1
		VO-25392050	RELAY RETAINER	1
		VO-979002	TERMINAL FEMALE	5
		VO-21244697	RELAY	1
		VO-949597	SLEEVE LOCKING	5
		VO-25171459	TORX SCREW M4 x 18mm	12
		MK-NARV56600	HEATSHRINK 1=1 150	1
		VO-82217702	ATTACHMENT KIT	1
		VO-8141219	Grommet, antenna coaxial cable	2
		MK-NARV56650	DUAL WALL HEAT SHR	1
		OTH-AMB25B	STICKY PAD	10

PC	Type	Code	Description (Original)	#
		MK-NARV56306	CABLE TIE 1=25PK	1
		VO-8394442	CLIPS, HUBCAP FIT	12
		AU2-20572280	WHEEL 22.5 X 8.25 DURA BRITE	1
		VO-993723	CABLE TERMINAL	3
		VO-20716730	HOUSING	1
		VO-20716731	HOUSING	1
		VO-995632	HOUSING	1
		VO-21708450	FMS PREPERATION KI	1
		VO-978999	FUSE, BLADE STD 20 AMP	1
		VO-969161	FUSE, BLADE STD 10 AMP	2
		VO-969162	FUSE, BLADE STD 15 AMP	1
		70	PAINT TURN TABLE	
		70	TURNTABLE MOD PLATE	
		VO-85135865	CONVERSION KIT	1
		MTELEC187	WALK PLATE CHECKER PLATE	
			MOUNT Ö 50MM FORWARD OF CENTRE	
			FRONT ALLOY DECKPLATE	
			CHROME NUT COVERS ALL AXLES	
			HUBCAPS TO REAR AXLES	
			ADD RUBER LOOP BETWEEN THE NEW GUARDS	
			NO HAIR REQUIRED	