



Vehicle History Summary



Fleet #	70
Registration	KST46
Make	Kenworth
Model	K104B
VIN / Chassis #	6F50000007A436332
Build Date	2007

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-5144	12/11/2022	424430	0	A - 30 Days		Colin Scott
S-5071	14/10/2022	407582		A - 30 Days		Kelvyn Fuller
S-5040	07/10/2022	403352	0	A - 30 Days		Colin Scott
S-5049	20/09/2022	390883	0	B - 50k		SH&M Fuller Transport Repairs
S-5012	19/09/2022	390883	0	B - 50k		SH&M Fuller Transport Repairs
R-2127	13/09/2022	0	0	MISC	REBUILD CAB MOUNT AND REASSEMBLE, REMOVE HORTON FAN ASSY, REPAIRS TO L/H/ R CAB SAFETY LOCK, FIT NEW R/H WEATHER SHIELD, REWIRE FRIDGE PLUG IN CAB, REMOVE L/H CAB MOUNT	SH&M Fuller Transport Repairs
S-4988	10/09/2022	386724	0	A - 30 Days		Colin Scott
T-1461	07/09/2022	0	0	Balance	2x Balances 2x Strip and flips	Tyreright
S-4983	03/09/2022	382569	0	A - 30 Days	Re kit horton fan hub. Replace horton air switch repair cab safety latch mechanism fir driver side window weather shield finish fitting LHS cab bushes Install new wiring and fit 12v socket to run fridge	Colin Scott
R-2120	24/08/2022	0	0	MISC	REPLACE AIR DRYER, AIR HOSE , FIT HORTON FAN VALVE, ADJUST RIDE HIGH VALVES, ADJUST BRAKE, R & R HOSE & FITTING TO AIR COMPRESSOR, R & R D 2 GOVERNOR VALVE	SH&M Fuller Transport Repairs
S-4961	22/08/2022	376308	0	A - 30 Days		Colin Scott
S-4836	23/07/2022	364466	0	A - 30 Days		Colin Scott

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-2086	27/06/2022	0	0	AIR Leak	REPLACE HORTON SOLENOID SWITCH - (SUPPLIED)	SH&M Fuller Transport Repairs
S-4813	25/06/2022	350746	0	A - 30 Days		Colin Scott
R-2090	09/06/2022	0	0	MISC	R & S SUZI COIL, DOOR LOCKS, MARKER SIGN, MUDFLAPS, AIR FITTING HORTON VALVE, ACCELERATOR PEDAL, STACKS, DIFF HOUSING GASKET, TOOLBOX HANDLES, CLUTCH PEDAL RUBBER, LOCK KITS. REPAIR DIPSTICK RUBBER , ADJUST CLUTCH.	SH
S-4711	23/05/2022	336781	0	B - 50k	R & R FILERTE HOUSING ORING, FRONT SHOCKIE RUBBERS, DRAY LINK, FRONT BOOSTRE DIAGRAM	SH&M Fuller Transport Repairs
S-4717	07/05/2022	329921	0	A - 30 Days		Colin Scott
S-4664	09/04/2022	315866	0	A - 30 Days		Colin Scott
S-4637	18/03/2022	305714	0	A - 30 Days		Colin Scott
S-4598	11/03/2022	302134	0	A - 30 Days		Colin Scott
S-4456	03/02/2022	282978	0	B - 30k	Repair reverse lights FURTHER REPAIRS Front spring bushes/pins Position 3,4,5,6 S Cam / bushes Position 5,6 slack adjusters Diff filter housing leak Air dryer re-kit Leaking pressure protection valve No plate lights - No plate Drag link Cab jack air leak Marker lights Door locks	Colin Scott
S-4440	27/01/2022	278902	0	A - 30 Days		Colin Scott
T-1321	13/01/2022	0	0	NEW & RETREAD	2 NEW 2 STRIP AND FIT 2 BALANCE	Tyreright
I-6	01/01/2022	263891	0	HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS		
S-4211	30/12/2021	263891	0	C - Annual		Colin Scott
T-1346	28/11/2021	0	0	STRIP & FIT	3 STRIP AND FIT	Tyreright
S-4203	25/11/2021	248198	0	A - 30 Days		Colin Scott
R-1998	14/11/2021	0	0	MISC	R & R DASH LIGHT BULBS, FIT INSTRUMENT CLUSTER (SUPPLIED) , SECURE WIRING TO GEARBOX PLUGS AND FIT NEW HARNESS STRAP .	SH&M Fuller
R-2000	12/11/2021	0	0	Windscreen	R & R L/H/S WINDSCREEN	Windscreen For Trucks
T-1342	10/11/2021	0	0	new	8 NEW	

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-2004	08/11/2021	0	0	Misc	CONNECTED LAPTOP AND FIND PROBLEM - TILT CAB OVER AND FOUND DATA LINK PLUG TO THE TECU WAS OUT. CLEANED PLUG AND APPLIED ELECTRICAL GREASE. CHECK AGAIN OK	Brown & Hurley
R-1976	08/11/2021	0	0	Misc	FIND FAULT - TIT CAB OVER AND FOUND THE DATA LINK PLUG TO THE TECU WAS OUT. CONTACT CLEANER -	Brown & Hurley
R-1989	04/11/2021	0	0	Misc	R & R TURNTABLE PEDESTAL BUSHES, BOLTS, PADS - R & R BAROMETRIC PRESSURE SENSOR - R & R DASH BULBS	SH&M Fuller
T-1288	31/10/2021	0	0	STRIP		Tyreright
S-4188	28/10/2021	233327	0	B - 30k		Colin Scott
S-3216	28/08/2021	202823	0	A - 30 Days		Colin Scott
S-4223	07/08/2021	192636	0	A - 30 Days		Colin Scott
R-1508	22/07/2021	184502		MISC	STRIP DOWN FRONT AXLE REMOVE AND REPLACE KING PIN KIT. CARRY OUT BRAKE RELINE ON FRONT AXLE AND R & R BRAKE DRUMS. FIT MIRROR LAMPS MAKE AND SUPPLY DRIVING LAMP BRACKET	SH&M Fuller
S-4137	10/07/2021	181144	0	B - 30k		Colin Scott
S-4136	10/07/2021	181144	0	A - 30 Days		Colin Scott
T-1246	07/07/2021			STIP & FIT		Tyreright
S-4153	19/06/2021	171123	0	A - 30 Days		Kelvyn Fuller
T-1218	31/05/2021			Pressure Test		TYRE EVOLUTION
S-3940	30/05/2021	160904	0	A - 30 Days		Kelvyn Fuller
R-1321	27/05/2021	998775		Brake	R & R POSITION 4 HUB SEA AND BRAKES SOME PARTS SUPPLIED	SH&M Fuller
T-1200	15/05/2021			STRIP		TYRE EVOLUTION
T-1199	15/05/2021			Rotate		TYRE EVOLUTION
R-1318	13/05/2021			Gearbox	TRAVEL TO VEHICLE BRAKEDOWN ISOLATE GEARBOX PROBLEM REMOVER XY SHIFTER FOUND END BROKEN OFF SELECTOR. FIT 2 ND HAND XY SHIFTER AND TEST.	SH&M Fuller
T-1176	27/04/2021			STRIP		TYRE EVOLUTION
T-1175	27/04/2021			Rotate		TYRE EVOLUTION

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-3606	23/04/2021	143381	0	A - 30 Days		Colin Scott
R-1287	22/03/2021			Windscreen	R & R WINDSCREEN	Windscreen For Trucks
S-3645	19/03/2021	125761	0	A - 30 Days		Colin Scott
S-3646	18/03/2021	125761	0	B - 30k		Colin Scott
T-1125	06/03/2021			Pressure Test		TYRE EVOLUTION
R-1238	20/01/2021	94332		MISC	CHECK WIRING ON ENGINE FOR OIL PRESSURE SENDER (OK) R & R TEE JOINER BEHIND SEAT	SH&M Fuller
T-1035	04/01/2021			New		TYRE EVOLUTION
S-3099	01/01/2021	88767	0	A - 30 Days		Colin Scott
S-3186	19/12/2020	83592		A - 30 Days		Kelvyn Fuller
R-1213	16/12/2020	80150		Body	REPAIR L/H CAB SHOCKIE BOLT PIVOT FIT BOLT BACK INTO PLACE	SH&M Fuller
S-3203	12/12/2020	80155		A - 30 Days		Kelvyn Fuller
R-1207	08/12/2020	75505		MISC	REPAIRS TO STEERING WHEEL AND SEAT AND DRIVER SIDE FRONT CAB SHOCK ABSORBERS	SH&M Fuller

Signed: _____

Name: _____

Date: _____