

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	06.10.2023	797077	Impact Diesel	Refit steps. LAB - Labour. Refit steps to LHS and RHS tanks. Replace mudflaps on rear. LAB - Labour. Removed old mudflaps. Had to cut bolts on LHS as bolts bent. Fit new mudflaps with new bolts and washers.	n/a
	04.09.2023	797077	Impact Diesel	Truck stuck in gear. LAB - Labour. Plumbed up airline to truck. Had to switch between air tanks to build gearbox pressure. After 15 mins eventually had enough pressure to come out of reverse. Truck will need to be jump started as battery flat.	n/a
	11.08.2023	793021	Impact Diesel	Check noise in engine bay. LAB-Labour. Inspection found pulley/bearing noise. Found numerous pullies worn. Check stock, travelled to Mack to get parts. Removed fan belt, fan belt tensioner, fan belt idler. replace idler and tensioner refit fanbelt. Removed alternator belt and got new as worn. Removed and replaced alternator tensioner. Fit new alternator belt. Inspected noise still present. Most likely in fan clutch. Told by Mick to leave until new truck truck comes.	Parts used: Alt belt 8pk1600hd Alt tensioner 89477 Fan tensioner Apv2739 STC Fan Idler
	04.08.2023	7911085	Impact Diesel	L/H head light blown. LAB - Labour	n/a
	08.08.2023	789393	Impact Diesel	Clean diff and inspect oil levels. LAB - Labour. Refilled both with approx. 5 litres. Transmax 85w-140w. Tighten loose guard ports. LAB - Labour. 1st drive rear port loose. 2nd drive rear port loose. Removed guards to gain access to bolt as too tight to do with a ratchet. Tightened up with rattle gun. Refit guards.	n/a
	19.07.2023	784386	Impact Diesel	Remove and repair R/H head light	n/a
	07.07.2023	779869	Impact Diesel	Breakdown at Kembla Grange.LAB - Labour. Travel to site, inspect tailgate not opening. Unable to test as on the side of road. Wait for loader to take truck in. use manual over ride and opened gate. Found one terminal off pressure switch. Reconnected tested OK	n/a
	07.07.2023	n/a	Impact Diesel	A service trailer Reline 2nd and 3rd axle Adjust bearings on 3rd axle Replace broken shock 1st axle Rectify tarp issue	Parts used: stock 4 x brake shoes 4 x brake drum Truckline ID309 1 x shock
	07.07.2023	778189	Impact Diesel	A service as required. Rectify light inop. Fit missing reflectors Replace RHS wiper. Ride height valve rod	n/a
	29/06/2023	N.A	Impact Diesel	Supply 2x H7 globes for Mick to replace	H7 globe
	23.06.23	N.A	Impact Diesel	Supply hydraulic fittings Hydraulic fittings male / female	
	15.06.23	N.A	Impact Diesel	Rectify crossmember cracked: Weld up as required through sublet repair	
	14.06.23	N/A	Impact Diesel	Breakdown - Tail gate won't open Packed up vehicle and travelled to Theresa park. Check air supply - OK. Checked gates. Found to be stuck closed. With 2 people managed to hot gates while using belt and tail gate switch. Got all product off. Cleaned hinges out with kerosine to get rid of the mix and rocks. Tested several times and travelled back to workshop.	

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	14/06/2023	767,203	Impact Diesel	Replace hydraulic fitting Removed and replaced L/H headlight globe H7 Checked both diff oil levels Engaged PTO and ran conveyor to test	Parts used - stock Male hydraulic fitting Female hydraulic fitting Diff oils
	8.06.23	n/a	Truckline		H11 LED CONVERSION KIT 12/24V
	7/06/2023	767 203 kms	APEX Auto Electrical	Check blower fan Test and check blower fan on vehicle. Find blower fan not operational. Dismantle vehicle. Test and check fan. Find fan faulty. Remove. Supply and fit new to suit vehicle. Reassemble vehicle Test and check operation. find ok	OEM blower fan - \$500 Consumables - \$10
	26.05.2023	n/a	Impact Diesel	A service on trailer	n/a
	05.04.2023	n/a	Impact Diesel	A service on trailer	n/a
	05.04.2023	744165	Impact Diesel	A service check D/S head light out	n/a
	04.04.2023	n/a	Resolution Tyres	Fitted run out tyres	n/a
	15.02.2023	n/a	Impact Diesel	A service on trailer	n/a
	15.02.2023	725848	Impact Diesel	A service . replaced roof light not working replaced fitting for air guage on trailer	n/a
	16.01.2023	n/a	Impact Diesel	C service on trailer found and re-tentioned loose wheel bearings x4	n/a
	16.01.2023	715741	Impact Diesel	C service ordered new part and replaced bonnet strap	n/a
	13.01.2023	n/a	truckline	n/a	AIR FILTER
	13.01.2023	n/a	Southern truck centre	n/a	TEMPERATURE SENSOR
	12.01.2023	n/a	Southern truck centre	n/a	Kit
	11.01.2023	n/a	Southern truck centre	n/a	Latch
	04.01.2023	n/a	Truckline	n/a	LINK END T
2023					
	23.12.22	N/A	Impact Diesel Group	Trailer A service. replace worn trailer rubbers for tailgate and live floor replace marker plates	N/A

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	23.12.22	713411	Impact Diesel Group	A service. replace damaged rear guards. checl lights, front parker not working replace driver side window wiper	N/A
	20/12/2022	N/A	truckline	MUDGUARD PLASTIC BLACK 650MM WIDE MG650.B	N/A
	29/11/2022	N/A	Southern truck centre	AC02E VO 25173616 AIR SPRING ASSY 033E04 VO 990952 FLANGE LOCK NUT	N/A
	29/11/2022	N/A	Southern truck centre	RK06A VO 85022395 EXCH CLUTCH KIT Surcharge No. 2008809 Serial No. . 250.00 BZ01C VO 22327069 SOLENOID VALVE AI02E VO 23417527 CYLINDER 028H08 VO 21666546 DISC AHE01 VO 20497205 GASKET	N/A
	24/11/2022	N/A	Southern truck centre	BV01B VO 82710488 WIPER BLADE BASIC 35.43 1-09 2.0	N/A
	26/11/2022	N/A	JW Fairall towing service	After hour tow front end lift and tow from bass point to depot unanderra remove tail shaft, supply air, lights, release brakes, oversize signs/ flags.	N/A
	25.11.22	N/A	Impact Diesel Group	A trailer service	N/A
	25.11.22	709711	Impact Diesel Group	A service	N/A
	17/11/2022	704290	APEX Auto Electrical	Check UHF Test and check UHF operation. Find UHF operational, but range limited. Test and check circuits. Find aerial missing and base threads damaged. Dismantle vehicle as necessary. Remove existing assembly and cable. Supply and fit new to suit vehicle. Route through mirror. door and	UHF aerial assembly - \$120 Consumables - \$10
	17/11/2022	N/A	Impact Diesel Group	live bottom not turning like normal cleaned belts and surrounds adjusted chains and belts found roll bar at back has flat spot from build up (stopping it from turning) requires new bar cleaned thoroughly and achieved normal operation	sundires

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	14/11/2022	702887	Impact Diesel Group	replace fuel tank steps loosened tank straps one at a time replaced step brakcet on rear sent bracket away to get repaired as they only had one in stock received back fit up and tested. okay	Brakcket repair \$85.25 sundires Parts ordered from STC on acc: PO number: ID83 x2 fuel tank straps x4 step brackets
	24/10/2022	695535	Impact Diesel Group	A service as per checklist	N/A
	25/10/2022	N/A	Impact Diesel Group	A service as per checklist	N/A
	25/10/2022	695536	Impact Diesel Group	replace wiper blades cabine air blower leaking -removed and trimmed air hose -refit to blower -tested ok	N/A
	21/10/2022	N/A	APEX Auto Electrical	Check trailer operation Test and check trailer belt operation. Find belt not operational from cab controls. Test and check circuits. Find no trigger from cab to trailer. Dismantle vehicle as necessary to trace and inspect. Trace fault to open circuit. Repair as necessary. Reassemble vehicle <u>Test and check operation, find ok.</u>	Consumables (cable ties, solder, tape, heat shrink, terminals, brake clean, rags, bolts, hand cleaner ETC) - \$10
	14/10//2022	N/A	drew/Brad	Fuel cap missing ordered cap from STC retrieved fuel cap fitted new fuel cap - part changed from STC to <u>Tar stuck on tarp runners</u>	sundires
	: 11/10/2022	N/A	Impact Diesel Group	Rectify vehicle PTO not working and making a grinding noise: LAB - Labour Drained gearbox oil. Removed and diagnosed PTO. Found collapsed bearing.	Gaskets Sundries
	6/10/2022	N/A	truckline	PTO - 145 VOLVO ISHIFT MOUNT KIT 1211B 145A08,139A23 PTO. VO	N/A
	5/10/2022	N/A	Southern truck centre	N/A	COVER

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	4/10/2022	N/A	resolution drive	ZFITBRCJUS FIT CUSTOMERS OWN TRUCK TYRE QTY:1 P:\$65.00 ZSCRAPTYRETBR SCRAP TYRES TRUCK QTY:1 P:\$24.50	N/A
	30/09/2022	N/A	HS company	N/A	N/A
	29/09/2022	N/A	Truckline	N/A	END YOKE 1810 2.016" X 39 SPLINE KIT NUT & WASHER BEARING CAP RETAINER SPL250 SERIES
	28/09/22	N/A	Southern truck centre	BS01A VO 25101923 SHAFT BH01F VO 25503149 RETAINER BF06B VO 25096437 BALL BEARING BG01C VO 25096459 COVER BE02B VO 23396652 OIL SEAL RING FILE-O VO 25502424 GASKET	N/A
	21/09/2022	N/A	brad/drew	removed and replace flat trailer tyre	N/A
	21/09/2022	N/A	brad/drew	completed A service as per checklist	sundries
	21/09/2022	686368	brad/drew	completed B service as per service	sundries
	september	N/A	Southern truck centre	N/A	Air filter cleaner
	10/08/2022	679329	Brad/drew	A service as required tightened all heater clamps removed second axle inner tyre and fit run out as it was bald	sundries

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	3/08/2022	N/A	brad/drew	A service as per check list	Sundries
	3/08/2022	N/A	BRAD/drew	retension all drive u bolts and repair thread on LHS second drive tightened loose guard posts on all drive replace worn air bag RHS thrid axle replaced all drive shocks	N/A
	2/08/2022	N/A	Multispares	N/A	57Y3029-OE SHOCK ABSORBER HENDRICKSON MACK HAS 57Y2220 AIRBAG ASSY
	1/08/2022	N/A	Multispares	N/A	57Y3013-OE SHOCK ABSORBER - HEND HITORQUE 19MM EYES
	29/06/2022	N/A	BRAD/drew	comptled trailer A service as per checklist tensioned LH 3rd axle guard post	SUNDRIES
	22/06/2022	664246	BRAD/drew	removed amd replaced flat tyre 3rd axle LH outer tyre flat replaced with tyre in workshop as requested	N/A
	9/06/2022	663720	drew/Brad	removed and replaced diverter vlave (diverter valve 23626042) removed and replaced leaking HP line safety valve (removed and cleaned HP line) part - safety valve	safety valve
	3/06/2022	N/A	drew/Brad	Inspect,diagnose and repair tarp issue. Travelled to workshop, found tarp running damaged by loader, removed and repaired as required, refit and modified in order to open, replacement required	N/A
	11/05/2022	656180	Brad	completed A service as per checklist removed and replaced faulty muffler as required removed and replaced front D/S parker as necessary completed trailer service as per checklist	Supplied by muffler D/S parker

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	13/04/2022	N/A	Brad	complete trailer service as per schedule and fit 1x red reflector as necessary	1 sundries
	13/04/2022	645755	Brad	A +B Service, Reline both drive axles and drums as necessary, tightened all loose guards as required	Supplied by *- x3 mack oil filters *- Adblue 23381558 x1, 22406383 x1 *- Engine oil x36L *-Red reflector *-x4 boxes brakes 4707
	21/02/2022	11026	Matthew Holt	REPLACE TYRE & BALANCE CARRY OUT PUNCTURE REPAIR.	REPLACEMENT TYRE REPLACEMENT ROYAL BLACK 11R22.5 DRIVE TYRE HAULMAX ATT307 11R22.5 DRIVE TYRE ROYAL BLACK 11R22.5 TRAILER TYRE CARRY OUT PUNCTURE REPAIR.
	12/02/2022	N/A	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. CARRY OUT TRAILER SERVICE.	SHELL GADUS S3 V220C 2 GREASE BELT CONDITIONER SHELL GADUS S3 V220C 2 GREASE WORKSHOP CONSUMABLES ENVIRONMENTAL LEVY
2022					
	13/12/2021	621756	Matthew Holt	RECTIFY 2ND AXLE DIFF OIL LEAK. - REPLACE 4x DRIVE TYRES ON 2ND AXLE.	SHELL SPIRAX S2 A 85W140 AXLE OIL USED TYRES WORKSHOP CONSUMABLES ENVIRONMENTAL LEVY
	30/11/2021	620393	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. CARRY OUT TRAILER SERVICE.	SHELL GADUS S3 V220C 2 GREASE BLEETGUARD AIR FILTER BELT CONDITIONER SHELL GADUS S3 V220C 2 GREASE WORKSHOP CONSUMABLES
	8/11/2021	616518	Matthew Holt	REPLACE STEERING WHEEL. - REPAIR RUBBER ON TAILGATE.	STEERING WHEEL WORKSHOP CONSUMABLES
	18/10/2021	613457	Matthew Holt	BREAKDOWN CALL FOR NO DRIVE. - TRAVEL TO SITE & FOUND FRONT DIFF PINION SNAPPED & TAIL SHAFT ON THE GROUND. - SECURED TAIL SHAFT & TOWED BACK TO WORKSHOP. - REMOVED DIFF & SENT TO TRUCK TRANS FOR REPAIRS. - RECIEVED DIFF BACK & REFITTED, FITTED NEW AXLE GASKETS & SIDE COVER. - REFILLED WITH OIL & TEST DROVE, WORKING AS NORMAL NOW.	650MM MUD GUARD BLACK DRIVE AXLE GASKET 8 STUD SHELL SPIRAX S2 A 85W140 AXLE OIL REBUILD CRD150 MACK DIFF INV NO 164992 NUTS BOLTS & WASHERS FOR TURN TABLE
	5/10/2021	605431	Matthew Holt	REGO INSPECTION - TRAILER - YN18NW	

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	29/09/2021	609652	Matthew Holt	CARRY OUT TRAILER SERVICE. - CONDITION BELT. . CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. - REPAIR ABS FAULT , ADJUST RH 3RD AXLE SENSOR & TEST, WORING AS NORMAL	SHELL GADUS S3 V220C 2 GREASE SHELL GADUS S3 V220C 2 GREASE BELT CONDITIONER WORKSHOP CONSUMABLES
	14/09/2021	605431	Matthew Holt	CHECK OPERATION OF THE UHF, SEEMS TO BE WORKING AS NORMAL ALTHOUGH ITS QUIET AT TIMES. - AERIAL CONNECTIONS ARE FINE BUT THE WHIP WAS A BIT LOOSE. - REPLACE HAND PIECE WITH GOOD 2ND HAND UNIT & CHECKED AGAIN. - TESTED AND SEEMS TO BE WORKING AS NORMAL	HAND PIECE 2ND HAND. WORKSHOP CONSUMABLES
	7/09/2021	603461	Matthew Holt	REPLACE LH REAR AXLE AIR BAG ASSY.	AIR BAG ASSY MACK
	31/08/2021	602486	Matthew Holt	BREAK DOWN CALL TO ST PETERS FOR DRIVE LINE NOISE. - FOUND REAR DIFF MAKING NOISE INTERNALLY. - REMOVED TOP COVER & FOUND DAMAGE TO CROWN WHEEL & PINION. - SENT TO TRUCK TRANS FOR REPAIRS. - REPLACED WHEEL BEARINGS & SEALS. - REFITTED DIFF CENTER.	WHEEL BEARING SET401 WHEEL BEARING SET403 SKF DRIVE HUB SEALO SHELL SPIRAX S2 A 85W140 AXLE OIL REBUILD REAR DIFFERENTIAL. REBUILD REAR DIFFERENTIAL - PAID BY
	26/08/2021	602486	Matthew Holt	CARRY OUT C SERVICE AS PER NHVR MAINTENANCE MANUAL. - CHANGE CAB STABILIZER BUSHES & TUBES. - CHANGE DIP STICK TUBE. CARRY OUT TRAILER SERVICE. - ADJUST CHAIN & BELT. - CHANGE GEARBOX OIL.	SHELL RIMULA R4 15W40 CK4 ENGINE OIL SHELL SPIRAX S6 GXME 75W80 GEAR OIL SHELL SPIRAX S2 A 85W140 AXLE OIL HI-TEC DD50 GREEN PREMIX COOLANT HI-TEC ATF MULTI TRANS FULL SYN SHELL GADUS S3 V220C 2 GREASE
	9/08/2021	595981	Matthew Holt	BREAKDOWN CALLOUT FOR TRAILER CONTROLS INOP. - TRAVEL TO BERRIMA, CHECKED & FOUND NO AIR SUPPLY. - REMOVED SUPPLY LINE FROM PP VALVE & FOUND PP VALVE BLOCKED. - RAN A TEMPOARY LINE FROM PTO SUPPLY TO TRAILER CONTROL TO UNLOAD. - TRAVEL BACK TO WORKSHOP & FIT NEW PP VALVE. - CHECKED OPERATION & WORKING AS NORMAL.	CALL OUT KM PRESSURE PROTECTION VALVE 65PSI 1/4" WORKSHOP CONSUMABLES
	5/08/2021	595482	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. - REPLACE 3RD AXLE RH AIR BAG. - REPLACE 2ND AXLE TORQUE ROD. - REPLACE 3RD AXLE HUB SEALS & CLEAN BEARINGS. - WASH DOWN 3RD AXLE BRAKES DUE TO CONTAMINATION. - REPLACE PCV BREATHER HOUSING GASKET.	SHELL GADUS S3 V220C 2 GREASE TORQUE ROD MACK/VOLVO AIR BAG ASSY MACK PCV BREATHER GASKET MACK HUB SEAL DRIVE MUD FLAP
	20/07/2021	590482	Matthew Holt	CARRY OUT REPAIRS FOR REGO INSPECTION. - REPLACE PARKING LIGHT GLOBES x6. - REPLACE INDICATOR GLOBE x1. - REPAIR WIRING FOR REVERSE LIGHT & SQUAWKER. - REPAIR EXHAUST SYSTEM. - REMOVE & SEND RADIATOR FOR REPAIRS.	Wedge Globe 12v 5w T10 BAYONET GLOBE 12V 21W BA15S DEFECT CLEARANCE - HVN0594502 REGO INSPECTION - CA2021875 ADAPTOR 1/2 NPSF-1/4 NPT ADAPTOR - NON SEALING 1/2" MALE
	2/07/2021	584612	Matthew Holt	02/07/21 Break down call to Hume Hwy Narellan. Check for fault codes, found Ad blue faults in the system Reset ECU and clear codes. Check vehicle operation. Everything working as normal.	CALL OUT KM FILTER - AD BLUE IN TANK AD BLUE FILTER KIT MACK SCREEN FILTER - FILTER NECK WORKSHOP CONSUMABLES

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	26/06/2021	582035	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. CARRY OUT TRAILER SERVICE. REPLACE TYRE & BALANCE	SHELL GADUS S3 V220C 2 GREASE WHEEL NUT INDICATOR ECCO BACK UP ALARM 12/24V 97DB BELT CONDITIONER WORKSHOP CONSUMABLES mICHELIN MULTI Z 295/80R22.5 STEER TYRE
	22/05/2021	570785	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. - REPAIR PARK BRAKE ALARM. - REPLACE AIR FILTER. CARRY OUT TRAILER SERVICE. - CONDRIION BELT. - ADJUST CHAIN & BELT.	SHELL GADUS S3 V220C 2 GREASE AIR FILTER BELT CONDITIONER SHELL GADUS S3 V220C 2 GREASE WORKSHOP CONSUMABLES
	20/04/2021	560228	Matthew Holt	CARRY OUT B SERVICE AS PER NHVR MAINTENANCE MANUAL. CARRY OUT TRAILER SERVICE.	DONALDSON FILTER KIT MACK SHELL RIMULA R4 15W40 CK4 ENGINE OIL SHELL GADUS S3 V220C 2 GREASE SHELL GADUS S3 V220C 2 GREASE WORKSHOP CONSUMABLES WASTE CHARGE
	18/03/2021	552768	Matthew Holt	REMOVE STEERING WHEEL & STEERING COLUMN TO CENTER STEERING WHEEL. - REFIT SEAT COVER	
	17/03/2021	551796	Matthew Holt	CLEANED OUT HEATER CORE & A/C EVAPORATOR, REPLACED CABIN FILTER & BLEW OUT ALL A/C VENTS. - CHECKED OPERATION & SEEMS TO BE WORKING WELL.	MACK CABIN FILTER WORKSHOP CONSUMABLES
	11/03/2021	551115	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. - ROTATE STEER TYRES. - REPLACE HEAD LIGHT GLOBES. - PRESSURE TEST COOLING SYSTEM, TIGHTEN HOSE CLAMPS & TOP UP COOLANT. CARRY OUT TRAILER SERVICE. - CONDITION BELT.	SHELL GADUS S3 V220C 2 GREASE H7 12V 55W GLOBE GREEN PREMIXED COOLANT BELT CONDITIONER SHELL GADUS S3 V220C 2 GREASE WORKSHOP CONSUMABLES
	22/02/2021	539834	Matthew Holt	REPLACE A PUNCTURED TYRE ON TRAILER & REFIT TYRE TO TRUCK AFTER PUNCTURE REPAIR	USED TYRES
	9/02/2021	539834	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. CARRY OUT TRAILER SERVICE. - ADJUST BELT & CHAIN TENSION. - CLEANED & CONDITIONED BELT.	SHELL GADUS S3 V220C 2 GREASE SHELL GADUS S3 V220C 2 GREASE BELT CONDITIONER WORKSHOP CONSUMABLES WASTE CHARGE

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	16/12/2020	525852	Matthew Holt	CARRY OUT B SERVICE AS PER NHVR MAINTENANCE MANUAL. - CHANGE ENGINE OIL & OIL FILTERS. - CHANGE FUEL FILTERS. - REPLACE ALTERNATOR BELT TENSIONER. - REPLACE WASTE GATE ACTUATOR HOSE & CLAMPS. CARRY OUT TRAILER SERVICE.	DONALDSON FILTER KIT MACK SHELL RIMULA R4 15W40 CK4 ENGINE OIL SHELL GADUS S3 V220C 2 GREASE 1/4 PUSH ON HOSE HOSE CLAMP BELT TENSIONER ALT MP8
	26/11/2020	517324	Matthew Holt	CALL OUT FOR DOOR NOT CLOSING, FOUND LATCH MECHANISM BROKEN, REPLACED & CHECKED, M WORKING AS NORMAL NOW.	RH DOOR LATCH MACK
	3/11/2020	510903	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. CARRY OUT TRAILER SERVICE.	SHELL GADUS S3 V220C 2 GREASE AIR FILTER SHELL GADUS S3 V220C 2 GREASE BELT CONDITIONER
	4/09/2020	501568	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. - REPLACED DRIVERS DOOR HINGES & ADJUST. - ADJUST CAB SUSPENSION TO RECTIFY KNOCKING. - ADJUST BONNET MOUNTS & STOPPERS TO STOP KNOCKING. CARRY OUT TRAILER SERVICE. - REPAIR BLINKER WIRING ON LH SIDE OF TRAILER.	SHELL GADUS S3 V220C 2 GREASE USED TYRES
	10/08/2020	494362	Matthew Holt	FITTED 3x RUNOUT TYRES, MIDDLE AXLE TYRES ARE ALL OLD STEERS AND ARE LOW ON TREAD BUT STILL ROADWORTHY, RECOMEND REPLACING IN THE NEAR FUTURE, DRIVER IS MONITORING.	USED TYRES, 2 RE GROVE, 1 STEER RUNOUT.
	1/08/2020	490708	Matthew Holt	MOVE TRAILER BACK ON TRUCK TO GET CORRECT WEIGHTS AND MAKE TRUCK BETTER TO DRIVE.	
	28/07/2020	490708	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL. - RE TENSION 2ND AXLE WHEEL NUTS CARRY OUT TRAILER SERVICE	SHELL GADUS S3 V220C 2 GREASE
	1/07/2020	483044	Matthew Holt	CHECK TRAILER SUSPENSION AND FOUND RH 3RD AXLE AIRBAG BROKEN, DIDN'T HAVE A 20901 IN STOCK BUT FITTING A 21800 TO GET IT ON THE ROAD AGAIN.	HENDRICKSON AIR BAG
	11/06/2020	479924	Matthew Holt	CARRY OUT C SERVICE AS PER NHVR MAINTENANCE MANUAL. CARRY OUT TRAILER SERVICE REPLACE TAIL LIGHTS AND NUMBER PLATE LIGHT ON TRUCK, REPAIR WIRING	SHELL RIMULA R4 15W40 CK4 SHELL SPIRAX S2 A 85W140 SHELL SPIRAX S6 GXME 75W 80 SHELL SPIRAX S3 ATF MD3 SHELL GADUS S3 V220C 2 DONALDSON FILTER KIT MACK

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	29/05/2020	477149	Matthew Holt	ADJUST RIDE HEIGHT VALVE AS THE BRACKET HAD COME LOOSE. - REPLACE PARKING LIGHT GLOBES ON RH SIDE OF TRUCK. - ADJUST GUARD BRACKETS AND TIGHTEN AS THEY WERE LOOSE AND MOVING ON POST.	Bayonet Globe 12v 5w BA15s
	21/03/2023	N/A	Truckline	N/A	VALVE - PRESSURE PROTECTION WM778
	21/03/2023	N/A	Southern truck centre	N/A	Globe 1-1 H7
	2/06/2020	477149	Matthew Holt	REPAIR AIR LEAK AT REAR OF CHASSIS, DIFF LOCK AIR FITTING HAD FAILED LETTING THE HOSE BLOW OUT, CUT BACK ALL AIR LINES AND FITTED NEW FITTING, WORKING AS NORMAL NOW.	1/4 AIR LINE TEE
	13/05/2020	471465	Matthew Holt	CHECK FOR AIR LEAK, FOUND LH 1ST AXLE AIR BAG LEAKING, REPLACED AND TESTED, ALL WORKING AS NORMAL NOW.	HENDRICKSON AIR BAG
	6/05/2020	469876	Matthew Holt	CARRY OUT A SERVICE AS PER NHVR MAINTENANCE MANUAL CARRIED OUT PRE REGO INSPECTION, REPLACED FOLLOWING PARTS - 4X REAR SHOCKS ON TRUCK - DRIVE BELTS ON TRUCK - AIR HOSE ON STEER BRAKES ON TRUCK - 2X SHOCKS ON 1ST AXLE ON TRAILER	MULTI GREASE KONI SHOCK ABSORBER REAR SHOCK ABSORBER MACK REAR MARKER STICKER - PLAIN R/H OR L/H DO NOT OVERTAKE STICKER 400 X 400MM LED RR DIRECTION LAMP-CLEAR-ROUND-
	27/03/2020	457817	Matthew Holt	Check Lights, Reflectors & Wipers. Check & Top up Fluids. Check Drive Belts. Check Air & Cab Filters. Check & Adjust Brakes. Check Chassis & Suspension For Wear. Grease Truck & Trailer. Check For Fluid Leaks. Drain Air Tanks. Check Hoist & Body Bolts. Inspect Tyres. Inspect Ringfeeder & Turntable. Inspect Safety Devices. Inspect Seats & Seat Belts. Inspect Tarp System. Change Engine Oil. Change Fuel Filters. Change Oil Filters. Check Driveline Oils. Repair Air lines for front braking system	Oil & Fuel Filter Kit Air Filter Engine Oil Grease Green Coolant Premix
	04.03.20	N/A	Matthew Holt	DOWN ON PAPER AND SURGING. WENT FOR TEST DRIVE AND BRANG BACK TO WORKSHOP. CHECKED AIR FILTER AND CLEANED. REPLACED FUEL FILTERS AS THE TANKS WERE RUN LOW AND SUSPECTED BAD FUEL PICK UP AT BOTTOM OF TANK. DROVE WELL AFTER REPAIRS. TEST OK.	FUEL FILTER WATER SEPERATOR
	16.03.20	N/A	Matthew Holt	CHECKED LIGHT SAND FOUND CONTACTS IN REAR LIGHTS CORRODED. REPLACED LIGHTS WITH THE ONES OFF THE WRECK. REPLACED X2 5W GLOBES. FOUND HEAD LIGHT GLOBE BLOWN AND REPLACED. TOPPED UP 2.5L OF COOLANT. REPAIR REQUEST #0325.	TAIL LIGHT ASSY 12V SW GLOBES H7 GLOBE COOLANT

SERVICE TYPE	SERVICE DATE	ODO	MECHANIC/ COMPANY	SERVICE DESCRIPTION	PARTS SUPPLIED
	18.02.20	449000	Matthew Holt	BREAKDOWN CALL FOR NOISE IN DRIVE LINE. ON INSPECTION FOUND BEARING INFRONT OF DIFF COLLAPSED. TOWED TO YARD. DRAINED OIL AND REMOVED SIDE COVER. FOUND PINION DAMAGED. REMOVER POWER DIVIDER AND FOUND PINION NUT LOOSE. REMOVED COMPLETE DIFF FROM TRUCK AS IT WAS LOADED AND SENT TO TRUCK TRANSMISSIONS FOR REPAIRS. PICKED UP NEXT DAY REFITTED HOUSING. WASHED ALL PARTS. REPLACED AXLE GASKETS AND FILLED WITH OIL. REFITTED COMPLETE UNIT TO TRUCK AND TEST DROVE WITH WARREN ALLEN.	AXLE GASKETS AXLE GASKETS DIFF REBUILD GEAR OIL GREASE CONSUMABLES
	14.02.20	447484	Matthew Holt	TURBO BOOST PROBLEM. REMOVED ENGINE BRAKE AIR VALVE. CLEANED OUT AND REPLACED O-RINGS. WARREN ALLEN TEST DROVE AND FOUND PROBLEM TO BE RECTIFIED. REPAIR REQUEST #0323	CONSUMABLES
	15.01.20	441237	Matthew Holt	CARRY OUT A SERVICE. CHECK OVER. GREASE AND ADJUST BRAKES. REFIT LH MUD FLAP ON TRAILER. REPLACE BRAKE. PARKER AND REVERSE LIGHT GLOBES ON TRUCK. REPLACED CLEARANCE LIGHT ON LH SIDE TRAILER. REPLACED REFLECTORS ON REAR OF TRAILER. WASHED DOWN OIL LEAK ON 2ND AXLE. REPLACED WASTE GATE HOSE ON TURBO AS IT WAS SPLIT.	CLEARANCE LIGHT RED REFLECTOR STOP/TAIL GLOBES REVERSE LIGHT GLOBES GREASE
2020					