

**Tax Invoice**

**Issue Date:** 1/04/2021  
**Due Date:** 31/05/2021

**Tax Invoice No.:**  
**Customer No.:** 2020957  
**Sales Order:** 5006372639  
**Sales Order Date:** 2/03/2021  
**Customer Requisition:**  
**Customer Reference:**  
**Sales Person:**  
**Payment Terms:** 30 days after month end

**Ship To:**

Mode Of Delivery	Make	Model	Serial No.	Customer Equipment No.			SMU	
Collect - Same Day							0.00	
Quantity	Unit	Part Number	Item Name	Unit Price	GST	Ext. Unit Price	Disc. Perc	Disc. Amt
2.00	PC	4992979	Segment	815.88	10%	1,387.00	15.00	0.00
Picking Journal: 3437852660,								
6.00	PC	4992980	Segment	979.34	10%	4,994.64	15.00	0.00
Picking Journal: 3437852660,								
64.00	PC	3S1356	Nut	6.64	10%	424.96	0.00	0.00
Picking Journal: 3437852660,								
64.00	PC	7T1243	Bolt	10.56	10%	574.72	15.00	0.00
Picking Journal: 3437852660,								
2.00	PC	5723289	Track Ar-Slv	38,939.16	10%	66,196.58	15.00	0.00
Picking Journal: 3437852660,								

Waiting on oredr number.

**Invoice Summary**

<b>Total excluding GST &amp; Duties</b>	<b>73,577.90</b>
Total Charges	0.00
<b>Sub Total</b>	<b>73,577.90</b>
GST 10%	7,357.79
<b>Total including GST &amp; Duties</b>	<b>AUD 80,935.69</b>



Pay this Amount:

AUD 80,935.69

Due Date: 31/05/2021

Terms:


30 days after month end

Please specify Customer No. on payment advice:

2020957

Additional Terms:

1. For credit account transactions, all payments for Goods and Services are due 30 days from the date of invoice and the supplier's Credit Terms apply – you can request a copy of the Credit Terms or they are available online at [www.hastingsdeering.com.au](http://www.hastingsdeering.com.au).
2. For cash sale transactions, all payments for Goods and Services are due and payable immediately upon delivery.
3. Sales Terms for Service Customers and Terms and Conditions for the Supply of Equipment and Engineering Services apply - you can request a copy of these terms or they are available online at [www.hastingsdeering.com.au](http://www.hastingsdeering.com.au).



# P 706 Caterpillar D11R

Last Service Tech Name Last Service Hrs Last Service Cost

Service Notes

Next Service Notes

28-Nov-22	Jesse		\$400.00	Remove blade and push arms for transport
27-Nov-22	Shane		\$240.00	Check over machine. Start & check, ok
27-Nov-22	Jesse		\$100.00	Install cover guards
				Reseal sump
26-Nov-22	Shane		\$960.00	Refit sump and fill with oil
26-Nov-22	Jesse		\$200.00	Help fitters
26-Nov-22	Craig	44465	\$550.00	Carried out engine repairs to machine
25-Nov-22	Shane		\$720.00	Continue with engine repairs
22-Nov-22	Oliver		\$400.00	Remove sumps, remove gasket and gerni sumps
08-Nov-22	Dan	44456	\$300.00	Finish off service
07-Nov-22	Jesse		\$700.00	Chochie bars on steps & tranny oil plug cover
07-Nov-22	Dan	44456	\$850.00	Service & defects
				Carried out 500hr service
07-Nov-22	Craig	44456	\$600.00	Carried out repairs
				Carry out repairs.
07-Nov-22	Shane	44457	\$1,536.00	Machine is down for blown hoses.
				Finish off service and fit hoses
				Diagnose engine oil leak (Sump)
				Top up and prime system, degrease cooler pack and wash
07-Nov-22	Jesse		\$700.00	Chochie bars on steps & tranny oil plug cover
07-Nov-22	Toddy		\$302.50	500hr service/defects
06-Nov-22	Toddy		\$55.00	Pulled off stabilizer arm hoses as they blew out
				Remove worn plates, prep for new plates and fit new plates
24-Oct-22	Oliver	44285	\$1,200.00	
22-Oct-22	Ben		\$500.00	Welded drill rod to protect master brake bolts
				Continue with track plate install
				Tension track bolt with Chris from hasting
				Complete service from 14/10/2022
				Filters ordered installed
22-Oct-22	Tom		\$800.00	Repair/plan master link bolts (needs attention)
22-Oct-22	Josh	44873	\$100.00	Fit grousers & chain up old ones
22-Oct-22	Oliver	44285	\$300.00	Assist hastings with torque gun
22-Oct-22	Dan	44285	\$450.00	Grouser change out
				Change out grouser & track bolts
				Set up job in workshop
21-Oct-22	Tom	44285	\$1,300.00	Remove all track plates
				Replace grousers on tracks, oxy old ones off,
21-Oct-22	Josh		\$1,200.00	replace with new ones
21-Oct-22	Ben		\$900.00	New track grazer plates
21-Oct-22	Dan	44285	\$200.00	Grouser change out
				Get change out new corner tips & flip centre edges
14-Oct-22	Jesse		\$400.00	
14-Oct-22	Shane		\$500.00	1000hr service and c/o GET

				1000hr service
				Change out GET
14-Oct-22	Tom		\$500.00	Complete work order
14-Oct-22	Ben		\$250.00	1000hr service
				Engine Change fuel filters. Test. Still +5 volts sensor supply code active. Chase fault, found fan pump pressure sensor all wires are bare & shorting to chassis.
25-Sep-22	Shane	23977	\$600.00	Repair & test. OK. Reassemble machine
24-Sep-22	Toddy		\$200.00	Replaced missing bolt/oring on hydraulic line
24-Sep-22	Shane	23977	\$150.00	Assist with oil leak
				Diagnose leaking oring in hell hole.
23-Sep-22	Shane	23977	\$150.00	Leave until morning to cool
				Goanna bar install
21-Sep-22	Jesse S		\$150.00	Gouge off cutting edge to install new goanna bar
18-Sep-22	Jesse		\$100.00	Install handrail on RHS
16-Sep-22	Toddy		\$100.00	Cleaned cabin filters
				Fill hydraulic oils
08-Sep-22	Michael		\$300.00	Fix light faults on top lights
07-Sep-22	Michael		\$150.00	Test fit new hose
				500hr service and defects.
07-Sep-22	Mich	44476	\$950.00	Trans plug rebuild. Lights replaced.
				Diagnose leaking hose. Drop rear belly guard & remove
06-Sep-22	Shane		\$300.00	Organise new one to be built
05-Sep-22	Shane		\$150.00	Jump start machine & fit new battieries
05-Sep-22	Toddy		\$200.00	Replaced 3 battery
04-Sep-22	Toddy		\$100.00	Heated up battery box to straighten out
04-Sep-22	Shane	43770	\$100.00	Battery box repairs & jump start
02-Sep-22	Shane		\$100.00	R+R ripper boot
				Changed out cutting edges on blade/greased and checked fluids
30-Aug-22	Toddy		\$100.00	C/O GET
30-Aug-22	Stephen		\$200.00	Fit blade GET & carry out 250hr service
30-Aug-22	Shane		\$400.00	Cutting edges & 250hr service
29-Aug-22	Jack	43710	\$300.00	Fit new mount rubber to RH outer cylinder light & rewire
25-Aug-22	Shane	43635	\$150.00	Headlight fault
24-Aug-22	Jack	43643	\$200.00	Replace ripper boot
19-Aug-22	Shane		\$100.00	Weld handrail and install new gowana bar on L/H side of blade
16-Aug-22	Jesse S		\$400.00	
				Remove x3 rocks from LH+RH tracks
16-Aug-22	Jack	43503	\$1,200.00	Remove broken bolts from LHR+RHR idlers
				Refit caps
				Remove broken bolts from LHS+RHS rear idlers
16-Aug-22	Sean	43503	\$1,000.00	Remove rocks off LHS+RHS tracks
14-Aug-22	Sean	43468	\$55.00	Install new powerwire UHF
				Cracked handrails & brace on RH side
10-Aug-22	Jesse		\$150.00	Need to be change to FSVV rope insight

				Inner RH window loose - shattered while removing
07-Aug-22	Shane		\$150.00	Clean up all broken glass
05-Aug-22	Jack	43317	\$200.00	250hr service
03-Aug-22	Shane		\$100.00	Check out missing bolts and order parts
26-Jul-22	Shane		\$440.00	Repair coolant leak
				R+R GET corner tip and turn middle ones
25-Jul-22	Shane	43160	\$800.00	Coolant leak - diagnose, found hose in front of engine leaking
				Check over system
				Greaser pumping but not switching off
18-Jul-22	Shane	43132	\$165.00	Needs new pressure switch
17-Jul-22	Shane	43078	\$200.00	Finish off 1000hr service & repairs
17-Jul-22	Rhys	43076	\$1,000.00	Defects & 1000hr service
17-Jul-22	Jack	43076	\$200.00	Finish 1000hr service & defects
				Order parts & organise pick up
				Blade repairs
				Fit wear plates
16-Jul-22	Shane	43078	\$600.00	1000hr service
16-Jul-22	Rhys	43076	\$500.00	1000hr service and defects
15-Jul-22	Rhys	43076	\$150.00	Oil leaks inspected
15-Jul-22	Shane	43078	\$200.00	Start 1000hr service
14-Jul-22	Rhys	43076	\$250.00	1000hr service
				1000hr service
				C/O roller
14-Jul-22	Jack	43076	\$1,200.00	Repaired trans filter housing
13-Jul-22	Jack	43006	\$500.00	Removed damaged RH roller
13-Jul-22	Sean	43006	\$500.00	Remove damaged roller
				Tighten all GET
				Adjust track
26-Jun-22	Shane		\$400.00	Replace wear plates on side of blade
				Tighten GET on blade
				Install side access platform
				Pump out cannon
26-Jun-22	Michael		\$850.00	Clamp side rear plates
26-Jun-22	Shane		\$800.00	Finish off cannon repairs
				Continue on with track adjuster repairs
				Join track fit cannon back into machine
25-Jun-22	Shane		\$1,200.00	Fit new G.E.T
				Oxyed off cutting edge bolts
				Removed and replaced cutting edge on blade
				Welded on chocky bar to strengthen damaged
25-Jun-22	Lain		\$412.50	step on draft arm
				Change out GET
				Install cannon ram
				Refit trackers
25-Jun-22	Michael		\$1,150.00	Change out seat covers
				Assist with refitting track adjuster into cannon
				Refit track chain and tighten
25-Jun-22	Shane	42891	\$600.00	Change blade GET
				Rebuild cannon D11 dozer
24-Jun-22	Sean	42862	\$500.00	D11 dozer RHS trailer frame rebuild

				Rebuild cannon
				Remove cannon out cylinder seals
24-Jun-22	Michael		\$1,150.00	Start removing GET
				Strip cannon replace seals
24-Jun-22	Shane		\$800.00	Fit back into machine
				Cannon rebuild
23-Jun-22	Michael		\$300.00	Remove cylinder
21-Jun-22	Shane	42891	\$450.00	Set up and remove track adjuster from cannon
				Crack master link bolts and roll off RH track
19-Jun-22	Shane	42890	\$200.00	Start removing RH cannon
15-Jun-22	Shane		\$600.00	Go pick up hire hi torque and trm to split track
14-Jun-22	Shane	42891	\$200.00	Re-steer R/H side cannon
				Went to replace damaged to find the wrong parts were ordered
				Took leaking implement pipe off, rewelded pipe down at w/shop
13-Jun-22	Lain	42890	\$495.00	Refitted pipe with new o-rings
				Topped up hydraulic oil
11-Jun-22	Lain	42867	\$82.50	Blew out air filters
				Had to make new handrail
11-Jun-22	Harry D		\$412.50	Bend the pipe and held it up and painted it
				RH lift cylinder quick dump valve loose and o-ring leaking
09-Jun-22	Shane	42859	\$150.00	Remove and fit new o-rings
				Topped up hydraulic oil
				Greased
09-Jun-22	Lain	42849	\$82.50	Blew out air filter
				Refit welded up hydraulic pipe to pump then refitted floor of the cab
07-Jun-22	Lain	42833	\$82.50	
				Removed floor to find hydraulic hose with hole in it
				Removed and replaced hose with one made up on site
				Filled hydraulic tank. Went back to get more hydraulic oil to continue filling tank. Tested machine to find another leak from hydraulic pipe, removed a
06-Jun-22	Lain	42833	\$742.50	
25-May-22	Shane	42740	\$100.00	Secure loose dash panels
23-May-22	Shane		\$150.00	Grease machine and adjust track
				Diagnose faulty pressure switch on auto greaser
				Change both outer LH cylinder hoses
				Manually grease machine
21-May-22	Shane	42701	\$300.00	Pump up RH track
				LH corner tip loose
				Remove, clean and refit
21-May-22	Shane	42707	\$300.00	Tighten all edge bolts
				Tensioned up tracks
				Replaced L & R lift cylinder hose
21-May-22	Lain	42693	\$165.00	Replaced ripper boot

19-May-22	Lain	42682	\$371.25	Tensioned track Replaced and flipped blade cutting edge Tightened up adjuster on RH track
14-May-22	Lain	42628	\$123.75	Greased and blew out air filter
13-May-22	Lain	42613	\$206.25	Fixed start fault in cab wiring
04-May-22	Shane	42570	\$400.00	go over defect list from compliance checks, sort out 3 points of contact access, replace leaking O'ring to hydraulic control valve in hell hole.
03-May-22	Shane	42570	\$300.00	Finish machine assembly and compliance repairs.
02-May-22	Shane	42570	\$300.00	Compliance checks and repairs
01-May-22	Shane O	42570	\$750.00	Machine assembly.
30-Apr-22	Shane O	42570	\$200.00	Set up for assembly and organise paperwork. Stripped transmission & torque converter
30-Jun-21	Connor		\$426.25	Waiting on parts
28-Jun-21	Connor		\$137.50	Removed cab
04-May-21	Duncan	10797	\$135.00	Complete pre start and grease. Battery light on. Check charge rate. OK. Repaired broken wire on alternator. Light out. Loaded out. Blade, push arms, tilt cylinders, rops, cab, ripper, walkway hand rails. Washed down tyres on crane & truck & trailer
20-Feb-21	Anthony W	42371	\$220.00	Washed machine down with pressure washer Refitted belly guards
18-Feb-21	Anthony W	42371	\$302.50	Fit fire extinguishers, ready for pick up Washed all belly guards out Carried out site specific inspection Requires safety decals & 9kg fire extinguisher so far
15-Feb-21	Anthony W	42371	\$247.50	
13-Feb-21	Brad Smith	42372	\$110.00	Continue wash down & site prep for Rookwood
12-Feb-21	Brad Smith	42372	\$137.50	Lift belly plates & move for a wash Drop belly plates, locate leaking hoses and replace weeping o-rings Help horsepower remove & refit rubbed and suspect hoses
11-Feb-21	Brad Smith	42372	\$632.50	Removed belly guards to find oil leaks Found multi hoses leaking. Started removal of hoses and organized hose power to repair
11-Feb-21	Anthony W	42371	\$220.00	Strip for transport
10-Feb-21	Brad Smith	42372	\$522.50	Hydraulic leak in hell hole
10-Feb-21	Anthony W	42371	\$440.00	Stripped down for transport Removed rops, removed cab, removed exhaust stacks, removed hand rails, removed blade cylinder arms, removed trunnions
09-Feb-21	Anthony W	42371	\$82.50	Wash down ready for strip down

08-Feb-21	Brad Smith	42354	\$27.50	Broken skin guard
02-Feb-21	Brad Smith	42320	\$27.50	Ripper box
				Carried out 250hr service
				Changed oil & filters & sampled
				Air filters need replacing
				Replaced alternator & a/c belts
				Replaced ripper shank protector pin
				Greased
				Check final oils & transmission oil & pivot shaft
				oils - all ok
25-Jan-21	Anthony	42277	\$385.00	Grease system is not working -
22-Jan-21	Brad Smith	42262	\$55.00	Replace radiator cap
				Refitted ripper tilt cylinder and repaired grease
				lines
15-Jan-21	Anthony	42223	\$165.00	Replaced ripper shank protector
				Removed broken ripper & replace with second
				hand one
12-Jan-21	Anthony	44202	\$137.50	Changed ripper boot over. Unable to change
				ripper protector due to rusty sleeve pins
				Replaced ripper boot & checked grease system
07-Dec-20	Anthony W	42105	\$82.50	Could not get it to fault. Need to monitor
				Greased & filled greased pot.
05-Dec-20	Anthony W	42095	\$55.00	Checked a/c cab pressurizer needs replacing
				Tighten all cutting edge bolts
27-Nov-20	Duncan		\$192.50	Replace ripper boot
				Fitted belly plate
				Fitted floor & top oil up
20-Nov-20	Duncan	41991	\$165.00	Hydraulic oil
				Replace Ripper boot
				Major oil leak - remove floor - washed area
				Started machine - oil leak from main block
				Ordered plugs & mounts.
				Removed bottom belly plate supported main
				valve
				Removed mounting plate. Cleaned. Replaced
				2 x plugs, bottom of main valve
19-Nov-20	Duncan	41991	\$495.00	R
				Replace Ripper Boot.
13-Nov-20	Duncan	41961	\$27.50	Top up box oils
				Hyd leak
				Capped hyd T and service line
				A/C failed. No gas in system.
				Charged with nitrogen. Found nut on receiver
				dryor leaking. Tightened nut.
12-Nov-20	Duncan	41945	\$192.50	Vac systems & Gassed



11-Nov-20	Duncan	41932	\$192.50	Remove A/C gas. Attempt to replace receiver dryer Quick couplers. Siezed. Replaced quick couplers. Vac system & gassed Topped up Bar oil
06-Nov-20	Duncan	41909	\$165.00	Replace ripper boot Replaced broken grease fitting on ripper Auto greaser faulting - manually greased machine Investigate AC fault - ordered parts
02-Nov-20	Anthony W	41879	\$55.00	Tighten up alternator belt & a/c belt. Found alternator mounting bolts loose & cover off
28-Oct-20	Duncan	41877	\$220.00	Fit fuel quick fill hose Mount to left LH lift (ripper) cylinder. Fitted grease nipples & greased brake tilt cylinders Connected washers, harness to lights on ..... Connected plugs & wires in cab AC vents UH Radio missing Electronics in cab been wet from be
27-Oct-20	Duncan	41877	\$550.00	Assemble dozer from transport. Fit cab, reps, ripper, blade, bush arms, tilt cylinders and hand rails
24-Oct-20	Dexter		\$110.00	Fix up wiring and fit new light. Swap cap. Clean workshop and clean and place back tooling
23-Oct-20	Dave Marshal		\$247.50	Repair light brackets & fitt bash plate Refit hell hole corners and park at boilermaker bay to weld belly guard hinge back on. Readjust
08-Oct-20	Daniel D		\$275.00	RH track chair.
08-Oct-20	Kyle M		\$247.50	Light guard rebuild Fit 2 front belly guards all RH side of engine cover. Fit alternator and new belt, repair 2 hinges on cover for step.
06-Oct-20	Daniel D		\$550.00	
29-Sep-20	Dave Marshal		\$192.50	Repair H/Rails Blade are repairs
29-Sep-20	KyleMusgrave		\$495.00	Hand rails
28-Sep-20	DaveMarshall		\$385.00	Install new ball cap on push arm
28-Sep-20	KyleMusgrave		\$330.00	No notes
27-Sep-20	DaveMarshall		\$110.00	Gouge of ball cap of push arm Move out of washbay - clean up / roll up mats - cut x1 bogie strap off.
26-Sep-20	Jack		\$137.50	

				Torq x 4 roller caps/start washing - fill hyd oil - change x 3 hyd filters - replace a fire suppression guage - cut straps off track frame - clean up tooling drain wheel and fill.
25-Sep-20	Jack	41873	\$426.25	Finish off P706 park over to wash bay, Jack started washing down.
25-Sep-20	Dex		\$550.00	Start to back up tools left over from job.
				Remove track frame
				Reduce oring
				Fit track frame
24-Sep-20	Greg	41870	\$110.00	Tighten cutting edges
				Finish off 1000hr service help jack with refill of oils
24-Sep-20	Dex		\$550.00	Park to remove track frame off, Replace oring and Refit frame and chain fill with oil - All ok
24-Sep-20	John		\$82.50	Remove and refit LH track
				Fit RH headlight assembly to lift cylinder and replace light. Fit new drives to fire suppression joiner and recharge system. Fittings not leaking, gauge on bottle now leaking, drain pressure and refit new bottle. Recharge system, gauges all reading differ
24-Sep-20	Shane	41872	\$467.50	Change fuel filters - clean x2 screens/start filling trans oil -top up engine oil - remove track frame / install - trnion track - replace all creen orings - clean up tooling.
24-Sep-20	Jack	41873	\$550.00	Park back in shed, perform service drain engine oil and tranny oil
23-Sep-20	Dex		\$522.50	Adjust track chains and fill cannon oil.
23-Sep-20	Jack	41873	\$178.75	Drain/fill engine oil/change oil filters - drain trans oil fill cannon oil.
23-Sep-20	Greg	41870	\$110.00	Fit cutting edges.
				Pad weld 4 track guide block
				Fit new bolts and roller caps
				Refit track frame to tracker
22-Sep-20	Dex		\$605.00	Roll chain back on
22-Sep-20	Greg	41870	\$165.00	Move blade and crusharms, Remove cutting edges, clean up blade.
22-Sep-20	John		\$27.50	Refit track frame
				Change fire suppression and check for leaks.
22-Sep-20	Shane	41872	\$467.50	Found joiner in hell hole leaking. Help with GET change out, refit LH track frame and tank.
22-Sep-20	KyleMusgrave		\$192.50	Hand rails
				D I I push arms
22-Sep-20	DaveMarshall		\$467.50	Repair hydraulic tank and hand rails
21-Sep-20	DaveMarshall		\$330.00	Repair crack in track frame

				Re press mirror bogie pin All ok
				Fit caps to truck frame, Remove broken bolts out of track frame, Replace rollers and caps, start to pod weld track for track guides.
21-Sep-20	Dex		\$550.00	LH side track frame repairs. Remove and refit rollers for boilermaker to weld up cracks.
				Remove and seal all suspension pad mounting bolts.
21-Sep-20	Shane	41872	\$412.50	Rebuild RHS blade lift ram
19-Sep-20	Lindsay		\$192.50	Fit into machine
19-Sep-20	Greg	4187	\$55.00	Fit lift cylinder
18-Sep-20	John		\$55.00	Remove LH track frame.
18-Sep-20	Lindsay		\$82.50	Assist Dex in removing LHS track frame.
				Try to press bogue back in no good, pull back out with 100 ton press
				pull tractor out of shed, put on stands split tracks
18-Sep-20	Dex		\$550.00	remove track frame.
18-Sep-20	Will		\$165.00	Assist dex in bogie axel and putting on stamps
18-Sep-20	Ted		\$27.50	Organise parts
17-Sep-20	Greg	41870	\$55.00	Start to assemble cylinder
				Fit raper bed to trackter and slim
				Fit 3 row minor bogue out to truck frame try to fit inner, no good pull back out ordered fill bungs
				try another day
17-Sep-20	Dex		\$495.00	Clean work shop.
				Refit exhaust manifolds, turbo, air filter and air intake pipes. Fill with coolant, start, check , ok.
17-Sep-20	Shane	41872	\$440.00	Assist with refitting ripper box.
17-Sep-20	Dave M		\$440.00	Repair track frame.
17-Sep-20	Will		\$220.00	Assist dex with dozer.
16-Sep-20	Kyle M		\$137.50	Repair cracks.
				Check out grease, clean up gease, repair oil leak on converter, diagnose trans temp fault.
16-Sep-20	Greg	41870	\$275.00	Clean up exhaust manifolds and heads ready for assembly. Look up and order parts for other defects found on machine. Remove engine oil cooler pipes and clean. Fit new orings and reinstall. Reseal hydraulic cooler manifold and hoses.
				Fit replacement hyd hoses
				Fit new ripper bed bushes to tractor frame
				Fit convertor drain tube orings
				Fit new grease line and repair
				Remove Hyd cooler lines from control block
16-Sep-20	Dex		\$550.00	Replace orings and refit.
				Remove RH 3rd row minor boge and rollers
				clean ready for install welding plug weld
				Remove oil cooler lines and order orings
				Remove hyd hoses for replacement
				Remove broken roller cap bolt out of RH side
15-Sep-20	Dex		\$550.00	front inner cap.

15-Sep-20	Shane	41872	\$165.00	Clean hydraulic tank and check leaks, crack on weld at front of tank. Reseal lift cylinder.
15-Sep-20	Greg	41802	\$220.00	Assembly cylinder and fit.
14-Sep-20	Shane	12391	\$330.00	Remove all guards, check exhaust leak no. 2 on LHS exhaust gasket blown. Remove turbo, etc and remove manifold section. Order parts.
14-Sep-20	Dexter		\$522.50	Common repairs on P706 Remove remover of belly guards Gouge bushes in trade frame Diagnose engine oil leak Diagnose hyd oil leak. Remove belly guard front of equiliser bar to check for movement Remove engine guard to diagnose fuel leak and check drive shift movement
12-Sep-20	Dexter		\$220.00	Remove hyd hose for replacement.
11-Sep-20	Greg Miller	41870	\$165.00	Remove left cylinder, disassemble. Remove tranny guard Drop ripper bed
11-Sep-20	Dexter		\$330.00	Remove belly guard under convertor to check engine oil leak.
10-Sep-20	Dexter		\$137.50	Check over dozer, prep defect list, sort to remove ripper bed.
03-Sep-20	Greg Mills	41870	\$412.50	Pull apart components and load on to float, Drive machine to load area.
02-Sep-20	Greg Mills	41870	\$605.00	Demob for transport
16-Mar-20	John	8544	\$55.00	Remove ECM from behind cab
15-Mar-20	Duncan	41869	\$302.50	Started machine and move to better location Begin to disconnect LH tilt cylinder Remove bottom pins Lowered middle belly plates Ready to replace starter motor Machine not starting Checked wiring and relay Top starter motor with pre lubed
30-Nov-19	D Stevens	41680	\$260.00	Jumped 2nd to move machine
26-Sep-19	Duncan	41538	\$192.50	Fit all remaining guards on Rh side of machine
25-Sep-19	Duncan	41538	\$165.00	Fit floor platse
28-Aug-19	Duncan	41362	\$55.00	Clean out and fit front belly plate
15-May-19	Greg	40923	\$385.00	Change ripper boot. Replace hydraulic suction hose. Reseal pilot control valve. Weld up belly guard plate. Fit UHF. Repair grease lear at greaser. Grease machine.
11-May-19	D O'Leary	40922	\$192.50	Assemble machine
10-May-19	Greg	40922	\$467.50	Assemble machine.
10-May-19	D O'Leary	40922	\$550.00	Finish striping machine. Load machine and components. Arrange unloading.
09-May-19	D O'Leary	40922	\$330.00	finish 1000hr service. Tranny leak.
26-Feb-19	Dane	40621	\$660.00	reseal leak at tranny drain. Finish service.
26-Feb-19	Dave	40921	\$715.00	

25-Feb-19	Dave	40921	\$715.00	Start 1000hr service. Order parts for tranny leaks.
23-Feb-19	Dave		\$110.00	pack for services + demop
				Fit repaired ripper leg, swap wear plates on push arms. Fit grease lines to power ripper pins.
14-Jan-19	Dave		\$660.00	Remove and inspect grease fill valve. Check + reassemble. Test, ok.
08-Jan-19	Dave	40786	\$495.00	250hr service. Inspect ripper shank. Nose U/S. repair hyd temp sensor wiring.
				Fit fan return filter. Fault still on. Replace hyd return filter + repair wiring fault in bypass switch wiring.
12-Dec-18	Dave		\$165.00	Fit head. Adjust valve and injector. Reassemble.
				Fitt coolant. Start. Check leaks, ok. Start removing all rocker covers to check rocker shaft bolts.
08-Dec-18	Dave		\$550.00	
				Found rubbed cat data link wires on tranny ecm harness intermittantly shorted to ground. Repair wires. Secure harness. Reassemble. Test, ok.
29-Nov-18	Dave	40600	\$684.75	Repair greaser fault, test, ok.
				Found water entry into engine harness plug.
				Clean and wrap with denso tape. Reassemble.
				Clear codes. Test, ok. Tighten greaser hose.
				Remove greaser fill valve. Free up and clean. Test, ok. Increase greaer on time. Check grease getting to ripper bed pins,
22-Nov-18	Dave		\$629.75	Electrical fault.
16-Nov-18	Dave		\$55.00	Finish assembly. Weld tabs to stop ripper bed pin turning.
14-Nov-18	Dave	40497	\$330.00	Continue assembly
13-Nov-18	Dave	40497	\$357.50	Crankshaft seal, fit components. Coolant fill, test look for faults.
13-Nov-18	Dane	40497	\$778.25	Replace front crankseal
12-Nov-18	Dave	40497	\$165.00	service.
08-Nov-18	Dane	40497	\$299.75	500hr service. Repair electrical fault.
08-Nov-18	Dave		\$385.00	Replace 3 coolant hoses. Pressure test, ok. Fd with water to make sure its right before filling with coolant. (to be changed when machine serviced)
26-Oct-18	Dave	40395	\$503.25	Fit and adjust sensor, test, ok. Refit belly plate and guards.
25-Oct-18	Dave	40391	\$577.50	
				Replace no 2 injector. Repair thread on no 1 tappet cover. Code for permanent timing sensor.
24-Oct-18	Dave	40391	\$701.25	Filled hyd oil up, filled auto greaser, tested power to auto greaser, connected grease lines, filled fire supression bottle.
08-Oct-18	Jacob		\$165.00	Fitted suction hose, filled hydraulics oil up. Fitted grease nipple adapter to auto greaser so it can be filled.
28-Sep-18	Jacob		\$110.00	Fit hyd pump suction hose.
27-Sep-18	Dave		\$55.00	Fit hyd tank drain valve. Drain hyd tank.
26-Sep-18	Dave		\$137.50	

				Refit turbo drain pipe. Rubbing on fuel supply pipe to head. Allow clearance between pipes.
				Refit. Timing sensor fault. Adjust sensors, test, ok.
06-Sep-18	Dave	40320	\$660.00	Wont start. Prime fuel several ways. No go. Block return and crank until engine started. Ok.
04-Sep-18	Dave	40320	\$577.50	Injectors hasn't leaked overnight.Injector was stuck open internally. Fit new injectors.
				Remove all injectors looking for tips missing. All injector look ok. Engine turns over. Order orings & hold down bolts for injectors. Seal up.
01-Sep-18	Dave	40320	\$275.00	
				Not winding over. Batteries pulling down. Jump start, no go. Drop t/c belly plate. Turn over by hand. Hyd lock. Remove valve covers. Remove #4 injector as it is close to topof compression stroke. Re,ove fuel return pipe. Try turn on engine. Still hyd lock
31-Aug-18	Dave	40320	\$357.50	
30-Jul-18	Dave		\$110.00	Hyd temp sensor fault. Repair wiring. Test, ok.
03-Jul-18	Dave O'Leary	40251	\$55.00	High crankcase pressure code. Check out no fault found. Didn't come back on.
29-Jun-18	Dave O'Leary		\$55.00	Refit batteries, test, ok.
				Refit batteries. Needed to jump start. RH Batteries low. Start and run. Tp up tranny oil after startup. Finish pumping tranny oil.
21-Jun-18	Dave	40250	\$220.00	Complete 1000hr service.
19-Jun-18	Dave	40250	\$137.50	1000hr service.
18-Jun-18	Jacob		\$495.00	Continue service
14-Jun-18	D. O'Leary		\$192.00	Continue 1000hr service
				Reseal hydraulic fitting
				Tighten clamps on rad hose
				Pressure test cooling system, ok.
				Locate diesel leak
				Transfer pump leaking
13-Jun-18	D. O'Leary	40250	\$632.00	Remove pump & order parts
12-Jun-18	D. O'Leary		\$247.00	Start 1000hr service
				Finish repairing oil leaks
				Get oil & fill tank
01-Jun-18	D. O'Leary		\$165.00	Test, ok
				Replace hose on fan pump
31-May-18	D. O'Leary		\$165.00	Replace O ring on hose fitting on implement valve