

QTY	DESCRIPTION	UNIT PRICE EX GST	DISC %	TOTAL PRICE EX GST
	<p>Isuzu FH FVZJZL11 Truck Serial No: JAH+LFVZ34P87000952 Hours: 9,0814 KM</p> <p>Service & Inspection - Charge Air Hose Needs Replacing - Rear Diff Torque Rod Bushes Delaminated From Mount Shaft - Front Diff Oil Leak - Jack Shaft Between Diffs, Loose Cap Screws on Uni Joints - All Brakes Need Adjusting - Engine Light On Dash</p> <p>Supplied & Installed Torque Rod Bushes, Mount Bolts & Nuts, LHR Slack Adjuster, Charge Air Hoe, Topped Up Front Diff Oil, Topped Up Coolant Expansion Tank With Distilled Water, Replaced Wiper Blades & Washed Truck</p> <p>Erased Fault Codes From System Store Codes Only - Low Boost From Turbo, DPF Flow Reduced - Sysuspect Codes Come From Hose Comning Adrift - Road Tested - All OK</p>			
18	Hour of Labour	\$145.00		\$2,610.00
	Parts Used:			
1	Service Kit - Outer Air Filter, Inner Air Filter, Oil Filter & Fuel Filter	\$242.72		\$242.72
20	Litre of Engine Oil - 5W/30 DH2	\$9.36		\$187.20
2	Litres of Gear Oil - 80W90	\$8.92		\$17.84
1	Grease Cartridge	\$11.00		\$11.00
2	Litres Distilled Water	\$1.95		\$3.90
1	Waste Disposal/Enviromental Levy	\$10.50		\$10.50
1	Charge Air Hose	\$195.00		\$195.00

Subtotal EX GST:	
Freight EX GST:	
GST:	
Total Inc GST:	
Paid to Date:	

Customer A,B,N.:

QTY	DESCRIPTION	UNIT PRICE EX GST	DISC %	TOTAL PRICE EX GST
1	Sump O-Ring	\$15.80		\$15.80
4	Torque Rod Bush	\$77.79		\$311.16
4	M18X100 10.9 Bolts	\$42.62		\$170.48
8	M18 Nuts	\$24.86		\$198.88
1	Slack Adjuster	\$358.25		\$358.25
3	Wiper Blade	\$5.95		\$17.85

Subtotal EX GST:	\$4,350.58
Freight EX GST:	\$0.00
GST:	\$435.06
Total Inc GST:	\$4,785.64
Paid to Date:	\$0.00
Balance Due:	\$4,785.64
