

Hall Plant Hire - Work Order Summary

Asset:
1248 - Volvo EC210CLC Excavator

Location:

Current Tracker Hours:

Current Tracker Kms:

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
97748	Get machine ready for auction	04/05/2023	9367	3198	19/06/2023	Equipment ineffective		Zac Selby
97749	Right side foot pedals sticking	04/05/2023	9367	3198	19/06/2023	Safety		Zac Selby
97575	Plant Risk assessment due	26/04/2023			19/06/2023	Plant Risk Assessment		
96962	Engine error light coming on	29/03/2023			19/06/2023	Mnor defects		
95570	Multiple Prestart Defects	01/02/2023				Safety	Open	
95218	Multiple Prestart Defects	17/01/2023				Safety	Open	
94437	Six monthly plant inspection	02/12/2022				Inspection	Open	
93990	Multiple Prestart Defects	14/11/2022				Safety	Open	
91602	replace broken front bottom window	01/07/2022	9220	3087	05/07/2022	Safety		Glass Precision
91605	ignition accessories wont turn off	01/07/2022	9220	3087	05/07/2022	Equipment ineffective		Skidders Auto Electrical
91606	reseal track adjusters	01/07/2022	9220	3087	19/06/2023	Equipment ineffective		Matthew Cahill
91607	severe rust in track frame	01/07/2022	9220	3087		Workshop Repairs	Open	Matthew Cahill
91611	Replace sprockets	01/07/2022	9220	3087	19/06/2023	Workshop Repairs		Matthew Cahill
91081	9250 hours service	08/06/2022	9197	3072	01/07/2022	Routine service		David Ford
90940	Six monthly plant inspection	02/06/2022			08/07/2022	Inspection		David Ford Hayden Neal Matthew Cahill
90865	Prestart Defect - Check Operation of Flashing Light Failed	30/05/2022			01/07/2022	Safety		
90670	HYD hoses u/s	18/05/2022			07/07/2022	Workshop Repairs		Suncoast Hoses
90675	Plns and bush's in hitch and "H" link worn out	18/05/2022	9141	3028	19/06/2023	Workshop Repairs		
90309	front lip on bucket broken off	22/04/2022			01/07/2022	Safety		
89799	boomlift slow	17/03/2022	9061	2976	26/03/2022	Equipment ineffective		Corey Reibelt
89715	door latch broken	09/03/2022	9053	2970	10/03/2022	Mnor defects		Corey Reibelt
89477	Check accumulator charge pressure	17/02/2022	9041	2961	17/02/2022	Mnor defects		
89479	radiator core leaking	17/02/2022	9041	2961		Equipment ineffective	In Progress	Corey Reibelt
88763	Six monthly plant inspection	02/12/2021			17/02/2022	Inspection		
88216	Prestart Defect - Check all Operator Controls and Gauges are	06/10/2021			17/02/2022	Safety		Troy Ferrari
87752	Prestart Defect - Read and sign machine SOPs - Scan QR Code.	23/08/2021			17/02/2022	Safety		Troy Ferrari
87620	Low on coolant and engine oil	09/08/2021			17/02/2022	Mnor defects		
87549	9000 hours service	31/07/2021	8953	2898	17/02/2022	Routine service		
87535	Prestart Defect - Check Condition of Hand Rails and Steps Fa	29/07/2021			17/02/2022	Safety		Troy Ferrari

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
87447	Prestart Defect - Aircon fault	23/07/2021			26/03/2022	Equipment ineffective		
87437	issues during mooloolaba job	22/07/2021	8920	2869	22/07/2021	Mnor defects		Corey Reibelt
87247	Prestart Defect - Broken windscreen	28/06/2021			14/07/2021	Equipment ineffective		Glass Precision
87067	Lights not working	10/06/2021	8873	2834	10/06/2021	Equipment ineffective		Stacey Rossetto
86967	Prestart Defect - Check Fire Extinguisher Failed	01/06/2021			10/06/2021	Safety		Tyson Arbon
86891	Prestart Defect - Check operation of Quick Hitch / Coupler Fa	25/05/2021			10/06/2021	Safety		Stacey Rossetto
86663	workshop repairs	29/04/2021	8862	2824	14/07/2021	Equipment breakdown		Corey Reibelt
86630	Plant Risk assessment due	26/04/2021			17/02/2022	Plant Risk Assessment		
86627	Six monthly plant inspection	25/04/2021			29/04/2021	Inspection		
86441	track frame condition report	30/03/2021	8821	2805	30/03/2021	Workshop Repairs		Matthew Cahill
86415	w/s repairs	26/03/2021	8820	2793	29/04/2021	Workshop Repairs		Corey Reibelt
86416	batter bucket floor	26/03/2021	8820	2793	30/03/2021	Equipment ineffective		Matthew Cahill
85355	Prestart Defect - Check E stops Failed	23/02/2021			23/02/2021	Safety		
85272	Quick hitch repairs	22/02/2021	8781	2755	29/03/2021	Workshop Repairs		Aaron Bruce
85207	Prestart Defect - Check Machine for Overall Condition/Damage	20/02/2021			07/03/2021	Safety		Adam Goad
85084	Prestart Defect - Check Machine for Overall Condition/Damage	18/02/2021			07/03/2021	Safety		Adam Goad
84425	Prestart Defect - Broken lower front windscreen	08/02/2021			07/03/2021	Equipment ineffective		Cody McCurdy
84317	8750 hours service	06/02/2021	8700	2703	17/03/2021	Routine service		Corey Reibelt
82878	6 month inspection defect list	23/12/2020	8657	2670	26/03/2021	Workshop Repairs		Matthew Cahill
82857	track frame needs painting/attention	22/12/2020	8656	2669	11/03/2021	Workshop Repairs		
80738	Prestart Defect - AC	06/11/2020			17/03/2021	Safety		
80263	Six monthly plant inspection	26/10/2020			23/12/2020	Inspection		
71095	Prestart Defect - No travel alarm	18/05/2020			06/11/2020	Workshop Repairs		Mark Challis
70383	Plant assessment due	06/05/2020			23/12/2020	Plant Risk Assessment		
68724	drain and re-fill hydraulic tank	08/04/2020	8532		06/11/2020	Workshop Repairs		
68725	replace quick hitch hoses	08/04/2020	8532		09/04/2020	Workshop Repairs		Tony Crawshaw
68727	Remove broken bolts from hammer attachment bracket Rhs	08/04/2020	8532		09/04/2020	Workshop Repairs		Tony Crawshaw
68728	Remove batteries clean, prep, paint battery box	08/04/2020	8532		09/04/2020	Workshop Repairs		Tony Crawshaw
68729	Add shims to attachment pins and stick	08/04/2020	8531		06/11/2020	Workshop Repairs		
68731	Fault find start fault	08/04/2020	8532		09/04/2020	Workshop Repairs		Tony Crawshaw
67331	over heating	16/03/2020	8515		16/03/2020	Equipment ineffective		Braeden Nx
65143	Prestart defects	15/01/2020			06/11/2020	Equipment ineffective		Grant Petersen
60805	8500 hours service	19/09/2019	8515	2551	16/03/2020	Routine service		Braeden Nx
55968	arm rest, foot pedals	10/06/2019			26/03/2021	Mnor defects		
55573	Prestart Defect - Check Machine for Overall Condition/Damage	30/05/2019			06/11/2020	Mnor defects		
53458	Prestart Defect - Check Condition of Hydraulic Cylinders and	27/03/2019	8365		27/03/2020	Mnor defects		Chris Jukes
53398	While in workshop having cylinder reseal	26/03/2019	8365		06/11/2020	Workshop Repairs		Braeden Nx

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
53231	Prestart Defect - Check all Operator Controls and Gauges are	21/03/2019	8365		06/11/2020	Mnor defects		Aaron Bruce
52713	Prestart Defect - Check Condition of Hydraulic Cylinders and	11/03/2019	8375		06/11/2020	Mnor defects		Braeden Nx
52052	Prestart Defect - Cracked windscreen	25/02/2019	8365		13/05/2019	Mnor defects		Cody McCurdy
50623	Prestart Defect - All Fuel/Oil Levels Failed	24/01/2019	8375		21/05/2019	Mnor defects		Braeden Nx
48825	8250 hours service	10/12/2018	8256		18/12/2018	Routine service		Jacob Castellaro
48971	Machine fail to start	21/11/2018			16/11/2018	Equipment breakdown		Stacey Rossetto
47936	Seat adjuster not locking in	12/09/2018	8089		12/09/2018	Safety		Dale Smyth
47274	8000 hours service	21/07/2018	8046		07/08/2018	Routine service		Peter Gillam
47157	Machine shut down	18/07/2018	7943		20/07/2018	Equipment breakdown		
47079	Bottom window, front cracked.	17/07/2018	7928		18/07/2018	Mnor defects		
46761	Quick hitch U/S	09/07/2018	7880		09/07/2018	Equipment ineffective		Dale Smyth
46280	Roller Broken Grease Line	04/06/2018	7843		26/06/2018	Mnor defects		Peter Gillam
45932	Rollers/Tracks	01/05/2018	7845		27/06/2018	Mnor defects		Dale Smyth
45934	Tyres/Tracks	01/05/2018	7843		26/06/2018	Mnor defects		
45829	7750 hours service	18/04/2018	7731		30/04/2018	Routine service		Peter Gillam
45752	Isolator Flap, Fuel Cap, Track Pedal	12/04/2018	7731		30/04/2018	Mnor defects		Luke Chirgwin
45665	Door lock damage	03/04/2018	7658		09/04/2018	Equipment ineffective		David Cairns
45589	Replace flashing light globe	23/03/2018	7582		23/03/2018	Equipment ineffective		Luke Chirgwin
45505	Machine down on power	13/03/2018	7843		26/06/2018	Equipment ineffective		Peter Gillam
45285	Isolator Flap Lock Broken	20/02/2018	7658		09/04/2018	Mnor defects		Peter Gillam
45298	Isolator Flap Broken	20/02/2018	7483		27/02/2018	Mnor defects		
45221	7500 hours service	13/02/2018	7476		19/02/2018	Routine service		Cody Davies
45107	Belt, Fire Extinguisher	02/02/2018	7505		03/03/2018	Mnor defects		Peter Gillam
44786	Replace grease nipples on lower boom base x 2	08/01/2018	7323		08/01/2018	Equipment ineffective		Luke Chirgwin
44695	Quick hitch not working	19/12/2017	7318		19/12/2017	Equipment breakdown		Peter Gillam
44696	Hyd hose leaking	19/12/2017	7318		20/12/2017	Equipment breakdown		Peter Gillam
44679	uhf not working, ac blowing fuses	15/12/2017	7335		10/01/2018	Mnor defects		Luke Chirgwin
44406	paint	21/11/2017	7240		21/11/2017	Workshop Repairs		Mark Challis
44411	bucket repairs	21/11/2017	7241		23/11/2017	Workshop Repairs		Matthew Cahill
44358	Misc repairs on excavator	16/11/2017	7239		16/11/2017	Workshop Repairs		Hayden Neal
44292	Track	13/11/2017	7241		23/11/2017	Mnor defects		Peter Gillam
44280	oil leaks and paint	10/11/2017	7241		23/11/2017	Equipment ineffective		Peter Gillam
44269	L/H final drive	09/11/2017	7239		16/11/2017	Workshop Repairs		Peter Gillam
44184	7250 hours service	02/11/2017	7238		13/11/2017	Routine service		Dale Smyth
43469	Replace serpentine belt	19/08/2017	6981		19/08/2017	Mnor defects		Cody Davies
43470	Bucket crowd cylinder leaking	19/08/2017	6993		25/08/2017	Mnor defects		Cody Davies
43462	Quick hitch jamming	18/08/2017	6981		18/08/2017	Equipment ineffective		Mark Pape

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Service	Item Status	Assigned To/Completed By
43291	deleted	05/08/2017	7753		14/05/2018		Workshop Repairs		Matthew Cahill
43219	Htch Flns	31/07/2017	6956		11/08/2017		Equipment ineffective		Mark Pape
42418	Plant assessment due.	07/06/2017	6791		10/07/2017		Routine service		Cody Davies
42346	6750 hours service	01/06/2017	6733		09/06/2017		Routine service		Cody Davies
42279	power	30/05/2017	7224		06/11/2017		Mnor defects		Cody Davies
41890	Quick hitch ID plate/safety labels	26/04/2017	7222		06/11/2017		Mnor defects		Craig Pitts
41714	Hyd leak	11/04/2017	6523		11/04/2017		Equipment breakdown		Luke Chirgwin
41176	6500 hours service	25/02/2017	6473		01/03/2017		Routine service		Luke Chirgwin
41019	Cab mounts loose	13/02/2017	6438		22/02/2017		Mnor defects		David Cairns
41020	Oil leak	13/02/2017	6438		22/02/2017		Equipment ineffective		Luke Chirgwin
40899	Eng oil leak	02/02/2017	6404		13/02/2017		Equipment ineffective		Luke Chirgwin
40806	Engine speed sensor	23/01/2017	6335		25/01/2017		Equipment breakdown		Chris Jukes
40741	oil leak / high oil temp / fan belt / air con belt	17/01/2017	6334		21/01/2017		Equipment ineffective		Stephen Czislowski
40702	Engine oil temp	10/01/2017	6305		20/01/2017		Equipment ineffective		Luke Chirgwin
40689	Engine temp light on	09/01/2017	6269		09/01/2017		Equipment breakdown		Luke Chirgwin
40640	Left ram leaking	19/12/2016	6305		20/01/2017		Mnor defects		Stephen Czislowski
40597	Fan belt	15/12/2016	6260		15/12/2016		Equipment breakdown		Luke Chirgwin
40439	Check for leaks	28/11/2016	6227		07/12/2016		Workshop Repairs		Jacob Castellaro
40112	Oil Leak	28/10/2016	6220	1155	28/10/2016		Mnor defects		Mark Pape
40084	L/h track falls off	26/10/2016	6227		07/12/2016		Equipment ineffective		Jacob Castellaro
35871	check l/h track coming off, idler u/s, sprockets worn, needs	26/10/2016			26/10/2016		Equipment ineffective		
35585	fit track plates, weld track pin	07/10/2016			07/10/2016		Equipment ineffective		
35557	split track and replaced r/h idler wheel	06/10/2016			06/10/2016		Equipment ineffective		
35584	replace idler	06/10/2016			06/10/2016		Equipment ineffective		
35359	change and flush final drive oil	24/09/2016			24/09/2016		Equipment ineffective		
35380	flush final drives	24/09/2016			24/09/2016		Equipment ineffective		
35376	check idlers and track adjusters, r/h idler has colapsed	23/09/2016			23/09/2016		Equipment ineffective		
35361	tighten loose bolt on turbo	22/09/2016			22/09/2016		Equipment ineffective		
35389	repalced blow n pump to control valve	20/09/2016			20/09/2016		Equipment ineffective		
35044	w/o 34023	07/09/2016			07/09/2016		Equipment ineffective		
34023	1000hr service and checks completed	07/09/2016			07/09/2016		Routine service		
35147	1000hr service and checks	07/09/2016			07/09/2016		Routine service		
35110	removed link from l.h track	03/09/2016			03/09/2016		Equipment ineffective		
35015	removed one link from both tracks	27/08/2016			27/08/2016		Equipment ineffective		
34873	fit new hour meter, repair oil leak at hammer piping valve,	19/08/2016			19/08/2016		Equipment ineffective		
34864	check tracks, out of adjustment, need link cut out	18/08/2016			18/08/2016		Equipment ineffective		

Work Order	Description	Created	Created Hours	Created Km	Completed	Equipment Ineffective Priority	Item Status	Assigned To/Completed By
34820	refit l/h track	09/08/2016			09/08/2016	Equipment ineffective		
34810	unload ute from saturdays repair	08/08/2016			08/08/2016	Equipment ineffective		
33894	replaced sprocks, oil leak not bad enough for repair	07/08/2016			07/08/2016	Equipment ineffective		
34809	remove l/h sprocket, fit 2 new sprockets, refit tracks and	06/08/2016			06/08/2016	Equipment ineffective		
34710	fit new sprockets and put track on	06/08/2016			06/08/2016	Equipment ineffective		
34808	remove tracks and r/h sprocket, new sprocket wrong, chase up	05/08/2016			05/08/2016	Equipment ineffective		
34707	remove tracks and sprockets	05/08/2016			05/08/2016	Equipment ineffective		
34702	top up slew oil, inspect track adjuster issue	04/08/2016			04/08/2016	Equipment ineffective		
34585	replace horn fuse	21/07/2016			21/07/2016	Equipment ineffective		
33767	not bad enough for repair	20/07/2016			20/07/2016	Equipment ineffective		
34517	clean out plug for engine oil temperature sensor	05/07/2016			05/07/2016	Equipment ineffective		
34350	refit radiator, oil cooler and intercooler, top up coolant and	02/07/2016			02/07/2016	Equipment ineffective		
34510	finish fitting turbo charger, fit radiator assy and test	02/07/2016			02/07/2016	Equipment ineffective		
33706	replaced bolts in grouser plates r/h side track	02/07/2016			02/07/2016	Equipment ineffective		
34508	fit new turbo, pick up intercooler, assemble radiator assy	01/07/2016			01/07/2016	Equipment ineffective		
34181	remove turbo, order parts, remove radiator assembly, dismantle,	30/06/2016			30/06/2016	Equipment ineffective		
34287	remove intercooler, change engine oil and filter	30/06/2016			30/06/2016	Equipment ineffective		
34174	blow n turbo, remove machine out of the way, chase up turbo and	29/06/2016			29/06/2016	Equipment ineffective		
33579	replaced hose clamps on coolant hose	25/06/2016			25/06/2016	Equipment ineffective		
33181	Replace Air Filter box	17/06/2016			17/06/2016	Equipment ineffective		
33078	Plant Risk Assessment - completed	17/06/2016			17/06/2016	Routine service		
34232	reapolce hyd tank orings and fit seat	17/06/2016			17/06/2016	Equipment ineffective		
33097	repaired seat	17/06/2016			17/06/2016	Equipment ineffective		
33105	change oil as per Robs Request	16/06/2016			16/06/2016	Equipment ineffective		
33555	remove seat and drop off for repairs	16/06/2016			16/06/2016	Equipment ineffective		
34227	fit airbox and remove seat for repair	16/06/2016			16/06/2016	Equipment ineffective		
34129	check fault with seat, needs more padding in cushion	15/06/2016			15/06/2016	Equipment ineffective		
34225	change hyd oil and complete plant assessment	15/06/2016			15/06/2016	Equipment ineffective		
34222	inspect seat	14/06/2016			14/06/2016	Equipment ineffective		
33410	carry out 500hr service on excavator as per check sheet,	25/05/2016			25/05/2016	Routine service		
32844	service completed in Hervey Bay	17/05/2016			17/05/2016	Routine service		
32860	replaced master links in track chains (cpitts, cdavies)	23/04/2016			23/04/2016	Equipment ineffective		
32007	replaced grouser bolts and both master link. mpape	23/04/2016			23/04/2016	Equipment ineffective		
32803	replace both track master links (MPape)	23/04/2016			23/04/2016	Equipment ineffective		
32724	replaced coolant reservoir (cpitts)	20/04/2016			20/04/2016	Equipment ineffective		
32445	DC - check over and lubricate and adjusted front window locks	22/03/2016			22/03/2016	Equipment ineffective		
31975	Check over & nil issues	10/03/2016			10/03/2016	Equipment ineffective		
32265	re-tension two grouser plates r/h side	10/03/2016			10/03/2016	Equipment ineffective		

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
32323	check over and repalce grease nipple and check hitch operation	25/02/2016			25/02/2016	Equipment ineffective		
31770	Replaced senser	06/02/2016			06/02/2016	Equipment ineffective		
31839	fit new engine oil level/ temp sensor	06/02/2016			06/02/2016	Equipment ineffective		
31757	Check Wiring for high engine oil temperature	30/01/2016			30/01/2016	Equipment ineffective		
31861	put quick hitch safety latch manual inspection card in machine	29/01/2016			29/01/2016	Equipment ineffective		
32234	SKINNERS - check wipers, found window not shut properly, shut	20/01/2016			20/01/2016	Equipment ineffective		
30916	Check hydraulic accumulator operation, u/s. Chase up new	15/12/2015			15/12/2015	Equipment ineffective		
30682	GENERAL: Error Code MA2303-04 Source E-ecu. Check wiring to	15/12/2015			15/12/2015	Equipment ineffective		
31027	Low pwer, fault with no 1-2-3 injectors wiring, check wiring,	15/12/2015			15/12/2015	Equipment ineffective		
30578	General: Slew motor oil low. Topped up slew box, 5006 Hours,	26/11/2015			26/11/2015	Equipment ineffective		
30627	Top up slew box. Recorded hour reading: 5006	24/11/2015			24/11/2015	Equipment ineffective		
30619	Top up slew box. Recorded hour reading: 4998	23/11/2015			23/11/2015	Equipment ineffective		
30359	URGENT: Seat wont adjust. Check and Lubricate seat slide's as	18/11/2015			18/11/2015	Equipment ineffective		
30502	Check over and organise parts modify hose for temporary	16/11/2015			16/11/2015	Equipment ineffective		
30084	URGENT: Seat won't adjust - Mbololaba. Check Seat Okay as per	13/11/2015			13/11/2015	Equipment ineffective		
30331	Check operation of seat, okay. Recorded hour reading: 4939	11/11/2015			11/11/2015	Equipment ineffective		
30345	Pck up mirpor fromsuncoast trucks and fit. Recorded hour	10/11/2015			10/11/2015	Equipment ineffective		
30338	Check operation of U.H.F radio, skinner to replace.	09/11/2015			09/11/2015	Equipment ineffective		
29965	Skinners - Fit music radio	27/10/2015			27/10/2015	Equipment ineffective		
29948	Repaired grease fitting top of dipper arm cylinder	27/10/2015			27/10/2015	Equipment ineffective		
29532	Fitted hand piece for UHF	24/10/2015			24/10/2015	Equipment ineffective		
29867	Check engine warning message coming up on dash, can't fault	21/10/2015			21/10/2015	Equipment ineffective		
29859	Pck up new battery isolator and fit "+" post on 1 battery	20/10/2015			20/10/2015	Equipment ineffective		
29897	Fill slew oil	20/10/2015			20/10/2015	Equipment ineffective		
29857	Battery isolator u/s	19/10/2015			19/10/2015	Equipment ineffective		
29522	Tracks Jumping. Refit track and adjusted tracks (Dave)	10/10/2015			10/10/2015	Equipment ineffective		
29636	Refitted L/H track and adjusted.	08/10/2015			08/10/2015	Equipment ineffective		
29267	Let track tension go, adjust tracks to correct tension	18/09/2015			18/09/2015	Equipment ineffective		
29229	Fit tracker, check electrical issue	10/09/2015			10/09/2015	Equipment ineffective		
28887	Replace all rollers, plant assessment, new engine oil filter	24/08/2015			24/08/2015	Equipment ineffective		
28345	Replaced fuel guage on tank	24/07/2015			24/07/2015	Equipment ineffective		
28073	Replaced lock bolts on hitch pin and check over for fuel leak	10/07/2015			10/07/2015	Equipment ineffective		
28051	Replace bucket teeth. Hour Reading: 4999 Hours.	09/07/2015			09/07/2015	Equipment ineffective		
28100	Repair oil leak on bucket cylinder pipe, look for fault with	08/07/2015			08/07/2015	Equipment ineffective		
28188	Skinner's Mbbile Auto Electrical. 1 x H4 globe, 134a gas, Air	16/06/2015			16/06/2015	Equipment ineffective		
28191	Skinner's Mbbile Electrical. 02/06/2015- Workshop. Check air	16/06/2015			16/06/2015	Equipment ineffective		
32261	repaired wiring for reverse alarm. adjusted front window wiper	09/03/2015			09/03/2015	Equipment ineffective		

Work Order	Description	Created	Created Hours	Created Km	Completed	Equipment	Item Status	Assigned To/Completed By
15278	500hr Service - Volvo Excavators	17/09/2012			17/09/2012		Routine service	
14108	1000hr Service - Volvo Excavators	28/03/2012			28/03/2012		Routine service	
13344	500hr Service - Volvo Excavators	14/08/2011			14/08/2011		Routine service	
13413	Start: 6/8 250hr service on Volvo Digger: Replace - oil filter,	07/08/2011			07/08/2011		Routine service	
12840	Start: 4/5/11 Order and replace bushes at the end of the stick	22/06/2011			22/06/2011		Equipment ineffective	
12720	Start: 31/5 Service due 500hr, change oil and filter and 2x	06/06/2011			06/06/2011		Routine service	
14065	1000hr Service - Volvo Excavators	06/06/2011			06/06/2011		Routine service	
13977	1000hr Service - Volvo Excavators	06/06/2011			06/06/2011		Routine service	
12532	Fit rear work lights or digger	18/03/2011			18/03/2011		Equipment ineffective	
12050	500hr service as per operations manual, replace a/c belt, oil	16/02/2011			16/02/2011		Routine service	
12011	500hr service as per operations manual replaced a/c belt	16/02/2011			16/02/2011		Routine service	
12049	replace oil hose going to oil filter housing	21/01/2011			21/01/2011		Equipment ineffective	
12048	refit lhs track, lower front window replaced, quick hitch hose	09/01/2011			09/01/2011		Equipment ineffective	