



Vehicle History Summary



Fleet #	QEM30
Registration	1GOI437
Make	Toyota
Model	HILUX
VIN / Chassis #	MR0KA3CD901216740
Build Date	2018

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-10722	06/10/2022			clean and wash	06.10.2022 - JS - Clean inside and out	QEM Group Australia Pty Ltd
R-10087	23/03/2022	0	0	ELECTRICAL, NO START	23.03.22 JA - Change battery and test for no starting. Found DPF blocked ad no voltage to injectors 23.03.22 PF - Wash QEM30 ready for Toyota	QEM Group Australia Pty Ltd
R-9763	11/01/2022	0	0	TURBO FAULT	Could not carry out DPF regen as turbo actuator faulting - No boost/power would not let regens complete Replaced turbo actuator, refit all removed and carried out DPF regeneration = DPF ok Over phone credit card payment made 13/12/2021 @11.30am by Dani with Sam in service dept at Toyota	Geraldton Toyota
T-689	11/11/2021	0	0	REPAIR	1x punture repair left rear used a 110tl paqтч 40psi admin workshop closed 11/11/21	QEM Group Australia Pty Ltd
S-874	11/11/2021	0	0	A - A	admin workshop closed 11/11/21	
R-9553	10/11/2021	0	0	CHECK ENGINE FAULT	admin workshop closed 10/11/21	
R-9554	10/11/2021	0	0	CHECK LIGHTS	admin workshop closed 10/11/21	
R-8791	06/09/2021	0	0	POWERSTEERING	COMPLETED	JA DIESEL
O-244	29/03/2021	0	0	Registration		Department of Transport
R-5103	11/02/2021			PARTS		Department of Transport
R-5106	11/02/2021			PARTS		Department of Transport
R-5105	11/02/2021			PARTS		Department of Transport
R-5104	11/02/2021			PARTS		Department of Transport
R-10758				AIRCON SWITCH		QEM Group Australia Pty Ltd

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-10755			143795	BROKEN TAIL LIGHT		QEM Group Australia Pty Ltd
R-10757			152841	REVERSE ALARM		QEM Group Australia Pty Ltd
S-1282			0	A - A	Service car (empty fuel tank and oil, change air/fuel filter and try to get running. - JS 25.08.22	QEM Group Australia Pty Ltd

Signed:

Name:

Date:
