

Fleet #	B21
Registration	346WVL
Make	Western Star
Model	4864FXB
VIN / Chassis #	5KKJBEDR5GPHM9576
Build Date	2016

Build Dat	te 2	2016					
Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer	
R- 23740	21/12/2022			Engine Light	Repair engine light - found soot level high and DPF zone 3 faults. Carried out forced regen then cleared faults	Pengelly	
S-15678	13/12/2022	1017036	0	B - 40,000 - 45,000	B service completed	Brisbane Workshop	
R- 23723	13/12/2022	1017036	0	Wiring	Repair wiring to LH bonnet light	Brisbane Workshop	
T-12258	12/11/2022	0	0	Pressure Check		Bridgestone- Townsville	
R- 23022	08/11/2022			shocks	R&R Broken Shockle and rubber	Western Truck Group	
R- 22556	05/10/2022			Engine Light, Wiper Blades	REMOVED THROTTLE BODY AND CLEANED FIT NEW WIPER BLADE AN WIPER ARM	Diesel Worx	
R- 22478	26/09/2022	980003		General Repairs	SEAL ROOF LIGHTS NEW BEACON COVERS	Brisbane Workshop	
R- 22640	14/09/2022	983450		Aerial, Oil	Drain oil to correct level and clean cap Replace 2 x aerials	Brisbane Workshop	
R- 22757	05/09/2022	978333		Bonnet Joint, safety check	"A "check completed Replace LH rear broke adjuster Tighten RH bonnet pivot bolt	Brisbane Workshop	
R- 23648	29/08/2022			Air Conditioner, Hub	Front R/H hub plug leaking R/H air cleaner extensions wobbles & shakes alot	Brisbane Workshop	
R- 22989	12/08/2022	964648		Gear Box, Mud Guards	R&R RH mudguard indicator and check gearbox level	Brisbane Workshop	
R- 23713	12/08/2022			Windscreen Repairs	Windscreen damaged Repair request 28051 - 12/08/2022	Alpha Glass Aust P/L	
R- 22917	11/08/2022			Eco Wind	Found W signal on Ecowind Remove covers, found idler pulley fallen off Remove and replace pulley	PRO TRUCK ELECTRICAL	
R- 22196	03/08/2022	959659		ECO WIND SERVICE, Service	COMPLETED 'B' SERVICE COMPLETED ECO WIND SERVICE	BRISBANE WORKSHOP	
R- 22260	26/07/2022	954386		WINDOW	R&R switch in power window drivers side	Pro Truck Electrical	

Number	Date !	Kms	Hours	Туре	Repairer Notes	Repairer
R- 21725	01/07/2022	942621		RADIO	LOOKED FOR RADIO FAULT NO FAULT FOUND	PROTRUCK ELEOTRICAL
R- 21719	01/07/2022			Heater	CABLE DISCONNECTED FROM HEATER TAP - RECONNECTED	PRO THE CON ELECTRICAL
R- 21704	01/07/2022			Air Conditioner	REPLACED LEAKING #8 HOSE, VACCED DOWN AND GASSED.	PRO TRUCK ELECTRICAL
R- 21739	29/06/2022	93675		HUB SEAL	R&R LEAKING HUB SEAL RH SIDE STEER	Western Truck Group
R- 21742	23/06/2022	942620		General Repairs	GENERAL REPAIRS AS PER ATTACHED SCANNED DOCUMENT - 29206	BRISBANE WORKSHOP
R- 21859	23/06/2022	937486		HUB CAP	R&R HUB CAP	RGM Maintenance Pty Ltd
R- 21769	16/06/2022	938175		Clutch Adjustment, Horton Fan	NEW HORTON FAN CLUTCH ADJUSTMENT	BRISBANE WORKSHOP
FI- 21906	10/06/2022	935152		Clutch Adjustment, HUBS, Lights, Turntable	L/H REAR TAIL LIGHTS CLUTCH ADJUSTMENT TURNTABLE ADJUSTMENT CHECK FRONT HUBS/BEARINGS/LEVELS	BRISBANE WORKSHOP
R- 21401	09/06/2022			Lights	R&R BLOWN FUSE & WIRE IN LOADING LIGHTS	PRO TRUCK ELECTRICAL
R- 21783	07/06/2022	932386	0	Marker Lights	R&R 2 tank marker lights	Brisbane Workshop
S-14857	07/06/2022	932386	0	C - Annual	C service completed	Brisbane Workshop
T-11239	26/05/2022	0	0	FIT	4 X 11003587 - 11R22.5 148/145L FS FD664 FIT POS 9,10,11,12	BRIDGESTONE
R- 21410	26/05/2022	926571		Air Conditioner, Engine Cover	REPAIR ENGINE COVER; CHECK CABIN AC FILTERS	BRISBANE WORKSHOP
T-11239	26/05/2022	0	0	Pressure Check		BRIDGESTONE
R- 21972	25/05/2022	926551		General Repairs	GENERAL REPAIRS AS PER ATTACHED SCANNED DOCUMENT - 29203	BRISBANE WORKSHOP
S-14711	20/05/2022	923233	0	B - 40,000 - 45,000	B service completed	Brisbane Workshop
R- 21340	20/05/2022	923233	0	Eco Wind, INDICATOR, Mud Guards	R&R LH bullbar indicator Fixed leaking fuel filter on eco wind Tightened mud guard brackets	Brisbane Workshop
R- 21944	19/05/2022	923232		Air Conditioner, INDICATOR, Mud Guards	AIR CON LEAKING L/H BULLBAR INDICATOR NOT WORKING MUDGUARD SUPPORT ARMS LOOSE	BRISBANE WORKSHOP
R- 21221	19/05/2022	917890		BATTERIES, ISOLATOR	Replaced faulty cab power isolator Cleaned up battery terminal	Pro Truck Electrical
R- 21967	03/05/2022	912621		General Repairs	GENERAL REPAIRS AS PER ATTACHED SCANNED DOCUMENT - 41948	BRISBANE WORKSHOP

Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer
R- 21257	29/04/2022	906715		Grease & Safety Check		Brisbane workshop
R- 21228	22/04/2022	906175		RELAY, Wiring	Repaired driving light wiring Replaced faulty relay Repaired auto greaser wiring	Pro Truck Electrical
R- 21955	21/04/2022	906714		Bracket, ECO WIND SERVICE, Steering	BONNET TO CHASSIS BRACKET STARTING TO WANDER TO THE LEFT ECO WIND SERVICE	BRISBANE WORKSHOP
R- 21317	19/04/2022	900284		Exhaust	Cleaned exhaust pipe and fitted new clamp & seal	Penske
R- 21059	14/04/2022	896017		Oil Leak	INSTALLED NEW APT GEARBOX SEE ATTACHED INV DTCST10346	Penske
R- 21238	05/04/2022	914043		ECO WIND SERVICE	Service & tune eco wind	Brisbane Workshop
R- 20977	31/03/2022			General Repairs	GENERAL REPAIRS AS PER 41946	BRISBANE WORKSHOP
R- 20681	30/03/2022	896694		Breakdown Repairs	OIL LEAK - FOUND APT GEAR BOX LEAK ADVISED TOW TRUCK	Penske
R- 20826	17/03/2022	888109		Auto Greaser	R&R FUSE HOLDERS	PRO TRUCK ELECTRICAL
R- 21273	16/03/2022	888100		Tune Up	Perform overhead adjustment to all valves & jakes	Brisbane Workshop
T-11583	03/03/2022	0	0	FIT	2 X 11001553 -295/80R22.5 152/148M BS R150 FIT POS 1,2	BRIDGESTONE
S-14376	02/03/2022	888100	0	B - 40,000 - 45,000	B service completed See attached Job card TB1068	Brisbane Workshop
R- 20203	28/02/2022			ELECTRICAL FAULT	REPAIR WIRING TO FUEL TANKS	Pro Truck Electrical
R- 20524	04/02/2022			BATTERIES, clearance lights	R&R START BATTERIES R&R CLEARANCE LIGHTS	NQ Goalectrix
R- 20525	13/12/2021	849760		RADIATOR HOSE	R&R RADIATOR HOSE	RGM Maintenance Pty Ltd
R- 20176	10/12/2021			Electrical Fault	R & R FAULTY SOCKET ON TRAILER	NQ Coolectrix
S-14214	27/11/2021	879326	0	B - 40,000 - 45,000	B service completed See attached Inv 400	Charlies Truck N Repairs
R- 20526	04/11/2021			Lights	R&R PARK LIGHTS, SIDE LIGHTS	NQ Coolectrix
S-14212	18/08/2021	814300	0	B - 40,000 - 45,000	B service completed	Charlies Truck N Repairs
S-13588	15/07/2021	813000	0	B - 40,000 - 45,000	B service completed	Pengelly
S-13592	19/06/2021	812276	0	B - 40,000 - 45,000	B service completed	Charlies Truck N Repairs
R- 17903	19/05/2021			Clearance Light	R&R clearance light Repair wiring to LH tail light	NQ Coolectrix

Number	Date	Kms	Hours -	Туре	Repairer Notes	Repairer :
T-10364	21/04/2021	797480	0	FIT	2 X fit 295/80R22.5 152/148M BS R154 Pos 1, 2	BRIDGESTONE
T-10364	21/04/2021	797480	0	RE TORQUE	2 X re torque Pos 1, 2	BRIDGESTONE
T-10364	21/04/2021	797480	0	Pressure Check		BRIDGESTONE
T-10364	21/04/2021	797480	0	FIT	8 X fit 11R22.5 146/143L BS M766 Pas 5, 6, 7, 8, 9, 10, 11, 12	BRIDGESTONE
T-10332	26/03/2021	786949	0	FIT	2 x fit r/outs Pos 10, 11	BRIDGESTONE
R- 17501	11/03/2021	776672		Lights	Locate & repair electrical fault in LHS head light & blinker	CENTRAL WEST DIESEL
R- 17393	09/03/2021	775437		Air Bag	R&R air bag	DieselWorx
S-13103	26/02/2021	768387	0	B - 40,000 - 45,000	B service completed	Pengelly
R- 17233	26/02/2021	768387	0	Air Filters, INDICATOR, Wiper Blades	Replaced LHS indicator on guard Replaced wiper blades Replaced air filters	Pengelly
R- 17029	29/01/2021			Wiring	Repair wiring to fuse holder	Pro Truck Electrical
R- 17030	27/01/2021	748131		General Checkover		Brisbane Workshop
H- 16914	18/01/2021			Fuse	R&R faulty luse to indicators	Gepps Cross Auto Elec
R- 16417	01/12/2020	731977		LIGHT BAR, Mud Guards, Turntable	Replace RHR mudguard & both RHR mudguard poles Straighten RHR light bar & chassis mounts R&R bent t/table jaw & other worn parts Check & adjust t/table	Brisbane Workshop
R- 16418	27/11/2020	727619		Cooling System, Fault Codes	DPF Ash measure request-reset accumulators to correct setting R&R thermostat & bottom radiator hose	Penske
R- 16419	23/11/2020	731556		ELECTRICAL BASE	R&R female electrical base at back of cab	Brisbane Workshop
R- 16420	17/11/2020	728164		FUSES	PM to trailer-no side lights - added some fuses R&R electrical lead	Brisbane Workshop
R- 16182	16/11/2020	728164	0	ECO WIND SERVICE, Fan Belt, RADIATOR	Replaced both fan belts on engine Serviced Eco Wind Cleaned inside screen Quick blow out of radiator Took to Detroit-check light on	Brisbane Workshop
S-12766	16/11/2020	728164	0	B - 40,000 - 45,000	B service completed	Brisbane Workshop
S-12712	10/11/2020	722989	0	C - Annual	C service completed	Brisbane workshop
R- 16422	03/11/2020	708349		Air bag fitting, Clutch Adjustment, Tank Strap	Adjust clutch R&R front drive air bag fittings R&R broken tank strap	Brisbane Workshop
R- 16426	26/10/2020	714713		Air Bag	Replace both front air bags	Brisbane Workshop
R- 16421	20/10/2020			Circuit Break	R&R circuit breaker to driving lights	PRO TRUCK ELECTRICAL

R- 16424	19/10/2020	710652		mudguards	Tighten all rear mudguards	Brisbane Workshop
R- 16425	13/10/2020	706560		Lights	Supply & fit relay for spotlights	
R- 16423	13/10/2020	706561		Air Intake	R&R broken clamp for LH air intake pipe	Brisbane Workshop
T-9365	07/10/2020	703177	0	Pressure Check		BRIDGESTONE
T-9355	07/10/2020	0	0	Rotate		BRIDGESTONE
R- 15786	06/10/2020	703176		Safety Inspection, Wiring	Safety check Repair marker light wiring	Brisbane workshop
R- 15789	30/09/2020	699954		INTERCOOLER	R&R LH intercooler hose & tightened all intercooler clamps	HI TORQUE
R- 15787	29/09/2020	699122		Electrical lead	R&R electrical lead for lights	Brisbane workshop
S-12475	31/08/2020	685996	0	B - 40,000 - 45,000	B service completed	Brisbane Workshop
R- 15451	31/08/2020	685996	0	DIFFERENTIAL, Mud Guards & Flaps	R&R front diff torque rod Weld/repair RHF drive mus guard Replace two broken RHF drive mudguard mounting brackets Straighten & tighten RH drive mounting posts Replace both rubber mudflaps between drive guards Fabricate 4 X checker plate hold downs (Paddy)	Brisbane Workshop
R- 15785	26/08/2020			Eco Wind	Weld broken frame on Eco wind	Crank IT
R- 15782	07/08/2020	672953		Clutch Adjustment, mudguard, Safety Inspection	Safety check Adjusted clutch Tighten mudguard brackets	Brisbane workshop
R- 15784	22/07/2020	669364		Air Leak, mudguard	Check truck for air leak (Paddy/Sam) Tighten loose mudguards (Paddy)	Brisbane workshop, Crank IT Mechanical
R- 15783	14/07/2020	660810		Turbo Timer	R&R turbo timer	Pro Truck Electrical
T-8725	13/07/2020	664252	0	FIT	2 X fit 295/80R22.5 152/148M BS R154 Pos 1, 2	BRIDGESTONE
R- 14875	29/06/2020			Air Leak	Repaired air leaks in air bags.	Brisbane Workshop
R- 14922	11/06/2020	653130		Air Conditioner, Belts, Englne Fan	Checked AC belt and main fan belt for squeaking nose. All belts in good condition. No bearing faults Checked engine fan - no faults found.	Brisbane Workshop
T-8479	09/06/2020	653043	0	Pressure Check		BRIDGESTONE
T- 84 88	09/06/2020	653043	0	Pressure Check		BRIDGESTONE

Number Date

Kms

Hours

Type

Repairer

Repairer Notes

Number	Date: 19	Kms	Hours	Туре шта далыны	Repairer Notes	Repairer
R- 14926	09/06/2020	653043		Lights	Replaced right hand indicator to bullbar.	Brisbane Workshop
R- 14663	03/06/2020	0	0	Bracket, Eco Wind, Lights, Walk Plate	Serviced eco wind. Replaced LH rotating beacon light. Replaced RH indicator on bullbar. Replaced 2 x walk plate hold down brackets. Replaced missing bolt on stainless bracket holding air clean housing to visor.	Brisbane workshop
S-12121	03/06/2020	0	0	B - 40,000 - 45,000	B Service completed	Brisbane Workshop
R- 14906	30/04/2020			Clamp, COOLANT PUMP, CYLINDERS, OIL FILTER, Tune Up, WATER PUMP	Found leaking from #2 cylinder. Liner had a pin hole through pitting and all other liners also pitted. Block also pitted in all bores - cleaned out block and filled up with devcon. Assembled kits with new liners, rings and pistons, removed 6 piston cooler nozzles, cleaned pump and bridge, reassembled and refit pump and sump with new gaskets & bolts. Cleaned out and fit intake manifold, refit cylinder head and tightened to torque, refit cambox etc and carried out engine tune. Fit new water pump as also corroded. Filled engine with fresh oil and coolant. Replaced oil filter. Replaced turbo outlet clamp.	Penske
R- 14407	20/04/2020	638974		Invertor	Mounted invertor box, wired in and ran wire to switch. Set timer on relay and checked operation.	PRO TRUCK ELECTRICAL
R- 14817	18/04/2020	638773		Front End, Grease, RUBBER	Greased. Checked front end rubbers.	Brisbane Workshop
R- 14128	08/04/2020			fights	ALL OKAY	PRO TRUCK ELECTRICAL
R- 14102	07/04/2020	631913		Engine	PICK UP TRUCK FROM PENSKE AFTER ENGINE REBUILD. CHECK OVER ENGINE AND TIGHEN EXHAUST MANIFOLD BOLTS.	Crank IT
R- 14142	30/03/2020	631864		Cooling System, Hose Clamps	PRESSURE TEST COOLING SYSTEM TIGHTEN BOTTOM HOSE CLAMPS	BRISBANE WORKSHOP
R- 13971	24/03/2020	628615		Safety Inspection	A CHECK	BRISBANE WORKSHOP
R- 13979	14/03/2020	625200		Coolant, RADIATOR	ABOVE WORKS HAVE BEEN COMPLETED	PRO TRUCK ELECTRICAL
R- 13952	10/03/2020	621362		Lights, Mirror	TIGHTEN BOTH L/H AND R/H MIRRORS AND ASSEMBLY REPLACE BOTH L/H AND R/H HIGH BEAM BULBS REPLACE BOTH L/H AND R/H LOW BEAM BULBS	BRISBANE WORKSHOP
R- 13707	10/03/2020	611897		Dash Cam, Lights	Replaced blown RH bulb headlight for low beam. Fit dash cam.	Brisbane Workshop

Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer
R- 13943	02/03/2020	616388		leak, Pressure Test	PRESSURE TEST FOUND LEAK FROM HOSE- TIGHTEN HOSE CLAMP- NOW OK FOUND LEAK IN RADIATOR- TIGHTEN ALL NUTS AND BOLTS ALONG EDGE OF TOP TANK- NOW OKAY TESTED COOLANYT LEVELS, TESTED OKAY	BRISBANE WORKSHOP
R- 13898	28/02/2020	610130		Coolant, Coolant Hose	R&R leaking coolant hoses Drained coolant & replaced with new	Westar Trucks
R- 13747	21/02/2020	610130		Coolant Hose	Travelled to breakdown and inspected vehicle. Found 1 x hose split and leaking and another leaking. Replaced both hoses and replaced coolant.	Westar Trucks
R- 13694	19/02/2020	607860		Cooling System, Engine	Replaced thermostate, aged hoses and clamps. Cleaned oil coolant module housing, fit new oil cooler with new seals, refit OCM with new gasket. Prime lubrication system, filled cooling system with water and flushing agent, run engine as per flushing recommendations. Refilled with fresh coolant.	Penske
R- 13412	10/02/2020	608319	0	ECO WIND SERVICE	Eco wind service	Brisbane workshop
S-11679	10/02/2020	608319	0	B - 40,000 - 45,000	B service completed	Brisbane workshop
R- 13984	04/02/2020	606277		Horton Fan	Full strip & clean horton fan hub assembly Full reassemble with new parts	Diesel Worx
H- 14823	21/01/2020	599193		Air Leak	Repaired air leak.	Brisbane Workshop
R- 13260	19/12/2019	570722		Flywheel	Clean mating surfaces, inspect & found sump & timing case mating surfaces fretted Swap parts to new timing case & fit with new gasket, torque to Fit oil pickup with new :O: rings Fit new sump	Penske
H- 12981	06/12/2019	576821		air bags, Height Control Valve	R&R both cab air bags R&R cab height control valve rubber	Brisbane Workshop
R- 12996	02/12/2019	574480		Clutch Adjustment	Adjust clutch	Brisbane Workshop
T-7093	26/11/2019	0	0	RE TORQUE	6 X retorque Pos 1,2,5,8,9,12	BRIDGESTONE
R- 12735	22/11/2019	570722		FLY WHEEL	Machine fly wheel	
T-7050	19/11/2019	571153	0	Pressure Check		BRIDGESTONE
T-7047	19/11/2019	571153	0	Balance, FIT	2 X fit 295/80R22.5 152/148M BS R156 Pos 1, 2 8 X fit 11R22.5 146/143L 16BS M766 Pos 5, 6, 7, 8, 9, 10, 11, 12	BRIDGESTONE

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-11397	18/11/2019	571153	0	C - Annual	G service completed	Brisbane Workshop
R- 12750	18/11/2019	571153	0	Air Intake, CLUTCH BRAKE, Idler Bearings	Align LH intake stack & tighten clamp Small crack evident in exhaust Y piece RHS clutch fork pivot bolt head broken off	Brisbane Workshop
R- 12688	11/11/2019	567482	0	ECO WIND SERVICE	Serviced Eco Wind	Brisbane Workshop
S-11372	11/11/2019	567482	0	B - 40,000 - 45,000	B service completed	Brisbane Workshop
R- 12482	23/10/2019			Lights	Supply & fit 1 X H4 headlight globe	AB AUTO ELECTRICS
R- 12112	30/09/2019			Air Cleaner, Grill, Light, WINDSCREEN WIPER	Re-fit chrome ring around LH headlight. Tighten front grill Tightened LH air cleaner hat. Replaced both windscreen wipers.	Brisbane Workshop
R- 12020	17/09/2019	541240		Bonnet, RADIATOR	Blow out radiator, check coolant level - ok Fitted new bonnet bracket	Brisbane Workshop
T-6494	19/08/2019	526773		wheel alignment		FORTUNA STRAIGHTLINE ENG
T-6504	19/08/2019	526763		FIT		BRIDGESTONE
R- 11799	19/08/2019	526763		EGR	REMOVE & BLOW OUT EGR SENSOR REFIT	Brisbane Workshop
R- 11760	12/08/2019	522585		Lights	REPAIR WIRING ON LH MUDGUARD INDICATOR	Brisbane Workshop
S-10970	12/08/2019	522585		B - 40,000kms	B SERVICE COMPLETED	Brisbane Workshop
R- 11760	12/08/2019	522585		General Checkover	BLOW OUT AIR CLEANERS & RADIATOR	Brisbane Workshop
R- 11560	22/07/2019	511525		Lights	REPLACED RH HEADLIGHT BULB REPLACED RH PARKER GLOBE	Brisbane Workshop
T-6254	15/07/2019			Wheel Nut Tensioned		BRIDGESTONE
R- 11432	08/07/2019	507427		Guard	LHS quarter guard not lining up with bonnet. Looseneed brackets and reposition guard and tighten brackets.	Brisbane Workshop
R-	08/07/2019	507427		Radiator and Cooling	Driver complaining of	Brisbane
11432				System	overheating.Clean out radiator as best as possible without removing from	Workshop
					Truck. Check coolant level-ok, Check	
					for coolant leaks-more found. Check that engine fan engages using manual	
					switch- OK	
T-6211	08/07/2019	507409		Puncture		BRIDGESTONE
R-	28/06/2019	496931		Eco Wind	Supply & install new base on unit Evacuate & regas Run system &	Briskair

Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer
R- 11131	10/06/2019	483946		General Repairs	Checked code, and confirm ash measure request. Remove Doc and completed measure. In spec, re assemble with new spherical gaskets. Reset counter, wash and return to service.	Penske
T-6040	05/06/2019	491984		Strip & Fit	Scrap x1	BRIDGESTONE
T-6039	05/06/2019	491984	:	Pressure Check		BRIDGESTONE
R- 11139	22/05/2019			Light	Checked charging fault on truck, found supply cable to alternator left off when new starter fitted recently by 3rd party. Reconnected and tested ok.	A1 Auto Electrical
R- 10919	20/05/2019	483940		Bonnet	REPLACED BROKEN RHS BONNET SPRING REPLACED BOTH BONNET LOCATING RUBBER PADS REPLACED BROKEN LHS BONNET LATCH BRACE	Brisbane Workshop
R- 10919	20/05/2019	483940		Air Bag	REPLACED LEAKING REAR DRIVE RH AIR BAG	Brisbane Workshop
R- 10919	20/05/2019	483940		Cross Member	TIGHTENED ALL CROSS MEMBER BOLTS	Brisbane Workshop
S-10580	20/05/2019	483940		B - 40,000kms	B SERVICE COMPLETED	Brisbane Workshop
R- 10861	20/05/2019	483490		Starter Motor	SUPPLY & FIT NEW STARTER MOTOR	PRO TRUCK ELECTRICAL
R- 11004	18/05/2019			Fire Extinguisher	TEST & TAG-THS-ABE-FIREWORLD- 4.5KG-PASS	Pengelly
R- 11004	18/05/2019			Fire Extinguisher	TEST & TAG-RHS-ABE-MEGAFIRE- 1KG-PASS	Pengelly
R- 10824	13/05/2019	480505		Light	REPLACED HEADLIGHT BULB	Brisbane Workshop
R- 10813	13/05/2019			Starter Motor	TIGHTENED LOOSE TERMINALS ON STARTER MOTOR	PRO TRUCK ELECTRICAL
R- 10824	13/05/2019	480505		OIL LEAK	ONLY COMING OUT OF ENGINE BREATHER	Brisbane Workshop
R- 10560	15/04/2019	466219		Marker Lights	Replace 3 chrome marker light covers. Landstock	
R- 10560	15/04/2019	466219		Electical	Replace both male and female electrical connections on susie coil. Con stock check susie coil for faults. Non found.	
R- 10560	15/04/2019	466219		Windscreen	Tighten R.H windscreen wiper arm.	
R- 10227	18/03/2019	450627		Light	REPLACE BLOWN PARK LIGHT BULB CHECKED ALL LIGHTS	Brisbane Workshop
S-10220	08/03/2019	447203		B - 40,000kms	B service completed	Brisbane Workshop

Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer
H- 10008	08/03/2019	447203		HUB SEAL	Left hand hub seal, remove tyre, brake drums amd brake shoes and hub.	Brisbane Workshop
					Clean wheel bearings. Fit hub seal. Fit hub, adjust wheel bearings, reassembled with new brake shoes.	
R- 10008	08/03/2019	447203		Eco Wind	Change oil, fiel, engine fuel, air filters	Brisbane Workshop
R- 10008	08/03/2019	447203		Air Filters	Replaced air filters	Brisbane Workshop
R- 10229	04/03/2019	442500		Air Leak	FIND & REPAIR AIR LEAKS	Brisbaпе Workshop
R- 10029	04/03/2019	444965		Air Bag	Replace left hand cab air bag replace L/R hand air bag fitting	Brisbane Workshop
R-9982	22/02/2019	438626		Wiper Blades	Fit new wiper blades	Brisbane Workshop
A-9982	22/02/2019	438626		Air Fitting + Hoses	Replaced leaking air fittings on the firewall coming out of the foot broke valve.	Brisbane Workshop
T-5185	15/02/2019	434531		FIT	1 X SCRAP	BRIDGESTONE
R-9832	07/02/2019	429772		ECO WIND SERVICE	ECO WIND SERVICE	Brisbane Workshop
R-9832	07/02/2019	429772		Air Leak	COULDN'T FIND AIR LEAK	Brisbane Workshop
T-5070	01/02/2019	426375		Pressure Check		BRIDGESTONE
T-5066	01/02/2019	426375		Rotate		BRIDGESTONE
R-9559	23/01/2019	422829		Hub Caps	TIGHTEN BOTH STEER H/CAPS & CLEAN UP FILL UP WITH OIL	Brisbane Workshop
R-9559	23/01/2019	422829		Eco Wind	ECOWIND DOOR	Brisbane Workshop
R-9559	23/01/2019	422829		Lights	REPLACE BOTH SPOTLIGHTS ON TOP OF BULLBAR & WIRE IN REPLACE LH LOW BEAM BULB	Brisbane Workshop
R-9396	09/01/2019	415414		CIRCUIT BREAKER	CIRCUIIT BREAKERS FOR BULL LIGHTS FULL OF WATER R&R CIRCUIT BREAKERS-TESTED, OK	PRO TRUCK ELECTRICAL
H-9188	17/12/2018	408091		Anderson Plug	REPLACED ANDERSON PLUG & SUPPLIED ANDERSON LEAD TO	Brisbane Workshop
S-9948	17/12/2018	408091		B - 30-35kms	DRIVER B SERVICE COMPLETED	Brisbane Workshop
R-9188	17/12/2018	408091		Lights	CHECK ISSUE WITH SPOT LIGHTS INTERMITTANTLY FLICKERING, COULD NOT REPLICATE THE FAULT	Brisbane Workshop
R-9188	17/12/2018	408091		Air Horn	REPLACED MISSING AIR HORN COVER-RH INNER	Brisbane Workshop

Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer
R-9188	17/12/2018	408091		AIR VENT	R&R RHS DASH AIR VENT	Brisbane Workshop
R-9131	07/12/2018	404001		WINDOW	RH WINDOW WON'T GO ALL THE WAY UP WINDOW REGULATOR FAILED R&R WINDOW REGULATOR TESTED-OK	Brisbane Workshop
R-8718	12/11/2018	392296		Lights	REMOVED BROKEN LH OUTER SPOTLIGHT & BOTH INNER SPOTLIGHTS FIT 1 SPOTLIGHT FROM INNER TO LH OUTER FIT LIGHT BAR TO REPLACE INNER SPOTLIGHTS FABRICATED BRACKETS & REMOVE WITING PLUG	Brisbane Workshop
S-9745	12/11/2018	392296		C - Annual	C SERVICE COMPLETED	Brisbane Workshop
A-8718	12/11/2018	392296		Power Steering	REPLACED POWER STEERING OIL & OIL FILTER & AIR DRYER FILTER	Brisbane Workshop
I-1751	12/11/2018				C SERVICE COMPLETED	Brisbane Workshop
R-8696	05/11/2018	388753		Lights	FITTED NEW BOLT, SPRING WASHER & FLAT WASHER TO LH SPOT LIGHT BOTTOM MOUNT	Brisbane Workshop
R-8354	22/10/2018			Starter Motor	R&R FAULTY STARTER MOTOR	PRO TRUCK ELECTRICAL
R-8477	19/10/2018	380746		RADIO	Checked radio - no fault found.	Brisbane Workshop
R-8477	19/10/2018	380746		Suzi Coil	Checked electrical suzi coil - no fault found.	Pengelly
R-8352	18/10/2018	380746		RADIO	REPAIRED RADIO LOOSE CONNECTIN	Brisbane Workshop
R-8352	18/10/2018	380746		S⊔zi Coil	REPLACED SUZI COIL	Brisbane Workshop
T-4599	03/10/2018	373415		FIT	5 X SCRAP	BRIDGESTONE
R-8204	03/10/2018	373415		Air Leak	Repaired numerous air leaks	Crank IT Mechanical
R-8194	02/10/2018	359913		Eco Wind	Repaired eco wind mount.	Brisbane Workshop
R-7912	17/09/2018	367919		Bonnet	Replaced LH bonnet spring	Brisbane Workshop
S-9445	17/09/2018	367 919		B - 18-22km	B Service completed	Brisbane Workshop
R-7912	17/09/2018	367919		Suzi Coil	Repaired suzí coils	Brisbane Workshop
R-7912	17/09/2018	367919		Deck Plate	Made up & fitted rear deck holding plate.	Brisbane Workshop

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-7912	17/09/2018	367919		Lights	Replaced missing rotating light cover Replaced LED indicator LH side of bonnet Repaired LH rear tank lights (bottom)	Brisbane Workshop
R-7912	17/09/2018	367919		Wiper Blades	Replaced wiper blades	Brisbane Workshop
T-4515	12/09/2018	363876		FIT		BRIDGESTONE
T-4502	12/09/2018	363876		Pressure Check		BRIDGESTONE
T-4463	11/09/2018	363888		wheel alignment		FORTUNA STRAIGHTLINE ENG
R-7964	10/09/2018			Fuse	SUPPLY & FIT FUSE FOR TRAILER LIGHT OUTPUT	CONSOLIDATED DIESELS
R-7963	08/09/2018			Air Leak	REMOVE FRONT LH MUD GUARD & REPAIR LEAK	CONSOLIDATED DIESELS
R-7871	04/09/2018			Starter Motor	CHECK OUT STARTING FAULT	PRO TRUCK ELECTRICAL
R-8216	29/08/2018			AIR LEAKS	Repaired air leaks in seat.	Brisbane Workshop
R-8216	29/08/2018			Eco Wind	Eco wind mounts	Brisbane Workshop
T-4338	22/08/2018			Pressure Check		BRIDGESTONE
T-4338	22/08/2018			FIT	2 X SCRAP	BRIDGESTONE
T- 435 8	17/08/2018			FIT	2 X SCRAP	BRIDGESTONE
T-4358	17/08/2018			Pressure Check		BRIDGESTONE
R-7659	30/07/2018	339242	·	Air Leak	REPAIR AIR LEAKS	Brisbane Workshop
R-7659	30/07/2018	339242		SEAT	REPAIR AIR LEAKS IN SEAT	Brisbane Workshop
R-7659	30/07/2018	339242		Lights	REPAIRED LIGHTS	Brisbane Workshop
П-7659	30/07/2018	339242		Overhead Adjustment	PERFORM OVERHEAD ADJUSTMENT ON ALL VALVES & JAKES (TUNE UP)	Crank IT Mechanical
R-7486	27/07/2018	339242		Air Leak	LOOK FOR AIR LEAKS-NONE	Brisbane Workshop
R-7486	27/07/2018	339242		Clamp	MAKE UP CHASSIS PLATE CLAMP	Brisbane Workshop
R-7486	27/07/2018	339242		Wiring	REPAIR WIRING ON RH SIDE FUEL TANK MARKER LIGHTS	Brisbane Workshop
T-4088	20/07/2018	335633		Puncture		BRIDGESTONE
R-7256	06/07/2018	328319		Checker Plate	REPLACED 1 MISSING BOLT ON WALK PLATE	Brisbane Workshop
R-7256	06/07/2018	328319		Electric Plug	REPLACED 7 PIN TRAILER PLUG	Brisbane Workshop

Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer
R-7256	06/07/2018	328319		SEAT	REPAIRED SEAT AIR LEAK	Brisbane Workshop
S-9151	06/07/2018	328319		B - 18-22km	B SERVICE COMPLETED	Brisbane Workshop
R-7231	22/06/2018	320000		Radiator and Cooling System	REPAIR RADIATOR SHROUD	Brisbane Workshop
R-7231	22/06/2018	320000		Walk Plate	REPAIR WALK PLATE	Brisbane Workshop
R-7231	22/06/2018	320000		Coolant	REPLACE TURBO ACTUATOR LEAKING COOLANT	Penske
R-7103	22/06/2018	320709		Coolant	FOUND COOLANT LEAKING FROM EGR ACTUATOR WELSH PLUG, REMOVED COOLANT DOWNLOAD REPORTS, REPLACE ERG ACTUATOR & BRACKET & PIPES FILL COOLENT, START TRUCK, CHECK FOR LEAKS & COOLANT LEVEL-OK RADIATOR TOP TANK ALSO COOLANT LEAK	Penske
R-7105	18/06/2018	317424		Signage	REFIT ROADTRAIN SIGN TO BULLBAR	Crank IT Mechanical
R-7105	18/06/2018	317424		Lights	R&R HEADLIGHT BULB	Crank IT Mechanical
R-7105	18/06/2018	317424		Exhaust	STRAIGHTEN & TIGHTEN AIR INTAKE STACKS	Crank IT Mechanical
R-7038	14/06/2018	316644		Lights	FIXED LIGHTS	Crank IT Mechanical
R-7038	14/06/2018	316644		Signage	REATTACHED FRONT SIGN ON BULLBAR	Crank IT Mechanical
R-7038	14/06/2018	316644		SEAT	REPLACED SEAT	Brisbane Workshop
R-7038	14/06/2018	316644		Air Intake	ADJUSTED & TIGHTENED AIR INTAKE PIPES	Crank IT Mechanical
T-3833	03/06/2018	309437		Pressure Check		Brisbane Workshop
T-3833	03/06/2018	309437		Strip & Fit		Brisbane Workshop
H-6757	30/05/2018	307408		Chassis	MAKE UP CHASSIS PLATE MOUNTING PLATE	Brisbane Workshop
R-6757	30/05/2018	307408		Eco Wind	REPLACE MOUNTING BOLT IN ECO WIND	Brisbane Workshop
R-6757	30/05/2018	307408		Hub Caps	REPLACE ALL 4 HUB CAPS ON DRIVE	Brisbane Workshop
R-6757	30/05/2018	307408		Roof	UNDO ROOF LIGHTS & SILASTIC AROUND ALL MOUNTING SCREWS & WIRE HOLES SILASTIC AROUND BEACON WIRE HOLES & BEACON MOUNTS	Brisbane Workshop

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-6757	30/05/2018	307408		Turntable	CHECK ADJUSTMENT & FEET BUSHES ON TURNTABLE-OK	Brisbane Workshop
R-6680	15/05/2018	297074		IDLER PULLEY	NOISE IN ENGINE BAY, INSPECTED BELTS/PULLEYS FOUND TOP IDLER PULLEY A LITTLE PLAY, REPLACED IDLER PULLEY & BOTH FAN BELTS STARTED &N CHECK	Brisbane Workshop
R-6680	15/05/2018	297074		Check Over	CHECKED OIL & WATER WHILE BONNET WAS UP	Brisbane Workshop
R-6635	08/05/2018	293684		Eco Wind	SERVICE ECO WIND	Brisbane Workshop
R-6524	24/04/2018	285553		Auto Greaser	Adjusted auto greaser settings.	Brisbane Workshop
R-6524	24/04/2018	285553		Battery	Checked batteries - all tested okay.	Brisbane Workshop
R-6524	24/04/2018	285553		Bracket	Straightened LHS tail light bracket. Fabricated 1 walk plate bracket, fit bracket, stragiht walk plate and	Brisbane Workshop
					tightened all brackets. Removed LHS front fuel tank bottom step, straightened step brackets & refit.	
R-6524	24/04/2018	285553		Air Leak	Checked for air leaks - no air leaks found. Truck held pressure okay.	Brisbane Workshop
R-6548	16/04/2018	281446		Gasket	Removed front caps, added new gasket + moreys oil addcated to front hub oil and fitted 2 x new plug caps	Brisbane Workshop
R-6395	09/04/2018	277871		Hub Caps	Tightened steer hub cap cover bolts. Replaced O Ring in steer hub cap drive bungs.	Brisbane Workshop
T-3570	27/03/2018			New		Brisbane Workshop
T-3476	27/03/2018			wheel alignment		FORTUNA STRAIGHTLINE ENG
T-3480	24/03/2018	268722		wheel alignment		FORTUNA STRAIGHTLINE ENG
R-6330	19/03/2018	266204		SEAT	REMOVE SEAT TO GET BASE REPAIRED & CHECKED OVER BY SEATS R US RE-FIT REPAIRED SEAT	Brisbane Workshop
R-6330	19/03/2018	266204		KING PINS	CHECK OUT FRONT END FOUND MOVEMENT IN LH KING PIN REPLACE LH & RH KING PINS	Brisbane Workshop
R-6180	01/03/2018	258121		Suspension	CHECK REAR SUSPENSION-ALL OVER ROAD CHECK DRIVE LINE CHECK FRONT END OUT-LH KING PIN NEEDS REPLACING REPLACE ROSE JOINT & BOLT	Brisbane Workshop

Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer
R-6180	01/03/2018	258121		Fuel Tank	MAKE NEW BRACKET FOR LH FUEL TANK STEP	Brisbane Workshop
T-3302	19/02/2018	251507		Pressure Check		Brisbane Workshop
R-6580	19/02/2018	251507		STEPS	Adjusted LH front bottom step replaced missing top LH step	Brisbarie Workshop
S-8522	16/02/2018	251506		B - 18-22km		Brisbane Workshop
R-6071	16/02/2018	251506		Ice Pack Service	SERVICE ICE PACK	Brisbane Workshop
R-6071	16/02/2018	251506		Seals	REPLACE FRONT THROUGH SHAFT SEAL	Brisbane Workshop
R-6071	16/02/2018	251506		Coolant	REPAIR BOTTOM COOLANT LEAK	Brisbane Workshop
R-6059	11/02/2018	247961		Data Star	Removed + replaced data star in dash and checked for working operation.	Brisbane Workshop
R-6059	11/02/2018	247961		Flare Guard	Removed LH side broken flare on guard. Drilled + pop riverts new flare onto guard also added 2 x new	Brisbane Workshop
R-5896	25/01/2018	239084		Wiper Blades	bolts/nuts. Replaced 2 x wiper blades	Brisbane Workshop
R-5896	25/01/2018	239084		Eco Wind	Serviced eco wind - moved exhaust pipe around to stop blowing on fuel tank	Brisbane Workshop
R-5711	05/01/2018	227500		Air Leak	REPAIRED AIR LEAK	Brisbane Workshop
R-5696	21/12/2017	223302		Mud Guards	TIGHTEN LOOSE DRIVE MUDGUARD POSTS & MUDGUARD BRACKETS	Brisbane Workshop
R-5696	21/12/2017	223302		Cross Member Bolts	TIGHTEN LOOSE CHASSIS CROSS MEMBER BOLTS UNDER WALKPLATE	Brisbane Workshop
R-5696	21/12/2017	223302		Walk Plate	MAKE UP 2 NEW WALKPLATE BRACKETS INSPECT FOR ANY DAMAGED CAUSED BY LR DRIVE TYRE BLOWOUT-ALL OK	Brisbane Workshop
R-5701	20/12/2017	223281		Mud Guards	TIGHTENED BOLTS ON LH REAR MUD GUARD	Brisbane Workshop
T-2999	18/12/2017	221243		Strip & Fit	1 X DUMP	Tyre Right
T-2981	15/12/2017	214274		Pressure Check		Brisbane Workshop
T-2981	15/12/2017	214274		Strip & Fit		Brisbane Workshop
R-5595	08/12/2017			Air Conditioner	CARRIED OUT SERVICE ON ECO WIND A/C	Brisbane Workshop

Number	Date	Kms 🦠	Hours	Туре	Repairer Notes	Repairer
H-5595	08/12/2017			Bracket	REMOVED BRACKET ON RH NEAR BONNET LOCK, WELDED UP BROKEN BRACKET & REFITTED	Brisbane Workshop
R-5579	07/12/2017	214180		Grill	RESCREWED BOTTOM RH GRILL	Brisbane Workshop
R-5579	07/12/2017	214180		Bonnet	REPAIRED BROKEN BONNET BRACKET	Brisbane Workshop
R-5579	07/12/2017	214180		Radiator and Cooling System	REPAIRED LH RADIATOR HOSE	Brisbane Workshop
I-1301	03/11/2017	190006				Brisbane Workshop
R-5255	03/11/2017	190006		Wheel Bearings	Removed, inspected and assembled front wheel bearings	Jones Diesel Services
R-5235	03/11/2017			Windscreen Repairs	SUPPLY & FIT RH WINDSCREEN	Alpha Glass Aust P/L
S-7955	03/11/2017	190006		C - Annual	C Service completed	Brisbane Workshop
R-5168	20/10/2017	182241		Lights	Fitted new amber lenses to flasing lights on roof. Fitted rebuilt spot light RHM of bull bar.	Brisbane Workshop
R-4956	11/09/2017	161015		Turbo Timer	Removed + replaced turbo timers + tested - okay. Had to cut off wiring plug from old timer + solder to new timer.	Brisbane Workshop
R-4902	29/08/2017	153478		Tune Up	PERFORM OVERHEAD ADJUSTMENT ON ALL VALVES, JAKES & INJECTORS	Crank IT
S-7603	21/08/2017			B - 18-22km	B Service completed	Brisbane Workshop
R-4806	21/08/2017			SEAT	Removed leather seat from B05 and fit Re-kit seat with chugger kit before fitment.	Brisbane Workshop
R-4806	21/08/2017			Bump Stop	Replaced missig LH front bump stop	Brisbane Workshop
R-4806	21/08/2017			Lights	Replaced blown LH park light bulb	Brisbane Workshop
R-4744	02/08/2017	138102		Tune Up	Removed all components to perform tune up. Assist with tune with Mess from Detroit.	Crank IT
R-4714	01/08/2017	138102		REVERSE BUZZER	Replaced reverse buzzer,	Brisbane Workshop
R-4682	24/07/2017	133600		TORQUE ROD	REPLACE BROKEN SLEEPER CAB TORQUE ROD	Brisbane Workshop
R-4579	10/07/2017	126503		Exhaust	REMOVE EXHAUST FLEX LHS REPAIR & REFIT WITH NEW CLAMPS	Crank IT
R-4509	30/06/2017	123000		TORQUE ROD	Replace sleeper cab torque rod.	Brisbane Workshop

Number	Date	Kma	Hours	Туре	Repairer Notes	Repairer
S-7331	30/06/2017	123000		B - 18-22km	B service completed	Brisbane Workshop
R-4459	16/06/2017			Lights	Replaced LH outter spotlight due to LED's not working. Replace missing bolts in LH inner spotlight.	Brisbane Workshop
R-5698	09/06/2017	110852		Lights	FITTED 2 NEW BOLTS TO MIDDLE DRIVING LIGHT	Brisbane Workshop
R-5698	09/06/2017	110852		Air Leak	REPAIRED AIR LEAK	Brisbane Workshop
R-4313	29/05/2017	103313		Bonnet Spring	Replaced bonnet spring	Pengelly
S-7075	29/05/2017	103313		B - 18-22km	Carried out B Service	Pengelly
R-4313	29/05/2017	103313		Turntable	Put bolt in turntable handle	Pengelly
R-4313	29/05/2017	103313		Lights	Put fuse in reverse lights	Pengelly
R-4341	16/05/2017	94657		Deck Plate	FABRICATE DECK PLATE HOLD DOWNS & FIT	Crank IT
R-4341	16/05/2017	94657		Ice Pack	R&R DAMAGED ICE PACK MOUNTING BOLTS AS ICE PACK WAS VERY LOOSE	Crank IT
R-4341	16/05/2017	94657		Air Leak	REPAIR NUMEROUS AIR LEAKS	Crank IT
R-4341	16/05/2017	94657		Grease Lines	R&R 2 X BROKEN AUTO GREASE LONES	Crank IT
R-4260	08/05/2017	90627		Signage	Supply 'Oversize' sign for front of truck Supply breakdown triangle kit	Brisbane Workshop
R-4260	08/05/2017	90627		Beacon Light	Supplied magnetic beacon light + rewired plug with trailer plug	Brisbane Workshop
R-4167	20/04/2017	80718		Lights	Replace missing bolt on spotlight	Brisbane Workshop
R-4167	20/04/2017	80718		Air Cleaner	Rewire clearance lights on air cleaner cannister.	Brisbane Workshop
R-4167	20/04/2017	80718		Bonnet	Reattach firewall bonnet rubber and secure	Brisbane Workshop
R-4110	20/04/2017	80718		Eco Wind	Service ecowind	Brisbane Workshop
S-6810	20/04/2017	80718		B - 18-22km	B Service completed	Brisbane Workshop
T-2440	13/04/2017			Rotate		Tyres 4 U
T-2440	13/04/2017			Balance		Tyres 4 U
R-4171	23/03/2017			Windscreen Repairs	Supply and fit RH windscreen.	ALPHA GLASS
R-3976	14/03/2017	59364		Ice Pack	SERVICE ICE WIND CHANGE OIL CLEAN OUT AIR & OIL FILTERS	Brisbane Workshop
S-6686	14/03/2017	59364		B - 18-22km	CHECK OVER GREASE CHANGE OIL & FILTER	Brisbane Workshop
S-6412	27/01/2017	33506		B - 18-22km	B Service completed	Pengelly
R-3703	27/01/2017	33506		Lights	Repaired spot lights (broken bolt)	Pengelly

Number	Date	Kms	Hours	Туре	Repairer Notes	Repairer
R-3309	28/11/2016			Fire Extinguisher	Tested and tagged fire ext. ABE, Mega Fire, 1kg. Next test due June 2017. PASSED	Toowoomba Workshop
R-3309	28/11/2016		325	Fire Extinguisher	Tested and tagged fire ext. ABE, Fire World, 4.5kg. Next test June 16. PASSED.	Toowoomba Workshop
S-6031	28/11/2016			A	A Service	Toowoomba Workshop
I-995	24/11/2016					
S-6304	24/11/2016			C - Annual	C Service created for starting point	

Signed:	
Name:	
Date:	