

BK Civil - Work Order Summary

Asset:
LV1029 (LV171) - 2015 MITSUBISHI TRITON
DUAL CAB

Location:

Current Tracker Hours:

Current Tracker Kms:

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
30295	REMOVE TRACKER	30/03/2023	1461	193687	30/03/2023	Routine Service		John Geldens
29495	Replace Radiator	01/02/2023	1416	191212	24/02/2023	Ask Supervisor		Murray Sampson
29082	fit new engine	21/12/2022	1405	41934	31/01/2023	Ask Supervisor		Juston Free
28504	Removal of engine due to possible cracked crank	02/11/2022	1405	41934	22/12/2022	Do Not Operate		Joseph Giles Juston Free
28091	Knocking noise coming from engine	14/09/2022	1405	41934	14/09/2022	Ask Supervisor		Juston Free
27768	10000 kmservice	17/08/2022	1347	38904	25/08/2022	Routine Service		Samuel Sparkes
26656	800 kmservice as per HMEngine warranty requirements	21/04/2022	971	29198	21/04/2022	Routine Service		Justin Debney
26663	Low braking	21/04/2022	971	29198	13/04/2022	Repair Next Service		
26648	weld hole in exhaust and fix mudguard	20/04/2022	965	28817	19/04/2022	Ask Supervisor		Jordan Humberdross
26078	Fit all stickers and unit numbers	14/02/2022	950	28094	18/02/2022	Repair Next Service		Joseph Giles Nicholas Radburn
25961	no compression	04/02/2022	950	28094	12/04/2022	Ask Supervisor		David Hbogkamp Nicholas Radburn Saul Whiteley
24980	Overflow is bubbling	03/10/2021			16/11/2021	Repair Next Service		David Hbogkamp
23090	160000 kmservice	23/04/2021	689	158839	28/05/2021	Routine Service		Jemalong Branch
22986	ABS and Traction control lights on	11/04/2021	658	157412	16/11/2021	Repair Next Service		David Hbogkamp
20750	service transmission	15/02/2021	536	150921	12/02/2021	Repair Next Service		Toowoomba Branch WSHOP - W
20514	Repair defects and checkover	10/02/2021	535	150892	11/02/2021	Repair Next Service		Toowoomba Branch WSHOP - W
20047	boost leak, pulley noise	02/02/2021	507	149098	10/04/2021	Ask Supervisor		Jemalong Branch
19916	150000 kmservice	01/02/2021	505	148947	13/02/2021	Routine Service		BKCGO BRANCH BK Cowal
19303	Replace broken tail light bracket	19/01/2021	475	147292	20/01/2021	Ask Supervisor		Toowoomba Branch WSHOP - R
19281	SERVICE	18/01/2021	472	147026	18/01/2021	Routine Service		EVOOGO Branch Cowal Evo
16514	140000 kmservice	18/11/2020	265	138945	18/12/2020	Routine Service		BKCGO BRANCH BK Cowal
12331	New right brake not working	02/09/2020			09/09/2020	Do Not Operate		
11634	130000 kmservice	16/08/2020		130407	28/08/2020	Routine Service		Toowoomba Branch WSHOP - W
10463	123750 kmservice	11/07/2020	2	123888	16/07/2020	Routine Service		Toowoomba Branch WSHOP - W
10454	Rear passenger brake lights not working	10/07/2020			20/08/2020	Do Not Operate		Toowoomba Branch WSHOP - W
10307	140000 KM Service	01/07/2020			14/07/2020	Routine Service		Toowoomba Branch WSHOP - W
10038	Prestart Defect - Tail Lights Failed	15/06/2020			20/08/2020	Do Not Operate		Toowoomba Branch WSHOP - W

Service Job History

Fleet No	Date	Staff	Completed	Days	Meter	Last Hirer	Job Description
BK171							UTILITY; MITSUBISHI TRITON DUAL CAB S/N: MMAJRKB40FD034101
2712	10/02/2020	Saul	3/03/2020	17			Repair. Belt faults.. Replace timing belt.
2653	31/01/2020	Trevor	7/02/2020	6		Evolution	Service. LV - Every 10k Service. Job cancelled.
2548	9/01/2020	Trevor	7/02/2020	22		Evolution	Repair. service ute. Service ute. Replace timing belts. Replace all belts. Repair fuse holder for A/C to work. Serviced at 102,300 km.
1781	11/10/2019	Trevor	11/10/2019	1		Evolution	Repair. REPAIR. fixed amber beacon , re-wired switch and installed new fuse holder.
1788	11/10/2019	Trevor	11/10/2019	1		Evolution	Repair. REPAIR. tighten loose hose on power steering rack.
1799	11/10/2019	Trevor	11/10/2019	1		Evolution	Service. LV - Every 10k Service. Completed 82372km.
1059	12/07/2019	Trevor	12/07/2019	1		Evolution	Repair. REPAIR. REWIRE FUEL POD
681	29/05/2019	PaulS	3/06/2019	4	70920	MCNAB D	Repair. Wire up Isolator and fit UHF. Fit and wire up battery isolator and starter isolater and find UHF aerial to fit into ute. Carry over fitting UHF, Light bar and wiring up and make brackets and assist Clay to weld to headboard. Finish off wheel nut indicators, hi-Vis striping, Fire extinguisher and brake tests.