

TAX INVOICE

Invoice Date
18 Oct 2023

Invoice Number
INV-000994

ABN

Description	Quantity	Unit Price	Amount AUD
Supply parts for Mack tipper engine repairs			
Timing gear assembly	1.00	4,483.56	4,483.56
Compressor gear	1.00	1,460.64	1,460.64
Power Steer pump mount seal	1.00	28.82	28.82
Compressor mount seal	1.00	30.58	30.58
Sump gasket	1.00	193.19	193.19
Rear main seal	1.00	171.23	171.23
Idler gear & bearing	1.00	930.22	930.22
		Subtotal	7,298.24
		TOTAL GST	729.82
		TOTAL AUD	8,028.06

Due Date: 25 Oct 2023

All accounts are strictly 7 days, unless otherwise agreed in writing.

Please use invoice number as reference for bank transfer

TAX INVOICE

Invoice Date

7 Nov 2023

Invoice Number

INV-001001

ABN

Description	Quantity	Unit Price	Amount AUD
Mack Tipper Engine Repairs. Rego: XN95WS. Km: 797223.			
Labour Hours	93.00	120.00	11,160.00
Parts Freight	1.00	75.00	75.00
Engine Oil	1.00	370.55	370.55
Transmission Oil	1.00	538.20	538.20
Engine Oil Filters	3.00	43.10	129.30
Power Steering Oil	1.00	121.67	121.67
Fuel Line & clamps	1.00	32.00	32.00
Consumables (brake cleaner, degreaser, sealants, buffing pads, emery paper)	1.00	100.00	100.00

Work Completed:

Jump started truck & drove to workshop. Removed driveshaft. Removed cross members. Removed R/H fuel tank & J-bracket. Removed R/H mudguard. Drained transmission & engine oil. Removed PTO pump from gearbox. Removed starter motor, power steering/fuel pump, removed air compressor. Removed clutch & flywheel. Removed engine sump, block support plate, oil pump & pick up piping. Supported engine. Removed rear engine mounts. Removed air intake & piping. Removed rocker cover. Removed rear timing gear top & bottom housings. Removed damaged gears & bearings. Ordered parts. Timed engine. Installed & torqued new gears & bearings. Checked gear backlash. Installed rear timing cover top & bottom housings. Installed rocker cover. Installed air intake & piping. Installed new gear on compressor. Installed compressor. Installed starter motor, power steering/ fuel pump. Installed new rear main seal. Installed rear engine mounts. Removed No. 7 main bearing cap & inspected bearing & crankshaft wear. Installed & torqued main bearing. Flushed out, cleaned & installed oil pump & pick up piping. Installed block support plate. Cleaned out & installed engine sump. Installed & torqued flywheel & clutch. Installed transmission, PTO pump, driveshaft, fuel tank, mudguard & cross members. Replaced filters. Filled transmission, engine & power steering oils. Charged batteries. Jump started truck. Test drove. Checked for leaks.

Subtotal	12,526.72
TOTAL GST	1,252.68
<hr/>	
TOTAL AUD	13,779.40

Due Date: 14 Nov 2023

All accounts are strictly 7 days, unless otherwise agreed in writing.

Please use invoice number as reference for bank transfer