

Stock No: APH00467

Volvo L60F IT Wheel Loader

Serial No: L60FV4389

Reg No: 96677D

Cat: LOAD IT

Year: 2014

Provisional?:

Supplier:

Model: Volvo L60F

Under Repair?

Log

<i>Date</i>	<i>Type</i>	<i>Description</i>	<i>Meter</i>	<i>Labour</i>	<i>Parts</i>
2/05/2024	REPAIR	Acemec: Repair lights and shorts		\$115.00	
5/02/2024	OTHER	Next REGISTRATION RENEWALS - date postponed from 18-Feb-24			
10/11/2023	OTHER	CJD Equip: Supply Lid			\$316.67
18/09/2023	OTHER	DCT: Supply fuel/water separator			\$89.60
13/09/2023	OTHER	Filtermax: Supply oil filter, fuel filter, air filter			\$270.28
11/09/2023	SERVICE	TG: Completed service as per manufactures specs (@ 11190 Hours)	11190		
19/05/2023	REPAIR	Harris Heavy Mechanical: Inspect hand brake. Found brake pads need changing. Fit new brake pads & test.		\$240.00	
8/05/2023	OTHER	CJD: Supply brake lining kit			\$330.17
14/02/2023	OTHER	Next REGISTRATION RENEWALS - date postponed from 18-Feb-23			
24/01/2023	REPAIR	Harris Heavy Mechanical: Change out coolant bottle, fill with coolant & bleed system		\$334.00	
19/01/2023	REPAIR	Inspect leak. Found coolant header tank cracked.		\$114.00	
14/12/2022	OTHER	Harris Heavy Mechanical: Adjust park brake. - pads need changing on park brake		\$110.00	
7/12/2022	OTHER	Jennings Glass: VOLVO F/G/H LOADER W/SCREEN 2008 ON			\$529.60

Stock No: APH00467

Volvo L60F IT Wheel Loader

Serial No: L60FV4389

Reg No: 96677D

1/12/2022	SERVICE	TG: Carry out 250hr service as per manufactures specifications. Change engine oil, oil filters, fuel filters, blow out air filter. Greased machine. Check all other fluids. Requires gas strut for access door (@ 10876 Hours)	10876	\$165.00	
1/12/2022	OTHER	DCT: Fuel/water separator			\$84.14
1/12/2022	OTHER	Acemec: Diagnose start fault		\$495.00	
21/09/2022	OTHER	CJD: pressure cap			\$57.32
15/09/2022	SERVICE	Narrabri Plant Repairs: carry out loader service and inspection .c/o engine oil and filters .c/o fuel filters(fuel and water separator filter has been swap out for aftermarket filter and oem filter is nonusable,will need parts to fit oem filter or can get aftermarket one instead) .grease machine .adjust park brake .radiator header tank cap is missing .machine has a ambient temp sensor fault and attachment lock fault a manual is required to help fix faults (@ 10732 Hours)	10732	\$550.00	
15/09/2022	REPAIR	Narrabri Plant Repairs: Carried out engine service Replaced engine oil and filters Replaced fuel filters Replaced air filter Looked over machine and found multiple hoses leaking Looked in to fault codes. 26/09/2022:Organise service Manual and research faults 05/10/2022: Fit new radiator cap Fit new ambient temp sensor Repair light bracket & fit light Test starting ok Fault code for amb/temp sensor cleared		\$670.00	
18/02/2022	OTHER	Next REGISTRATION RENEWALS - date postponed from 18-Feb-22			

Stock No: APH00467

Volvo L60F IT Wheel Loader

Serial No: L60FV4389

Reg No: 96677D

29/09/2021	REPAIR	JB: Refit fuel filter/coolant housing with new gasket and adaptor pipe with new o-rings. Fit new fuel filter and fill radiator with coolant. Replace RHS battery. Run and check for leaks. Tighten coolant and intake hoses (@ 9903 Hours)	9903	\$150.00	
22/09/2021	REPAIR	JB: Remove leaking fuel filter/coolant housing and broken coolant pipe. Clean off old gaskets		\$100.00	
9/09/2021	REPAIR	ACEMEC: Test a/c. Remove and bypass prestart system		\$100.00	\$35.00
29/07/2021	OTHER	JB: Refit guards and covers, charge battery run and test OK (@ 9886 Hours)	9886	\$135.00	
28/07/2021	REPAIR	JB: Run and check fuel pressure (low). Found fuel leak at fuel/water separator sensor. Replace fuel/water separator and sensor o-ring. Run and test. Retest after 12 hours OK (@ 9886 Hours)	9886	\$202.50	
28/07/2021	OTHER	DCT: Fuel/water separator			\$70.35
1/07/2021	REPAIR	PC DIESEL: Complete visual checks of fuel system for leaks, remove check valves and inspect condition, pressurize fuel rail and check for air leaks, test fuel pickup pump supply pressure		\$352.00	
13/05/2021	REPAIR	HR: Diagnose fuel starting issue. Removed rear guards to access fuel tank hose. Clamp loose. Tightened. Removed fuel filter housing leaking diesel fitting on head installed new washers (@ 9886 Hours)	9886	\$140.00	
13/05/2021	REPAIR	HR: Continued on finishing service C Fuel water separator filters. Adjusted forward and back switch (loose). Welded door lock back on as it was broken off. (@ 9886 Hours)	9886	\$105.00	

Stock No: APH00467

Volvo L60F IT Wheel Loader

Serial No: L60FV4389

Reg No: 96677D

11/05/2021	SERVICE	HR: Service. Replace oil, fuel and air filters (@ 9882 Hours)	9882	\$35.00	
10/05/2021	REPAIR	CJD: Fault: Coolant low level dash code. Carry out diagnosing on fault, replaced coolant sensor. Replaced 4 x globes for worn lights		\$718.00	\$67.00
10/11/2020	SERVICE	GC: Full Engine Service (@ 9322 Hours)	9322	\$315.00	
19/08/2020	OTHER	DCT - Pin, Retainer, Adaptor, Long Tip			\$372.70
11/08/2020	OTHER	Komatsu - Pin			\$540.90
27/06/2020	SERVICE	Service as per manufacturers recommendation (@ 8739 Hours)	8739		
18/06/2020	OTHER	Tyremax - 2 x Maxam Tyres, Fitting Labour			\$4,100.00
14/05/2020	SERVICE	Carry out service as required (@ 8387 Hours)	8387		
1/05/2020	OTHER	Future Fleet - Diagnose Faults			\$382.50
16/04/2020	REPAIR	ACEMEC: Read through wiring diagrams and fit pre-start module		\$570.00	\$387.00
14/04/2020	REPAIR	Future Fleet - Repairs to Volvo IT loader, fit reverse camera anc carry out service (@ 8123 Hours)	8123		\$977.50
19/03/2020	SERVICE	Carry out Service as per manufacturers recommendation (@ 7754 Hours)	7754		
25/02/2020	OTHER	DOUGLAS TYRE: Onsite service call to repair slow leak		\$325.00	
24/02/2020	OTHER	SCW: 50mm lugs as required			\$1,368.00
20/02/2020	REPAIR	ACEMEC: Test a/c, found heater tap failed		\$95.00	
20/02/2020	OTHER	New Stereo			\$129.00
20/02/2020	OTHER	REPCO: Rear LED Light, Autofix			\$105.99
20/02/2020	OTHER	AUTO ONE: Comb lamp w/lic lam			\$65.41
19/02/2020	REPAIR	Fit New LED Beacon, New UHF radio (@ 6698 Hours)	6698		
18/02/2020	REPAIR	Fix heater tap, Put in new valve			
18/02/2020	OTHER	HARTWIGS: UHF Transceiver 80 channel			\$280.00

