

Takata Airbag Search Result

Search date: 20/03/2023 8:11 AM +08

Vehicle Identification Number (VIN) entered: WDF63960523720805

Vehicle model: Vito

Model year: 2012

Response:

The Takata airbag recall has already been completed on your 2012 Vito.

The affected airbag inflators in this vehicle have either been replaced, removed or been deployed.

When replaced, a superior technology inflator has been installed in your vehicle and no further replacement regarding this concern will be required in the future.

ACCC Product Recall Assessment (PRA) if applicable: 2018/16910

Website address: <https://recall.mercedes-benz.com.au>

Email address: takata_au@mercedes-benz.com

Mercedes - Benz Australia/Pacific Pty Ltd Takata Customer Assistance Centre: 1300 659 307

Mercedes-Benz

