

Work Order Description	Repairer	Repair Hrs	Completed Date
NON STATER			19/04/2015
No first aid kit			4/08/2014
No radio			12/06/2014
No first aid kit			19/03/2014
No radio			19/03/2014
Cracked windscreen LHS			17/03/2014
c/o clutch	LUKE	41620	4/12/2013
TSB0007 Truck Park Brake Alarm	R.Brockwel		18/04/2013
OIL LEAK STEERING			25/07/2012
K/W MSG A Service 125HR	luke patio	40919	6/07/2012
rear diff cracked RHS	johnathon	40922	6/07/2012
ajust clutch	luke patio	40919	6/07/2012
replace hood strap	luke patio	40919	6/07/2012
DOOR			6/07/2012
K/W MSG B Service 250HR	luk darren	40789	30/06/2012
DROP BACK TRAILER	MICK	40738	24/06/2012
DROP BACK TRAILER AS REQUESTED	MICK	40738	24/06/2012
TREAD PLATE	MICK	40738	24/06/2012
FIT TREAD PLATE AS REQUESTED	MICK	40738	24/06/2012
Horton Fan			17/06/2012
grub screw replaced in horton fan	boboy	40624	17/06/2012
K/W MSG C Service 500HR	Boboy	40574	14/06/2012
Front RHS slack ajuster replaced	boboy	40574	14/06/2012
leaking air start soleniod repaired	boboy	40574	14/06/2012
HUB CAPS			12/06/2012
TIGHTEN	BRAD	18290	12/06/2012
K/W MSG B Service 250HR	callan	40448	8/06/2012
K/W MSG B Service 250HR	jermery	40220	12/05/2012
Remove and replace PTO power trailer		35060	26/04/2012
Change air filters		5092	26/04/2012
A servie and repairs		35113	26/04/2012
B Service. repalce cab torque rod. Rop up front st			26/04/2012
Top up diffs PM		35199	26/04/2012
Check and adjust last trailer brakes for dragging			26/04/2012
Fit rubber protection on intercoler LHS rubbing b		35340	26/04/2012
Repalce rocker box pin and bushes. Replace both			26/04/2012
and bushes on lift rams last trailer. Investigate an			26/04/2012
fault for throttle position sensor. Found loose plu			26/04/2012
wiring. Tighten front axle LHS u-bolts last trailer.			26/04/2012
and replace bent tracking rod last axle RHS and b			26/04/2012
last trailer		35406	26/04/2012
Carry out B service. Replace LHS rear axle booste			26/04/2012
Repaired and checked PT hyd fan			26/04/2012
Bin wouldn't tip so replaced fuse			26/04/2012
Diagnose & repair electrical fault on bin 2 tipping		35412	26/04/2012
Clean bearing replace hub cap. Remove and weld			26/04/2012
air bracket		35478	26/04/2012
Remove leaking valve under cab come back to sh			26/04/2012
fittings go to rail to refit valve		35511	26/04/2012

Check for trailers not tipping. Replace blown fuse control box on PT. Check solenoids for operation.		26/04/2012
another load. (OK)	35539	26/04/2012
Replaced blown hyd hose for PTO	35547	26/04/2012
R&R turbo and ex man. GAC. Repair top rad stary		26/04/2012
Repair fridge mount. Replace turbo	35580	26/04/2012
Refit turbo, grease steering and fit new frame for		26/04/2012
Fit fridge bracket and fridge lock up fan hub	35592	26/04/2012
Tighten turbo drain bolts	35601	26/04/2012
B Service		26/04/2012
PT 153 - B Service	35611	26/04/2012
Drive to rail and check massive coolant leak - sus		26/04/2012
cracked head/split bone. Travel to rail R&R boost		26/04/2012
the dolly.	35622	26/04/2012
Remove engine head	25675	26/04/2012
Continue fitting cylinder head		26/04/2012
Refit front drive and diff. Keep fitting head and ra		26/04/2012
Removed and cleaned air filter power trailer		26/04/2012
Went to rail to fix turbo leak		26/04/2012
Trouble shoot engine loose power		26/04/2012
Travel to rail swap out filters check over truck fou		26/04/2012
drive axle on PT leaking oil		26/04/2012
C service		26/04/2012
C service and checked all drive wheel bearings an		26/04/2012
oil and all diffs and final drives	35796	26/04/2012
Blow out air filters		26/04/2012
Coolant in engine oil, repaired crank angle sensor		26/04/2012
repaired 4 major coolant leaks, checked over roc		26/04/2012
conditions on trailers - ok - pump up tire		26/04/2012
Diagnose coolant useage found to be going out e		26/04/2012
Replace treadle valve	35917	26/04/2012
Replace tailshaft on PT	35938	26/04/2012
vehicle had near miss due to no brakes adjusted 1		26/04/2012
are gone, LH mid axel last trailer booster u/s R+R	35972	26/04/2012
Daily service at rail head, repair arms for decomp	35993	26/04/2012
Clean up heat exchanger and regas A/C system	36054	26/04/2012
Daily service at rail head - air filters.	36074	26/04/2012
C service	36084	26/04/2012
Drive to rail and check LHR wheel for oil leaks, str		26/04/2012
rear wheel bearing	36096	26/04/2012
Replace spider gears (bearings) replace wheel be.		26/04/2012
seal swap drums, install cups and bearing, seals a		26/04/2012
Replaced blown globe - low beam - LHS	36148	26/04/2012
Every day check, and blown air filter on PT, trans		26/04/2012
buzzer staying on - on way out- engine oil filter tc		26/04/2012
start check out send 3 trips to haul road, blowing		26/04/2012
white smoke, bring back to yard and find fault.		26/04/2012
Start brakes on last axel powertrailer	36176	26/04/2012
Asset Maintenace Notes		26/04/2012
B Service	34273	26/04/2012

Asset Maintenance Notes		26/04/2012
Removed damaged hub on tow trailer		26/04/2012
Asset Maintenance Notes		26/04/2012
Replaced damaged hub replace smashed spring		26/04/2012
Asset Maintenance Notes		26/04/2012
C service adjust wheel bearings replace brake bo	34920	26/04/2012
Asset Maintenance Notes		26/04/2012
Free up locked up S Cam replace hyd filters	34512	26/04/2012
Asset Maintenance Notes		26/04/2012
Repaired power steering, collant leak, lhs bonnet		26/04/2012
B Service		26/04/2012
Asset Maintenance Notes		26/04/2012
Repair and replace A frame		26/04/2012
A Service replaced milky oil in front LH hub on PM	34727	26/04/2012
Asset Maintenance Notes		26/04/2012
Repair and replace A frame		26/04/2012
Replace drivers seat		26/04/2012
Asset Maintenance Notes		26/04/2012
Repalce spring on bonnet, B service	34420	26/04/2012
Asset Maintenance Notes		26/04/2012
R&R radiator	34431	26/04/2012
Asset Maintenance Notes		26/04/2012
B service and repaires	34585	26/04/2012
KW C500 - FRONT DIFF OVHL	35675	19/04/2011
KW C500 - REAR DIFF OVHL	34009	31/10/2010
KW C500 - FRONT DIFF OVHL	34009	31/10/2010
KENWORTH C500 - ENG OVHL	30137	3/03/2010
KW C500 - TRANS/CLUTCH OVHL		3/03/2010
KW C500 - FRONT DIFF OVHL	27133	12/08/2009