

Coates Hire Pre Divestment Inspection Checklist

Trucks / Motor Vehicles

Description Truck - Tipper 6t (3 Way) Asset # 1079895 Service Job # 4075866

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate information in this section ***

Make/ Model MITSUBISHI TIPPER5-6T3WAY Engine/Motor - Make/Model Mitsubishi Fuso
 Year 2011 Engine Serial Number 6M60-3AT1
 Serial Number JLFFK61FH0KJ00157 Meter Reading 79899

Comments: _____

Features:

Pickup Flat Bed Dump Boom Other Comments: _____
 Drive System 2WD 4WD Power Take Off Yes No
 Axle Weights Rating: Front 3600 kg
 Axle Weights Rating: Rear 6800 kg
 Registration Information Number SB 97 EM Year _____

Overall Appearance:

Control Station/Operator Station	Good <input checked="" type="checkbox"/>	Fair <input type="checkbox"/>	Poor <input type="checkbox"/>	Comments: _____
Sheet metal/Fiberglass Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Paint	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Operator Station	Good <input checked="" type="checkbox"/>	Fair <input type="checkbox"/>	Poor <input type="checkbox"/>	N/A <input type="checkbox"/>	Comments: _____
Seat Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Steering Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Powertrain Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Hydraulic Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Safety Belt	Operates Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	N/A <input type="checkbox"/>	Horn	Operates Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	N/A <input type="checkbox"/>
Gauges	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Warning Alarms	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Conditioner	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Odometer	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Engine or Electric Motor:

Power: Diesel Gas Comments: _____
 Does it start? Yes No
 Did it need to be jumped? Yes No
 Acceptable Power Yes No
 Unusual Noises Yes No

Transmission

Transmission Auto Manual Hydrostatic N Speeds 6 Comments: _____
 Operates Yes No N/A
 Forward Reverse Shifting
 Clutch Parking Brake Brakes

Chassis

Bumpers	Good <input checked="" type="checkbox"/>	Fair <input type="checkbox"/>	Poor <input type="checkbox"/>	Inoper <input type="checkbox"/>	Missing <input type="checkbox"/>	N/A <input type="checkbox"/>	Comments: _____
Windshield Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Trailer Electrical Connections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Work Body Function	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Tyre Condition:

Left - Front	Left - Rear <u>2x tyres</u>	Right - Front	Right - Rear <u>2x tyres</u>
Brand- <u>Double Coin</u>	Brand- <u>Double Coin</u>	Brand- <u>Double Coin</u>	Brand- <u>Hankook</u>
Size- <u>17.5</u>	Size- <u>17.5</u>	Size- <u>17.5</u>	Size- <u>17.5</u>
Condition- <u>Good</u>	Condition- <u>side wts.</u>	Condition- <u>Good</u>	Condition- <u>Poor</u>

Full Name of Employee completing Inspection: Andres Barros Caceres Branch where Inspection completed: Boxby Downs

Any other known issues, faults: _____