

## Coates Hire Pre Divestment Inspection Checklist Boom Lift (Electric or Internal Combustion)

Name COATES Branch MILDURA  
 Description 60FT BOOM Asset # 1101500 Service Job # \_\_\_\_\_

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at [www.coateshire.com.au](http://www.coateshire.com.au).

**General Information:** \*\*\* Copy Data Plate information in this section \*\*\*

Make/ Model GENE 60D Engine/Motor - Make/Model DEUTZ  
 Year 2009 Engine Serial Number 10653290  
 Serial Number Z60089601 Meter Reading 3084

Comments: \_\_\_\_\_

**Features:**

Max Lift Height 60FT Comments: \_\_\_\_\_  
 Drive System 2WD  4WD  Platform size 2.4x1.2  
 AC Chord to Basket Yes  No  Battery Charger Yes  No   
 Air to Basket  Generator   
 Does Basket Rotate  Outriggers   
 Knuckle Boom  Extendable axles   
 Straight Boom  Articulating Jib

**Overall Appearance:** Good Fair Poor Comments: \_\_\_\_\_

Control Station/Operator Station     
 Sheet metal/Fiberglass Condition     
 Paint     
 Lights

**Control Station** Operates Yes No N/A Comments: \_\_\_\_\_

Operator Controls: Platform     
 Operator Controls: Ground     
 Gauges Operational?

**Engine or Electric Motor:** Power: Diesel  Gas  Dual Fuel  Electric   
 Does it start? Yes  No   
 Did it need to be jumped?    
 Acceptable Power    
 Unusual Noises

Comments: \_\_\_\_\_

**Hydraulics** Operates Yes No Leaks Yes No Comments: \_\_\_\_\_

Pump      
 Hoses      
 Cylinders      
 Drive Motors      
 Brakes      
 Parking Brakes

**Chassis:** Good Fair Poor Inoper Missing N/A Comments: \_\_\_\_\_

Frame Condition        
 Mast/ Boom Sections        
 Boom Extension Wear Guides        
 Basket Condition        
 Outriggers and Pads Condition        
 Rotational Gear Condition        
 Extendable Axle        
 TurnTable Bearing Play

**Tyre Condition:**

Left - Front	Left - Rear	Right - Front	Right - Rear
Brand- _____	Brand- _____	Brand- _____	Brand- _____
Size- _____	Size- _____	Size- _____	Size- _____
Condition- <u>GOOD</u>	Condition- <u>GOOD</u>	Condition- <u>GOOD</u>	Condition- <u>GOOD</u>

Definium Device fitted? Yes  No  Definium device returned to BU ASM

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_