

Coates Inspection Checklist

Light Towers

Photos

See Light Tower Photo Log for required pictures

Asset # 1109816

General Information:

*** Copy Data Plate information in this section ***

Make/ Model All lights MS6K-01 Engine / Motor - Make / Model CATERPILLAR C1.1
 Year 2012 Engine Serial Number C3MD2281
 Serial Number 6JETRAMLTCL1A09825 Meter Reading 8954 HRS.

Data Plate

Comments: Beyond Years - 12 Years Old.

Features:

List features or options for the machine:

Number of Lights 4 Wattage per light 1500 W
 Height of Mast 9M Generator KVA 12 KVA
 Power Outlets Qty Single Phase N/A Amps per outlet _____
 Qty 3 Phase N/A Amps per outlet _____

4-Corner Photos

- Left-Front Corner
- Left-Rear Corner
- Right-Front Corner
- Right-Rear Corner
- Damage
- Damage

Overall Appearance:

| | | | |
|----------------------------------|-------------------------------------|--------------------------|-------------------------------------|
| | Good | Fair | Poor |
| Control Station/Operator Station | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Sheet metal/Fiberglass Condition | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Paint | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Lights | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

Comments: RH SIDE HOOD COVER MISSING/DAMAGED LATCH.
MISSING XI GLOBE
LIGHTS NOT WORKING

Control Station

Operates

| | | |
|-------------------------------------|--------------------------|--------------------------|
| Yes | No | N/A |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: _____

Operator Controls
 Gauges Operational?

- Hour Meter
- Gauges
- Damage
- Damage

Engine or Electric Motor:

Power: Diesel Gas Electric
 Does it start? Yes No
 Did it need to be jumped? Yes No
 Acceptable Power No
 Unusual Noises Yes No

Comments: - LEAK AT FRONT ENGINE COVER
- NO GENERATOR OUTPUT VOLTAGE.

- Right Side hood open
- Left Side hood open

Chassis

| | | | | | | |
|--|-------------------------------------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|--------------------------|
| | Good | Fair | Poor | Inoper | Missing | N/A |
| Landing Gear / Outriggers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Frame Condition | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Trailer Lights | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Trailer Electrical Connections | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Trailer Brakes | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Switches | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Light Tower (Take picture with tower up) | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Lights (Take picture with lights on) | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Power Cables | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: - MINOR OIL LEAK AT THE LIGHTS
TILT CYLINDER.
SOME OF THE LIMIT SWITCHES NEED NEW

- Hitch
- Lights on
- Light Tower (Extended)

Tire Condition:

| | |
|------------------------|------------------------|
| Left | Right |
| Brand- _____ | Brand- <u>NEXEN</u> |
| Size- <u>205R16LT</u> | Size- <u>205R16C</u> |
| Condition- <u>GOOD</u> | Condition- <u>FAIR</u> |

Tire pictures at a 45 degree angle showing the tread and side walls

- Left
- Right