

## Coates Hire Pre Divestment Inspection Checklist

### Excavator

Description 1.4T Excavator Asset # 1113412 Service Job # 3893635

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at [www.coateshire.com.au](http://www.coateshire.com.au).

General Information: \*\*\* Copy Data Plate Information in this section \*\*\*

Make/Model CAF 301.4 Engine/Motor - Make/Model YANMAR 3TNV76-SNS2  
 Year 2012 Engine Serial Number 30717  
 Serial Number LOK60780 Meter Reading \_\_\_\_\_

Comments: \_\_\_\_\_

Features:  
 List features or options for the machine:  
 Cab  Yes  No Front Blade width at the widest point 1290mm Comments: BLADE PINS + BUSHES WORN  
 Thumb  Yes  No Rear Bucket width at the widest point \_\_\_\_\_  
 Auxiliary Hydraulics  Yes  No  
 Push Blade  Yes  No

Overall Appearance:  
 Control Station/Operator Station  Good  Fair  Poor Comments: NEEDS PAINT. BODY PANELS MOUNTS NOT FITTING  
 Sheet metal/Fiberglass Condition  Good  Fair  Poor  
 Paint  Good  Fair  Poor  
 Lights  Good  Fair  Poor

Operator Station  
 Seat Condition  Good  Fair  Poor  N/A Comments: SEAT BELT WONG RETRACT  
 Steering Controls  Good  Fair  Poor  N/A  
 Control Lock Lever  Good  Fair  Poor  N/A  
 Powertrain Controls  Good  Fair  Poor  N/A  
 Hydraulic Controls  Good  Fair  Poor  N/A  
 Operational:  Yes  No  N/A Operates:  Yes  No  N/A  
 Safety Belt  Yes  No  N/A Horn  Yes  No  N/A  
 Gauges  Yes  No  N/A Warning Alarms  Yes  No  N/A  
 Air Conditioner  Yes  No  N/A Hour Meter  Yes  No  N/A  
 Heater  Yes  No  N/A Wipers  Yes  No  N/A

Engine Power: Diesel  Gas  Comments: STARTER IS INTERMITTENT  
 Does it start?  Yes  No  
 Did it need to be jumped?  Yes  No  
 Acceptable Power  Yes  No  
 Unusual Noises  Yes  No  
FRONT CRANK SEAL IS LEAKING

Drive System  
 Operates:  Yes  No Number of Speeds: 1 Comments: \_\_\_\_\_  
 Drive/Propel Motors  Yes  No  
 Final Drives  Yes  No  
 Brake and Travel Locks  Yes  No

Hydraulics  
 Operates:  Yes  No  N/A Leaks:  Yes  No  N/A Comments: BUCKET CYLINDER IS BENT  
 Pump  Yes  No  N/A  
 Hoses  Yes  No  N/A  
 Cylinders  Yes  No  N/A  
 Drive Motors  Yes  No  N/A  
 Brakes  Yes  No  N/A  
 Parking Brakes  Yes  No  N/A

Chassis  
 Condition:  Good  Fair  Poor  Inoper  Missing  N/A Comments: UNIT NEEDS ALL BEAM & STICK AND KNUCKLE BUSHES AND PINS REPLACED.  
 Slick  Good  Fair  Poor  Inoper  Missing  N/A  
 Boom  Good  Fair  Poor  Inoper  Missing  N/A  
 Roller Frame  Good  Fair  Poor  Inoper  Missing  N/A  
 Bottom Covers  Good  Fair  Poor  Inoper  Missing  N/A  
 Bucket  Good  Fair  Poor  Inoper  Missing  N/A  
 Blade  Good  Fair  Poor  Inoper  Missing  N/A  
 Wear: Minimal Moderate Excessive  
 Pin & Bushing Wear at Base Of Boom  Minimal  Moderate  Excessive  
 Pin & Bushing Wear on Slick & Bucket  Minimal  Moderate  Excessive  
 Turntable Bearing Play  Minimal  Moderate  Excessive

Undercarriage  
 Track Belt (steel / rubber) Width: 230mm Overall Machine Width (Outsides of tracks): 1300mm  
 Grouser Height: N/A Comments: \_\_\_\_\_  
 Track belt (steel / rubber)  Good  Fair  Poor  N/A  
 Idlers  Good  Fair  Poor  N/A  
 Track Rollers  Good  Fair  Poor  N/A  
 Sprockets  Good  Fair  Poor  N/A  
 Track Bushings  Good  Fair  Poor  N/A

Any other known issues, faults: Bucket # 1127700  
1127641  
1127683