

Coates Hire Pre Divestment Inspection Checklist

Loaders (eg. Backhoe / Tractor / Tool Carrier / Wheel Loader)

Description KANGA MINI LOADER Asset # 1143260 Service Job # 4009912

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate Information in this section ***

Make/ Model KANGA/DW265 Engine/Motor - Make/Model KUBOTA/D902
 Year 2014 Engine Serial Number 4DY1064
 Serial Number KLAL200F40 Meter Reading 1920 HRS

Comments: _____

Features:
 Drive System 2WD 4WD
 Cab Yes No Front Bucket width at widest point 1050mm Bucket # 1143270
 Multi-Purpose Bucket Front Bucket width at widest point _____
 Rear Box Blade Rear Box Blade width at widest point _____

Overall Appearance:
 Control Station/Operator Station Good Fair Poor Comments: _____
 Sheet metal/Fiberglass Condition Good Fair Poor
 Paint Good Fair Poor
 Lights Good Fair Poor

Operator Station
 Seat Condition Good Fair Poor N/A Comments: _____
 Steering Controls Good Fair Poor N/A
 Control Lock Lever Good Fair Poor N/A
 Powertrain Controls Good Fair Poor N/A
 Hydraulic Controls Good Fair Poor N/A
 Safety Belt Yes No N/A Operates Yes No N/A
 Gauges Yes No N/A Horn Warning Alarms Yes No N/A
 Air Conditioner Yes No N/A Hour Meter Yes No N/A
 Heater Yes No N/A Wipers Yes No N/A

Engine
 Power: Diesel Gas Comments: _____
 Does it start? Yes No
 Did it need to be jumped? Yes No
 Acceptable Power Yes No
 Unusual Noises Yes No

Transmission
 Operates? Forward Yes No Reverse Yes No Shifting Yes No
 Operates? Parking Brakes Yes No
 Comments: _____

Hydraulics
 Operates? Pump Yes No Hoses Yes No
 Leaks? Cylinders Yes No Drive Motors Yes No
 Brakes Yes No Parking Brakes Yes No
 Comments: _____

Chassis
 Condition Good Fair Poor Inoper Missing N/A Comments: _____
 Stick Good Fair Poor Inoper Missing N/A
 Boom Good Fair Poor Inoper Missing N/A
 Outriggers and Pads Good Fair Poor Inoper Missing N/A
 Loader Lift Arms Good Fair Poor Inoper Missing N/A
 Rear Boom & Stick Good Fair Poor Inoper Missing N/A
 Boom Lock Good Fair Poor Inoper Missing N/A
 Front Bucket Good Fair Poor Inoper Missing N/A
 Rear Bucket Good Fair Poor Inoper Missing N/A
 Wear Minimal Moderate Excessive
 Upper Lift Arm Pins & Bushing Wear Minimal Moderate Excessive
 Bucket Tilt Linkage Pins & Bushing Wear Minimal Moderate Excessive
 Loader Bucket Pins & Bushing Wear Minimal Moderate Excessive
 Extend-a-hoe Stick Guide Wear Minimal Moderate Excessive
 Boom & Stick Pins & Bushing Wear Minimal Moderate Excessive

BUCKET DOES NOT LINE UP, PINS & BUSHINGS WORN

Tyre Condition:
 Left - Front Brand- NHS Size- 23 x 8.5 Condition- POOR
 Left - Rear Brand- NHS Size- 23 x 8.5 Condition- POOR
 Right - Front Brand- NHS Size- 23 x 8.5 Condition- POOR
 Right - Rear Brand- NHS Size- 23 x 8.5 Condition- POOR

Any other known issues, faults:
MACHINE IS OLD & TIRED NEEDS NEW TYRES
ISSUES WITH PIN, BUSHES & BUCKET MOUNTING.