Coates Hire Pre Divestment Inspection Checklist Scissor Lift (Electric or Internal Combustion)					
		COISSUI LIIL (E	lectric of internal Co	iiibuəti0ii)	
Description19' ELECTRIC S	CISSORLIFT		ASSET 1143925		
inspection and assessment of the equ from defects in materials and workma Competition and Consumer Act 2010, Coates which conditions, warranties a	ipment. The equipmenship, or complies win nor statutes, rules or nd obligations canno	ent is used and sold th all relevant laws, regulations from tir t, or cannot to a limi	as is. Coates does not warrar Australian Standards, licence me to time in force in Australia ited extent be excluded, restric	ne. It should only be used as a guide. The buyer should rely of that the equipment is new, fit for purpose, of merchantable or permit requirements. Nothing herein shall limit those provis which imply certain conditions or warranties or impose obligated or modified. The Coates Hire Used Equipment Terms and the these terms which are available upon request or at	quality, free sions of the ations on
General Information: *** C	opy Data Plate inform	nation in this section	ן ***		
Make/ Model JLG 1	930ES	Engine/	Motor - Make/Model		
Year		Engine Serial Number			
Serial Number B200017518		Meter Reading 462			
Comments:	DOES	NOT I	RIVE		_
Features:					
	_		Max Lift Height	5.7mtr	
Drive System 2WD	4WD		Platform size (LxW)		
Platform Extension	Yes No	Dotton	Charres	Yes No	
AC Chord to Platform		Genera			
Air to Platform	L K	Outrigge Non-ma	ers arking Tyres		
Overall Appearance:	Occident Fair	Comme	ents:		
Control Station\Operator Station	Good Fair □ □	Poor			
Sheet metal\Fiberglass Condition Paint					
Control Station					_
Yes	Operates No N/A	Comments:			
		-		*	
Operator Controls: Platform Operator Controls: Ground Gauges Operational?				5	
Engine or Electric Motor:					
Power: Diesel	Gas 🗌	Dual Fuel	Electric 🗔		
Yes Does it start?	No	Comments:			
Did it need to be jumped?			DOES NOT	DRIVE.	
Acceptable Power Unusual Noises			3002 1101		-
Hydraulics Operates	1.6	eaks	_		
Yes No	N/A Yes	No N/A	Comments:		
Pump 🖳 🗆					
Cylinders					_
Brakes 🗒 🗒		₩ ⊔			-
Parking Brakes	_	_			
Frame Condition	Good Fair	Poor Inoper	Missing N/A Commen	ts:	
Scissor Linkage			<u> </u>		_
Steering Linkage Nork Platform Condition					
Outriggers and Pads Condition					_
Γyre Condition: ∟eft - Front	Left - Rear		Right- Front	Right - Rear	
Brand-	Brand-		Brand-	Brand-	
Size-	Size-	,	Size-	Size-	
Conditior GOOD	Conditior GOOD		Conditior GOOD	Condition- GOOD	
Any other known issues, faults:					
ssue 1.1		· · · · · · · · · · · · · · · · · · ·	1/01/2013	AST-CL-011A Asset Inspection Checklist - Scissor	